

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 737579	Problem: PRE-DELIVERY INSPECTION				
Meter Reading: 0		Labor		Parts	
In Date: 04/24/2007	Close Date: 04/24/2007	Hours	Description		Quantity
- Pre-Delivery Inspection		2.00			
	Parts Charge: 0.00	Labor Charge:	110.00		

Workorder: 738896	Problem: 001 WASH TICKET ISSUED OUT 05/17/07				
Meter Reading: 0		Labor		Parts	
In Date: 05/17/2007	Close Date: 05/18/2007	Hours	Description		Quantity
- 001 Wash Ticket Issued Out 05/17/07					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 7.14		

Workorder: 742822	Problem: SISTERS TOWING & TRANSPORTATON TOW FROM 160 AUTSTA				
Meter Reading: 0		Labor		Parts	
In Date: 08/13/2007	Close Date: 08/20/2007	Hours	Description		Quantity
- Sisters Towing & Transportaton Tow From 160 Autstalian Ave - Tow To					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 78.00		

Workorder: 742861	Problem: NO START				
Meter Reading: 2652		Labor		Parts	
In Date: 08/20/2007	Close Date: 08/21/2007	Hours	Description		Quantity
- Ck Battery Condition,Recharge & Test Main Battery.Verify Charging Sys Operation.Found Rear Hatch Slightly Open		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 55.00			

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 746455

Problem: P.M. SERVICE.

Meter Reading: 3884	Labor	Parts	
In Date: 10/30/2007	Hours	Description	Quantity
- Perform Pm Service	4.00	SHOP SUPPLIES	1.00
- Perform Nitrogen Fill Tires Inflation Conversion Service On All Tires Complete.		5W30 OIL	4.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- High Speed Balance All 4 Tires To Correct Vibration In The Body Of Vehicle When Driving Over 50 Mph.			
- Shop Supplies			
Parts Charge:	16.36	Labor Charge:	60.00

Workorder: 833242

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	
In Date: 01/16/2008	Hours	Description	Quantity
- Tiresoles Of Broward Inc			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	60.00

Workorder: 840155

Problem: P.M SERVICE

Meter Reading: 8741	Labor	Parts	
In Date: 06/17/2008	Hours	Description	Quantity
- Pm Service Complete	4.00	5W30 OIL	4.00
- Service & Adjust Rear Drum Brakes.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- High Speed Balance All 4 Tires To Correct Body Vibration.		SHOP SUPPLIES	1.00
- Shop Supplies		09997 BRAKE CLEAN	1.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
		31-24 WIPER BLADES 24" BLADE	1.00
Parts Charge:	34.37	Labor Charge:	60.00

Workorder: 846550

Problem: 005 WASH TICKETS ISSUED OUT 10/17/08

Meter Reading: 0	Labor	Parts	
In Date: 10/17/2008	Hours	Description	Quantity
- 005 Wash Tickets Issued Out 10/17/08			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	35.70

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 846781

Problem: SISTERS TOWING & TRANSPORTATON TOW FROM GLADES RD

Meter Reading: 0	Labor	Parts			
In Date: 11/05/2008	Hours	Description	Quantity		
- Sisters Towing & Transportaton Tow From Glades Rd Just West Of Turnpike - Tow To					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	78.00

Workorder: 847336

Problem: REPLACE R/F TIRE.ALIGN.

Meter Reading: 12262	Labor	Parts	
In Date: 11/20/2008	Hours	Description	Quantity
- Mount Balance And Nitrofill 1 New Tire On R/F			
- Frontend Alignment.Fab And Modify R/F Strut To Get Camber & Caster Within Specs			
- Tire Light On.Diag Tire Monitor Moduled Failed,R&R Module An Register Tire Codes And Recalibrate Sys.			
- Shop Supplies			
Parts Charge:	545.19	Labor Charge:	240.00

Workorder: 848094

Problem: GUARANTEED BUMPER & SUPPLIERS

Meter Reading: 0	Labor	Parts			
In Date: 11/05/2008	Hours	Description	Quantity		
- Guaranteed Bumper & Suppliers					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	6,356.74

Workorder: 933229

Problem: 002 WASH TICKETS ISSUED OUT 01/26/09

Meter Reading: 0	Labor	Parts			
In Date: 01/26/2009	Hours	Description	Quantity		
- 002 Wash Tickets Issued Out 01/26/09					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	14.28

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 934680

Problem: P.M. SERVICE.

Meter Reading: 13855		Labor		Parts	
In Date: 03/03/2009	Close Date: 03/10/2009	Hours	Description	Quantity	
- Pm Service		4.00	5W30 OIL		4.00
- Rotate And Balance All 4 Tires			05046 BATTERY PROTECTOR (CRC)		1.00
- Clean,Adjust And Service Rear Brakes.			CA10159 AIR FILTER WIX 49116 PRIUS 04-UP		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			ANTISEIZE 405540005		1.00
			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
Parts Charge: 30.81		Labor Charge: 240.00			

Workorder: 940618

Problem: clunking noise in L/F

Meter Reading: 16824		Labor		Parts	
In Date: 07/10/2009	Close Date: 07/16/2009	Hours	Description	Quantity	
- Diagnose Clunking Noise In Front End, Replace R/F Lower Ball Joint.		3.50	SHOP SUPPLIES		1.00
- Alignment.			R/FRONT LOWER BALL JOINT		1.00
- Shop Supplies					
Parts Charge: 65.78		Labor Charge: 210.00			

Workorder: 941908

Problem: front bumper sheild loose

Meter Reading: 16667		Labor		Parts	
In Date: 08/10/2009	Close Date: 08/11/2009	Hours	Description	Quantity	
- Drill And Install New Screws To Hold On Frt Skid Shield		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 942042

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 16824		Labor		Parts	
In Date: 08/12/2009	Close Date: 08/12/2009	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 72.00	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 943339

Problem: P.M service, check rattle in passenger side door

Meter Reading: 17352		Labor		Parts	
In Date: 09/16/2009	Close Date: 09/23/2009	Hours	Description	Quantity	
-	P.M Service.	5.80	SHOP SUPPLIES		1.00
-	Mount One New Tire, Repair R/R Tire, Rotate & Balance All Four Tires.		5W30 OIL		4.00
-	Service Rear Drum Brakes.		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
-	Driver Complain Of Rattle Noise In R/F Door.R&R Passenger Seat And Secure Trim Panel.		31-24 WIPER BLADES 24" BLADE		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			NB-18 WIPER BLADES 18" ANCO 31-18		1.00
			402032477 185/65R15 INTEGRITY DON'T REORDER		1.00
			8524247010 BLADE REAR WIPER (TOYOTA)		1.00
Parts Charge: 104.28		Labor Charge: 348.00			

Workorder: 1002859

Problem: PM service.

Meter Reading: 19208		Labor		Parts	
In Date: 03/19/2010	Close Date: 04/05/2010	Hours	Description	Quantity	
-	P.M Service.	4.00	5W30 OIL		4.00
-	Remove R/F Axle Assembly & Replace Damaged Inner Boot.		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
-	Shop Supplies		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP		1.00
			INNER AXLE BOOT		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 47.17		Labor Charge: 240.00			

Workorder: 1009628

Problem: Abs light on and brake light on .

Meter Reading: 21052		Labor		Parts	
In Date: 09/02/2010	Close Date: 09/20/2010	Hours	Description	Quantity	
-	Computer Diagnose Abs Concern.Test And Replace Failed Brake Light Switch With New.Clear Codes And Road Test.	2.75	SHOP SUPPLIES		1.00
-	Shop Supplies		STOP LIGHT SWITCH		1.00
Parts Charge: 66.05		Labor Charge: 165.00			

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1011257

Problem: P.M. Service.

Meter Reading: 21060		Labor		Parts	
In Date: 10/13/2010	Close Date: 10/21/2010	Hours	Description	Quantity	
-	Preform Pm Service.	4.00	8524247010 BLADE REAR WIPER (TOYOTA)	1.00	
-	Rotate And Balance All Four Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00	
-	Perform Rear Drum Brakes Servce And Adjust Brake Shoes.		31-24 WIPER BLADES 24" BLADE	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			5W30 OIL	4.00	
			PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00	
Parts Charge: 42.74		Labor Charge: 240.00			

Workorder: 1104135

Problem: P.M . Service.Recall.

Meter Reading: 23190		Labor		Parts	
In Date: 04/15/2011	Close Date: 05/05/2011	Hours	Description	Quantity	
-	Perform Pm Service.	6.75	SHOP SUPPLIES	1.00	
-	Rotate And Balance All Four Tires.		31-24 WIPER BLADES 24" BLADE	1.00	
-	Perform Rear Drum Brakes Service And Adjust Brake Shoes.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00	
-	Remove Right Front Wheel And Inner Fender Liner To Access And Repair Failed Windshield Washer Hose.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00	
-	Transport Vehicle To And From Dealer For Hybrid Water Pump And Accelerator Pedal Recall.Installing New Hybrid Water Pump And Modify Pedal To Floor Surface.		CF9846A CAB FILTER WIX 24875	1.00	
-	Shop Supplies		5W30 OIL	4.00	
			09997 BRAKE CLEAN	1.00	
Parts Charge: 26.88		Labor Charge: 405.00			

Workorder: 1105787

Problem: 1 - Wash ticket(s) issued

Meter Reading: 23259		Labor		Parts	
In Date: 06/01/2011	Close Date: 06/01/2011	Hours	Description	Quantity	
-	1 - Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 8.51	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1106487 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 23762	Labor	Parts	Quantity
In Date: 06/20/2011	Hours	Description	Quantity
- 1 - Wash Ticket(S) Issued			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 9.73	

Workorder: 1112351 **Problem:** Pm service.Low tire pressure warning light on.Front bumper damage.

Meter Reading: 25628	Labor	Parts	Quantity
In Date: 11/18/2011	Hours	Description	Quantity
- P.M. Service.	6.25	SHOP SUPPLIES	1.00
- Test Battery And Charging System,Battery Failed Load		00544-21171-325 BATTERY (TOYOTA)	1.00
- Test.Replace Defective Battery.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Remove Interior Panel And Replace Defective Trunk Hatch Lock.		5W30 OIL	4.00
- Rotate And Balance All Tires.		84840-47010 SWITCH LIFT GATE RELEASE	1.00
- Service And Adjust Rear Brakes.			
- Shop Supplies			
Parts Charge: 190.72	Labor Charge: 375.00		

Workorder: 1205921 **Problem:** Pm service.

Meter Reading: 27575	Labor	Parts	Quantity
In Date: 06/22/2012	Hours	Description	Quantity
- Perform Pm Service.	4.00	5W30 OIL	4.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Rotate And Balance All Four Tires.		31-24 WIPER BLADES 24" BLADE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
Parts Charge: 26.60	Labor Charge: 240.00		

Workorder: 1209599 **Problem:** Transition Prep Charge

Meter Reading: 28426	Labor	Parts	Quantity
In Date: 10/05/2012	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge: 0.00	Labor Charge: 0.00		

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1209817 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 28426 **Labor**

In Date: 10/12/2012 **Hours** **Description** **Parts** **Quantity**

- 1 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 8.51

Workorder: 1210747 **Problem:** flat tire

Meter Reading: 28790 **Labor**

In Date: 11/02/2012 **Hours** **Description** **Parts** **Quantity**

- Repalce Two Tires Nitro And Balance And Rotate New Tires To Front

Parts Charge: 232.38 **Labor Charge:** 90.00

738523571 P185-65R15 1.00
738523571 P185-65R15 1.00

Workorder: 1210770 **Problem:** flat tire/ keys under mat

Meter Reading: 28722 **Labor**

In Date: 11/02/2012 **Hours** **Description** **Parts** **Quantity**

- Tow From: 100 Austrailian Air Port Hilton To: Vista

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 104.15

Workorder: 1211021 **Problem:** No Start

Meter Reading: 28850 **Labor**

In Date: 11/13/2012 **Hours** **Description** **Parts** **Quantity**

- Charge And Test Battery

Parts Charge: 0.00 **Labor Charge:** 60.00

Workorder: 1212121 **Problem:** pm service

Meter Reading: 29460 **Labor**

In Date: 12/17/2012 **Hours** **Description** **Parts** **Quantity**

- Pm Service **3.00** NAPAGOLD OIL FILTER 1.00

- Rear Brake Service NAPA QUART 5W30 4.00

Parts Charge: 19.76 **Labor Charge:** 180.00

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1300893 **Problem:** to dealer for steering recall

Meter Reading: 29845	Labor	Parts		
In Date: 01/25/2013	Hours	Description	Quantity	
- To And From Dealer For Steering Recall	1.00			
Parts Charge:	0.00	Labor Charge:	60.00	

Workorder: 1302076 **Problem:** no start

Meter Reading: 30137	Labor	Parts		
In Date: 02/28/2013	Hours	Description	Quantity	
- Ck For No Start-Recharge Battery And Load Test Ok-Founddoor Not Full Closed	1.00			
Parts Charge:	0.00	Labor Charge:	60.00	

Workorder: 1305260 **Problem:** PM SERVICE

Meter Reading: 32260	Labor	Parts		
In Date: 05/29/2013	Hours	Description	Quantity	
- Pm Service	3.00	NAPA QUART 5W30	4.00	
- Rear Brake Service		NAPAGOLD OIL FILTER	1.00	
Parts Charge:	18.21	Labor Charge:	180.00	

Workorder: 1305312 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 32258	Labor	Parts		
In Date: 05/30/2013	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 91.80

Workorder: 1305467 **Problem:** alignment

Meter Reading: 32260	Labor	Parts		
In Date: 06/04/2013	Hours	Description	Quantity	
- Alignment	2.50			
Parts Charge:	0.00	Labor Charge:	150.00	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1305587 **Problem:** REMOTE INOP

Meter Reading: 32293	Labor	Parts	Quantity
In Date: 06/05/2013	Hours	Description	
- Repalce Remote Key And Install Remote Battery	0.50	ENR ELECT BATTERY	1.00
Parts Charge: 5.60	Labor Charge: 30.00		

Workorder: 1308132 **Problem:** no start in FDO parking lot

Meter Reading: 33084	Labor	Parts	Quantity
In Date: 08/14/2013	Hours	Description	
- Ck Battery Check For No Start	0.50		
Parts Charge: 0.00	Labor Charge: 30.00		

Workorder: 1310010 **Problem:** pm service/ noise?

Meter Reading: 34645	Labor	Parts	Quantity
In Date: 10/02/2013	Hours	Description	
- Pm Service	3.00	31-24 WIPER BLADES 2	1.00
- Rear Brake Service		NAPA QUART 5W30	4.00
		NAPAGOLD OIL FILTER	1.00
		8524247010 BLADE REAR	1.00
		WIPER BLADE	1.00
Parts Charge: 48.09	Labor Charge: 180.00		

Workorder: 1310713 **Problem:** repaint frt bumper

Meter Reading: 34645	Labor	Parts	Quantity
In Date: 10/04/2013	Hours	Description	
- Repaint Frt Bumper			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 377.40	

Workorder: 1310745 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 34645	Labor	Parts	Quantity
In Date: 10/28/2013	Hours	Description	
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 91.80	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1312439

Problem: Check engine and tire light on

Meter Reading: 34758	Labor	Parts	
In Date: 12/13/2013	Hours	Description	Quantity
<hr/>			
- Diagnose Check Engine Light Replace Fuel Cap	3.50	GAS CAP NON-LOCKING	1.00
- Right Front Tire Repair Reprogram Tire Sensors			
- Charge And Test Battery			
Parts Charge:	13.26	Labor Charge:	210.00

Workorder: 1312812

Problem: lf fender shield off

Meter Reading: 34986	Labor	Parts	
In Date: 12/26/2013	Hours	Description	Quantity
<hr/>			
- Repair And Reinstall L/Front Inner Fender Sheild	1.00		
Parts Charge:	0.00	Labor Charge:	60.00

Workorder: 1400002

Problem: Front end under prius came loose(Section 1 bldg #5)

Meter Reading: 34986	Labor	Parts	
In Date: 12/26/2013	Hours	Description	Quantity
<hr/>			
- Tow From: 14455 Strathmore Lane, Delray Beach, 33446 To: Se Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	104.15

Workorder: 1402334

Problem: pm/ clicks on turns/ detail

Meter Reading: 35920	Labor	Parts	
In Date: 03/10/2014	Hours	Description	Quantity
<hr/>			
- Pm	7.00	NAPAGOLD OIL FILTER	1.00
- Diagnose Front Suspension Noise. Lube		MAC WITE LITHIUM GRES	1.00
- Wash Vehicle		10W30 MOTOR OIL	4.00
- Service Rear Drums And Shoes			
Parts Charge:	18.98	Labor Charge:	420.00

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1403429 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 36157	Labor	Parts		
In Date: 04/08/2014	Hours	Description	Quantity	
- 1 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 8.51

Workorder: 1404517 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 36466	Labor	Parts		
In Date: 05/08/2014	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 91.80

Workorder: 1407691 **Problem:** tire light on

Meter Reading: 37760	Labor	Parts		
In Date: 08/05/2014	Hours	Description	Quantity	
- Repair Rr Tire 3.50 3M TM HEADLIGHT LENS 1.00				
- Wash Vehicle				
- Clean Head Lights Reseal Glass				
Parts Charge:	24.56	Labor Charge:	210.00	

Workorder: 1408615 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 37760	Labor	Parts		
In Date: 08/27/2014	Hours	Description	Quantity	
- 1 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 8.51

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1410574

Problem: pm service

Meter Reading: 38228		Labor		Parts	
In Date: 10/22/2014	Close Date: 10/28/2014	Hours	Description	Quantity	
- Pm		4.50	NAPAGOLD AIR FILTER		1.00
- R/R 2 Tires, Balance And Nitro			TIRE DISPOSAL FEE		2.00
- Clean And Adjust Rear Brakes			738274571 195-65R15 A		2.00
			NAPAGOLD OIL FILTER		1.00
			NAPA QUART 5W30		4.00
			WIPER BLADE		1.00
			NAPA CABIN AIR FILTER		1.00
			REAR COMPOSITE BLADE		1.00
			31-24 WIPER BLADES 2		1.00
Parts Charge: 314.09		Labor Charge: 270.00			

Workorder: 1410704

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 38228		Labor		Parts	
In Date: 10/27/2014	Close Date: 10/27/2014	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 91.80	

Workorder: 1502067

Problem: 1 - Wash ticket(s) issued

Meter Reading: 40118		Labor		Parts	
In Date: 02/26/2015	Close Date: 02/26/2015	Hours	Description	Quantity	
- 1 - Wash Ticket(S) Issued					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 8.34	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1502252 **Problem:** pm service

Meter Reading: 40446	Labor	Parts	Quantity
In Date: 03/03/2015	Hours	Description	
- Pm	3.00	WIPER BLADE	1.00
- Clean And Adjust Service Rear Brakes		NAPAGOLD OIL FILTER	1.00
		NAPA QUART 5W30	4.00
		BRAKE CLEANER	1.00
		31-24 WIPER BLADES 2	1.00
Parts Charge: 31.78		Labor Charge: 180.00	

Workorder: 1505714 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 40878	Labor	Parts	Quantity
In Date: 06/08/2015	Hours	Description	
- 1 - Wash Ticket(S) Issued			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 8.34

Workorder: 1508188 **Problem:** pm service

Meter Reading: 41497	Labor	Parts	Quantity
In Date: 08/14/2015	Hours	Description	
- Pm	4.00	NAPAGOLD OIL FILTER	1.00
- Clean And Readjust Rear Shoes And Drums		BRAKE CLEANER	1.00
- Wash		NAPA QUART 5W30	4.00
		NAPAGOLD AIR FILTER	1.00
Parts Charge: 28.98		Labor Charge: 240.00	

Workorder: 1508840 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 41749	Labor	Parts	Quantity
In Date: 09/02/2015	Hours	Description	
- 1 - Wash Ticket(S) Issued			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 8.34

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1510529 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 42033	Labor	Parts		
In Date: 10/19/2015	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 90.00

Workorder: 1512392 **Problem:** low tire press light on

Meter Reading: 42090	Labor	Parts		
In Date: 12/08/2015	Hours	Description	Quantity	
- Add Nitro All 4 Tires And Reset Tpms Sensors	2.00			
- Carwash				
Parts Charge:	0.00	Labor Charge:	120.00	

Workorder: 1600284 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 42781	Labor	Parts		
In Date: 01/08/2016	Hours	Description	Quantity	
- 1 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 8.34

Workorder: 1601785 **Problem:** pm service

Meter Reading: 42922	Labor	Parts		
In Date: 02/22/2016	Hours	Description	Quantity	
- Pm	5.00	18" wiper blades	1.00	
- Service Rear Brakes		NAPA QUART 5W30	4.00	
- Balance All Tires		BRAKE CLEANER	1.00	
- Install Asset #S		NAPAGOLD OIL FILTER	1.00	
		1CART PALLADIUM 2 GRS	1.00	
		WASHER FLUID CONCENTR	1.00	
		WIPER BLADES 24"	1.00	
Parts Charge:	34.66	Labor Charge:	300.00	

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1602832 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 42922		Labor		Parts
In Date: 03/17/2016	Close Date: 03/17/2016	Hours	Description	Quantity

- 1 - Wash Ticket(S) Issued

Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	8.34
----------------------	------	----------------------	------	---------------------------	------

Workorder: 1603744 **Problem:** replace rgt frt tire

Meter Reading: 43835		Labor		Parts
In Date: 04/08/2016	Close Date: 04/13/2016	Hours	Description	Quantity

- Replace Right Front Tire **1.50** TIRE DISPOSAL FEE 1.00

- Reset Tire Sensor 738274571 195-65R15 A 1.00

Parts Charge:	117.49	Labor Charge:	90.00	
----------------------	--------	----------------------	-------	--

Workorder: 1604507 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 44357		Labor		Parts
In Date: 04/28/2016	Close Date: 04/28/2016	Hours	Description	Quantity

- 1 - Wash Ticket(S) Issued

Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	8.34
----------------------	------	----------------------	------	---------------------------	------

Workorder: 1608464 **Problem:** P.M. Service.

Meter Reading: 47555		Labor		Parts
In Date: 08/16/2016	Close Date: 08/31/2016	Hours	Description	Quantity

- P.M. Service. **7.00** TIRE DISPOSAL FEE 1.00

- Test Battery And Charging System.Replace Bad Battery. NAPA QUART 5W30 4.00

- Replace Serpentine Belt. NAPA CABIN AIR FILTER 1.00

- Replace One Tire,Repair Right Rear,Rotate And Balance SHOP SUPPLIES 1.00

 All Four. V-RIBBED BELT 1.00

- Service And Adjust Rear Brakes. WASHER FLUID CONCENTR 1.00

- Shop Supplies NAPAGOLD OIL FILTER 1.00

 738274571 195-65R15 A 1.00

 AGM BATTERY 1.00

Parts Charge:	372.61	Labor Charge:	420.00	
----------------------	--------	----------------------	--------	--

10/17/2016
9:01:21AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166694 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1609259

Problem: Transition Prep Charge

Meter Reading: 47624

Labor

Parts

In Date: 09/06/2016

Close Date: 09/06/2016

Hours

Description

Quantity

-	Transition Prep Charge			2.00				
		Parts Charge:	0.00	Labor Charge:	0.00			

Total Parts Charges:	2,481.40	Total Labor Charges:	6,588.00	Total Comm. Charges:	7,838.57
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------