

**Palm Beach County Fleet Management
Asset Maintenance History**

10189091 2013 FORD TRANSIT CONNECT Mini Van, Animal Care

Workorder: 1304969 **Meter:** 305 **In Date:** 05/20/2013 **Closed:** 05/20/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1308787 **Meter:** 2798 **In Date:** 08/27/2013 **Closed:** 08/29/2013
Problem: flat tire repair

- Tire Service 13th street and "e" ave - flat tire repair

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1308813 **Meter:** 3019 **In Date:** 08/30/2013 **Closed:** 09/04/2013
Problem: Left front tire flat damage beyond repairs.

- Install new tire to the left front wheel.nitrogen fill and balance same.put back spare tire to spare tire rack under vehicle.

- Shop Supplies

Parts List	Qty
P20565r15conti Procont	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 1.00 Labor: 60.00 Parts: 165.57 Total: 225.57
 :

Workorder: 1311866 **Meter:** 7322 **In Date:** 11/25/2013 **Closed:** 12/10/2013
Problem: Pm service.Low tire pressure warning light on and check over radio.

- P.m. Service.

- Repair right front tire,rotate and balance all four.

- Service and adjust rear brakes.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Washer FI	1.00
Shop Supplies	1.00

Hours 5.75 Labor: 345.00 Parts: 20.50 Total: 365.50
 :

Workorder: 1400860 **Meter:** 9758 **In Date:** 01/27/2014 **Closed:** 01/28/2014
Problem: Power outlet fuse inop.

- Test for short circuit and replace open 20 amps fuse with new.

Hours 0.50 Labor: 30.00 Parts: 0.00 Total: 30.00
 :

Workorder: 1401834 **Meter:** 11028 **In Date:** 02/24/2014 **Closed:** 02/25/2014
Problem: Flat tire on r/r

- Tire Service 7100 Belverdere Rd (animal Care) - Flat tire on r/r

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402834 **Meter:** 12863 **In Date:** 03/25/2014 **Closed:** 04/07/2014
Problem: P.M. service.

- Perform pm service	Parts List	Qty
- Install new front brake pads and resurface brake rotors.service calipers and flush brake fluid.perform rear drum brake service and adjust brake shoes.automated bleed hydraulic system with scan tool.	5w20 Engine Oil	5.00
	Napagold Oil Filter	1.00
	Exact Fit Blade	1.00
- Rotate and balance all four tires.	Accufit Conventional	1.00
- Shop Supplies	Brake Pads Fr Trans	1.00
	Shop Supplies	1.00
Hours 7.75	Labor: 465.00	Parts: 104.39
:		Total: 569.39

Workorder: 1404181 **Meter:** 14151 **In Date:** 04/30/2014 **Closed:** 04/30/2014
Problem: Left rear tire going flat.

- Repair flat left rear tire.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1406177 **Meter:** 16999 **In Date:** 06/24/2014 **Closed:** 06/25/2014
Problem: Right front tire flat.

- Repair right front tire flat.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1407236 **Meter:** 19178 **In Date:** 07/23/2014 **Closed:** 08/11/2014
Problem: P.M. service.

- Perform pm service.	Parts List	Qty
- Install four new tires and balance all four.	5w20 Engine Oil	5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter	1.00
- Perform wheel alignment complete.	Exact Fit Blade	1.00
- Transport vehicle to and from dealer for replacing failed water pump,coolant recovery tank,serpentine belt and power steering pump o ring.	Accufit Conventional	1.00
	P20565r15conti Procont	4.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 10.25	Labor: 615.00	Parts: 692.68
:		Total: 1,307.68

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1411340 **Meter:** 25464 **In Date:** 11/13/2014 **Closed:** 11/25/2014
Problem: P.M. service

- Pm service.	Parts List	Qty
- Test and replace defective left tag lamp bulb.	5w20 Engine Oil	5.00
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Exact Fit Blade	1.00
- Inspect and service rear drum brakes.	Accufit Conventional	1.00
- Shop Supplies	Bulb	1.00
	Napagold Air Filter	1.00
	Hub Cap	4.00
	Motorcraft 96r Battery	1.00
	Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 497.47
:		Total: 872.47

Workorder: 1501652 **Meter:** 30991 **In Date:** 02/13/2015 **Closed:** 02/26/2015
Problem: P.M. service.

- Pm service.	Parts List	Qty
- Repair broken ground wire for front strobe lights.	5w20 Engine Oil	5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Exact Fit Blade	1.00
- Shop Supplies	Accufit Conventional	1.00
	Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 38.42
:		Total: 353.42

Workorder: 1504570 **Meter:** 34934 **In Date:** 05/04/2015 **Closed:** 05/05/2015
Problem: Flat tire on Passenger Rear

- Tire Service Animal Care (7100 Belvedere Rd) - Flat tire on Passenger Rear

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1505253 **Meter:** 36441 **In Date:** 05/26/2015 **Closed:** 06/02/2015
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Inspect and replace bent lower radiator support and lower radiator hose(rubbing on compressor pulley).flush and refill cooling system.	5w20 Engine Oil	5.00
- Service and adjust rear brakes.	Napagold Oil Filter	1.00
- Rotate and balance tires.	Exact Fit Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Lower Hose	1.00
	Coolant Ford Gold	1.00
	Radiator Sup Bracket	1.00
	Ford Red Antifreeze	1.00
	Lower Hose	1.00
	Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 337.40
:		Total: 832.40

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505869	Meter: 36759	In Date: 06/12/2015	Closed: 06/16/2015
Problem: Right brake light inop.			
- Replace the right side brake light bulb.		Parts List	Qty
		Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 1.86	Total: 31.86
:			
Workorder: 1506339	Meter: 37533	In Date: 06/24/2015	Closed: 06/29/2015
Problem: Right window inop			
- Diagnose for right side power window inop.test and replace defective power window switch.		Parts List	Qty
		heber	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 76.16	Total: 136.16
:			
Workorder: 1507681	Meter: 39346	In Date: 08/03/2015	Closed: 08/06/2015
Problem: Towed in left front tire flat.			
- Repair and balance left front tire.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1507734	Meter: 39205	In Date: 08/01/2015	Closed: 08/03/2015
Problem: Flat Tire			
- Tow From: Animal Care To: Fleet North			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1508593	Meter: 40943	In Date: 08/27/2015	Closed: 08/31/2015
Problem: Two flat front tires.Pulls to left.			
- Replace and balance two tires.		Parts List	Qty
- Shop Supplies		P205/65r15 Assurance	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 1.00	Labor: 60.00	Parts: 261.39	Total: 321.39
:			
Workorder: 1509649	Meter: 42078	In Date: 09/24/2015	Closed: 10/20/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Check for noise in right front engine area.replace defective idler pulley and drive belt.		5w20 Engine Oil	5.00
		Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.		Exact Fit Blade	1.00
- Inspect and service rear brakes.		Wiper Blade	1.00
- Complete front end alignment and test drive.		P205/65r15 Assurance	2.00
- Shop Supplies		Tensioner	1.00
		V Belt	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 9.50	Labor: 570.00	Parts: 356.06	Total: 926.06
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600767 **Meter:** 48656 **In Date:** 01/22/2016 **Closed:** 01/29/2016
Problem: P.M. service and driver visor loose.

- Pm service.	Parts List	Qty
- Resurface drums and rotors.replace brake pads.service front calipers.flush and bleed brake system.replace brake shoes.service springs and hardware.	Brake Pads	1.00
	5w20 Engine Oil	5.00
- Inspect and tighten sun visors screws.	18" wiper blades	1.00
- Rotate and balance four tires.	Wiper Bleade Anco	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Reman Brake Shoes	1.00
	Brake Cleaner	1.00
	B Fluid Dot 3-32oz	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 163.97
:		Total: 778.97

Workorder: 1602794 **Meter:** 51128 **In Date:** 03/16/2016 **Closed:** 03/31/2016
Problem: Towed in for stalling.

- Check and inspect electrical system and fuel system.check for codes.check under hood relay center.multiple burnt relays.replace four burnt relays.roadtest.	Parts List	Qty
	Relay	3.00
- Shop Supplies	Relay	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 103.16
:		Total: 283.16

Workorder: 1602871 **Meter:** 51047 **In Date:** 03/16/2016 **Closed:** 03/17/2016
Problem: Stalling Out

- Tow From: 1907 Hartford Crout			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1604103 **Meter:** 53324 **In Date:** 04/19/2016 **Closed:** 04/26/2016
Problem: Left front tire going flat.

- Re;pair and balance left front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605810 **Meter:** 58898 **In Date:** 06/06/2016 **Closed:** 08/18/2016
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Service transmission.flush and refill system.	5w20 Engine Oil	5.00
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Long cranking before engine starts.perform fuel system diagnostics.fuel pressure leaking down while vehicle sits.r&r fuel tank and replace fuel pump module.	Wiper Bleade Anco	1.00
	18" wiper blades	1.00
- Replace right front marker lamp.	Syn-atf Trans Fluid S	10.00
- Service and adjust rear brakes.	P205/65r15 Assurance	2.00
- Diagnose and replace inop cooling fan module,resistor and melted connector.repklace blown 40amp fuse.	Transmission Filter	1.00
	Ptex Ultra Grey 3oz	1.00
- A/c performance test.replace defective compressor,orifice tube and accumulator.vacuum and recharge system to specs.	trailer plug	1.00
- Replace antenna	Fuel Pump Assy	1.00
- Shop Supplies	Gasket	1.00
	Fan Resistor Conrector	1.00
	Lamp Asy	1.00
	Fan Motor Assy	1.00
	Circuit	1.00
	A/c Flush	1.00
	Ac Compressor	1.00
	Drier A/ C	1.00
	Orifice Tube Filter	1.00
	Seal	2.00
	R134a Lv Shop 2	3.00
	E8 A/c Oil Univ W Dye	1.00
	Mast	1.00
	Antenna	1.00
	O Ring	3.00
	O-ring	3.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours 20.75 Labor: 1,245.0 Parts: 2,109.27 Total: 3,354.27
:

Workorder: 1608803 **Meter:** 59358 **In Date:** 08/24/2016 **Closed:** 08/31/2016
Problem: Had to jump start in A/M.

	Parts List	Qty
- Test battery and chjarging system.replace bad battery.	Battery	1.00
- Shop Supplies	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 122.35 Total: 182.35
:

Workorder: 1611914 **Meter:** 63022 **In Date:** 11/17/2016 **Closed:** 11/29/2016
Problem: Right front turn signal inop.

	Parts List	Qty
- Replace right front signal light bulb.	Bulb	1.00

Hours 0.50 Labor: 30.00 Parts: 1.77 Total: 31.77
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700364 **Meter:** 66948 **In Date:** 01/11/2017 **Closed:** 01/31/2017
Problem: P.M. service and noise and vibration from engine felt in cab.

	Parts List	Qty
- P.m. Service.		
- Diagnose and replace back up alarm relay.	5w20 Engine Oil	5.00
- Replace two worn out engine mount and transmission mount.	Napagold Oil Filter	1.00
	18" wiper blades	1.00
- Pressure test and inspect cooling system.replace leaking upper and lower radiator hoses.top off coolanrt.	Enr Elect Battery	1.00
	Engine Moont	1.00
- Replace two tires,rotate and balance all four.	Engine Mount	1.00
- Replace and program one key fob.	Trans Mount	1.00
- Service ande adjust rear brakes.	Lower Hose	1.00
- Shop Supplies	P205/65r15 Assurance	2.00
	Wiper Bleade Anco	1.00
	Relay	1.00
	Key Fob	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 12.25	Labor: 735.00	Parts: 846.62
:		Total: 1,581.62

Workorder: 1701886 **Meter:** 71437 **In Date:** 02/23/2017 **Closed:** 04/04/2017
Problem: Left rear tire going flat. Towed in for overheating.

	Parts List	Qty
- Replace leaking a/c condensor .vacuum and recharge a/c system to specs.test and replace blown cooling fan fuses.	A/c Condenser	1.00
- Replace leaking radiator and lower hose.flush and bleed system.	E8 A/c Oil Univ W Dye	1.00
	Freon Lv Shop 2	3.00
- Repair aux. cooling fan brackets.replace lower grill insert.	Radiator Assy	1.00
- Repair and balance left rear tire.	Anti Freeze Motorcraft	1.00
- Diagnose and repair cage lighting wiring.	Lower Hose	1.00
- Shop Supplies	Grille	1.00
	Fuse Holder	2.00
	Shop Supplies	1.00
Hours 11.00	Labor: 660.00	Parts: 745.07
:		Total: 1,405.07

Workorder: 1702350 **Meter:** 69628 **In Date:** 03/08/2017 **Closed:** 03/08/2017
Problem: Overheating

- Tow From: Lyons rd Nb Just n of Lw rd To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704861 **Meter:** 73388 **In Date:** 05/16/2017 **Closed:** 05/18/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace two tires mount on front.balance and rotate all four tires.	5w20 Engine Oil	5.00
	Napagold Oil Filter	1.00
- Inspect and service rear brakes.	18" wiper blades	1.00
- Complete front end alignment . Road test.	Wiper Bleade Anco	1.00
- Shop Supplies	P205/65r15 Assurance	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.25	Labor: 495.00	Parts: 257.90
:		Total: 752.90

Workorder: 1708960 **Meter:** 80249 **In Date:** 09/18/2017 **Closed:** 10/05/2017
Problem: P.M. Service.Pulls right.Crane inop.

- P.m. service.	Parts List	Qty
- Check and replace both rear shock absorbers.	5w20 Engine Oil	5.00
- Installed power inverter,circuit breaker. wire loom and fabricate harness as needed.	Napagold Oil Filter	1.00
	18" wiper blades	1.00
- Replace two front tires.balance and rotate all four .	Wiper Bleade Anco	1.00
- Inspect and service rear brakes.	Oespectrum Trk Shock	2.00
- Shop Supplies	Cpi 1575 Inverter 1500 W	1.00
	Cb185-100 Cir Brkr	1.00
	Bulk Battery Cable	12.00
	Cabl/lug	6.00
	Fab Loom-split Poly	12.00
	P205/65r15 Assurance	2.00
	Terminal	2.00
	Bulk Battery Cable	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.75	Labor: 705.00	Parts: 615.35
:		Total: 1,320.35

Workorder: 1711908 **Meter:** 81968 **In Date:** 12/05/2017 **Closed:** 12/07/2017
Problem: Right rear tire going flat.

- Repair right rear tire and balance .	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804091 **Meter:** 85228 **In Date:** 04/19/2018 **Closed:** 05/03/2018
Problem: P.M. service and loud noise from front on highway.

- P.m. service.	Parts List	Qty
- Road test .remove and replace both front hub bearings .test drive to verify repair.	5w20 Engine Oil	5.00
- Resurface both front rotors. Replace brake pads and service calipers .inspect and service rear brakes .road test.	Napagold Oil Filter	1.00
- Test and replace right side sliding door latch assembly. Retest.	Washer Fluid Concentr	1.00
- Performance test A/c system .evacuate system .replace faulty compressor,accumulator,oriface tube and seals .flush system and complete recharge to spec. Retest.	Wiper Bleade Anco	1.00
- Rotate and balance all four tires.	18" wiper blades	1.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Brk Fluid Dot 4-12oz	1.00
	Kit Bearing	2.00
	Brake Pads	1.00
	Latch	1.00
	Ac Compressor	1.00
	Drier A/ C	1.00
	Tube Filter	1.00
	O Ring	6.00
	O-ring	2.00
	Freon Lv Shop 2	2.00
	Flush Solvent	1.00
	Latch	1.00
	Shop Supplies	1.00
Hours 19.75	Labor: 1,185.0	Parts: 1,924.67
:	0	Total: 3,109.67

Workorder: 1807499 **Meter:** 86475 **In Date:** 07/24/2018 **Closed:** 07/24/2018
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
: