



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Affron Park	1	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	1
Affron Park	2	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones that have diameter of between 1 1/4 inches and 2 inches in cross-sectional nominal dimension for circular handrails. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2 1/4 inches maximum.	\$980.00	2	each	\$1,960.00	1
Affron Park	3	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface. Cost included in earlier finding.	\$0.00	2	each	\$0.00	1
Affron Park	4	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through	\$525.00	2	each	\$1,050.00	1
Affron Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Affron Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Affron Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$9,187.50	1	each	\$9,187.50	1
Affron Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Affron Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Affron Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Affron Park	11	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Affron Park	13	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Affron Park	14	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	2
Affron Park	15	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	1	each	\$2,486.00	4
Affron Park	16	Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Affron Park	17	2-5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Cost included in 5-12 play area finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Affron Park	18	2-5 Play Area	Play Area	Make corrections to surface to provide accessible EPCs.  Cost included in a 5-12 playground finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Affron Park	19	2-5 Play Area	Play Area	Make corrections to surface to provide accessible GLPCs.  Cost included in a 5-12 playground finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Affron Park	20	2-5 Play Area	Play Area	Make corrections to surface to provide accessible GLPCs.  Cost included in a 5-12 playground finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Affron Park	21	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
Affron Park	22	5-12 Play Area	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Affron Park	23	5-12 Play Area	Play Area	Make corrections to play area surface to provide accessible EPCs.  Cost included in earlier finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Affron Park	24	5-12 Play Area	Play Area	Make corrections to surface to provide accessible GLPCs.  Cost included in an earlier finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Affron Park	25	5-12 Play Area	Play Area	Add one more GLPCs of type other than swings and climbers to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Affron Park	26	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
Affron Park	27	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Affron Park	28	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	750	sq ft	\$91,875.00	5
Affron Park	29	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Affron Park	30	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Affron Park	31	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Affron Park	32	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	550	sq ft	\$67,375.00	5
American Homes Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
American Homes Park	3	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
American Homes Park	4	Parking	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
American Homes Park	5	Exterior Accessible Route	Accessible Routes	Remove bollard to widen EAR to min 36" clear width.	\$59.20	5	lin ft	\$296.00	1
American Homes Park	6	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
American Homes Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
American Homes Park	8	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
American Homes Park	9	Park Element	Play Area	Replace surface at fitness area with one that is accessible.	\$70.00	1000	sq ft	\$70,000.00	2
American Homes Park	10	Park Element	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  Provide designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	2
American Homes Park	11	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
American Homes Park	14	Picnic Area	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
American Homes Park	15	Picnic Shelter	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	1	each	\$2,486.00	4
American Homes Park	16	Play Area (2-5)	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
American Homes Park	17	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
American Homes Park	18	Play Area (2-5)	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
American Homes Park	21	Play Area (2-5)	Play Area	For children age 3 to 4, raise/lower the play component to min 20" and max 36".  In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
American Homes Park	23	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Pricing in a previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	N/A	\$0.00	4
American Homes Park	24	Play Area (5-12)	Play Area	Raise platform on transfer system to 11" to 18" AGL, in the alternative, remove and maintain surface fill level to achieve the same.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
American Homes Park	28	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
American Homes Park	29	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
American Homes Park	30	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
American Homes Park	31	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
American Homes Park	32	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Aqua Crest Pool	2	East Parking Lot & Front Loop	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Aqua Crest Pool	3	East Parking Lot & Front Loop	Accessible Routes	Relocate parking and stripe a no parking zone at entry to accessible route (AR) to prevent cars from blocking AR.	\$367.50	1	each	\$367.50	1
Aqua Crest Pool	4	East Parking Lot & Front Loop	Parking - Off Street	Add van parking sign to an accessible stall.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	5	East Parking Lot & Front Loop	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Aqua Crest Pool	6	East Parking Lot & Front Loop	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles. Resurface stalls and access aisles to eliminate gaps and cracks.	\$1,448.13	2	each	\$2,896.26	1
Aqua Crest Pool	7	East Parking Lot & Front Loop	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Aqua Crest Pool	8	South Parking Lot	Parking - Off Street	Add van parking sign to an accessible stall and repaint stall and access aisle to 12' and 5'. Paint pricing addressed in a different finding.	\$210.00	1	each	\$210.00	1
Aqua Crest Pool	9	South Parking Lot	Parking - Off Street	Repaint access aisles to be 5' each. Pricing addressed in a different finding.	\$0.00	1	each	\$0.00	1
Aqua Crest Pool	10	South Parking Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Aqua Crest Pool	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Aqua Crest Pool	13	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%. For all doors along the public circulation route, widen doors to 36" for recessed doors. For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$5,834.50	1	each	\$5,834.50	1
Aqua Crest Pool	14	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Aqua Crest Pool	15	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Aqua Crest Pool	16	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Aqua Crest Pool	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Aqua Crest Pool	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Aqua Crest Pool	19	Exterior Accessible Route	Accessible Routes	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice.	\$367.50	1	each	\$367.50	5
Aqua Crest Pool	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Aqua Crest Pool	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Aqua Crest Pool	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
Aqua Crest Pool	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Aqua Crest Pool	24	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	7	each	\$673.75	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	25	Deck	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	2
Aqua Crest Pool	26	Deck	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	2
Aqua Crest Pool	27	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	2
Aqua Crest Pool	28	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	2
Aqua Crest Pool	29	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	2
Aqua Crest Pool	30	Deck	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	2
Aqua Crest Pool	31	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	2
Aqua Crest Pool	32	Deck	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	2
Aqua Crest Pool	33	Deck	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Aqua Crest Pool	34	Common Areas	Clear Floor Space	Remove, or relocate storage in CGS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	35	Common Areas	Outdoor - Constructed Features (C)	Relocate table to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Aqua Crest Pool	37	Common Areas	Toilet and Bathing Rooms	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held, in the alternative, install a fixed shower head at 48" agl.  Provide level clear ground space (CGS) at shower.  Correct or fill 1" gap in shower CGS.	\$3,699.50	2	each	\$7,399.00	2
Aqua Crest Pool	38	Common Areas	Assembly Areas	Repair landing at accessible seating to be level or no more than 2.08% slope in any direction and free of gaps and CIL	\$1,470.00	2	each	\$2,940.00	2
Aqua Crest Pool	40	Common Areas	Picnic Tables (C)	Replace or add picnic table of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Aqua Crest Pool	41	Common Areas	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4"	\$420.00	1	each	\$420.00	2
Aqua Crest Pool	42	Common Areas	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Aqua Crest Pool	43	Pool	Pool / Spa	Anchor pool lift when pool is open in compliant location where water level does not exceed 48".	\$600.00	1	each	\$600.00	2
Aqua Crest Pool	44	Pool	Pool / Spa	Train staff to keep batteries charged, and to install batteries in the lift for all hours the pool is open to allow for independent operation.	\$0.00	1	staff time	\$0.00	2
Aqua Crest Pool	45	Pool	Pool / Spa	Relocate pool lift to an area providing required slopes and correct distance from pool edge.	\$0.00	1	staff time	\$0.00	2
Aqua Crest Pool	46	Pool	Pool / Spa	Install a second means of entry to the pool such as a transfer wall, stairs or a transfer system.	\$7,140.00	1	each	\$7,140.00	2
Aqua Crest Pool	47	Pool	Pool / Spa	Provide additional handrail at one set of pool stairs, mounted 20" to 24" apart from existing handrail.	\$980.00	1	each	\$980.00	2
Aqua Crest Pool	48	Pool	Pool / Spa	Create a sloped entry into wading pool if feasible.	\$6,510.00	1	each	\$6,510.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	49	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	50	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Aqua Crest Pool	51	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Lower sink in main area to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Aqua Crest Pool	52	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	53	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Aqua Crest Pool	54	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace one urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Aqua Crest Pool	55	Men's Locker Room/Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Leave as is baby changer citing construction tolerance.	\$350.00	2	each	\$700.00	1
Aqua Crest Pool	56	Men's Locker Room/Restroom	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	1
Aqua Crest Pool	57	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Aqua Crest Pool	58	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Aqua Crest Pool	59	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Aqua Crest Pool	60	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Aqua Crest Pool	61	Men's Locker Room/Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Aqua Crest Pool	62	Men's Locker Room/Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	3	each	\$9,187.50	1
Aqua Crest Pool	63	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" above the finished floor (AFF).	\$420.00	2	each	\$840.00	1
Aqua Crest Pool	64	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	65	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space (CFS) on the short axis of the bench.	\$840.00	1	each	\$840.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	66	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the shower, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
Aqua Crest Pool	67	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the shower, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
Aqua Crest Pool	68	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the roll in shower.	\$467.25	1	each	\$467.25	2
Aqua Crest Pool	69	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	1
Aqua Crest Pool	70	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	2
Aqua Crest Pool	71	Men's Locker Room/Restroom	Doors	Install hardware on both sides of shower compartment door that is operable without a tight pinch or grasp.	\$420.00	1	each	\$420.00	1
Aqua Crest Pool	72	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Aqua Crest Pool	73	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Enlarge dressing stalls to 60" by 60" clear inside dimension.	\$1,036.00	1	each	\$1,036.00	1
Aqua Crest Pool	74	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space (CFS) on the short axis of the bench.	\$840.00	1	each	\$840.00	1
Aqua Crest Pool	75	Men's Locker Room/Restroom	Room/Space (C)	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
Aqua Crest Pool	76	Men's Locker Room/Restroom	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Aqua Crest Pool	77	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Aqua Crest Pool	78	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Replace one mirror not over a sink or counter and mount to max 35" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Aqua Crest Pool	79	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace faucet controls with lever controls operable with max force of 5lbs.  Lower sinks in main area to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$735.00	2	each	\$1,470.00	1
Aqua Crest Pool	80	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	81	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	2	each	\$154.00	1
Aqua Crest Pool	82	Women's Locker Room/Restroom	Reach Ranges	Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.  Leave as is dryers citing construction tolerance.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	83	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	\$5,510.75	1	each	\$5,510.75	1
Aqua Crest Pool	84	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	85	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Aqua Crest Pool	86	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Aqua Crest Pool	87	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Reconfigure plumbing to be min 1.5" below rear grab bar; leave as is if location of pipes required by another code and provide split grab bar.	\$393.75	1	each	\$393.75	1
Aqua Crest Pool	88	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	2	each	\$591.50	1
Aqua Crest Pool	89	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	2	each	\$420.00	1
Aqua Crest Pool	90	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Aqua Crest Pool	91	Women's Locker Room/Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	4	each	\$1,400.00	1
Aqua Crest Pool	92	Women's Locker Room/Restroom	Accessible Routes	Ensure floors to be firm, stable and slip resistant.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	93	Women's Locker Room/Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Aqua Crest Pool	94	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	95	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
Aqua Crest Pool	96	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Acquire and mount grab bars to the correct location in the shower, mounted 33" to 36" above the finished floor (AFF) and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
Aqua Crest Pool	97	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the roll in shower.	\$467.25	1	each	\$467.25	2
Aqua Crest Pool	98	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Aqua Crest Pool	99	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	2
Aqua Crest Pool	100	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.  Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Aqua Crest Pool	101	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.  Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	102	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Enlarge one dressing stalls to 60" by 60" clear inside dimension.	\$1,036.00	1	each	\$1,036.00	1
Aqua Crest Pool	103	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace bench in new accessible dressing room with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
Aqua Crest Pool	104	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Remount hook in new accessible dressing room to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	105	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" above the finished floor (AFF).	\$420.00	2	each	\$840.00	5
Aqua Crest Pool	106	Women's Locker Room/Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	1
Aqua Crest Pool	107	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	108	Pool Area Offices	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Aqua Crest Pool	109	Pool Area Offices	Room/Space (C)	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	2	each	\$1,029.00	3
Aqua Crest Pool	110	Pool Area Offices	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$2,135.00	1	each	\$2,135.00	3
Aqua Crest Pool	111	Pool Area Offices	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	3
Aqua Crest Pool	112	Pool Area Offices	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised lettering, mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	113	Pool Area Offices	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p>	\$2,772.50	1	each	\$2,772.50	3
Aqua Crest Pool	114	Pool Area Offices	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, provide beveled threshold.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>For all doors/gates along the public circulation route, remount hardware at 34 inches minimum and 48 inches maximum above the finish floor or ground.</p>	\$1,555.75	1	each	\$1,555.75	3
Aqua Crest Pool	115	Weight Room Building Offices	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$3,287.00	1	each	\$3,287.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	116	Weight Room Building Offices	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	3
Aqua Crest Pool	117	Weight Room Building Offices	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Aqua Crest Pool	118	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF. In the alternative, leave as is citing construction tolerance	\$1,099.00	1	each	\$1,099.00	4
Aqua Crest Pool	119	Public Spaces	Signs	Remount signage to min 40" AFF.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	120	Play Area, 2-5	Play Area	Leave as is play area surface until new play area is installed.	\$0.00	1	each	\$0.00	4
Aqua Crest Pool	121	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,574.13	2	each	\$3,148.26	1
Aqua Crest Pool	122	Public Spaces	Exercise Equipment	Relocate obstacles to create route to one of each type of exercise equipment.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	123	Public Spaces	Exercise Equipment	Create a 30" by 48" "parking space" next to one of each type of fitness equipment offered in the center.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	124	Public Spaces	Accessible Routes	Relocate obstacles to create an accessible route (AR) through indicated rooms.	\$0.00	1	staff time	\$0.00	1
Aqua Crest Pool	125	Public Spaces	Accessible Routes	Secure mats to floor.	\$140.00	1	each	\$140.00	1
Aqua Crest Pool	126	Public Spaces	Accessible Routes	Tape or bevel a 36" wide portion of the mats to provide a designated entry to the mat area.  Replace mat with one having max pile or edge of 1/4".  Secure mats to prevent trip hazard.	\$140.00	10	each	\$1,400.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Aqua Crest Pool	127	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR)	\$0.00	1	staff time	\$0.00	1
<a href="#">Belvedere Heights Park</a>	2	Playground	Play Area	Fill and compact EWF surface so that it becomes level with adjacent surfaces	\$0.00	1	staff time	\$0.00	2
Belvedere Heights Park	3	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2
Belvedere Heights Park	4	Playground	Play Area	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same	\$0.00	1	staff time	\$0.00	2
Belvedere Heights Park	7	Playground	Play Area	Lower or adjust entry point to play component to 11" to 24" aff	\$350.00	1	each	\$350.00	2
Belvedere Heights Park	9	Park Elements	Plumbing Fixtures & Elements	Remount fountain to provide centered clear floor space.	\$2,380.00	1	each	\$2,380.00	2
Belvedere Heights Park	10	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Belvedere Heights Park	11	Park Elements	Outdoor - Constructed Features (C)	Fill and compact EWF surface so that it becomes level with adjacent surfaces.	\$0.00	1	staff time	\$0.00	5
<a href="#">Bert Winters Park</a>	2	Parking	Parking - Off Street	Relocate at least 1 accessible space to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Bert Winters Park	3	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Bert Winters Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	9	each	\$27,562.50	1
Bert Winters Park	5	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs, including penalty information, for all the stalls.	\$210.00	2	each	\$420.00	1
Bert Winters Park	6	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	5	staff time	\$0.00	1
Bert Winters Park	7	Parking	Parking - Off Street	Add one van parking sign to one standard-sized and one over-sized accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Bert Winters Park	8	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Bert Winters Park	9	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	12	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Bert Winters Park	13	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Bert Winters Park	14	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Bert Winters Park	15	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Bert Winters Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Bert Winters Park	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Bert Winters Park	19	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Bert Winters Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Bert Winters Park	21	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Bert Winters Park	22	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Bert Winters Park	24	Sports Fields/Courts	Assembly Areas	Correct or fill gaps to max .5".	\$96.25	2	each	\$192.50	2
Bert Winters Park	25	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	45	lin ft	\$2,664.00	2
Bert Winters Park	26	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Bert Winters Park	27	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County baseball fields accessible.	\$59.20	45	lin ft	\$2,664.00	4
Bert Winters Park	28	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County baseball fields accessible.	\$59.20	45	lin ft	\$2,664.00	4
Bert Winters Park	30	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  Establish protocols for regular and frequent inspection and maintenance of walkway and door clearance surfaces.	\$1,531.25	2	each	\$3,062.50	2
Bert Winters Park	31	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	230	lin ft	\$13,616.00	4
Bert Winters Park	32	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR.  Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Bert Winters Park	33	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR.  Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Bert Winters Park	34	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Bert Winters Park	35	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. Replace picnic table with one of an accessible design as a smart practice.	\$4,672.00	1	each	\$4,672.00	5
Bert Winters Park	36	Park Elements	Accessible Routes	Relocate garbage can to be along AR. In the alternative, leave as is as others are accessible.	\$0.00	1	staff time	\$0.00	4
Bert Winters Park	37	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Bert Winters Park	38	Park Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$0.00	1	staff time	\$0.00	5
Bert Winters Park	39	Park Elements	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain.	\$5,598.25	1	each	\$5,598.25	2
Bert Winters Park	40	Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Bert Winters Park	41	Boat Ramp	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Bert Winters Park	42	Boat Ramp	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	2
Bert Winters Park	43	Boat Ramp	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Bert Winters Park	44	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Bert Winters Park	45	Playground	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs.  Pricing provided in a previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Bert Winters Park	47	Playground	Play Area	Provide an AR to element for one of each type accessible.  Pricing for surface correction in a previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Bert Winters Park	48	Playground	Play Area	Make corrections to surface to meet incentive scoping.  Price included in earlier finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Bert Winters Park	49	Ball Field - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Bert Winters Park	50	Ball Field - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Bert Winters Park	51	Ball Field - Men's Restroom	Clear Floor Space	Relocate soap dispenser to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	52	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Bert Winters Park	53	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Bert Winters Park	54	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Bert Winters Park	55	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Bert Winters Park	56	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
Bert Winters Park	57	Ball Field - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	58	Ball Field - Men's Restroom	Accessible Routes	Raise overhead partition support to min 80", or pad object to prevent hazard in overhead clearance along AR.	\$140.00	1	each	\$140.00	1
Bert Winters Park	59	Ball Field - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	60	Ball Field - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	61	Ball Field - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Bert Winters Park	62	Ball Field - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Bert Winters Park	63	Ball Field - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Bert Winters Park	64	Ball Field - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Bert Winters Park	65	Ball Field - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	66	Ball Field - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	67	Ball Field - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	68	Ball Field - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Bert Winters Park	69	Boat Ramp - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top in main area.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	70	Boat Ramp - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. Leave as is sink in stall citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	1
Bert Winters Park	71	Boat Ramp - Men's Restroom	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of restroom floor surface.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	72	Boat Ramp - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Bert Winters Park	73	Boat Ramp - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	74	Boat Ramp - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Bert Winters Park	75	Boat Ramp - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	76	Boat Ramp - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Bert Winters Park	77	Boat Ramp - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	78	Boat Ramp - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Bert Winters Park	79	Boat Ramp - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	80	Boat Ramp - Women's Restroom	Plumbing Fixtures & Elements	Lower one sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Bert Winters Park	81	Boat Ramp - Women's Restroom	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	82	Boat Ramp - Women's Restroom	Toilet and Bathing Rooms	Correct door alignment so door closes fully.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door, mounted 34" to 48" aff.  All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open.	\$420.00	1	each	\$420.00	1
Bert Winters Park	83	Boat Ramp - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	84	Boat Ramp - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Bert Winters Park	85	Boat Ramp - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	86	Boat Ramp - All Gender Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	87	Boat Ramp - All Gender Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Bert Winters Park	88	Boat Ramp - All Gender Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	89	Boat Ramp - All Gender Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Bert Winters Park	90	Boat Ramp - All Gender Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Relocate hand dryer to an area out of the door clearance and where it won't protrude into the circulation path.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$350.00	1	each	\$350.00	1
Bert Winters Park	91	Public Spaces	Custom/Special	Ensure renovated boat dock is fully compliant.	\$0.00	1	staff time	\$0.00	1
Bert Winters Park	92	Public Spaces	Custom/Special	Ensure new facility is fully compliant.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
<u>Burt Aaronson South County Regional</u>	2	Osprey Point Golf Course - Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	3	Osprey Point Golf Course - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
Burt Aaronson South County Regional	4	Osprey Point Golf Course - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Burt Aaronson South County Regional	5	Osprey Point Golf Course - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. Leave as is stall slopes of 2.2% citing construction tolerance.	\$3,062.50	7	each	\$21,437.50	1
Burt Aaronson South County Regional	6	Osprey Point Golf Course - Parking	Parking - Off Street	Correct or fill gap to .5" max.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	7	Osprey Point Golf Course - Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	8	Osprey Point Golf Course - Parking	Parking - Off Street	Add one van parking sign to two accessible stalls and ensure stalls and access aisles are 12' and 5'.	\$210.00	2	each	\$420.00	1
Burt Aaronson South County Regional	9	Osprey Point Golf Course - EAR	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	40	lin ft	\$2,368.00	2
Burt Aaronson South County Regional	10	Osprey Point Golf Course - EAR	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Burt Aaronson South County Regional	11	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Burt Aaronson South County Regional	12	Osprey Point Golf Course - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	13	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Burt Aaronson South County Regional	14	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Burt Aaronson South County Regional	15	Osprey Point Golf Course - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	16	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	17	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	18	Osprey Point Golf Course - EAR	Accessible Routes	Replace mat or carpet with one having max pile or edge of 1/4".	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	19	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Burt Aaronson South County Regional	20	Osprey Point Golf Course - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	21	Osprey Point Golf Course - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	23	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	24	Osprey Point Golf Course - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	25	Osprey Point Golf Course - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	26	Osprey Point Golf Course - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	27	Osprey Point Golf Course - EAR	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Aaronson South County Regional	29	Osprey Golf Course - Don Law Golf Academy Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	30	Osprey Golf Course - Don Law Golf Academy Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate changes in level, gaps, and cracks.	\$2,800.00	1	each	\$2,800.00	1
Burt Aaronson South County Regional	31	Osprey Golf Course - Don Law Golf Academy Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	32	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Burt Aaronson South County Regional	33	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	3
Burt Aaronson South County Regional	34	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Burt Aaronson South County Regional	35	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Relocate sculpture and shoe cleaner from landings on ramp where directions change.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	36	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	3
Burt Aaronson South County Regional	37	Osprey Point Golf Course - Driving Range/Practice Facilities	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface.	\$980.00	1	each	\$980.00	3
Burt Aaronson South County Regional	38	Osprey Point Golf Course - Driving Range/Practice Facilities	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Burt Aaronson South County Regional	39	Osprey Point Golf Course - Driving Range/Practice Facilities	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	40	Osprey Point Golf Course - Driving Range/Practice Facilities	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	42	Osprey Point Golf Course - Driving Range/Practice Facilities	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Burt Aaronson South County Regional	43	Osprey Point Golf Course - Driving Range/Practice Facilities	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Burt Aaronson South County Regional	44	Osprey Point Golf Course - Driving Range/Practice Facilities	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (grills, garbage, water spigots). Replace one picnic table with one of an accessible design as a smart practice.	\$3,784.00	1	each	\$3,784.00	5
Burt Aaronson South County Regional	45	Osprey Point Golf Course - Driving Range/Practice Facilities	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	47	Osprey Point Golf Course - Driving Range/Practice Facilities	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	48	Osprey Point Golf Course - Driving Range/Practice Facilities	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	49	Osprey Point Golf Course - Driving Range/Practice Facilities	Toilet and Bathing Rooms	Relocate garbage can and shelf to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	50	Osprey Point Golf Course - Driving Range/Practice Facilities	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Burt Aaronson South County Regional	51	Osprey Point Golf Course - Driving Range/Practice Facilities	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	52	Osprey Point Golf Course - Driving Range/Practice Facilities	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	53	Osprey Point Golf Course - Driving Range/Practice Facilities	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	54	Osprey Point Golf Course - Driving Range/Practice Facilities	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	55	Osprey Point Golf Course - Driving Range/Practice Facilities	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	56	Osprey Point Golf Course - Driving Range/Practice Facilities	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	57	Osprey Point Golf Course - Driving Range/Practice Facilities	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$2,868.75	1	each	\$2,868.75	1
Burt Aaronson South County Regional	58	Osprey Point Golf Course - Driving Range/Practice Facilities	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Aaronson South County Regional	63	Osprey Point Golf Course - Driving Range/Practice Facilities	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	65	Osprey Point Golf Course - Driving Range/Practice Facilities	Doors	Correct or fill gap to max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	66	Osprey Point Golf Course - Driving Range/Practice Facilities	Doors	Replace doors with doors having 80" overhead clearance.	\$2,772.50	1	each	\$2,772.50	1
Burt Aaronson South County Regional	67	Osprey Point Golf Course - Driving Range/Practice Facilities	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	68	Osprey Point Golf Course - Driving Range/Practice Facilities	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	69	Osprey Point Golf Course - The Nest Eatery	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$280.00	1	each	\$280.00	1
Burt Aaronson South County Regional	70	Osprey Point Golf Course - The Nest Eatery	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.	\$140.00	1	each	\$140.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	71	Osprey Point Golf Course - The Nest Eatery	Kitchens, Kitchenettes, And Wet Bars	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	\$3,360.00	1	each	\$3,360.00	1
Burt Aaronson South County Regional	72	Osprey Point Golf Course - The Nest Eatery	Accessible Routes	Relocate kitchen items and equipment to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	73	Osprey Point Golf Course - The Nest Eatery	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	74	Osprey Point Golf Course - The Nest Eatery	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	76	Osprey Point Golf Course - The Nest Eatery	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$140.00	1	each	\$140.00	3
Burt Aaronson South County Regional	77	Osprey Point Golf Course - The Nest Eatery	Dining, Bar and Work Surfaces	Replace 5% of the tables in each of the three dining areas (bar, indoor tables, patio seating) with ones providing the required knee and toe clearances.	\$1,120.00	3	each	\$3,360.00	1
Burt Aaronson South County Regional	78	Osprey Point Golf Course - The Nest Eatery	Restaurants/Cafeterias (C)	Relocate self service items to an area providing CFS and correct reach range for users in mobility devices.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	79	Osprey Point Golf Course - The Nest Eatery	Accessible Routes	Correct service counter to be 36" AFF and correct width based on approach.	\$747.25	1	each	\$747.25	1
Burt Aaronson South County Regional	81	Osprey Point Golf Course - The Nest Eatery	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Aaronson South County Regional	82	Osprey Point Golf Course - The Nest Eatery	Room/Space (C)	Fill gaps at door entries to max .5".	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	83	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	84	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Toilet and Bathing Rooms	Raise mirror not over a sink or counter to max 35" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	85	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Burt Aaronson South County Regional	86	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at mirror.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	87	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF), with a min 12" clearance above or 1.5" clearance below grab bar.  In the alternative, replace flush controls with one that allows min 1.5" clearance below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	88	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	89	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	90	Osprey Point Golf Course - The Nest Eatery - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	91	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Toilet and Bathing Rooms	Raise mirror not over a sink or counter to max 35" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	92	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Burt Aaronson South County Regional	93	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at mirror.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	94	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	95	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	96	Osprey Point Golf Course - The Nest Eatery - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	97	Osprey Point Golf Course - Proshop	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$280.00	1	sq ft	\$280.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	100	Osprey Point Golf Course - Proshop	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	101	Osprey Point Golf Course - Proshop	Accessible Routes	Relocate or reposition merchandise to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	102	Osprey Point Golf Course - Proshop	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	103	Osprey Point Golf Course - Proshop	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	104	Osprey Point Golf Course - Proshop	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	105	Osprey Point Golf Course - Proshop	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	106	Osprey Point Golf Course - Proshop	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	107	Osprey Point Golf Course - Proshop	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	108	Osprey Point Golf Course - Proshop	Accessible Routes	Widen AR to compliant 36" clear width	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	109	Osprey Point Golf Course - Proshop	Turning Space	Relocate obstacles to create turning space in room.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	110	Osprey Point Golf Course - Proshop	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	111	Osprey Point Golf Course - Proshop	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	112	Osprey Point Golf Course - Proshop	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	113	Osprey Point Golf Course - Proshop	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	114	Osprey Point Golf Course - Proshop	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	115	Osprey Point Golf Course - Proshop	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	117	Osprey Point Golf Course - Proshop	Clear Floor Space	Relocate shoe cleaner along an accessible route with level CFS with max slope of 2.08%.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	118	Osprey Point Golf Course - Proshop	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
Burt Aaronson South County Regional	119	Osprey Point Golf Course - Proshop	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	120	Osprey Point Golf Course - Proshop	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	121	Osprey Point Golf Course - Proshop	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	122	Osprey Point Golf Course - Proshop	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.	\$140.00	1	each	\$140.00	3
Burt Aaronson South County Regional	123	Osprey Point Golf Course - Proshop	Sales and Service Counters/Tables	Relocate storage to provide clear 36" wide lowered counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	124	Osprey Point Golf Course - Proshop	Clear Floor Space	Relocate bench along an accessible route with level CFS with max slope of 2.08%.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	125	Osprey Point Golf Course - Pro Shop Women's Restroom	Toilet and Bathing Rooms	Raise mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	126	Osprey Point Golf Course - Pro Shop Women's Restroom	Toilet and Bathing Rooms	Raise mirror not over a sink or counter to max 35" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	127	Osprey Point Golf Course - Pro Shop Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	128	Osprey Point Golf Course - Pro Shop Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	129	Osprey Point Golf Course - Pro Shop Women's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	130	Osprey Point Golf Course - Pro Shop Men's Restroom	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	131	Osprey Point Golf Course - Pro Shop Men's Restroom	Toilet and Bathing Rooms	Raise mirror not over a sink or counter to max 35" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	132	Osprey Point Golf Course - Pro Shop Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Burt Aaronson South County Regional	133	Osprey Point Golf Course - Pro Shop Men's Restroom	Toilet and Bathing Rooms	Relocate items stored on grab bar, and remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	134	Osprey Point Golf Course - Pro Shop Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	135	Osprey Point Golf Course - Pro Shop Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	139	Osprey Point Golf Course - Raven	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	142	Osprey Point Golf Course - Falcon	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Burt Aaronson South County Regional	143	Osprey Point Golf Course - Hawk	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Burt Aaronson South County Regional	144	Osprey Point Golf Course - Hawk	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	2
Burt Aaronson South County Regional	147	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	148	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	149	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Toilet and Bathing Rooms	Relocate trash can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	150	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	151	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	152	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 2	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48".	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	153	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	154	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	155	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	156	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	157	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	158	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 2	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48".	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	160	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	161	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	162	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	163	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	164	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	165	Osprey Point Golf Course - Comfort Station on Raven, men's restroom near Hole 8	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	166	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	167	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	168	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	169	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Toilet and Bathing Rooms	Relocate storage to provide clearance min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	170	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	171	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	172	Osprey Golf Course - Comfort Station On Raven, women's restroom near Hole 8	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48".	\$514.50	1	each	\$514.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	174	Osprey Point Golf Course - Cart Barn	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$4,702.25	1	each	\$4,702.25	3
Burt Aaronson South County Regional	176	Osprey Point Golf Course - Maintenance Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	177	Osprey Point Golf Course - Maintenance Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	178	Osprey Point Golf Course - Maintenance Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	179	Osprey Point Golf Course - Maintenance Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Burt Aaronson South County Regional	180	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 2 lockers as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	2	each	\$840.00	2
Burt Aaronson South County Regional	181	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	2	each	\$840.00	2
Burt Aaronson South County Regional	182	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Burt Aaronson South County Regional	183	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Enlarge shower stall, if feasible, to compliant dimensions for a roll in shower of 30" deep by 60" wide with a 60" opening.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	184	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the roll in shower.	\$467.25	1	each	\$467.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	185	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	186	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	187	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	188	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	189	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Toilet and Bathing Rooms	Relocate storage from grab bars and remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	190	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	191	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	192	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	193	Osprey Point Golf Course - Maintenance - Men's Restroom and Locker Room	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	195	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF. Mount shelves between 15" and 48" AFF.	\$420.00	2	each	\$840.00	2
Burt Aaronson South County Regional	196	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Burt Aaronson South County Regional	197	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Enlarge shower stall, if feasible, to compliant dimensions for a roll in shower of 30" deep by 60" wide with a 60" opening.	\$5,498.50	1	each	\$5,498.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	198	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the roll in shower.	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	199	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	200	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower. Pricing in another finding for seat.	\$0.00	1	N/A	\$0.00	2
Burt Aaronson South County Regional	201	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Leave sink as is, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	202	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	203	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	204	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	205	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	206	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	207	Osprey Point Golf Course - Maintenance - Women's Restroom and Locker Room	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	209	Osprey Point Golf Course - Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.	\$140.00	1	each	\$140.00	3
Burt Aaronson South County Regional	210	Osprey Point Golf Course - Maintenance	Accessible Routes	Relocate or reposition chairs and table to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	211	Osprey Point Golf Course - Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	212	Osprey Point Golf Course - Maintenance	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	213	Osprey Point Golf Course - Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	214	Osprey Point Golf Course - Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	215	Osprey Point Golf Course - Maintenance	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	216	Osprey Point Golf Course - Maintenance	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	217	Osprey Point Golf Course - Maintenance	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	218	Osprey Point Golf Course - Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	219	Osprey Point Golf Course - Maintenance	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	220	Osprey Point Golf Course - Maintenance	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
Burt Aaronson South County Regional	221	Osprey Point Golf Course - Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$3,158.75	1	each	\$3,158.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	222	Osprey Point Golf Course - Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$4,908.75	1	each	\$4,908.75	1
Burt Aaronson South County Regional	223	Osprey Point Golf Course - Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$654.50	1	each	\$654.50	3
Burt Aaronson South County Regional	224	Osprey Point Golf Course - Maintenance	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	226	Osprey Point Golf Course - Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	227	Osprey Point Golf Course - Maintenance	Accessible Routes	Secure rug to prevent trip hazard.	\$280.00	1	each	\$280.00	1
Burt Aaronson South County Regional	228	Osprey Point Golf Course - Maintenance	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	229	Osprey Point Golf Course - Maintenance	Doors	Repair, bevel or ramp CIL at doorway.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	230	Osprey Point Golf Course - Maintenance	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	232	Sunset Cove Amphitheater - Main Parking Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
Burt Aaronson South County Regional	233	Sunset Cove Amphitheater - Main Parking Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Burt Aaronson South County Regional	234	Sunset Cove Amphitheater - Main Parking Lot	Parking - Off Street	Add two van parking signs to two accessible stalls and ensure stalls and access aisles are 12' and 5'.	\$210.00	2	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	235	Sunset Cove Amphitheater - Main Parking Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	16	each	\$1,176.00	1
Burt Aaronson South County Regional	236	Sunset Cove Amphitheater - Vendor Parking	Parking - Off Street	Create one or more 12' accessible trailer/RV parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Burt Aaronson South County Regional	237	Sunset Cove Amphitheater - Vendor Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	238	Sunset Cove Amphitheater - Vendor Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	239	Sunset Cove Amphitheater - Vendor Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	240	Sunset Cove Amphitheater - Vendor Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Burt Aaronson South County Regional	242	Sunset Cove Amphitheater - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	243	Sunset Cove Amphitheater - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	244	Sunset Cove Amphitheater - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	245	Sunset Cove Amphitheater - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	246	Sunset Cove Amphitheater - EAR	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,015.00	1	each	\$1,015.00	1
Burt Aaronson South County Regional	247	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Burt Aaronson South County Regional	248	Sunset Cove Amphitheater - EAR	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Aaronson South County Regional	251	Sunset Cove Amphitheater - EAR	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	253	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Burt Aaronson South County Regional	254	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	1
Burt Aaronson South County Regional	255	Sunset Cove Amphitheater - EAR	Shelters, Picnic Facilities (C)	Add an accessible picnic table to the two shelters with routes; in the alternative, create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to two shelters with tables.	\$1,120.00	2	each	\$2,240.00	5
Burt Aaronson South County Regional	256	Sunset Cove Amphitheater - EAR	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	7	each	\$673.75	5
Burt Aaronson South County Regional	257	Sunset Cove Amphitheater - EAR	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	258	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Burt Aaronson South County Regional	259	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	260	Sunset Cove Amphitheater - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	262	Sunset Cove Amphitheater - EAR	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Burt Aaronson South County Regional	263	Sunset Cove Amphitheater - EAR	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Burt Aaronson South County Regional	264	Sunset Cove Amphitheater - EAR	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Burt Aaronson South County Regional	265	Sunset Cove Amphitheater - EAR	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Burt Aaronson South County Regional	266	Sunset Cove Amphitheater - EAR	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	3
Burt Aaronson South County Regional	267	Sunset Cove Amphitheater - EAR	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	1	each	\$875.00	3
Burt Aaronson South County Regional	268	Sunset Cove Amphitheater - EAR	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Burt Aaronson South County Regional	269	Sunset Cove Amphitheater - EAR	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	6	each	\$750.00	5
Burt Aaronson South County Regional	270	Sunset Cove Amphitheater - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	271	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	440	sq ft	\$53,900.00	1
Burt Aaronson South County Regional	272	Sunset Cove Amphitheater - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	273	Sunset Cove Amphitheater - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	274	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	1
Burt Aaronson South County Regional	275	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	700	sq ft	\$85,750.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	276	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	595	sq ft	\$72,887.50	3
Burt Aaronson South County Regional	277	Sunset Cove Amphitheater - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	278	Sunset Cove Amphitheater - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$3,500.00	1	each	\$3,500.00	3
Burt Aaronson South County Regional	279	Sunset Cove Amphitheater - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	280	Sunset Cove Amphitheater - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3
Burt Aaronson South County Regional	281	Sunset Cove Amphitheater - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".	\$2,868.75	1	each	\$2,868.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	282	Sunset Cove Amphitheater - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	284	Sunset Cove Amphitheater - Public Spaces	Assembly Areas	<p>Provide required amount of accessible seats as required in section 221.2 based on the capacity of the amphitheater.</p> <p>If renters or vendors are responsible for providing the accessible seating, ensure that each contract addresses this requirement.</p>	\$629.50	41	each	\$25,809.50	3
Burt Aaronson South County Regional	286	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Stairways	<p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	10	each	\$1,250.00	1
Burt Aaronson South County Regional	287	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Stairways	Replace or repair handrails to provide a smooth surface	\$980.00	1	each	\$980.00	1
Burt Aaronson South County Regional	288	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Room/Space (C)	<p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace mat or carpet with one having max pile or edge of 1/4".</p>	\$1,890.00	1	each	\$1,890.00	3
Burt Aaronson South County Regional	289	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Doors	Secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	291	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Doors	<p>For all doors/gates along the public circulation route, provide beveled threshold.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p>	\$253.75	1	each	\$253.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	292	Sunset Cove Amphitheater - Stage/Production Areas/Loading Dock	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	293	Sunset Cove Amphitheater - Dressing Rooms	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	294	Sunset Cove Amphitheater - Dressing Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	295	Sunset Cove Amphitheater - Dressing Rooms	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	296	Sunset Cove Amphitheater - Dressing Rooms	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	297	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Relocate trash can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	298	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	299	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	300	Sunset Cove Amphitheater - Dressing Rooms	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	301	Sunset Cove Amphitheater - Dressing Rooms	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Burt Aaronson South County Regional	302	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	303	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Remount shower controls to max 48".	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	304	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Replace grab bars with ones providing 1.5" gap between bar and wall and mount so no objects interfere within 1.5" below and 12" above bar.	\$603.75	1	each	\$603.75	2
Burt Aaronson South County Regional	305	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Repair shower seat so seat height is in a compliant range.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	306	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$0.00	1	N/A	\$0.00	2
Burt Aaronson South County Regional	308	Sunset Cove Amphitheater - Dressing Rooms	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	1	each	\$1,750.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	309	Sunset Cove Amphitheater - Dressing Rooms	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	310	Sunset Cove Amphitheater - Dressing Rooms	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	311	Sunset Cove Amphitheater - Dressing Rooms	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	312	Sunset Cove Amphitheater - Dressing Rooms	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	313	Sunset Cove Amphitheater - Dressing Rooms	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	314	Sunset Cove Amphitheater - Dressing Rooms	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	315	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	316	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Remount diverter controls to max 48".	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	317	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF.	\$393.75	1	each	\$393.75	2
Burt Aaronson South County Regional	318	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Repair shower seat so seat height is in a compliant range.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	319	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Relocate items to provide 18" by 18" CFS centered on the sign.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	320	Sunset Cove Amphitheater - Dressing Rooms	Plumbing Fixtures & Elements	Provide required 30" X 48" CFS at accessible sinks.	\$2,100.00	1	each	\$2,100.00	1
Burt Aaronson South County Regional	321	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	322	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	323	Sunset Cove Amphitheater - Dressing Rooms	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	324	Sunset Cove Amphitheater - Dressing Rooms	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	325	Sunset Cove Amphitheater - Dressing Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	326	Sunset Cove Amphitheater - Dressing Rooms	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	327	Sunset Cove Amphitheater - Dressing Rooms	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	328	Sunset Cove Amphitheater - Dressing Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	329	Sunset Cove Amphitheater - Dressing Rooms	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	330	Sunset Cove Amphitheater - Dressing Rooms	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	331	Sunset Cove Amphitheater - Dressing Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	332	Sunset Cove Amphitheater - Dressing Rooms	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	333	Sunset Cove Amphitheater - Restroom By Production Office	Toilet and Bathing Rooms	Acquire and mount signage, including access symbol.  Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	334	Sunset Cove Amphitheater - Restroom By Production Office	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	335	Sunset Cove Amphitheater - Restroom By Production Office	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	336	Sunset Cove Amphitheater - Restroom By Production Office	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	337	Sunset Cove Amphitheater - Restroom By Production Office	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	338	Sunset Cove Amphitheater - Restroom By Production Office	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	339	Sunset Cove Amphitheater - Restroom By Production Office	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	340	Sunset Cove Amphitheater - North Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	341	Sunset Cove Amphitheater - North Men's Restroom	Plumbing Fixtures & Elements	Leave as is sink, citing construction tolerance.	\$0.00	1	N/A	\$0.00	4
Burt Aaronson South County Regional	342	Sunset Cove Amphitheater - North Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	343	Sunset Cove Amphitheater - North Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	344	Sunset Cove Amphitheater - North Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	345	Sunset Cove Amphitheater - North Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	346	Sunset Cove Amphitheater - North Women's Restroom	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	347	Sunset Cove Amphitheater - North Women's Restroom	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	2	N/A	\$0.00	4
Burt Aaronson South County Regional	348	Sunset Cove Amphitheater - North Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	349	Sunset Cove Amphitheater - North Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	350	Sunset Cove Amphitheater - North Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	351	Sunset Cove Amphitheater - North Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	352	Sunset Cove Amphitheater - North Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	353	Sunset Cove Amphitheater - North Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	354	Sunset Cove Amphitheater - South Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	355	Sunset Cove Amphitheater - South Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	356	Sunset Cove Amphitheater - South Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and in accessible stall.	\$77.00	2	each	\$154.00	1
Burt Aaronson South County Regional	357	Sunset Cove Amphitheater - South Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	358	Sunset Cove Amphitheater - South Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	359	Sunset Cove Amphitheater - South Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	360	Sunset Cove Amphitheater - South Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	361	Sunset Cove Amphitheater - South Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	362	Sunset Cove Amphitheater - South Men's Restroom	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	363	Sunset Cove Amphitheater - South Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	364	Sunset Cove Amphitheater - South Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	365	Sunset Cove Amphitheater - South Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	366	Sunset Cove Amphitheater - South Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	367	Sunset Cove Amphitheater - South Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	368	Sunset Cove Amphitheater - South Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	369	Sunset Cove Amphitheater - South Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	370	Sunset Cove Amphitheater - South Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	371	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	372	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  Replace mat or carpet with one having max pile or edge of 1/4".	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	373	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Burt Aaronson South County Regional	374	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	375	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Remount shower diverter controls to the correct location in the transfer shower, max 48".	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	376	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF.	\$393.75	1	each	\$393.75	2
Burt Aaronson South County Regional	377	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	378	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	379	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Clear Floor Space	Remove or replace floor mat with one having max pile or edge of 1/4".	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	380	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	381	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	382	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	383	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount hand dryer a min 12" above or 1.5" below grab bar. Pricing in a previous finding.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	384	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Accessible Routes	Replace mat or carpet with one having max pile or edge of 1/4". Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	1
Burt Aaronson South County Regional	385	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Accessible Routes	Replace mat or carpet with one having max gaps of 1/2". Pricing for replacing floor mat in a previous finding.	\$0.00	1	N/A	\$0.00	1
Burt Aaronson South County Regional	386	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	387	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Clear Floor Space	Remove or replace floor mat with one having max pile or edge of 1/4".	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	388	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	389	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	390	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount hand dryer a min 12" above or 1.5" below grab bar. Pricing in a previous finding.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	391	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	392	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Accessible Routes	Replace mat or carpet with one having max pile or edge of 1/4". Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	1
Burt Aaronson South County Regional	393	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Accessible Routes	Replace mat or carpet with one having max gaps of 1/2". Pricing for replacing floor mat in a previous finding.	\$0.00	1	N/A	\$0.00	1
Burt Aaronson South County Regional	394	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	395	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	396	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	2	each	\$934.50	2
Burt Aaronson South County Regional	397	Sunset Cove Amphitheater - Roadie Showers and Restrooms	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF.	\$393.75	1	each	\$393.75	2
Burt Aaronson South County Regional	398	Canine Cove Dog Park - EAR	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48".</p>	\$20,111.00	1	each	\$20,111.00	1
Burt Aaronson South County Regional	399	Canine Cove Dog Park - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	400	Canine Cove Dog Park - EAR	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".</p>	\$6,639.50	1	each	\$6,639.50	1
Burt Aaronson South County Regional	401	Canine Cove Dog Park - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	402	Canine Cove Dog Park - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	403	Canine Cove Dog Park - EAR	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$3,577.00	1	each	\$3,577.00	1
Burt Aaronson South County Regional	404	Canine Cove Dog Park - EAR	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	1
Burt Aaronson South County Regional	405	Canine Cove Dog Park - EAR	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	1
Burt Aaronson South County Regional	406	Canine Cove Dog Park - EAR	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$610.75	1	each	\$610.75	1
Burt Aaronson South County Regional	407	Canine Cove Dog Park - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	409	Canine Cove Dog Park - Exterior Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Burt Aaronson South County Regional	410	Canine Cove Dog Park - Exterior Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	4	lin ft	\$236.80	2
Burt Aaronson South County Regional	412	Canine Cove Dog Park - Exterior Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	413	Canine Cove Dog Park - Dog Washing Stations	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	414	Canine Cove Dog Park - Dog Washing Stations	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$6,639.50	1	each	\$6,639.50	1
Burt Aaronson South County Regional	416	Canine Cove Dog Park - Dog Washing Stations	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$3,577.00	1	each	\$3,577.00	1
Burt Aaronson South County Regional	417	Canine Cove Dog Park - Large Dog - Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	418	Canine Cove Dog Park - Large Dog - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	2
Burt Aaronson South County Regional	421	Canine Cove Dog Park - Large Dog - Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	424	Canine Cove Dog Park - Large Dog - Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	426	Canine Cove Dog Park - Large Dog - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Burt Aaronson South County Regional	427	Canine Cove Dog Park - Large Dog - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to water spout.	\$59.20	5	lin ft	\$296.00	5
Burt Aaronson South County Regional	428	Canine Cove Dog Park - Large Dog - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to water spout.	\$59.20	18	lin ft	\$1,065.60	2
Burt Aaronson South County Regional	431	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	lin ft	\$9,187.50	5
Burt Aaronson South County Regional	432	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	433	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	225	sq ft	\$27,562.50	5
Burt Aaronson South County Regional	434	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	435	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Burt Aaronson South County Regional	436	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Burt Aaronson South County Regional	437	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	438	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	439	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	440	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	441	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	442	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	443	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Burt Aaronson South County Regional	444	Canine Cove Dog Park - Large Dog - Walking Path	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	445	Canine Cove Dog Park - Large Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
Burt Aaronson South County Regional	446	Canine Cove Dog Park - Medium - Dog Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	447	Canine Cove Dog Park - Medium - Dog Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to water spout.	\$59.20	25	lin ft	\$1,480.00	5
Burt Aaronson South County Regional	448	Canine Cove Dog Park - Medium - Dog Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	451	Canine Cove Dog Park - Medium - Dog Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	2
Burt Aaronson South County Regional	452	Canine Cove Dog Park - Medium - Dog Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Aaronson South County Regional	453	Canine Cove Dog Park - Medium Dog - Walking Path	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	8	each	\$770.00	5
Burt Aaronson South County Regional	454	Canine Cove Dog Park - Medium Dog - Walking Path	Outdoor - Trails (C)	Resurface trail with to eliminate deterioration as a smart practice.	\$59.20	60	lin ft	\$3,552.00	5
Burt Aaronson South County Regional	455	Canine Cove Dog Park - Medium Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	456	Canine Cove Dog Park - Medium Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	457	Canine Cove Dog Park - Medium Dog - Walking Path	Outdoor - Trails (C)	Resurface trail with to eliminate deterioration as a smart practice.	\$59.20	100	lin ft	\$5,920.00	5
Burt Aaronson South County Regional	458	Canine Cove Dog Park - Small Dog - Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	461	Canine Cove Dog Park - Small Dog - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to water spout.	\$59.20	3	lin ft	\$177.60	5
Burt Aaronson South County Regional	462	Canine Cove Dog Park - Small Dog - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Burt Aaronson South County Regional	464	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
Burt Aaronson South County Regional	465	Canine Cove Dog Park - Small Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Burt Aaronson South County Regional	466	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
Burt Aaronson South County Regional	467	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	468	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	469	Canine Cove Dog Park - Small Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	470	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Resurface trail with to eliminate deterioration as a smart practice.	\$59.20	35	lin ft	\$2,072.00	5
Burt Aaronson South County Regional	471	Canine Cove Dog Park - Small Dog - Walking Path	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	472	Canine Cove Dog Park - Small Dog - Walking Path	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Aaronson South County Regional	473	Southwest Playgrounds - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Burt Aaronson South County Regional	474	Southwest Playgrounds - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	475	Southwest Playgrounds - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	476	Southwest Playgrounds - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Burt Aaronson South County Regional	477	Southwest Playgrounds - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Burt Aaronson South County Regional	478	Southwest Playgrounds - EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	479	Southwest Playgrounds - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	480	Southwest Playgrounds - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	481	Southwest Playgrounds - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Burt Aaronson South County Regional	482	Southwest Playgrounds - EAR	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$4,529.00	1	each	\$4,529.00	1
Burt Aaronson South County Regional	483	Southwest Playgrounds - 2 to 5 Play Area	Play Area	Create designated entry as a smart practice.	\$700.00	1	each	\$700.00	5
Burt Aaronson South County Regional	484	Southwest Playgrounds - 2 to 5 Play Area	Play Area	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface.  Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Burt Aaronson South County Regional	485	Southwest Playgrounds - 2 to 5 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	486	Southwest Playgrounds - 2 to 5 Play Area	Play Area	Remount handrails along both sides of ramp at 20" to 28" AFF.	\$350.00	4	each	\$1,400.00	2
Burt Aaronson South County Regional	487	Southwest Playgrounds - 2 to 5 Play Area	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%.	\$1,190.00	2	each	\$2,380.00	2
Burt Aaronson South County Regional	488	Southwest Playgrounds - 2 to 5 Play Area	Play Area	Adjust ramp to achieve maximum rise of 12".	\$1,190.00	1	each	\$1,190.00	2
Burt Aaronson South County Regional	489	Southwest Playgrounds - 2 to 5 Play Area	Play Area	For children age 3 to 4, raise/lower the play component to min 20" and max 36".	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	490	Southwest Playgrounds - 2 to 5 Play Area	Play Area	For children age 3 to 4, raise/lower the play component to min 20" and max 36".	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	494	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Create designated entry as a smart practice.	\$700.00	2	each	\$1,400.00	2
Burt Aaronson South County Regional	495	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface.  Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Burt Aaronson South County Regional	496	Southwest Playgrounds - 5 to 12 Play Area	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	2
Burt Aaronson South County Regional	497	Southwest Playgrounds - 5 to 12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	498	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Consider adding a second transfer system as a smart practice.	\$4,970.00	1	each	\$4,970.00	5
Burt Aaronson South County Regional	499	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Remount handrails along both sides of ramp at 20" to 28" AFF.	\$350.00	12	each	\$4,200.00	2
Burt Aaronson South County Regional	500	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%.	\$1,190.00	8	each	\$9,520.00	2
Burt Aaronson South County Regional	501	Southwest Playgrounds - 5 to 12 Play Area	Play Area	Adjust ramp to achieve maximum rise of 12".	\$1,190.00	1	each	\$1,190.00	2
Burt Aaronson South County Regional	503	Southwest Playgrounds - 5 to 12 Play Area	Play Area	For children age 5 to 12, raise/lower the play component to min 16" and 44".	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	505	Southwest Playgrounds - 5 to 12 Play Area	Play Area	For children age 5 to 12, raise/lower the play component to min 16" and 44".	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	508	Southwest Playgrounds - Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	509	Southwest Playgrounds - Elements	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	510	Southwest Playgrounds - Elements	Picnic Tables (C)	Replace one picnic table on an accessible route with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Burt Aaronson South County Regional	511	Southwest Playgrounds - Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
Burt Aaronson South County Regional	512	Southwest Playgrounds - Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	513	Southwest Playgrounds - Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	514	Southwest Playgrounds - Elements	Clear Floor Space	Repair, bevel or ramp CIL in CFS to max .25".	\$96.25	1	each	\$96.25	2
Burt Aaronson South County Regional	515	Southwest General - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	516	Southwest General - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Burt Aaronson South County Regional	517	Southwest General - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Burt Aaronson South County Regional	518	Southwest General - EAR	Accessible Routes	Correct running slope along the AR to max 5%.	\$122.50	50	sq ft	\$6,125.00	1
Burt Aaronson South County Regional	519	Southwest General - EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces, and remove objects that protrude into the circulation path.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	520	Southwest General - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	521	Southwest General - Boating/Fishing	Accessible Routes	Correct cross slopes of floating dock to max 2.08%.  Correct running slope of accessible route to boarding pier at boat ramp to max 5% running or to include compliant ramps or gangways.  Correct or fill gaps to max .5".	\$11,245.00	1	each	\$11,245.00	2
Burt Aaronson South County Regional	522	Southwest General - Boating/Fishing	Boating Facilities	Provide 60" clear pier space for the entire length of pier.	\$875.00	1	each	\$875.00	2
Burt Aaronson South County Regional	523	Southwest General - Boating/Fishing	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	1	each	\$875.00	2
Burt Aaronson South County Regional	524	Southwest General - Boating/Fishing	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	525	Southwest General - Boating/Fishing	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Burt Aaronson South County Regional	526	Southwest General - Boating/Fishing	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Burt Aaronson South County Regional	527	Southwest General - Boating/Fishing	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Burt Aaronson South County Regional	528	Southwest General - Boating/Fishing	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	10	lin ft	\$592.00	5
Burt Aaronson South County Regional	529	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	900	sq ft	\$110,250.00	5
Burt Aaronson South County Regional	530	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	580	sq ft	\$71,050.00	5
Burt Aaronson South County Regional	531	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
Burt Aaronson South County Regional	532	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	810	sq ft	\$99,225.00	5
Burt Aaronson South County Regional	533	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Burt Aaronson South County Regional	534	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Burt Aaronson South County Regional	535	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	390	sq ft	\$47,775.00	5
Burt Aaronson South County Regional	536	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	78	sq ft	\$9,555.00	5
Burt Aaronson South County Regional	537	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Burt Aaronson South County Regional	538	Southwest General - Trail - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Burt Aaronson South County Regional	539	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	540	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Burt Aaronson South County Regional	541	Southwest General - Trail - Surface	Outdoor - Trails (C)	Create 60" level turning space every 1000' along the trail.	\$875.00	1	each	\$875.00	5
Burt Aaronson South County Regional	542	Southwest General - Trail - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Burt Aaronson South County Regional	543	Southwest General - Trail - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	544	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Burt Aaronson South County Regional	545	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	880	sq ft	\$107,800.00	5
Burt Aaronson South County Regional	546	Southwest General - Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	660	sq ft	\$80,850.00	5
Burt Aaronson South County Regional	547	Southwest General - Trail - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Burt Aaronson South County Regional	548	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Burt Aaronson South County Regional	549	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
Burt Aaronson South County Regional	550	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Burt Aaronson South County Regional	551	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	552	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
Burt Aaronson South County Regional	553	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	554	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	555	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	2	each	\$4,972.00	5
Burt Aaronson South County Regional	556	Southwest General - 5 Small Shelters Near Mary Lou Berger Pavilion	Outdoor Recreation Access Route	Relocate 20% of garbage cans to be along AR, and relocate one garbage can to shelter with route to it.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	557	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Create one or more 12' trailer accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
Burt Aaronson South County Regional	558	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	559	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	560	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	561	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	562	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Add one van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Burt Aaronson South County Regional	563	Southwest Area - Boat Ramp - Boat Trailer Parking Lot	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	565	Southwest Area - Boat Ramp - Main Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	566	Southwest General - Boat Ramp - Picnic Area Along Main Parking Lot	Outdoor Recreation Access Route	Replace one picnic table with one of an accessible design and create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to one more picnic table.	\$2,008.00	1	each	\$2,008.00	5
Burt Aaronson South County Regional	567	Southwest General - Boat Ramp - Picnic Area Along Main Parking Lot	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Burt Aaronson South County Regional	568	Southwest General - Boat Ramp - Picnic Area Along Main Parking Lot	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.  Provide required 36" clear ground space around all usable portions of the table as a smart practice.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over grass.	\$2,486.00	1	each	\$2,486.00	5
Burt Aaronson South County Regional	569	Southwest General - Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	570	Southwest General - Mary Lou Berger Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	15	each	\$1,443.75	5
Burt Aaronson South County Regional	571	Southwest General - Mary Lou Berger Pavilion	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	3	lin ft	\$177.60	5
Burt Aaronson South County Regional	572	Southwest General - Mary Lou Berger Pavilion	Shelters/Picnic Areas (C)	Replace one grill with one of an accessible design and provide required clear ground space.  Remount or replace one garbage can to be in reach range of 15" min to 48" max.  Remount one water spout to 28" min or 36" max above the ground as a smart practice.  Replace remounted water spout with handles usable without a tight pinch or grasp.	\$810.00	1	each	\$810.00	5
Burt Aaronson South County Regional	574	Southwest General - Combined Parking For SW Play Area And Dog Parks	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Burt Aaronson South County Regional	575	Southwest General - Combined Parking For SW Play Area And Dog Parks	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.  Correct or fill gaps to max .5".	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	576	Southwest General - Combined Parking For SW Play Area And Dog Parks	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	577	Southwest General - Playground Men's Restroom	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	578	Southwest General - Playground Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	579	Southwest General - Playground Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	580	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	581	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	582	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Rehang stall door to provide required maneuvering clearance on pull side.	\$2,749.25	1	each	\$2,749.25	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	583	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	584	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	585	Southwest General - Playground Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	586	Southwest General - Playground Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	587	Southwest General - Playground Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	588	Southwest General - Playground Men's Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	589	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	590	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	591	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	592	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	593	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	594	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	595	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	596	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Rehang stall door to provide required maneuvering clearance on pull side.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	597	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	598	Southwest General - Playground Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	599	Southwest General - Playground Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	600	Southwest General - Playground Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	601	Southwest General - Playground Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	602	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Remount or replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
Burt Aaronson South County Regional	603	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Adjust spout flow to max 15 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	604	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	605	Southwest General - Playground Women's Restroom	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Burt Aaronson South County Regional	606	Southwest General - Playground Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	607	Southwest General - Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	20	lin ft	\$1,184.00	2
Burt Aaronson South County Regional	608	Southwest General - Park Elements	Parking - Off Street	Add an estimated 25 accessible parking stalls to other lots serving areas that this overflow lot is intended to serve based on the number of spaces in the overflow lot and leave this lot as is.	\$1,589.00	25	each	\$39,725.00	1
Burt Aaronson South County Regional	609	DNC - Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	610	DNC - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	611	DNC - Parking	Parking - Off Street	Leave as is slope of 2.2%, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	612	DNC - Parking	Parking - Off Street	Resurface accessible stalls and access aisles to eliminate gaps and changes in level.	\$2,800.00	1	each	\$2,800.00	1
Burt Aaronson South County Regional	613	DNC - Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	614	DNC - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	615	DNC - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Burt Aaronson South County Regional	616	DNC - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	617	DNC - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	618	DNC - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
Burt Aaronson South County Regional	619	DNC - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	620	DNC - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	621	DNC - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	622	DNC - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	623	DNC - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	624	DNC - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	42	each	\$4,042.50	1
Burt Aaronson South County Regional	625	DNC - EAR	Detectable Warnings	Remove existing detectable warning from drive aisle, and install a detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Aaronson South County Regional	626	DNC - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	627	DNC - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	629	DNC - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	631	DNC - Employee Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	632	DNC - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	633	DNC - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	634	DNC - Employee Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	4
Burt Aaronson South County Regional	635	DNC - Employee Spaces	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	636	DNC - Employee Spaces	Toilet and Bathing Rooms	Relocate shelf to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	637	DNC - Employee Spaces	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	638	DNC - Employee Spaces	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	3
Burt Aaronson South County Regional	639	DNC - Employee Spaces	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	640	DNC - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	641	DNC - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	642	DNC - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	643	DNC - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	644	DNC - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$376.25	1	each	\$376.25	1
Burt Aaronson South County Regional	645	DNC - Public Spaces	Accessible Routes	Relocate or reposition chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	646	DNC - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	647	DNC - Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	648	DNC - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	649	DNC - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	650	DNC - Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$747.25	1	each	\$747.25	1
Burt Aaronson South County Regional	651	DNC - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$376.25	1	each	\$376.25	1
Burt Aaronson South County Regional	652	DNC - Men's Restroom	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	653	DNC - Men's Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	654	DNC - Men's Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	655	DNC - Men's Restroom	Accessible Routes	Replace mat or carpet with one having max pile or edge of 1/4".  Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	656	DNC - Men's Restroom	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	657	DNC - Men's Restroom	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	658	DNC - Men's Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	659	DNC - Men's Restroom	Plumbing Fixtures & Elements	Remove or raise apron to provide 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	660	DNC - Men's Restroom	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	661	DNC - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	662	DNC - Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	663	DNC - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	664	DNC - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	665	DNC - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	666	DNC - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	667	DNC - Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	668	DNC - Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	669	DNC - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	670	DNC - Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Burt Aaronson South County Regional	671	DNC - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	672	DNC - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	673	DNC - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	674	DNC - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar. Relocate hand dryer and garbage can a min 12" above or 1.5" below grab bar.	\$393.75	2	each	\$787.50	1
Burt Aaronson South County Regional	675	DNC - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	676	DNC - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	677	DNC - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	678	DNC - Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	679	DNC - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	680	DNC - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	681	DNC - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	682	DNC - Women's Restroom	Plumbing Fixtures & Elements	Remove floor mat to provide 27" knee clearance that is a min 8" deep.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	683	DNC - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.  Remount signage to the proper location based on the type of door provided.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	684	DNC - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	685	DNC - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	686	DNC - Display/Exhibit Areas	Doors	Replace door with one having 32" clear width.	\$2,772.50	1	each	\$2,772.50	1
Burt Aaronson South County Regional	687	DNC - Display/Exhibit Areas	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	688	DNC - Display/Exhibit Areas	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	689	DNC - Display/Exhibit Areas	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Burt Aaronson South County Regional	690	DNC - Display/Exhibit Areas	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	1	each	\$980.00	3
Burt Aaronson South County Regional	691	DNC - Display/Exhibit Areas	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions; in the alternative, remove, relocate, or renovate this display to not obstruct the ramp handrail.	\$980.00	1	each	\$980.00	1
Burt Aaronson South County Regional	692	DNC - Display/Exhibit Areas	Accessible Routes	Widen AR to compliant 36" clear width.	\$1,540.00	5	lin ft	\$7,700.00	1
Burt Aaronson South County Regional	693	DNC - Display/Exhibit Areas	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
Burt Aaronson South County Regional	694	DNC - Display/Exhibit Areas	Accessible Routes	Correct or repair slope to max 5% running and 2.08% cross.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	695	DNC - Display/Exhibit Areas	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
Burt Aaronson South County Regional	696	DNC - Display/Exhibit Areas	Signs	Remount signage to min 40" AFF.	\$0.00	14	staff time	\$0.00	1
Burt Aaronson South County Regional	698	DNC - Display/Exhibit Areas	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Burt Aaronson South County Regional	699	DNC - Display/Exhibit Areas	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	700	DNC - Laboratory	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	3
Burt Aaronson South County Regional	701	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	35	each	\$3,368.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	702	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	21	each	\$2,021.25	5
Burt Aaronson South County Regional	703	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	25	each	\$2,406.25	5
Burt Aaronson South County Regional	704	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	7	each	\$673.75	5
Burt Aaronson South County Regional	705	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	9	each	\$866.25	5
Burt Aaronson South County Regional	706	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Burt Aaronson South County Regional	707	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Burt Aaronson South County Regional	708	DNC - Trail/Boardwalk - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	11	each	\$1,058.75	5
Burt Aaronson South County Regional	709	DNC - Trail/Boardwalk - Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site as a smart practice.	\$46,631.00	1	each	\$46,631.00	5
Burt Aaronson South County Regional	710	DNC - Trail/Boardwalk - Elements	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	35	each	\$14,148.75	5
Burt Aaronson South County Regional	711	DNC - Trail/Boardwalk - Elements	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	35	each	\$4,375.00	5
Burt Aaronson South County Regional	712	DNC - Trail/Boardwalk - Elements	Stairways	Correct or fill gaps on treads to max .5".	\$96.25	15	each	\$1,443.75	5
Burt Aaronson South County Regional	713	DNC - Trail/Boardwalk - Elements	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	5
Burt Aaronson South County Regional	715	DNC - Trail/Boardwalk - Elements	Viewing Areas (C)	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51".	\$980.00	2	each	\$1,960.00	5
Burt Aaronson South County Regional	717	DNC - Exterior Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	718	DNC - Exterior Elements	Signs	Replace signage with compliant signage.	\$210.00	3	each	\$630.00	1
Burt Aaronson South County Regional	719	DNC - Exterior Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	722	CC Waterpark - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	2	each	\$3,178.00	1
Burt Aaronson South County Regional	723	CC Waterpark - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Burt Aaronson South County Regional	724	CC Waterpark - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Burt Aaronson South County Regional	725	CC Waterpark - Parking	Parking - Off Street	Correct or fill gaps to max .5".	\$96.25	4	each	\$385.00	1
Burt Aaronson South County Regional	726	CC Waterpark - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	727	CC Waterpark - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	13	each	\$955.50	1
Burt Aaronson South County Regional	730	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	731	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	7	each	\$673.75	1
Burt Aaronson South County Regional	732	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	733	CC Waterpark - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	734	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Burt Aaronson South County Regional	735	CC Waterpark - EAR	Reach Ranges	Remount two garbage cans along an accessible route to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	736	CC Waterpark - EAR	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Burt Aaronson South County Regional	737	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	738	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	739	CC Waterpark - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	740	CC Waterpark - EAR	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
Burt Aaronson South County Regional	741	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	750	sq ft	\$91,875.00	3
Burt Aaronson South County Regional	742	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	743	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	744	CC Waterpark - Pool	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	745	CC Waterpark - Pool	Accessible Routes	Create an accessible route connecting to slide entry, crossing feature, and staff building.	\$6,510.00	4	each	\$26,040.00	3
Burt Aaronson South County Regional	746	CC Waterpark - Pool	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Burt Aaronson South County Regional	747	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	748	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Burt Aaronson South County Regional	749	CC Waterpark - Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Burt Aaronson South County Regional	750	CC Waterpark - Pool	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Burt Aaronson South County Regional	751	CC Waterpark - Pool	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	752	CC Waterpark - Pool	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	753	CC Waterpark - Pool	Play Area	Lower platform on transfer system to 11" to 18" aff, in the alternative, add a compliant transfer system to the structure.	\$2,800.00	1	each	\$2,800.00	2
Burt Aaronson South County Regional	754	CC Waterpark - Pool	Play Area	Install transfer steps on play structure, 24" wide by 14" deep	\$2,000.00	4	each	\$8,000.00	2
Burt Aaronson South County Regional	755	CC Waterpark - Pool	Play Area	Install compliant transfer steps for access to min 50% of EPCs.	\$5,800.00	1	each	\$5,800.00	2
Burt Aaronson South County Regional	757	CC Waterpark - Pool	Play Area	Add one more GLPC of a type other than climber and manipulable to meet incentive scoping	\$2,800.00	1	each	\$2,800.00	2
Burt Aaronson South County Regional	758	CC Waterpark - Pool	Pool / Spa	Install a second means of entry to the pool such as a lift, transfer wall, stairs, or a transfer system	\$7,140.00	1	each	\$7,140.00	3
Burt Aaronson South County Regional	759	CC Waterpark - Pool	Pool / Spa	Correct sloped entry to extend to a depth of 24" min and 30" maximum.  Leave as is, existing sloped landing and provide a lift or another accessible means of entry into the pool.	\$10,000.00	1	each	\$10,000.00	3
Burt Aaronson South County Regional	760	CC Waterpark - Pool	Pool / Spa	Install a handrail on one wall of the zero depth entry and extend for 24' to 30', with the top of the handrail between 34" and 38" AFF.	\$980.00	1	each	\$980.00	3
Burt Aaronson South County Regional	761	CC Waterpark - Pool	Pool / Spa	Correct slope of pool entry to max 8.33% running and 2.08% cross.  Leave as is if technically infeasible to correct and install another means of entry.	\$6,510.00	1	each	\$6,510.00	3
Burt Aaronson South County Regional	762	CC Waterpark - Pool	Stairways	Correct riser heights on stairs to consistent height between 4" to 7"; leave as is if technically infeasible.	\$404.25	22	each	\$8,893.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	763	CC Waterpark - Pool	Stairways	Correct tread depth on stairs to 11" minimum and consistent. ; leave as is if technically infeasible.	\$404.25	20	each	\$8,085.00	3
Burt Aaronson South County Regional	764	CC Waterpark - Pool	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	22	each	\$2,750.00	5
Burt Aaronson South County Regional	765	CC Waterpark - Pool	Accessible Routes	Create an accessible route to slide tower base.	\$13,020.00	1	each	\$13,020.00	3
Burt Aaronson South County Regional	766	CC Waterpark - Pool	Accessible Routes	Create an accessible route to crossing feature and staff building.	\$13,020.00	1	each	\$13,020.00	3
Burt Aaronson South County Regional	767	CC Waterpark - Pool	Stairways	Correct riser heights on stairs to consistent height between 4" to 7"; leave as is if technically infeasible.	\$404.25	12	each	\$4,851.00	3
Burt Aaronson South County Regional	768	CC Waterpark - Pool	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	22	each	\$2,750.00	5
Burt Aaronson South County Regional	769	CC Waterpark - Pool	Pool / Spa	Install pool lift and make it available every hour the pool is open; if pool has more than 300' of linear wall, install a second means of entry.	\$8,400.00	1	each	\$8,400.00	3
Burt Aaronson South County Regional	770	CC Waterpark - Employee Spaces	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	771	CC Waterpark - Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25".	\$192.50	1	each	\$192.50	3
Burt Aaronson South County Regional	772	CC Waterpark - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.  Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	773	CC Waterpark - Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	774	CC Waterpark - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	3
Burt Aaronson South County Regional	775	CC Waterpark - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	776	CC Waterpark - Employee Spaces	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	777	CC Waterpark - Employee Spaces	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	778	CC Waterpark - Employee Spaces	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	3
Burt Aaronson South County Regional	779	CC Waterpark - Employee Spaces	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	3
Burt Aaronson South County Regional	780	CC Waterpark - Employee Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	781	CC Waterpark - Employee Spaces	Doors	Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Burt Aaronson South County Regional	782	CC Waterpark - Employee Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	3
Burt Aaronson South County Regional	783	CC Waterpark - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	784	CC Waterpark - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	785	CC Waterpark - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	786	CC Waterpark - Public Spaces	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	788	CC Waterpark - Public Spaces	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Burt Aaronson South County Regional	789	CC Waterpark - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	790	CC Waterpark - Concessions	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	791	CC Waterpark - Concessions	Room/Space (C)	Inspect, adjust, and maintain 5 lbf to open interior doors.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,380.00	1	each	\$1,380.00	3
Burt Aaronson South County Regional	792	CC Waterpark - Concessions	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.	\$1,120.00	2	each	\$2,240.00	1
Burt Aaronson South County Regional	793	CC Waterpark - Employee Office Restroom By Locker Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	794	CC Waterpark - Employee Office Restroom By Locker Rooms	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of restroom floor surface.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	795	CC Waterpark - Employee Office Restroom By Locker Rooms	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	3
Burt Aaronson South County Regional	796	CC Waterpark - Employee Office Restroom By Locker Rooms	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	797	CC Waterpark - Employee Office Restroom By Locker Rooms	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount toilet seat cover dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	798	CC Waterpark - Employee Office Restroom By Locker Rooms	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Burt Aaronson South County Regional	799	CC Waterpark - Employee Office Restroom By Locker Rooms	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	800	CC Waterpark - Employee Office Restroom By Locker Rooms	Operable Parts	Replace cabinet handles with ones usable without a tight pinch or grasp.	\$210.00	3	each	\$630.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	801	CC Waterpark - Employee Office Restroom By Locker Rooms	Reach Ranges	Lower cabinets to max 48" above the finished floor (AFF) to highest operable part.  Lower paper towel dispenser to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	1	each	\$350.00	3
Burt Aaronson South County Regional	802	CC Waterpark - Employee Office Restroom By Locker Rooms	Plumbing Fixtures & Elements	Remove or relocate garbage can from clear floor space of sink.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	803	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	804	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	805	CC Waterpark - Men's Locker Room Family Changing Room	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	806	CC Waterpark - Men's Locker Room Family Changing Room	Custom/Special	Maintain all features, appliances, and other items to be operational when the site is open.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	807	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Relocate toilet to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	808	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	809	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	810	CC Waterpark - Men's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	811	CC Waterpark - Men's Locker Room Family Changing Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	813	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	814	CC Waterpark - Women's Locker Room Family Changing Room	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	815	CC Waterpark - Women's Locker Room Family Changing Room	Reach Ranges	Provide the same level of amenities in each restroom with accessible features.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	816	CC Waterpark - Women's Locker Room Family Changing Room	Custom/Special	Maintain all features, appliances, and other items to be operational when the site is open.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	817	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	818	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	819	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	820	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	821	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	822	CC Waterpark - Women's Locker Room Family Changing Room	Toilet and Bathing Rooms	Replace or repair toilet paper dispenser with one that provides continuous flow of paper.	\$84.00	1	each	\$84.00	1
Burt Aaronson South County Regional	823	CC Waterpark - Women's Locker Room Family Changing Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	824	CC Waterpark - Women's Locker Room Family Changing Room	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	825	CC Waterpark - Men's Locker Room and Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	826	CC Waterpark - Men's Locker Room and Restroom	Toilet and Bathing Rooms	Replace one mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	827	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	828	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	829	CC Waterpark - Men's Locker Room and Restroom	Reach Ranges	Lower one hand dryer to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	830	CC Waterpark - Men's Locker Room and Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	831	CC Waterpark - Men's Locker Room and Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Burt Aaronson South County Regional	832	CC Waterpark - Men's Locker Room and Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Burt Aaronson South County Regional	833	CC Waterpark - Men's Locker Room and Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	6	each	\$2,100.00	1
Burt Aaronson South County Regional	834	CC Waterpark - Men's Locker Room and Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	5	each	\$15,312.50	1
Burt Aaronson South County Regional	835	CC Waterpark - Men's Locker Room and Restroom	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" aff.	\$420.00	4	each	\$1,680.00	2
Burt Aaronson South County Regional	836	CC Waterpark - Men's Locker Room and Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Burt Aaronson South County Regional	837	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	838	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	839	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Burt Aaronson South County Regional	840	CC Waterpark - Men's Locker Room and Restroom	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	1
Burt Aaronson South County Regional	842	CC Waterpark - Men's Locker Room and Restroom	Doors	Provide required maneuvering clearance on push side of door. Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	843	CC Waterpark - Men's Locker Room and Restroom	Doors	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48". Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	1
Burt Aaronson South County Regional	844	CC Waterpark - Men's Locker Room and Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	845	CC Waterpark - Men's Locker Room and Restroom	Room/Space (C)	Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	2	each	\$5,545.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	846	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	847	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Replace one mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	848	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Lower one sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	849	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	850	CC Waterpark - Women's Locker Room and Restroom	Reach Ranges	Lower hook to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	851	CC Waterpark - Women's Locker Room and Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	852	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Burt Aaronson South County Regional	853	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	854	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Burt Aaronson South County Regional	855	CC Waterpark - Women's Locker Room and Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	856	CC Waterpark - Women's Locker Room and Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	6	each	\$2,100.00	1
Burt Aaronson South County Regional	857	CC Waterpark - Women's Locker Room and Restroom	Accessible Routes	Replace drain with one having openings max .5".	\$140.00	1	each	\$140.00	1
Burt Aaronson South County Regional	858	CC Waterpark - Women's Locker Room and Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	5	each	\$15,312.50	1
Burt Aaronson South County Regional	859	CC Waterpark - Women's Locker Room and Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	860	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Enlarge transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Burt Aaronson South County Regional	861	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2
Burt Aaronson South County Regional	862	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Burt Aaronson South County Regional	863	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
Burt Aaronson South County Regional	864	CC Waterpark - Women's Locker Room and Restroom	Plumbing Fixtures & Elements	Replace shower seat based on shower type.	\$840.00	1	each	\$840.00	1
Burt Aaronson South County Regional	865	CC Waterpark - Women's Locker Room and Restroom	Doors	Repair closer, then inspect, adjust, and maintain 5 lbf to open door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	866	CC Waterpark - Women's Locker Room and Restroom	Room/Space (C)	Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	3	each	\$8,317.50	3
Burt Aaronson South County Regional	867	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	868	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	869	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	870	CC Community Center - Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	872	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	873	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	874	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	875	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.00	1	each	\$2,772.00	3
Burt Aaronson South County Regional	876	CC Community Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	877	CC Community Center - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,380.00	4	each	\$5,520.00	1
Burt Aaronson South County Regional	878	CC Community Center - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	880	CC Community Center - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	881	CC Community Center - Public Spaces	Plumbing Fixtures & Elements	Remove objects from knee clearance under sinks.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	882	CC Community Center - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$3,130.00	1	each	\$3,130.00	1
Burt Aaronson South County Regional	883	CC Community Center - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$4,812.50	1	each	\$4,812.50	1
Burt Aaronson South County Regional	884	CC Community Center - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,380.00	1	each	\$1,380.00	1
Burt Aaronson South County Regional	885	CC Community Center - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	886	CC Community Center - Public Spaces	Dining, Bar and Work Surfaces	Provide one table at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	887	CC Community Center - Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.  Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	888	CC Community Center - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$3,270.00	1	each	\$3,270.00	1
Burt Aaronson South County Regional	889	CC Community Center - Kitchen	Doors	Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	1
Burt Aaronson South County Regional	890	CC Community Center - Kitchen	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	891	CC Community Center - Kitchen	Plumbing Fixtures & Elements	Lower one sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	892	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	893	CC Community Center - Women's Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	894	CC Community Center - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	895	CC Community Center - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	896	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	897	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Burt Aaronson South County Regional	898	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	899	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	900	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	901	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	902	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	903	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	904	CC Community Center - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	905	CC Community Center - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	906	CC Community Center - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	907	CC Community Center - Women's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	908	CC Community Center - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	909	CC Community Center - Men's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	910	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	911	CC Community Center - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	912	CC Community Center - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	913	CC Community Center - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	914	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	915	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Burt Aaronson South County Regional	916	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	917	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	918	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	919	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	920	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	921	CC Community Center - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	922	CC Community Center - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	923	CC Community Center - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	924	Community Center - Interior Route	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	925	Community Center - Interior Route	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	926	Community Center - Interior Route	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Burt Aaronson South County Regional	927	Community Center - Interior Route	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	928	Community Center - Interior Route	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	929	Community Center - Interior Route	Clear Floor Space	Remove or relocate table to provide 30" by 48" clear floor space at brochure rack.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	930	Community Center - Interior Route	Reach Ranges	Lower operating mechanisms to max 48" AFF to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	931	Community Center - Interior Route	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	932	Community Center - Interior Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	933	Community Center - Interior Route	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	934	Community Center - Interior Route	Custom/Special	Ensure compliance of all doors intended for operation and maintain them to be operational.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	935	Community Center - Interior Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$3,130.00	1	each	\$3,130.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	936	Community Center - Interior Route	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$288.75	1	each	\$288.75	1
Burt Aaronson South County Regional	937	Northeast Playgrounds Near Multi-Use Fields	Play Area	Create designated entry as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Burt Aaronson South County Regional	938	Northeast Playgrounds Near Multi-Use Fields	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Burt Aaronson South County Regional	939	Northeast Playgrounds Near Multi-Use Fields	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	940	Northeast Playgrounds Near Multi-Use Fields	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	941	Northeast Playgrounds Near Multi-Use Fields	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	942	Northeast Playgrounds Near Multi-Use Fields	Play Area	Add 2 more GLPC's of 2 other types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
Burt Aaronson South County Regional	943	Northeast General North Playground near Yamato Rd	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	5	lin ft	\$296.00	4
Burt Aaronson South County Regional	944	Northeast General North Playground near Yamato Rd	Play Area	Create designated as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Burt Aaronson South County Regional	945	Northeast General North Playground near Yamato Rd	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	946	Northeast General North Playground near Yamato Rd	Play Area	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	947	Northeast General North Playground near Yamato Rd	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	948	Northeast General North Playground near Yamato Rd	Play Area	Provide an AR to element for one of each type accessible.  Pricing in a previous finding for playground surface replacement.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	949	Northeast General North Playground near Yamato Rd	Play Area	See previous finding or surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	950	Northeast General North Playground near Yamato Rd	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Pricing in finding for other play area at this location.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	951	Northeast General North Playground near Yamato Rd	Play Area	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	952	Northeast General North Playground near Yamato Rd	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	953	Northeast General North Playground near Yamato Rd	Play Area	Provide an AR to element for one of each type accessible.  Pricing in a previous finding for correcting play area surface.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Aaronson South County Regional	954	Northeast General North Playground near Yamato Rd	Play Area	Add 1 more GLPCs of 1 other type to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Burt Aaronson South County Regional	956	Northeast Maintenance - Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	957	Northeast Maintenance - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	958	Northeast Maintenance - Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'. Pricing for restriping stall and access aisle in a previous finding.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	959	Northeast Maintenance - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	960	Northeast Maintenance - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks. Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	2	each	\$5,600.00	1
Burt Aaronson South County Regional	961	Northeast Maintenance - Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	962	Northeast Maintenance - Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	963	Northeast Maintenance - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	965	Northeast Maintenance - EAR	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	966	Northeast Maintenance - Employee Spaces	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	2	each	\$280.00	3
Burt Aaronson South County Regional	967	Northeast Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Replace doors with doors having 80" overhead clearance and 32" clear width. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,551.50	1	each	\$5,551.50	3
Burt Aaronson South County Regional	968	Northeast Maintenance - Employee Spaces	Doors	Provide required maneuvering clearance around pull side of door. Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	969	Northeast Maintenance - Employee Spaces	Accessible Routes	Relocate or reposition tables to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	970	Northeast Maintenance - Employee Spaces	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	971	Northeast Maintenance - Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	972	Northeast Maintenance - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	3
Burt Aaronson South County Regional	973	Northeast Maintenance - Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Burt Aaronson South County Regional	974	Northeast Maintenance - Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	976	Northeast Maintenance - Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Burt Aaronson South County Regional	977	Northeast Maintenance - Men's Restroom	Plumbing Fixtures & Elements	Relocate garbage can from CFS of sink.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	978	Northeast Maintenance - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet; in the alternative, reconfigure restroom to be a single user restroom if doing so will not conflict with other codes.	\$8,295.00	1	each	\$8,295.00	3
Burt Aaronson South County Regional	979	Northeast Maintenance - Men's Restroom	Reach Ranges	Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	980	Northeast Maintenance - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	3
Burt Aaronson South County Regional	981	Northeast Maintenance - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	982	Northeast Maintenance - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	3
Burt Aaronson South County Regional	983	Northeast Maintenance - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	3
Burt Aaronson South County Regional	984	Northeast Maintenance - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$2,264.50	1	each	\$2,264.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	985	Northeast Maintenance - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Burt Aaronson South County Regional	986	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	987	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	988	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Burt Aaronson South County Regional	989	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Burt Aaronson South County Regional	990	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor	\$2,380.00	1	each	\$2,380.00	3
Burt Aaronson South County Regional	991	Northeast Maintenance - Women's Restroom	Reach Ranges	Lower paper towel dispenser to max 48" above the finished floor (AFF) to highest operable part. Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	992	Northeast Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	3
Burt Aaronson South County Regional	994	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	2	each	\$735.00	1
Burt Aaronson South County Regional	995	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Burt Aaronson South County Regional	996	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	997	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	998	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	999	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Burt Aaronson South County Regional	1000	Northeast General Soccer/Multi-use Field 13 Parking	Parking - Off Street	Create one or more accessible parking stalls in adjacent paved lots based on the number of parking spaces in overflow lot, leave as is overflow lot.	\$1,589.00	1	each	\$1,589.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1001	Northeast General Parking At North Restrooms (01)	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	5	each	\$7,945.00	1
Burt Aaronson South County Regional	1003	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	1004	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	1005	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1006	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1007	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1008	Northeast General Parking - Small Lot At Outfield Of Ballfield 9	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Burt Aaronson South County Regional	1010	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
Burt Aaronson South County Regional	1011	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	1012	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.  Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$2,800.00	6	each	\$16,800.00	1
Burt Aaronson South County Regional	1013	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1014	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1015	Northeast General Parking Lot Adjacent To Pickle Ball Courts	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	12	each	\$882.00	1
Burt Aaronson South County Regional	1017	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1018	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	3	each	\$4,767.00	1
Burt Aaronson South County Regional	1019	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'. Pricing for repainting in a previous finding.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1020	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	1021	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks. Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	2	each	\$5,600.00	1
Burt Aaronson South County Regional	1022	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1023	Northeast General Parking At Football Fields 1 And 2 And Restroom 06	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1025	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	1026	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Burt Aaronson South County Regional	1027	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1028	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks. Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	2	each	\$5,600.00	1
Burt Aaronson South County Regional	1029	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1030	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1031	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1032	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1033	Northeast General Parking Lot At Park Entry From Park Access Road Near Multi-use Fields	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Burt Aaronson South County Regional	1035	Northeast General Yamato Rd Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1036	Northeast General Yamato Rd Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
Burt Aaronson South County Regional	1037	Northeast General Yamato Rd Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Burt Aaronson South County Regional	1038	Northeast General Yamato Rd Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1039	Northeast General Yamato Rd Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Burt Aaronson South County Regional	1040	Northeast General EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Burt Aaronson South County Regional	1041	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
Burt Aaronson South County Regional	1042	Northeast General EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
Burt Aaronson South County Regional	1043	Northeast General EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	30	lin ft	\$1,776.00	1
Burt Aaronson South County Regional	1044	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1045	Northeast General EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Burt Aaronson South County Regional	1046	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1047	Northeast General EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1048	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1049	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1050	Northeast General EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Burt Aaronson South County Regional	1051	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	60	lin ft	\$3,552.00	4
Burt Aaronson South County Regional	1052	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	30	lin ft	\$1,776.00	4
Burt Aaronson South County Regional	1053	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	65	lin ft	\$3,848.00	4
Burt Aaronson South County Regional	1054	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	45	lin ft	\$2,664.00	2
Burt Aaronson South County Regional	1055	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	40	lin ft	\$2,368.00	4
Burt Aaronson South County Regional	1056	Northeast General Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	120	lin ft	\$7,104.00	4
Burt Aaronson South County Regional	1057	Northeast General Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	3	lin ft	\$177.60	2
Burt Aaronson South County Regional	1059	Northeast General Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1060	Northeast General Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1061	Northeast General Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
Burt Aaronson South County Regional	1062	Northeast General Park Elements	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1063	Northeast General Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1065	Northeast General Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1066	Northeast General Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1067	Northeast General Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Aaronson South County Regional	1069	Northeast General Amphitheater Near Nature Center	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	4	each	\$3,595.00	2
Burt Aaronson South County Regional	1070	Northeast General Amphitheater Near Nature Center	Assembly Areas	Provide signage informing patrons of the availability of assistive listening systems if amplification is provided for events.	\$210.00	1	each	\$210.00	2
Burt Aaronson South County Regional	1071	Northeast General Amphitheater Near Nature Center	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Burt Aaronson South County Regional	1072	Northeast General Amphitheater Near Nature Center	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
Burt Aaronson South County Regional	1074	Northeast General Amphitheater Near Nature Center	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1075	Northeast General Amphitheater Near Nature Center	Park Site (C)	Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1076	Northeast General Amphitheater Near Nature Center	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1077	Northeast General Amphitheater Near Nature Center	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1081	Northeast General Pickle Ball Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1082	Northeast General Pickle Ball Courts	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	120	sq ft	\$14,700.00	1
Burt Aaronson South County Regional	1083	Northeast General Pickle Ball Courts	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Burt Aaronson South County Regional	1084	Northeast General Pickle Ball Courts	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Aaronson South County Regional	1086	Northeast General Pickle Ball Courts	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	40	lin ft	\$2,368.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1087	Northeast General Pickle Ball Courts	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	1088	Northeast General Pickle Ball Courts	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF	\$514.50	1	each	\$514.50	1
Burt Aaronson South County Regional	1090	Northeast General Sand Volleyball Near Pickle Ball Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	20	lin ft	\$1,184.00	2
Burt Aaronson South County Regional	1092	Northeast General Multi-use Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	400	lin ft	\$23,680.00	2
Burt Aaronson South County Regional	1093	Northeast General Multi-use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1094	Northeast General Multi-use Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	1095	Northeast General Multi-use Fields	Accessible Routes	Relocate or reposition storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1096	Northeast General Multi-use Fields	Turning Space	Relocate obstacles to create turning space in concessions room.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1097	Northeast General Multi-use Fields	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	1098	Northeast General Multi-use Fields	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Burt Aaronson South County Regional	1099	Northeast General Multi-use Fields	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	3
Burt Aaronson South County Regional	1100	Northeast General Multi-use Fields	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	1101	Northeast General Multi-use Fields	Stairways	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	\$404.25	14	each	\$5,659.50	1
Burt Aaronson South County Regional	1102	Northeast General Multi-use Fields	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	17	each	\$2,125.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1103	Northeast General Multi-use Fields	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Burt Aaronson South County Regional	1104	Northeast General Multi-use Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide beveled threshold.	\$253.75	1	each	\$253.75	1
Burt Aaronson South County Regional	1106	Northeast General Multi-use Field 13	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1107	Northeast General Multi-use Field 13	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1108	Northeast General Restroom 01 - Men's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$2,038.75	1	each	\$2,038.75	1
Burt Aaronson South County Regional	1109	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1110	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1111	Northeast General Restroom 01 - Men's	Plumbing Fixtures & Elements	Lower one main sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1112	Northeast General Restroom 01 - Men's	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	1113	Northeast General Restroom 01 - Men's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1114	Northeast General Restroom 01 - Men's	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Burt Aaronson South County Regional	1115	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1116	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1117	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1118	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1119	Northeast General Restroom 01 - Men's	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	1120	Northeast General Restroom 01 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1121	Northeast General Restroom 01 - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Pricing for moving hand dryer in stall in a previous finding.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1122	Northeast General Restroom 01 - Men's	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1123	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	sq ft	\$210.00	1
Burt Aaronson South County Regional	1124	Northeast General Restroom 01 - Women's	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1125	Northeast General Restroom 01 - Women's	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1126	Northeast General Restroom 01 - Women's	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	1127	Northeast General Restroom 01 - Women's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1128	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1129	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1130	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1131	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1132	Northeast General Restroom 01 - Women's	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1133	Northeast General Restroom 01 - Women's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1134	Northeast General Restroom 01 - Women's	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1135	Northeast General Restroom 01 - Women's	Doors	Provide required maneuvering clearance on push side of door.	\$1,750.00	1	each	\$1,750.00	1
				For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.					
Burt Aaronson South County Regional	1136	Northeast General Restroom 05 - Men's	Doors	For all doors/gates along the public circulation route, provide beveled threshold.	\$5,066.25	1	each	\$5,066.25	1
Burt Aaronson South County Regional	1137	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1138	Northeast General Restroom 05 - Men's	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1139	Northeast General Restroom 05 - Men's	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Burt Aaronson South County Regional	1140	Northeast General Restroom 05 - Men's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1141	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1142	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1143	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1144	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1145	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
				Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing in a previous finding for replacing grab bars.					
Burt Aaronson South County Regional	1146	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1147	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Relocate hand dryer from stall door clearance.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1148	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1149	Northeast General Restroom 05 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1150	Northeast General Restroom 05 - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.  Pricing for hand dryer in stall in a previous finding.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1151	Northeast General Restroom 05 - Women's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1152	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.  Relocate sink to provide clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,730.00	1	each	\$2,730.00	1
Burt Aaronson South County Regional	1153	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1154	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1155	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1156	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1157	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1158	Northeast General Restroom 05 - Women's	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	1159	Northeast General Restroom 05 - Women's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1160	Northeast General Restroom 05 - Women's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide beveled threshold.	\$5,066.25	1	each	\$5,066.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1161	Northeast General Restroom 06 - Men's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,908.75	1	each	\$4,908.75	1
Burt Aaronson South County Regional	1162	Northeast General Restroom 06 - Men's	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1163	Northeast General Restroom 06 - Men's	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1164	Northeast General Restroom 06 - Men's	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Burt Aaronson South County Regional	1165	Northeast General Restroom 06 - Men's	Reach Ranges	Lower hook to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1166	Northeast General Restroom 06 - Men's	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Burt Aaronson South County Regional	1167	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1168	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1169	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1170	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1171	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1172	Northeast General Restroom 06 - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1173	Northeast General Restroom 06 - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1174	Northeast General Restroom 06 - Men's	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1175	Northeast General Restroom 06 - Women's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,812.50	1	each	\$4,812.50	1
Burt Aaronson South County Regional	1176	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1177	Northeast General Restroom 06 - Women's	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1178	Northeast General Restroom 06 - Women's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1179	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1180	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1181	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1182	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1183	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1184	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1185	Northeast General Restroom 06 - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1186	Northeast General Restroom 06 - Women's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1187	Northeast General Restroom 07 - Basketball - Men's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1
Burt Aaronson South County Regional	1188	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1189	Northeast General Restroom 07 - Basketball - Men's	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1190	Northeast General Restroom 07 - Basketball - Men's	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1191	Northeast General Restroom 07 - Basketball - Men's	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Burt Aaronson South County Regional	1192	Northeast General Restroom 07 - Basketball - Men's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1193	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1194	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1195	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1196	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1197	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1198	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1199	Northeast General Restroom 07 - Basketball - Men's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1200	Northeast General Restroom 07 - Basketball - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1201	Northeast General Restroom 07 - Basketball - Men's	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1202	Northeast General Restroom 07 - Basketball - Women's	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1203	Northeast General Restroom 07 - Basketball - Women's	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1204	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1205	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1206	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1207	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1208	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1209	Northeast General Restroom 07 - Basketball - Women's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1210	Northeast General Restroom 07 - Basketball - Women's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1211	Northeast General Restroom 07 - Basketball - Women's	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,908.75	1	each	\$4,908.75	1
Burt Aaronson South County Regional	1212	Northeast General ORAR At Pavilions 1-5	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1213	Northeast General ORAR At Pavilions 1-5	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Burt Aaronson South County Regional	1214	Northeast General ORAR At Pavilions 1-5	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Burt Aaronson South County Regional	1215	Northeast General ORAR At Shelters 12-17	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Burt Aaronson South County Regional	1216	Northeast General ORAR At Shelters 12-17	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Burt Aaronson South County Regional	1217	Northeast General Cypress Pavilion (03)	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1218	Northeast General Cypress Pavilion (03)	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	35	each	\$3,368.75	5
Burt Aaronson South County Regional	1219	Northeast General Shelters 01, 02, 04, 05	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
Burt Aaronson South County Regional	1220	Northeast General Shelters 01, 02, 04, 05	Outdoor Recreation Access Route	Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1221	Northeast General Shelters 01, 02, 04, 05	Shelters/Picnic Areas (C)	Remount garbage cans to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Repair grills that do not spin so they have compliant 30" by 48" clear ground space at front of grill.	\$350.00	2	each	\$700.00	5
Burt Aaronson South County Regional	1222	Northeast General Shelters 01, 02, 04, 05	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1223	Northeast General Pond Apple Pavilion (08)	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	10	each	\$962.50	5
Burt Aaronson South County Regional	1224	Northeast General Pond Apple Pavilion (08)	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Burt Aaronson South County Regional	1225	Northeast General Pond Apple Pavilion (08)	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	5
Burt Aaronson South County Regional	1226	Northeast General Pavilions 09, 10, 11	Shelters, Picnic Facilities (C)	Relocate garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1227	Northeast General Pavilions 09, 10, 11	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	2	each	\$700.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1228	Northeast General Pavilions 09, 10, 11	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1229	Northeast General Shelter 12	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1230	Northeast General Shelter 12	Outdoor Recreation Access Route	Relocate garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1231	Northeast General Shelter 12	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1232	Northeast General Shelter 13	Outdoor Recreation Access Route	Relocate one garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1233	Northeast General Shelter 13	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1234	Northeast General Shelter 14	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1235	Northeast General Shelter 14	Outdoor Recreation Access Route	Relocate garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1236	Northeast General Shelter 14	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1237	Northeast General Shelter 15	Outdoor Recreation Access Route	Relocate garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1238	Northeast General Shelter 15	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1239	Northeast General Shelter 16	Outdoor Recreation Access Route	Relocate garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1240	Northeast General Shelter 16	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1241	Northeast General Shelter 17	Shelters/Picnic Areas (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Repair grill so it spins and has 30" by 48" clear ground space facing front of grill.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1242	Northeast General Shelter 18	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1244	Northeast General Shelter 18	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1245	Northeast General Shelter 18	Outdoor Recreation Access Route	Relocate garbage can to be along an accessible route.	\$0.00	1	staff time	\$0.00	5
Burt Aaronson South County Regional	1246	Northeast General Shelter 18	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Repair grills so they spin to provide 30" by 48" clear ground space at front of grill.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1247	Northeast General Shelter 19 (Close To Pickle Ball Courts)	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1248	Northeast General Shelter 19 (Close To Pickle Ball Courts)	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Repair grill so it spins to provide 30" by 48" at front of grill.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1249	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1250	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1251	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	45	each	\$2,664.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1252	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	280	sq ft	\$34,300.00	5
Burt Aaronson South County Regional	1253	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1254	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Burt Aaronson South County Regional	1255	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	140	sq ft	\$17,150.00	5
Burt Aaronson South County Regional	1256	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	N/A	\$96.25	5
Burt Aaronson South County Regional	1257	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
Burt Aaronson South County Regional	1258	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
Burt Aaronson South County Regional	1259	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	30	each	\$1,776.00	5
Burt Aaronson South County Regional	1260	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	720	sq ft	\$88,200.00	5
Burt Aaronson South County Regional	1261	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1262	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Burt Aaronson South County Regional	1263	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Burt Aaronson South County Regional	1264	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1265	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Burt Aaronson South County Regional	1266	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2400	sq ft	\$294,000.00	5
Burt Aaronson South County Regional	1267	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Burt Aaronson South County Regional	1268	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1269	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
Burt Aaronson South County Regional	1270	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	staff time	\$58,800.00	5
Burt Aaronson South County Regional	1271	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	210	sq ft	\$25,725.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1272	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	15	lin ft	\$888.00	5
Burt Aaronson South County Regional	1273	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1274	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Burt Aaronson South County Regional	1275	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Burt Aaronson South County Regional	1276	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
Burt Aaronson South County Regional	1277	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Burt Aaronson South County Regional	1278	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Burt Aaronson South County Regional	1279	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	3	lin ft	\$177.60	5
Burt Aaronson South County Regional	1280	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Burt Aaronson South County Regional	1281	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	15	sq ft	\$888.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1282	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	45	lin ft	\$2,664.00	5
Burt Aaronson South County Regional	1283	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	3	lin ft	\$177.60	5
Burt Aaronson South County Regional	1284	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Burt Aaronson South County Regional	1285	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
Burt Aaronson South County Regional	1286	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1287	Northeast General Trail - Surface (Area Between Yamoto Rd And Old Pump House Rd)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
Burt Aaronson South County Regional	1288	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	520	sq ft	\$63,700.00	5
Burt Aaronson South County Regional	1289	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	15	lin ft	\$888.00	5
Burt Aaronson South County Regional	1290	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1291	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	280	sq ft	\$34,300.00	5
Burt Aaronson South County Regional	1292	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1293	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	525	sq ft	\$64,312.50	5
Burt Aaronson South County Regional	1294	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Aaronson South County Regional	1295	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Burt Aaronson South County Regional	1296	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1297	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Burt Aaronson South County Regional	1298	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Burt Aaronson South County Regional	1299	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	840	sq ft	\$102,900.00	5
Burt Aaronson South County Regional	1300	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Burt Aaronson South County Regional	1301	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Burt Aaronson South County Regional	1302	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	15	lin ft	\$888.00	5
Burt Aaronson South County Regional	1303	Northeast General Trail - Surface (From Old Pump House Rd Around Tennis Complex)	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Burt Aaronson South County Regional	1304	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1305	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	128	sq ft	\$15,680.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1306	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	35	lin ft	\$2,072.00	5
Burt Aaronson South County Regional	1307	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Burt Aaronson South County Regional	1308	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	216	sq ft	\$26,460.00	5
Burt Aaronson South County Regional	1309	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1310	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1311	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	232	sq ft	\$28,420.00	5
Burt Aaronson South County Regional	1312	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	232	sq ft	\$28,420.00	5
Burt Aaronson South County Regional	1313	Northeast General Trail Surface Apple Pond Pavilion Loop	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1314	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1315	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	152	sq ft	\$18,620.00	5
Burt Aaronson South County Regional	1316	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1317	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	656	sq ft	\$80,360.00	5
Burt Aaronson South County Regional	1318	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Burt Aaronson South County Regional	1319	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	96	sq ft	\$11,760.00	5
Burt Aaronson South County Regional	1320	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	336	sq ft	\$41,160.00	5
Burt Aaronson South County Regional	1321	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	48	sq ft	\$5,880.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1322	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1323	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	704	sq ft	\$86,240.00	5
Burt Aaronson South County Regional	1324	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	136	sq ft	\$16,660.00	5
Burt Aaronson South County Regional	1325	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2272	sq ft	\$278,320.00	5
Burt Aaronson South County Regional	1326	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1327	Northeast General Trail Surface Apple Pond Pavilion Loop	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Burt Aaronson South County Regional	1328	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Burt Aaronson South County Regional	1329	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Burt Aaronson South County Regional	1330	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	35	lin ft	\$2,072.00	5
Burt Aaronson South County Regional	1331	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Burt Aaronson South County Regional	1332	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Burt Aaronson South County Regional	1333	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1334	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Burt Aaronson South County Regional	1335	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Remove bollard to correct trail width to min 36" clear width with 60" turning spaces every 1000'.	\$350.00	1	each	\$350.00	5
Burt Aaronson South County Regional	1336	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Burt Aaronson South County Regional	1337	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Burt Aaronson South County Regional	1338	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1339	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Burt Aaronson South County Regional	1340	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1341	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1342	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1343	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1344	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Burt Aaronson South County Regional	1345	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1400	sq ft	\$171,500.00	5
Burt Aaronson South County Regional	1346	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	210	sq ft	\$25,725.00	5
Burt Aaronson South County Regional	1347	Northeast General Trail - Surface (From Intersection Of Striker Circle And Regional Park Road Arou	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Aaronson South County Regional	1348	Northeast General Trail - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Burt Aaronson South County Regional	1350	Ballfields 8-11 - Parking	Parking - Off Street	Improve dispersement of accessible stalls to be on the shortest AR to the building entries or each park feature served.	\$367.50	7	each	\$2,572.50	1
Burt Aaronson South County Regional	1351	Ballfields 8-11 - Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Burt Aaronson South County Regional	1352	Ballfields 8-11 - Parking	Parking - Off Street	Raise obstructions over van stalls to provide 98" vertical clearance.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1353	Ballfields 8-11 - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	11	each	\$33,687.50	1
Burt Aaronson South County Regional	1354	Ballfields 8-11 - Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface.  Correct or fill gaps to .5" max.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$8,496.25	1	each	\$8,496.25	1
Burt Aaronson South County Regional	1355	Ballfields 8-11 - Parking	Parking - Off Street	Acquire and mount correct fine sign for all stalls.	\$210.00	3	each	\$630.00	1
Burt Aaronson South County Regional	1356	Ballfields 8-11 - Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1357	Ballfields 8-11 - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1358	Ballfields 8-11 - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	14	each	\$1,029.00	1
Burt Aaronson South County Regional	1359	Ballfields 8-11 - EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	2	each	\$118.40	1
Burt Aaronson South County Regional	1360	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1361	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1362	Ballfields 8-11 - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1363	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	30	each	\$2,887.50	1
Burt Aaronson South County Regional	1364	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	17	each	\$1,636.25	1
Burt Aaronson South County Regional	1365	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	30	each	\$2,887.50	1
Burt Aaronson South County Regional	1366	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	15	each	\$1,443.75	1
Burt Aaronson South County Regional	1367	Ballfields 8-11 - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	15	each	\$1,443.75	1
Burt Aaronson South County Regional	1368	Ballfields 8-11 - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Burt Aaronson South County Regional	1369	Ballfields 8-11 - EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1370	Ballfields 8-11 - EAR	Accessible Routes	Raise roof to min 80", or pad object to prevent hazard in overhead clearance.	\$1,540.00	8	each	\$12,320.00	2
Burt Aaronson South County Regional	1371	Ballfields 8-11 - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Burt Aaronson South County Regional	1372	Ballfields 8-11 - Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1373	Ballfields 8-11 - Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1374	Ballfields 8-11 - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Burt Aaronson South County Regional	1376	Ballfields 8-11 - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Burt Aaronson South County Regional	1377	Ballfields 8-11 - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Burt Aaronson South County Regional	1378	Ballfields 8-11 - Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1379	Ballfields 8-11 - Elements	Clear Floor Space	Relocate garbage can from CGS of bag dispenser.	\$0.00	1	staff time	\$0.00	2
Burt Aaronson South County Regional	1380	Ballfields 8-11 - Press Box	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1381	Ballfields 8-11 - Press Box	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Burt Aaronson South County Regional	1382	Ballfields 8-11 - Press Box	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1383	Ballfields 8-11 - Press Box	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	1384	Ballfields 8-11 - Press Box	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	17	each	\$2,125.00	5
Burt Aaronson South County Regional	1385	Ballfields 8-11 - Press Box	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Burt Aaronson South County Regional	1386	Ballfields 8-11 - Press Box	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	1387	Batting Cages	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Remount gate hardware to between 34" and 48" AGL.	\$1,106.50	1	each	\$1,106.50	2
Burt Aaronson South County Regional	1388	Ballfield 8	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	1389	Ballfield 8	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench. In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	1	each	\$840.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1392	Ballfield 8	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Burt Aaronson South County Regional	1394	Ballfield 9	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	1397	Ballfield 9	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	65	lin ft	\$3,848.00	4
Burt Aaronson South County Regional	1398	Ballfield 9	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	45	lin ft	\$2,664.00	4
Burt Aaronson South County Regional	1400	Ballfield 10	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Burt Aaronson South County Regional	1401	Ballfield 10	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	1402	Ballfield 10	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench. In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
Burt Aaronson South County Regional	1404	Ballfield 10	Reach Ranges	Lower operating mechanisms to max 48" aff to highest operable part. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Burt Aaronson South County Regional	1406	Ballfield 11	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Burt Aaronson South County Regional	1408	Ballfield 11	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench. In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
Burt Aaronson South County Regional	1410	Ballfields 8-11 - Men's Restroom	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	2	each	\$192.50	1
Burt Aaronson South County Regional	1411	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1412	Ballfields 8-11 - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1413	Ballfields 8-11 - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1414	Ballfields 8-11 - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1415	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1416	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1417	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1418	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1419	Ballfields 8-11 - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Burt Aaronson South County Regional	1420	Ballfields 8-11 - Men's Restroom	Plumbing Fixtures & Elements	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1421	Ballfields 8-11 - Men's Restroom	Hazards	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Burt Aaronson South County Regional	1422	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1423	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1424	Ballfields 8-11 - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1425	Ballfields 8-11 - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Aaronson South County Regional	1426	Ballfields 8-11 - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1427	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1428	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1429	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1430	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1431	Ballfields 8-11 - Women's Restroom	Plumbing Fixtures & Elements	Adjust stall door to be self-closing.					
Burt Aaronson South County Regional	1432	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1433	Ballfields 8-11 - Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1432	Ballfields 8-11 - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1433	Ballfields 8-11 - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Burt Aaronson South County Regional	1434	Ballfields 8-11 - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1
Burt Aaronson South County Regional	1436	Northeast Softball - Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Burt Aaronson South County Regional	1437	Northeast Softball - Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1438	Northeast Softball - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Burt Aaronson South County Regional	1439	Northeast Softball - Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1440	Northeast Softball - Parking	Parking - Off Street	Replace faded sign and mount at appropriate height and location for the accessible parking stall.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1441	Northeast Softball - Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1442	Northeast Softball - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1443	Northeast Softball - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	7	each	\$514.50	1
Burt Aaronson South County Regional	1444	Northeast Softball - EAR	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1445	Northeast Softball - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	540	sq ft	\$66,150.00	1
Burt Aaronson South County Regional	1446	Northeast Softball - EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
Burt Aaronson South County Regional	1447	Northeast Softball - EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1448	Northeast Softball - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1449	Northeast Softball - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1450	Northeast Softball - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1451	Northeast Softball - EAR	Accessible Routes	Replace drain grate with one having openings max .5".	\$5,000.00	1	each	\$5,000.00	2
Burt Aaronson South County Regional	1452	Northeast Softball - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Burt Aaronson South County Regional	1453	Northeast Softball - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Aaronson South County Regional	1454	Northeast Softball - Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	45	lin ft	\$2,664.00	2
Burt Aaronson South County Regional	1456	Northeast Softball - Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Burt Aaronson South County Regional	1457	Northeast Softball - Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Aaronson South County Regional	1458	Northeast Softball - Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Burt Aaronson South County Regional	1460	Northeast Softball - Concession Building	Doors	Provide required maneuvering clearance on push side of door. Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1461	Northeast Softball - Concession Building	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Burt Aaronson South County Regional	1462	Northeast Softball - Concession Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1463	Northeast Softball - Concession Building	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Burt Aaronson South County Regional	1464	Northeast Softball - Concession Building	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	17	each	\$2,125.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1465	Northeast Softball - Concession Building	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Burt Aaronson South County Regional	1466	Northeast Softball - Concession Building	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
Burt Aaronson South County Regional	1467	Northeast Softball - Concession Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$2,003.75	1	each	\$2,003.75	1
Burt Aaronson South County Regional	1468	Northeast Softball - Field 4	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Burt Aaronson South County Regional	1469	Northeast Softball - Field 4	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
Burt Aaronson South County Regional	1470	Northeast Softball - Field 5	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
Burt Aaronson South County Regional	1471	Northeast Softball - Field 5	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Burt Aaronson South County Regional	1472	Northeast Softball - Field 6	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
Burt Aaronson South County Regional	1473	Northeast Softball - Field 6	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Burt Aaronson South County Regional	1474	Northeast Softball - Field 7	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
Burt Aaronson South County Regional	1475	Northeast Softball - Field 7	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Burt Aaronson South County Regional	1476	Northeast Softball - Men's Restroom 02	Doors	Provide required maneuvering clearance on push side of door.	\$1,750.00	1	each	\$1,750.00	1
Burt Aaronson South County Regional	1477	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1478	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1479	Northeast Softball - Men's Restroom 02	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1480	Northeast Softball - Men's Restroom 02	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1481	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1482	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1483	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1484	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1485	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1486	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1487	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Relocate hand dryer to widen AR to stall to min 42" clear width.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1488	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Burt Aaronson South County Regional	1488	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1489	Northeast Softball - Men's Restroom 02	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1490	Northeast Softball - Men's Restroom 02	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.  Pricing for one hand dryer in a previous finding.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1491	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1492	Northeast Softball - Women's Restroom 02	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1493	Northeast Softball - Women's Restroom 02	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Burt Aaronson South County Regional	1494	Northeast Softball - Women's Restroom 02	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1495	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012	\$2,380.00	1	each	\$2,380.00	1
Burt Aaronson South County Regional	1496	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Aaronson South County Regional	1497	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Aaronson South County Regional	1498	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Aaronson South County Regional	1499	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1500	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Aaronson South County Regional	1501	Northeast Softball - Women's Restroom 02	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Aaronson South County Regional	1502	Northeast Softball - Women's Restroom 02	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Aaronson South County Regional	1503	Northeast Softball - Women's Restroom 02	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Burt Aaronson South County Regional	1504	Northeast Softball - Women's Restroom 02	Doors	Provide required maneuvering clearance on push side of door.	\$1,750.00	1	each	\$1,750.00	1
Burt Reynolds Park	2	Parking - West Boat Launch Standard Sized	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Reynolds Park	3	Parking - West Boat Launch Standard Sized	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	4	Parking - West Boat Launch Standard Sized	Parking - Off Street	Repaint stall to eliminate gaps in paint. Replace drain grate with one having openings max .5".	\$2,600.00	1	each	\$2,600.00	1
Burt Reynolds Park	5	Parking - West Boat Launch Standard Sized	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Reynolds Park	7	Parking - West Boat Launch Boat Trailer	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Burt Reynolds Park	8	Parking - West Boat Launch Boat Trailer	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Burt Reynolds Park	9	Parking - West Boat Launch Boat Trailer	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	10	Parking - West Boat Launch Boat Trailer	Parking - Off Street	Repaint access aisles to eliminate gaps and cracks. Establish protocols for regular and frequent inspection and maintenance of parking surface. Replace drain grate with one having openings max .5".	\$2,700.00	1	each	\$2,700.00	1
Burt Reynolds Park	12	Parking - Shelter 7	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
Burt Reynolds Park	13	Parking - Shelter 7	Parking - Off Street	Add van parking sign to accessible stall and repaint stall and access aisle to 12' and 5'. See previous finding for cost.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	14	Parking - Shelter 7	Parking - Off Street	Leave as is, lack of parking sign, exempt if lot includes less than 4 parking spaces.	\$0.00	1	each	\$0.00	4
Burt Reynolds Park	15	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Create three more oversized 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Burt Reynolds Park	16	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Burt Reynolds Park	17	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	18	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Burt Reynolds Park	19	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	20	Parking - East Side, Oversized Spaces Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Burt Reynolds Park	22	Parking - Shelter 8	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Burt Reynolds Park	23	Parking - Shelter 8	Parking - Off Street	Leave as is, lack of parking sign, exempt if lot includes less than 4 parking spaces.	\$0.00	1	each	\$0.00	4
Burt Reynolds Park	24	Parking - Shelter 8	Parking - Off Street	Leave as is, lack of parking sign, exempt if lot includes less than 4 parking spaces.	\$0.00	1	each	\$0.00	4
Burt Reynolds Park	26	Parking - East Side, Two Accessible Spaces Near Underpass Walkway	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Burt Reynolds Park	27	Parking - East Side, Two Accessible Spaces Near Underpass Walkway	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Burt Reynolds Park	28	Parking - East Side, Two Accessible Spaces Near Underpass Walkway	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Burt Reynolds Park	29	Parking - Standard Sized Lot Near Play Area	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Burt Reynolds Park	30	Parking - Standard Sized Lot Near Play Area	Parking - Off Street	Relocate one stall and access aisle to be on the shortest AR to the shelters.	\$367.50	1	each	\$367.50	1
Burt Reynolds Park	31	Parking - Standard Sized Lot Near Play Area	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	32	Parking - Grass Surfaced Overflow Trailer Parking	Parking - Off Street	Create two oversized 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Burt Reynolds Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	36	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	37	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Burt Reynolds Park	39	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Burt Reynolds Park	40	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Burt Reynolds Park	41	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Burt Reynolds Park	42	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	45	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	47	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	48	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	2	lin ft	\$118.40	1
Burt Reynolds Park	49	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	50	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	51	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Reynolds Park	52	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	350	sq ft	\$42,875.00	1
Burt Reynolds Park	53	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Reynolds Park	54	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Burt Reynolds Park	55	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Reynolds Park	56	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
Burt Reynolds Park	57	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	12	each	\$1,155.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	58	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Burt Reynolds Park	59	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Burt Reynolds Park	60	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Reynolds Park	61	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1
Burt Reynolds Park	62	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	63	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	64	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Burt Reynolds Park	65	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	66	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Burt Reynolds Park	67	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Burt Reynolds Park	68	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	69	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
Burt Reynolds Park	70	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	71	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	72	Exterior Accessible Route	Detectable Warnings	Re-install detectable warning perpendicular to the direction of the ramp run, where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Burt Reynolds Park	73	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	74	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Burt Reynolds Park	75	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	96	sq ft	\$11,760.00	1
Burt Reynolds Park	76	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	78	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Burt Reynolds Park	79	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Burt Reynolds Park	80	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Burt Reynolds Park	81	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Burt Reynolds Park	82	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	83	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Burt Reynolds Park	84	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Burt Reynolds Park	85	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	86	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Burt Reynolds Park	87	West Boat Launch	Accessible Routes	Create an accessible route to the boat pier or make corrections for a compliant route.  Correct or fill gaps to be max .5".  Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$96.25	5	each	\$481.25	2
Burt Reynolds Park	88	West Boat Launch	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	42	each	\$36,750.00	2
Burt Reynolds Park	89	East Boat Launch	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Reynolds Park	90	East Boat Launch	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	6	each	\$5,250.00	2
Burt Reynolds Park	91	East Boat Launch	Dining, Bar and Work Surfaces	Replace or add one work surface max 34" to surface and allowing knee and toe clearance.  Replace operable part with one usable without a tight pinch or grasp.	\$2,450.00	1	each	\$2,450.00	2
Burt Reynolds Park	92	East Boat Launch	Accessible Routes	Create an outdoor accessible route to the boat pier or make corrections for a compliant route.  Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.  Correct or fill gaps to be max .5".	\$11,986.00	1	each	\$11,986.00	1
Burt Reynolds Park	93	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to at least one of each element within the site.	\$59.20	25	lin ft	\$1,480.00	2
Burt Reynolds Park	94	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	15	lin ft	\$888.00	4
Burt Reynolds Park	95	Waterway Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Burt Reynolds Park	96	Waterway Pavilion	Picnic Tables (C)	Rearrange tables to provide a 36" clearance around all sides of the accessible tables.	\$0.00	2	staff time	\$0.00	5
Burt Reynolds Park	97	Waterway Pavilion	Shelters/Picnic Areas (C)	Replace or lower grill to max height of cooking surface 34".  Replace operable parts with ones usable without a tight pinch or grasp.	\$460.00	1	each	\$460.00	5
Burt Reynolds Park	98	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Reynolds Park	99	Picnic Areas	Picnic Tables (C)	Replace one more picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Burt Reynolds Park	100	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	4	lin ft	\$236.80	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	101	Picnic Areas	Shelters/Picnic Areas (C)	Replace or lower grill to max height of cooking surface 34".	\$250.00	1	each	\$250.00	5
Burt Reynolds Park	102	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Reynolds Park	103	Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Burt Reynolds Park	104	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Burt Reynolds Park	105	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
Burt Reynolds Park	106	Picnic Areas	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Burt Reynolds Park	107	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	4	lin ft	\$236.80	5
Burt Reynolds Park	108	Picnic Areas	Shelters/Picnic Areas (C)	Raise water spout to 28" to 36" above the ground.  Replace faucet controls with ones operable without a tight pinch or grasp.  Relocate garbage can to be along AR with max slope of 2.08% in CGS.	\$210.00	1	each	\$210.00	5
Burt Reynolds Park	109	Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other shelters as accessible.	\$59.20	30	lin ft	\$1,776.00	4
Burt Reynolds Park	110	Picnic Areas	Picnic Tables (C)	Replace picnic tables with one of an accessible design as a smart practice; in the alternative, leave as is and designate other shelters as accessible.	\$1,120.00	14	each	\$15,680.00	4
Burt Reynolds Park	111	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.  Relocate garbage can to along an accessible route without obstructions and with max slope of 2.08% in CGS.  In the alternative, leave as is and designate other shelters as accessible.	\$59.20	35	lin ft	\$2,072.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	112	Picnic Areas	Shelters/Picnic Areas (C)	Raise water spout to 28" to 36" above the ground.  Replace water spout handles with ones operable without a tight pinch or grasp.  Relocate garbage can at Shelter 1 along an accessible route with max slopes of 2.08% in CGS.  In the alternative, leave as is and designate other bshelters as accessible.	\$420.00	1	each	\$420.00	4
Burt Reynolds Park	113	Park Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Burt Reynolds Park	116	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
Burt Reynolds Park	117	Park Elements	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Burt Reynolds Park	118	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Reynolds Park	121	Park Elements	ATM's and Fare Machines	Contact provider to replace parking pay kiosk with a compliant model.	\$5,000.00	1	each	\$5,000.00	3
Burt Reynolds Park	122	Park Elements	ATM's and Fare Machines	Replace parking pay kiosk with one that has compliant features.  Pricing in the previous finding.	\$0.00	1	each	\$0.00	2
Burt Reynolds Park	123	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	25	lin ft	\$1,480.00	2
Burt Reynolds Park	124	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Burt Reynolds Park	125	Park Elements	ATM's and Fare Machines	Contact provider to replace parking pay kiosks with a compliant models.	\$5,000.00	2	each	\$10,000.00	3
Burt Reynolds Park	126	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Burt Reynolds Park	127	Park Elements	ATM's and Fare Machines	Replace parking pay kiosks with ones that have compliant features.  Pricing in a previous finding.	\$0.00	2	each	\$0.00	3
Burt Reynolds Park	128	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
Burt Reynolds Park	131	West - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Burt Reynolds Park	132	West - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Reynolds Park	133	West - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	134	West - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Reynolds Park	135	West - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Reynolds Park	136	West - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	137	West - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	138	West - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Reynolds Park	139	West - Men's Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	140	West - Women's Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	141	West - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Reynolds Park	142	West - Women's Restroom	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	143	West - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	144	West - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Reynolds Park	145	East - Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	146	East - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	147	East - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Reynolds Park	148	East - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	149	East - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Burt Reynolds Park	150	East - Men's Restroom	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	151	East - Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	152	East - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Burt Reynolds Park	153	East - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. In the alternative, leave as is citing construction tolerance.	\$393.75	1	each	\$393.75	1
Burt Reynolds Park	154	East - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Burt Reynolds Park	155	East - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	156	East - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Burt Reynolds Park	157	East - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Burt Reynolds Park	159	East - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	160	East - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Burt Reynolds Park	161	East - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Burt Reynolds Park	162	East - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Burt Reynolds Park	163	East - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Burt Reynolds Park	164	Playground	Play Area	Repair, bevel or ramp CIL at playground entry/border. In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	1	each	\$96.25	4
Burt Reynolds Park	165	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Burt Reynolds Park	166	Playground	Play Area	Raise decks/play component to provide 80" overhead clearance to GLPC below. In the alternative, leave as is as correction may be technically infeasible.	\$2,800.00	1	each	\$2,800.00	4
Burt Reynolds Park	167	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Reynolds Park	168	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Burt Reynolds Park	169	Playground	Play Area	Add two more GLPCs of two different types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
Burt Reynolds Park	170	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$4,092.00	1	each	\$4,092.00	3
Burt Reynolds Park	171	Trail Surface	Outdoor - Trails (C)	Work with trail owner to replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Burt Reynolds Park	172	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	420	sq ft	\$51,450.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	2	East Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Buttonwood Park	3	East Parking	Parking - Off Street	Resurface and repaint stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	2	each	\$5,600.00	1
Buttonwood Park	4	East Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Buttonwood Park	5	East Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Buttonwood Park	6	North Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Buttonwood Park	7	North Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Buttonwood Park	8	North Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Buttonwood Park	9	North Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Buttonwood Park	10	North Parking	Parking - Off Street	Repaint 3 stalls and access aisles to eliminate gaps and cracks.  Resurface 2 accessible stalls and access aisles with a firm, stable, and slip. resistant material.	\$1,164.10	5	each	\$5,820.50	1
Buttonwood Park	11	North Parking	Parking - Off Street	Remove sign from 3rd stall at basketball, as it does not meet van space width requirements.  Add two van parking signs to first stall at basketball, one accessible stall at fields 2 and 3, and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Buttonwood Park	12	North Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Buttonwood Park	13	Overflow Parking	Parking - Off Street	Create three or more 12' accessible parking stalls in paved lot adjacent, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls and leave as is overflow lot.	\$1,589.00	3	each	\$4,767.00	1
Buttonwood Park	14	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Buttonwood Park	15	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	2	each	\$1,750.00	1
Buttonwood Park	16	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%.	\$1,015.00	1	each	\$1,015.00	1
Buttonwood Park	17	Exterior Accessible Route	Detectable Warnings	Replace existing detectable warning with one with visual contrast and compliant truncated dome template integrated into the walking surface.	\$329.00	1	each	\$329.00	5
Buttonwood Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	15	each	\$1,443.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	23	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Buttonwood Park	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	7	each	\$673.75	1
Buttonwood Park	25	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%. In the alternative, leave as is citing construction tolerance.	\$1,015.00	1	each	\$1,015.00	4
Buttonwood Park	26	Exterior Accessible Route	Curb Ramps	Recut or repour ramp to be min. 36" clear width.	\$1,487.00	2	each	\$2,974.00	1
Buttonwood Park	27	Exterior Accessible Route	Curb Ramps	Correct curb ramp landing slope to max 2.08%	\$1,487.50	1	each	\$1,487.50	1
Buttonwood Park	28	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Buttonwood Park	29	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Buttonwood Park	30	Exterior Accessible Route	Detectable Warnings	Replace existing detectable warnings with ones with visual contrast and compliant truncated dome template integrated into the walking surface.	\$329.00	4	each	\$1,316.00	5
Buttonwood Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	205	sq ft	\$25,112.50	1
Buttonwood Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Buttonwood Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Buttonwood Park	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	255	sq ft	\$31,237.50	1
Buttonwood Park	35	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Buttonwood Park	36	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Buttonwood Park	37	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Buttonwood Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	210	sq ft	\$25,725.00	1
Buttonwood Park	40	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Buttonwood Park	41	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Buttonwood Park	42	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	6	each	\$1,974.00	5
Buttonwood Park	43	Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Buttonwood Park	44	Exterior Accessible Route	Curb Ramps	Correct slope of side flares to max 8.33%.	\$1,015.00	2	each	\$2,030.00	1
Buttonwood Park	45	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	30	lin ft	\$1,776.00	4
Buttonwood Park	47	Sports Fields/Courts	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48". In the alternative, leave as is and designate other County rectangular fields accessible.	\$1,225.00	2	each	\$2,450.00	4
Buttonwood Park	48	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	51	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Buttonwood Park	52	Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Buttonwood Park	53	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow to max 15 degrees measured from the front of the unit, and so stream does not flow away from fountain.	\$420.00	1	each	\$420.00	2
Buttonwood Park	54	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Buttonwood Park	55	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Buttonwood Park	56	Park Elements	Park Site (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Buttonwood Park	57	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$122.50	25	sq ft	\$3,062.50	4
Buttonwood Park	58	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$96.25	1	each	\$96.25	4
Buttonwood Park	59	Shelters/Picnic Areas	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$1,120.00	3	each	\$3,360.00	4
Buttonwood Park	60	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Buttonwood Park	61	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  Reposition accessible picnic tables to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Buttonwood Park	62	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
Buttonwood Park	63	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Provide minimum two accessible picnic tables including required 36" clear ground space around all usable portions of the table as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$2,486.00	1	each	\$2,486.00	4
Buttonwood Park	64	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$96.25	2	each	\$192.50	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	65	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$122.50	120	sq ft	\$14,700.00	4
Buttonwood Park	66	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$122.50	25	sq ft	\$3,062.50	4
Buttonwood Park	67	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$1,120.00	2	each	\$2,240.00	4
Buttonwood Park	68	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Provide an AR and accessible tables to shelter/picnic area to achieve the required number accessible.  Pricing in previous findings.  In the alternative, leave as is and designate other County shelters and picnic areas accessible.	\$0.00	1	each	\$0.00	4
Buttonwood Park	69	2-5 Play Area	Play Area	Correct or repair running slope of designated entry to max 5%. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	4	each	\$2,800.00	4
Buttonwood Park	70	2-5 Play Area	Play Area	Install transfer system on play structure with access to 50% of the EPC's, if feasible. In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4
Buttonwood Park	72	2-5 Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" aff; or provide another swing component that meets entry height requirements. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Buttonwood Park	73	2-5 Play Area	Play Area	Add 3 more GLPCs of 3 types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	3	each	\$8,400.00	4
Buttonwood Park	76	5-12 Play Area	Play Area	Add one more GLPCs of any other type to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Buttonwood Park	77	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	78	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Buttonwood Park	79	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Buttonwood Park	80	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	81	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Buttonwood Park	82	Women's Restroom	Toilet and Bathing Rooms	Replace or remount grab bar with a 1.5" max spacing between wall and bar.	\$393.75	1	each	\$393.75	1
Buttonwood Park	83	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Buttonwood Park	84	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	85	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Buttonwood Park	86	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Buttonwood Park	87	Men's Restroom	Toilet and Bathing Rooms	Replace one mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Buttonwood Park	88	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Buttonwood Park	89	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Buttonwood Park	90	Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Buttonwood Park	91	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	92	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet. Leave as is if installed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Buttonwood Park	93	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Buttonwood Park	94	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	95	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Buttonwood Park	96	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Buttonwood Park	97	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	98	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	99	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Buttonwood Park	100	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,712.00	1	each	\$5,712.00	3
Buttonwood Park	101	Employee Spaces	Ramps (Not Curb Ramps)	Widen ramp clear width to min 36".  Provide handrails for ramps with rise greater than 6".	\$8,102.50	1	each	\$8,102.50	3
Buttonwood Park	102	Employee Spaces	Accessible Routes	Widen EAR to min 36" clear width.	\$59.20	25	lin ft	\$1,480.00	3
Buttonwood Park	103	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	3
Buttonwood Park	104	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Buttonwood Park	105	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.  Repair, bevel, or ramp CIL along AR.	\$288.75	1	each	\$288.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Buttonwood Park	106	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Fill gaps at door entries to max .5".	\$3,158.75	1	each	\$3,158.75	3
Buttonwood Park	107	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	3
Buttonwood Park	108	Public Spaces	Reach Ranges	Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$0.00	3	staff time	\$0.00	3
Buttonwood Park	109	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	3
Buttonwood Park	110	Maintenance Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Buttonwood Park	111	Maintenance Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	3
Buttonwood Park	112	Maintenance Restroom	Reach Ranges	Lower operating mechanisms of soap dispenser, paper towel dispenser, and light switch to max 48" above the finished floor (AFF) to highest operable part.  Lower outlet to max 44" above the finished floor (AFF) for a forward reach over sink or counter.  Leave as is light switch and outlet if constructed prior to March 15, 2012.	\$175.00	4	each	\$700.00	3
Buttonwood Park	113	Maintenance Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if installed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	3
Buttonwood Park	114	Maintenance Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove storage from grab bar.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	115	Maintenance Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Buttonwood Park	116	Maintenance Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Cabana Colony Park	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Cabana Colony Park	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Cabana Colony Park	3	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	500	sq ft	\$61,250.00	1
Cabana Colony Park	4	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	350	sq ft	\$42,875.00	1
Cabana Colony Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	250	sq ft	\$30,625.00	1
Cabana Colony Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	50	sq ft	\$6,125.00	1
Cabana Colony Park	7	Park Element	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	300	sq ft	\$21,000.00	2
Cabana Colony Park	8	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08% in at least 1 bench.	\$1,470.00	1	each	\$1,470.00	5
Cabana Colony Park	12	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Cabana Colony Park	13	Park Element	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Cabana Colony Park	14	Park Element	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	2
Cabana Colony Park	16	Sports Courts/Fields	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	1	each	\$840.00	2
Cabana Colony Park	17	Picnic Area	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.	\$59.20	10	lin ft	\$592.00	5
Cabana Colony Park	18	Picnic Area	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	2	each	\$4,972.00	5
Cabana Colony Park	21	Play Area (2-5)	Play Area	Provide CFS and turning space at all GLPCs	\$154.00	1	each	\$154.00	2
Cabana Colony Park	23	Play Area (2-5)	Play Area	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface.  Repair damaged areas on playground surface to eliminate gaps and changes in level.	\$70.00	16	sq ft	\$1,120.00	2
Cabana Colony Park	24	Play Area (5-12)	Play Area	Relocate informational signage to be along the AR with a 30" by 48" level CFS for viewing. In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
Cabana Colony Park	25	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Cabana Colony Park	26	Play Area (5-12)	Play Area	See previous finding for correction to surface. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Cabana Colony Park	27	Play Area (5-12)	Play Area	Add another manipulable ground level play component on the route. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Cabana Colony Park	28	Play Area (5-12)	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Cabana Colony Park	29	Play Area (5-12)	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Caloosa Park	2	Parking - Sports Courts	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	2	each	\$735.00	1
Caloosa Park	3	Parking - Sports Courts	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Caloosa Park	4	Parking - Sports Courts	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	1	each	\$1,589.00	1
Caloosa Park	5	Parking - Sports Courts	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Caloosa Park	6	Parking - Sports Courts	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	4	each	\$11,200.00	1
Caloosa Park	7	Parking - Sports Courts	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	3	each	\$630.00	1
Caloosa Park	8	Parking - Sports Courts	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	5	staff time	\$0.00	1
Caloosa Park	9	Parking - Sports Courts	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Caloosa Park	10	Parking - Sports Courts	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk	\$367.50	3	each	\$1,102.50	1
Caloosa Park	11	Parking - Field 4 Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Caloosa Park	12	Parking - Fields 5 & 6 Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Caloosa Park	13	Parking - Fields 5 & 6 Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	4	staff time	\$0.00	1
Caloosa Park	14	Parking - Fields 5 & 6 Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Caloosa Park	15	Parking - Fields 5 & 6 Lot	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	16	Parking - Fields 5 & 6 Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Caloosa Park	17	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Create three or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Caloosa Park	18	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Caloosa Park	19	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Caloosa Park	20	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	3	staff time	\$0.00	1
Caloosa Park	21	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Caloosa Park	22	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Widen accessible route to min 44" clear width and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
Caloosa Park	23	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	4	each	\$294.00	1
Caloosa Park	24	Parking - Baseball/Softball Fields 7 Large Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Caloosa Park	26	Parking - Picnic Area	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	1	each	\$1,589.00	1
Caloosa Park	27	Parking - Picnic Area	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'. See previous finding for cost.	\$0.00	1	each	\$0.00	1
Caloosa Park	28	Parking - Picnic Area	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	29	Parking - Picnic Area	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.  Pricing in the previous finding.	\$0.00	1	each	\$0.00	1
Caloosa Park	30	Parking - Picnic Area	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Caloosa Park	31	Parking - Picnic Area	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	32	Parking - Picnic Area	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	33	Parking - North Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Caloosa Park	34	Parking - North Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Caloosa Park	35	Parking - North Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Caloosa Park	36	Parking - North Lot	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	4	each	\$385.00	1
Caloosa Park	37	Parking - North Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Caloosa Park	39	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Caloosa Park	40	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Caloosa Park	41	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	42	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	43	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	44	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	275	sq ft	\$33,687.50	1
Caloosa Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Caloosa Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Caloosa Park	47	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	21	lin ft	\$1,243.20	1
Caloosa Park	48	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	49	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	1	each	\$59.20	1
Caloosa Park	50	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Caloosa Park	51	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Caloosa Park	52	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Caloosa Park	53	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Caloosa Park	54	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Caloosa Park	55	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Caloosa Park	56	Exterior Accessible Route	Ramps (Not Curb Ramps)	Repair fence to widen ramp clear width to min. 36"	\$3,080.00	1	each	\$3,080.00	3
Caloosa Park	57	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	58	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Caloosa Park	59	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground. Pricing in the previous finding.	\$0.00	2	each	\$0.00	3
Caloosa Park	60	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	3
Caloosa Park	61	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Caloosa Park	62	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Caloosa Park	63	Exterior Accessible Route	Accessible Routes	Repair or reset pavers to eliminate change in level.	\$28.00	20	sq ft	\$560.00	1
Caloosa Park	64	Exterior Accessible Route	Accessible Route - Slope (C)	Resent entire paver are to correct cross slopes to max 2.08%.	\$28.00	5000	sq ft	\$140,000.00	1
Caloosa Park	65	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Caloosa Park	66	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	30	lin ft	\$1,776.00	1
Caloosa Park	67	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Caloosa Park	68	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Caloosa Park	69	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	70	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Caloosa Park	71	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Caloosa Park	72	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Caloosa Park	73	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Caloosa Park	74	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Caloosa Park	75	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Caloosa Park	76	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	1
Caloosa Park	77	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	78	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	280	sq ft	\$34,300.00	1
Caloosa Park	79	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	30	each	\$9,870.00	5
Caloosa Park	80	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Caloosa Park	81	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Caloosa Park	82	Sports Courts/Fields	Clear Floor Space	Correct or repair slope in CFS to max 2.08%; in the alternative, relocate garbage can to location with compliant CFS.	\$122.50	25	sq ft	\$3,062.50	2
Caloosa Park	83	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	5
Caloosa Park	84	Sports Courts/Fields	Reach Ranges	Lower operating mechanisms to max 48" aff to highest operable part.	\$350.00	2	each	\$700.00	2
Caloosa Park	85	Sports Courts/Fields	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	88	Sports Courts/Fields	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	2
Caloosa Park	89	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	2
Caloosa Park	90	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	5
Caloosa Park	91	Sports Courts/Fields	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2
Caloosa Park	92	Sports Courts/Fields	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	3	each	\$2,696.25	2
Caloosa Park	93	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	2	each	\$6,125.00	2
Caloosa Park	96	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	300	lin ft	\$17,760.00	4
Caloosa Park	97	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	150	lin ft	\$8,880.00	4
Caloosa Park	98	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	150	lin ft	\$8,880.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	99	Sports Courts/Fields	Doors	<p>Make the following correction to at least two doors.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25"; in the alternative, use a temporary ramp for access onto the rink as needed.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp that can be opened from both sides.</p>	\$4,287.00	2	each	\$8,574.00	2
Caloosa Park	100	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	5
Caloosa Park	101	Sports Courts/Fields	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	3	each	\$2,696.25	2
Caloosa Park	102	Sports Courts/Fields	Assembly Areas	Widen adjacent wheelchair seats to min. 33" each and min 60" deep.	\$1,258.25	1	each	\$1,258.25	2
Caloosa Park	103	Sports Courts/Fields	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Caloosa Park	104	Sports Courts/Fields	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	3
Caloosa Park	105	Sports Courts/Fields	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	3
Caloosa Park	106	Sports Courts/Fields	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Caloosa Park	107	Sports Courts/Fields	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground. Pricing provided in the previous finding.	\$0.00	2	each	\$0.00	3
Caloosa Park	109	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp that can be opened from both sides.	\$514.50	2	each	\$1,029.00	2
Caloosa Park	110	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Caloosa Park	111	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Caloosa Park	113	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Caloosa Park	114	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR.  Remount operable parts to be in reach range of 15" min to 48" max.	\$296.00	1	each	\$296.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	115	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Caloosa Park	116	Park Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
Caloosa Park	117	Park Elements	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
Caloosa Park	118	Park Elements	Park Site (C)	Relocate 20% of garbage cans to be along AR.  Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Caloosa Park	119	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	1	each	\$96.25	4
Caloosa Park	120	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$350.00	1	each	\$350.00	4
Caloosa Park	121	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	2	each	\$2,240.00	4
Caloosa Park	122	Shelters	Shelters, Picnic Facilities (C)	Relocate ash garbage can to be along AR. In the alternative, leave as is and designate other County shelters accessible.	\$0.00	1	staff time	\$0.00	4
Caloosa Park	123	Shelters	Shelters/Picnic Areas (C)	Remount garbage cans to be in reach range of 15" min to 48" max.  Replace operable parts of garbage can, grills, and spigot with ones usable without a tight pinch or grasp.  Adjust grill lids to be usable with 5 lbf or less.  In the alternative, leave as is and designate other County shelters accessible.	\$210.00	5	each	\$1,050.00	4
Caloosa Park	124	Shelters	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Caloosa Park	125	Shelters	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
Caloosa Park	126	Shelters	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Remount operable parts to be in reach range of 15" min to 48" max.	\$59.20	3	lin ft	\$177.60	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	127	Shelters	Shelters/Picnic Areas (C)	Provide an AR and accessible tables to shelter/picnic area to achieve the required number accessible	\$59.20	20	lin ft	\$1,184.00	5
Caloosa Park	128	Concessions	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors as.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$1,846.25	1	each	\$1,846.25	3
Caloosa Park	129	Concessions	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	2
Caloosa Park	131	Ballfield 4	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.  In the alternative, leave as is and designate other County ball fields accessible.	\$3,645.00	1	each	\$3,645.00	4
Caloosa Park	132	Ballfield 4	Clear Floor Space	Remove, or relocate storage in CFS of bench.  Provide required 30" by 48" CFS at operable parts.  Correct or repair slope in CFS to max 2.08%.  In the alternative, leave as is and designate other County ball fields accessible.	\$3,062.50	1	each	\$3,062.50	4
Caloosa Park	133	Ballfield 4	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	300	lin ft	\$17,760.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	134	Ballfield 5	Accessible Routes	<p>Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.</p> <p>Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.</p> <p>In the alternative, leave as is and designate other County ball fields accessible.</p>	\$3,645.00	1	each	\$3,645.00	4
Caloosa Park	135	Ballfield 5	Doors	<p>For all doors along the public circulation route, remount hardware to 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Caloosa Park	136	Ballfield 5	Park Site (C)	<p>Provide an accessible route (AR) to each element within the site.</p> <p>Widen dugout entries to 32 inches minimum.</p> <p>In the alternative, leave as is and designate other County ball fields accessible.</p>	\$12,649.00	1	each	\$12,649.00	4
Caloosa Park	137	Ballfield 6	Doors	<p>For all doors along the public circulation route, remount hardware to 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Caloosa Park	138	Ballfield 6	Assembly Areas	<p>Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$898.75	4	each	\$3,595.00	4
Caloosa Park	139	Ballfield 6	Park Site (C)	<p>Provide an accessible route (AR) to each element within the site.</p> <p>Widen dugout entries to 32 inches minimum.</p> <p>In the alternative, leave as is and designate other County ball fields accessible.</p>	\$12,649.00	1	each	\$12,649.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	140	Ballfield 7	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep. In the alternative, leave as is and designate other County ball fields accessible.	\$898.75	2	each	\$1,797.50	4
Caloosa Park	141	Ballfield 7	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Widen dugout entries to 32 inches minimum.  In the alternative, leave as is and designate other County ball fields accessible.	\$12,649.00	1	each	\$12,649.00	4
Caloosa Park	142	Ballfield Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	2
Caloosa Park	143	Ballfield Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Caloosa Park	144	Ballfield Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	145	Ballfield Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Replace one picnic table with one of an accessible design as a smart practice.	\$3,488.00	1	each	\$3,488.00	5
Caloosa Park	146	Ballfield Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	330	lin ft	\$19,536.00	2
Caloosa Park	147	Ballfield Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Replace picnic table with one of an accessible design as a smart practice.	\$4,672.00	1	each	\$4,672.00	5
Caloosa Park	148	Play Area, 2-12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Caloosa Park	151	Play Area, 2-12	Play Area	Lower or adjust entry point to one swing to 11" to 24" AFF.	\$0.00	1	staff time	\$0.00	2
Caloosa Park	152	Play Area, 2-12	Play Area	Correct entry height to one swing to meet incentive scoping.	\$0.00	1	staff time	\$0.00	2
Caloosa Park	153	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Caloosa Park	154	Trail Surface	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Caloosa Park	155	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	156	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Caloosa Park	157	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	280	sq ft	\$34,300.00	5
Caloosa Park	158	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
				Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Frequently maintain trail surface in identified washout areas to assure CIL's remain 2" or less and gaps are filled as a smart practice.					
Caloosa Park	159	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	40	lin ft	\$2,368.00	5
Caloosa Park	160	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
Caloosa Park	161	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Caloosa Park	162	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Caloosa Park	163	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Caloosa Park	164	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Caloosa Park	165	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Caloosa Park	166	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Caloosa Park	167	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Caloosa Park	168	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Caloosa Park	169	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Caloosa Park	170	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	490	sq ft	\$60,025.00	5
Caloosa Park	171	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	7	sq ft	\$857.50	5
Caloosa Park	172	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	175	sq ft	\$21,437.50	5
Caloosa Park	173	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
Caloosa Park	174	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	440	sq ft	\$53,900.00	5
Caloosa Park	175	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
Caloosa Park	176	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Caloosa Park	177	Trail Surface	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	5
Caloosa Park	178	Trail Surface	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	5
Caloosa Park	179	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	280	sq ft	\$34,300.00	5
Caloosa Park	180	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	760	sq ft	\$93,100.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	181	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Caloosa Park	182	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	760	sq ft	\$93,100.00	5
Caloosa Park	183	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Caloosa Park	184	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Caloosa Park	185	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	210	sq ft	\$25,725.00	5
Caloosa Park	186	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	6125	lin ft	\$362,600.00	4
Caloosa Park	187	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	188	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Caloosa Park	189	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	190	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Caloosa Park	191	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	192	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Caloosa Park	193	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Caloosa Park	194	Men's Restroom - Baseball/Softball Fields	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Caloosa Park	195	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	196	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Caloosa Park	197	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Caloosa Park	198	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Pricing provided in the previous finding.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	199	Men's Restroom - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace grab bars with a 1.5" spacing between bars and wall or partition. Pricing provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	3	staff time	\$0.00	1
Caloosa Park	200	Men's Restroom - Baseball/Softball Fields	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	201	Men's Restroom - Baseball/Softball Fields	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	202	Men's Restroom - Baseball/Softball Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,812.50	1	each	\$4,812.50	1
Caloosa Park	203	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Caloosa Park	204	Women's Restrooms - Baseball/Softball Fields	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	205	Women's Restrooms - Baseball/Softball Fields	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Caloosa Park	206	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	207	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Caloosa Park	208	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Caloosa Park	209	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Pricing provided in the previous finding.	\$0.00	2	each	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	210	Women's Restrooms - Baseball/Softball Fields	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	211	Women's Restrooms - Baseball/Softball Fields	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	212	Women's Restrooms - Baseball/Softball Fields	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$5,755.75	1	each	\$5,755.75	1
Caloosa Park	213	Men's Restroom By Tennis	Toilet and Bathing Rooms	Replace one mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Caloosa Park	214	Men's Restroom By Tennis	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	215	Men's Restroom By Tennis	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	216	Men's Restroom By Tennis	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Caloosa Park	217	Men's Restroom By Tennis	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Caloosa Park	218	Men's Restroom By Tennis	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Caloosa Park	219	Men's Restroom By Tennis	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	220	Men's Restroom By Tennis	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	221	Men's Restroom By Tennis	Accessible Routes	Raise overhead bar to min 80" to prevent hazard in overhead clearance along AR.	\$420.00	1	each	\$420.00	1
Caloosa Park	222	Men's Restroom By Tennis	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	223	Men's Restroom By Tennis	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	224	Men's Restroom By Tennis	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, widen doors to 36" for recessed doors.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,618.75	1	each	\$4,618.75	1
Caloosa Park	225	Women's Restroom By Tennis	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, widen doors to 36" for recessed doors.	\$4,522.50	1	each	\$4,522.50	1
Caloosa Park	226	Women's Restroom By Tennis	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	227	Women's Restroom By Tennis	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	228	Women's Restroom By Tennis	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Caloosa Park	229	Women's Restroom By Tennis	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	230	Women's Restroom By Tennis	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Caloosa Park	231	Women's Restroom By Tennis	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Caloosa Park	232	Women's Restroom By Tennis	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	233	Women's Restroom By Tennis	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	234	Women's Restroom By Tennis	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	235	Women's Restroom By Tennis	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	236	Men's Restroom At Caloosa Park Pavilion	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	237	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Caloosa Park	238	Men's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	239	Men's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Caloosa Park	240	Men's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Caloosa Park	241	Men's Restroom At Caloosa Park Pavilion	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$350.00	1	each	\$350.00	1
Caloosa Park	242	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	243	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Caloosa Park	244	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Caloosa Park	245	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Caloosa Park	246	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Caloosa Park	247	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Pricing in the previous finding.	\$0.00	2	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	248	Men's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Replace and remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF), with 1.5" spacing between bars and walls/partition. Pricing provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	249	Men's Restroom At Caloosa Park Pavilion	Hazards	Relocate protruding objects. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	1
Caloosa Park	250	Women's Restroom At Caloosa Park Pavilion	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	251	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	252	Women's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Caloosa Park	253	Women's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Caloosa Park	254	Women's Restroom At Caloosa Park Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Caloosa Park	255	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Caloosa Park	256	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Caloosa Park	257	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.  Adjust stall door to be self-closing.	\$1,828.40	1	each	\$1,828.40	1
Caloosa Park	258	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Caloosa Park	259	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Caloosa Park	260	Women's Restroom At Caloosa Park Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	261	Women's Restroom At Caloosa Park Pavilion	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Caloosa Park	262	Women's Restroom At Caloosa Park Pavilion	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Caloosa Park	263	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Replace closer to provide 80" overhead clearance .  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$485.62	2	each	\$971.24	3
Caloosa Park	264	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Remove door holder and bolt lock to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Caloosa Park	265	Employee Spaces	Custom/Special	Ensure press box is compliant if reopened.	\$0.00	1	staff time	\$0.00	1
Caloosa Park	266	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Repair, provide beveled threshold.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$8,245.00	1	each	\$8,245.00	3
Caloosa Park	267	Employee Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Caloosa Park	268	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caloosa Park	269	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	2	each	\$5,545.00	3
<u>Canal Point Park and Community Center</u>	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Canal Point Park and Community Center	3	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Canal Point Park and Community Center	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Canal Point Park and Community Center	5	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	7	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Canal Point Park and Community Center	8	Parking	Parking - Off Street	Leave as is, lack of access aisles at parallel on-street parking, and provide curb ramp between accessible parking spaces.	\$1,487.50	1	each	\$1,487.50	1
Canal Point Park and Community Center	9	Parking	Parking - Off Street	Repair or correct slope of on-street parking space to max 2.08% in any direction as a smart practice	\$3,062.50	1	each	\$3,062.50	5
Canal Point Park and Community Center	10	Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.  Correct or fill gaps to max .5".	\$96.25	5	each	\$481.25	1
Canal Point Park and Community Center	11	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Canal Point Park and Community Center	12	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Canal Point Park and Community Center	13	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Canal Point Park and Community Center	14	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Canal Point Park and Community Center	15	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Canal Point Park and Community Center	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Canal Point Park and Community Center	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.	\$122.50	540	sq ft	\$66,150.00	1
Canal Point Park and Community Center	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canal Point Park and Community Center	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canal Point Park and Community Center	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canal Point Park and Community Center	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Canal Point Park and Community Center	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	125	sq ft	\$15,312.50	1
Canal Point Park and Community Center	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Canal Point Park and Community Center	27	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	28	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Canal Point Park and Community Center	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Canal Point Park and Community Center	31	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	32	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Canal Point Park and Community Center	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Canal Point Park and Community Center	35	Exterior Accessible Route	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	3	each	\$1,212.75	1
Canal Point Park and Community Center	36	Exterior Accessible Route	Stairways	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible.	\$404.25	2	each	\$808.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	37	Exterior Accessible Route	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	3	each	\$375.00	5
Canal Point Park and Community Center	38	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	1	each	\$980.00	1
Canal Point Park and Community Center	39	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Canal Point Park and Community Center	40	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails on both sides of ramp, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	\$980.00	2	each	\$1,960.00	3
Canal Point Park and Community Center	41	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Canal Point Park and Community Center	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Canal Point Park and Community Center	43	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	315	sq ft	\$38,587.50	1
Canal Point Park and Community Center	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	1
Canal Point Park and Community Center	45	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Canal Point Park and Community Center	46	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	4	each	\$3,920.00	1
Canal Point Park and Community Center	47	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Canal Point Park and Community Center	48	Sports Courts/Fields	Doors	For all doors along the public circulation route, remount hardware to 34" to 48" AFF. In the alternative, leave as is and designate other County tennis courts accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	49	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County tennis courts accessible.	\$59.20	280	lin ft	\$16,576.00	4
Canal Point Park and Community Center	50	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County basketball courts accessible.	\$59.20	10	lin ft	\$592.00	4
Canal Point Park and Community Center	52	Sports Courts/Fields	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep. In the alternative, leave as is and designate other County basketball courts accessible.	\$898.75	2	each	\$1,797.50	4
Canal Point Park and Community Center	54	Park Elements	Plumbing Fixtures & Elements	Remount fountain to provide centered clear floor space.	\$2,380.00	1	each	\$2,380.00	2
Canal Point Park and Community Center	55	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Canal Point Park and Community Center	56	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Canal Point Park and Community Center	57	Park Elements	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
Canal Point Park and Community Center	59	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Pricing provided in a previous finding for lack of route to tennis court entries.	\$0.00	1	each	\$0.00	2
Canal Point Park and Community Center	60	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Canal Point Park and Community Center	62	Picnic Area	Outdoor - Constructed Features (C)	Relocate accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Canal Point Park and Community Center	63	Picnic Area	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.  Relocate 20% of garbage cans to be along AR.	\$59.20	50	lin ft	\$2,960.00	5
Canal Point Park and Community Center	64	Picnic Area	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain.	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	65	Play Area	Play Area	Create designated entry a min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Canal Point Park and Community Center	66	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Canal Point Park and Community Center	67	Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Canal Point Park and Community Center	68	Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Canal Point Park and Community Center	69	Play Area	Play Area	Create designated entry a min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
Canal Point Park and Community Center	70	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Pricing provided in a previous finding for the 2-5 play area surface.	\$0.00	1	each	\$0.00	2
Canal Point Park and Community Center	71	Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Canal Point Park and Community Center	72	Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.	\$2,003.75	1	each	\$2,003.75	3
Canal Point Park and Community Center	73	Men's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.  Remove restroom sign with symbol of accessibility at corner of building leading to inaccessible men's restroom.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	74	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, provide beveled threshold.	\$4,776.25	1	each	\$4,776.25	1
Canal Point Park and Community Center	75	Men's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and without the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	76	Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	77	Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and without the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	78	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, provide beveled threshold.	\$4,776.25	1	each	\$4,776.25	1
Canal Point Park and Community Center	79	All Gender Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.  Remove misleading restroom sign with symbol of accessibility that is located far from all-gender restroom door.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	80	All Gender Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Canal Point Park and Community Center	81	All Gender Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	82	All Gender Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	83	All Gender Restroom	Toilet and Bathing Rooms	Relocate garbage to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	84	All Gender Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Canal Point Park and Community Center	85	All Gender Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Canal Point Park and Community Center	86	All Gender Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	87	All Gender Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Canal Point Park and Community Center	88	All Gender Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	89	All Gender Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace closer for 80" overhead clearance	\$2,100.00	1	each	\$2,100.00	1
Canal Point Park and Community Center	90	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$5,834.50	1	each	\$5,834.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	91	Public Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,578.50	1	each	\$1,578.50	1
Canal Point Park and Community Center	92	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,158.75	1	each	\$3,158.75	1
Canal Point Park and Community Center	94	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	95	Public Spaces	Accessible Routes	Provide a ramp for access to the stage.	\$6,510.00	1	each	\$6,510.00	2
Canal Point Park and Community Center	96	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$2,380.00	1	each	\$2,380.00	2
Canal Point Park and Community Center	97	Public Spaces	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	98	Public Spaces	Kitchens, Kitchenettes, And Wet Bars	Lower 50% of shelving, or relocate supplies to within reach range, max 48" AFF.	\$700.00	1	each	\$700.00	1
Canal Point Park and Community Center	99	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Canal Point Park and Community Center	100	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	101	Public Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,674.75	1	each	\$1,674.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	102	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Canal Point Park and Community Center	103	Employee Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$6,510.00	1	each	\$6,510.00	3
Canal Point Park and Community Center	104	Men's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	105	Men's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and mount on the wall on latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.  Remount signage to the proper location based on the type of door provided.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	106	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$4,522.50	1	each	\$4,522.50	1
Canal Point Park and Community Center	107	Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Canal Point Park and Community Center	108	Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and mount on the wall on latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canal Point Park and Community Center	109	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$4,522.50	1	each	\$4,522.50	1
Canal Point Park and Community Center	111	All Gender Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	112	All Gender Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Canal Point Park and Community Center	113	All Gender Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; in the alternative, leave as is citing safe harbor.	\$0.00	1	each	\$0.00	4
Canal Point Park and Community Center	114	All Gender Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Canal Point Park and Community Center	115	All Gender Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Canal Point Park and Community Center	116	All Gender Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF), with a minimum 1.5" between the bar and the top of the toilet tank.  Remount toilet paper dispenser and soap dispenser min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Canal Point Park and Community Center	117	All Gender Restroom	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Canal Point Park and Community Center	118	All Gender Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Canyon Amphitheater	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	3	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Canyon Amphitheater	4	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Canyon Amphitheater	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Canyon Amphitheater	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon Amphitheater	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Canyon Amphitheater	11	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Canyon Amphitheater	12	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	2	staff time	\$0.00	1
Canyon Amphitheater	13	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Canyon Amphitheater	14	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Canyon Amphitheater	15	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Canyon Amphitheater	16	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Canyon Amphitheater	17	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Canyon Amphitheater	18	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Canyon Amphitheater	19	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Canyon Amphitheater	20	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	2	staff time	\$0.00	1
Canyon Amphitheater	21	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Canyon Amphitheater	22	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Canyon Amphitheater	23	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Canyon Amphitheater	24	Women's Restroom	Turning Space	Reconfigure restroom to provide min 60" diameter turning space or t-shaped turning space.	\$8,295.00	1	each	\$8,295.00	1
Canyon Amphitheater	25	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	2	staff time	\$0.00	1
Canyon Amphitheater	26	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Canyon Amphitheater	27	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Canyon Amphitheater	28	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon Amphitheater	29	Park Element	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Canyon Amphitheater	30	Park Element	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Canyon Amphitheater	31	Park Element	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Canyon Amphitheater	32	Park Element	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table, as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Canyon Amphitheater	35	Amphitheater	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Canyon Amphitheater	36	Amphitheater	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	1	each	\$875.00	3
Canyon Amphitheater	37	Amphitheater	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Canyon Amphitheater	38	Amphitheater	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	1	each	\$875.00	3
Canyon Amphitheater	39	Amphitheater	Ramps (Not Curb Ramps)	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	1	each	\$980.00	3
Canyon Amphitheater	41	Amphitheater	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Canyon Amphitheater	42	Amphitheater	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Canyon District Park	4	Parking - Between Play Area and Soccer	Parking - Off Street	Relocate 2 of 7 stalls to be on the shortest AR to the soccer fields.	\$367.50	2	each	\$735.00	1
Canyon District Park	5	Parking - Between Play Area and Soccer	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Canyon District Park	6	Parking - Between Play Area and Soccer	Parking - Off Street	Add two van parking signs to two accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Canyon District Park	8	Parking - Large lot near Maintenance	Parking - Off Street	Create seven or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls; in the alternative, leave as is if accessible stalls in adjacent lot are intended to cover scoping for both lots.	\$1,589.00	7	each	\$11,123.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon District Park	11	Parking - Maintenance	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Canyon District Park	12	Parking - Maintenance	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Canyon District Park	13	Park Element	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Canyon District Park	14	Park Element	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Canyon District Park	15	Sports Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is the two soccer fields without routes to bleachers and seating, and designate other County rectangular fields accessible.	\$59.20	50	lin ft	\$2,960.00	2
Canyon District Park	16	Picnic Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Canyon District Park	17	Picnic Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Canyon District Park	19	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	3
Canyon District Park	20	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$1,750.00	1	each	\$1,750.00	3
Canyon District Park	21	Employee Spaces	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Canyon District Park	22	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	2	staff time	\$0.00	3
Canyon District Park	23	Employee Spaces	Reach Ranges	Lower operating mechanisms to max 48" AFF to highest operable part.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon District Park	24	Employee Restrooms and Shower	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Canyon District Park	25	Employee Restrooms and Shower	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	3
Canyon District Park	26	Employee Restrooms and Shower	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	3
Canyon District Park	27	Employee Restrooms and Shower	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	3
Canyon District Park	28	Employee Restrooms and Shower	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	3
Canyon District Park	29	Employee Restrooms and Shower	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	3
Canyon District Park	30	Employee Restrooms and Shower	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	3
Canyon District Park	31	Employee Restrooms and Shower	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension. In the alternative, leave as is citing construction tolerance.	\$5,498.50	1	each	\$5,498.50	4
Canyon District Park	32	Employee Restrooms and Shower	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	3
Canyon District Park	34	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Canyon District Park	35	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Canyon District Park	36	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	40	lin ft	\$2,368.00	5
Canyon District Park	37	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Canyon District Park	38	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Canyon District Park	39	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Canyon District Park	40	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Canyon District Park	41	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Canyon District Park	42	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Canyon District Park	43	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Canyon District Park	44	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	40	lin ft	\$2,368.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon District Park	45	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Canyon District Park	46	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Canyon District Park	47	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Canyon District Park	48	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Canyon District Park	52	Trail Element	Reach Ranges	Lower garbage cans so rims are max 48" AFF to highest operable part.  Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Canyon District Park	53	Men's Restroom	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Canyon District Park	54	Men's Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF. In the alternative, leave as is citing construction tolerance.	\$514.50	1	each	\$514.50	4
Canyon District Park	55	Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Canyon District Park	56	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Canyon District Park	57	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Canyon District Park	58	Women's Restroom	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Canyon District Park	59	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Canyon District Park	60	Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Canyon District Park	61	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Canyon District Park	62	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	4	each	\$12,250.00	1
Canyon District Park	63	Single User Restroom Near Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount hardware at 34 inches minimum and 48 inches maximum above the finish floor or ground. In the alternative, leave as is citing construction tolerance.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Canyon District Park	64	Single User Restroom Near Concessions	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Canyon District Park	65	Single User Restroom Near Concessions	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Canyon District Park	66	Single User Restroom Near Concessions	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	2	Parking - Beach	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Carlin Park	3	Parking - Beach	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	3	each	\$220.50	1
Carlin Park	4	Parking - Beach	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Carlin Park	5	Parking - Beach	Parking - Off Street	Add one van parking sign to two accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Carlin Park	6	Parking - Beach	Parking - Off Street	Remove extra lines from parking stall.	\$73.50	1	each	\$73.50	1
Carlin Park	7	Parking - Beach	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Carlin Park	8	Parking - Gumbo Limbo Pavilion	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	9	Parking - Gumbo Limbo Pavilion	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	11	Parking - Gumbo Limbo Pavilion	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	3	each	\$220.50	1
Carlin Park	12	Parking - Gumbo Limbo Pavilion	Accessible Routes	Add parking stop or mount signage to prohibit cars from parking and obstructing accessible route	\$210.00	1	each	\$210.00	1
Carlin Park	13	Parking - Gumbo Limbo Pavilion	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Carlin Park	14	Parking - Gumbo Limbo Pavilion	Parking - Off Street	Add one van parking sign to one accessible stall with aisle on passenger side and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Carlin Park	16	Parking - Sea Oats/Denise Marie Nieman Pavilion	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Carlin Park	17	Parking - Sea Oats/Denise Marie Nieman Pavilion	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Carlin Park	19	Parking - Tennis/Overflow	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
Carlin Park	20	Parking - Tennis/Overflow	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Carlin Park	21	Parking - Tennis/Overflow	Curb Ramps	Correct curb ramp cross slope to max 2.08%	\$1,487.50	1	each	\$1,487.50	1
Carlin Park	22	Parking - Tennis/Overflow	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%	\$875.00	1	each	\$875.00	1
Carlin Park	23	Parking - Tennis/Overflow	Parking - Off Street	Disperse stalls to be on the shortest AR to the building entries or park features	\$367.50	1	each	\$367.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	24	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Carlin Park	25	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	300	sq ft	\$36,750.00	1
Carlin Park	26	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	27	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Carlin Park	28	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.00	75	sq ft	\$9,150.00	1
Carlin Park	29	Exterior Accessible Route - Beach Side	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice	\$3,062.50	1	each	\$3,062.50	5
Carlin Park	30	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	31	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	32	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	33	Exterior Accessible Route - Beach Side	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	34	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Carlin Park	35	Exterior Accessible Route - Beach Side	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	12	each	\$1,155.00	1
Carlin Park	36	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Carlin Park	37	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	8	each	\$24,500.00	1
Carlin Park	38	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	10	each	\$30,625.00	1
Carlin Park	39	Exterior Accessible Route - Beach Side	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	400	sq ft	\$49,000.00	1
Carlin Park	40	Exterior Accessible Route - Beach Side	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Carlin Park	41	Exterior Accessible Route - Beach Side	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
Carlin Park	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Carlin Park	43	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	36	sq ft	\$2,131.20	1
Carlin Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Carlin Park	45	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	47	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	48	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	49	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	50	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	51	Exterior Accessible Route	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Carlin Park	52	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	53	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	54	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	6	each	\$1,974.00	5
Carlin Park	55	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Carlin Park	56	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Carlin Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	245	sq ft	\$30,012.50	1
Carlin Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	105	sq ft	\$12,862.50	1
Carlin Park	59	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	375	sq ft	\$45,937.50	1
Carlin Park	60	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	sq ft	\$3,062.50	1
Carlin Park	61	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	62	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	250	sq ft	\$30,625.00	1
Carlin Park	63	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	125	sq ft	\$15,312.50	1
Carlin Park	64	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	65	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Carlin Park	66	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Carlin Park	67	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Carlin Park	68	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Carlin Park	69	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Carlin Park	70	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Carlin Park	71	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Carlin Park	72	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Carlin Park	73	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	74	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Carlin Park	75	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	13	each	\$1,251.25	1
Carlin Park	76	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	77	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Carlin Park	78	Exterior Accessible Route	Parking - Off Street	Install parking stops or mount signage preventing cars from overhanging in accessible route.	\$210.00	12	each	\$2,520.00	1
Carlin Park	79	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	80	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" aff, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	36	each	\$35,280.00	3
Carlin Park	81	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	3960	sq ft	\$485,100.00	5
Carlin Park	82	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	2700	sq ft	\$330,750.00	5
Carlin Park	83	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Carlin Park	84	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
Carlin Park	85	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	86	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1260	sq ft	\$154,350.00	1
Carlin Park	87	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	88	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	89	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$3,062.50	2	each	\$6,125.00	5
Carlin Park	90	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Carlin Park	91	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	480	sq ft	\$58,800.00	1
Carlin Park	92	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	4	lin ft	\$236.80	1
Carlin Park	93	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	94	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Carlin Park	95	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Carlin Park	96	Exterior Accessible Route	Accessible Routes	Open all gates for pedestrian access to amphitheater area when amphitheater is in use.	\$0.00	1	staff time	\$0.00	1
Carlin Park	97	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Carlin Park	98	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	350	sq ft	\$42,875.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	99	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	80	sq ft	\$9,800.00	1
Carlin Park	100	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
Carlin Park	101	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	102	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
Carlin Park	103	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	104	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%	\$875.00	2	each	\$1,750.00	1
Carlin Park	105	Exterior Accessible Route	Accessible Routes	Resurface AR where deterioration occurs.	\$96.25	1	each	\$96.25	1
Carlin Park	106	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$980.00	1	each	\$980.00	1
Carlin Park	107	Exterior Accessible Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" aff	\$350.00	1	each	\$350.00	1
Carlin Park	108	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	1
Carlin Park	109	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Carlin Park	110	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
Carlin Park	111	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Carlin Park	112	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Carlin Park	113	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	960	sq ft	\$117,600.00	1
Carlin Park	114	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Carlin Park	115	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	600	sq ft	\$73,500.00	1
Carlin Park	116	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Carlin Park	117	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,158.25	1	each	\$3,158.25	2
Carlin Park	118	Sports Fields/Courts	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Relocate trash can to provide min 30" by 48" CGS at controls.	\$350.00	1	each	\$350.00	2
Carlin Park	119	Sports Fields/Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	2
Carlin Park	120	Sports Fields/Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	2
Carlin Park	122	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	123	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$4,908.75	1	each	\$4,908.75	2
Carlin Park	124	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Repair, bevel, or ramp CIL at entry to bocce court.	\$3,633.75	1	each	\$3,633.75	2
Carlin Park	125	Sports Fields/Courts	Accessible Routes	Widen EAR to min 36" clear width	\$0.00	1	staff time	\$0.00	2
Carlin Park	126	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	20	lin ft	\$1,184.00	2
Carlin Park	127	Sports Fields/Courts	Doors	Provide required maneuvering clearance around pull side of door  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door  For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$3,062.50	1	each	\$3,062.50	2
Carlin Park	131	Sports Fields/Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	2
Carlin Park	132	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	75	lin ft	\$4,440.00	4
Carlin Park	133	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	150	lin ft	\$8,880.00	4
Carlin Park	134	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	150	lin ft	\$8,880.00	2
Carlin Park	135	Small Picnic Shelters/Picnic Area Along Beach	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  Relocate accessible picnic table to provide 36" min clear space around entire usable portion of table as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Carlin Park	136	Small Picnic Shelters/Picnic Area Along Beach	Shelters/Picnic Areas (C)	Lower garbage bins to max 48" AGL.	\$0.00	1	staff time	\$0.00	3
Carlin Park	137	Small Picnic Shelters/Picnic Area Along Beach	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Carlin Park	138	Small Picnic Shelters/Picnic Area Along Beach	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	11	each	\$1,058.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	139	Small Picnic Shelters/Picnic Area Along Beach	Picnic Tables (C)	Replace 6 picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	6	each	\$6,720.00	5
				Correct or repair clear ground space at grills to max 2.08% as a smart practice.					
				Relocate accessible picnic table to provide 36" min clear space around entire usable portion of table as a smart practice.					
				Replace operable parts with ones useable without a tight pinch or grasp.					
Carlin Park	140	Small Picnic Shelters/Picnic Area Along Beach	Shelters/Picnic Areas (C)	Lower grill cooking surface to max 34" as a smart practice.	\$9,957.50	1	each	\$9,957.50	5
Carlin Park	141	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	142	Park Elements	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth	\$1,540.00	1	each	\$1,540.00	5
Carlin Park	143	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Carlin Park	144	Park Elements	Plumbing Fixtures & Elements	Install a second low bowl fountain for individuals using wheelchairs	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	147	Park Elements	Signs	Replace sign with one having contrasting color and on a non-glare surface	\$210.00	1	each	\$210.00	2
Carlin Park	148	Park Elements	Signs	Replace sign with one having contrasting color and on a non-glare surface	\$210.00	1	each	\$210.00	2
Carlin Park	149	Park Elements	Signs	Relocate signs to provide CGS; in the alternative, extend and accessible route to the signs and provide CGS.	\$350.00	1	each	\$350.00	2
Carlin Park	150	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	151	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Carlin Park	152	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	153	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$0.00	1	staff time	\$0.00	2
Carlin Park	154	Park Elements	Clear Floor Space	Remove objects or enlarge CGS to min 48" depth	\$1,540.00	1	each	\$1,540.00	2
Carlin Park	155	Park Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less	\$0.00	1	staff time	\$0.00	2
Carlin Park	156	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Carlin Park	157	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$750.00	2	each	\$1,500.00	5
Carlin Park	159	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Carlin Park	160	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$750.00	1	each	\$750.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	162	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	163	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max aff to the spout	\$2,380.00	1	each	\$2,380.00	2
Carlin Park	164	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	2
Carlin Park	165	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$750.00	2	each	\$1,500.00	5
Carlin Park	166	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	12	lin ft	\$710.40	2
Carlin Park	168	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	169	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Carlin Park	170	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs	\$5,598.25	1	each	\$5,598.25	2
Carlin Park	171	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Carlin Park	172	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	2
Carlin Park	173	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Carlin Park	174	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	2
Carlin Park	175	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Carlin Park	176	Gumbo Limbo Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	2	N/A	\$192.50	5
Carlin Park	177	Gumbo Limbo Pavilion	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance	\$140.00	360	each	\$50,400.00	3
Carlin Park	178	Gumbo Limbo Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	179	Gumbo Limbo Pavilion	Shelters/Picnic Areas (C)	Replace operable parts with ones that can be used without a tight pinch or grasp and that require less than 5lbf to operate.  Provide min 72" by 48" CGS at water spouts as a smart practice.  Replace grills with ones that have cooking surfaces at fixed height of max 34".  Remount trash cans to max 48".	\$1,034.00	1	each	\$1,034.00	5
Carlin Park	180	Sea Oats /Denise Marie Niemam Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Carlin Park	181	Sea Oats /Denise Marie Niemam Pavilion	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance	\$140.00	36	each	\$5,040.00	3
Carlin Park	182	Sea Oats /Denise Marie Niemam Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5
Carlin Park	183	Sea Oats /Denise Marie Niemam Pavilion	Shelters/Picnic Areas (C)	Replace operable parts with ones that can be used without a tight pinch or grasp and that require less than 5lbf to operate.  Provide min 72" by 48" CGS at water spouts as a smart practice.  Remount trash cans to max 48".	\$684.00	1	each	\$684.00	5
Carlin Park	184	Beach Access Route	Beach Access Route (C)	Correct tread obstacle on BAR to max .5" or 1" where surface is other than asphalt, concrete or boards as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$96.25	1	each	\$96.25	4
Carlin Park	185	Beach Access Route	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Carlin Park	186	Beach Access Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material to base of lifeguard station. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	200	lin ft	\$11,840.00	4
Carlin Park	187	Beach Access Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material to base of lifeguard tower. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	125	lin ft	\$7,400.00	4
Carlin Park	188	Beach Access Route	Signs	Remount signage to be a min of 40" AGL (above ground level)	\$0.00	1	staff time	\$0.00	5
Carlin Park	189	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	280	lin ft	\$16,576.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	190	Beach Access Route	Signs	Remount signage to be a min of 40" AGL (above ground level)	\$0.00	1	staff time	\$0.00	5
Carlin Park	191	Beach Access Route	Signs	Remount signage to be a min of 40" AGL (above ground level) Provide min 30" by 48" CGS at sign.	\$0.00	1	staff time	\$0.00	5
Carlin Park	192	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.  Maintain beach access routes to be firm and stable.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	250	lin ft	\$14,800.00	4
Carlin Park	193	Beach Access Route	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	3
Carlin Park	194	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	250	lin ft	\$14,800.00	4
Carlin Park	195	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	250	lin ft	\$14,800.00	4
Carlin Park	196	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	250	lin ft	\$14,800.00	4
Carlin Park	197	Beach Access Route	Stairways	Install kick plates on all stairs or replace with ones having closed risers. In the alternative, leave as is and designate other County beaches accessible.	\$84.00	8	each	\$672.00	4
Carlin Park	198	Beach Access Route	Stairways	SMART PRACTICE  Install contrasting strip along front 2" of each tread  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.  In the alternative, leave as is and designate other County beaches accessible.	\$125.00	7	each	\$875.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	199	Beach Access Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.  In the alternative, leave as is and designate other County beaches accessible.	\$980.00	4	each	\$3,920.00	4
Carlin Park	200	Picnic Area By Seabreeze Amphithester	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Carlin Park	201	Picnic Area By Seabreeze Amphithester	Clear Floor Space	Repair, bevel or ramp CIL in CFS to max .25".	\$96.25	1	each	\$96.25	5
Carlin Park	202	Picnic Area By Seabreeze Amphithester	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	5
Carlin Park	203	Picnic Area By Seabreeze Amphithester	Clear Floor Space	Repair, bevel or ramp CIL in CFS to max .25".	\$96.25	1	each	\$96.25	5
Carlin Park	204	Picnic Area By Seabreeze Amphithester	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	5
Carlin Park	205	Picnic Area By Seabreeze Amphithester	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table at min 20% of the tables as a smart practice.	\$2,486.00	3	each	\$7,458.00	5
Carlin Park	206	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$0.00	1	staff time	\$0.00	5
Carlin Park	207	Picnic Areas	Shelters/Picnic Areas (C)	Remount garbage cans to max 48".  Relocate picnic table to provide min 36" around all usable sides of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Carlin Park	208	Laurie Schobelock Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Carlin Park	209	Laurie Schobelock Pavilion	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance	\$140.00	52	each	\$7,280.00	3
Carlin Park	210	Laurie Schobelock Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5
Carlin Park	211	Laurie Schobelock Pavilion	Shelters/Picnic Areas (C)	Provide clear ground space min 48" by 72" at water spout.  Replace grills with ones having hardware operable without tight, pinch, or grasp and requiring no more than 5lbf to operate.	\$824.00	1	each	\$824.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	212	Laurie Schobelock Pavilion	Shelters, Picnic Facilities (C)	<p>Replace or correct surface to be firm and stable.</p> <p>Provide clear ground space min 36" beyond all usable sides of the accessible picnic table.</p> <p>Extend outdoor recreation accessible route to each amenity as a smart practice.</p> <p>Replace one picnic table with one of an accessible design.</p>	\$2,948.00	1	each	\$2,948.00	5
Carlin Park	213	Laurie Schobelock Pavilion	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	\$980.00	6	each	\$5,880.00	3
Carlin Park	214	Lifeguard Station/Office	Room/Space (C)	Leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here.	\$46,631.00	1	each	\$46,631.00	4
Carlin Park	215	Lifeguard Station/Office	Kitchens, Kitchenettes, And Wet Bars	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	\$3,360.00	1	each	\$3,360.00	3
Carlin Park	216	Lifeguard Station/Office	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	3
Carlin Park	217	Lifeguard Station/Office	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised lettering, mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3
Carlin Park	218	Lifeguard Station/Office	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room	\$5,498.50	1	each	\$5,498.50	3
Carlin Park	219	Lifeguard Station/Office	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure rug at door to prevent trip hazard.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$7,064.50	1	each	\$7,064.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	220	Lifeguard Station/Office	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, provide beveled threshold.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$5,290.25	1	each	\$5,290.25	3
Carlin Park	221	Lifeguard Station/Office	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves	\$420.00	1	each	\$420.00	3
Carlin Park	222	Lifeguard Station/Office	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" aff.	\$420.00	1	each	\$420.00	3
Carlin Park	223	Lifeguard Station/Office	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$404.25	19	each	\$7,680.75	3
Carlin Park	224	Lifeguard Station/Office	Stairways	Install kick plates on all stairs or replace with ones having closed risers	\$84.00	19	each	\$1,596.00	3
Carlin Park	225	Lifeguard Station/Office	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	19	each	\$2,375.00	5
Carlin Park	226	Lifeguard Station/Office	Stairways	<p>Install handrails on both sides of stairway mounted 34" to 38" aff, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall.</p> <p>Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.</p>	\$980.00	2	each	\$1,960.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	227	Lifeguard Station/Office	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Price included in earlier finding.	\$0.00	1	each	\$0.00	3
Carlin Park	228	Lifeguard Station/Office	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Price included in earlier finding.	\$0.00	2	each	\$0.00	3
Carlin Park	229	Beach Pavilion Playground	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	10	lin ft	\$592.00	4
Carlin Park	230	Beach Pavilion Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Carlin Park	231	Beach Pavilion Playground	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
Carlin Park	232	Beach Pavilion Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Carlin Park	233	Beach Pavilion Playground	Play Area	Make corrections to surface to provide accessible route to one of each type. In the alternative, leave as is and designate other County playgrounds accessible. Price included in earlier finding.	\$0.00	1	each	\$0.00	4
Carlin Park	235	Ball Field Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Carlin Park	236	Ball Field Playground	Play Area	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Carlin Park	239	Ball Field Playground	Play Area	Add one more GLPC of type other than interactive or manipulable to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	240	Ball Field Playground	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted between 34" and 48" AGL.  In the alternative, leave as is and designate other County playgrounds accessible.	\$5,327.00	1	each	\$5,327.00	4
Carlin Park	241	Ball Field Playground	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.	\$3,062.50	1	each	\$3,062.50	4
Carlin Park	242	5-12 Gumbo Limbo Pavilion Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Carlin Park	243	5-12 Gumbo Limbo Pavilion Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Carlin Park	244	5-12 Gumbo Limbo Pavilion Playground	Accessible Routes	Create an AR to the play area within the site. See previous finding for surface correction and cost. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Carlin Park	245	5-12 Gumbo Limbo Pavilion Playground	Play Area	Install raised sand table with knee clearance or provide a means of transfer to the sand surface as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,100.00	1	each	\$2,100.00	4
Carlin Park	246	2-12 Gumbo Limbo Pavilion Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Carlin Park	247	2-12 Gumbo Limbo Pavilion Playground	Accessible Routes	Repair, bevel or ramp change in level along accessible route. In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	1	each	\$96.25	4
Carlin Park	248	2-12 Gumbo Limbo Pavilion Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	249	2-12 Gumbo Limbo Pavilion Playground	Play Area	Widen AR to minimum 60" through play area  Reduce the distance of 36" wide AR to max 60" and provide 60" long sections between reductions.  In the alternative, leave as is and designate other County playgrounds accessible.	\$67.20	1	each	\$67.20	4
Carlin Park	250	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	251	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Carlin Park	252	Near Ocean Blvd - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	253	Near Ocean Blvd - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.  Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Carlin Park	254	Near Ocean Blvd - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Carlin Park	255	Near Ocean Blvd - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Carlin Park	256	Near Ocean Blvd - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Carlin Park	257	Near Ocean Blvd - Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth	\$2,749.25	1	each	\$2,749.25	1
Carlin Park	258	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	259	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	260	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	261	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Carlin Park	262	Near Ocean Blvd - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	263	Near Ocean Blvd - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	264	Near Ocean Blvd - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	265	Near Ocean Blvd - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$5,005.00	1	each	\$5,005.00	1
Carlin Park	266	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	267	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Carlin Park	268	Near Ocean Blvd - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	269	Near Ocean Blvd - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Carlin Park	270	Near Ocean Blvd - Women's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth	\$2,749.25	1	each	\$2,749.25	1
Carlin Park	271	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	272	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	273	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	274	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Remount flush control to be 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar, located on the open side of the toilet.	\$296.00	1	each	\$296.00	1
Carlin Park	275	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Carlin Park	276	Near Ocean Blvd - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser to wall closest to toilet 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	277	Near Ocean Blvd - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	278	Near Ocean Blvd - Women's Restroom	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Carlin Park	279	Gumbo Limbo - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,908.75	1	each	\$4,908.75	1
Carlin Park	280	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	281	Gumbo Limbo - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	282	Gumbo Limbo - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Carlin Park	283	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	284	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	285	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	286	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	287	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	288	Gumbo Limbo - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Carlin Park	289	Gumbo Limbo - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Carlin Park	290	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	291	Gumbo Limbo - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	292	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	293	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	294	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	295	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	296	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	297	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount flush control to the open side of the toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$296.00	1	each	\$296.00	1
Carlin Park	298	Gumbo Limbo - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Carlin Park	299	Gumbo Limbo - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	300	Gumbo Limbo - Women's Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,158.75	1	each	\$3,158.75	1
Carlin Park	301	Tennis - Men's Restroom	Signs	Correct or repair CIL in CFS at sign to max .25"	\$96.25	1	each	\$96.25	1
Carlin Park	302	Tennis - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Carlin Park	303	Tennis - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Carlin Park	304	Tennis - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Carlin Park	305	Tennis - Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS	\$2,749.25	1	each	\$2,749.25	1
Carlin Park	306	Tennis - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	lin ft	\$0.00	1
Carlin Park	307	Tennis - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Carlin Park	308	Tennis - Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	309	Tennis - Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	310	Tennis - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Carlin Park	311	Tennis - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Carlin Park	312	Tennis - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	313	Tennis - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	314	Tennis - Men's Restroom	Turning Space	Relocate obstacles to create turning space in restroom	\$0.00	1	staff time	\$0.00	1
Carlin Park	315	Tennis - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Carlin Park	316	Tennis - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Carlin Park	317	Tennis - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Carlin Park	318	Tennis - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	319	Tennis - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Carlin Park	320	Tennis - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Carlin Park	321	Tennis - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part. Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
Carlin Park	322	Tennis - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Carlin Park	323	Tennis - Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	\$2,749.25	1	each	\$2,749.25	1
Carlin Park	324	Tennis - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	325	Tennis - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	326	Tennis - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Carlin Park	327	Tennis - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	328	Tennis - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	329	Tennis - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	330	Tennis - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Carlin Park	331	Tennis - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Carlin Park	332	Women's Restroom	Clear Floor Space	Remove, or relocate paper towel dispenser to provide CFS at sink	\$0.00	1	staff time	\$0.00	1
Carlin Park	333	Women's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last altered before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	334	Women's Restroom	Toilet and Bathing Rooms	Remove storage from grab bars to allow min 12" clearance above bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	335	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	336	Women's Restroom	Toilet and Bathing Rooms	Remount soap dispenser to location that is not within toilet clearance, mounted 15" to 48" aff..	\$0.00	1	staff time	\$0.00	1
Carlin Park	337	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	338	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	339	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Carlin Park	340	Women's Restroom	Protruding Object	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	341	Single User Restroom 104	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Carlin Park	342	Single User Restroom 104	Toilet and Bathing Rooms	Remount sign to the wall closest to the latch side of the door where an 18" by 18" CFS can be provided that is centered on the sing.	\$210.00	1	each	\$210.00	1
Carlin Park	343	Single User Restroom 104	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Carlin Park	344	Single User Restroom 104	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Carlin Park	345	Single User Restroom 104	Clear Floor Space	Relocate paper towel dispenser to provide CFS at sink.	\$0.00	1	staff time	\$0.00	1
Carlin Park	346	Single User Restroom 104	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	347	Single User Restroom 104	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	348	Single User Restroom 104	Toilet and Bathing Rooms	Remount soap dispenser to location that is not within toilet clearance, mounted 15" to 48" aff..	\$0.00	1	staff time	\$0.00	1
Carlin Park	349	Single User Restroom 104	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	350	Single User Restroom 104	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	354	Public Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Carlin Park	355	Public Spaces	Doors	Provide required maneuvering clearance on push side of door	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	358	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$350.00	1	each	\$350.00	1
Carlin Park	359	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$350.00	1	each	\$350.00	1
Carlin Park	361	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$0.00	1	staff time	\$0.00	1
Carlin Park	362	Public Spaces	Plumbing Fixtures & Elements	Remount fountain to provide centered clear floor space.	\$2,380.00	1	each	\$2,380.00	1
Carlin Park	363	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	1
Carlin Park	364	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	365	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	366	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	367	Public Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$350.00	1	each	\$350.00	1
Carlin Park	368	Public Spaces	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Carlin Park	369	Public Spaces	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60"	\$875.00	1	each	\$875.00	1
Carlin Park	370	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	371	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Carlin Park	372	Public Spaces	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Carlin Park	373	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	1
Carlin Park	374	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	1
Carlin Park	375	Public Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Carlin Park	376	Public Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	377	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Carlin Park	378	Public Spaces	Assembly Areas	Provide wheelchair spaces min 36" wide or 33" wide each when two are spaced next to each other, with required companion seats, and disperse the accessible seating throughout the seating area.	\$629.50	16	each	\$10,072.00	2
Carlin Park	379	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	3
Carlin Park	380	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	3
Carlin Park	381	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Carlin Park	382	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$2,118.00	1	each	\$2,118.00	3
Carlin Park	383	Trail - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	6600	lin ft	\$390,720.00	4
Carlin Park	384	Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.  Fill gaps at door entries to max .5".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Remount lock to max 48" aff.	\$4,023.25	1	each	\$4,023.25	3
Carlin Park	386	Employee Spaces	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".	\$1,846.25	1	each	\$1,846.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	387	Employee Spaces	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors. Repair, bevel, or ramp CILs at door entries to max .25".	\$1,846.25	1	each	\$1,846.25	3
Carlin Park	388	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$59.20	65	lin ft	\$3,848.00	3
Carlin Park	389	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Correct slope in door clearance to max 2.08%. Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$5,320.00	1	each	\$5,320.00	3
Carlin Park	390	Employee Spaces	Accessible Routes	Widen AR to compliant 36" clear width	\$0.00	1	staff time	\$0.00	1
Carlin Park	391	Employee Spaces	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
Carlin Park	392	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	3
Carlin Park	393	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	3
Carlin Park	394	Employee Spaces	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,264.50	1	each	\$2,264.50	3
Carlin Park	395	Public Spaces	Custom/Special	Ensure facility is fully compliant when renovations are completed.	\$0.00	1	staff time	\$0.00	1
Carlin Park	396	Men's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1
Carlin Park	397	Men's Restroom	Toilet and Bathing Rooms	Replace signage with one that includes Braille and raised lettering without the access symbol and mount on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Carlin Park	398	Women's Restroom	Toilet and Bathing Rooms	Replace signage with one that includes Braille and raised lettering without the access symbol and mount on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Carlin Park	399	Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Carlin Park	400	Single User Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Carlin Park	401	Single User Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	2	staff time	\$0.00	1
Carlin Park	402	Single User Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Carlin Park	403	Single User Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Carlin Park	404	Single User Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Carlin Park	405	Single User Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Carlin Park	406	Single User Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	1
Carlin Park	407	Single User Restroom	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Carlin Park	408	Single User Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	409	Single User Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Carlin Park	410	Single User Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Carlin Park	411	Single User Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Carlin Park	412	Single User Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Carlin Park	413	Single User Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Carlin Park	414	Single User Restroom	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Carlin Park	415	Single User Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Carlin Park	416	Single User Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Caroline Park	1	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Caroline Park	2	2 to 5 Play Area	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	2
Caroline Park	3	2 to 5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2
Caroline Park	4	2 to 5 Play Area	Accessible Routes	Fill and compact EWF surface so that it becomes level with adjacent surfaces	\$0.00	1	staff time	\$0.00	2
Caroline Park	11	Park Elements	Accessible Routes	Relocate trash bag dispenser to be within reach from accessible route.	\$0.00	1	staff time	\$0.00	2
Caroline Park	12	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Caroline Park	16	Gazebo	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
Coral Cove Park	2	Parking	Parking - Off Street	Relocate two stalls to be on the shortest AR to the restrooms and playground.	\$367.50	2	each	\$735.00	1
Coral Cove Park	3	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Coral Cove Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	9	each	\$27,562.50	1
Coral Cove Park	5	Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.  Repair, bevel and ramp CIL in stalls and access aisles.  Correct or fill gap to max .5".	\$96.25	2	each	\$192.50	1
Coral Cove Park	6	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, with penalty information provided.	\$210.00	5	each	\$1,050.00	1
Coral Cove Park	7	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 11' and 5' or 8' and 8'.	\$210.00	1	each	\$210.00	1
Coral Cove Park	8	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Coral Cove Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Coral Cove Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	375	sq ft	\$45,937.50	1
Coral Cove Park	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Coral Cove Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	13	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Coral Cove Park	14	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Coral Cove Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	16	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Coral Cove Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	60	sq ft	\$7,350.00	1
Coral Cove Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	60	sq ft	\$7,350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	20	Exterior Accessible Route	Accessible Routes	Replace drain grate with one having max gaps of .5".	\$850.00	1	each	\$850.00	1
Coral Cove Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	225	sq ft	\$27,562.50	1
Coral Cove Park	22	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Coral Cove Park	23	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Coral Cove Park	24	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Coral Cove Park	25	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Coral Cove Park	26	Park Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Coral Cove Park	27	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Coral Cove Park	30	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Coral Cove Park	31	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Coral Cove Park	32	Beach Access Route	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Coral Cove Park	33	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	250	lin ft	\$14,800.00	4
Coral Cove Park	34	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	100	sq ft	\$12,250.00	4
Coral Cove Park	35	Beach Access Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.  In the alternative, leave as is and designate other County beaches accessible.	\$3,062.50	2	each	\$6,125.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	36	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	750	sq ft	\$91,875.00	4
Coral Cove Park	37	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	1200	sq ft	\$147,000.00	4
Coral Cove Park	38	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	800	sq ft	\$98,000.00	4
Coral Cove Park	39	Beach Access Route	Outdoor Recreation Access Routes (C)	Establish protocols for regular and frequent inspection and maintenance of ORAR surfaces.  In the alternative, leave as is and designate other County beaches accessible.	\$0.00	1	staff time	\$0.00	4
Coral Cove Park	40	Beach Access Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.  In the alternative, leave as is and designate other County beaches accessible.	\$875.00	1	each	\$875.00	4
Coral Cove Park	41	Beach Access Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.  In the alternative, leave as is and designate other County beaches accessible.	\$875.00	1	each	\$875.00	4
Coral Cove Park	42	Beach Access Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4" - 6.25" max with a min gap of 1.5" between handrail and wall.  In the alternative, leave as is and designate other County beaches accessible.	\$980.00	28	each	\$27,440.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	43	Beach Access Route	Stairways	<p>Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.</p> <p>Pricing provided in a previous finding.</p> <p>In the alternative, leave as is and designate other County beaches accessible.</p>	\$0.00	10	each	\$0.00	4
Coral Cove Park	44	Beach Access Route	Stairways	<p>Mount new handrails to 34" to 38" AFF.</p> <p>Pricing provided in a previous finding.</p> <p>In the alternative, leave as is and designate other County beaches accessible.</p>	\$0.00	10	each	\$0.00	4
Coral Cove Park	45	Picnic Areas	Turning Space	<p>Correct slopes in turning spaces at accessible picnic tables to max 2.08%.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$3,062.50	2	each	\$6,125.00	4
Coral Cove Park	46	Picnic Areas	Picnic Tables (C)	<p>Replace picnic table with one of an accessible design as a smart practice.</p> <p>Provide required 36" clear ground space around all usable portions of the table as a smart practice.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$3,606.00	2	each	\$7,212.00	4
Coral Cove Park	47	Picnic Areas	Shelters, Picnic Facilities (C)	<p>Create an ORAR to two grills and provide accessible features as a smart practice.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$59.20	20	lin ft	\$1,184.00	4
Coral Cove Park	48	Picnic Areas	Reach Ranges	<p>Remount operable parts to be in reach range of 15" min to 48" max.</p> <p>Relocate 20% of garbage cans to be along AR, with max slopes of 2.08% in clear ground space.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$0.00	2	staff time	\$0.00	4
Coral Cove Park	49	5-12 Play Area	Play Area	<p>Consider adding a second transfer system as a smart practice.</p>	\$4,970.00	1	each	\$4,970.00	5
Coral Cove Park	53	5-12 Play Area	Doors	<p>Provide kick plate on push side of door from floor to 10" AFF. Leave as is if constructed prior to March 15, 2012.</p>	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	54	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	55	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Coral Cove Park	56	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under right sink.	\$77.00	1	each	\$77.00	1
Coral Cove Park	57	Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Coral Cove Park	58	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Coral Cove Park	59	Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Coral Cove Park	60	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Coral Cove Park	61	Men's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Coral Cove Park	62	Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Coral Cove Park	63	Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Coral Cove Park	64	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Coral Cove Park	65	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.  Relocate to wall with grab bars.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	66	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$175.00	2	each	\$350.00	1
Coral Cove Park	67	Men's Restroom	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	1
Coral Cove Park	68	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	69	Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	70	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	71	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Coral Cove Park	72	Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	2
Coral Cove Park	73	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Coral Cove Park	74	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Coral Cove Park	75	Women's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Coral Cove Park	76	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Coral Cove Park	77	Women's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Coral Cove Park	78	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Coral Cove Park	79	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Coral Cove Park	80	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.  Relocate to wall with grab bars.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	81	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Coral Cove Park	82	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Coral Cove Park	83	Women's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide a ramp for access.	\$6,510.00	1	each	\$6,510.00	3
Coral Cove Park	84	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
Coral Cove Park	85	Employee Spaces	Reach Ranges	Lower hook in lockers to max 48" AFF.  Remount shelves in lockers to min 40" and max 48".	\$175.00	1	each	\$175.00	3
Coral Cove Park	86	Employee Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Coral Cove Park	87	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.	\$1,890.00	1	each	\$1,890.00	3
Coral Cove Park	88	Lifeguard Restroom and Shower	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Coral Cove Park	89	Lifeguard Restroom and Shower	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Coral Cove Park	90	Lifeguard Restroom and Shower	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Coral Cove Park	91	Lifeguard Restroom and Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	92	Lifeguard Restroom and Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	93	Lifeguard Restroom and Shower	Toilet and Bathing Rooms	Relocate storage to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	94	Lifeguard Restroom and Shower	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Coral Cove Park	95	Lifeguard Restroom and Shower	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Coral Cove Park	96	Lifeguard Restroom and Shower	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Coral Cove Park	97	Lifeguard Restroom and Shower	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
County Pines Rec Complex at Samuel Friedland Park	2	Parking - Ballfields	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
County Pines Rec Complex at Samuel Friedland Park	3	Parking - Ballfields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	6	each	\$441.00	1
County Pines Rec Complex at Samuel Friedland Park	4	Parking - Ballfields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	7	each	\$514.50	1
County Pines Rec Complex at Samuel Friedland Park	5	Parking - Ballfields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	8	each	\$24,500.00	1
County Pines Rec Complex at Samuel Friedland Park	6	Parking - Ballfields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. Leave as is 2.2% slope citing construction tolerance.	\$3,062.50	10	each	\$30,625.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	7	Parking - Ballfields	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	8	Parking - Ballfields	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	9	Parking - Ballfields	Parking - Off Street	Add one van parking sign to two accessible east stalls and two accessible west stalls (4 total required) and ensure stall and access aisle are 12' and 5'.	\$210.00	4	each	\$840.00	1
County Pines Rec Complex at Samuel Friedland Park	11	Parking - Multi-Use Fields	Parking - Off Street	Relocate two stalls to be on the shortest AR to multi-use fields 10 and 11.	\$367.50	2	each	\$735.00	1
County Pines Rec Complex at Samuel Friedland Park	12	Parking - Multi-Use Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
County Pines Rec Complex at Samuel Friedland Park	13	Parking - Multi-Use Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	14	Parking - Multi-Use Fields	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
County Pines Rec Complex at Samuel Friedland Park	15	Parking - Maintenance	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
County Pines Rec Complex at Samuel Friedland Park	16	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	17	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
County Pines Rec Complex at Samuel Friedland Park	18	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	19	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
County Pines Rec Complex at Samuel Friedland Park	20	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	21	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
County Pines Rec Complex at Samuel Friedland Park	22	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Repair and reset pavers to eliminate CIL and gaps	\$28.00	240	sq ft	\$6,720.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	23	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	24	Exterior Accessible Route - Baseball Fields 1-4	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
County Pines Rec Complex at Samuel Friedland Park	25	Exterior Accessible Route - Baseball Fields 1-4	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
County Pines Rec Complex at Samuel Friedland Park	26	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	27	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Reposition bleachers to widen EAR to min 36" clear width. Reposition bleachers to widen AR at the turn to be 42" wide and 48" deep at the turn.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	28	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
County Pines Rec Complex at Samuel Friedland Park	29	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
County Pines Rec Complex at Samuel Friedland Park	30	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1950	sq ft	\$238,875.00	1
County Pines Rec Complex at Samuel Friedland Park	31	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	32	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	70	sq ft	\$8,575.00	1
County Pines Rec Complex at Samuel Friedland Park	33	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
County Pines Rec Complex at Samuel Friedland Park	34	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	35	sq ft	\$4,287.50	1
County Pines Rec Complex at Samuel Friedland Park	35	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	126	sq ft	\$15,435.00	1
County Pines Rec Complex at Samuel Friedland Park	36	Exterior Accessible Route - Multi-Use Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	140	sq ft	\$17,150.00	1
County Pines Rec Complex at Samuel Friedland Park	37	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	38	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	39	Exterior Accessible Route - Multi-Use Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	40	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
County Pines Rec Complex at Samuel Friedland Park	41	Park Element	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
County Pines Rec Complex at Samuel Friedland Park	42	Park Element	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
County Pines Rec Complex at Samuel Friedland Park	43	Park Element	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
County Pines Rec Complex at Samuel Friedland Park	44	Park Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5
County Pines Rec Complex at Samuel Friedland Park	46	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
County Pines Rec Complex at Samuel Friedland Park	47	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
County Pines Rec Complex at Samuel Friedland Park	48	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
County Pines Rec Complex at Samuel Friedland Park	49	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
County Pines Rec Complex at Samuel Friedland Park	50	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
County Pines Rec Complex at Samuel Friedland Park	51	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
County Pines Rec Complex at Samuel Friedland Park	52	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
County Pines Rec Complex at Samuel Friedland Park	53	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
County Pines Rec Complex at Samuel Friedland Park	54	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	8	each	\$770.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	55	Mockingbird Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5
County Pines Rec Complex at Samuel Friedland Park	56	Mockingbird Pavilion	Shelters/Picnic Areas (C)	<p>Replace existing amenities with ones of an accessible design and provide required clear ground space.</p> <p>Replace or lower grill to max height of cooking surface 34".</p> <p>Adjust grill cooking surface lids to be usable with 5 lbf or less.</p> <p>Replace operable parts of grills and water spigot with ones usable without a tight pinch or grasp.</p> <p>Remount rims of garbage cans to be in reach range of 15" min to 48" max.</p>	\$786.50	3	each	\$2,359.50	5
County Pines Rec Complex at Samuel Friedland Park	57	Multi-Use Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	25	lin ft	\$1,480.00	2
County Pines Rec Complex at Samuel Friedland Park	59	Multi-Use Fields	Reach Ranges	Remount garbage cans to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	60	Multi-Use Fields	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	4	each	\$3,595.00	2
County Pines Rec Complex at Samuel Friedland Park	61	Multi-Use Fields	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	3	each	\$2,696.25	2
County Pines Rec Complex at Samuel Friedland Park	62	Multi-Use Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	28	lin ft	\$1,657.60	2
County Pines Rec Complex at Samuel Friedland Park	63	Multi-Use Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	28	lin ft	\$1,657.60	2
County Pines Rec Complex at Samuel Friedland Park	65	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	66	Soccer Fields - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
County Pines Rec Complex at Samuel Friedland Park	67	Soccer Fields - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	68	Soccer Fields - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
County Pines Rec Complex at Samuel Friedland Park	69	Soccer Fields - Women's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	70	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	71	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing for remounting one bar provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$131.25	3	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	72	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Provide maneuvering clearance at accessible compartment door min 18" to pull side.  Adjust stall door to be self-closing.	\$2,749.25	1	each	\$2,749.25	1
County Pines Rec Complex at Samuel Friedland Park	73	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	74	Soccer Fields - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
County Pines Rec Complex at Samuel Friedland Park	75	Soccer Fields - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
County Pines Rec Complex at Samuel Friedland Park	76	Soccer Fields - Men's Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	77	Soccer Fields - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	78	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	79	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	80	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
County Pines Rec Complex at Samuel Friedland Park	81	Soccer Fields - Men's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	82	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. In the alternative, leave as is citing construction tolerance.	\$393.75	1	each	\$393.75	4
County Pines Rec Complex at Samuel Friedland Park	83	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	84	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing provided in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	85	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	86	Soccer Fields - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
County Pines Rec Complex at Samuel Friedland Park	87	Soccer Fields - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
County Pines Rec Complex at Samuel Friedland Park	88	Portable Restroom At North Ballfields	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
County Pines Rec Complex at Samuel Friedland Park	89	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
County Pines Rec Complex at Samuel Friedland Park	90	Public Spaces	Stairways	Relocate storage to remove obstruction from handrail gripping surface.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	91	Public Spaces	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	92	Public Spaces	Turning Space	Relocate obstacles to create turning space in lower press box area.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	93	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	94	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	2
County Pines Rec Complex at Samuel Friedland Park	95	Public Spaces	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	3	each	\$231.00	2
County Pines Rec Complex at Samuel Friedland Park	96	Public Spaces	Kitchens, Kitchenettes, And Wet Bars	Provide required clear floor space at appliances.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	97	Public Spaces	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	98	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
County Pines Rec Complex at Samuel Friedland Park	99	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$5,835.00	1	each	\$5,835.00	3
County Pines Rec Complex at Samuel Friedland Park	100	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$5,835.00	1	each	\$5,835.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	101	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	102	Men's Restroom	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	103	Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	104	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
County Pines Rec Complex at Samuel Friedland Park	105	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area, and sink in stall.	\$77.00	2	each	\$154.00	1
County Pines Rec Complex at Samuel Friedland Park	106	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	107	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	108	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	109	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	110	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
County Pines Rec Complex at Samuel Friedland Park	111	Women's Restroom	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	112	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	113	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
County Pines Rec Complex at Samuel Friedland Park	114	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	115	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	116	Women's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
County Pines Rec Complex at Samuel Friedland Park	117	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	118	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	119	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
County Pines Rec Complex at Samuel Friedland Park	120	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
County Pines Rec Complex at Samuel Friedland Park	121	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
County Pines Rec Complex at Samuel Friedland Park	122	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.00	225	sq ft	\$27,450.00	3
County Pines Rec Complex at Samuel Friedland Park	123	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	3
County Pines Rec Complex at Samuel Friedland Park	124	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$1,961.25	1	each	\$1,961.25	3
County Pines Rec Complex at Samuel Friedland Park	125	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
County Pines Rec Complex at Samuel Friedland Park	126	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	127	Employee Spaces	Reach Ranges	Lower operating mechanisms of alarms controls, thermostat, AED, and toaster to max 48" above the finished floor (AFF) to highest operable part. In the alternative, leave as is if constructed before March 15, 2012.  Lower operating mechanisms of paper towel and soap dispensers to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$116.50	6	each	\$699.00	3
County Pines Rec Complex at Samuel Friedland Park	128	Employee Spaces	Dining, Bar and Work Surfaces	Provide one table with surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
County Pines Rec Complex at Samuel Friedland Park	129	Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. in the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
County Pines Rec Complex at Samuel Friedland Park	130	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Repair, provide beveled threshold.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$737.50	7	each	\$5,162.50	3
County Pines Rec Complex at Samuel Friedland Park	131	Employee Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	4	each	\$840.00	1
County Pines Rec Complex at Samuel Friedland Park	132	Maintenance - Men's Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	133	Maintenance - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	134	Maintenance - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	135	Maintenance - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	136	Maintenance - Men's Restroom	Toilet and Bathing Rooms	Relocate urinal and garbage can to provide required 60" clearance around toilet. Leave as is urinal if constructed prior to March 15, 2012.	\$1,704.50	1	each	\$1,704.50	1
County Pines Rec Complex at Samuel Friedland Park	137	Maintenance - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	138	Maintenance - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	139	Maintenance - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar. Remove storage from grab bar.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	140	Maintenance - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
County Pines Rec Complex at Samuel Friedland Park	141	Maintenance - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
County Pines Rec Complex at Samuel Friedland Park	142	Maintenance - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
County Pines Rec Complex at Samuel Friedland Park	143	Maintenance - Women's Restroom	Accessible Routes	Raise shower curtain rod to min 80".	\$140.00	1	each	\$140.00	1
County Pines Rec Complex at Samuel Friedland Park	144	Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	145	Maintenance - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
County Pines Rec Complex at Samuel Friedland Park	146	Maintenance - Women's Restroom	Toilet and Bathing Rooms	Relocate storage and paper towel dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	147	Maintenance - Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	148	Maintenance - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	149	Maintenance - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	150	Maintenance - Women's Restroom	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
County Pines Rec Complex at Samuel Friedland Park	151	Maintenance - Women's Restroom	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension. In the alternative, leave as is citing construction tolerance.	\$5,498.50	1	each	\$5,498.50	4
County Pines Rec Complex at Samuel Friedland Park	152	Maintenance - Women's Restroom	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the transfer shower.	\$350.00	1	each	\$350.00	2
County Pines Rec Complex at Samuel Friedland Park	153	Maintenance - Women's Restroom	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	154	Maintenance - Women's Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
County Pines Rec Complex at Samuel Friedland Park	155	Maintenance - Women's Restroom	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	156	North Ballfields Elements	Reach Ranges	Remount two garbage cans to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	157	North Ballfields Elements	Operable Parts	Provide method to enter batting cages that does not require pinch or grasp	\$210.00	1	each	\$210.00	2
County Pines Rec Complex at Samuel Friedland Park	158	North Ballfields Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	30	lin ft	\$1,776.00	3
County Pines Rec Complex at Samuel Friedland Park	159	North Ballfields EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
County Pines Rec Complex at Samuel Friedland Park	160	North Ballfields EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
County Pines Rec Complex at Samuel Friedland Park	161	North Ballfields EAR	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	2
County Pines Rec Complex at Samuel Friedland Park	162	North Ballfields EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	10	lin ft	\$592.00	2
County Pines Rec Complex at Samuel Friedland Park	163	North Ballfields EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
County Pines Rec Complex at Samuel Friedland Park	164	North Ballfields EAR	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	16	lin ft	\$947.20	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	165	North Ballfields EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	30	each	\$2,887.50	1
County Pines Rec Complex at Samuel Friedland Park	166	North Ballfields EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	2
County Pines Rec Complex at Samuel Friedland Park	167	North Ballfields EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
County Pines Rec Complex at Samuel Friedland Park	168	North Ballfields EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	360	sq ft	\$44,100.00	2
County Pines Rec Complex at Samuel Friedland Park	169	North Ballfields EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	360	sq ft	\$44,100.00	2
County Pines Rec Complex at Samuel Friedland Park	170	North Ballfields EAR	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	6	each	\$1,974.00	5
County Pines Rec Complex at Samuel Friedland Park	172	North Ballfield 5	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Remount bolt locks 34" to 48" AFF.	\$610.75	1	each	\$610.75	3
County Pines Rec Complex at Samuel Friedland Park	174	North Ballfield 5	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
County Pines Rec Complex at Samuel Friedland Park	175	North Ballfield 5	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$3,026.50	2	each	\$6,053.00	2
County Pines Rec Complex at Samuel Friedland Park	176	North Ballfield 5	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of route surfaces.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	177	North Ballfield 5	Park Site (C)	Relocate garbage can to provide 36" by 48" adjacent to each player bench.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	178	North Ballfield 7	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of dugout surfaces.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	180	North Ballfield 7	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$3,757.25	2	each	\$7,514.50	2
County Pines Rec Complex at Samuel Friedland Park	181	North Ballfield 7	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	35	lin ft	\$2,072.00	2
County Pines Rec Complex at Samuel Friedland Park	182	North Ballfield 7	Park Site (C)	Relocate garbage can to provide 36" by 48" adjacent to each player bench.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	183	North Ballfield 7	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	1	each	\$840.00	2
County Pines Rec Complex at Samuel Friedland Park	184	North Ballfield 7	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$851.50	1	each	\$851.50	3
County Pines Rec Complex at Samuel Friedland Park	187	North Ballfield 8	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	20	lin ft	\$1,184.00	2
County Pines Rec Complex at Samuel Friedland Park	188	North Ballfield 8	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$3,853.50	2	each	\$7,707.00	1
County Pines Rec Complex at Samuel Friedland Park	189	South Baseball Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
County Pines Rec Complex at Samuel Friedland Park	190	South Baseball Fields	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	191	South Baseball Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$2,360.75	2	each	\$4,721.50	2
County Pines Rec Complex at Samuel Friedland Park	192	South Baseball Fields	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	2
County Pines Rec Complex at Samuel Friedland Park	193	South Baseball Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$2,360.75	2	each	\$4,721.50	2
County Pines Rec Complex at Samuel Friedland Park	194	South Baseball Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
County Pines Rec Complex at Samuel Friedland Park	195	South Baseball Fields	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
County Pines Rec Complex at Samuel Friedland Park	197	South Baseball Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$2,103.50	2	each	\$4,207.00	2
County Pines Rec Complex at Samuel Friedland Park	198	South Baseball Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
County Pines Rec Complex at Samuel Friedland Park	199	South Baseball Fields	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
County Pines Rec Complex at Samuel Friedland Park	200	South Baseball Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$2,360.75	2	each	\$4,721.50	2
County Pines Rec Complex at Samuel Friedland Park	201	South Baseball Fields	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
County Pines Rec Complex at Samuel Friedland Park	202	South Baseball Fields	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.	\$840.00	2	each	\$1,680.00	2
DuBois Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
DuBois Park	3	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
DuBois Park	5	Parking	Parking - Off Street	Widen accessible route to min 44" clear width and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
DuBois Park	6	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
DuBois Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
DuBois Park	8	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
DuBois Park	9	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%. In the alternative, leave as is ciping construction tolerance.	\$6,510.00	1	each	\$6,510.00	4
DuBois Park	10	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%. Correct transition to max 8.33% slope.	\$875.00	2	each	\$1,750.00	1
DuBois Park	11	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	1
DuBois Park	12	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	1
DuBois Park	14	Picnic area parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
DuBois Park	15	Picnic area parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
DuBois Park	17	Beachfront And Pineapple House Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
DuBois Park	18	Beachfront And Pineapple House Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
DuBois Park	19	Beachfront And Pineapple House Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way and connect aisle to min 44" wide accessible route.	\$1,487.50	1	each	\$1,487.50	1
DuBois Park	20	Beachfront And Pineapple House Parking	Parking - Off Street	Paint 5' access aisle to be adjacent to the parking stall.	\$1,589.00	1	each	\$1,589.00	1
DuBois Park	21	Boat Docks	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	20	lin ft	\$1,184.00	2
DuBois Park	22	Boat Docks	Boating Facilities	Provide 60" clear pier space for the entire length of at least one pier.  In the alternative, leave as is and designate other County boat docks accessible.	\$6,510.00	1	each	\$6,510.00	4
DuBois Park	23	Boat Docks	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  In the alternative, leave as is and designate other County boat docks accessible.	\$96.25	3	each	\$288.75	4
DuBois Park	24	Water Taxi	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
DuBois Park	25	Water Taxi	Boating Facilities	Provide 60" clear pier space for the entire length of pier.	\$6,510.00	1	each	\$6,510.00	2
DuBois Park	26	Water Taxi	Boating Facilities	Correct gangway to reduce the slope of the transition plate to a max of 8.33% at all water levels; leave as is if technically infeasible.	\$3,062.50	1	each	\$3,062.50	2
DuBois Park	27	Picnic Areas	Shelters/Picnic Areas (C)	Provide an AR and accessible tables to picnic units to achieve the required number of 20% accessible as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$5,560.00	2	each	\$11,120.00	4
DuBois Park	28	Picnic Areas	Outdoor Recreation Access Routes (C)	Provide maintenance to remove protruding objects along the ORAR as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
DuBois Park	29	Picnic Areas	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.  Provide CGS at grills.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
DuBois Park	30	Picnic Areas	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
DuBois Park	31	Rood Pavilion	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
DuBois Park	32	Rood Pavilion	Outdoor - Constructed Features (C)	Provide required clear ground space at water hydrant as a smart practice.	\$700.00	1	sq ft	\$700.00	5
DuBois Park	33	Rood Pavilion	Outdoor - Constructed Features (C)	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
DuBois Park	34	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08% at two benches as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
DuBois Park	36	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	12	lin ft	\$710.40	2
DuBois Park	37	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
DuBois Park	38	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$5,598.25	1	each	\$5,598.25	2
DuBois Park	39	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice at one shower.	\$540.75	1	each	\$540.75	5
DuBois Park	40	Park Elements	Outdoor - Constructed Features (C)	Provide required 60" by 60" clear ground space at outdoor showers as a smart practice.	\$1,480.00	1	each	\$1,480.00	5
DuBois Park	41	Beach Access Route	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (grills, garbage, water spigots)	\$59.20	50	lin ft	\$2,960.00	5
DuBois Park	42	Beach Access Route	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice.	\$59.20	100	lin ft	\$5,920.00	5
DuBois Park	43	Beach Access Route	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice	\$59.20	100	lin ft	\$5,920.00	5
DuBois Park	44	Beach Access Route	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice.	\$59.20	50	lin ft	\$2,960.00	5
DuBois Park	45	Playground	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	25	sq ft	\$1,750.00	4
DuBois Park	46	Playground	Play Area	Raise platform on transfer system to 11" to 18" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
DuBois Park	47	Playground	Play Area	Install descending step on transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$750.00	1	each	\$750.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
DuBois Park	50	Playground	Play Area	Raise or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
DuBois Park	51	Playground	Play Area	Add 1 more GLPC's of 1 type to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
DuBois Park	52	Employee Spaces	Room/Space (C)	Provide an accessible route to the building entry.	\$59.20	35	lin ft	\$2,072.00	3
DuBois Park	53	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$59.20	100	lin ft	\$5,920.00	3
DuBois Park	54	Caretaker's House	1.0 Capture (C)	Provide a ramp to access entry of residence.	\$6,510.00	1	each	\$6,510.00	3
DuBois Park	55	Public Spaces	Accessible Routes	Provide a ramp or other accessible route to access DuBois House.  Prior to making any changes at this site, check with the State Historic Preservation Officer.	\$6,510.00	2	each	\$13,020.00	3
DuBois Park	56	Public Spaces	Doors	For all doors along the public circulation route, ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Prior to making any changes at this site, check with the State Historic Preservation Officer.	\$7,014.50	1	each	\$7,014.50	3
DuBois Park	57	Public Spaces	Accessible Routes	Widen doorways along the interior route to min. 32" clear width.  Prior to making any changes at this site, check with the State Historic Preservation Officer.	\$2,772.50	2	each	\$5,545.00	3
DuBois Park	58	Public Spaces	Stairways	Install kick plates on all stairs or replace with ones having closed risers.  Prior to making any changes at this site, check with the State Historic Preservation Officer.	\$84.00	18	each	\$1,512.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
DuBois Park	59	Public Spaces	Stairways	<p>Install contrasting strip along front 2" of each tread as a smart practice.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p> <p>Prior to making any changes at this site, check with the State Historic Preservation Officer.</p>	\$125.00	18	each	\$2,250.00	5
DuBois Park	60	Public Spaces	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.</p> <p>Prior to making any changes at this site, check with the State Historic Preservation Officer.</p>	\$980.00	2	each	\$1,960.00	3
DuBois Park	61	Restrooms	Toilet and Bathing Rooms	<p>Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible. Until renovations occur, mount signage directing patrons to an accessible restroom.</p> <p>Prior to making any changes at this site, check with the State Historic Preservation Officer.</p>	\$24,928.75	1	each	\$24,928.75	3
DuBois Park	62	Pineapple Packing House	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	1
DuBois Park	64	Women's Restroom	Doors	Relocate garbage bin to keep door 32" clear width.	\$0.00	1	staff time	\$0.00	1
DuBois Park	65	Women's Restroom	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
DuBois Park	66	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
DuBois Park	67	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area of restroom.	\$77.00	1	each	\$77.00	1
DuBois Park	68	Women's Restroom	Reach Ranges	Lower top of baby changing surfaces to 28 inches minimum and 34 inches maximum above the finish floor or ground.	\$0.00	1	staff time	\$0.00	1
DuBois Park	69	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
DuBois Park	70	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
DuBois Park	71	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
DuBois Park	72	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
DuBois Park	73	Men's Restroom	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
DuBois Park	74	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
DuBois Park	75	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
DuBois Park	76	Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,978.50	1	each	\$2,978.50	1
DuBois Park	77	Men's Restroom	Reach Ranges	Lower baby changing table surface to 28 inches minimum and 34 inches maximum above the finish floor or ground.	\$0.00	1	staff time	\$0.00	1
DuBois Park	78	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
DuBois Park	79	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
DuBois Park	80	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Duncan Padgett Park	1	Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Duncan Padgett Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Duncan Padgett Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Duncan Padgett Park	4	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$210.00	1	each	\$210.00	1
Duncan Padgett Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Duncan Padgett Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Duncan Padgett Park	13	Play Area - 2-5	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	25	lin ft	\$1,480.00	4
Duncan Padgett Park	14	Play Area - 2-5	Play Area	Create min 36" wide designated entry as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Duncan Padgett Park	15	Play Area - 2-5	Play Area	Consider adding a second transfer system as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Duncan Padgett Park	17	Play Area - 2-5	Play Area	Provide an AR to element for one of each type accessible. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	25	lin ft	\$1,480.00	4
Duncan Padgett Park	18	Play Area - 2-5	Play Area	Add at least 2 more GLPCs of 2 types other than swings to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
Duncan Padgett Park	19	Play Area - 5-12	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	25	lin ft	\$1,480.00	4
Duncan Padgett Park	20	Play Area - 5-12	Play Area	Create min 36" wide designated entry as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Duncan Padgett Park	21	Play Area - 5-12	Play Area	Consider adding a second transfer system as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Duncan Padgett Park	22	Play Area - 5-12	Play Area	Add one more play components to the elevated structure and on the accessible route, such as a steering wheel, periscope, or talk tube, to meet the 50% accessible standard for EPCs  Adjust height of platform decks to max 8" for access to EPCs, in the alternative, install compliant transfer steps  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Duncan Padgett Park	23	Play Area - 5-12	Play Area	Provide an AR to element for one of each type accessible. Cost in Play Area 2-5 Findings.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	lin ft	\$0.00	4
Duncan Padgett Park	24	Play Area - 5-12	Play Area	Add min 2 more GLPCs of 2 types other than swings to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
Duncan Padgett Park	25	Sport Fields/Courts	Doors	Repair, bevel or ramp CIL at doorway.	\$96.25	18	each	\$1,732.50	2
Duncan Padgett Park	26	Sport Fields/Courts	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain and provide route and clear ground space.	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Duncan Padgett Park	29	Sport Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to one ball field and leave the other field as is.  Provide required clear ground space min 36" by 48" adjacent to short end of bench in each dugout.	\$914.00	1	each	\$914.00	2
Duncan Padgett Park	30	Sport Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to one ball field and leave the other field as is.  Provide required clear ground space min 36" by 48" adjacent to short end of bench in each dugout.	\$914.00	1	each	\$914.00	2
Duncan Padgett Park	31	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Duncan Padgett Park	32	Park Elements	Accessible Routes	Lower garbage cans on route to 48" AFF.	\$0.00	1	staff time	\$0.00	2
Duncan Padgett Park	33	Parking and Exterior Accessible Route	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	3
Duncan Padgett Park	34	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	35	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	36	Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Repair, provide beveled threshold.	\$3,255.00	1	each	\$3,255.00	3
Duncan Padgett Park	37	Employee Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	3
Duncan Padgett Park	38	Employee Restroom	Toilet and Bathing Rooms	Remount signage to the proper location based on the type of door provided.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Duncan Padgett Park	39	Employee Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	3
Duncan Padgett Park	40	Employee Restroom	Plumbing Fixtures & Elements	Relocate items to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	41	Employee Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	42	Employee Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	3
Duncan Padgett Park	43	Employee Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Duncan Padgett Park	44	Employee Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	45	Employee Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Duncan Padgett Park	46	Public Spaces	Accessible Routes	Widen AR to compliant 36" clear width	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	47	Public Spaces	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	48	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	49	Public Spaces	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	3
Duncan Padgett Park	50	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Duncan Padgett Park	51	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	3
Duncan Padgett Park	52	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Duncan Padgett Park	53	Women's Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Duncan Padgett Park	54	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Duncan Padgett Park	55	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Duncan Padgett Park	56	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Duncan Padgett Park	57	Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Duncan Padgett Park	58	Women's Restroom	Accessible Routes	Widen AR to compliant 36" clear width	\$2,945.00	1	each	\$2,945.00	1
Duncan Padgett Park	59	Women's Restroom	Turning Space	Relocate obstacles to create turning space in restroom.	\$2,749.25	1	each	\$2,749.25	1
Duncan Padgett Park	60	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Duncan Padgett Park	61	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	62	Women's Restroom	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	63	Men's Restroom	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
Duncan Padgett Park	64	Men's Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Duncan Padgett Park	65	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Duncan Padgett Park	66	Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Duncan Padgett Park	67	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	1	Parking - RC Airfield	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Dyer Park	3	Parking - Soccer Fields	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	4	each	\$294.00	1
Dyer Park	4	Parking - Soccer Fields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Dyer Park	5	Parking - Soccer Fields	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.  Remove van sign from leftmost space, unless that space is chosen to be restriped to provide compliant widths of both stall and access aisle.	\$283.50	1	each	\$283.50	1
Dyer Park	6	Parking - Soccer Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Dyer Park	7	Parking - Soccer Fields	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps, cracks, and CILs  Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$2,800.00	2	each	\$5,600.00	1
Dyer Park	8	Parking - Soccer Fields	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Dyer Park	10	Parking - Ballfields	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Dyer Park	11	Parking - Ballfields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	12	Parking - Ballfields	Parking - Off Street	Add one van parking sign to left-middle accessible stall and ensure stall and access aisle are 12' and 5'.  Remove van signs from leftmost and rightmost spaces, as they do not meet width requirements for van accessible parking spaces.	\$210.00	1	each	\$210.00	1
Dyer Park	13	Parking - Ballfields	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps, cracks, and CILS.  Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$2,800.00	2	each	\$5,600.00	1
Dyer Park	14	Parking - Ballfields	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	2	each	\$420.00	1
Dyer Park	15	Parking - Ballfields	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking. See previous finding for some of the cost.	\$73.50	5	each	\$367.50	1
Dyer Park	17	Parking - Play Area	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Dyer Park	18	Parking - Play Area	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Dyer Park	19	Parking - Play Area	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Dyer Park	20	Parking - Play Area	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Dyer Park	21	Parking - Play Area	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$0.00	1	staff time	\$0.00	1
Dyer Park	22	Parking - Play Area	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	2	each	\$420.00	1
Dyer Park	23	Parking - Play Area	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking. Cost included in previous finding.	\$0.00	5	each	\$0.00	1
Dyer Park	24	Overflow Parking	Parking - Off Street	Create four or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls and add them to the main lot.	\$1,589.00	4	each	\$6,356.00	1
Dyer Park	26	Maintenance - Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Dyer Park	27	Maintenance - Parking	Parking - Off Street	Add one 5' adjacent access aisle, with proper signage and striping to existing stall.	\$1,589.00	1	each	\$1,589.00	1
Dyer Park	28	Maintenance - Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'. Cost included in previous findings.	\$0.00	1	each	\$0.00	1
Dyer Park	29	Maintenance - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Dyer Park	30	Maintenance - Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	31	Maintenance - Parking	Parking - Off Street	Mount accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Dyer Park	32	Maintenance - Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Dyer Park	33	Maintenance - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
Dyer Park	35	Parking - Golf Learning Center	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	7	each	\$514.50	1
Dyer Park	36	Parking - Golf Learning Center	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
Dyer Park	37	Parking - Golf Learning Center	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	10	each	\$30,625.00	1
Dyer Park	38	Parking - Golf Learning Center	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks. Cost included in slope correction.	\$0.00	7	each	\$0.00	1
Dyer Park	39	Parking - Golf Learning Center	Parking - Off Street	Add one van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$210.00	2	each	\$420.00	1
Dyer Park	40	Parking - Golf Learning Center	Parking - Off Street	Relocate obstructions from accessible route to provide a min 44" clear width and assure connection to access aisle.	\$350.00	1	each	\$350.00	1
Dyer Park	41	Parking - Golf Learning Center	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	11	each	\$808.50	1
Dyer Park	42	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	43	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	210	sq ft	\$25,725.00	1
Dyer Park	44	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	96	sq ft	\$11,760.00	1
Dyer Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Dyer Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	630	sq ft	\$77,175.00	1
Dyer Park	47	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	265	sq ft	\$32,462.50	1
Dyer Park	48	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	570	sq ft	\$69,825.00	1
Dyer Park	49	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Dyer Park	50	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Dyer Park	51	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	52	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	390	sq ft	\$47,775.00	1
Dyer Park	53	Exterior Accessible Route	Detectable Warnings	Replace existing detectable warning with compliant truncated dome template integrated into the walking surface, where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Dyer Park	54	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	55	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	56	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Dyer Park	57	Exterior Accessible Route	Accessible Routes	Replace drain grates with ones having openings max .5".	\$2,000.00	3	each	\$6,000.00	1
Dyer Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	650	sq ft	\$79,625.00	1
Dyer Park	59	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Dyer Park	60	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	650	sq ft	\$1,990,625.00	1
Dyer Park	61	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Dyer Park	62	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Dyer Park	63	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%.	\$1,015.00	1	each	\$1,015.00	1
Dyer Park	64	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Dyer Park	65	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Dyer Park	66	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Dyer Park	67	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1225	sq ft	\$150,062.50	1
Dyer Park	68	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Dyer Park	69	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Dyer Park	70	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	lin ft	\$55,125.00	1
Dyer Park	71	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1400	sq ft	\$171,500.00	1
Dyer Park	72	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	73	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Dyer Park	74	Soccer Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	450	lin ft	\$26,640.00	4
Dyer Park	75	Soccer Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	450	lin ft	\$26,640.00	4
Dyer Park	76	Soccer Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	450	lin ft	\$26,640.00	4
Dyer Park	77	Basketball Courts	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Dyer Park	79	Ballfield 1	Clear Floor Space	Remove, or relocate storage or obstructions in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	80	Ballfield 1	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$6,413.75	1	each	\$6,413.75	2
Dyer Park	81	Ballfield 1	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Dyer Park	82	Ballfield 1	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of dugout surface.	\$0.00	1	staff time	\$0.00	1
Dyer Park	83	Ballfield 1	Park Site (C)	Correct or repair slope in CFS to max 2.08%.  Remove, or relocate storage in CFS to provide required 36" by 48" CFS.	\$122.50	24	sq ft	\$2,940.00	2
Dyer Park	84	Ballfield 1	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Dyer Park	87	Ballfield 1	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	88	Ballfield 2	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of dugout surfaces.	\$0.00	1	staff time	\$0.00	1
Dyer Park	89	Ballfield 2	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps in door/gate clearances.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$9,380.00	1	each	\$9,380.00	2
Dyer Park	90	Ballfield 2	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Dyer Park	91	Ballfield 2	Park Site (C)	Correct or repair slope in CFS to max 2.08%.  Remove, or relocate storage in CFS to provide required 36" by 48" CFS.	\$122.50	12	sq ft	\$1,470.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	94	Ballfield 2	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	250	lin ft	\$14,800.00	2
Dyer Park	95	RC Airfield	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR	\$1,092.00	1	each	\$1,092.00	1
Dyer Park	96	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	40	lin ft	\$2,368.00	2
Dyer Park	97	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	110	lin ft	\$6,512.00	2
Dyer Park	98	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$55,084.00	1	each	\$55,084.00	2
Dyer Park	99	RC Airfield	Park Site (C)	Provide an accessible route (AR) to at least one of each element within the site.	\$59.20	15	lin ft	\$888.00	2
Dyer Park	100	RC Airfield	Dining, Bar and Work Surfaces	Replace or add one work surface max 34" to surface and allowing knee and toe clearance. In the alternative, leave as is citing construction tolerance.	\$1,120.00	1	each	\$1,120.00	4
Dyer Park	102	RC Airfield	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
Dyer Park	103	RC Airfield	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable.	\$122.50	350	sq ft	\$42,875.00	5
Dyer Park	104	RC Airfield	Picnic Tables (C)	Replace two picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
Dyer Park	105	RC Airfield	Shelters/Picnic Areas (C)	Provide an AR and accessible tables to shelter/picnic area to achieve the required number accessible. Pricing provided in previous findings.	\$0.00	1	N/A	\$0.00	5
Dyer Park	106	RC Airfield	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.	\$59.20	10	lin ft	\$592.00	5
Dyer Park	107	RC Airfield	Picnic Tables (C)	Replace both picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
Dyer Park	108	RC Airfield	Shelters, Picnic Facilities (C)	Relocate garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	5
Dyer Park	109	RC Airfield	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Dyer Park	110	RC Airfield	Park Site (C)	Relocate garbage cans to be along AR. Remount garbage cans for rims to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Dyer Park	111	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Dyer Park	113	Park Elements	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
Dyer Park	115	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
Dyer Park	116	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	117	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain with one provided 17" min and 25" max deep toe clearance. Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	2
Dyer Park	118	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	2
Dyer Park	119	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Dyer Park	121	Park Elements	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth. Correct or repair slope in CFS to max 2.08%.	\$3,062.50	1	each	\$3,062.50	2
Dyer Park	124	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08% in one more bench.	\$1,470.00	1	each	\$1,470.00	5
Dyer Park	125	Park Elements	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$236.25	1	each	\$236.25	1
Dyer Park	126	Park Elements	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$236.25	1	each	\$236.25	1
Dyer Park	127	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
Dyer Park	128	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain with one provided 17" min and 25" max deep toe clearance. Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	2
Dyer Park	129	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. Pricing in a previous finding.	\$0.00	1	each	\$0.00	2
Dyer Park	130	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Dyer Park	131	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
Dyer Park	132	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%. In the alternative, leave as is citing construction tolerance.	\$122.50	25	sq ft	\$3,062.50	4
Dyer Park	133	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	2
Dyer Park	134	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	135	Park Elements	Plumbing Fixtures & Elements	Remount or replace fountain with one provided 17" min and 25" max deep toe clearance. Pricing in a previous finding.	\$0.00	1	each	\$0.00	2
Dyer Park	136	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max, and relocate 20% of garbage cans along an accessible route with max slope of 2.08% in CGS.	\$0.00	1	staff time	\$0.00	2
Dyer Park	138	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Dyer Park	139	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	1	each	\$2,486.00	4
Dyer Park	140	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	5	each	\$481.25	4
Dyer Park	141	Shelters/Picnic Areas	Picnic Tables (C)	Replace three picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	3	each	\$3,360.00	4
Dyer Park	142	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Relocate picnic table to provide a 36" create width route to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Dyer Park	143	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Remount outlets to be in reach range of 15" min to 48" max.  Replace operable part with one usable without a tight pinch or grasp.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$560.00	1	each	\$560.00	4
Dyer Park	144	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Dyer Park	145	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Dyer Park	146	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
Dyer Park	147	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	510	sq ft	\$62,475.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	148	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Dyer Park	149	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	150	2-5 Play Area	Play Area	Create designated entries as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	2	each	\$1,400.00	4
Dyer Park	151	2-5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Dyer Park	152	2-5 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. See previous finding for surface replacement.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Dyer Park	153	2-5 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Dyer Park	154	5-12 Play Area	Play Area	Create designated entry as a smart practice.	\$700.00	2	each	\$1,400.00	5
Dyer Park	155	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Dyer Park	156	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. See previous finding for surface replacement.	\$0.00	1	staff time	\$0.00	2
Dyer Park	157	5-12 Play Area	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	2
Dyer Park	158	5-12 Play Area	Play Area	Lower platform on transfer system to 11" to 18" AFF, in the alternative, add and maintain surface fill level to achieve the same.	\$0.00	1	staff time	\$0.00	2
Dyer Park	159	5-12 Play Area	Play Area	Relocate or add transfer supports on the correct side of the transfer platform.	\$560.00	1	each	\$560.00	2
Dyer Park	160	5-12 Play Area	Play Area	See previous finding for surface recommendations.	\$0.00	1	each	\$0.00	2
Dyer Park	161	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Dyer Park	162	5-12 Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.	\$0.00	1	staff time	\$0.00	2
Dyer Park	163	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	164	Play Area Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	2	each	\$2,940.00	5
Dyer Park	165	Play Area Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Dyer Park	166	Play Area Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Dyer Park	167	Play Area Elements	Clear Floor Space	Enlarge CFS to min 48" depth.	\$1,225.00	1	each	\$1,225.00	2
Dyer Park	168	Play Area Elements	Plumbing Fixtures & Elements	Remount or relocate drinking fountain to provide a forward approach 30" X 48" CFS to the fountain. Pricing in the previous finding.	\$0.00	1	each	\$0.00	2
Dyer Park	169	Play area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	170	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Dyer Park	171	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Dyer Park	172	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Dyer Park	173	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	174	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	175	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	176	Play area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Dyer Park	177	Play area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	178	Play area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	179	Play area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Dyer Park	180	Play area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	183	Trail From Equestrian To Playground	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Dyer Park	184	Trail From Equestrian To Playground	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Dyer Park	185	Trail From Equestrian To Playground	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	550	sq ft	\$67,375.00	5
Dyer Park	186	ORAR To Trails	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	189	Trail Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Dyer Park	190	Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Dyer Park	191	Trail Elements	Reach Ranges	Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over obstruction.	\$0.00	1	staff time	\$0.00	2
Dyer Park	192	Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Dyer Park	193	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	350	sq ft	\$42,875.00	5
Dyer Park	194	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Dyer Park	195	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4500	sq ft	\$551,250.00	5
Dyer Park	196	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Dyer Park	197	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3150	sq ft	\$385,875.00	5
Dyer Park	198	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Dyer Park	199	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	900	sq ft	\$110,250.00	5
Dyer Park	200	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	201	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
Dyer Park	202	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Dyer Park	203	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Dyer Park	204	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Dyer Park	205	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Dyer Park	206	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
Dyer Park	207	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
Dyer Park	208	Outer Loop Of Hill Trails - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	209	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Dyer Park	210	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Dyer Park	211	Outer Loop Of Hill Trails - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	6	each	\$577.50	5
Dyer Park	212	Outer Loop Of Hill Trails - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	213	Outer Loop Of Hill Trails - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	214	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	215	Outer Loop Of Hill Trails - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Dyer Park	216	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
Dyer Park	217	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Dyer Park	218	Outer Loop Of Hill Trails - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Dyer Park	219	Outer Loop Of Hill Trails - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	60	lin ft	\$3,552.00	5
Dyer Park	220	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
Dyer Park	221	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Dyer Park	222	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	2000	sq ft	\$245,000.00	5
Dyer Park	223	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
Dyer Park	224	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Dyer Park	225	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2100	sq ft	\$257,250.00	5
Dyer Park	226	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2250	sq ft	\$275,625.00	5
Dyer Park	227	Trail Surface - Inside Loop And Connection	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Dyer Park	228	Trail Surface - Inside Loop And Connection	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Dyer Park	229	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	190	sq ft	\$23,275.00	5
Dyer Park	230	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1800	sq ft	\$220,500.00	5
Dyer Park	231	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1000	sq ft	\$122,500.00	5
Dyer Park	232	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Dyer Park	233	Trail Surface - Inside Loop And Connection	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
Dyer Park	235	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Dyer Park	236	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	237	Ballfields - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Dyer Park	238	Ballfields - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Dyer Park	239	Ballfields - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Dyer Park	240	Ballfields - Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Dyer Park	241	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Dyer Park	242	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	243	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	244	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Dyer Park	245	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Provide 18" pull side clearance at stall door.	\$2,749.25	1	each	\$2,749.25	1
Dyer Park	246	Ballfields - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Dyer Park	247	Ballfields - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Dyer Park	248	Ballfields - Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Dyer Park	249	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Dyer Park	250	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Dyer Park	251	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Dyer Park	252	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Dyer Park	253	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Dyer Park	254	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.  Relocate or add a urinal in a location that provides 30" X 48" CFS for a forward approach.	\$2,749.25	1	each	\$2,749.25	1
Dyer Park	255	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Dyer Park	256	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	257	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	258	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Dyer Park	259	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Dyer Park	260	Ballfields - Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Dyer Park	261	Ballfields - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Dyer Park	262	Soccer Fields - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
Dyer Park	263	Soccer Fields - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Dyer Park	264	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Dyer Park	265	Soccer Fields - Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Dyer Park	266	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	267	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	268	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Dyer Park	269	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Dyer Park	270	Soccer Fields - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Dyer Park	271	Soccer Fields - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Dyer Park	272	Soccer Fields - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	273	Soccer Fields - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gap to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
Dyer Park	274	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Dyer Park	275	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Dyer Park	276	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Dyer Park	277	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF. In the alternative, leave as is citing construction tolerance.	\$1,704.50	1	each	\$1,704.50	4
Dyer Park	278	Soccer Fields - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Dyer Park	279	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline. In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Dyer Park	280	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	281	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	282	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Dyer Park	283	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Dyer Park	284	Soccer Fields - Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet. In the alternative, leave as is citing construction tolerance.	\$420.00	1	each	\$420.00	4
Dyer Park	285	Soccer Fields - Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Dyer Park	286	Soccer Fields - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Dyer Park	287	Soccer Fields - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	288	Hawk Pavilion - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Dyer Park	289	Hawk Pavilion - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Dyer Park	290	Hawk Pavilion - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Dyer Park	291	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Dyer Park	292	Hawk Pavilion - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Dyer Park	293	Hawk Pavilion - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Dyer Park	294	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Dyer Park	295	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Dyer Park	296	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	297	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	298	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Dyer Park	299	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Dyer Park	300	Hawk Pavilion - Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Dyer Park	301	Hawk Pavilion - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Dyer Park	302	Hawk Pavilion - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Dyer Park	303	Hawk Pavilion - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.  Provide required maneuvering clearance around pull side of door.	\$3,062.50	2	each	\$6,125.00	1
Dyer Park	304	Hawk Pavilion - Women's Restroom	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Dyer Park	305	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	306	Hawk Pavilion - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	sq ft	\$2,380.00	1
Dyer Park	307	Hawk Pavilion - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	each	\$0.00	1
Dyer Park	308	Hawk Pavilion - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Dyer Park	309	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline. In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Dyer Park	310	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	311	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Dyer Park	312	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Remount soap dispenser a min 12" above or 1.5" below grab bar.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Dyer Park	313	Hawk Pavilion - Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Dyer Park	314	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Dyer Park	315	Hawk Pavilion - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Dyer Park	316	Hawk Pavilion - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Dyer Park	317	Hawk Pavilion - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Dyer Park	318	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Dyer Park	319	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
Dyer Park	320	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Dyer Park	321	Employee Spaces	Doors	Repair, bevel or ramp CIL at doorway.	\$96.25	3	each	\$288.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Dyer Park	322	Employee Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$1,720.50	1	each	\$1,720.50	3
Dyer Park	323	Maintenance - Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	3
Dyer Park	324	Maintenance - Restroom	Reach Ranges	Lower paper towels to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	2	staff time	\$0.00	3
Dyer Park	325	Maintenance - Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Dyer Park	326	Maintenance - Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Dyer Park	327	Maintenance - Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	3
<a href="#">Flamango Lake Park</a>	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Flamango Lake Park	2	Park Elements	Custom/Special	If future plans to develop, ensure accessibility standards are included in the design.	\$0.00	1	N/A	\$0.00	4
<a href="#">Fullerton Island</a>	1	Exterior Accessible Route	Accessible Routes	Ensure the accessible route complies with all requirements of width, slopes, changes in level, and gaps.	\$0.00	1	staff time	\$0.00	1
Fullerton Island	2	Boat Docks	Boating Facilities	Provide one accessible boat slip based on the total provided. In the alternative, leave as is and designate other County boating facilities accessible.	\$2,800.00	1	each	\$2,800.00	4
Fullerton Island	3	Boat Docks	Accessible Routes	Ensure compliance of gangway and accessible route including compliant slopes, handrails, transition plates, gaps, and changes in level. In the alternative, leave as is and designate other County boating facilities accessible.	\$0.00	1	staff time	\$0.00	4
Fullerton Island	4	Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	2	each	\$4,972.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Fullerton Island	5	Park Elements	Compliant (C)	Ensure the kiosk sign meets requirements of proximity to an accessible route and level clear ground space.	\$0.00	1	staff time	\$0.00	2
Glades Pioneer Park	1	Fitness Area Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Glades Pioneer Park	2	Fitness Area Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	1	each	\$1,589.00	1
Glades Pioneer Park	3	Fitness Area Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Glades Pioneer Park	4	Fitness Area Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	2	each	\$5,600.00	1
Glades Pioneer Park	5	Fitness Area Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	6	Fitness Area Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Glades Pioneer Park	7	Fitness Area Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	8	Ball Field 1 Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Glades Pioneer Park	9	Ball Field 1 Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Glades Pioneer Park	10	Ball Field 1 Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	12	Aquatic Center and Play Area Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	6	each	\$2,205.00	1
Glades Pioneer Park	13	Aquatic Center and Play Area Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	7	each	\$514.50	1
Glades Pioneer Park	14	Aquatic Center and Play Area Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	5	each	\$367.50	1
Glades Pioneer Park	15	Aquatic Center and Play Area Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	6	each	\$18,375.00	1
Glades Pioneer Park	16	Aquatic Center and Play Area Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Glades Pioneer Park	17	Aquatic Center and Play Area Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Glades Pioneer Park	19	Soccer Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Glades Pioneer Park	20	Soccer Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	21	Soccer Parking	Parking - Off Street	Remove bollard or widen accessible route to min 44" clear width and assure connection to access aisle.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	80	sq ft	\$9,800.00	1
Glades Pioneer Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	80	sq ft	\$9,800.00	1
Glades Pioneer Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	80	sq ft	\$245,000.00	1
Glades Pioneer Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Glades Pioneer Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Glades Pioneer Park	27	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	6	each	\$18,375.00	1
Glades Pioneer Park	28	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	4	each	\$236.80	1
Glades Pioneer Park	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Glades Pioneer Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Glades Pioneer Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Glades Pioneer Park	32	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Glades Pioneer Park	33	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Glades Pioneer Park	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	200	sq ft	\$24,500.00	1
Glades Pioneer Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	120	sq ft	\$14,700.00	1
Glades Pioneer Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Glades Pioneer Park	37	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Glades Pioneer Park	38	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Glades Pioneer Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.					
Glades Pioneer Park	40	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Glades Pioneer Park	41	Exterior Accessible Route	Custom/Special	Remove the detectable warnings that are not located along the vehicular way.	\$296.00	2	each	\$592.00	1
Glades Pioneer Park	42	Pool	Pool / Spa	If pool perimeter is greater than 300 linear feet, ensure compliance of two means of entry to the pool.	\$0.00	1	staff time	\$0.00	2
Glades Pioneer Park	43	Pool	Pool / Spa	Replace pool lift with compliant model and make it available every hour the pool is open	\$8,400.00	1	each	\$8,400.00	3
Glades Pioneer Park	44	Pool	Pool / Spa	Correct pool stair treads to be min 11" deep and riser heights to be uniform if feasible.	\$404.25	4	each	\$1,617.00	3
Glades Pioneer Park	45	Pool	Pool / Spa	Provide two handrails on pool stairs, mounted 20" to 24" apart.	\$980.00	1	each	\$980.00	3
Glades Pioneer Park	46	Pool	Pool / Spa	Maintain an accessible route along the pool deck that is min 36" clear width and having 80" overhead clearance and turning spaces and free of gaps and CIL. Provide a guard rail or barrier at protruding objects.	\$3,062.50	1	each	\$3,062.50	3
Glades Pioneer Park	47	Pool	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$0.00	1	staff time	\$0.00	2
Glades Pioneer Park	48	Pool	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	49	Pool	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Glades Pioneer Park	50	Pool	Doors	Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Glades Pioneer Park	51	Public Spaces	Sales and Service Counters/Tables	Remove storage from clear floor space of service counter.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	52	Public Spaces	Signs	Remount signage to 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$0.00	12	staff time	\$0.00	1
Glades Pioneer Park	53	Men's Locker Room	Doors	Inspect, adjust, and maintain closing speed on door closers	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	54	Men's Locker Room	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	55	Men's Locker Room	Toilet and Bathing Rooms	Confirm compliance of all restroom features when room can be accessed.	\$6,300.00	1	each	\$6,300.00	1
Glades Pioneer Park	56	Women's Locker Room	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	57	Women's Locker Room	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	2	staff time	\$0.00	1
Glades Pioneer Park	58	Women's Locker Room	Reach Ranges	Lower changing table to provide a work surface max 34" AFF.	\$350.00	1	each	\$350.00	1
Glades Pioneer Park	59	Women's Locker Room	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Glades Pioneer Park	60	Women's Locker Room	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Install hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	61	Women's Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	62	Women's Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	63	Women's Locker Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Glades Pioneer Park	64	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	65	Employee Spaces	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" aff.	\$420.00	1	each	\$420.00	3
Glades Pioneer Park	68	Employee Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	3
Glades Pioneer Park	69	Employee Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	3
Glades Pioneer Park	70	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$3,136.00	1	each	\$3,136.00	1
Glades Pioneer Park	71	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	72	Guard Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	73	Guard Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	74	Guard Restroom	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom was constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	75	Guard Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Glades Pioneer Park	76	Guard Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Glades Pioneer Park	77	Guard Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	78	Guard Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Glades Pioneer Park	79	Guard Restroom	Plumbing Fixtures & Elements	Correct transfer shower to compliant 36" by 36" clear inside dimension	\$5,498.50	1	each	\$5,498.50	3
Glades Pioneer Park	80	Guard Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower	\$467.25	1	each	\$467.25	3
Glades Pioneer Park	81	Unisex	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	82	Unisex	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Glades Pioneer Park	83	Unisex	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Glades Pioneer Park	84	Unisex	Toilet and Bathing Rooms	Remount paper towel dispenser to be outside of toilet clearance, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$350.00	1	each	\$350.00	3
Glades Pioneer Park	85	Unisex	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	86	Unisex	Plumbing Fixtures & Elements	Correct transfer shower to compliant 36" by 36" clear inside dimension	\$5,498.50	1	each	\$5,498.50	1
Glades Pioneer Park	87	Unisex	Plumbing Fixtures & Elements	Relocate chair to provide appropriate CFS on the exterior of the transfer shower	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	88	Unisex	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower	\$467.25	1	each	\$467.25	1
Glades Pioneer Park	89	Unisex	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	90	Play Area - Near Splash Pad	Play Area	Correct or fill gaps at playground entry.	\$96.25	4	each	\$385.00	2
Glades Pioneer Park	91	Play Area - Near Splash Pad	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Glades Pioneer Park	92	Play Area - Near Splash Pad	Play Area	Correct or repair slope in clear ground space at transfer system.	\$12.50	12	sq ft	\$150.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	96	Splash Pad	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	4
Glades Pioneer Park	97	Sports Fields/Courts	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$404.25	16	each	\$6,468.00	3
Glades Pioneer Park	98	Sports Fields/Courts	Stairways	SMART PRACTICE  Install contrasting strip along front 2" of each tread  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	16	each	\$2,000.00	5
Glades Pioneer Park	99	Sports Fields/Courts	Stairways	Repair nosings to be curved or beveled at a .5" radius	\$84.00	16	each	\$1,344.00	3
Glades Pioneer Park	100	Sports Fields/Courts	Stairways	Replace or remount handrails to 34" to 38" aff	\$350.00	1	each	\$350.00	2
Glades Pioneer Park	101	Sports Fields/Courts	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Glades Pioneer Park	102	Sports Fields/Courts	Accessible Routes	Relocate storage to provide accessible route and turning space within room.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	103	Sports Fields/Courts	Doors	Provide required maneuvering clearance around pull side of door  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	104	Sports Fields/Courts	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	2
Glades Pioneer Park	105	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	80	lin ft	\$4,736.00	4
Glades Pioneer Park	106	Sports Fields/Courts	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	107	Sports Fields/Courts	Accessible Routes	Create an accessible route to dugouts without requiring players to enter field first and provide min 36" by 48" clear ground space at the end of the benches.	\$2,933.00	2	each	\$5,866.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	109	Sports Fields/Courts	Accessible Routes	Create an accessible route to dugouts without requiring players to enter field first and provide min 36" by 48" clear ground space at the end of the benches.  Widen gates to min 32".  In the alternative, leave as is and designate other County ball fields accessible.	\$2,933.00	2	each	\$5,866.00	4
Glades Pioneer Park	112	Sports Fields/Courts	Accessible Routes	Create an accessible route to dugouts without requiring players to enter field first and provide min 36" by 48" clear ground space at the end of the benches.  Widen gates to min 32".  In the alternative, leave as is and designate other County ball fields accessible.	\$2,933.00	1	each	\$2,933.00	4
Glades Pioneer Park	114	Sports Fields/Courts	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Glades Pioneer Park	116	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	55	lin ft	\$3,256.00	2
Glades Pioneer Park	117	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	85	lin ft	\$5,032.00	4
Glades Pioneer Park	119	Sports Fields/Courts	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	1	staff time	\$0.00	2
Glades Pioneer Park	120	Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	3	each	\$288.75	4
Glades Pioneer Park	121	Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	2	each	\$2,240.00	4
Glades Pioneer Park	122	Pavilion	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$59.20	5	lin ft	\$296.00	4
Glades Pioneer Park	123	Pavilion	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space. In the alternative, leave as is and designate other County shelters accessible.	\$210.00	1	each	\$210.00	4
Glades Pioneer Park	125	Park Elements	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Glades Pioneer Park	128	Park Elements	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	131	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl	\$5,598.25	1	each	\$5,598.25	2
Glades Pioneer Park	132	Shelters	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  Extend route to grills and provide min 48" by 48" clear ground space as a smart practice.	\$2,486.00	6	each	\$14,916.00	5
Glades Pioneer Park	133	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3360	sq ft	\$411,600.00	5
Glades Pioneer Park	134	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Glades Pioneer Park	135	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Glades Pioneer Park	136	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	137	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	138	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	139	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	140	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Glades Pioneer Park	141	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
Glades Pioneer Park	142	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	680	sq ft	\$83,300.00	5
Glades Pioneer Park	143	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$59.20	240	sq ft	\$14,208.00	5
Glades Pioneer Park	144	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Glades Pioneer Park	145	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Glades Pioneer Park	146	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Glades Pioneer Park	147	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	148	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Glades Pioneer Park	149	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Glades Pioneer Park	150	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Glades Pioneer Park	151	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Glades Pioneer Park	152	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	10	each	\$3,290.00	5
Glades Pioneer Park	153	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Glades Pioneer Park	154	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
Glades Pioneer Park	155	Trail Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	2
Glades Pioneer Park	156	Trail Elements	Exercise Equipment	Create CGS at one of each type of exercise equipment	\$161.00	13	each	\$2,093.00	3
Glades Pioneer Park	157	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$59.20	35	lin ft	\$2,072.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	158	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25". Inspect, adjust, and maintain closing speed on door closers.	\$192.50	1	each	\$192.50	3
Glades Pioneer Park	159	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25". Provide an accessible route to building entry.	\$2,353.50	1	each	\$2,353.50	5
Glades Pioneer Park	160	Caretaker's House	Custom/Special	Provide paved parking surface and accessible route to home entry.	\$9,310.00	1	each	\$9,310.00	3
Glades Pioneer Park	161	Press Box Women's Restroom	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	162	Press Box Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	163	Press Box Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Glades Pioneer Park	164	Press Box Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	165	Press Box Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Glades Pioneer Park	166	Press Box Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Glades Pioneer Park	167	Press Box Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Glades Pioneer Park	168	Press Box Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	169	Press Box Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	170	Press Box Women's Restroom	Turning Space	Reconfigure restroom to provide min 60" turning space.	\$8,295.00	1	each	\$8,295.00	1
Glades Pioneer Park	172	Press Box Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	173	Press Box Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Glades Pioneer Park	174	Press Box Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Glades Pioneer Park	175	Press Box Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Glades Pioneer Park	176	Press Box Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	177	Press Box Men's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Glades Pioneer Park	178	Press Box Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	179	Football Women'sxl Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	180	Football Women'sxl Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Glades Pioneer Park	181	Football Women'sxl Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	182	Football Women'sxl Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	183	Football Women'sxl Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Glades Pioneer Park	184	Football Women'sxl Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	185	Football Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Glades Pioneer Park	186	Football Men's Restroom	Doors	For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	187	Football Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	188	Football Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	189	Football Men's Restroom	Toilet and Bathing Rooms	Remount seat covers, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
				Adjust stall door to be self-closing.					
Glades Pioneer Park	190	Football Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	191	Football Men's Restroom	Accessible Routes	Fill and maintain gaps to max .5"	\$96.25	1	each	\$96.25	1
Glades Pioneer Park	192	Football Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
				For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.					
				For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.					
Glades Pioneer Park	193	Football Single User	Doors		\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	194	Football Single User	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	195	Football Single User	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	196	Football Single User	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	197	Football Single User	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Glades Pioneer Park	198	Play Area Women's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	199	Play Area Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Glades Pioneer Park	200	Play Area Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Glades Pioneer Park	201	Play Area Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
				Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.					
Glades Pioneer Park	202	Play Area Women's Restroom	Reach Ranges	Remount changing table to provide work surface max 34".	\$350.00	1	each	\$350.00	1
Glades Pioneer Park	203	Play Area Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
				Adjust stall door to be self-closing.					
Glades Pioneer Park	204	Play Area Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Glades Pioneer Park	205	Play Area Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Glades Pioneer Park	206	Play Area Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Glades Pioneer Park	207	Play Area Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Glades Pioneer Park	208	Play Area Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Glades Pioneer Park	209	Play Area Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	210	Play Area Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Glades Pioneer Park	211	Play Area Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Glades Pioneer Park	212	Play Area Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Glades Pioneer Park	213	Play Area Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Glades Pioneer Park	214	Play Area Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Glades Pioneer Park	215	Play Area Men's Restroom	Toilet and Bathing Rooms	Install toilet paper dispenser that provides continuous flow of paper, mounted to max 7" to 9" from front of toilet and 15" to 48" aff	\$84.00	1	each	\$84.00	1
Glades Pioneer Park	216	Play Area Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Glades Pioneer Park	217	Play Area Men's Restroom	Accessible Routes	Fill and maintain gaps to max .5"	\$250.00	1	each	\$250.00	1
Glades Pioneer Park	218	Play Area Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Golfview Heights Park	1	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Golfview Heights Park	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Golfview Heights Park	3	2 to 5 Playground	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Golfview Heights Park	4	2 to 5 Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
Golfview Heights Park	5	2 to 5 Playground	Accessible Routes	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. See previous finding for cost.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1000	sq ft	\$0.00	4
Golfview Heights Park	9	5 to 12 Playground	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Golfview Heights Park	10	5 to 12 Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. See previous finding for cost.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1000	sq ft	\$0.00	4
Golfview Heights Park	12	5 to 12 Playground	Play Area	Provide an AR to element for one of each type accessible.  In the alternative, add another manipulable ground level play component on the route.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Golfview Heights Park	13	5 to 12 Playground	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Golfview Heights Park	14	5 to 12 Playground	Play Area	Correct swing height to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Golfview Heights Park	15	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Golfview Heights Park	18	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Golfview Heights Park	19	Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" aff.	\$2,380.00	1	each	\$2,380.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Golfview Heights Park	20	Gazebo	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area.  Cost for correction of surface included in earlier finding.  In the alternative, leave as is and designate other County shelters accessible.	\$0.00	10	lin ft	\$0.00	4
Golfview Heights Park	21	Gazebo	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4
<u>Governor Lawton Chiles Memorial Park</u>	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Governor Lawton Chiles Memorial Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Governor Lawton Chiles Memorial Park	4	Parking	Parking - Off Street	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	1	each	\$2,800.00	1
Governor Lawton Chiles Memorial Park	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Governor Lawton Chiles Memorial Park	7	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Governor Lawton Chiles Memorial Park	8	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Governor Lawton Chiles Memorial Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Governor Lawton Chiles Memorial Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Governor Lawton Chiles Memorial Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	210	sq ft	\$643,125.00	1
Governor Lawton Chiles Memorial Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Governor Lawton Chiles Memorial Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
Governor Lawton Chiles Memorial Park	14	Exterior Accessible Route	Detectable Warnings	Replace existing detectable warning with visual contrast and compliant truncated dome template integrated into the walking surface.	\$329.00	1	each	\$329.00	5
Governor Lawton Chiles Memorial Park	15	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Governor Lawton Chiles Memorial Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	330	sq ft	\$40,425.00	1
Governor Lawton Chiles Memorial Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Governor Lawton Chiles Memorial Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Governor Lawton Chiles Memorial Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Governor Lawton Chiles Memorial Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Governor Lawton Chiles Memorial Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	210	sq ft	\$25,725.00	1
Governor Lawton Chiles Memorial Park	22	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Governor Lawton Chiles Memorial Park	23	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Governor Lawton Chiles Memorial Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1
Governor Lawton Chiles Memorial Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Governor Lawton Chiles Memorial Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	720	sq ft	\$88,200.00	1
Governor Lawton Chiles Memorial Park	27	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	5	each	\$1,645.00	5
Governor Lawton Chiles Memorial Park	28	Multipurpose Field	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Governor Lawton Chiles Memorial Park	29	Softball Field	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	215	lin ft	\$12,728.00	4
Governor Lawton Chiles Memorial Park	30	Softball Field	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.  In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
Governor Lawton Chiles Memorial Park	31	Bocce Courts	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	4	each	\$7,000.00	2
Governor Lawton Chiles Memorial Park	32	Horseshoes	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	80	lin ft	\$4,736.00	2
Governor Lawton Chiles Memorial Park	33	Petanque Court	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Governor Lawton Chiles Memorial Park	34	Exercise Course	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	1325	lin ft	\$78,440.00	4
Governor Lawton Chiles Memorial Park	35	Exercise Course	Accessible Routes	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% along the AR where curbs are present. In the alternative, leave as is and designate other County trails accessible.	\$1,487.50	1	each	\$1,487.50	4
Governor Lawton Chiles Memorial Park	37	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Governor Lawton Chiles Memorial Park	38	Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
Governor Lawton Chiles Memorial Park	39	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Governor Lawton Chiles Memorial Park	40	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Governor Lawton Chiles Memorial Park	41	Park Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Governor Lawton Chiles Memorial Park	43	Park Elements	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Governor Lawton Chiles Memorial Park	44	Park Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice and place on a firm and stable surface with 36" route around all sides. In the alternative, leave as is and designate other County picnic areas accessible.	\$1,120.00	1	each	\$1,120.00	4
Governor Lawton Chiles Memorial Park	45	Park Elements	Park Site (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Governor Lawton Chiles Memorial Park	46	Pavilion	Picnic Tables (C)	Replace 4 picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	4	each	\$4,480.00	4
Governor Lawton Chiles Memorial Park	47	Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	3	each	\$288.75	4
Governor Lawton Chiles Memorial Park	48	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Governor Lawton Chiles Memorial Park	49	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Governor Lawton Chiles Memorial Park	50	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	51	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Governor Lawton Chiles Memorial Park	52	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Governor Lawton Chiles Memorial Park	53	Men's Restroom	Toilet and Bathing Rooms	Replace or remount grab bars with a max 1.5" spacing between wall and bar.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$196.75	2	each	\$393.50	1
Governor Lawton Chiles Memorial Park	54	Men's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width or reverse door swing if stall has required additional depth.	\$2,749.25	1	each	\$2,749.25	1
Governor Lawton Chiles Memorial Park	55	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Governor Lawton Chiles Memorial Park	56	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Governor Lawton Chiles Memorial Park	57	Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	58	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Governor Lawton Chiles Memorial Park	59	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Governor Lawton Chiles Memorial Park	60	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Governor Lawton Chiles Memorial Park	61	Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$3,158.75	1	each	\$3,158.75	3
Governor Lawton Chiles Memorial Park	62	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,158.75	1	each	\$3,158.75	1
Governor Lawton Chiles Memorial Park	63	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	64	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	65	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Governor Lawton Chiles Memorial Park	66	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	67	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF). In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Governor Lawton Chiles Memorial Park	68	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Governor Lawton Chiles Memorial Park	69	Women's Restroom	Toilet and Bathing Rooms	Replace or remount grab bars with a max 1.5" spacing between wall and bar.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$196.75	2	each	\$393.50	1
Governor Lawton Chiles Memorial Park	70	Women's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width or reverse door swing if stall has required additional depth.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Governor Lawton Chiles Memorial Park	71	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Governor Lawton Chiles Memorial Park	72	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	73	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Governor Lawton Chiles Memorial Park	74	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Governor Lawton Chiles Memorial Park	75	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Governor Lawton Chiles Memorial Park	76	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Gramercy Park	2	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Gramercy Park	5	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Gramercy Park	6	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,890.00	1	each	\$1,890.00	1
Gramercy Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Gramercy Park	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Gramercy Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Gramercy Park	10	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Gramercy Park	11	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Gramercy Park	12	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Gramercy Park	13	Park Element	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Gramercy Park	14	Park Element	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Gramercy Park	18	Play Area (2-5)	Play Area	Create designated entry as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gramercy Park	19	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Gramercy Park	20	Play Area (2-5)	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Gramercy Park	22	Play Area (5-12)	Play Area	Create designated entry as a smart practice.  Pricing included in 2-5 Play Area checklist.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Gramercy Park	23	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Price included in finding for 2-5 area.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Gramercy Park	25	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Frequently maintain trail surface in identified washout areas to assure CIL's remain 2" or less and gaps are filled as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Green Cay Nature Center and Wetlands	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	6	each	\$441.00	1
Green Cay Nature Center and Wetlands	3	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Green Cay Nature Center and Wetlands	4	Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.	\$96.25	2	each	\$192.50	1
Green Cay Nature Center and Wetlands	5	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	8	each	\$2,632.00	5
Green Cay Nature Center and Wetlands	6	Exterior Accessible Route	Accessible Routes	Repair and reset pavers to eliminate CIL and gaps	\$28.00	700	sq ft	\$19,600.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Green Cay Nature Center and Wetlands	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Green Cay Nature Center and Wetlands	9	Exterior Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Green Cay Nature Center and Wetlands	12	Exterior Elements	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	150	sq ft	\$18,375.00	1
Green Cay Nature Center and Wetlands	13	Tropical Hammock Trail Loop - Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$59.20	25	sq ft	\$1,480.00	5
Green Cay Nature Center and Wetlands	14	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Green Cay Nature Center and Wetlands	15	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	7	each	\$673.75	5
Green Cay Nature Center and Wetlands	16	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	11	each	\$1,058.75	5
Green Cay Nature Center and Wetlands	17	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	6	each	\$577.50	5
Green Cay Nature Center and Wetlands	18	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	15	each	\$1,443.75	5
Green Cay Nature Center and Wetlands	19	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	13	each	\$1,251.25	5
Green Cay Nature Center and Wetlands	20	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	15	each	\$1,443.75	5
Green Cay Nature Center and Wetlands	21	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
Green Cay Nature Center and Wetlands	22	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Green Cay Nature Center and Wetlands	23	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Green Cay Nature Center and Wetlands	24	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Green Cay Nature Center and Wetlands	25	Tropical Hammock Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	18	each	\$1,732.50	5
Green Cay Nature Center and Wetlands	26	Tropical Hammock Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground	\$980.00	18	each	\$17,640.00	3
Green Cay Nature Center and Wetlands	27	Tropical Hammock Trail Loop - Surface	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Green Cay Nature Center and Wetlands	28	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground	\$980.00	4	each	\$3,920.00	3
Green Cay Nature Center and Wetlands	29	Chickee Hut Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	30	each	\$2,887.50	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	30	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	4	each	\$3,920.00	3
Green Cay Nature Center and Wetlands	31	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface. Pricing in a previous finding.	\$0.00	1	N/A	\$0.00	3
Green Cay Nature Center and Wetlands	32	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	2	each	\$1,960.00	3
Green Cay Nature Center and Wetlands	33	Chickee Hut Trail Loop - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Green Cay Nature Center and Wetlands	34	Chickee Hut Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	20	each	\$1,925.00	5
Green Cay Nature Center and Wetlands	35	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	2	each	\$1,960.00	3
Green Cay Nature Center and Wetlands	36	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	2	each	\$1,960.00	3
Green Cay Nature Center and Wetlands	37	Chickee Hut Trail Loop - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Green Cay Nature Center and Wetlands	38	Chickee Hut Trail Loop - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Green Cay Nature Center and Wetlands	39	Chickee Hut Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	30	each	\$2,887.50	5
Green Cay Nature Center and Wetlands	40	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	2	each	\$1,960.00	5
Green Cay Nature Center and Wetlands	41	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	2	each	\$1,960.00	3
Green Cay Nature Center and Wetlands	42	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	4	each	\$3,920.00	3
Green Cay Nature Center and Wetlands	43	Chickee Hut Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	30	each	\$2,887.50	5
Green Cay Nature Center and Wetlands	44	Chickee Hut Trail Loop - Surface	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground.	\$980.00	4	each	\$3,920.00	3
Green Cay Nature Center and Wetlands	45	Chickee Hut Trail Loop - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	15	each	\$1,443.75	5
Green Cay Nature Center and Wetlands	46	Boardwalk Trail Loops - Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Green Cay Nature Center and Wetlands	51	Boardwalk Trail Loops - Elements	Signs	Remount signage to min 40" AFF.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	52	Boardwalk Trail Loops - Elements	Protruding Object	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	2
Green Cay Nature Center and Wetlands	53	Boardwalk Trail Loops - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp; leave as is if needed to keep animals out.	\$0.00	1	N/A	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	54	Boardwalk Trail Loops - Elements	Clear Floor Space	Remove bench from clear ground space of sign, or relocate sign to provide 30" by 48" clear ground space adjacent.	\$0.00	1	staff time	\$0.00	5
Green Cay Nature Center and Wetlands	55	Boardwalk Trail Loops - Elements	Clear Floor Space	Remove bench from clear ground space of sign, or relocate sign to provide 30" by 48" clear ground space adjacent.	\$0.00	1	staff time	\$0.00	5
Green Cay Nature Center and Wetlands	56	Men's Restroom - Nature Center	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	57	Men's Restroom - Nature Center	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Green Cay Nature Center and Wetlands	58	Men's Restroom - Nature Center	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	59	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Replace mirror mounts for both mirrors to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Green Cay Nature Center and Wetlands	60	Men's Restroom - Nature Center	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Green Cay Nature Center and Wetlands	61	Men's Restroom - Nature Center	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	62	Men's Restroom - Nature Center	Reach Ranges	Lower toilet seat cover dispenser to max 44" above the finished floor (AFF) for a forward reach over toilet.  Lower baby changing table so work surface is min 28" and max 34" AFF.	\$175.00	2	each	\$350.00	1
Green Cay Nature Center and Wetlands	63	Men's Restroom - Nature Center	Operable Parts	Replace baby changing table latch with one usable without a tight pinch or grasp, and usable with one hand.	\$210.00	1	each	\$210.00	1
Green Cay Nature Center and Wetlands	64	Men's Restroom - Nature Center	Clear Floor Space	Relocate toilet seat cover dispenser to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	65	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Green Cay Nature Center and Wetlands	66	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	67	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Remount rear grab bar in accessible stall to 33" to 36" above the finished floor (AFF), providing 1.5" clearance below the bar. Pricing in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	68	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Green Cay Nature Center and Wetlands	69	Men's Restroom - Nature Center	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	70	Men's Restroom - Nature Center	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Green Cay Nature Center and Wetlands	71	Men's Restroom - Nature Center	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Green Cay Nature Center and Wetlands	72	Women's Restroom - Nature Center	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	73	Women's Restroom - Nature Center	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	74	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Green Cay Nature Center and Wetlands	75	Women's Restroom - Nature Center	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Green Cay Nature Center and Wetlands	76	Women's Restroom - Nature Center	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	77	Women's Restroom - Nature Center	Reach Ranges	Lower seat cover dispenser to max 44" above the finished floor (AFF) for a forward reach over toilet.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	78	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Green Cay Nature Center and Wetlands	79	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	80	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	81	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	82	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	83	Women's Restroom - Nature Center	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	84	Women's Restroom - Nature Center	Hazards	Repair or replace baby changing table; in the alternative, relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Green Cay Nature Center and Wetlands	85	Women's Restroom - Nature Center	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Green Cay Nature Center and Wetlands	86	Unisex Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	87	Unisex Restroom	Toilet and Bathing Rooms	Leave as is and remount sign in future if drinking fountain is relocated.	\$0.00	1	N/A	\$0.00	4
Green Cay Nature Center and Wetlands	88	Unisex Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Green Cay Nature Center and Wetlands	89	Unisex Restroom	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.	\$2,380.00	1	each	\$2,380.00	1
Green Cay Nature Center and Wetlands	90	Unisex Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	91	Unisex Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	92	Unisex Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	93	Unisex Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount toilet seat cover dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	94	Unisex Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	95	Staff Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	96	Staff Restroom	Toilet and Bathing Rooms	Acquire and mount signage identifying the space as a restroom, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Green Cay Nature Center and Wetlands	97	Staff Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	98	Staff Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Green Cay Nature Center and Wetlands	99	Staff Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing in previous findings.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	3	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	100	Staff Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	101	Staff Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Green Cay Nature Center and Wetlands	102	Lecture Hall	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	4	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	103	Lecture Hall	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	104	Lecture Hall	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Green Cay Nature Center and Wetlands	105	Lecture Hall	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	106	Lecture Hall	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	107	Lecture Hall	Turning Space	Relocate obstacles to create turning space in storage rooms.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	108	Lecture Hall	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	109	Lecture Hall	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	4	each	\$560.00	1
Green Cay Nature Center and Wetlands	110	Gift Shop	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Green Cay Nature Center and Wetlands	112	Gift Shop	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	113	Gift Shop	Turning Space	Relocate obstacles to create turning space in storage room.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	114	Exhibit Areas	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	3	each	\$630.00	1
Green Cay Nature Center and Wetlands	115	Exhibit Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	116	Exhibit Areas	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	117	Exhibit Areas	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$140.00	4	each	\$560.00	1
Green Cay Nature Center and Wetlands	118	Exhibit Areas	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$210.00	4	each	\$840.00	1
Green Cay Nature Center and Wetlands	119	Exhibit Areas	Doors	Mount signage at entrance designating it as accessible.	\$210.00	3	each	\$630.00	1
Green Cay Nature Center and Wetlands	120	Exhibit Areas	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	5	each	\$1,050.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	121	Exhibit Areas	Signs	Remount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	24	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	122	Exhibit Areas	Signs	Remount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	9	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	123	Employee Spaces	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width to cabinets/counter.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	124	Employee Spaces	Accessible Routes	Relocate or raise bird feeders to min 80" to prevent hazard in overhead clearance along AR.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	125	Employee Spaces	Accessible Routes	Replace grate with one having max openings of 1/2 inch.	\$140.00	1	each	\$140.00	3
Green Cay Nature Center and Wetlands	126	Employee Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Green Cay Nature Center and Wetlands	127	Employee Spaces	Plumbing Fixtures & Elements	Relocate items to provide CFS at sink. Adjust timing of sink faucets to remain on for min 10 seconds.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	128	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$1,750.00	1	each	\$1,750.00	3
Green Cay Nature Center and Wetlands	129	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$1,750.00	1	each	\$1,750.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	131	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$1,750.00	1	each	\$1,750.00	3
Green Cay Nature Center and Wetlands	132	Employee Spaces	Turning Space	Relocate obstacles to create turning space in 111.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	133	Employee Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	134	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Green Cay Nature Center and Wetlands	135	Employee Spaces	Accessible Routes	Relocate stanchions to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	136	Employee Spaces	Protruding Object	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
Green Cay Nature Center and Wetlands	138	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	139	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$420.00	1	each	\$420.00	1
Green Cay Nature Center and Wetlands	140	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$420.00	1	each	\$420.00	1
Green Cay Nature Center and Wetlands	142	Public Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Green Cay Nature Center and Wetlands	143	Public Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	144	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	145	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	1
Green Cay Nature Center and Wetlands	146	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	1
Green Cay Nature Center and Wetlands	147	Public Spaces	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	148	Public Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Green Cay Nature Center and Wetlands	149	Public Spaces	Accessible Routes	Relocate bird cage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	150	Public Spaces	Turning Space	Relocate obstacles to create turning space behind counter of interpretive area.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	151	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Green Cay Nature Center and Wetlands	152	Laboratory	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	153	Laboratory	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$514.50	1	each	\$514.50	1
Green Cay Nature Center and Wetlands	154	Laboratory	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Green Cay Nature Center and Wetlands	155	Laboratory	Turning Space	Relocate obstacles to create turning space in Lab.	\$0.00	1	staff time	\$0.00	1
Gulfstream Park	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Gulfstream Park	3	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Gulfstream Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	7	each	\$21,437.50	1
Gulfstream Park	5	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	1	each	\$96.25	1
Gulfstream Park	6	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	7	Exterior Accessible Route	Beach Access Route (C)	Correct or repair running slopes along the BAR to max 5% for any distance, 8.33% for 50' max or 10% for 30' max as a smart practice	\$122.50	55	lin ft	\$6,737.50	5
Gulfstream Park	8	Exterior Accessible Route	Beach Access Route (C)	Correct or fill opening along the BAR to be max .5" and travel perpendicular to path of travel as a smart practice	\$96.25	4	each	\$385.00	5
Gulfstream Park	9	Exterior Accessible Route	Beach Access Route (C)	Create a beach access route of a firm and stable material as a smart practice.	\$6,510.00	1	each	\$6,510.00	5
Gulfstream Park	10	Exterior Accessible Route	Stairways	Install kick plates on all stairs or replace with ones having closed risers.	\$84.00	14	each	\$1,176.00	5
Gulfstream Park	11	Exterior Accessible Route	Stairways	Provide maintenance to keep stair treads clear of sand and assure surface is firm stable and slip resistant.	\$0.00	1	staff time	\$0.00	5
Gulfstream Park	12	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread as smart practice.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	16	each	\$2,000.00	5
Gulfstream Park	13	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	5
Gulfstream Park	14	Exterior Accessible Route	Stairways	Replace handrails with ones have a smooth surface. Cost in previous finding.	\$0.00	1	staff time	\$0.00	5
Gulfstream Park	15	Exterior Accessible Route	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Gulfstream Park	16	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Gulfstream Park	17	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Gulfstream Park	18	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	5
Gulfstream Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Gulfstream Park	20	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Gulfstream Park	21	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	22	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Gulfstream Park	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Gulfstream Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Gulfstream Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Gulfstream Park	26	Exterior Accessible Route	Stairways	Install kick plates on all stairs or replace with ones having closed risers.	\$84.00	7	each	\$588.00	5
Gulfstream Park	27	Exterior Accessible Route	Stairways	Provide maintenance to remove sand from treads and landing and assure surface is firm stable and slip resistant.	\$0.00	1	staff time	\$0.00	5
Gulfstream Park	28	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread as a smart practice.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	8	each	\$1,000.00	5
Gulfstream Park	29	Exterior Accessible Route	Stairways	Replace tread with one having openings max .5".	\$96.25	6	each	\$577.50	5
Gulfstream Park	30	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	5
Gulfstream Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	5	each	\$15,312.50	1
Gulfstream Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Gulfstream Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Gulfstream Park	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	10	each	\$30,625.00	1
Gulfstream Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	3	each	\$9,187.50	1
Gulfstream Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	12	each	\$36,750.00	1
Gulfstream Park	37	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%	\$875.00	1	each	\$875.00	1
Gulfstream Park	38	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Gulfstream Park	39	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Gulfstream Park	40	Park Elements	Beach Access Route (C)	Create at least one beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	180	lin ft	\$10,656.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	41	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material to the base of the lifeguard tower. Leave vertical access as is - exempt.	\$59.20	15	lin ft	\$888.00	3
Gulfstream Park	42	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Gulfstream Park	43	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Gulfstream Park	44	Park Elements	Drinking Fountains	Provide 30" by 48" deep CFS for a forward approach to fountain; centered on unit.	\$2,380.00	1	staff time	\$2,380.00	2
Gulfstream Park	45	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	2
Gulfstream Park	46	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Gulfstream Park	47	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Gulfstream Park	48	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from walkway to element. Repair, bevel, or ramp CIL to shower.	\$688.25	1	each	\$688.25	5
Gulfstream Park	52	Park Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%. Relocate 20% of garbage bins to be along the AR. Remount garbage bins to between 15" and 48" agl.	\$1,470.00	1	each	\$1,470.00	2
Gulfstream Park	53	Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Gulfstream Park	54	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Gulfstream Park	55	Picnic Areas	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
Gulfstream Park	56	Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of at least three tables as a smart practice.	\$2,486.00	3	each	\$7,458.00	5
Gulfstream Park	57	Picnic Areas	Shelters/Picnic Areas (C)	Extend a firm and stable route from shelter to amenities. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4
Gulfstream Park	58	Play Area, 5-12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	59	Play Area, 5-12	Play Area	Repair, bevel or ramp CIL at playground entry/border. See previous finding for cost. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Gulfstream Park	60	Play Area, 5-12	Play Area	Correct transfer step riser height to 8" max and uniform. Leave as is if technically infeasible.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Gulfstream Park	61	Play Area, 5-12	Play Area	Correct transfer step riser height to 8" max and uniform. Leave as is if technically infeasible.  Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Gulfstream Park	62	Play Area, 5-12	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Gulfstream Park	63	Play Area, 5-12	Play Area	Lower or adjust entry point to play component to 11" to 24" AGL. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Gulfstream Park	64	Play Area, 5-12	Play Area	Relocate one climbing component to an area providing 80" overhead clearance and 60" turning space, if feasible. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Gulfstream Park	65	Play Area, 5-12	Play Area	Add 2 more GLPCs of 1 type or make corrections to GLPCs to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Gulfstream Park	66	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Gulfstream Park	67	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Gulfstream Park	68	Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Gulfstream Park	69	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Gulfstream Park	70	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Gulfstream Park	71	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	72	Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth	\$2,749.25	1	each	\$2,749.25	1
Gulfstream Park	73	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Gulfstream Park	74	Men's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Gulfstream Park	75	Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Gulfstream Park	76	Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Gulfstream Park	77	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door and adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	1
Gulfstream Park	78	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Gulfstream Park	79	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Gulfstream Park	80	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Gulfstream Park	81	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Gulfstream Park	82	Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Gulfstream Park	83	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Gulfstream Park	84	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Gulfstream Park	85	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
Gulfstream Park	86	Women's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth	\$2,749.25	1	each	\$2,749.25	1
Gulfstream Park	87	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Gulfstream Park	88	Women's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Gulfstream Park	89	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Gulfstream Park	90	Women's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$2,749.25	1	each	\$2,749.25	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	91	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Gulfstream Park	92	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Gulfstream Park	93	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Gulfstream Park	94	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, remount hardware to be 34" to 48" aff.	\$416.25	1	each	\$416.25	1
Gulfstream Park	95	Exterior of Ocean Rescue Office	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	3
Gulfstream Park	96	Exterior of Ocean Rescue Office	Accessible Routes	Repair, bevel or ramp change in level along accessible route. In the alternative, mount signage directing to the accessible route.	\$6,510.00	9	each	\$58,590.00	3
Gulfstream Park	97	Exterior of Ocean Rescue Office	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$610.25	1	each	\$610.25	3
Gulfstream Park	98	Ocean Rescue Office - Employee Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	3
Gulfstream Park	99	Ocean Rescue Office - Employee Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	3
Gulfstream Park	100	Ocean Rescue Office - Employee Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised lettering on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	101	Ocean Rescue Office - Employee Restroom	Plumbing Fixtures & Elements	Create accessible shower in employee restroom.	\$6,300.00	1	each	\$6,300.00	3
Gulfstream Park	102	Ocean Rescue Office - Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$3,287.00	1	each	\$3,287.00	3
Gulfstream Park	103	Ocean Rescue Office - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Provide kick plate on push side of door from floor to 10" AFF.</p>	\$664.50	1	each	\$664.50	3
Gulfstream Park	104	Ocean Rescue Office - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$3,801.50	1	each	\$3,801.50	3
Gulfstream Park	105	Ocean Rescue Office - Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Gulfstream Park	106	Ocean Rescue Office - Employee Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25". In the alternative, leave stairs as is and mount signage to nearest accessible exit.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$7,024.50	1	each	\$7,024.50	3
Gulfstream Park	107	Ocean Rescue Office - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,327.00	1	each	\$5,327.00	3
Gulfstream Park	108	Caretaker House	Accessible Routes	For changes in level 6" or greater, provide a ramp for access.	\$6,510.00	1	each	\$6,510.00	3
Haverhill Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Haverhill Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Haverhill Park	4	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Haverhill Park	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Haverhill Park	6	Parking	Parking - Off Street	Widen accessible route to min 44" clear width and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
Haverhill Park	7	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".  Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$96.25	1	each	\$96.25	1
Haverhill Park	8	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Haverhill Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Haverhill Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Haverhill Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Haverhill Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Haverhill Park	13	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Haverhill Park	15	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	50	lin ft	\$2,960.00	2
Haverhill Park	18	Sports Fields/Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	2
Haverhill Park	20	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Haverhill Park	21	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Haverhill Park	23	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	2
Haverhill Park	24	Park Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	2	each	\$4,972.00	5
Haverhill Park	25	Park Elements	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	45	lin ft	\$2,664.00	5
Haverhill Park	26	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2
Haverhill Park	27	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Haverhill Park	28	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Haverhill Park	29	Shelters	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	20	each	\$7,000.00	3
Haverhill Park	30	Shelters	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice. Replace spout hardware with one that is operable without a tight pinch or grasp.	\$280.00	2	each	\$560.00	5
Haverhill Park	31	Shelters	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space. Replace or lower one grill to max height of cooking surface 34". Adjust one grill lid to be usable with 5 lbf or less. Replace handles for one grill with ones usable without a tight pinch or grasp. Remount garbage can rim to be in reach range of 15" min to 48" max.	\$230.00	2	each	\$460.00	5
Haverhill Park	32	Play Area 2-5	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.	\$350.00	1	each	\$350.00	5
Haverhill Park	33	Play Area 2-5	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. Price included in finding for 5-12 play area.	\$0.00	1	each	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Haverhill Park	34	Play Area 2-5	Play Area	Lower platform on transfer system to 11" to 18" AFF, in the alternative, add and maintain surface fill level to achieve the same.	\$70.00	100	sq ft	\$7,000.00	2
Haverhill Park	35	Play Area 2-5	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Haverhill Park	36	Play Area 2-5	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Haverhill Park	37	Play Area 2-5	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	4
Haverhill Park	38	Play Area 5-12	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Haverhill Park	39	Play Area 5-12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Haverhill Park	40	Play Area 5-12	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Haverhill Park	41	Play Area 5-12	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Haverhill Park	42	Play Area 5-12	Play Area	Add one more GLPC of type other than a climber or swing to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Haverhill Park	43	Play Area 5-12	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Haverhill Park	44	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	5280	lin ft	\$312,576.00	4
Haverhill Park	45	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	2
Haverhill Park	46	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	2
Haverhill Park	47	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
Haverhill Park	48	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Haverhill Park	49	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Haverhill Park	50	Trail Elements	Outdoor - Trails (C)	Replace surface of trail and clear ground spaces with one that is firm and stable as a smart practice.  Price included in earlier finding.  In the alternative, leave as is and designate other County fitness amenities accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Haverhill Park	51	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Haverhill Park	52	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in accessible stall.	\$77.00	2	each	\$154.00	1
Haverhill Park	53	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Haverhill Park	54	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Haverhill Park	55	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Haverhill Park	56	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Haverhill Park	57	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Haverhill Park	58	Men's Restroom	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Haverhill Park	59	Women's Restroom	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Haverhill Park	60	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Haverhill Park	61	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Haverhill Park	62	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Haverhill Park	63	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Haverhill Park	64	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Haverhill Park	65	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
Haverhill Park	66	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Ixora Park	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ixora Park	2	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Ixora Park	3	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ixora Park	4	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Ixora Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ixora Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ixora Park	7	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
Ixora Park	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ixora Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ixora Park	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ixora Park	13	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Ixora Park	14	Play Area	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
Ixora Park	15	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Ixora Park	16	Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Ixora Park	18	Play Area	Play Area	Provide an AR to element for one of each type accessible.  In the alternative, add another ground level play component on the route.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Ixora Park	19	Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Ixora Park	20	Play Area	Play Area	Add 1 more GLPCs of any other type to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Jim Barry Light Harbor Park	2	Parking - Standard Sized	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Jim Barry Light Harbor Park	3	Parking - Standard Sized	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Jim Barry Light Harbor Park	4	Parking - Standard Sized	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Jim Barry Light Harbor Park	5	Parking - Oversized/Trailer	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jim Barry Light Harbor Park	6	Parking - Oversized/Trailer	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Jim Barry Light Harbor Park	7	Parking - Oversized/Trailer	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Jim Barry Light Harbor Park	8	Parking - Oversized/Trailer	Parking - Off Street	Correct or fill gaps to .5" max.	\$96.25	1	each	\$96.25	1
Jim Barry Light Harbor Park	9	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Jim Barry Light Harbor Park	10	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3
Jim Barry Light Harbor Park	11	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
Jim Barry Light Harbor Park	12	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Jim Barry Light Harbor Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	4	each	\$12,250.00	1
Jim Barry Light Harbor Park	14	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	1
Jim Barry Light Harbor Park	15	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Jim Barry Light Harbor Park	16	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Jim Barry Light Harbor Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jim Barry Light Harbor Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jim Barry Light Harbor Park	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Jim Barry Light Harbor Park	20	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Jim Barry Light Harbor Park	21	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	1	each	\$980.00	3
Jim Barry Light Harbor Park	22	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Jim Barry Light Harbor Park	23	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
Jim Barry Light Harbor Park	24	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Jim Barry Light Harbor Park	25	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Jim Barry Light Harbor Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	220	sq ft	\$26,950.00	1
Jim Barry Light Harbor Park	28	Boating	Accessible Routes	Correct running slopes of transition plates to max 5% if feasible.	\$6,221.25	1	each	\$6,221.25	2
Jim Barry Light Harbor Park	29	Fishing	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	62	each	\$60,760.00	4
Jim Barry Light Harbor Park	30	Park Elements	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over obstruction.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jim Barry Light Harbor Park	31	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	20	lin ft	\$1,184.00	2
Jim Barry Light Harbor Park	32	Park Elements	ATM's and Fare Machines	Contact provider to replace parking pay kiosk with a compliant model.	\$5,000.00	1	each	\$5,000.00	2
Jim Barry Light Harbor Park	33	Park Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Jim Barry Light Harbor Park	34	Park Elements	ATM's and Fare Machines	Replace parking pay kiosk with one that has compliant features. Pricing in a previous finding.	\$0.00	1	each	\$0.00	2
Jim Barry Light Harbor Park	35	Park Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Jim Barry Light Harbor Park	36	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
Jim Barry Light Harbor Park	37	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jim Barry Light Harbor Park	39	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	40	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jim Barry Light Harbor Park	41	Women's Restroom	Custom/Special	Repair or replace faucet in accessible toilet compartment.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	42	Women's Restroom	Plumbing Fixtures & Elements	Repair damaged faucet or replace with compliant faucet. Adjust timing of sink faucets to remain on for min. 10 seconds.	\$735.00	1	each	\$735.00	1
Jim Barry Light Harbor Park	43	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in stall.	\$77.00	1	each	\$77.00	1
Jim Barry Light Harbor Park	44	Women's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	45	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Jim Barry Light Harbor Park	46	Women's Restroom	Toilet and Bathing Rooms	Relocate partition or rehang door to provide min 18" on the pull side of the stall door. Relocate hand dryer to provide maneuvering clearance at stall door.	\$3,099.25	1	each	\$3,099.25	1
Jim Barry Light Harbor Park	47	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jim Barry Light Harbor Park	48	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item. Pricing in a previous finding.	\$0.00	1	each	\$0.00	1
Jim Barry Light Harbor Park	49	Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	50	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jim Barry Light Harbor Park	51	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	52	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in stall.	\$77.00	1	each	\$77.00	1
Jim Barry Light Harbor Park	53	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	54	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Jim Barry Light Harbor Park	55	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Jim Barry Light Harbor Park	56	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jim Barry Light Harbor Park	57	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Jim Barry Light Harbor Park	58	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jim Barry Light Harbor Park	59	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
John Prince Park	2	Sport Courts/Fields - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
John Prince Park	3	Sport Courts/Fields - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	4	Sport Courts/Fields - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	5	Sport Courts/Fields - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	6	Sport Courts/Fields - Parking	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
John Prince Park	7	Sport Courts/Fields - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	8	Sport Courts/Fields - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
John Prince Park	10	Sport Courts/Fields - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	11	Sport Courts/Fields - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	12	Sport Courts/Fields - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	13	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	14	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	15	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Replace drain grate with one having max gaps of .5".	\$5,000.00	1	each	\$5,000.00	1
John Prince Park	16	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	18	each	\$55,125.00	1
John Prince Park	17	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	11	each	\$33,687.50	1
John Prince Park	18	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	19	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	20	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	21	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	22	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	8	each	\$24,500.00	1
John Prince Park	23	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	9	each	\$27,562.50	1
John Prince Park	24	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
John Prince Park	25	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	26	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Provide maintenance to keep sand off sidewalk at sand volleyball courts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	27	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Provide maintenance to keep mud off sidewalks at parking by basketball court.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	28	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	29	Sport Courts/Fields - Exterior Accessible Route	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	25	sq ft	\$3,062.50	1
John Prince Park	30	Sport Courts/Fields - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	31	Sport Courts/Fields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	32	Pickleball Courts	Doors	For all gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$3,062.50	1	each	\$3,062.50	2
John Prince Park	33	Pickleball Courts	Doors	For all gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	34	Pickleball Courts	Doors	For all gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$0.00	2	staff time	\$0.00	2
John Prince Park	35	Pickleball Courts	Doors	For all gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$0.00	1	staff time	\$0.00	2
John Prince Park	36	Pickleball Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
John Prince Park	39	Tennis Courts	Doors	For all gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$3,062.50	1	each	\$3,062.50	2
John Prince Park	40	Volleyball Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	15	each	\$888.00	4
John Prince Park	42	Volleyball Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
John Prince Park	44	Cricket Field	Park Site (C)	Provide an outdoor recreation accessible route (ORAR) to 20% of benches.	\$59.20	10	lin ft	\$592.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	46	Sport Courts/Fields - Building 17 - Women's Restroom	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	47	Sport Courts/Fields - Building 17 - Women's Restroom	Clear Floor Space	Correct or repair slope in CGS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	1
John Prince Park	48	Sport Courts/Fields - Building 17 - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	49	Sport Courts/Fields - Building 17 - Women's Restroom	Doors	For all doors along the public circulation route, remount hardware to 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
John Prince Park	50	Sport Courts/Fields - Building 17 - Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	51	Sport Courts/Fields - Building 17 - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
John Prince Park	52	Sport Courts/Fields - Building 17 - Women's Restroom	Plumbing Fixtures & Elements	Lower one sink in main area to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	53	Sport Courts/Fields - Building 17 - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	54	Sport Courts/Fields - Building 17 - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
John Prince Park	55	Sport Courts/Fields - Building 17 - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	56	Sport Courts/Fields - Building 17 - Women's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width. Adjust stall door to be self-closing.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	57	Sport Courts/Fields - Building 17 - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	58	Sport Courts/Fields - Building 17 - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	59	Sport Courts/Fields - Building 17 - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
John Prince Park	60	Sport Courts/Fields - Building 17 - Men's Restroom	Plumbing Fixtures & Elements	Lower one sink in main area to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	61	Sport Courts/Fields - Building 17 - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	62	Sport Courts/Fields - Building 17 - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
John Prince Park	63	Sport Courts/Fields - Building 17 - Men's Restroom	Toilet and Bathing Rooms	Review the accessible stall for accessibility compliance and make corrections using the women's restroom recommendations as a guide.	\$4,500.00	1	each	\$4,500.00	1
John Prince Park	64	Sport Courts/Fields - Building 17 - Men's Restroom	Custom/Special	Upon completion of stall, assure that restroom meets standards.	\$0.00	1	each	\$0.00	1
John Prince Park	65	Soccer 5 Area	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	66	Soccer 5 Area	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	69	Soccer 5 Area	Doors	For all doors along the public circulation route, remount hardware to 34" to 48" AFF.	\$0.00	1	staff time	\$0.00	1
John Prince Park	70	Soccer 5 Area	Picnic Tables (C)	Replace 20% of picnic tables with ones of an accessible design as a smart practice and disperse them between covered and open areas. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	4	each	\$4,480.00	4
John Prince Park	71	Soccer 5 Area	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. and locate closer to the walkway.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	72	Soccer 5 Area	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Leave as is, stairs correction may be technically infeasible.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$2,135.00	1	each	\$2,135.00	2
John Prince Park	73	Soccer 5 Area	Stairways	Install kick plates on all stairs or replace with ones having closed risers.	\$84.00	16	each	\$1,344.00	2
John Prince Park	74	Soccer 5 Area	Stairways	Install contrasting strip along front 2" of each tread as smart practice.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	16	each	\$2,000.00	5
John Prince Park	75	Soccer 5 Area	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	2
John Prince Park	76	Soccer 5 Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	77	Soccer 5 Area	Accessible Routes	Provide vertical access to upper levels if feasible.	\$43,631.00	1	each	\$43,631.00	3
John Prince Park	78	Soccer 5 Area	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
John Prince Park	79	Soccer 5 Area	Dining, Bar and Work Surfaces	Extend counter to provide 17" deep toe clearance.	\$1,120.00	1	each	\$1,120.00	2
John Prince Park	80	North Park Area - Boating Ramp - Parking	Parking - Off Street	Create one or more 12' accessible trailer parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	81	North Park Area - Boating Ramp - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
John Prince Park	82	North Park Area - Boating Ramp - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	83	North Park Area - Boating Ramp - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	84	Fishing and Boating - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
John Prince Park	85	Fishing and Boating - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	2
John Prince Park	86	Fishing and Boating - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	2
John Prince Park	87	North Park Area - Boat Ramp	Boating Facilities	Reduce the slopes of the transition plates to max 8.33% and provide a landing at the base of the gangway. Leave as is if technically infeasible.	\$1,302.00	6	each	\$7,812.00	2
John Prince Park	88	North Park Area - Boat Ramp	Accessible Routes	Correct or fill gaps to be max .5". Leave as is if technically infeasible and provide curbs or barriers that will prevent wheels or casters from falling into the gaps.	\$96.25	6	each	\$577.50	2
John Prince Park	89	North Park Area - Boat Ramp	Accessible Routes	Consider restriping the accessible route to connect to a more accessible pier from parking stalls as a smart practice.	\$367.50	1	each	\$367.50	5
John Prince Park	90	Fishing Piers/Docks	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is and designate other County fishing areas accessible.	\$122.50	100	sq ft	\$12,250.00	4
John Prince Park	91	Fishing Piers/Docks	Accessible Routes	Correct or fill gaps to be max .5". In the alternative, leave as is and designate other County fishing areas accessible.	\$96.25	4	each	\$385.00	4
John Prince Park	92	Fishing Piers/Docks	Accessible Routes	Create an accessible route to the fishing pier or make corrections for a compliant route. In the alternative, leave as is and designate other County fishing areas accessible.	\$122.50	250	sq ft	\$30,625.00	4
John Prince Park	93	Fishing Piers/Docks	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	9	each	\$8,820.00	4
John Prince Park	94	Fishing Piers/Docks	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection. In the alternative, leave as is and designate other County fishing areas accessible.	\$525.00	6	each	\$3,150.00	4
John Prince Park	95	Fishing Piers/Docks	Accessible Routes	Create an accessible route to the fishing pier or make corrections for a compliant route. Correct slope to max 5% or treat as a ramp and add handrails.	\$122.50	100	sq ft	\$12,250.00	2
John Prince Park	96	Fishing Piers/Docks	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	9	each	\$8,820.00	2
John Prince Park	97	Fishing Piers/Docks	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection.	\$525.00	6	each	\$3,150.00	2
John Prince Park	98	Fishing Piers/Docks	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection.	\$525.00	6	each	\$3,150.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	99	Fishing Piers/Docks	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	3	each	\$2,940.00	4
John Prince Park	100	Fishing Piers/Docks	Accessible Routes	Correct or fill gaps to be max .5" for a compliant route to the fishing pier. In the alternative, leave as is and designate other County fishing areas accessible.	\$96.25	3	each	\$288.75	4
John Prince Park	101	Fishing Piers/Docks	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	11	each	\$10,780.00	4
John Prince Park	102	Fishing Piers/Docks	Accessible Route - Slope (C)	Correct running slopes to max 5%. In the alternative, leave as is and designate other County fishing areas accessible.	\$3,062.50	1	each	\$3,062.50	4
John Prince Park	104	South Park Area - Square Lake Fishing - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
John Prince Park	105	South Park Area - Square Lake Fishing - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
John Prince Park	106	South Park Area - Square Lake Fishing - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	2	each	\$192.50	1
John Prince Park	107	South Park Area - Square Lake Fishing - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	108	South Park Area - Square Lake Fishing - Parking	Parking - Off Street	Create one 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	109	North Park Area - Trail off Lake Worth Dr near Pickleball - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	110	North Park Area - Trail off Lake Worth Dr near Pickleball - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
John Prince Park	111	North Park Area - Trail off Lake Worth Dr near Pickleball - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	112	North Park Area - Trail Loop Around Lake - Surface	Custom/Special	Ensure trail is compliant with guidelines when construction completed as a smart practice.	\$0.00	1	staff time	\$0.00	5
John Prince Park	113	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	114	North Park Area - Trail Loop Around Lake - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	115	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1600	sq ft	\$196,000.00	5
John Prince Park	116	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	40	lin ft	\$2,368.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	117	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
John Prince Park	118	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	9000	sq ft	\$1,102,500.00	5
John Prince Park	119	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	90	lin ft	\$5,328.00	5
John Prince Park	120	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
John Prince Park	121	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2000	sq ft	\$245,000.00	5
John Prince Park	122	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	100	lin ft	\$5,920.00	5
John Prince Park	123	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
John Prince Park	124	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	95	lin ft	\$5,624.00	5
John Prince Park	125	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	180	lin ft	\$10,656.00	5
John Prince Park	126	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	15	lin ft	\$888.00	5
John Prince Park	127	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
John Prince Park	128	North Park Area - Trail Loop Around Lake - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	129	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	12800	sq ft	\$1,568,000.00	5
John Prince Park	130	North Park Area - Trail Loop Around Lake - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	131	North Park Area - Trail Loop Around Lake - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	132	North Park Area - Trail Loop Around Lake - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	40	each	\$3,850.00	5
John Prince Park	133	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4800	sq ft	\$588,000.00	5
John Prince Park	134	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4800	sq ft	\$588,000.00	5
John Prince Park	135	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1680	sq ft	\$205,800.00	5
John Prince Park	136	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
John Prince Park	137	North Park Area - Trail Loop Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	17600	sq ft	\$2,156,000.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	138	North Park Area - Trail Loop Around Lake - Elements	Accessible Routes	Relocate 20% of the garbage bins to an accessible route.	\$0.00	1	staff time	\$0.00	2
John Prince Park	139	North Park Area - Trail Loop Around Lake - Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	140	North Park Area - Trail Loop Around Lake - Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	141	North Park Area - Trail Loop Around Lake - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5
John Prince Park	142	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	143	South Park Area - Trail Along 6th Ave	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
John Prince Park	144	South Park Area - Trail Along 6th Ave	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	5
John Prince Park	145	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	146	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	147	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
John Prince Park	148	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	149	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
John Prince Park	150	South Park Area - Trail Along 6th Ave	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
John Prince Park	151	South Park Area - Trail Along 6th Ave	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	175	sq ft	\$21,437.50	5
John Prince Park	152	South Park Area - Trail Along 6th Ave	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
John Prince Park	153	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	10	each	\$962.50	5
John Prince Park	154	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
John Prince Park	155	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	4
John Prince Park	156	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
John Prince Park	157	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
John Prince Park	158	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
John Prince Park	159	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	8	each	\$770.00	5
John Prince Park	160	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	163	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
John Prince Park	164	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	165	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	750	sq ft	\$91,875.00	5
John Prince Park	166	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	167	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
John Prince Park	168	South Park Area - Wheelchair Course	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	7	each	\$673.75	5
John Prince Park	169	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
John Prince Park	170	South Park Area - Wheelchair Course	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	171	South Park Area - Heart Trail (Mulch/Woodchips) - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	5808	lin ft	\$343,833.60	4
John Prince Park	172	South Park Area - Heart Trail (Mulch/Woodchips) - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
John Prince Park	173	South Park Area - Heart Trail (Mulch/Woodchips) - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
John Prince Park	174	South Park Area - Heart Trail (Mulch/Woodchips) - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	15	lin ft	\$888.00	4
John Prince Park	175	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
John Prince Park	176	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1600	sq ft	\$196,000.00	5
John Prince Park	177	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
John Prince Park	178	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
John Prince Park	179	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
John Prince Park	180	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2560	sq ft	\$313,600.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	181	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
John Prince Park	182	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	183	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
John Prince Park	184	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair trail running slope to not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$11,550.00	1	each	\$11,550.00	5
John Prince Park	185	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	186	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
John Prince Park	187	South Park Area - Around Lake - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	188	South Park Area - Around Lake - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	189	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	190	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1600	sq ft	\$196,000.00	5
John Prince Park	191	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	192	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	193	South Park Area - Around Lake - Surface	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	5
John Prince Park	194	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	each	\$4,900.00	5
John Prince Park	195	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
John Prince Park	196	South Park Area - Around Lake - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
John Prince Park	197	South Park Area - Around Lake - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	198	South Park Area - Around Lake - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5
John Prince Park	199	South Park Area - Along Prince Dr - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	200	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	201	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	202	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	203	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	204	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	205	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
John Prince Park	206	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	720	sq ft	\$88,200.00	5
John Prince Park	207	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2400	sq ft	\$294,000.00	5
John Prince Park	208	South Park Area - Along Prince Dr - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
John Prince Park	209	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	210	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
John Prince Park	211	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	212	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
John Prince Park	213	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	214	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
John Prince Park	215	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
John Prince Park	216	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	217	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	218	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	219	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	220	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	720	sq ft	\$88,200.00	5
John Prince Park	221	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
John Prince Park	222	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2200	sq ft	\$269,500.00	5
John Prince Park	223	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	224	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	225	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
John Prince Park	226	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	5
John Prince Park	227	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
John Prince Park	228	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2800	sq ft	\$343,000.00	5
John Prince Park	229	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	230	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	231	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	232	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
John Prince Park	233	South Park Area - Trail Around Petanque Courts, Pavilions, and Play Areas	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
John Prince Park	234	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	235	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
John Prince Park	236	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
John Prince Park	237	South Park Area - Trail To Campground - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	238	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
John Prince Park	239	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
John Prince Park	240	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
John Prince Park	241	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
John Prince Park	242	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
John Prince Park	243	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	350	sq ft	\$42,875.00	5
John Prince Park	244	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	245	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
John Prince Park	246	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
John Prince Park	247	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	248	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
John Prince Park	249	South Park Area - Trail To Campground - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
John Prince Park	250	Custard Apple Nature Trail - Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
John Prince Park	251	Custard Apple Nature Trail - Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
John Prince Park	252	Custard Apple Nature Trail - Surface	Accessible Routes	Maintain overhead clearance of tree branches of min. 80".	\$0.00	1	staff time	\$0.00	5
John Prince Park	253	Custard Apple Nature Trail - Surface	Accessible Routes	Provide maintenance so that object to not protrude into the circulation path.	\$0.00	1	staff time	\$0.00	5
John Prince Park	254	Custard Apple Nature Trail - Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$59.20	50	sq ft	\$2,960.00	5
John Prince Park	255	Custard Apple Nature Trail - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
John Prince Park	257	Dog Park - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
John Prince Park	258	Dog Park - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	259	Dog Park - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	260	Dog Park - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	261	Dog Park - Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
John Prince Park	262	Dog Park - Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%	\$1,015.00	1	each	\$1,015.00	1
John Prince Park	263	Dog Park - Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%. Cost included in previous finding.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	264	Dog Park - Exterior Accessible Route	Protruding Object	Provide maintenance on trees to ensure they do not project more than 4 inches into the circulation path.	\$0.00	1	staff time	\$0.00	1
John Prince Park	265	Dog Park - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	266	Dog Park - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	267	Dog Park - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	268	Dog Park - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	269	Dog Park - Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
John Prince Park	270	Dog Park - Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
John Prince Park	271	Dog Park - Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	2
John Prince Park	272	Dog Park - Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	2
John Prince Park	273	Dog Park - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	274	Dog Park - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
John Prince Park	275	Dog Park - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	276	Dog Park - Exterior Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	279	Dog Washing Stations	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	2	each	\$1,029.00	2
John Prince Park	280	Dog Washing Stations	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	4	each	\$2,058.00	2
John Prince Park	283	Dog Area 1	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	284	Dog Area 1	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	286	Dog Area 1	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	3	lin ft	\$177.60	5
John Prince Park	287	Dog Area 1	Outdoor - Trails (C)	Resurface trail to be firm and stable as a smart practice.	\$59.20	2	lin ft	\$118.40	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	288	Dog Area 1	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
John Prince Park	290	Dog Area 1	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	291	Dog Area 1	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	292	Dog Area 1	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	1	each	\$514.50	2
John Prince Park	295	Dog Area 2/Large Dog Park	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	3	each	\$630.00	2
John Prince Park	296	Dog Area 2/Large Dog Park	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
John Prince Park	297	Dog Area 2/Large Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	298	Dog Area 2/Large Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	300	Dog Area 2/Large Dog Park	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	301	Dog Area 2/Large Dog Park	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	1	each	\$514.50	2
John Prince Park	303	Dog Area 2/Large Dog Park	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
John Prince Park	304	Dog Area 2/Large Dog Park	Accessible Routes	Repair or reset pavers to eliminate change in level.	\$96.25	1	each	\$96.25	2
John Prince Park	306	Dog Area 3	Doors	For all gates along the public circulation route, replace hardware with lever hardware where indicated mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	2
John Prince Park	307	Dog Area 3	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	24	sq ft	\$2,940.00	2
John Prince Park	311	Dog Area 3	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
John Prince Park	312	Dog Area 4/Small Dog Park	Operable Parts	Adjust pressure to operate controls on fountain to max 5lbf.	\$0.00	3	staff time	\$0.00	2
John Prince Park	313	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
John Prince Park	314	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
John Prince Park	315	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
John Prince Park	316	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
John Prince Park	317	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	318	Dog Area 4/Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5
John Prince Park	319	Dog Area 4/Small Dog Park	Doors	For all gates along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	1	each	\$514.50	2
John Prince Park	320	Dog Area 4/Small Dog Park	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	25	sq ft	\$3,062.50	2
John Prince Park	321	Dog Area 4/Small Dog Park	Accessible Routes	Repair or reset pavers to eliminate change in level.	\$96.25	1	each	\$96.25	2
John Prince Park	322	Dog Area 4/Small Dog Park	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	2
John Prince Park	325	Dog Area 5/Medium Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	100	sq ft	\$12,250.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	326	Dog Area 5/Medium Dog Park	Doors	For all gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	2
John Prince Park	327	Dog Area 5/Medium Dog Park	Accessible Routes	Repair or reset pavers to eliminate change in level.	\$96.25	1	each	\$96.25	2
John Prince Park	328	Dog Area 5/Medium Dog Park	Operable Parts	Adjust control buttons to require less than 5 lbf to operate.	\$0.00	1	staff time	\$0.00	2
John Prince Park	329	Dog Area 5/Medium Dog Park	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
John Prince Park	330	Dog Area 5/Medium Dog Park	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	2
John Prince Park	332	Dog Area 5/Medium Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	175	sq ft	\$21,437.50	5
John Prince Park	333	Dog Area 5/Medium Dog Park	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	50	sq ft	\$6,125.00	2
John Prince Park	335	Dog Area 5/Medium Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
John Prince Park	336	Dog Area 5/Medium Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
John Prince Park	337	Dog Park - Building 19 - Men's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	338	Dog Park - Building 19 - Men's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and remove the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	339	Dog Park - Building 19 - Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$3,062.50	1	each	\$3,062.50	3
John Prince Park	340	Dog Park - Building 19 - Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	341	Dog Park - Building 19 - Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and remove the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	342	Campground - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	3
John Prince Park	343	Campground - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	344	Campground - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	346	Campground - Parking	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
John Prince Park	347	Campground - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall is 12' with 5' adjacent access aisle.	\$210.00	1	each	\$210.00	1
John Prince Park	349	Campground - Parking	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1
John Prince Park	350	Campground - Parking	Parking - Off Street	Create one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	351	Campground - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	352	Campground - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	353	Campground - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	354	Campground - Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking. Price included in previous finding.	\$0.00	1	each	\$0.00	1
John Prince Park	356	Campground - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	357	Campground - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	358	Campground - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls and add accessible stalls to closer parking areas.	\$1,589.00	2	each	\$3,178.00	1
John Prince Park	359	Campground - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	360	Campground - Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
John Prince Park	361	Campground - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
John Prince Park	362	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	9	each	\$27,562.50	1
John Prince Park	363	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	364	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	365	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	366	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	367	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
John Prince Park	368	Campground - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	369	Campground - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
John Prince Park	370	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	371	Campground - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	372	Campground - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	373	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	374	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
John Prince Park	376	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	240	sq ft	\$29,400.00	1
John Prince Park	377	Campground - Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
John Prince Park	378	Campground - Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	8	lin ft	\$473.60	1
John Prince Park	379	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	150	sq ft	\$18,375.00	1
John Prince Park	380	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	40	sq ft	\$4,900.00	1
John Prince Park	381	Campground - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
John Prince Park	382	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
John Prince Park	383	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	384	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	385	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	386	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	387	Campground - Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	1
John Prince Park	388	Campground - Exterior Accessible Route	Accessible Routes	Provide cane detectable warning at base of object along the AR.	\$350.00	1	each	\$350.00	1
John Prince Park	389	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	390	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	391	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	392	Campground - Exterior Accessible Route	Accessible Routes	Repair or reset pavers to eliminate change in level.	\$96.25	4	each	\$385.00	1
John Prince Park	393	Campground - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
John Prince Park	394	Campground - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	395	Campground - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	5	each	\$1,645.00	5
John Prince Park	396	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	397	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	398	Campground - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	400	Campground - Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	401	Campground - Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	402	Campground - Elements	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
John Prince Park	403	Campground - Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	404	Campground - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	12	sq ft	\$710.40	2
John Prince Park	405	Campground - Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
John Prince Park	406	Campground - Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	12	each	\$1,470.00	2
John Prince Park	408	Campground - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
John Prince Park	409	Campground - Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	410	Campground - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
John Prince Park	412	Campground - Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
John Prince Park	413	Campground - Elements	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	5
John Prince Park	414	Campground - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to water spigot.	\$59.20	5	lin ft	\$296.00	2
John Prince Park	415	Campground - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
John Prince Park	416	Campground - Elements	Outdoor Recreation Access Route	Correct surface of ORAR to be firm and stable, a min 36" wide and having gaps and changes in level of max .5" .	\$59.20	25	sq ft	\$1,480.00	5
John Prince Park	417	Campground - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$750.00	1	each	\$750.00	5
John Prince Park	418	Campground - Elements	Outdoor - Constructed Features (C)	Provide required 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$950.00	1	each	\$950.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	419	Campground - Elements	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$750.00	1	each	\$750.00	5
John Prince Park	420	Campground - Elements	Outdoor Constructed Feature	Replace 20%, but not less than one of each type of outdoor constructed feature in common areas.	\$2,120.00	1	each	\$2,120.00	5
John Prince Park	421	Campground - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	30	lin ft	\$1,776.00	5
John Prince Park	422	Campground - Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
John Prince Park	423	Campground - Elements	Outdoor - Constructed Features (C)	Provide required 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$950.00	1	each	\$950.00	5
John Prince Park	424	Campground - Elements	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$750.00	1	each	\$750.00	5
John Prince Park	425	Campground - Elements	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
John Prince Park	426	Campground - Elements	Outdoor Constructed Feature	Replace 20%, but not less than one of each type of outdoor constructed feature in common areas.	\$2,120.00	1	each	\$2,120.00	2
John Prince Park	427	Campground - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	25	lin ft	\$1,480.00	5
John Prince Park	428	Campground - Elements	Outdoor - Constructed Features (C)	Replace surface to provide required 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$950.00	1	each	\$950.00	5
John Prince Park	429	Campground - Elements	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
John Prince Park	430	Campground - Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the new tables as a smart practice.	\$2,486.00	2	each	\$4,972.00	5
John Prince Park	431	Campground - Elements	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$750.00	1	each	\$750.00	5
John Prince Park	432	Campground - Elements	Camping (C)	Create the required number of accessible camp sites per table F244.2 as a smart practice.	\$4,298.00	11	each	\$47,278.00	5
John Prince Park	433	Campground - Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	100	lin ft	\$5,920.00	5
John Prince Park	434	Campground - Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	435	Campground - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$750.00	1	each	\$750.00	5
John Prince Park	436	Campground - Elements	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$750.00	1	each	\$750.00	5
John Prince Park	437	Campground - Elements	Outdoor - Constructed Features (C)	Provide required 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$950.00	1	each	\$950.00	5
John Prince Park	438	Campground - Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	439	Campground - Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
John Prince Park	440	Campground - Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	staff time	\$420.00	1
John Prince Park	441	Campground - Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
John Prince Park	442	Campground - Boat Ramp/Docks	Accessible Routes	Create an outdoor accessible route to one boat pier or make corrections for a compliant route.	\$3,255.00	1	each	\$3,255.00	2
John Prince Park	443	Campground - Boat Ramp/Docks	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10' at one pier.	\$875.00	1	each	\$875.00	2
John Prince Park	444	Campground - Boat Ramp/Docks	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	7	lin ft	\$414.40	2
John Prince Park	445	Campground - Boat Ramp/Docks	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	4	each	\$1,400.00	2
John Prince Park	446	Campground - Boat Ramp/Docks	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.	\$96.25	1	each	\$96.25	2
John Prince Park	447	Campground - Boat Ramp/Docks	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	448	Campground - Boat Ramp/Docks	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	449	Campground - Boat Ramp/Docks	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	450	Campground - Pavilions/Shelters/ Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
John Prince Park	451	Campground - Pavilions/Shelters/ Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of item as a smart practice.	\$350.00	4	each	\$1,400.00	5
John Prince Park	452	Campground - Pavilions/Shelters/ Picnic Areas	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	453	Campground - Pavilions/Shelters/ Picnic Areas	Shelters/Picnic Areas (C)	Rearrange accessible table to provide 36" clearance around all sides. Adjust operable parts to be useable with max 5 lbf	\$0.00	1	staff time	\$0.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	454	Campground - Pavilions/Shelters/Picnic Areas	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace door hardware with hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$2,138.12	4	each	\$8,552.48	3
John Prince Park	455	Campground - Pavilions/Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
John Prince Park	456	Campground - Pavilions/Shelters/Picnic Areas	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (table, garbage)	\$59.20	65	lin ft	\$3,848.00	5
John Prince Park	457	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	458	Campground - Pavilions/Shelters/Picnic Areas	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance or place cane detectable bollard at foot of item to warn of reduced overhead clearance.	\$350.00	20	each	\$7,000.00	5
John Prince Park	459	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice.	\$350.00	3	each	\$1,050.00	5
John Prince Park	460	Campground - Pavilions/Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
John Prince Park	461	Campground - Pavilions/Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.	\$350.00	1	each	\$350.00	5
John Prince Park	462	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
John Prince Park	463	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	464	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
John Prince Park	465	Campground - Pavilions/Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	466	Campground - Pavilions/Shelters/ Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	467	Campground - Campground Office	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,037.00	1	each	\$5,037.00	3
John Prince Park	468	Campground - Campground Office	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
John Prince Park	469	Campground - Campground Office	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
John Prince Park	470	Campground - Campground Office	Turning Space	Relocate obstacles to create turning space in campground office.	\$3,360.00	1	each	\$3,360.00	1
John Prince Park	471	Campground - Campground Office	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,649.50	1	each	\$2,649.50	2
John Prince Park	472	Campground - Campground Office	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
John Prince Park	473	Campground - Playgrounds	Custom/Special	When renovated, assure accessibility standards are included in the design.	\$0.00	1	each	\$0.00	4
John Prince Park	474	Campground - Playgrounds	Custom/Special	When renovated, assure accessibility standards are included in the design.	\$0.00	1	each	\$0.00	4
John Prince Park	475	Campground - Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	50	lin ft	\$2,960.00	2
John Prince Park	476	Campground - Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	30	lin ft	\$1,776.00	2
John Prince Park	477	Campground - Sports Fields/Courts	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice and provide a route to it and a 36" route around it.	\$1,750.00	2	each	\$3,500.00	5
John Prince Park	478	Campground - Sports Fields/Courts	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	479	Campground - Laundry	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  In the alternative, mount signage directing users to the accessible entry.	\$1,750.00	1	each	\$1,750.00	1
John Prince Park	480	Campground - Laundry	Doors	Provide required maneuvering clearance on push side of door and required maneuvering clearance around pull side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
John Prince Park	481	Campground - Laundry	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
John Prince Park	482	Campground - Laundry	Accessible Routes	Correct or repair slope to max 2.08% in CGS of washer and dryer.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	483	Campground - Laundry	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	484	Campground - Laundry	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
John Prince Park	485	Campground - Laundry	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	4	each	\$1,400.00	1
John Prince Park	486	Campground - Laundry	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	487	Campground - Laundry	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	488	Campground - Building 5 (Laundry) - Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
John Prince Park	489	Campground - Building 5 (Laundry) - Men's Restroom	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	490	Campground - Building 5 (Laundry) - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	491	Campground - Building 5 (Laundry) - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
John Prince Park	492	Campground - Building 5 (Laundry) - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	2	each	\$700.00	1
John Prince Park	493	Campground - Building 5 (Laundry) - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	494	Campground - Building 5 (Laundry) - Men's Restroom	Toilet and Bathing Rooms	Review and correct ambulatory stall when reopened. In the alternative, eliminate features of ambulatory stall and instead create a wheelchair stall if this restroom includes less than six toilets and/or urinals.	\$0.00	1	staff time	\$0.00	1
John Prince Park	495	Campground - Building 5 (Laundry) - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	496	Campground - Building 5 (Laundry) - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom. In the alternative leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
John Prince Park	497	Campground - Building 5 (Laundry) - Men's Restroom	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	498	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	499	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	500	Campground - Building 5 (Laundry) - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	501	Campground - Building 5 (Laundry) - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$175.00	2	each	\$350.00	1
John Prince Park	502	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	503	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	504	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	505	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	506	Campground - Building 5 (Laundry) - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount garbage to min 12" above and 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
John Prince Park	507	Campground - Building 5 (Laundry) - Women's Restroom	Accessible Routes	Widen AR to compliant 36" clear width	\$2,772.50	1	each	\$2,772.50	1
John Prince Park	508	Campground - Building 5 (Laundry) - Women's Restroom	Turning Space	Reconfigure restroom to provide min 60" turning space.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	509	Campground - Building 5 (Laundry) - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	510	Campground - Building 5 (Laundry) - Women's Restroom	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	511	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
John Prince Park	512	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	1
John Prince Park	513	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
John Prince Park	514	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Enlarge shower stall, if feasible, to compliant dimensions for a roll in shower of 30" deep by 60" wide with a 60" opening. In the alternative, leave as is citing construction tolerance.	\$5,498.50	1	each	\$5,498.50	4
John Prince Park	515	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the shower, mounted 33" to 36" AFF and max 6" from adjacent walls. Add third grab bar.	\$393.75	3	each	\$1,181.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	516	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Train staff to keep shower head stored in the lowest position.	\$0.00	1	staff time	\$0.00	1
John Prince Park	517	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF. Priced in previous finding.	\$0.00	2	each	\$0.00	1
John Prince Park	518	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	519	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	520	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	521	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	522	Campground - Building 8 - Men's Restroom and Showers Near Campsites 161-168	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	523	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
John Prince Park	524	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the shower, mounted 33" to 36" AFF and max 6" from adjacent walls. Add third grab bar.	\$393.75	3	each	\$1,181.25	1
John Prince Park	525	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF. Priced in previous finding.	\$0.00	2	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	526	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$253.75	1	each	\$253.75	1
John Prince Park	527	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
John Prince Park	528	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	529	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Toilet and Bathing Rooms	Install stall hardware on interior and exterior that is operable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
John Prince Park	530	Campground - Building 8 - Women's Restroom and Showers Near Campsites 161-168	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	531	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	532	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	533	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	534	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	535	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Reach Ranges	Lower hook to max 48" above the finished floor (AFF) to highest operable part.  Lower soap and one outlet to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	2	each	\$700.00	1
John Prince Park	536	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	537	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	538	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	539	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	540	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Priced in previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	each	\$0.00	1
John Prince Park	541	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Accessible Routes	Widen AR to compliant 36" clear width	\$2,772.50	1	each	\$2,772.50	1
John Prince Park	542	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Turning Space	Reconfigure restroom to provide min 60" turning space.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	543	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	544	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	545	Campground - Women's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	546	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	547	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	548	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	549	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
John Prince Park	550	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Reach Ranges	Lower outlets to max 44" above the finished floor (AFF) for a forward reach over sink or counter. Lower hooks to max 48" AFF.	\$175.00	2	each	\$350.00	1
John Prince Park	551	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	552	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	553	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees. Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	554	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	555	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Priced in previous finding. Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	556	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Accessible Routes	Widen AR to compliant 36" clear width	\$2,772.50	1	each	\$2,772.50	1
John Prince Park	557	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	558	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	559	Campground - Men's Restroom and Showers Near Campsites 99 & 138	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	560	Campground - Dog Fitness Walk Area	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	561	Campground - Dog Fitness Walk Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	562	Campground - Dog Fitness Walk Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	563	Campground - Dog Fitness Walk Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	567	Campground - Dog Fitness Walk Area	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice and place on a firm and stable surface connected to the route.	\$1,750.00	1	each	\$1,750.00	5
John Prince Park	569	Campground - Dog Fitness Walk Area	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	450	lin ft	\$26,640.00	5
John Prince Park	570	Campground - Dog Fitness Walk Area	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2
John Prince Park	571	Campground - Manager Residence	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.	\$59.20	60	lin ft	\$3,552.00	4
John Prince Park	572	Campground - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	573	Campground - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$10,505.75	1	each	\$10,505.75	3
John Prince Park	574	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character. Correct slope in clearance at sign to max 2.08%	\$3,272.50	1	each	\$3,272.50	1
John Prince Park	575	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	576	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	577	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
John Prince Park	578	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF. Cost in previous finding.	\$0.00	1	each	\$0.00	1
John Prince Park	579	Campground - Building 6 - Men's Restroom and Showers	Reach Ranges	Lower one outlet to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
John Prince Park	580	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	581	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$640.00	1	each	\$640.00	1
John Prince Park	582	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	583	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	584	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Prices in previous finding. Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	each	\$0.00	1
John Prince Park	585	Campground - Building 6 - Men's Restroom and Showers	Toilet and Bathing Rooms	See previous finding to TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	586	Campground - Building 6 - Men's Restroom and Showers	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	587	Campground - Building 6 - Men's Restroom and Showers	Accessible Routes	Correct or repair slope to max 2.08% in restroom. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
John Prince Park	588	Campground - Building 6 - Men's Restroom and Showers	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" aff and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
John Prince Park	589	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Resize transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	590	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	591	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	1
John Prince Park	592	Campground - Building 6 - Men's Restroom and Showers	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
John Prince Park	593	Campground - Building 6 - Men's Restroom and Showers	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	1
John Prince Park	594	Campground - Building 6 - Men's Restroom and Showers	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%. For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.	\$5,835.00	1	each	\$5,835.00	1
John Prince Park	595	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character. Relocate fountain for CGS at sign.	\$2,590.00	1	each	\$2,590.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	596	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	597	Campground - Building 6 - Women's Restroom and Showers	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter. Lower hook to max 48" AFF.	\$175.00	2	each	\$350.00	1
John Prince Park	598	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	599	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	600	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
John Prince Park	601	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	602	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	603	Campground - Building 6 - Women's Restroom and Showers	Toilet and Bathing Rooms	See previous finding for TP dispenser placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	604	Campground - Building 6 - Women's Restroom and Showers	Accessible Routes	Widen AR to compliant 36" clear width.	\$1,890.00	1	each	\$1,890.00	1
John Prince Park	605	Campground - Building 6 - Women's Restroom and Showers	Hazards	Relocate protruding objects or place cane detectable bollard at foot of sink. Relocate hand dryer or replace with a slimmer model.	\$350.00	2	each	\$700.00	1
John Prince Park	606	Campground - Building 6 - Women's Restroom and Showers	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	sq ft	\$888.00	1
John Prince Park	607	Campground - Building 6 - Women's Restroom and Showers	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	608	Campground - Building 6 - Women's Restroom and Showers	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	609	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Resize transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	1
John Prince Park	610	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	1
John Prince Park	611	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	1
John Prince Park	612	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	1
John Prince Park	613	Campground - Building 6 - Women's Restroom and Showers	Plumbing Fixtures & Elements	Rpplace and remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	1
John Prince Park	614	Campground - Building 6 - Women's Restroom and Showers	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.	\$5,835.00	1	each	\$5,835.00	1
John Prince Park	615	Campground - Building 9 - Men's Restroom at Campground Entry	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	616	Campground - Building 9 - Men's Restroom at Campground Entry	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille and raised characters mounted on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	617	Campground - Building 9 - Women's Restroom at Campground Entry	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	618	Campground - Building 9 - Women's Restroom at Campground Entry	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille and raised characters mounted on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	619	McMillen Island - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	620	McMillen Island - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	621	McMillen Island - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	622	McMillen Island - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	623	McMillen Island - Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of gate.  For all gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,736.25	1	each	\$3,736.25	1
John Prince Park	625	McMillen Island - Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
John Prince Park	626	McMillen Island - Playground	Play Area	Raise fill to be level with adjacent surface. See following finding for cost reference.	\$0.00	1	staff time	\$0.00	2
John Prince Park	627	McMillen Island - Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
John Prince Park	628	McMillen Island - Playground	Play Area	Provide level 30" x 48" minimum CFS centered and parallel to the 24" side of the transfer platform. Cost in previous finding.	\$0.00	1	staff time	\$0.00	2
John Prince Park	629	McMillen Island - Playground	Play Area	Make correction to surface to provide 50% of EPCs compliant. Price included in earlier finding.	\$0.00	1	staff time	\$0.00	2
John Prince Park	630	McMillen Island - Playground	Play Area	Make correction to surface to provide accessible route to one of each type of GLPC. Price included in earlier finding.	\$0.00	1	staff time	\$0.00	2
John Prince Park	632	McMillen Island - Playground	Play Area	Replace surface to provide accessible GLPCs and meet incentive scoping. Price included in earlier finding.	\$0.00	1	each	\$0.00	2
John Prince Park	633	McMillen Island - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	3	each	\$288.75	4
John Prince Park	634	McMillen Island - Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
John Prince Park	635	McMillen Island - Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.  Replace or lower grill to max height of cooking surface 34".  Relocate 20% of garbage cans to be along AR.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,192.00	1	each	\$1,192.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	636	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
John Prince Park	637	McMillen Island - Trail Surface	Trails	Resurface trail where deteriorated to eliminate gaps as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
John Prince Park	638	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	639	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	640	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	641	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	642	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	643	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	210	sq ft	\$25,725.00	5
John Prince Park	644	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	645	McMillen Island - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
John Prince Park	646	McMillen Island - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Prince Park	647	McMillen Island - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	649	McMillen Island - Trail Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
John Prince Park	650	Golf Learning Center - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	651	Golf Learning Center - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
John Prince Park	652	Golf Learning Center - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	653	Golf Learning Center - Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
John Prince Park	654	Golf Learning Center - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
John Prince Park	655	Golf Learning Center - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	656	Golf Learning Center - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
John Prince Park	657	Golf Learning Center - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	658	Golf Learning Center - Exterior Accessible Route	Parking - Off Street	Designate an access aisle for the passenger drop off area by painting an aisle that is 60" wide and 20' long.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	659	Golf Learning Center - Clubhouse	Plumbing Fixtures & Elements	Remove cabinets to provide knee and toe clearance  Relocate items to provide CFS at sink  Remount operable parts of paper towel dispenser to be in reach range of 15" min to 48" max.	\$1,176.00	1	each	\$1,176.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	660	Golf Learning Center - Clubhouse	Accessible Routes	Correct service counter to be 36" aff and correct width based on approach.  Remove storage and display items from lowered counters and from the clear floor space.	\$1,099.00	2	each	\$2,198.00	1
John Prince Park	661	Golf Learning Center - Clubhouse	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	8	each	\$1,120.00	1
John Prince Park	662	Golf Learning Center - Clubhouse	Accessible Routes	Relocate items to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	663	Golf Learning Center - Clubhouse	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	664	Golf Learning Center - Clubhouse	Accessible Routes	Relocate storage and merchandise items to provide 36" clear width route.	\$0.00	1	staff time	\$0.00	1
John Prince Park	666	Golf Learning Center - Clubhouse	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
John Prince Park	667	Golf Learning Center - Clubhouse	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	668	Golf Learning Center - Clubhouse	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
John Prince Park	669	Golf Learning Center - Clubhouse	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	1
John Prince Park	670	Golf Learning Center - Clubhouse	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$420.00	1	each	\$420.00	1
John Prince Park	671	Golf Learning Center - Clubhouse	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$3,062.50	1	each	\$3,062.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	672	Golf Learning Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
John Prince Park	674	Golf Learning Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Relocate pull-up bar to provide 80" overhead clearance.	\$0.00	3	staff time	\$0.00	3
John Prince Park	675	Golf Learning Center - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.  Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
John Prince Park	676	Golf Learning Center - Employee Spaces	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
John Prince Park	677	Golf Learning Center - Employee Spaces	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
John Prince Park	678	Golf Learning Center - Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	3
John Prince Park	679	Golf Learning Center - Employee Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
John Prince Park	680	Golf Learning Center - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$481.25	1	each	\$481.25	3
John Prince Park	683	Golf Learning Center - Driving Range/Practice Greens	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	684	Golf Learning Center - Driving Range/Practice Greens	Clear Floor Space	Repair, bevel or ramp CIL in CFS to max .25".  Secure edges of carpeting or mats to prevent trip hazard.  Correct or fill gap to .5" max.	\$110.75	3	each	\$332.25	1
John Prince Park	687	Golf Learning Center - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
John Prince Park	688	Golf Learning Center - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	689	Golf Learning Center - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	690	Golf Learning Center - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	691	Golf Learning Center - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
John Prince Park	692	Golf Learning Center - Men's Restroom	Toilet and Bathing Rooms	Relocate urinal to provide required 60" clearance around toilet. In the alternative, leave as is citing safe harbor.	\$2,978.50	1	each	\$2,978.50	4
John Prince Park	693	Golf Learning Center - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	694	Golf Learning Center - Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	695	Golf Learning Center - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	696	Golf Learning Center - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
John Prince Park	698	Maintenance - Parking	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1
John Prince Park	699	Maintenance - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
John Prince Park	700	Maintenance - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 11' and 5' or 8' and 8'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	701	Maintenance - Parking	Parking - Off Street	Create five or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	5	each	\$7,945.00	1
John Prince Park	702	Maintenance - Parking	Parking - Off Street	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	703	Maintenance - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	704	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	705	Maintenance - Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	706	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
John Prince Park	707	Maintenance - Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	1
John Prince Park	708	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
John Prince Park	709	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	2	each	\$1,750.00	3
John Prince Park	710	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
John Prince Park	711	Maintenance - Exterior Accessible Route	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from building to building within the site.	\$59.20	800	lin ft	\$47,360.00	3
John Prince Park	712	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	713	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	250	sq ft	\$30,625.00	1
John Prince Park	714	Maintenance - Exterior Accessible Route	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	715	Maintenance - Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	716	Maintenance - Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF. Pricing for replacing guardrails with handrails in the previous finding.	\$0.00	2	each	\$0.00	1
John Prince Park	717	Maintenance - Exterior Accessible Route	Stairways	Replace handrails with compliant handrails. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	1
John Prince Park	718	Maintenance - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	719	Maintenance - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	720	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
John Prince Park	721	Maintenance - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
John Prince Park	722	Maintenance - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	723	Maintenance - Exterior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2
John Prince Park	724	Maintenance - Public Spaces	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs and adjust high bowl to 38" to 43" to the spout.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	725	Maintenance - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	726	Maintenance - Employee Spaces	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
John Prince Park	728	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
John Prince Park	729	Maintenance - Employee Spaces	Accessible Routes	Provide vertical access to all levels of the building.  No AR to employee area, leave as is, and reassign duties if an employee with disabilities requires access here.	\$43,631.00	1	each	\$43,631.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	730	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$2,614.75	2	each	\$5,229.50	3
John Prince Park	731	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Provide kick plate on push side of door from floor to 10" AFF.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$1,785.25	4	each	\$7,141.00	3
John Prince Park	732	Maintenance - Employee Spaces	Stairways	Make corrections to stairs to upper level; leave as is risers and treads if technically infeasible.	\$7,619.50	1	each	\$7,619.50	3
John Prince Park	733	Maintenance - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$2,772.50	1	each	\$2,772.50	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	734	Maintenance - Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$5,037.00	1	each	\$5,037.00	3
John Prince Park	735	Maintenance - Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$2,264.50	1	each	\$2,264.50	3
John Prince Park	736	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Repair, provide beveled threshold.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$2,138.00	4	each	\$8,552.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	737	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$2,431.50	3	each	\$7,294.50	3
John Prince Park	738	Maintenance - Employee Spaces	Accessible Routes	<p>Provide vertical access to all levels of the building.</p> <p>No AR to employee area, leave as is, and reassign duties if an employee with disabilities requires access here.</p>	\$43,631.00	1	each	\$43,631.00	3
John Prince Park	739	Maintenance - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	3
John Prince Park	740	Maintenance - Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
John Prince Park	741	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure rug at door to prevent trip hazard.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p>	\$1,728.25	2	each	\$3,456.50	3
John Prince Park	742	Maintenance - Employee Spaces	Accessible Route - Slope (C)	<p>Correct running slopes to max 5%.</p> <p>Correct cross slopes to max 2.08%.</p>	\$122.50	800	sq ft	\$98,000.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	743	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$1,718.75	6	each	\$10,312.50	3
John Prince Park	744	Maintenance - Employee Spaces	Room/Space (C)	<p>Make corrections for compliant circulation path.</p>	\$2,772.50	1	each	\$2,772.50	3
John Prince Park	745	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure grate at door to prevent trip hazard.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$2,112.25	2	each	\$4,224.50	3
John Prince Park	746	Maintenance - Employee Spaces	Room/Space (C)	<p>Make corrections for compliant circulation path.</p> <p>Correct or repair running slope of AR to max 5%</p>	\$3,062.50	1	each	\$3,062.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	747	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$7,024.50	1	each	\$7,024.50	3
John Prince Park	748	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$7,024.50	1	each	\$7,024.50	3
John Prince Park	749	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$1,485.75	2	each	\$2,971.50	3
John Prince Park	750	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$768.25	1	each	\$768.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	751	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the building</p>	\$5,732.50	1	each	\$5,732.50	3
John Prince Park	752	Maintenance - Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$2,852.25	3	each	\$8,556.75	3
John Prince Park	753	Maintenance - Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$6,787.00	1	each	\$6,787.00	3
John Prince Park	754	Maintenance - Employee Spaces	Toilet and Bathing Rooms	<p>Create compliant wheelchair accessible restrooms and correct all features to be accessible if feasible to meet 50% compliant restrooms in this location.</p> <p>Create an accessible shower in locker/bathing room.</p>	\$30,427.25	1	each	\$30,427.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	755	Maintenance - Employee Spaces	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	756	Maintenance - Employee Spaces	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised lettering and mount on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	757	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,455.50	2	each	\$6,911.00	3
John Prince Park	758	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Remount lock hardware min 34" and max 48".	\$610.75	1	each	\$610.75	3
John Prince Park	759	Maintenance - Employee Spaces	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.	\$59.20	50	lin ft	\$2,960.00	5
John Prince Park	760	Maintenance - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Repair, provide beveled threshold.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,257.00	5	each	\$16,285.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	761	Maintenance - Employee Spaces	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
John Prince Park	762	Maintenance - Employee Spaces	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
John Prince Park	763	Maintenance - Employee Spaces	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	3
John Prince Park	764	Maintenance - Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
John Prince Park	765	Maintenance - Employee Spaces	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
John Prince Park	766	Maintenance - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	2
John Prince Park	767	Maintenance - Employee Spaces	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	768	Maintenance - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Lower sinks to max 34" above the finished floor (AFF) to front of rim.  Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  Provide required 30" by 48" CFS at operable parts.	\$2,380.00	1	each	\$2,380.00	3
John Prince Park	770	Maintenance - Employee Spaces	Park Site (C)	Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
John Prince Park	771	Maintenance - Main Maintenance Office Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
John Prince Park	772	Maintenance - Main Maintenance Office Building	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	3
John Prince Park	773	Maintenance - Main Maintenance Office Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$70.00	5	each	\$350.00	3
John Prince Park	774	Maintenance - Main Maintenance Office Building	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3
John Prince Park	775	Maintenance - Main Maintenance Office Building	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
John Prince Park	776	Maintenance - Main Maintenance Office Building	Accessible Routes	Relocate tables and chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	777	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	1
John Prince Park	778	Maintenance - Main Maintenance Office Building	Reach Ranges	<p>Remount operable parts to be in reach range of 15" min to 48" max.</p> <p>Replace operable part of window blinds with ones usable without a tight pinch or grasp.</p>	\$1,680.00	1	each	\$1,680.00	3
John Prince Park	779	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$472.50	2	each	\$945.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	780	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$542.50	2	each	\$1,085.00	1
John Prince Park	781	Maintenance - Main Maintenance Office Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Leave as is fire alarm control - employees only.	\$350.00	2	each	\$700.00	1
John Prince Park	782	Maintenance - Main Maintenance Office Building	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	783	Maintenance - Main Maintenance Office Building	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure rug at door to prevent trip hazard.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Fill gaps at door entries to max .5".</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p>	\$144.50	15	each	\$2,167.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	784	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$1,750.00	1	each	\$1,750.00	1
John Prince Park	785	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$1,750.00	1	each	\$1,750.00	3
John Prince Park	786	Maintenance - Main Maintenance Office Building	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open doors/gates.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$3,276.00	1	each	\$3,276.00	1
John Prince Park	787	Maintenance - Main Maintenance Office Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	788	Maintenance - Main Maintenance Office Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
John Prince Park	789	Maintenance - Building 7	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	1
John Prince Park	790	Maintenance - Building 7	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	2	each	\$192.50	3
John Prince Park	791	Maintenance - Building 7	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	792	Maintenance - Building 7	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	4	each	\$3,920.00	1
John Prince Park	793	Maintenance - Building 7	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	10	each	\$1,250.00	5
John Prince Park	794	Maintenance - Building 7	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Replace doors with ones having sidelight viewing windows max 43" AFF.  Inspect, adjust, and maintain closing speed on door closers.	\$652.40	10	each	\$6,524.00	3
John Prince Park	795	Maintenance - Building 8	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	796	Maintenance - Building 8	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	3
John Prince Park	797	Maintenance - Building 8	Signs	Restroom not accessible, acquire and mount signage directing staff to accessible restroom	\$210.00	1	each	\$210.00	1
John Prince Park	798	Maintenance - Building 8	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering, mounted on wall on latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	799	Maintenance - Building 8	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,814.75	1	each	\$1,814.75	3
John Prince Park	800	Maintenance - Building 8	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
John Prince Park	801	Maintenance - Building 8	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	9	each	\$3,638.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	802	Maintenance - Building 8	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	9	each	\$1,125.00	5
John Prince Park	803	Maintenance - Building 8	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
John Prince Park	804	Maintenance - Building 8	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
John Prince Park	805	Maintenance - Building 8	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4" - 6.25" max with a min gap of 1.5" between handrail and wall.  Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	1
John Prince Park	806	Maintenance - Building 8	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	807	Maintenance - Building 8	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.	\$59.20	25	lin ft	\$1,480.00	1
John Prince Park	808	Maintenance - Building 8	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance	\$59.20	125	lin ft	\$7,400.00	1
John Prince Park	809	Maintenance - Stock Room and Carpenter Room Restrooms	Toilet and Bathing Rooms	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	\$24,928.75	1	each	\$24,928.75	1
John Prince Park	810	Maintenance - Stock Room and Carpenter Room Restrooms	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	811	Maintenance - Stock Room and Carpenter Room Restrooms	Toilet and Bathing Rooms	Replace sign with one that is gender neutral and of contrasting colors that includes Braille, raised characters, mounted on the wall on latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	812	Maintenance - Stock Room and Carpenter Room Restrooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$9,282.50	1	each	\$9,282.50	1
John Prince Park	813	Maintenance - Stock Room and Carpenter Room Restrooms	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$9,797.00	1	each	\$9,797.00	1
John Prince Park	814	Maintenance - Stock Room and Carpenter Room Restrooms	Toilet and Bathing Rooms	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	\$24,928.75	1	each	\$24,928.75	1
John Prince Park	815	Maintenance - Stock Room and Carpenter Room Restrooms	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	816	Maintenance - Stock Room and Carpenter Room Restrooms	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering, mounted on wall on latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	817	Maintenance - Stock Room and Carpenter Room Restrooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,264.50	1	each	\$2,264.50	1
John Prince Park	818	Maintenance - Men's Exterior Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	3
John Prince Park	819	Maintenance - Men's Exterior Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	820	Maintenance - Women's Exterior Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	821	Maintenance - Women's Exterior Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	822	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
John Prince Park	823	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	2	staff time	\$0.00	1
John Prince Park	824	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	825	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	826	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	827	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Reach Ranges	Remount operable parts of paper towel dispenser to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	828	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	829	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Price for one in previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount hand dryer to max 48" above the floor and at least 12" above grab bar.	\$185.93	4	each	\$743.72	1
John Prince Park	830	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	831	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Prince Park	832	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	833	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Accessible Routes	Widen stall doors to 32" when opened to 90 degrees.	\$420.00	1	each	\$420.00	1
John Prince Park	834	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	835	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
John Prince Park	836	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Plumbing Fixtures & Elements	Establish protocols for regular and frequent inspection of adjustable shower head to ensure bracket is max 48" AFF.	\$0.00	1	staff time	\$0.00	2
John Prince Park	837	Maintenance - Main Maintenance Office Building - Men's Restroom/Shower	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
John Prince Park	838	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	839	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	2	staff time	\$0.00	1
John Prince Park	840	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	841	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	842	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	843	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Reach Ranges	Lower operating mechanisms of paper towel dispenser to max 48" above the finished floor (AFF) to highest operable part.  Relocate seat covers to be max 48" to the handle and out of clearance of toilet and grab bars.	\$0.00	2	staff time	\$0.00	1
John Prince Park	844	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Relocate paper towel dispenser to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
John Prince Park	845	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	846	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	847	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  See previous finding for relocation of seat covers.	\$98.50	4	each	\$394.00	1
John Prince Park	848	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	849	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	850	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
John Prince Park	851	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
John Prince Park	852	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held, the a mounting bracket max 48" AFF.	\$540.75	1	each	\$540.75	2
John Prince Park	853	Maintenance - Main Maintenance Office Building - Women's Restroom/Shower	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	3
John Prince Park	855	Admin Offices - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	6	each	\$441.00	1
John Prince Park	856	Admin Offices - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. Leave as is 2.2% slope citing construction tolerance.	\$3,062.50	4	each	\$12,250.00	1
John Prince Park	857	Admin Offices - Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.	\$96.25	1	each	\$96.25	1
John Prince Park	858	Admin Offices - Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.  Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$6,630.00	1	each	\$6,630.00	1
John Prince Park	859	Admin Offices - Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	1
John Prince Park	860	Admin Offices - Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	7	each	\$673.75	1
John Prince Park	861	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	1
John Prince Park	862	Admin Offices - Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	863	Admin Offices - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	1
John Prince Park	864	Admin Offices - Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
John Prince Park	865	Admin Offices - Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	4	each	\$385.00	1
John Prince Park	866	Admin Offices - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	1	each	\$525.00	1
John Prince Park	867	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
John Prince Park	868	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	200	sq ft	\$24,500.00	1
John Prince Park	869	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	870	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	225	sq ft	\$27,562.50	1
John Prince Park	871	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	872	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
John Prince Park	873	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	874	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
John Prince Park	875	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	876	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	877	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
John Prince Park	878	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	879	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	1
John Prince Park	880	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	881	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
John Prince Park	882	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
John Prince Park	883	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	884	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	885	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	886	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	887	Admin Offices - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	250	sq ft	\$30,625.00	1
John Prince Park	888	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	889	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	890	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	891	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	892	Admin Offices - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	893	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	894	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	895	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	896	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	897	Admin Offices - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
John Prince Park	898	Admin Offices - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	899	Admin Offices - Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,487.50	1	each	\$1,487.50	1
John Prince Park	900	Admin Offices - Exterior Accessible Route	Detectable Warnings	Install detectable warning with contract where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	901	Admin Offices - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	902	Admin Offices - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	904	Admin Offices - Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	3
John Prince Park	905	Admin Offices - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$200.00	7	each	\$1,400.00	3
John Prince Park	906	Admin Offices - Employee Spaces	Operable Parts	Replace operable parts with one usable without a tight pinch or grasp.	\$210.00	5	each	\$1,050.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	907	Admin Offices - Employee Spaces	Dining, Bar and Work Surfaces	Provide two tables or work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	2	each	\$2,240.00	3
				Make corrections for compliant circulation path.					
John Prince Park	908	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
				For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	9	staff time	\$0.00	3
John Prince Park	909	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
				Make corrections for compliant circulation path.					
John Prince Park	910	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
				For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.					
John Prince Park	911	Admin Offices - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
				For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.					
John Prince Park	912	Admin Offices - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
				Make corrections for compliant circulation path.					
John Prince Park	913	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	3
				Make corrections for compliant circulation path.					
John Prince Park	914	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$262.50	4	each	\$1,050.00	3
				Make corrections for compliant circulation path.					
John Prince Park	916	Admin Offices - Employee Spaces	Room/Space (C)	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
				For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.					
John Prince Park	917	Admin Offices - Employee Spaces	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors.	\$0.00	13	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	918	Admin Offices - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	12	staff time	\$0.00	3
John Prince Park	919	Admin Offices - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain closing speed on door closers.  Provide kick plate on push side of door from floor to 10" AFF.	\$105.00	18	each	\$1,890.00	3
John Prince Park	920	Admin Offices - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$276.50	24	each	\$6,636.00	3
John Prince Park	921	Admin Offices - Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.  Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
John Prince Park	922	Admin Offices - Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	923	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	924	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	925	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	3	each	\$630.00	3
John Prince Park	926	Admin Offices - Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	927	Admin Offices - Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	928	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$116.50	3	each	\$349.50	1
John Prince Park	929	Admin Offices - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
John Prince Park	930	Admin Offices - Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	931	Admin Offices - Public Spaces	Accessible Routes	Relocate or raise hanging plant to min 80".	\$0.00	1	staff time	\$0.00	1
John Prince Park	932	Admin Offices - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	933	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	934	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
John Prince Park	935	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
John Prince Park	937	Admin Offices - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
John Prince Park	938	Admin Offices - Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	939	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	940	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$70.00	5	each	\$350.00	1
John Prince Park	941	Admin Offices - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,890.00	1	each	\$1,890.00	1
John Prince Park	942	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	6	each	\$1,260.00	3
John Prince Park	943	Admin Offices - Public Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
John Prince Park	944	Admin Offices - Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	945	Admin Offices - Public Spaces	Turning Space	Relocate obstacles to create turning space in conference room 201.	\$0.00	1	staff time	\$0.00	1
John Prince Park	946	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	947	Admin Offices - Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	948	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$233.25	3	each	\$699.75	1
John Prince Park	949	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	4	each	\$840.00	3
John Prince Park	950	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	951	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is employee operated.	\$233.25	3	each	\$699.75	4
John Prince Park	952	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3
John Prince Park	955	Admin Offices - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
John Prince Park	956	Admin Offices - Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	957	Admin Offices - Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	958	Admin Offices - Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
John Prince Park	959	Admin Offices - Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	4	each	\$840.00	3
John Prince Park	960	Admin Offices - Public Spaces	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
John Prince Park	961	Admin Offices - Public Spaces	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
John Prince Park	963	Admin Offices - Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
John Prince Park	966	Admin Offices - Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	967	Admin Offices - Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	968	Admin Offices - Interior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	969	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$3,510.00	1	each	\$3,510.00	1
John Prince Park	970	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$140.00	1	each	\$140.00	1
John Prince Park	971	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct door to open to 90 degrees.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$1,890.00	1	each	\$1,890.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	972	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$376.25	1	each	\$376.25	1
John Prince Park	973	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$140.00	1	each	\$140.00	1
John Prince Park	974	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton      Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	975	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$612.50	1	each	\$612.50	1
John Prince Park	976	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$472.50	1	each	\$472.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	977	Admin Offices - Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$612.50	1	each	\$612.50	1
John Prince Park	978	Admin Offices - Interior Accessible Route	Doors	Mount signage at entrance designating it as accessible.	\$210.00	2	each	\$420.00	1
John Prince Park	979	Admin Offices - Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1
John Prince Park	980	Admin Offices - Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1
John Prince Park	981	Admin Offices - Interior Accessible Route	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	10	each	\$2,100.00	1
John Prince Park	982	Admin Offices - Women's Restroom (229)	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
John Prince Park	983	Admin Offices - Women's Restroom (229)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	984	Admin Offices - Women's Restroom (229)	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
John Prince Park	985	Admin Offices - Men's Restroom (225)	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
John Prince Park	986	Admin Offices - Men's Restroom (225)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	987	Admin Offices - Women's Restroom (137)	Plumbing Fixtures & Elements	Remove face board to provide 8" deep knee clearance and insulate exposed pipes.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	988	Admin Offices - Women's Restroom (137)	Reach Ranges	Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
John Prince Park	989	Admin Offices - Women's Restroom (137)	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
John Prince Park	990	Admin Offices - Women's Restroom (137)	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	991	Admin Offices - Women's Restroom (137)	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$116.50	3	each	\$349.50	1
John Prince Park	992	Admin Offices - Women's Restroom (137)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	993	Admin Offices - Women's Restroom (137)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
John Prince Park	993	Admin Offices - Women's Restroom (137)	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Prince Park	994	Admin Offices - Women's Restroom (137)	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
John Prince Park	995	Admin Offices - Women's Restroom (137)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	996	Admin Offices - Women's Restroom (137)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	998	Admin Offices - Men's Restroom (135)	Plumbing Fixtures & Elements	Remove face board to provide 8" deep knee clearance.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	999	Admin Offices - Men's Restroom (135)	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1000	Admin Offices - Men's Restroom (135)	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	1
John Prince Park	1001	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$116.50	3	each	\$349.50	1
John Prince Park	1002	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1003	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1004	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.					
John Prince Park	1004	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Relocate seat cover dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1005	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
John Prince Park	1005	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1006	Admin Offices - Men's Restroom (135)	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
John Prince Park	1007	Admin Offices - Men's Restroom (135)	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1008	Admin Offices - Men's Restroom (135)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1010	Admin Offices - Women's Restroom (166)	Plumbing Fixtures & Elements	Remove face board to provide 8" deep knee clearance.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	1011	Admin Offices - Women's Restroom (166)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1012	Admin Offices - Women's Restroom (166)	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
John Prince Park	1013	Admin Offices - Women's Restroom (166)	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$116.50	3	each	\$349.50	1
John Prince Park	1014	Admin Offices - Women's Restroom (166)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1015	Admin Offices - Women's Restroom (166)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1016	Admin Offices - Women's Restroom (166)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Prince Park	1017	Admin Offices - Women's Restroom (166)	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
John Prince Park	1018	Admin Offices - Women's Restroom (166)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1019	Admin Offices - Women's Restroom (166)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1020	Admin Offices - Women's Restroom (166)	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1021	Admin Offices - Men's Restroom (168)	Plumbing Fixtures & Elements	Remove face board to provide 8" deep knee clearance.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	1022	Admin Offices - Men's Restroom (168)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1023	Admin Offices - Men's Restroom (168)	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
John Prince Park	1024	Admin Offices - Men's Restroom (168)	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$116.50	3	each	\$349.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1025	Admin Offices - Men's Restroom (168)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1026	Admin Offices - Men's Restroom (168)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1027	Admin Offices - Men's Restroom (168)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Prince Park	1028	Admin Offices - Men's Restroom (168)	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
John Prince Park	1029	Admin Offices - Men's Restroom (168)	Accessible Routes	Widen AR to compliant 36" clear width	\$1,540.00	1	each	\$1,540.00	1
John Prince Park	1030	Admin Offices - Men's Restroom (168)	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1031	Admin Offices - Men's Restroom (168)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1032	Admin Offices - Men's Restroom (168)	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1034	North Park Area - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	5	each	\$367.50	1
John Prince Park	1035	North Park Area - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	2	each	\$192.50	1
John Prince Park	1036	North Park Area - Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
John Prince Park	1037	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	225	sq ft	\$27,562.50	1
John Prince Park	1038	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
John Prince Park	1039	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1040	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1041	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1042	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
John Prince Park	1043	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	1044	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	12	each	\$1,155.00	1
John Prince Park	1045	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1046	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1047	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
John Prince Park	1048	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1049	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1050	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1051	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1052	North Park Area - Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs as smart practice.	\$59.20	100	sq ft	\$5,920.00	5
John Prince Park	1053	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1054	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1055	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
John Prince Park	1056	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1057	North Park Area - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	1058	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
John Prince Park	1059	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1060	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
John Prince Park	1061	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	9	each	\$27,562.50	1
John Prince Park	1062	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
John Prince Park	1063	North Park Area - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	1064	North Park Area - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	1065	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
John Prince Park	1066	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1067	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1068	North Park Area - Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	25	each	\$1,480.00	1
John Prince Park	1069	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
John Prince Park	1070	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1071	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1072	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
John Prince Park	1073	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
John Prince Park	1074	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1075	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	18	each	\$55,125.00	1
John Prince Park	1076	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	5	each	\$15,312.50	1
John Prince Park	1077	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1078	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
John Prince Park	1079	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
John Prince Park	1080	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1081	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1082	North Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
John Prince Park	1083	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
John Prince Park	1084	North Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1085	North Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1086	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	1087	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1088	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
John Prince Park	1089	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	1	each	\$96.25	1
John Prince Park	1090	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1091	North Park Area - Parking For 6 Shelters Of 6th Ave Bridge	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	1092	North Park Area - Park Elements	Park Site (C)	Relocate garbage bins to along an accessible route (AR) and lower top of garbage bin to 48" AGL.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1093	North Park Area - Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	1096	North Park Area - Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1097	North Park Area - Park Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	1098	North Park Area - Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl along an accessible route.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1101	North Park Area - Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
John Prince Park	1102	North Park Area - Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1105	North Park Area - Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Provide required clear ground space at accessible picnic tables.	\$59.20	180	sq ft	\$10,656.00	2
John Prince Park	1106	North Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	1107	North Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	1108	North Park Area - Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.	\$350.00	1	each	\$350.00	2
John Prince Park	1109	North Park Area - Shelters/Picnic Areas	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
John Prince Park	1110	North Park Area - 2 to 5 Play Area	Play Area	Create designated entry by removing 36" portion of play area boundary at swings and repair other designated entries that are free of CIL and gaps as a smart practice.	\$700.00	1	each	\$700.00	5
John Prince Park	1111	North Park Area - 2 to 5 Play Area	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	6	each	\$577.50	2
John Prince Park	1113	North Park Area - 2-12 Play Area	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1114	North Park Area - 2-12 Play Area	Play Area	Correct or repair ground ramp slope to be max 6.25%. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	50	sq ft	\$6,125.00	4
John Prince Park	1115	North Park Area - 2-12 Play Area	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	75	sq ft	\$9,187.50	4
John Prince Park	1116	North Park Area - 2-12 Play Area	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  Repair seams in turf to eliminate change in level.  In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	3	each	\$288.75	4
John Prince Park	1117	North Park Area - 2-12 Play Area	Play Area	Install compliant handrails along both sides of ramp at 20" to 28" AFF. In the alternative, leave as is and designate other County playgrounds accessible.	\$1,190.00	6	each	\$7,140.00	4
John Prince Park	1118	North Park Area - 2-12 Play Area	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,604.00	2	each	\$5,208.00	4
John Prince Park	1121	North Park Area - 2-12 Play Area	Play Area	Add 8 more GLPCs of 4 types other than climbers to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	8	each	\$22,400.00	4
John Prince Park	1122	North Park Area - 5 to 12 Play Area	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.	\$700.00	1	each	\$700.00	5
John Prince Park	1123	North Park Area - 5 to 12 Play Area	Play Area	Correct or repair ground ramp slope to be max 6.25%.	\$122.50	25	sq ft	\$3,062.50	2
John Prince Park	1124	North Park Area - 5 to 12 Play Area	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	2
John Prince Park	1125	North Park Area - 5 to 12 Play Area	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
John Prince Park	1126	North Park Area - 5 to 12 Play Area	Play Area	Consider adding a second transfer system as a smart practice	\$2,800.00	1	each	\$2,800.00	5
John Prince Park	1127	North Park Area - 5 to 12 Play Area	Play Area	Provide level 30" x 48" minimum CFS centered and parallel to the 24" side of the transfer platform.	\$122.50	12	sq ft	\$1,470.00	2
John Prince Park	1128	North Park Area - 5 to 12 Play Area	Play Area	Install compliant handrails along both sides of ramp at 20" to 28" AGL.	\$1,190.00	9	each	\$10,710.00	2
John Prince Park	1129	North Park Area - 5 to 12 Play Area	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%.	\$2,604.00	3	each	\$7,812.00	2
John Prince Park	1132	North Park Area - 5 to 12 Play Area	Play Area	For children age 9 to 12, raise/lower the play component to min 16" and 44".	\$350.00	1	each	\$350.00	2
John Prince Park	1133	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	2	each	\$1,400.00	4
John Prince Park	1134	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1135	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Play Area	Correct or repair ground ramp slope to be max 6.25%. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	75	sq ft	\$9,187.50	4
John Prince Park	1136	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	100	sq ft	\$12,250.00	4
John Prince Park	1137	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Accessible Routes	Repair or reset turf to eliminate change in level. In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	2	each	\$192.50	4
John Prince Park	1138	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Play Area	Provide level 30" x 48" minimum CGS centered and parallel to the 24" side of the transfer platform. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	12	sq ft	\$1,470.00	4
John Prince Park	1140	North Park Area - 5 to 12 Play Area (Pirate Ship-themed Play Structure)	Play Area	Provide an AR to element for one of each type accessible. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
John Prince Park	1143	North Park Area - Splash Pad	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	25	each	\$3,062.50	2
John Prince Park	1144	North Park Area - Splash Pad	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
John Prince Park	1146	North Park Area - Splash Pad	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1147	North Park Area - Splash Pad	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AGL.	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	1148	North Park Area - Splash Park Men's Restroom/Bldg 16	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1
John Prince Park	1149	North Park Area - Splash Park Men's Restroom/Bldg 16	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	1150	North Park Area - Splash Park Men's Restroom/Bldg 16	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior door.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1152	North Park Area - Splash Pad Women's Restroom/Bldg 16	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Prince Park	1153	North Park Area - Splash Pad Women's Restroom/Bldg 16	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1154	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	1155	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1156	North Park Area - Splash Park Accessible Single User Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1157	North Park Area - Splash Park Accessible Single User Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1158	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1159	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1160	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1161	North Park Area - Splash Park Accessible Single User Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
John Prince Park	1162	North Park Area - Splash Park Accessible Single User Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1163	North Park Area - Splash Park Accessible Single User Restroom	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1164	North Park Area - Splash Park Accessible Single User Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1165	North Park Area - Splash Park Accessible Single User Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	1	staff time	\$0.00	1
John Prince Park	1166	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1167	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted at 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$2,218.50	1	each	\$2,218.50	3
John Prince Park	1169	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1170	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1171	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$140.00	1	each	\$140.00	1
John Prince Park	1172	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Doors	Inspect, adjust, and maintain closing speed on door closers	\$0.00	1	staff time	\$0.00	1
John Prince Park	1173	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$5,691.00	1	each	\$5,691.00	3
John Prince Park	1174	North Park Area - PBC Sheriff's Office/Park Enforcement Unit	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
John Prince Park	1175	North Park Area - PBC Sheriff's Office Restroom	Toilet and Bathing Rooms	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	\$24,928.75	1	each	\$24,928.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1176	North Park Area - PBC Sheriff's Office Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	1177	South Park Area - Parking	Parking - Off Street	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	1178	South Park Area - Parking	Parking - Off Street	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	1180	South Park Area - Parking	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
John Prince Park	1181	South Park Area - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	6	each	\$18,375.00	1
John Prince Park	1182	South Park Area - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	2	each	\$192.50	1
John Prince Park	1183	South Park Area - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	1185	South Park Area - Parking	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	2	each	\$147.00	1
John Prince Park	1186	South Park Area - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
John Prince Park	1187	South Park Area - Parking	Parking - Off Street	Add one van parking sign to two accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
John Prince Park	1188	South Park Area - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	22	each	\$67,375.00	1
John Prince Park	1189	South Park Area - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	15	each	\$1,443.75	1
John Prince Park	1190	South Park Area - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
John Prince Park	1191	South Park Area - Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1192	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	5	each	\$15,312.50	1
John Prince Park	1193	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	20	each	\$61,250.00	1
John Prince Park	1194	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	16	each	\$49,000.00	1
John Prince Park	1195	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1196	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	15	each	\$45,937.50	1
John Prince Park	1197	South Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1198	South Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
John Prince Park	1199	South Park Area - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	1200	South Park Area - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	1201	South Park Area - Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	10	lin ft	\$592.00	1
John Prince Park	1202	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	4	each	\$12,250.00	1
John Prince Park	1203	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1204	South Park Area - Exterior Accessible Route	Accessible Routes	Provide maintenance to keep EAR to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1205	South Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1206	South Park Area - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1207	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1208	South Park Area - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	12	each	\$36,750.00	1
John Prince Park	1209	South Park Area - Park Elements	Clear Floor Space	Provide required 30" by 48" CFS at operable parts.	\$59.20	12	sq ft	\$710.40	2
John Prince Park	1210	South Park Area - Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
John Prince Park	1211	South Park Area - Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
John Prince Park	1212	South Park Area - Park Elements	Park Site (C)	Relocate element to an accessible route (AR) within the site.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1213	South Park Area - Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1214	South Park Area - Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	25	lin ft	\$1,480.00	4
John Prince Park	1215	South Park Area - Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1216	South Park Area - Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max aff to the spout.	\$2,380.00	1	each	\$2,380.00	2
John Prince Park	1217	South Park Area - Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1218	South Park Area - Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1219	South Park Area - Park Elements	Hazards	Place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1220	South Park Area - Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
John Prince Park	1221	South Park Area - Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
John Prince Park	1222	South Park Area - Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to one more picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4
John Prince Park	1223	South Park Area - Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	1224	South Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects or place cane detectable bollard at foot of item as a smart practice.	\$350.00	24	each	\$8,400.00	5
John Prince Park	1225	South Park Area - Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Move garbage can to be in reach range of the shelter.	\$0.00	1	staff time	\$0.00	5
John Prince Park	1226	South Park Area - Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
John Prince Park	1227	South Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	1228	South Park Area - Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.	\$350.00	2	each	\$700.00	5
John Prince Park	1229	South Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Prince Park	1230	South Park Area - Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects or place cane detectable bollard at foot of item as a smart practice.	\$350.00	22	each	\$7,700.00	5
John Prince Park	1231	South Park Area - Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Lower counter to max 34" AGL and provide knee and toe clearance.	\$1,900.00	1	each	\$1,900.00	2
John Prince Park	1232	South Park Area - Playground Near Smythe Pavilion	Play Area	Repair, bevel or ramp CIL at playground entry/border. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1233	South Park Area - Playground Near Smythe Pavilion	Play Area	Relocate informational signage to be along the AR with a 30" by 48" level CFS for viewing. In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1234	South Park Area - Playground Near Smythe Pavilion	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
John Prince Park	1235	South Park Area - Playground Near Smythe Pavilion	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1236	South Park Area - Playground Near Smythe Pavilion	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1237	South Park Area - Playground Near Smythe Pavilion	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1238	South Park Area - Playground Near Eric Call Pavilion	Play Area	Repair, bevel or ramp CIL at playground entry/border. Cost in resurfacing finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1239	South Park Area - Playground Near Eric Call Pavilion	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
John Prince Park	1240	South Park Area - Playground Near Eric Call Pavilion	Play Area	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same. In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
John Prince Park	1241	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1242	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1243	South Park Area - Playground Near Eric Call Pavilion	Play Area	Lower or adjust entry point to play component to 11" to 24" AGL. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
John Prince Park	1244	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous findings for correction to swings and surface. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1245	South Park Area - Playground Near Eric Call Pavilion	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1246	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
John Prince Park	1247	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
John Prince Park	1248	South Park Area - Playground Near Eric Call Pavilion	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
John Prince Park	1250	South Park Area - Fitness Zone	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
John Prince Park	1252	South Park Area - Building 10 - Women's Restroom	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	2
John Prince Park	1253	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	1254	South Park Area - Building 10 - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1255	South Park Area - Building 10 - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	3	each	\$1,050.00	1
John Prince Park	1256	South Park Area - Building 10 - Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1257	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	1258	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1259	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	1
John Prince Park	1260	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	1261	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	2	each	\$787.50	1
John Prince Park	1262	South Park Area - Building 10 - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1263	South Park Area - Building 10 - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1264	South Park Area - Building 10 - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1265	South Park Area - Building 10 - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
John Prince Park	1266	South Park Area - Building 10 - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	1267	South Park Area - Building 10 - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1268	South Park Area - Building 10 - Men's Restroom	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF. See next finding for cost.	\$0.00	1	each	\$0.00	1
John Prince Park	1269	South Park Area - Building 10 - Men's Restroom	Plumbing Fixtures & Elements	Replace one urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
John Prince Park	1270	South Park Area - Building 10 - Men's Restroom	Plumbing Fixtures & Elements	Assure new urinal flush handle to max 48" AFF. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
John Prince Park	1271	South Park Area - Building 10 - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
John Prince Park	1272	South Park Area - Building 10 - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	1273	South Park Area - Building 10 - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	1
John Prince Park	1274	South Park Area - Building 10 - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	1275	South Park Area - Building 10 - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1276	South Park Area - Building 10 - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
John Prince Park	1277	South Park Area - Building 10 - Men's Restroom	Accessible Routes	Maintain floors to be firm, stable and slip resistant.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1278	South Park Area - Building 10 - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1279	South Park Area - Building 10 - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$2,264.50	1	each	\$2,264.50	1
John Prince Park	1280	South Park Area - Building 10 - Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
John Prince Park	1281	South Park Area - Building 10 - Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
John Prince Park	1282	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1283	South Park Area - Women's Restroom At Eric Call Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1284	South Park Area - Women's Restroom At Eric Call Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1285	South Park Area - Women's Restroom At Eric Call Pavilion	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	2	each	\$700.00	1
John Prince Park	1286	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1287	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1288	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1289	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1290	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1291	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	1292	South Park Area - Women's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1293	South Park Area - Women's Restroom At Eric Call Pavilion	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
John Prince Park	1294	South Park Area - Men's Restroom At Eric Call Pavilion	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$1,846.25	1	each	\$1,846.25	1
John Prince Park	1295	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	2	each	\$700.00	1
John Prince Park	1296	South Park Area - Men's Restroom At Eric Call Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1297	South Park Area - Men's Restroom At Eric Call Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	1298	South Park Area - Men's Restroom At Eric Call Pavilion	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
John Prince Park	1299	South Park Area - Men's Restroom At Eric Call Pavilion	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1300	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1301	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1302	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1303	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1304	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	1305	South Park Area - Men's Restroom At Eric Call Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1306	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
John Prince Park	1307	South Park Area - Women's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
John Prince Park	1308	South Park Area - Women's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	1309	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Relocate soap to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1310	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1311	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1312	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1313	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Priced in previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	each	\$0.00	1
John Prince Park	1314	South Park Area - Women's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
John Prince Park	1315	South Park Area - Women's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1316	South Park Area - Women's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1317	South Park Area - Women's Restroom at Smythe Pavilion	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1318	South Park Area - Women's Restroom at Smythe Pavilion	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
John Prince Park	1319	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
John Prince Park	1320	South Park Area - Men's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. Leave as is 34.25" citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1321	South Park Area - Men's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	1322	South Park Area - Men's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
John Prince Park	1323	South Park Area - Men's Restroom at Smythe Pavilion	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1324	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1325	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1326	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1327	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	1
John Prince Park	1328	South Park Area - Men's Restroom at Smythe Pavilion	Plumbing Fixtures & Elements	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1329	South Park Area - Men's Restroom at Smythe Pavilion	Toilet and Bathing Rooms	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1330	South Park Area - Men's Restroom at Smythe Pavilion	Accessible Routes	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1331	South Park Area - Men's Restroom at Smythe Pavilion	Doors	Correct or repair slope to max 2.08% in restroom.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1332	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	1333	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1334	South Park Area - Women's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1335	South Park Area - Women's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1336	South Park Area - Women's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	1337	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Relocate soap dispenser and sink to provide required 60" clearance around toilet. In the alternative, leave as is sink citing safe harbor.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1338	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1339	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1340	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1341	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1342	South Park Area - Women's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
John Prince Park	1343	South Park Area - Women's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1345	South Park Area - Men's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1346	South Park Area - Men's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1347	South Park Area - Men's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Prince Park	1348	South Park Area - Men's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Remount grab bars in accessible stall to provide 1.5" gap between bar and wall.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
John Prince Park	1349	South Park Area - Men's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1350	South Park Area - Men's Restroom At Commodore Pavilion	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
John Prince Park	1351	South Park Area - Men's Restroom At Commodore Pavilion	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1352	South Park Area - Commodore Pavilion	Clear Floor Space	Correct or repair slope in CFS to max 2.08% as a smart practice.  Maintain surface to be firm and stable.	\$3,062.50	1	each	\$3,062.50	5
John Prince Park	1353	South Park Area - Commodore Pavilion	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	1354	South Park Area - Commodore Pavilion	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.	\$350.00	1	each	\$350.00	2
John Prince Park	1355	South Park Area - Commodore Pavilion	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Fill gaps at door entries to max .5".	\$514.00	1	each	\$514.00	3
John Prince Park	1356	South Park Area - Commodore Pavilion	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
John Prince Park	1357	South Park Area - Commodore Pavilion	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Fill gaps at door entries to max .5".	\$2,868.75	1	each	\$2,868.75	3
John Prince Park	1358	South Park Area - Commodore Pavilion	Accessible Routes	Maintain route where noted and remove obstruction for 36" clear width along the route.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1359	South Park Area - Commodore Pavilion	Clear Floor Space	Provide required 30" by 48" CFS at bike rack.	\$59.20	25	sq ft	\$1,480.00	2
John Prince Park	1360	South Park Area - Building 11 Restrooms -Along Lake Osborne, NE of Square Lake	Custom/Special	If future plans to renovate or rebuild, assure accessibility standards are included in the design.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1362	South Park Area - Parking At Smythe And Granowitz Pavilion	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
John Prince Park	1363	South Park Area - Parking At Smythe And Granowitz Pavilion	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1364	South Park Area - Parking At Smythe And Granowitz Pavilion	Parking - Off Street	Add van parking sign to two accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
John Prince Park	1367	South Park Area - Square Lake West Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
John Prince Park	1368	South Park Area - Square Lake West Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
John Prince Park	1369	South Park Area - Square Lake West Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	4	each	\$385.00	1
John Prince Park	1370	South Park Area - Square Lake West Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	1371	South Park Area - Square Lake Shelter	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
John Prince Park	1372	South Park Area - Square Lake Shelter	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	8	each	\$2,800.00	1
John Prince Park	1373	South Park Area - Square Lake Shelter	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice. Arrange tables to provide 36" clearance around all sides.	\$1,120.00	1	each	\$1,120.00	5
John Prince Park	1374	South Park Area - Square Lake Shelter	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.	\$59.20	70	lin ft	\$4,144.00	5
John Prince Park	1375	South Park Area - Square Lake Playground	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.	\$700.00	1	each	\$700.00	5
John Prince Park	1376	South Park Area - Square Lake Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2
John Prince Park	1377	South Park Area - Square Lake Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
John Prince Park	1378	South Park Area - Square Lake Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
John Prince Park	1379	South Park Area - Square Lake Playground	Play Area	Adjust entry point to play component to 11" to 24" AGL.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1380	South Park Area - Square Lake Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1382	South Park Area - Square Lake Playground	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
John Prince Park	1383	South Park Area - Square Lake Playground	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1385	South Park Area - Petanque Parking Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
John Prince Park	1386	South Park Area - Petanque Parking Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1387	South Park Area - Petanque Parking Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Prince Park	1388	South Park Area - Petanque Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	1	each	\$59.20	1
John Prince Park	1389	South Park Area - Petanque Exterior Accessible Route	Accessible Routes	Provide maintenance on accessible route where deterioration occurs.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1390	South Park Area - Petanque Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	50	sq ft	\$6,125.00	2
John Prince Park	1391	South Park Area - Petanque Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
John Prince Park	1392	South Park Area - Petanque Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1393	South Park Area - Petanque Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
John Prince Park	1394	South Park Area - Petanque Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1395	South Park Area - Petanque Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	26	each	\$79,625.00	1
John Prince Park	1396	South Park Area - Petanque Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	200	sq ft	\$24,500.00	1
John Prince Park	1397	South Park Area - Petanque Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Prince Park	1398	South Park Area - Petanque Playground	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	240	sq ft	\$29,400.00	2
John Prince Park	1399	South Park Area - Petanque Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
John Prince Park	1400	South Park Area - Petanque Playground	Play Area	Correct cross slopes to max 2.08% at playground entry. In the alternative, leave as is and designate other County playgrounds accessible.	\$3,062.50	1	each	\$3,062.50	4
John Prince Park	1401	South Park Area - Petanque Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1402	South Park Area - Petanque Playground	Accessible Routes	Repair, bevel or ramp change in level along accessible route. In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	1	each	\$96.25	4
John Prince Park	1403	South Park Area - Petanque Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
John Prince Park	1404	South Park Area - Petanque Playground	Play Area	Add 1 more GLPC of any type to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
John Prince Park	1405	South Park Area - Petanque Courts	Park Site (C)	Remove sections of 3" barrier to courts to provide access to at least two petanque courts.	\$96.25	2	each	\$192.50	2
John Prince Park	1406	South Park Area - Petanque Courts	Park Site (C)	Provide maintenance at change in surface of accessible route (AR) to each element within the site.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1407	South Park Area - Petanque Area Amenities	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
John Prince Park	1408	South Park Area - Petanque Area Amenities	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5
John Prince Park	1409	South Park Area - Petanque Area Amenities	Accessible Routes	Maintain surface to be firm and stable.	\$59.20	275	lin ft	\$16,280.00	2
John Prince Park	1411	South Park Area - Petanque Area Amenities	Outdoor - Constructed Features (C)	Add fill and maintain surface to be firm and stable.	\$0.00	1	staff time	\$0.00	5
John Prince Park	1412	South Park Area - Petanque Area Amenities	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1413	South Park Area - Petanque Area Amenities	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1414	South Park Area - Petanque Area Amenities	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1415	South Park Area - Petanque Area Amenities	Shelters, Picnic Facilities (C)	Replace picnic table on route with ones of an accessible design. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
John Prince Park	1416	South Park Area - Petanque Area Amenities	Signs	Consider replacing sign with one having contrasting color and on a non-glare surface.	\$210.00	1	each	\$210.00	5
John Prince Park	1417	Men's Restroom At Petanque Court	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
John Prince Park	1418	Men's Restroom At Petanque Court	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1419	Men's Restroom At Petanque Court	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
John Prince Park	1420	Men's Restroom At Petanque Court	Reach Ranges	Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1421	South Park Area - Men's Restroom At Petanque Court	Toilet and Bathing Rooms	Relocate soap and sink to provide required 60" clearance around toilet; leave as is sink if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1422	South Park Area - Men's Restroom At Petanque Court	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1423	South Park Area - Men's Restroom At Petanque Court	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
John Prince Park	1424	South Park Area - Men's Restroom At Petanque Court	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1425	South Park Area - Men's Restroom At Petanque Court	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1426	South Park Area - Men's Restroom At Petanque Court	Doors	Resurface landing to eliminate cracks and gaps in doorway clearance.	\$96.25	1	each	\$96.25	1
John Prince Park	1427	South Park Area - Men's Restroom At Petanque Court	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
John Prince Park	1428	South Park Area - Men's Restroom At Petanque Court	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
John Prince Park	1429	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
John Prince Park	1430	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1431	South Park Area - Women's Restroom At Petanque Court	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1432	South Park Area - Women's Restroom At Petanque Court	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1433	South Park Area - Women's Restroom At Petanque Court	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1434	South Park Area - Women's Restroom At Petanque Court	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1435	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
John Prince Park	1436	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1437	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1438	South Park Area - Women's Restroom At Petanque Court	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
John Prince Park	1439	South Park Area - Women's Restroom At Petanque Court	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
John Prince Park	1440	South Park Area - Women's Restroom At Petanque Court	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1441	South Park Area - Women's Restroom At Petanque Court	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1442	South Park Area - Women's Restroom At Petanque Court	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1444	North Ballfields - Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	7	each	\$514.50	1
John Prince Park	1445	North Ballfields - Parking	Accessible Routes	Install wheels stops at parking stalls along the AR to prevent vehicles from overhanging into the clear width of the accessible route.	\$210.00	3	each	\$630.00	1
John Prince Park	1446	North Ballfields - Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	1447	North Ballfields - Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	10	each	\$962.50	1
John Prince Park	1448	North Ballfields - Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1449	Ballfields - Exterior Accessible Route	Accessible Routes	Provide maintenance to keep loose dirt off field entrance.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1450	Ballfields - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	55	each	\$5,293.75	2
John Prince Park	1451	Ballfields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	2
John Prince Park	1452	Ballfields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	2
John Prince Park	1453	Ballfields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1454	Ballfields - Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
John Prince Park	1455	Ballfields - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1456	Ballfield 2	Accessible Routes	Raise roofline to min 80" for overhead clearance. In the alternative, leave as is and designate other County ball fields accessible.	\$1,500.00	1	each	\$1,500.00	4
John Prince Park	1457	Ballfield 2	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground.  In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
John Prince Park	1458	Ballfield 2	Accessible Routes	Replace surface of dugouts with firm and stable surface. In the alternative, leave as is and designate other County ball fields accessible.	\$500.00	2	each	\$1,000.00	4
John Prince Park	1459	Ballfield 2	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench. In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
John Prince Park	1462	Ballfield 2	Park Site (C)	Provide a second gate entry to dugout and connect to an accessible route (AR). In the alternative, leave as is and designate other County ball fields accessible.	\$2,772.50	2	each	\$5,545.00	4
John Prince Park	1463	Ballfield 3	Doors	For all doors/gates along the public circulation route, remount hardware to 34 inches minimum and 48 inches maximum above the finish floor or ground. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
John Prince Park	1464	Ballfield 3	Accessible Routes	Resurface dugouts with firm and stable surface. In the alternative, leave as is and designate other County ball fields accessible.	\$500.00	2	each	\$1,000.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1465	Ballfield 3	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench. In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
John Prince Park	1466	Ballfield 3	Accessible Routes	Raise dugout roof to min 80", or pad object to prevent hazard in overhead clearance. In the alternative, leave as is and designate other County ball fields accessible.	\$1,500.00	2	each	\$3,000.00	4
John Prince Park	1469	Ballfield 3	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	5	lin ft	\$296.00	4
John Prince Park	1470	Ballfield - Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
John Prince Park	1471	Ballfield - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted between 34" and 48" aff.	\$1,282.75	1	each	\$1,282.75	3
John Prince Park	1472	Ballfield - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" to 48" aff.	\$4,154.50	1	each	\$4,154.50	3
John Prince Park	1473	Ballfield - Employee Spaces	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	120	lin ft	\$7,104.00	3
John Prince Park	1474	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1475	Ballfields - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1476	Ballfields - Women's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1477	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	1478	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	1479	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1480	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1481	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	1482	Ballfields - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1483	Ballfields - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Prince Park	1484	Ballfields - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	1485	Ballfields - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$5,066.25	1	each	\$5,066.25	1
John Prince Park	1486	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
John Prince Park	1487	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
John Prince Park	1488	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1489	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF.	\$1,704.50	1	each	\$1,704.50	1
John Prince Park	1490	Ballfields - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser to max 46" for a forward reach over the sink.	\$0.00	3	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Prince Park	1491	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
John Prince Park	1492	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
John Prince Park	1493	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
John Prince Park	1494	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
John Prince Park	1495	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
John Prince Park	1496	Ballfields - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Prince Park	1497	Ballfields - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
John Prince Park	1498	Ballfields - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
John Prince Park	1499	Ballfields - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
John Prince Park	1500	Ballfields - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Prince Park	1501	Ballfields - Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1502	Ballfields - Elements	Plumbing Fixtures & Elements	Remove or reduce the utility height to provide a forward approach 30" X 48" CFS to the fountain with knee and toe clearance.	\$350.00	1	each	\$350.00	2
John Prince Park	1503	Ballfields - Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$5,598.25	1	each	\$5,598.25	2
John Prince Park	1504	Ballfields - Elements	Operable Parts	Adjust control on drinking fountain to use max 5 lbf to operate.	\$0.00	1	staff time	\$0.00	2
John Prince Park	1505	Ballfields - Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	2
John Stretch Park	1	General Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	3	General Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
John Stretch Park	4	General Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
John Stretch Park	5	Sports Field Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
John Stretch Park	6	Sports Field Parking	Parking - Off Street	Add van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Stretch Park	7	Sports Field Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
John Stretch Park	9	Sports Field Restroom Bldg Parking	Parking - Off Street	Add van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Stretch Park	10	Sports Field Restroom Bldg Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
John Stretch Park	12	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	4	each	\$294.00	1
John Stretch Park	13	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	4	each	\$6,356.00	1
John Stretch Park	14	Shelters 5, 10, 15, 20 Parking Stalls	Accessible Routes	Relocate parking and stripe a no parking zone at entry to AR to prevent cars from blocking AR.	\$210.00	4	each	\$840.00	1
John Stretch Park	15	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Add van parking sign to 1 accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
John Stretch Park	16	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
John Stretch Park	17	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	4	each	\$840.00	1
John Stretch Park	18	Shelters 5, 10, 15, 20 Parking Stalls	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking. Pricing in a previous finding.	\$0.00	1	each	\$0.00	1
John Stretch Park	19	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Stretch Park	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
John Stretch Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	600	sq ft	\$73,500.00	1
John Stretch Park	22	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
John Stretch Park	23	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County basketball courts accessible.	\$59.20	25	lin ft	\$1,480.00	4
John Stretch Park	24	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	600	lin ft	\$35,520.00	2
John Stretch Park	25	Sports Fields/Courts	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	26	Sports Fields/Courts	Outdoor - Constructed Features (C)	Remount water spouts between 28" min and 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
John Stretch Park	27	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
John Stretch Park	28	Park Elements	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$17,760.00	1	each	\$17,760.00	4
John Stretch Park	29	Park Elements	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	6	each	\$6,720.00	4
John Stretch Park	30	Park Elements	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. Pricing provided in a previous finding.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	each	\$0.00	4
John Stretch Park	31	Park Elements	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant grill as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	2	each	\$700.00	4
John Stretch Park	32	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
John Stretch Park	33	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
John Stretch Park	34	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Stretch Park	35	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
John Stretch Park	36	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Stretch Park	37	Shelters	Accessible Routes	Raise roofline to min 80", or pad object to prevent hazard in overhead clearance.	\$1,500.00	1	each	\$1,500.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	38	Shelters	Outdoor Recreation Access Route	<p>Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.</p> <p>Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to trailhead and one of each type of amenity.</p> <p>Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.</p>	\$59.20	15	lin ft	\$888.00	5
John Stretch Park	39	Shelters	Outdoor - Constructed Features (C)	<p>Remount water spouts to 28" min or 36" max above the ground as a smart practice.</p> <p>Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.</p>	\$350.00	2	each	\$700.00	5
John Stretch Park	40	Shelters	Accessible Routes	Raise roofline to min 80", or pad object to prevent hazard in overhead clearance.	\$1,500.00	1	each	\$1,500.00	5
John Stretch Park	41	Shelters	Outdoor Recreation Access Route	<p>Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.</p> <p>Relocate garbage can to be along AR.</p>	\$59.20	8	lin ft	\$473.60	5
John Stretch Park	42	Shelters	Accessible Routes	Raise roofline to min 80", or pad object to prevent hazard in overhead clearance.	\$1,500.00	1	each	\$1,500.00	5
John Stretch Park	43	Shelters	Outdoor Recreation Access Route	<p>Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.</p> <p>Relocate garbage can to be along AR.</p>	\$59.20	15	lin ft	\$888.00	5
John Stretch Park	44	Shelters	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	5
John Stretch Park	45	Shelters	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
John Stretch Park	46	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
John Stretch Park	47	Shelters	Accessible Routes	Raise roofline to min 80", or pad object to prevent hazard in overhead clearance.	\$1,500.00	1	each	\$1,500.00	5
John Stretch Park	48	Shelters	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.	\$59.20	20	lin ft	\$1,184.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	49	Play Area	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
John Stretch Park	50	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
John Stretch Park	54	Pavilion	Picnic Tables (C)	Replace one more picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table.  Provide required 36" clear ground space around all usable portions of the accessible tables as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
John Stretch Park	55	Pavilion	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Relocate 20% of garbage cans to be along AR, with any slopes in CGS at max 2.08%.	\$175.00	2	each	\$350.00	5
John Stretch Park	56	Pavilion	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$2,908.25	2	each	\$5,816.50	3
John Stretch Park	57	Pavilion Men's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Stretch Park	58	Pavilion Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
John Stretch Park	59	Pavilion Men's Restroom	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	1	each	\$1,750.00	1
John Stretch Park	60	Pavilion Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
John Stretch Park	61	Pavilion Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	62	Pavilion Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,500.00	1	each	\$3,500.00	1
John Stretch Park	63	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.  Add mirror to accessible stall, mounted max 40" AFF to the bottom of the reflective surface and min 74" to the top.	\$350.00	2	each	\$700.00	1
John Stretch Park	64	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Stretch Park	65	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under both sinks.	\$77.00	2	each	\$154.00	1
John Stretch Park	66	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Stretch Park	67	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Stretch Park	68	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Stretch Park	69	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
John Stretch Park	70	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Stretch Park	71	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
John Stretch Park	72	Men's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$514.50	1	each	\$514.50	1
John Stretch Park	73	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
John Stretch Park	74	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
John Stretch Park	75	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under both sinks.	\$77.00	2	each	\$154.00	1
John Stretch Park	76	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
John Stretch Park	77	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
John Stretch Park	78	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
John Stretch Park	81	Stretch Pavillion Family Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
John Stretch Park	82	Stretch Pavillion Family Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
John Stretch Park	83	Stretch Pavillion Family Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
John Stretch Park	84	Stretch Pavillion Family Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Stretch Park	85	Stretch Pavillion Family Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
John Stretch Park	86	Stretch Pavillion Family Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
John Stretch Park	87	Stretch Pavillion Family Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Juno Beach Park	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Juno Beach Park	3	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Juno Beach Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	7	each	\$21,437.50	1
Juno Beach Park	5	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	5	each	\$14,000.00	1
Juno Beach Park	6	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Juno Beach Park	7	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Juno Beach Park	8	Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Juno Beach Park	9	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	11	each	\$808.50	1
Juno Beach Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Juno Beach Park	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Juno Beach Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	13	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	7	each	\$2,303.00	1
Juno Beach Park	14	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Juno Beach Park	15	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Juno Beach Park	16	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Beach Park	17	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	10	each	\$962.50	1
Juno Beach Park	18	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Beach Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Juno Beach Park	20	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Beach Park	21	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Juno Beach Park	22	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
Juno Beach Park	23	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	1
Juno Beach Park	25	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	12	staff time	\$0.00	2
Juno Beach Park	26	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Juno Beach Park	27	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Juno Beach Park	29	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Juno Beach Park	30	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.	\$59.20	10	lin ft	\$592.00	5
Juno Beach Park	31	Shelters/Picnic Areas	Accessible Routes	Raise roof to min 80", or pad object to prevent hazard in overhead clearance.	\$1,540.00	1	each	\$1,540.00	3
Juno Beach Park	32	Shelters/Picnic Areas	Picnic Tables (C)	Replace 3 picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	3	each	\$3,360.00	5
Juno Beach Park	33	Pier	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	124	each	\$121,520.00	3
Juno Beach Park	34	Pier	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection. Eliminate the gap created between the existing railing and the concrete pier.	\$525.00	68	each	\$35,700.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	35	Pier	Accessible Routes	Resurface 36" wide portion and clear ground spaces at each lowered section to be free of gaps and CILs.	\$184,000.00	1	each	\$184,000.00	3
Juno Beach Park	36	Pier	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Juno Beach Park	37	Pier	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
Juno Beach Park	38	Pier	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Juno Beach Park	39	Pier	Accessible Routes	Correct or fill gaps to be max .5"; see earlier finding regarding resurfacing of pier.	\$0.00	9	each	\$0.00	1
Juno Beach Park	40	Pier	Dining, Bar and Work Surfaces	Replace or add one work surface max 34" to surface and allowing knee and toe clearance.	\$1,120.00	1	each	\$1,120.00	2
Juno Beach Park	41	Pier	Dining, Bar and Work Surfaces	Replace or add one work surface max 34" to surface and allowing knee and toe clearance.	\$1,120.00	1	each	\$1,120.00	2
Juno Beach Park	42	Pier	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.  Remount operable parts to be in reach range of 15" min to 48" max.	\$210.00	1	each	\$210.00	2
Juno Beach Park	43	Pier	Reach Ranges	Remount opening of fishing line disposal to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Juno Beach Park	44	Pier	Doors	Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Juno Beach Park	45	Pier	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	1	each	\$1,120.00	5
Juno Beach Park	46	Pier	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$5,022.50	1	each	\$5,022.50	1
Juno Beach Park	48	Beach	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	350	lin ft	\$20,720.00	4
Juno Beach Park	49	Beach	Stairways	Install kick plates on all stairs or replace with ones having closed risers. In the alternative, leave as is and designate other County beaches accessible.	\$84.00	20	each	\$1,680.00	4
Juno Beach Park	50	Beach	Stairways	Establish protocols for regular and frequent inspection and maintenance of stairway surfaces. In the alternative, leave as is and designate other County beaches accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	51	Beach	Stairways	<p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p> <p>In the alternative, leave as is and designate other County beaches accessible.</p>	\$125.00	20	each	\$2,500.00	4
Juno Beach Park	52	Beach	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. In the alternative, leave as is and designate other County beaches accessible.</p>	\$980.00	2	each	\$1,960.00	4
Juno Beach Park	53	Beach	Stairways	<p>Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible. In the alternative, leave as is and designate other County beaches accessible.</p>	\$404.25	22	each	\$8,893.50	4
Juno Beach Park	54	Beach	Stairways	<p>Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible. In the alternative, leave as is and designate other County beaches accessible.</p>	\$404.25	22	each	\$8,893.50	4
Juno Beach Park	55	Beach	Stairways	<p>Install kick plates on all stairs or replace with ones having closed risers. In the alternative, leave as is and designate other County beaches accessible.</p>	\$84.00	22	each	\$1,848.00	4
Juno Beach Park	56	Beach	Stairways	<p>Establish protocols for regular and frequent inspection and maintenance of stairway surfaces. In the alternative, leave as is and designate other County beaches accessible.</p>	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	57	Beach	Stairways	<p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p> <p>In the alternative, leave as is and designate other County beaches accessible.</p>	\$125.00	22	each	\$2,750.00	4
Juno Beach Park	58	Beach	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. In the alternative, leave as is and designate other County beaches accessible.</p>	\$980.00	2	each	\$1,960.00	4
Juno Beach Park	59	Men's Restroom	Toilet and Bathing Rooms	<p>Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.</p>	\$350.00	1	each	\$350.00	1
Juno Beach Park	60	Men's Restroom	Plumbing Fixtures & Elements	<p>Lower sinks to max 34" above the finished floor (AFF) to front of rim.</p>	\$2,380.00	1	each	\$2,380.00	1
Juno Beach Park	61	Men's Restroom	Plumbing Fixtures & Elements	<p>Adjust timing of sink faucets to remain on for min. 10 seconds.</p>	\$0.00	1	staff time	\$0.00	1
Juno Beach Park	62	Men's Restroom	Plumbing Fixtures & Elements	<p>Insulate exposed pipes under one sink.</p>	\$77.00	1	each	\$77.00	1
Juno Beach Park	63	Men's Restroom	Plumbing Fixtures & Elements	<p>Lower urinal so that rim height is max 17" AFF.</p>	\$1,704.50	1	each	\$1,704.50	1
Juno Beach Park	64	Men's Restroom	Plumbing Fixtures & Elements	<p>Relocate privacy wall at urinal to provide 30" CFS.</p>	\$420.00	1	each	\$420.00	1
Juno Beach Park	65	Men's Restroom	Reach Ranges	<p>Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.</p>	\$0.00	1	staff time	\$0.00	1
Juno Beach Park	66	Men's Restroom	Toilet and Bathing Rooms	<p>Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.</p>	\$5,510.75	1	each	\$5,510.75	1
Juno Beach Park	67	Men's Restroom	Toilet and Bathing Rooms	<p>Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.</p>	\$2,749.25	1	each	\$2,749.25	1
Juno Beach Park	68	Men's Restroom	Toilet and Bathing Rooms	<p>Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.</p>	\$1,828.40	1	each	\$1,828.40	1
Juno Beach Park	69	Men's Restroom	Toilet and Bathing Rooms	<p>Adjust stall door to be self-closing.</p> <p>Replace stall door hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.</p> <p>Replace lock hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.</p>	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	70	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Juno Beach Park	71	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	2	each	\$787.50	1
Juno Beach Park	72	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Juno Beach Park	73	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Juno Beach Park	74	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,522.50	1	each	\$4,522.50	1
Juno Beach Park	75	Men's Restroom	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
Juno Beach Park	76	Women's Restroom	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
Juno Beach Park	77	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Juno Beach Park	78	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Juno Beach Park	79	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Juno Beach Park	80	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Juno Beach Park	81	Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Juno Beach Park	82	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Juno Beach Park	83	Public Spaces	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	84	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$140.00	1	each	\$140.00	3
Juno Beach Park	85	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p>	\$1,890.00	1	each	\$1,890.00	3
Juno Beach Park	86	Public Spaces	Doors	Mount signage at entrance designating it as accessible.	\$210.00	1	each	\$210.00	3
Juno Beach Park	87	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$0.00	11	staff time	\$0.00	3
Juno Beach Park	88	Public Spaces	Signs	Remount signage at permanent rooms/spaces having Braille and raised characters, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the inactive leaf.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	89	Public Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	2	each	\$420.00	3
Juno Beach Park	90	Employee Spaces	Accessible Routes	Relocate tables and chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	91	Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	92	Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$3,647.20	2	each	\$7,294.40	3
Juno Beach Park	93	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$0.00	5	staff time	\$0.00	3
Juno Beach Park	94	Women's Restroom And Shower	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p>	\$2,772.50	1	each	\$2,772.50	3
Juno Beach Park	95	Women's Restroom And Shower	Doors	<p>Provide required maneuvering clearance around pull side of door.</p> <p>Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.</p>	\$1,750.00	1	each	\$1,750.00	3
Juno Beach Park	96	Women's Restroom And Shower	Dressing / Fitting / Locker Rooms	<p>Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.</p>	\$420.00	1	each	\$420.00	3
Juno Beach Park	97	Women's Restroom And Shower	Dressing / Fitting / Locker Rooms	<p>Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.</p>	\$420.00	1	each	\$420.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	98	Women's Restroom And Shower	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	3
Juno Beach Park	99	Women's Restroom And Shower	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Juno Beach Park	100	Women's Restroom And Shower	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	101	Women's Restroom And Shower	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	3
Juno Beach Park	102	Women's Restroom And Shower	Reach Ranges	Lower hook to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms of paper towel dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	103	Women's Restroom And Shower	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Juno Beach Park	104	Women's Restroom And Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	105	Women's Restroom And Shower	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	3
Juno Beach Park	106	Women's Restroom And Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	107	Women's Restroom And Shower	Accessible Routes	Raise curtain rods to min 80", or pad object to prevent hazard in overhead clearance along AR.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	108	Women's Restroom And Shower	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$233.25	3	each	\$699.75	3
Juno Beach Park	109	Men's Restroom And Shower	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	1	each	\$420.00	3
Juno Beach Park	110	Men's Restroom And Shower	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	3
Juno Beach Park	111	Men's Restroom And Shower	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	3
Juno Beach Park	112	Men's Restroom And Shower	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Juno Beach Park	113	Men's Restroom And Shower	Clear Floor Space	Remove, or relocate hand dryer in CFS at sink.	\$350.00	1	each	\$350.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Beach Park	114	Men's Restroom And Shower	Plumbing Fixtures & Elements	Insulate exposed pipes under one main area sink.	\$77.00	1	each	\$77.00	3
Juno Beach Park	115	Men's Restroom And Shower	Reach Ranges	Remount hook and soap dispenser to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	116	Men's Restroom And Shower	Toilet and Bathing Rooms	Relocate toilet cleaning supplies to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	117	Men's Restroom And Shower	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	3
Juno Beach Park	118	Men's Restroom And Shower	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	3
Juno Beach Park	119	Men's Restroom And Shower	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Juno Beach Park	120	Men's Restroom And Shower	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Juno Beach Park	121	Men's Restroom And Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	122	Men's Restroom And Shower	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	3
Juno Beach Park	123	Men's Restroom And Shower	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	3
Juno Beach Park	124	Men's Restroom And Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Juno Beach Park	125	Men's Restroom And Shower	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	3
Juno Park	1	Parking - Ballfields	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Juno Park	2	Parking - Ballfields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Juno Park	4	Parking - Main	Parking - Off Street	Repaint stalls to be 12' wide (144") each.	\$73.50	1	each	\$73.50	1
Juno Park	5	Parking - Main	Parking - Off Street	Repaint stalls adding one 5' adjacent access aisle, with proper signage and striping.	\$73.50	3	each	\$220.50	1
Juno Park	6	Parking - Main	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Juno Park	7	Parking - Main	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Juno Park	8	Parking - Main	Parking - Off Street	Provide a curb ramp at the head of each access aisle and connect to AR.	\$1,487.50	1	each	\$1,487.50	1
Juno Park	9	Parking - Main	Parking - Off Street	Create one or more 12' accessible boat parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Park	10	Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Juno Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Juno Park	12	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Park	13	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Juno Park	14	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Park	15	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Park	16	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Juno Park	17	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Juno Park	18	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Juno Park	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Juno Park	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Juno Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Juno Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Juno Park	24	Ballfields	Accessible Routes	Replace existing surface of dugouts with an accessible surface such as crushed stone or asphalt with compliant slopes and CILs.  Provide required 36" by 48" CGS at bench.  In the alternative, leave as is and designate other County ball fields accessible.	\$4,430.00	2	each	\$8,860.00	4
Juno Park	25	Ballfields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	225	lin ft	\$13,320.00	4
Juno Park	26	Ballfields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	110	lin ft	\$6,512.00	4
Juno Park	27	Ballfields	Assembly Areas	Repair CIL to cement pad for access. In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	1	each	\$96.25	4
Juno Park	28	Ballfields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	125	lin ft	\$7,400.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Park	29	Ballfields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Juno Park	30	Ballfields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Replace two picnic tables with one of an accessible design as a smart practice.	\$3,520.00	2	each	\$7,040.00	2
Juno Park	32	Ballfields	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$1,470.00	1	each	\$1,470.00	2
Juno Park	33	Concessions	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF. In the alternative, leave as is citing construction tolerance.	\$1,099.00	1	each	\$1,099.00	4
Juno Park	34	Concessions	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Juno Park	35	Concessions	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Juno Park	36	Concessions	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	1
Juno Park	37	Concessions	Custom/Special	Ensure the concession stand complies based on the type of occupants.	\$0.00	1	staff time	\$0.00	1
Juno Park	38	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Juno Park	40	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Juno Park	41	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Juno Park	42	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Juno Park	43	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Relocate garbage can to be along AR.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Park	44	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	2	each	\$4,972.00	4
Juno Park	46	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Replace picnic tables with ones of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$7,272.00	1	each	\$7,272.00	4
Juno Park	47	Boating	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Juno Park	48	Boating	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Park	49	Boating	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Juno Park	50	5-12 Play Area	Play Area	Relocate informational signage to be along the AR with a 30" by 48" level CFS for viewing.	\$0.00	1	staff time	\$0.00	2
Juno Park	51	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Juno Park	52	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Juno Park	53	5-12 Play Area	Play Area	See previous finding recommending surface replacement.	\$0.00	1	each	\$0.00	2
Juno Park	54	Ballfield Restrooms - Men's	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Juno Park	55	Ballfield Restrooms - Men's	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Juno Park	56	Ballfield Restrooms - Men's	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Juno Park	57	Ballfield Restrooms - Men's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Juno Park	58	Ballfield Restrooms - Men's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Park	59	Ballfield Restrooms - Men's	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Juno Park	60	Ballfield Restrooms - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Juno Park	61	Ballfield Restrooms - Men's	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Juno Park	62	Ballfield Restrooms - Women's	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.  Replace mirror in stall and mount to max 40" AFF to the bottom reflective surface and 74" to the top in stall.	\$175.00	2	each	\$350.00	1
Juno Park	63	Ballfield Restrooms - Women's	Plumbing Fixtures & Elements	Lower one sink in main area to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Juno Park	64	Ballfield Restrooms - Women's	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Juno Park	65	Ballfield Restrooms - Women's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Juno Park	66	Ballfield Restrooms - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Juno Park	67	Ballfield Restrooms - Women's	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Juno Park	68	Ballfield Restrooms - Women's	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Juno Park	69	Ballfield Restrooms - Women's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Juno Park	71	Play Area Restrooms - Men's	Doors	Ramp CIL at doorway.	\$6,510.00	1	each	\$6,510.00	1
Juno Park	72	Play Area Restrooms - Men's	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Juno Park	73	Play Area Restrooms - Men's	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and without a symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.  Remount signage to the proper location based on the type of door provided.	\$210.00	1	each	\$210.00	1
Juno Park	74	Play Area Restrooms - Women's	Doors	Ramp CIL at doorway.	\$6,510.00	1	each	\$6,510.00	1
Juno Park	75	Play Area Restrooms - Women's	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Juno Park	76	Play Area Restrooms - Women's	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Juno Park	77	Play Area Restrooms - Unisex	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount locking hardware a min 34" and max 48".	\$3,577.00	1	each	\$3,577.00	1
Juno Park	78	Play Area Restrooms - Unisex	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Juno Park	79	Play Area Restrooms - Unisex	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Juno Park	80	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$238.00	1	each	\$238.00	1
Juno Park	81	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Juno Park	82	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Juno Park	83	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Juno Park	84	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing provided in previous findings.	\$0.00	1	N/A	\$0.00	1
Juno Park	85	Play Area Restrooms - Unisex	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Juno Park	86	Play Area Restrooms - Unisex	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	2	Parking - Lot Across From Picnic Island	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	3	Parking - Lot Across From Picnic Island	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Jupiter Beach Park	4	Parking - Lot Across From Picnic Island	Parking - Off Street	Resurface stalls and access aisles to eliminate deterioration.  Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$96.25	4	each	\$385.00	1
Jupiter Beach Park	5	Parking - Lot Across From Picnic Island	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Jupiter Beach Park	6	Parking - Lot Across From Picnic Island	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	7	Parking - Lot Across From Picnic Island	Parking - Off Street	Provide maintenance to widen accessible route to min 44" clear width and assure connection to access aisle.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	9	Parking - Small Parking Lots At Picnic Areas Along Roadway	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Jupiter Beach Park	10	Parking - Small Parking Lots At Picnic Areas Along Roadway	Parking - Off Street	Resurface stalls and access aisles to eliminate deterioration.	\$2,800.00	1	each	\$2,800.00	1
Jupiter Beach Park	11	Parking - Small Parking Lots At Picnic Areas Along Roadway	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	13	Parking - North Beach Area	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Jupiter Beach Park	14	Parking - North Beach Area	Accessible Routes	Install wheels stops at parking stalls along the AR to prevent vehicles from overhanging into the clear width of the AR.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	15	Parking - North Beach Area	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Jupiter Beach Park	16	Parking - North Beach Area	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.  Correct or fill gaps to max .5".	\$96.25	2	each	\$192.50	1
Jupiter Beach Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Beach Park	18	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	19	Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	20	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	3	each	\$1,575.00	3
Jupiter Beach Park	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Jupiter Beach Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Jupiter Beach Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	200	sq ft	\$24,500.00	1
Jupiter Beach Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	680	sq ft	\$83,300.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	26	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface	\$980.00	2	each	\$1,960.00	1
Jupiter Beach Park	27	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	28	Exterior Accessible Route	Accessible Routes	Install wheels stops at parking stalls along the AR to prevent vehicles from overhanging into the clear width of the AR.	\$210.00	37	each	\$7,770.00	1
Jupiter Beach Park	29	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	1
Jupiter Beach Park	31	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	32	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Jupiter Beach Park	33	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Jupiter Beach Park	34	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Jupiter Beach Park	35	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	5	each	\$481.25	1
Jupiter Beach Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Jupiter Beach Park	37	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	4	each	\$3,920.00	1
Jupiter Beach Park	38	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	4	each	\$1,400.00	1
Jupiter Beach Park	39	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" - 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$0.00	4	each	\$0.00	1
Jupiter Beach Park	40	Exterior Accessible Route	Stairways	Replace handrails with ones have a smooth surface. Pricing provided in a previous finding.	\$0.00	4	each	\$0.00	1
Jupiter Beach Park	41	Exterior Accessible Route	Stairways	Establish protocols for regular and frequent inspection and maintenance of stairway tread surfaces.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Jupiter Beach Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Jupiter Beach Park	45	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	65	sq ft	\$7,962.50	1
Jupiter Beach Park	47	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	48	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Jupiter Beach Park	49	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Jupiter Beach Park	50	Park Elements	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Jupiter Beach Park	51	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Jupiter Beach Park	53	Park Elements	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	56	each	\$54,880.00	2
Jupiter Beach Park	54	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Jupiter Beach Park	55	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Jupiter Beach Park	56	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Jupiter Beach Park	57	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Jupiter Beach Park	58	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Jupiter Beach Park	59	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Jupiter Beach Park	60	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	62	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Jupiter Beach Park	63	Park Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Correct surface of ORAR to be firm and stable, a min 36" wide and having gaps and changes in level of max .5" as a smart practice.	\$3,412.50	1	each	\$3,412.50	5
Jupiter Beach Park	65	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	67	Picnic Areas	Picnic Tables (C)	Replace one more picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table.  Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$3,606.00	1	each	\$3,606.00	4
Jupiter Beach Park	68	Picnic Areas	Shelters, Picnic Facilities (C)	Relocate 20% of garbage cans to be along an accessible route. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Jupiter Beach Park	69	Picnic Areas	Shelters/Picnic Areas (C)	Remount garbage cans to max 48" AFF or provide additional lowered garbage cans. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Jupiter Beach Park	70	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Jupiter Beach Park	71	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Jupiter Beach Park	72	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
Jupiter Beach Park	73	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Jupiter Beach Park	74	Picnic Areas	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	75	Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	5	each	\$12,430.00	5
Jupiter Beach Park	76	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to grill.  Relocate 20% of garbage cans to be along AR.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	5	lin ft	\$296.00	4
Jupiter Beach Park	77	Picnic Areas	Shelters/Picnic Areas (C)	Remount garbage cans to max 48" AFF or provide additional lowered garbage cans. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	2	staff time	\$0.00	4
Jupiter Beach Park	78	Beach Access Route	Beach Access Route (C)	Correct or fill opening along the BAR to be max .5" and travel perpendicular to path of travel as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$96.25	3	each	\$288.75	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	79	Beach Access Route	Beach Access Route (C)	Correct or repair running slopes along the BAR to max 5% for any distance, 8.33% for 50' max or 10% for 30' max as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$122.50	30	sq ft	\$3,675.00	4
Jupiter Beach Park	80	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	300	lin ft	\$17,760.00	4
Jupiter Beach Park	81	Lifeguard Office	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$140.00	1	each	\$140.00	3
Jupiter Beach Park	82	Lifeguard Office	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Jupiter Beach Park	83	Lifeguard Office	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	84	Lifeguard Office	Toilet and Bathing Rooms	Replace mirror and mount to max 35" AFF to the bottom reflective surface and 74" to the top.  Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	85	Lifeguard Office	Plumbing Fixtures & Elements	Relocate storage and shelf to provide clear floor space, knee clearance, and toe clearance at sink.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	86	Lifeguard Office	Toilet and Bathing Rooms	Relocate sink, storage, and water spout to provide required 60" clearance around toilet.	\$2,730.00	1	each	\$2,730.00	3
Jupiter Beach Park	87	Lifeguard Office	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Jupiter Beach Park	88	Lifeguard Office	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	89	Lifeguard Office	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Beach Park	90	Lifeguard Office	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	91	Lifeguard Office	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	92	Lifeguard Office	Accessible Routes	Relocate storage and furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	93	Lifeguard Office	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	94	Lifeguard Office	Hazards	Relocate protruding objects.	\$0.00	1	staff time	\$0.00	3
Jupiter Beach Park	95	Lifeguard Office	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Beach Park	96	Lifeguard Office	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	1	each	\$420.00	3
Jupiter Beach Park	97	Lifeguard Office	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
Jupiter Beach Park	98	Lifeguard Office	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$0.00	1	staff time	\$0.00	3
Jupiter Beach Park	99	Lifeguard Office	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	2
Jupiter Beach Park	100	Lifeguard Office	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Jupiter Beach Park	101	Lifeguard Office	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over toilet.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	102	Picnic Island	Custom/Special	Ensure compliance of these facilities when access to this area is restored.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	103	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3250	sq ft	\$398,125.00	5
Jupiter Beach Park	104	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Jupiter Beach Park	105	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	106	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Jupiter Beach Park	107	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	65	sq ft	\$7,962.50	5
Jupiter Beach Park	108	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Jupiter Beach Park	109	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Jupiter Beach Park	110	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Jupiter Beach Park	111	Portable Restrooms At North Beach Parking	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Jupiter Beach Park	112	North Beach - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Beach Park	113	North Beach - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one main area sink and sink in stall.	\$77.00	2	each	\$154.00	1
Jupiter Beach Park	114	North Beach - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Jupiter Beach Park	115	North Beach - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispensers max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Jupiter Beach Park	116	North Beach - Men's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
Jupiter Beach Park	117	North Beach - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Jupiter Beach Park	117	North Beach - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	118	North Beach - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	119	North Beach - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Beach Park	120	North Beach - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Jupiter Beach Park	121	North Beach - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	122	North Beach - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Beach Park	123	North Beach - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Jupiter Beach Park	124	North Beach - Women's Restroom	Reach Ranges	Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	125	North Beach - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	126	North Beach - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	127	North Beach - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	128	North Beach - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	129	North Beach - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Beach Park	130	North Beach - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount lock hardware to between 15" and 48" AFF.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	131	South Beach - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Jupiter Beach Park	132	South Beach - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	133	South Beach - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Jupiter Beach Park	134	South Beach - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Beach Park	135	South Beach - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Jupiter Beach Park	136	South Beach - Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF.	\$1,704.50	1	each	\$1,704.50	1
Jupiter Beach Park	137	South Beach - Men's Restroom	Reach Ranges	Lower hand dryer to max 48" above the finished floor (AFF) to highest operable part.  Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	138	South Beach - Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Jupiter Beach Park	139	South Beach - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	140	South Beach - Men's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Beach Park	141	South Beach - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Beach Park	142	South Beach - Men's Restroom	Toilet and Bathing Rooms	Replace grab bars with ones having 1.5" space between the bar and adjacent surface. Pricing provided in previous findings.	\$0.00	2	each	\$0.00	1
Jupiter Beach Park	143	South Beach - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Jupiter Beach Park	144	South Beach - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, on the wall with the side grab bar, mounted 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	145	South Beach - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	146	South Beach - Men's Restroom	Reach Ranges	Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	147	South Beach - Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Jupiter Beach Park	148	South Beach - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	149	South Beach - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Jupiter Beach Park	150	South Beach - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Beach Park	151	South Beach - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	152	South Beach - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Jupiter Beach Park	153	South Beach - Women's Restroom	Reach Ranges	Lower hand dryer to max 48" above the finished floor (AFF) to highest operable part. Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	2	each	\$700.00	1
Jupiter Beach Park	154	South Beach - Women's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Jupiter Beach Park	155	South Beach - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Beach Park	156	South Beach - Women's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Beach Park	157	South Beach - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Beach Park	158	South Beach - Women's Restroom	Toilet and Bathing Rooms	Replace grab bars with ones having 1.5" space between the bar and adjacent surface. Pricing provided in previous findings.	\$0.00	2	each	\$0.00	1
Jupiter Beach Park	159	South Beach - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Jupiter Beach Park	160	South Beach - Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Jupiter Beach Park	161	South Beach - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Beach Park	162	South Beach - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jupiter Beach Park	163	South Beach - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
Jupiter Farms Park	2	Parking - Multi-purpose Fields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Jupiter Farms Park	3	Parking - Multi-purpose Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Jupiter Farms Park	5	Parking - Equestrian Lot	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	2	each	\$147.00	1
Jupiter Farms Park	6	Parking - Equestrian Lot	Parking - Off Street	Repaint access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Jupiter Farms Park	8	Parking - Ball Fields	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	2	each	\$147.00	1
Jupiter Farms Park	9	Parking - Ball Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Jupiter Farms Park	10	Parking - Ball Fields	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	4	each	\$11,200.00	1
Jupiter Farms Park	11	Parking - Ball Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	13	Parking - Pavilion	Parking - Off Street	Repaint access aisle to be 5' each.	\$73.50	1	each	\$73.50	1
Jupiter Farms Park	14	Parking - Pavilion	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Jupiter Farms Park	15	Exterior Accessible Route - Community Pavilion	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	20	each	\$1,925.00	1
Jupiter Farms Park	16	Exterior Accessible Route - Community Pavilion	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	17	Exterior Accessible Route - Community Pavilion	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
Jupiter Farms Park	18	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Jupiter Farms Park	19	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	20	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	21	Exterior Accessible Route - General	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
Jupiter Farms Park	22	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Jupiter Farms Park	23	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	350	sq ft	\$42,875.00	1
Jupiter Farms Park	24	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	140	sq ft	\$17,150.00	1
Jupiter Farms Park	25	Exterior Accessible Route - General	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	35	sq ft	\$4,287.50	1
Jupiter Farms Park	27	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	500	lin ft	\$29,600.00	4
Jupiter Farms Park	28	Sports Fields/Courts	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Jupiter Farms Park	30	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Provide a 36" by 48" clear ground space for wheelchair seating adjacent to team bench in dugout.  In the alternative, leave as is and designate other County ball fields accessible.	\$1,040.00	1	each	\$1,040.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	33	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Provide a 36" by 48" clear ground space for wheelchair seating adjacent to team bench in dugout.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,040.00	1	each	\$1,040.00	4
Jupiter Farms Park	34	Sports Fields/Courts	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	35	Sports Fields/Courts	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	36	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Provide a 36" by 48" clear ground space for wheelchair seating adjacent to team bench in dugout.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,040.00	1	each	\$1,040.00	4
Jupiter Farms Park	37	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	90	lin ft	\$5,328.00	1
Jupiter Farms Park	38	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to bench.	\$59.20	80	lin ft	\$4,736.00	5
Jupiter Farms Park	42	Community Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Jupiter Farms Park	43	Community Pavilion	Outdoor - Constructed Features (C)	Lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	5
Jupiter Farms Park	44	Community Pavilion	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Jupiter Farms Park	45	Community Pavilion	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	46	Community Pavilion	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	47	Community Pavilion	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Farms Park	48	Community Pavilion	Reach Ranges	Relocate stored items on freezer to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	49	Community Pavilion	Reach Ranges	Relocate items on cabinet to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	50	Community Pavilion	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	51	Community Pavilion	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$2,772.00	1	each	\$2,772.00	1
Jupiter Farms Park	52	Community Pavilion	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	53	Community Pavilion	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Jupiter Farms Park	54	Community Pavilion	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Jupiter Farms Park	55	Press Box/Concession	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$96.25	1	each	\$96.25	3
Jupiter Farms Park	56	Press Box/Concession	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Jupiter Farms Park	57	Press Box/Concession	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Jupiter Farms Park	58	Press Box/Concession	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Jupiter Farms Park	59	Press Box/Concession	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	60	Press Box/Concession	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jupiter Farms Park	61	Press Box/Concession	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Jupiter Farms Park	62	Press Box/Concession	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Jupiter Farms Park	63	Press Box/Concession	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	16	each	\$2,000.00	5
Jupiter Farms Park	65	Press Box/Concession	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Jupiter Farms Park	66	Press Box/Concession	Clear Floor Space	Provide required 30" by 48" CFS at operable parts or install outlets that are in reach range.	\$350.00	1	each	\$350.00	3
Jupiter Farms Park	67	Press Box/Concession	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Jupiter Farms Park	69	Equestrian Facilities	Outdoor Recreation Access Routes (C)	Provide a firm and stable route to the tables and info sign.  Replace one picnic table with one of an accessible design as a smart practice.	\$2,780.00	2	each	\$5,560.00	5
Jupiter Farms Park	71	Equestrian Facilities	Signs	Replace sign with one having contrasting color and on a non-glare surface.	\$210.00	1	each	\$210.00	5
Jupiter Farms Park	72	Equestrian Facilities	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	73	Equestrian Facilities	Assembly Areas	Relocate wheelchair seating to location that does not block the accessible route or widen pad to allow for parking and route.	\$350.00	1	each	\$350.00	2
Jupiter Farms Park	74	Equestrian Facilities	Assembly Areas	See previous finding for recommendation.	\$898.75	2	each	\$1,797.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	75	Equestrian Facilities	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Jupiter Farms Park	76	Equestrian Facilities	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	200	lin ft	\$11,840.00	2
Jupiter Farms Park	77	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Jupiter Farms Park	78	Playground	Play Area	Raise platform on transfer system to 11" to 18" AGL, in the alternative, remove and maintain surface fill level to achieve the same.	\$0.00	1	staff time	\$0.00	2
Jupiter Farms Park	79	Playground	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Jupiter Farms Park	80	Playground	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Jupiter Farms Park	81	Playground	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Jupiter Farms Park	82	Men's Restroom - Ballfield	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Jupiter Farms Park	83	Men's Restroom - Ballfield	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Jupiter Farms Park	84	Men's Restroom - Ballfield	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	85	Men's Restroom - Ballfield	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Jupiter Farms Park	86	Men's Restroom - Ballfield	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.  Remount stall door so it does not obstruct the clear floor space of the accessible urinal; in the alternative, relocate accessible urinal.	\$420.00	2	each	\$840.00	1
Jupiter Farms Park	87	Men's Restroom - Ballfield	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Farms Park	88	Men's Restroom - Ballfield	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Jupiter Farms Park	89	Men's Restroom - Ballfield	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	90	Men's Restroom - Ballfield	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jupiter Farms Park	91	Men's Restroom - Ballfield	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Jupiter Farms Park	92	Women's Restroom - Ballfield	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Jupiter Farms Park	93	Women's Restroom - Ballfield	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	94	Women's Restroom - Ballfield	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Jupiter Farms Park	95	Women's Restroom - Ballfield	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	96	Women's Restroom - Ballfield	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Jupiter Farms Park	97	Women's Restroom - Ballfield	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	98	Women's Restroom - Ballfield	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Jupiter Farms Park	99	Women's Restroom - Ballfield	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Jupiter Farms Park	100	Unisex Restroom - Pavilion	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	3	each	\$288.75	1
Jupiter Farms Park	101	Unisex Restroom - Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	102	Unisex Restroom - Pavilion	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$350.00	1	each	\$350.00	1
Jupiter Farms Park	103	Unisex Restroom - Pavilion	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	104	All-Gender Restroom - Pavilion	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	2	each	\$192.50	1
Jupiter Farms Park	105	All-Gender Restroom - Pavilion	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	106	All-Gender Restroom - Pavilion	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	107	All-Gender Restroom - Pavilion	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	108	All-Gender Restroom - Pavilion	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$350.00	1	each	\$350.00	1
Jupiter Farms Park	109	All-Gender Restroom - Pavilion	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Jupiter Farms Park	110	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Fill gaps at door entries to max .5".</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$6,431.25	1	each	\$6,431.25	3
Jupiter Farms Park	111	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Repair, provide beveled threshold.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$768.25	1	each	\$768.25	3
Jupiter Farms Park	112	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p>	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Jupiter Farms Park	113	Caretaker's House	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,769.50	1	each	\$3,769.50	3
Kennedy Estates Park	1	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Kennedy Estates Park	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Kennedy Estates Park	3	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Kennedy Estates Park	4	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Kennedy Estates Park	5	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Kennedy Estates Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Kennedy Estates Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Kennedy Estates Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Kennedy Estates Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Kennedy Estates Park	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Kennedy Estates Park	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Kennedy Estates Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Kennedy Estates Park	13	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	20	lin ft	\$1,184.00	1
Kennedy Estates Park	14	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	10	lin ft	\$592.00	1
Kennedy Estates Park	17	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Kennedy Estates Park	18	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	6	lin ft	\$355.20	2
Kennedy Estates Park	19	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$96.25	1	each	\$96.25	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Kennedy Estates Park	20	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$96.25	1	each	\$96.25	4
Kennedy Estates Park	21	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$1,120.00	1	each	\$1,120.00	4
Kennedy Estates Park	22	5-12 Play Area	Play Area	Create designated entry as a smart practice.	\$700.00	1	each	\$700.00	5
Kennedy Estates Park	23	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Kennedy Estates Park	24	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Kennedy Estates Park	25	5-12 Play Area	Play Area	Raise platform on transfer system to 11" to 18" AFF, in the alternative, remove and maintain surface fill level to achieve the same.	\$0.00	1	staff time	\$0.00	2
<u>Kenwood Park</u>	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Kenwood Park	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Kenwood Park	3	Play Area	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Kenwood Park	4	Play Area	Play Area	Relocate informational signage to be along the AR with a 30" by 48" level CFS for viewing.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Kenwood Park	5	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Kenwood Park	9	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
<u>Lake Belvedere Estates Park</u>	1	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Belvedere Estates Park	2	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	25	sq ft	\$3,062.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Belvedere Estates Park	3	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	150	lin ft	\$8,880.00	2
Lake Belvedere Estates Park	4	Play Area, 5-12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Lake Belvedere Estates Park	5	Play Area, 5-12	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Lake Belvedere Estates Park	8	Play Area, 5-12	Play Area	Add 1 more GLPC of a type other than interactive or swings to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Lake Charleston Park	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Lake Charleston Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Lake Charleston Park	3	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Lake Charleston Park	4	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Charleston Park	5	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Charleston Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	210	sq ft	\$25,725.00	1
Lake Charleston Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	830	sq ft	\$101,675.00	1
Lake Charleston Park	8	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Charleston Park	9	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Lake Charleston Park	10	Sports Fields/Courts	Park Site (C)	Construct firm, stable, and slip resistant level pad at least 36" by 48" adjacent to each player bench.  In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	8	each	\$6,720.00	4
Lake Charleston Park	11	Sports Fields/Courts	Accessible Routes	Raise dugout roof to min 80", or pad object to prevent hazard in overhead clearance.  In the alternative, leave as is and designate other County ball fields accessible.	\$1,540.00	8	each	\$12,320.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Charleston Park	12	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	1850	lin ft	\$109,520.00	4
Lake Charleston Park	13	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. Pricing provided in a previous finding for lack of route to ballfields and amenities.  In the alternative, leave as is and designate other County ball field facilities accessible.	\$0.00	1	staff time	\$0.00	4
Lake Charleston Park	14	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	80	lin ft	\$4,736.00	1
Lake Charleston Park	15	Park Elements	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.  Pricing for adding a route to and CGS at concession stand counter provided in a previous finding.	\$1,099.00	1	each	\$1,099.00	2
Lake Charleston Park	16	Park Elements	Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.  Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	2
Lake Charleston Park	17	Park Elements	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Lake Charleston Park	18	Park Elements	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48".  Provide method to enter nets without requiring tight pinch or grasp.	\$864.50	1	each	\$864.50	2
Lake Charleston Park	19	Park Elements	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,517.75	1	each	\$5,517.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Charleston Park	20	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons or raise one of the fountains so spigot is 38" minimum and 43" maximum.	\$2,380.00	1	each	\$2,380.00	2
Lake Charleston Park	21	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4" at lowered bowl.	\$420.00	1	each	\$420.00	2
Lake Charleston Park	22	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	2
Lake Charleston Park	23	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Lake Charleston Park	24	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	30	lin ft	\$1,776.00	2
Lake Charleston Park	25	Park Elements	Park Site (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Lake Charleston Park	26	Men's Restroom	Toilet and Bathing Rooms	Rotate and lower mirror in stall so bottom reflective surface is max 40" AFF and 74" at the top.  Install mirror in main area and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Charleston Park	27	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in accessible stall.	\$77.00	2	each	\$154.00	1
Lake Charleston Park	28	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Charleston Park	29	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Lake Charleston Park	30	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$393.75	1	each	\$393.75	1
Lake Charleston Park	31	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF. In the alternative, leave as is if sink meets safe harbor.	\$393.75	1	each	\$393.75	1
Lake Charleston Park	32	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Charleston Park	33	Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Lake Charleston Park	34	Men's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
Lake Charleston Park	35	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Charleston Park	36	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Charleston Park	37	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Charleston Park	38	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Charleston Park	39	Men's Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,062.50	1	each	\$3,062.50	1
Lake Charleston Park	40	Women's Restroom	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
Lake Charleston Park	41	Women's Restroom	Toilet and Bathing Rooms	Install and mount mirror in main area to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Charleston Park	42	Women's Restroom	Plumbing Fixtures & Elements	Lower sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Lake Charleston Park	43	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Lake Charleston Park	44	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Charleston Park	45	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Lake Charleston Park	46	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Charleston Park	47	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF. In the alternative, leave as is if sink meets safe harbor.	\$393.75	1	each	\$393.75	1
Lake Charleston Park	48	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Charleston Park	49	Women's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width.	\$2,749.25	1	each	\$2,749.25	1
Lake Charleston Park	50	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Charleston Park	51	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Charleston Park	52	Playground	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1
Lake Charleston Park	53	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Charleston Park	54	Playground	Accessible Routes	Repair or reset tiles to eliminate change in level.	\$28.00	50	sq ft	\$1,400.00	1
Lake Ida East Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each and extending the full length of the accessible stall.	\$73.50	1	each	\$73.50	1
Lake Ida East Park	3	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Ida East Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Lake Ida East Park	5	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate deterioration.	\$2,800.00	1	each	\$2,800.00	1
Lake Ida East Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida East Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	1
Lake Ida East Park	8	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	60	sq ft	\$7,350.00	5
Lake Ida East Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Lake Ida East Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	1
Lake Ida East Park	11	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
Lake Ida East Park	12	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County sand volleyball courts accessible.	\$59.20	5	lin ft	\$296.00	4
Lake Ida East Park	13	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	1
Lake Ida East Park	15	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Ida East Park	16	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
Lake Ida East Park	17	Park Elements	Plumbing Fixtures & Elements	Reroute plumbing to provide required knee clearance.	\$350.00	1	each	\$350.00	2
Lake Ida East Park	18	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Ida East Park	19	Shelters and Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$59.20	5	lin ft	\$296.00	4
Lake Ida East Park	20	Shelters and Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$2,486.00	1	each	\$2,486.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida East Park	21	Shelters and Picnic Areas	Outdoor - Constructed Features (C)	Correct surface at picnic table to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$122.50	25	sq ft	\$3,062.50	4
Lake Ida East Park	22	Shelters and Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  In the alternative, leave as is and designate other County picnic areas accessible.	\$59.20	5	lin ft	\$296.00	4
Lake Ida East Park	23	Shelters and Picnic Areas	Outdoor - Constructed Features (C)	Correct surface at picnic to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$122.50	25	sq ft	\$3,062.50	4
Lake Ida East Park	24	Shelters and Picnic Areas	Outdoor - Constructed Features (C)	Repair or correct slope of clear space to max 2.08% in any direction for fire ring, grill, fireplace, or woodstove as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$122.50	25	sq ft	\$3,062.50	4
Lake Ida East Park	25	Shelters and Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  In the alternative, leave as is and designate other County picnic areas accessible.	\$59.20	15	lin ft	\$888.00	4
Lake Ida East Park	26	Shelters and Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$96.25	4	each	\$385.00	4
Lake Ida East Park	27	Shelters and Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida East Park	28	Shelters and Picnic Areas	Shelters/Picnic Areas (C)	<p>Replace existing amenities with ones of an accessible design and provide required clear ground space.</p> <p>Remount one outlet to be in reach range of 15" min to 48" max.</p> <p>Replace or lower one grill to max height of cooking surface 34".</p> <p>In the alternative, leave as is and designate other County shelters accessible.</p>	\$300.00	2	each	\$600.00	4
Lake Ida East Park	29	Lake Front	Fishing Piers And Platforms	<p>Lower 25% of the railing; dispersed through pier, to max 34".</p> <p>In the alternative, leave as is and designate other County fishing areas accessible.</p>	\$980.00	8	each	\$7,840.00	4
Lake Ida East Park	30	5-12 Play Area	Play Area	<p>Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$7,000.00	1	each	\$7,000.00	4
Lake Ida East Park	31	5-12 Play Area	Play Area	<p>Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70,000.00	1	each	\$70,000.00	4
Lake Ida East Park	32	5-12 Play Area	Play Area	<p>Consider adding a second transfer system as a smart practice.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$4,970.00	1	each	\$4,970.00	4
Lake Ida East Park	33	5-12 Play Area	Play Area	<p>Lower platform on transfer system to 11" to 18" AFF, in the alternative, add and maintain surface fill level to achieve the same.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$0.00	1	staff time	\$0.00	4
Lake Ida East Park	34	5-12 Play Area	Play Area	<p>See previous finding for surface correction.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$0.00	1	each	\$0.00	4
Lake Ida East Park	35	5-12 Play Area	Play Area	<p>Add one more climber to meet one of each type accessible.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$2,800.00	1	each	\$2,800.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida East Park	36	5-12 Play Area	Play Area	See previous finding for surface correction.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Ida East Park	37	Men's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Lake Ida East Park	38	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Lake Ida East Park	39	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Lake Ida East Park	40	Men's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Ida East Park	41	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Lake Ida East Park	42	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Ida East Park	43	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$262.50	3	each	\$787.50	1
Lake Ida East Park	44	Men's Restroom	Toilet and Bathing Rooms	Replace stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida East Park	45	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida East Park	46	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Ida East Park	47	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida East Park	48	Men's Restroom	Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds.	\$253.75	1	each	\$253.75	1
Lake Ida East Park	49	Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Lake Ida East Park	50	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Ida East Park	51	Women's Restroom	Toilet and Bathing Rooms	Ensure a compliant sink in wheelchair accessible toilet stall is present unless doing so would reduce the required clearance at the toilet.	\$0.00	1	staff time	\$0.00	1
Lake Ida East Park	52	Women's Restroom	Toilet and Bathing Rooms	Ensure a wheelchair accessible stall is present with grab bars and fixtures mounted in correct locations and at correct heights.	\$0.00	1	staff time	\$0.00	1
Lake Ida East Park	53	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida East Park	54	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida East Park	55	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	1
Lake Ida East Park	56	Maintenance Building	Custom/Special	Ensure compliance of building once renovated and reopened.	\$0.00	1	staff time	\$0.00	3
Lake Ida East Park	57	Maintenance Building	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	3
Lake Ida East Park	58	Maintenance Building	Room/Space (C)	Replace with doors/gates having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".	\$3,157.50	1	each	\$3,157.50	3
Lake Ida East Park	59	Maintenance Building	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.	\$59.20	75	lin ft	\$4,440.00	3
Lake Ida East Park	60	Maintenance Building	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".	\$481.25	1	each	\$481.25	3
Lake Ida West Park	2	Parking - Dog Park	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	3	Parking - Dog Park	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Lake Ida West Park	4	Parking - Dog Park	Parking - Off Street	Correct or fill gaps to max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	5	Parking - On Street Parking Spaces Near Dog Park	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls and locate these stalls near an accessible route; in the alternative, add two more accessible stalls to the adjacent parking lot.	\$1,589.00	2	each	\$3,178.00	1
Lake Ida West Park	7	Parking - North Lot	Parking - Off Street	Relocate stalls to be on the shortest accessible route to the building entry or park features.	\$367.50	2	each	\$735.00	1
Lake Ida West Park	8	Parking - North Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	9	Parking - North Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	10	Parking - North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Lake Ida West Park	11	Parking - North Lot	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	13	Parking - Play Area	Parking - Off Street	Relocate stalls to be on the shortest accessible route to the building entry or park features.	\$367.50	1	each	\$367.50	1
Lake Ida West Park	14	Parking - Play Area	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Lake Ida West Park	15	Parking - Play Area	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Lake Ida West Park	16	Parking - Play Area	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Lake Ida West Park	17	Parking - Boat Ramp	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Lake Ida West Park	18	Parking - Lot by Wood Bridge	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Lake Ida West Park	19	Parking - Lot by Wood Bridge	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	20	Parking - Lot by Wood Bridge	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Lake Ida West Park	22	Parking - South Lot w/ Shelters	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Lake Ida West Park	23	Parking - South Lot w/ Shelters	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Lake Ida West Park	24	Parking - South Lot w/ Shelters	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Lake Ida West Park	25	Parking - South Lot w/ Shelters	Parking - Off Street	Resurface stalls and access aisles to eliminate deterioration, gaps, and cracks.	\$2,800.00	2	each	\$5,600.00	1
Lake Ida West Park	26	Parking - South Lot w/ Shelters	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	4	each	\$294.00	1
Lake Ida West Park	28	Parking - Heron Pavilion	Parking - Off Street	Relocate stalls to be on the shortest accessible route to the building entry or park features.	\$367.50	2	each	\$735.00	1
Lake Ida West Park	29	Parking - Heron Pavilion	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	30	Parking - Heron Pavilion	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	31	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Lake Ida West Park	32	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	33	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	2	each	\$1,750.00	3
Lake Ida West Park	34	Exterior Accessible Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	3
Lake Ida West Park	35	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Lake Ida West Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
Lake Ida West Park	37	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	250	sq ft	\$30,625.00	1
Lake Ida West Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Lake Ida West Park	39	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Ida West Park	40	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Ida West Park	41	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	42	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	46	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Lake Ida West Park	47	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Lake Ida West Park	48	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	49	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	50	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	51	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Ida West Park	52	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Ida West Park	53	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Lake Ida West Park	54	Exterior Accessible Route	Ramps (Not Curb Ramps)	Upon corrections to top landing and gate maneuvering clearance, replace handrails with ones that are continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	2
Lake Ida West Park	55	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Lake Ida West Park	56	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Lake Ida West Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	62	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Ida West Park	63	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Ida West Park	64	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Ida West Park	65	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	66	Park Elements	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth	\$1,225.00	1	each	\$1,225.00	2
Lake Ida West Park	67	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Ida West Park	68	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Lake Ida West Park	69	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Lake Ida West Park	70	Shelters	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$467.25	1	each	\$467.25	4
Lake Ida West Park	71	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	6	each	\$2,100.00	5
Lake Ida West Park	72	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	2	each	\$192.50	4
Lake Ida West Park	73	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	32	each	\$11,200.00	4
Lake Ida West Park	74	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	2	each	\$700.00	4
Lake Ida West Park	75	Shelters	Picnic Tables (C)	Replace one more picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Lake Ida West Park	76	Shelters	Outdoor - Constructed Features (C)	Correct surface at water spout to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$122.50	25	sq ft	\$3,062.50	4
Lake Ida West Park	77	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	78	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	12	each	\$4,200.00	5
Lake Ida West Park	79	Shelters	Shelters, Picnic Facilities (C)	Extend an accessible route to features and elements in the shelter or picnic area as a smart practice.  Ensure water spout is mounted 28" min to 36" max above the ground as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	80	Shelters	Shelters, Picnic Facilities (C)	Resurface shelter to eliminate pooling water and deterioration.	\$122.50	75	sq ft	\$9,187.50	5
Lake Ida West Park	81	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	82	Shelters	Shelters, Picnic Facilities (C)	Extend an accessible route to features and elements in the shelter or picnic area as a smart practice.	\$59.20	15	lin ft	\$888.00	5
Lake Ida West Park	83	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	84	Shelters	Shelters, Picnic Facilities (C)	Extend an accessible route to features and elements in the shelter or picnic area as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Lake Ida West Park	85	Boat Ramps	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice	\$950.00	1	each	\$950.00	5
Lake Ida West Park	86	Boat Ramps	Outdoor - Constructed Features (C)	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Lake Ida West Park	87	Boat Ramps	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Lake Ida West Park	88	Boat Ramps	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	4	each	\$12,250.00	2
Lake Ida West Park	89	Boat Ramps	Clear Floor Space	Relocate garbage can to be along AR with level CGS at max 2.08%, with the garbage can rim 15" to 48" AGL.	\$0.00	1	staff time	\$0.00	2
Lake Ida West Park	90	Pier	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	6	each	\$5,880.00	4
Lake Ida West Park	91	Pier	Fishing Piers And Platforms	Provide level CFS at lowered portions of rail on the pier. In the alternative, leave as is and designate other County fishing areas accessible.	\$875.00	6	each	\$5,250.00	4
Lake Ida West Park	92	Pier	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	15	each	\$14,700.00	2
Lake Ida West Park	93	Pier	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection.	\$525.00	2	each	\$1,050.00	2
Lake Ida West Park	95	Barrier-Free Play Area, 2-5	Play Area	For children age 3 to 4, raise/lower the play component to min 20" and max 36".  For children age 5 to 8, raise/lower the play component to min 18" and max 40".	\$350.00	3	each	\$1,050.00	5
Lake Ida West Park	97	Barrier-Free Play Area, 2-5	Play Area	Remount handrails along both sides of ramp at 20" to 28" AFF.	\$350.00	4	each	\$1,400.00	2
Lake Ida West Park	98	Barrier-Free Play Area, 2-5	Play Area	Repair or correct slope of play area accessible surface to max 6.25%.	\$3,062.50	1	each	\$3,062.50	2
Lake Ida West Park	99	Barrier-Free Play Area, 2-5	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps as a smart practice.	\$700.00	1	each	\$700.00	5
Lake Ida West Park	100	Barrier-Free Play Area 5-12	Play Area	Consider adding a second transfer system as a smart practice.	\$4,970.00	1	each	\$4,970.00	5
Lake Ida West Park	101	Barrier-Free Play Area 5-12	Play Area	Remount handrails along both sides of ramp at 20" to 28" AFF.	\$350.00	2	each	\$700.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	102	Barrier-Free Play Area 5-12	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%.	\$1,015.00	3	each	\$3,045.00	2
Lake Ida West Park	105	GLPC-only Play Area	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Lake Ida West Park	106	GLPC-only Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Lake Ida West Park	107	GLPC-only Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	100	sq ft	\$7,000.00	4
Lake Ida West Park	108	GLPC-only Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Ida West Park	109	GLPC-only Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Lake Ida West Park	111	Large Dog Area - North	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp between 34" minimum and 48" maximum above the finish floor or ground.	\$6,989.50	1	each	\$6,989.50	1
Lake Ida West Park	112	Large Dog Area - North	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	675	sq ft	\$82,687.50	5
Lake Ida West Park	113	Large Dog Area - North	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Lake Ida West Park	114	Large Dog Area - North	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Lake Ida West Park	115	Large Dog Area - North	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Lake Ida West Park	116	Large Dog Area - North	Accessible Routes	Relocate dog-waste bag dispenser to be along accessible route.	\$0.00	1	staff time	\$0.00	5
Lake Ida West Park	117	Large Dog Area - North	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Lake Ida West Park	118	Large Dog Area - North	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	119	Large Dog Area - North	Reach Ranges	Relocate dog-waste bag dispensers to be along AR, and remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	121	Large Dog Area - North	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable with one hand and without a tight pinch or grasp.	\$4,091.50	1	each	\$4,091.50	1
Lake Ida West Park	122	Large Dog Area - North	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Lake Ida West Park	123	Large Dog Area - South	Outdoor - Constructed Features (C)	Correct clear ground space at bench to have max slope of 2.08% in any direction.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	124	Large Dog Area - South	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Lake Ida West Park	125	Large Dog Area - South	Plumbing Fixtures & Elements	Correct clear ground space at fountain to have max slope of 2.08% in any direction.	\$122.50	25	sq ft	\$3,062.50	2
Lake Ida West Park	126	Large Dog Area - South	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
Lake Ida West Park	127	Large Dog Area - South	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Lake Ida West Park	129	Large Dog Area - South	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	130	Large Dog Area - South	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	5
Lake Ida West Park	131	Large Dog Area - South	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
Lake Ida West Park	132	Large Dog Area - South	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,264.50	1	each	\$2,264.50	1
Lake Ida West Park	133	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
Lake Ida West Park	134	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	135	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Lake Ida West Park	136	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	137	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	138	Small Dog Area	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	139	Small Dog Area	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Lake Ida West Park	140	Small Dog Area	Clear Floor Space	Correct or repair slope to max 2.08% in any direction for level CGS.	\$122.50	25	sq ft	\$3,062.50	2
Lake Ida West Park	141	Small Dog Area	Outdoor - Constructed Features (C)	Relocate 20% of garbage cans and dog bag dispenser to be along the route and within 15" to 48" AFF.	\$0.00	1	staff time	\$0.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	143	Small Dog Area	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	5
Lake Ida West Park	144	Communal Dog Park Spaces	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	5
Lake Ida West Park	145	Communal Dog Park Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	5
Lake Ida West Park	146	Communal Dog Park Spaces	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable with one hand and without a tight pinch or grasp.	\$3,609.00	3	each	\$10,827.00	1
Lake Ida West Park	147	Communal Dog Park Spaces	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	148	Communal Dog Park Spaces	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable with one hand without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	1
Lake Ida West Park	149	Communal Dog Park Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Ida West Park	150	Communal Dog Park Spaces	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Lake Ida West Park	151	Communal Dog Park Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Ida West Park	152	Communal Dog Park Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,327.00	1	each	\$5,327.00	1
Lake Ida West Park	153	Communal Dog Park Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,327.00	1	each	\$5,327.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	154	Communal Dog Park Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Lake Ida West Park	155	Communal Dog Park Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	2
Lake Ida West Park	156	Men's Restroom - Dog Park	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	2	staff time	\$0.00	1
Lake Ida West Park	157	Men's Restroom - Dog Park	Plumbing Fixtures & Elements	Lower main area sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Lake Ida West Park	158	Men's Restroom - Dog Park	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Lake Ida West Park	159	Men's Restroom - Dog Park	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$262.50	3	each	\$787.50	1
Lake Ida West Park	160	Men's Restroom - Dog Park	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	161	Men's Restroom - Dog Park	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	162	Men's Restroom - Dog Park	Accessible Routes	Raise bar to min 80", or pad object to prevent hazard in overhead clearance along accessible route.	\$140.00	1	each	\$140.00	1
Lake Ida West Park	163	Men's Restroom - Dog Park	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Ida West Park	164	Men's Restroom - Dog Park	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$350.00	1	each	\$350.00	1
Lake Ida West Park	165	Women's Restroom - Dog Park	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	166	Women's Restroom - Dog Park	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	167	Women's Restroom - Dog Park	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	168	Women's Restroom - Dog Park	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	169	Women's Restroom - Dog Park	Accessible Routes	Raise bar to min 80", or pad object to prevent hazard in overhead clearance along accessible route.	\$140.00	1	each	\$140.00	1
Lake Ida West Park	170	Women's Restroom - Dog Park	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	171	Women's Restroom - Dog Park	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	172	Men's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	173	Men's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	174	Men's Restroom By 'Barrier Free' Play Area	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	175	Men's Restroom By 'Barrier Free' Play Area	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in stall.	\$77.00	1	each	\$77.00	1
Lake Ida West Park	176	Men's Restroom By 'Barrier Free' Play Area	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Lake Ida West Park	177	Men's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	178	Men's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Replace stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	179	Men's Restroom By 'Barrier Free' Play Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Lake Ida West Park	180	Men's Restroom By 'Barrier Free' Play Area	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	181	Women's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	182	Women's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	183	Women's Restroom By 'Barrier Free' Play Area	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Lake Ida West Park	184	Women's Restroom By 'Barrier Free' Play Area	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	185	Women's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	186	Women's Restroom By 'Barrier Free' Play Area	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	187	Women's Restroom By 'Barrier Free' Play Area	Toilet and Bathing Rooms	Replace stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	188	Women's Restroom By 'Barrier Free' Play Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Lake Ida West Park	189	Women's Restroom By 'Barrier Free' Play Area	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%. For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Lake Ida West Park	190	Women's Restroom Closest To Park Entry	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	191	Women's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Ida West Park	192	Women's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	193	Women's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	194	Women's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	195	Women's Restroom Closest To Park Entry	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Ida West Park	196	Women's Restroom Closest To Park Entry	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	197	Men's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top. Install mirror in accessible stall max 40" AFF and min 74" at the top.	\$350.00	1	each	\$350.00	1
Lake Ida West Park	198	Men's Restroom Closest To Park Entry	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	199	Men's Restroom Closest To Park Entry	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in stall.	\$77.00	1	each	\$77.00	1
Lake Ida West Park	200	Men's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Ida West Park	201	Men's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	202	Men's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Replace stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Ida West Park	203	Men's Restroom Closest To Park Entry	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	204	Men's Restroom Closest To Park Entry	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Lake Ida West Park	205	Men's Restroom Closest To Park Entry	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Lake Ida West Park	206	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Lake Ida West Park	207	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Lake Ida West Park	208	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	96	sq ft	\$11,760.00	5
Lake Ida West Park	209	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	216	sq ft	\$26,460.00	5
Lake Ida West Park	210	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	152	sq ft	\$18,620.00	5
Lake Ida West Park	211	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Lake Ida West Park	212	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	176	sq ft	\$21,560.00	5
Lake Ida West Park	213	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
Lake Ida West Park	214	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	168	sq ft	\$20,580.00	5
Lake Ida West Park	215	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	152	sq ft	\$18,620.00	5
Lake Ida West Park	216	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	217	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	218	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	219	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	220	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	37	each	\$3,561.25	5
Lake Ida West Park	221	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	222	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	560	sq ft	\$68,600.00	5
Lake Ida West Park	223	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Lake Ida West Park	224	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Lake Ida West Park	225	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	945	sq ft	\$115,762.50	5
Lake Ida West Park	226	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Lake Ida West Park	227	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3600	sq ft	\$441,000.00	5
Lake Ida West Park	228	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Lake Ida West Park	229	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1000	sq ft	\$122,500.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	230	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	560	sq ft	\$68,600.00	5
Lake Ida West Park	231	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Lake Ida West Park	232	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2000	sq ft	\$245,000.00	5
Lake Ida West Park	233	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Lake Ida West Park	234	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Lake Ida West Park	235	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Lake Ida West Park	236	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1880	sq ft	\$230,300.00	5
Lake Ida West Park	237	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Lake Ida West Park	238	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
Lake Ida West Park	239	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	240	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	241	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	242	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1600	sq ft	\$196,000.00	5
Lake Ida West Park	243	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Lake Ida West Park	244	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Lake Ida West Park	245	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Lake Ida West Park	246	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	250	sq ft	\$30,625.00	5
Lake Ida West Park	247	Trail Surface	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	248	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Lake Ida West Park	249	Trail Surface	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Lake Ida West Park	250	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Lake Ida West Park	251	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	675	sq ft	\$82,687.50	5
Lake Ida West Park	252	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	8	each	\$770.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Ida West Park	253	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
Lake Ida West Park	254	Trail Surface	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
Lake Ida West Park	255	Covered Picnic Tables Along Trail	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the accessible tables as a smart practice.	\$2,486.00	3	each	\$7,458.00	5
Lake Ida West Park	256	Uncovered Picnic Tables From Park Entry To Boat Ramp	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Replace operable parts with ones usable without a tight pinch or grasp.  Correct surface at water spout to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$3,739.75	2	each	\$7,479.50	4
Lake Ida West Park	258	Uncovered Picnic Tables From Park Entry To Boat Ramp	Outdoor - Constructed Features (C)	Correct or repair slopes in wheelchair space to max 2.08% in any direction. In the alternative, leave as is and designate other County picnic facilities accessible.	\$3,062.50	2	each	\$6,125.00	4
Lake Ida West Park	259	Uncovered Picnic Tables From Park Entry To Boat Ramp	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	4	each	\$9,944.00	4
Lake Ida West Park	260	Uncovered Picnic Tables From Park Entry To Boat Ramp	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	100	lin ft	\$5,920.00	4
Lake Ida West Park	261	Uncovered Picnic Tables From Park Entry To Boat Ramp	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max  Relocate 20% of garbage cans to be along AR.	\$0.00	3	staff time	\$0.00	2
Lake Ida West Park	262	Trail Elements	Accessible Routes	Replace both picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
Lake Lytal Park	2	Parking - Tennis/Racquetball Courts	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	6	each	\$18,375.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	3	Parking - Tennis/Racquetball Courts	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Lake Lytal Park	4	Parking - Tennis/Racquetball Courts	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	6	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Lake Lytal Park	7	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	11	each	\$33,687.50	1
Lake Lytal Park	8	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Resurface access aisle to remove built up curb ramp.	\$2,800.00	1	each	\$2,800.00	1
Lake Lytal Park	9	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	3	each	\$630.00	1
Lake Lytal Park	10	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Add one van parking sign to one accessible stall at soccer spaces and one at pool spaces, and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Lake Lytal Park	11	Parking - Baseball/Softball Fields West Lot	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Lake Lytal Park	12	Parking - Soccer Fields North Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Lake Lytal Park	13	Parking - Soccer Fields North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Lake Lytal Park	14	Parking - Soccer Fields North Lot	Parking - Off Street	Correct or fill gaps to max .5".	\$724.00	4	each	\$2,896.00	1
Lake Lytal Park	15	Parking - Soccer Fields North Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Lake Lytal Park	16	Parking - Soccer Fields North Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	18	Parking - Soccer Fields East Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Lake Lytal Park	19	Parking - Soccer Fields East Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	10	each	\$30,625.00	1
Lake Lytal Park	20	Parking - Soccer Fields East Lot	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	21	Parking - Soccer Fields East Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	22	Parking - Soccer Fields East Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	23	Parking - Baseball/Softball Fields North Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Lake Lytal Park	24	Parking - Baseball/Softball Fields North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	25	Parking - Baseball/Softball Fields North Lot	Parking - Off Street	Remove van sign from west stall.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	26	Parking - Baseball/Softball Fields North Lot	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Lake Lytal Park	27	Parking - Basketball Courts	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Lake Lytal Park	28	Parking - Basketball Courts	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Lake Lytal Park	29	Parking - Basketball Courts	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Lake Lytal Park	30	Parking - Basketball Courts	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Lake Lytal Park	31	Parking - Basketball Courts	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Lake Lytal Park	32	Parking - Basketball Courts	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	34	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	2	each	\$735.00	1
Lake Lytal Park	35	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	5	each	\$367.50	1
Lake Lytal Park	36	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Lake Lytal Park	37	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Lake Lytal Park	38	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Lake Lytal Park	39	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Correct or fill gap to max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	40	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	41	Parking - Play Area By Lake Lytal Pavilion/ Armed Forces Memorial	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	8	each	\$588.00	1
Lake Lytal Park	43	Parking - Activity Building/Play Area And Youth Football Building	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Lake Lytal Park	44	Parking - Activity Building/Play Area And Youth Football Building	Parking - Off Street	Add van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	45	Parking - Activity Building/Play Area And Youth Football Building	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	46	Parking - Activity Building/Play Area And Youth Football Building	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	3	staff time	\$0.00	1
Lake Lytal Park	47	Parking - Activity Building/Play Area And Youth Football Building	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	48	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	49	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	50	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	51	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	52	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	53	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	54	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Lake Lytal Park	55	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	56	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Lytal Park	57	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Lake Lytal Park	58	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	59	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	60	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1000	sq ft	\$122,500.00	1
Lake Lytal Park	61	Exterior Accessible Route	Accessible Routes	Install guard rail under support to warn of reduced overhead clearance	\$1,500.00	1	each	\$1,500.00	3
Lake Lytal Park	62	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Lake Lytal Park	63	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	51	each	\$4,908.75	1
Lake Lytal Park	64	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Lake Lytal Park	65	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Lake Lytal Park	66	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	67	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Lake Lytal Park	68	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Lytal Park	69	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	70	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	12	each	\$1,155.00	1
Lake Lytal Park	71	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	72	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	280	sq ft	\$34,300.00	1
Lake Lytal Park	73	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	9	each	\$866.25	1
Lake Lytal Park	74	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	75	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	76	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	77	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	6	each	\$577.50	1
Lake Lytal Park	78	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Lake Lytal Park	79	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	250	sq ft	\$30,625.00	1
Lake Lytal Park	80	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	81	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Lake Lytal Park	82	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	35	each	\$3,368.75	1
Lake Lytal Park	83	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Lake Lytal Park	84	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1680	sq ft	\$205,800.00	1
Lake Lytal Park	85	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	86	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Lake Lytal Park	87	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	21	each	\$2,021.25	1
Lake Lytal Park	88	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Lake Lytal Park	89	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	720	sq ft	\$88,200.00	1
Lake Lytal Park	90	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	91	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	52	each	\$5,005.00	1
Lake Lytal Park	92	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	93	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	94	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Lake Lytal Park	95	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	96	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	97	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	98	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	99	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Lake Lytal Park	100	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Lake Lytal Park	101	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Lake Lytal Park	102	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Lake Lytal Park	103	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Lake Lytal Park	104	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Lake Lytal Park	105	Public Spaces	1.0 Capture (C)	Ensure new swimming pool facility is fully compliant.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	106	Park Elements	Outdoor Recreation Access Routes (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	5
Lake Lytal Park	107	Park Elements	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Lake Lytal Park	108	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	109	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Lake Lytal Park	110	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Lake Lytal Park	111	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Lake Lytal Park	112	Sports Fields/Courts	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	4	each	\$12,250.00	1
Lake Lytal Park	113	Sports Fields/Courts	1.0 Capture (C)	Ensure the ball fields are compliant if they are reopened.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	114	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$3,717.00	1	each	\$3,717.00	1
Lake Lytal Park	115	Sports Fields/Courts	Accessible Route - Slope (C)	Mount signage at the accessible entrances designating them as accessible	\$210.00	2	each	\$420.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	116	Sports Fields/Courts	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	2	each	\$1,680.00	1
Lake Lytal Park	119	Sports Fields/Courts	Reach Ranges	Remount rims of 3 or more garbage bins to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	2
Lake Lytal Park	120	Sports Fields/Courts	Assembly Areas	Extend accessible route to bleachers at opposite sides of the soccer fields and provide wheelchair accessible spaces at each set of bleachers.	\$629.50	4	each	\$2,518.00	2
Lake Lytal Park	121	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	60	lin ft	\$3,552.00	4
Lake Lytal Park	122	Sports Fields/Courts	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	123	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	225	lin ft	\$13,320.00	4
Lake Lytal Park	124	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	225	lin ft	\$13,320.00	4
Lake Lytal Park	125	Sports Fields/Courts	Assembly Areas	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to bleachers. In the alternative, leave as is and designate other County ball fields accessible.	\$629.50	4	each	\$2,518.00	4
Lake Lytal Park	126	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	40	lin ft	\$2,368.00	4
Lake Lytal Park	127	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	325	sq ft	\$19,240.00	4
Lake Lytal Park	128	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	200	lin ft	\$11,840.00	4
Lake Lytal Park	129	Sports Fields/Courts	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	130	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	75	lin ft	\$4,440.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	132	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,264.50	1	each	\$2,264.50	1
Lake Lytal Park	133	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,264.50	1	each	\$2,264.50	1
Lake Lytal Park	134	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$5,162.50	1	each	\$5,162.50	1
Lake Lytal Park	135	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$5,162.50	1	each	\$5,162.50	1
Lake Lytal Park	136	Sports Fields/Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1
Lake Lytal Park	137	Sports Fields/Courts	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$3,062.50	1	each	\$3,062.50	2
Lake Lytal Park	138	Sports Fields/Courts	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	139	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Lake Lytal Park	140	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Lake Lytal Park	141	Shelters	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Lake Lytal Park	142	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	5	each	\$481.25	4
Lake Lytal Park	143	Shelters	Accessible Routes	Raise angled beams to min 80", or pad object to prevent hazard in overhead clearance. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	30	each	\$10,500.00	4
Lake Lytal Park	144	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Lake Lytal Park	145	Shelters	Picnic Tables (C)	Replace one more picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Lake Lytal Park	146	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	5	lin ft	\$296.00	4
Lake Lytal Park	147	Shelters	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.  Replace drinking fountain with a hi-lo bowl fountain.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	148	Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
Lake Lytal Park	149	Concessions	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.  Relocate items to provide CFS at sink	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	150	Concessions	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	151	Concessions	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Lake Lytal Park	152	Concessions	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	153	Concessions	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	2
Lake Lytal Park	154	Concessions	Kitchens, Kitchenettes, And Wet Bars	Correct or replace sink to be accessible.	\$3,479.00	1	each	\$3,479.00	1
Lake Lytal Park	155	Concessions	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Lake Lytal Park	156	Concessions	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Lake Lytal Park	157	Concessions	Kitchens, Kitchenettes, And Wet Bars	Relocate storage and other items to provide required clear floor space at appliances.	\$0.00	1	staff time	\$0.00	3
Lake Lytal Park	158	Concessions	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	159	Concessions	Accessible Routes	Raise fans and cords to min 80", or pad objects to prevent hazard in overhead clearance along AR.	\$140.00	4	each	\$560.00	1
Lake Lytal Park	160	Concessions	Turning Space	Relocate obstacles to create turning space in soccer fields concessions.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	161	Concessions	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$233.25	3	each	\$699.75	1
Lake Lytal Park	162	Concessions	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	9	staff time	\$0.00	1
Lake Lytal Park	163	Concessions	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	164	Concessions	Accessible Routes	Correct or repair slope to max 5% running and 2.08% cross.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	165	Veterans Memorial	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Lake Lytal Park	166	Veterans Memorial	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Lake Lytal Park	167	Veterans Memorial	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Lake Lytal Park	168	Veterans Memorial	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Lytal Park	169	Veterans Memorial	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Lake Lytal Park	171	Youth Football Building	Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS.  Pricing provided in a previous accessible route finding.	\$0.00	1	each	\$0.00	1
Lake Lytal Park	172	Football - Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	173	Football - Men's Restroom	Plumbing Fixtures & Elements	Remount signage to the proper location based on the type of door provided.  Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model if making the 1st or 2nd sink accessible.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	174	Football - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim if making the 3rd sink accessible.	\$2,380.00	1	each	\$2,380.00	1
Lake Lytal Park	175	Football - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Lake Lytal Park	176	Football - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Lake Lytal Park	177	Football - Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Lake Lytal Park	178	Football - Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Lake Lytal Park	179	Football - Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF.	\$1,704.50	1	each	\$1,704.50	1
Lake Lytal Park	180	Football - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	181	Football - Men's Restroom	Clear Floor Space	Relocate soap dispenser to provide required 30" by 48" CFS at operable parts, mounted 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	182	Football - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Lake Lytal Park	183	Football - Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	184	Football - Men's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Lake Lytal Park	185	Football - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	186	Football - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	187	Football - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	188	Football - Men's Restroom	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$2,965.00	1	each	\$2,965.00	1
Lake Lytal Park	189	Football - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.  Remount signage to the proper location based on the type of door provided.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	190	Football - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	191	Football - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	192	Football - Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Lake Lytal Park	193	Football - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Lake Lytal Park	194	Football - Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Lake Lytal Park	195	Football - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	196	Football - Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Lake Lytal Park	197	Football - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	198	Football - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	199	Football - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	staff time	\$350.00	1
Lake Lytal Park	200	Football - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	201	Football - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Pricing provided in a previous finding.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	each	\$0.00	1
Lake Lytal Park	202	Activity Building - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	203	Activity Building - Men's Restroom	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.	\$2,380.00	1	each	\$2,380.00	1
Lake Lytal Park	204	Activity Building - Men's Restroom	Reach Ranges	Remount stored items to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	205	Activity Building - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  Provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	206	Activity Building - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	207	Activity Building - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	208	Activity Building - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	209	Activity Building - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	210	Activity Building - Men's Restroom	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Lake Lytal Park	211	Activity Building - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	212	Activity Building - Men's Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Lake Lytal Park	213	Activity Building - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	214	Activity Building - Women's Restroom	Toilet and Bathing Rooms	Relocate garbage to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	215	Activity Building - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	216	Activity Building - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	217	Activity Building - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing to remount one grab bar in a previous finding.	\$196.75	2	each	\$393.50	1
Lake Lytal Park	218	Activity Building - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	219	Activity Building - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	220	Baseball - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	221	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Lake Lytal Park	222	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Lake Lytal Park	223	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Lake Lytal Park	224	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Lake Lytal Park	225	Baseball - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	226	Baseball - Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	227	Baseball - Men's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	228	Baseball - Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	229	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Lake Lytal Park	230	Baseball - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	231	Baseball - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	232	Baseball - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	233	Baseball - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Lake Lytal Park	234	Baseball - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Lake Lytal Park	235	Baseball - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	236	Baseball - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Lake Lytal Park	237	Baseball - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Lake Lytal Park	238	Baseball - Women's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Lake Lytal Park	239	Baseball - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	240	Baseball - Women's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	241	Baseball - Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Lake Lytal Park	242	Baseball - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Lake Lytal Park	243	Baseball - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	244	Baseball - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Lake Lytal Park	245	Baseball - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Lake Lytal Park	246	Baseball - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Lake Lytal Park	247	Baseball - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Lake Lytal Park	248	Baseball - Women's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Remount hardware to be 34" to 48" AFF.	\$3,287.00	1	each	\$3,287.00	3
Lake Lytal Park	249	2-5 Play Area At Activity Center	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Lake Lytal Park	250	2-5 Play Area At Activity Center	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Lake Lytal Park	251	2-5 Play Area At Activity Center	Accessible Routes	Raise tree branches to min 80".  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Lake Lytal Park	252	2-5 Play Area At Activity Center	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	253	2-5 Play Area At Activity Center	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  In the alternative, leave as is and designate other County playgrounds accessible.	\$3,062.50	1	each	\$3,062.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	254	5-12 Play Area At Activity Center	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Lake Lytal Park	255	5-12 Play Area At Activity Center	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Pricing provided in 2-5 play area checklist.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	256	5-12 Play Area At Activity Center	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	257	Play Area, 2-5	Play Area	Correct or repair cross slope of designated entry to max 2.08%.  Repair, bevel or ramp CIL at playground entry/border.  In the alternative, leave as is and designate other County playgrounds accessible.	\$3,158.75	1	each	\$3,158.75	4
Lake Lytal Park	258	Play Area, 2-5	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	100	sq ft	\$7,000.00	4
Lake Lytal Park	259	Play Area, 2-5	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	260	Play Area, 2-5	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	261	Play Area, 2-5	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF or provide a swing that can be mounted within this range. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Lake Lytal Park	262	Play Area, 2-5	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	263	Play Area, 2-5	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	264	Play Area, 5-12	Play Area	Install transfer system to connect to 50% of EPCs. In the alternative, leave as is and designate other County playgrounds accessible.	\$5,800.00	1	each	\$5,800.00	4
Lake Lytal Park	265	Play Area, 5-12	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	266	Play Area, 5-12	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Lytal Park	267	Public Spaces	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	268	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	269	Public Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	270	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  Provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	271	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Lake Lytal Park	272	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide beveled threshold.	\$3,316.25	1	each	\$3,316.25	1
Lake Lytal Park	273	Public Spaces	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" to 48".	\$610.75	1	each	\$610.75	1
Lake Lytal Park	274	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Lytal Park	275	Public Spaces	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	each	\$3,062.50	2
Lake Lytal Park	276	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Lake Lytal Park	277	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	278	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Lake Lytal Park	279	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,158.75	1	each	\$3,158.75	1
Lake Lytal Park	280	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove shelf or replace with a shelf having a max profile of 4".	\$350.00	1	each	\$350.00	1
Lake Lytal Park	281	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates that open to 90 degrees.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$2,772.50	1	each	\$2,772.50	1
Lake Lytal Park	282	Public Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Lake Lytal Park	283	Public Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	284	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$5,005.00	1	each	\$5,005.00	1
Lake Lytal Park	285	Employee Spaces	Viewing Areas (C)	Lower a 32" wide portion of viewing windows to max 32" for unobstructed viewing as a smart practice.	\$980.00	1	each	\$980.00	5
Lake Lytal Park	286	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
Lake Lytal Park	287	Employee Spaces	Accessible Routes	Provide vertical access to commentator area.	\$46,631.00	1	each	\$46,631.00	3
Lake Lytal Park	288	Employee Spaces	Accessible Routes	Provide vertical access to commentator area.	\$46,631.00	1	each	\$46,631.00	3
Lake Lytal Park	289	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$288.75	1	each	\$288.75	3
Lake Lytal Park	290	Employee Spaces	Viewing Areas (C)	Lower a 32" wide portion of viewing windows to max 32" for unobstructed viewing as a smart practice.	\$980.00	1	each	\$980.00	5
Lake Lytal Park	291	Employee Spaces	1.0 Capture (C)	Leave as is unless facility is reopened in the future.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Lytal Park	292	Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Lake Lytal Park	293	Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Lake Lytal Park	294	Maintenance	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Lake Lytal Park	295	Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
Lake Worth West Park	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	90	sq ft	\$11,025.00	1
Lake Worth West Park	2	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
Lake Worth West Park	3	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Lake Worth West Park	4	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Worth West Park	5	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Lake Worth West Park	6	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Lake Worth West Park	11	Park Elements	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of exercise area surfaces.	\$0.00	1	staff time	\$0.00	2
Lake Worth West Park	12	2-5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Lake Worth West Park	13	2-5 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Lake Worth West Park	14	2-5 Play Area	Play Area	Install transfer system on play structure with access to 50% of the EPCs, if feasible. In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4
Lake Worth West Park	15	2-5 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Lake Worth West Park	16	2-5 Play Area	Play Area	Add 1 more GLPC of type other than swings to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Lake Worth West Park	17	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Lake Worth West Park	18	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Lake Worth West Park	19	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Lake Worth West Park	20	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Lake Worth West Park	21	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Limestone Creek Park	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Limestone Creek Park	2	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Limestone Creek Park	3	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Limestone Creek Park	4	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	1	each	\$59.20	1
Limestone Creek Park	5	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Limestone Creek Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Limestone Creek Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Limestone Creek Park	10	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Limestone Creek Park	11	Park Elements	Accessible Routes	Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
Limestone Creek Park	12	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Limestone Creek Park	13	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to benches.	\$59.20	20	lin ft	\$1,184.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Limestone Creek Park	14	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Limestone Creek Park	15	Park Elements	Clear Floor Space	Repair, bevel or ramp CIL in CGS to max .25".	\$96.25	1	each	\$96.25	1
Limestone Creek Park	16	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$96.25	9	each	\$866.25	4
Limestone Creek Park	17	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic tables from under the shelter with the ones of an accessible design located outside of the shelter, as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$0.00	1	staff time	\$0.00	4
Limestone Creek Park	18	Shelters/Picnic Areas	Clear Floor Space	Provide a 30" by 48" clear ground space at grills.  In the alternative, leave as is and designate other County shelters accessible.	\$1,225.00	2	each	\$2,450.00	4
Limestone Creek Park	19	2-5 Play Area	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Limestone Creek Park	20	2-5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Limestone Creek Park	23	2-5 Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Limestone Creek Park	25	5-12 Play Area	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4
Limestone Creek Park	26	5-12 Play Area	Play Area	Add one more play component to the elevated structure, such as a steering wheel, periscope, or talk tube, to meet the 50% accessible standard for EPCs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Loggerhead Park	2	Parking - North Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	3	Parking - North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	10	each	\$30,625.00	1
Loggerhead Park	4	Parking - North Lot	Parking - Off Street	Correct or fill gaps to max .5". Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$96.25	1	each	\$96.25	1
Loggerhead Park	5	Parking - North Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Loggerhead Park	6	Parking - North Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Loggerhead Park	8	Parking - Loggerhead Marine Center	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Loggerhead Park	9	Parking - Loggerhead Marine Center	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Loggerhead Park	10	Parking - Loggerhead Marine Center	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Loggerhead Park	11	Parking - Picnic Shelter	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Loggerhead Park	12	Parking - Picnic Shelter	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Loggerhead Park	13	Parking - Picnic Shelter	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Loggerhead Park	14	Parking - Picnic Shelter	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Loggerhead Park	15	Parking - Picnic Shelter	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Loggerhead Park	16	Parking - Picnic Shelter	Parking - Off Street	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material. Cost included in slope correction.	\$0.00	1	each	\$0.00	1
Loggerhead Park	18	Parking - Ocean Rescue	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Loggerhead Park	19	Parking - Ocean Rescue	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Loggerhead Park	20	Parking - Ocean Rescue	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Loggerhead Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Loggerhead Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggerhead Park	23	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Loggerhead Park	24	Exterior Accessible Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
Loggerhead Park	25	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	26	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	1	each	\$525.00	3
Loggerhead Park	27	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	1
Loggerhead Park	28	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Loggerhead Park	29	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loggerhead Park	30	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	31	Exterior Accessible Route	Accessible Routes	Remove plant overgrowth to widen EAR to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	32	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggerhead Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$4,083.25	6	each	\$24,499.50	1
Loggerhead Park	34	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Loggerhead Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Loggerhead Park	36	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Loggerhead Park	37	Exterior Accessible Route	Detectable Warnings	Replace existing detectable warning with compliant truncated dome template, with visual contrast and is integrated into the walking surface.	\$329.00	1	each	\$329.00	5
Loggerhead Park	38	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggerhead Park	39	Exterior Accessible Route	Curb Ramps	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp.	\$875.00	1	each	\$875.00	1
Loggerhead Park	40	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 8.33%. In the alternative, leave as is citing construction tolerance.	\$1,015.00	1	each	\$1,015.00	4
Loggerhead Park	41	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Loggerhead Park	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	900	sq ft	\$110,250.00	1
Loggerhead Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Loggerhead Park	44	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Loggerhead Park	45	Exterior Accessible Route	Ramps (Not Curb Ramps)	Tighten or repair handrail to be secure in its fittings.	\$420.00	1	each	\$420.00	1
Loggerhead Park	46	Exterior Accessible Route	Ramps (Not Curb Ramps)	Repair, bevel, or ramp CIL on ramp landings.	\$96.25	3	each	\$288.75	1
Loggerhead Park	47	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	1	each	\$980.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	48	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	1
Loggerhead Park	49	Exterior Accessible Route	Ramps (Not Curb Ramps)	Tighten or repair handrail to be secure in its fittings.	\$420.00	1	each	\$420.00	1
Loggerhead Park	50	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	1	each	\$525.00	1
Loggerhead Park	51	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	1
Loggerhead Park	52	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Loggerhead Park	53	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggerhead Park	54	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggerhead Park	55	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Loggerhead Park	56	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Loggerhead Park	57	Park Elements	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Loggerhead Park	58	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggerhead Park	59	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Loggerhead Park	60	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Loggerhead Park	62	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%; in the alternative, relocate beach cleanup station to location with level CFS.	\$122.50	25	sq ft	\$3,062.50	2
Loggerhead Park	63	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$38,822.00	1	each	\$38,822.00	5
Loggerhead Park	66	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Loggerhead Park	67	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Loggerhead Park	68	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR. Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Loggerhead Park	70	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Loggerhead Park	71	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Loggerhead Park	72	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
Loggerhead Park	73	Park Elements	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	74	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Loggerhead Park	75	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggerhead Park	76	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Loggerhead Park	77	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Loggerhead Park	78	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Loggerhead Park	79	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Relocate 20% of accessible garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	5
Loggerhead Park	80	Shelters/Picnic Areas	Picnic Tables (C)	Provide picnic tables of an accessible design in both newer shelters as a smart practice. Leave as is the other four shelters.	\$1,120.00	4	each	\$4,480.00	5
Loggerhead Park	81	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	20	each	\$1,184.00	4
Loggerhead Park	82	Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Loggerhead Park	83	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4
Loggerhead Park	84	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  Remount garbage can to be in reach range of 15" min to 48" max.  Remount water spouts to 28" min or 36" max above the ground as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$233.25	3	each	\$699.75	4
Loggerhead Park	85	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	20	lin ft	\$1,184.00	4
Loggerhead Park	86	Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	87	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	8	each	\$473.60	4
Loggerhead Park	88	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Loggerhead Park	89	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to three picnic units/tables as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	75	lin ft	\$4,440.00	4
Loggerhead Park	90	Shelters/Picnic Areas	Picnic Tables (C)	Replace three picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	3	each	\$3,360.00	4
Loggerhead Park	91	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.  Relocate garbage can to be along AR.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
Loggerhead Park	92	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$175.00	2	each	\$350.00	4
Loggerhead Park	93	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4
Loggerhead Park	94	Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Loggerhead Park	95	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	5	lin ft	\$296.00	4
Loggerhead Park	96	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Loggerhead Park	97	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	98	Shelters/Picnic Areas	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Loggerhead Park	99	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,575.00	1	each	\$1,575.00	4
Loggerhead Park	100	Beach Access Route	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	500	lin ft	\$29,600.00	5
Loggerhead Park	101	Beach Access Route	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible. In the alternative, leave as is and designate other County beaches accessible.	\$404.25	6	each	\$2,425.50	4
Loggerhead Park	102	Beach Access Route	Stairways	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible. In the alternative, leave as is and designate other County beaches accessible.	\$404.25	5	each	\$2,021.25	4
Loggerhead Park	103	Beach Access Route	Stairways	Install kick plates on all stairs or replace with ones having closed risers. Leave as is if open risers are essential to function. In the alternative, leave as is and designate other County beaches accessible.	\$84.00	17	each	\$1,428.00	4
Loggerhead Park	104	Beach Access Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of stairway surfaces. In the alternative, leave as is and designate other County beaches accessible.	\$0.00	1	staff time	\$0.00	4
Loggerhead Park	105	Beach Access Route	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.  In the alternative, leave as is and designate other County beaches accessible.	\$125.00	11	each	\$1,375.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	106	Beach Access Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.  In the alternative, leave as is and designate other County beaches accessible.	\$980.00	1	each	\$980.00	4
Loggerhead Park	107	Beach Access Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.  In the alternative, leave as is and designate other County beaches accessible.	\$980.00	3	each	\$2,940.00	4
Loggerhead Park	108	Beach Access Route	Stairways	Replace or remount handrails to 34" to 38" AFF. In the alternative, leave as is and designate other County beaches accessible.	\$350.00	1	each	\$350.00	4
Loggerhead Park	109	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$122.50	250	sq ft	\$30,625.00	4
Loggerhead Park	110	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$122.50	25	sq ft	\$3,062.50	4
Loggerhead Park	111	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$122.50	50	sq ft	\$6,125.00	4
Loggerhead Park	112	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$6,510.00	3	each	\$19,530.00	4
Loggerhead Park	113	Beach Access Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.  In the alternative, leave as is and designate other County beaches accessible.	\$980.00	2	each	\$1,960.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	114	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	100	lin ft	\$5,920.00	4
Loggerhead Park	115	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Loggerhead Park	116	Playground	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs.  Pricing provided in the previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Loggerhead Park	117	Playground	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Loggerhead Park	118	Playground	Play Area	Correct transfer step riser height to 8" max and uniform. In the alternative, leave as is citing construction tolerance. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Loggerhead Park	120	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Loggerhead Park	121	Playground	Play Area	Replace surface with accessible surface such as EWF, PIP or tiles.  Pricing provided in a previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Loggerhead Park	122	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County beaches accessible.	\$59.20	790	lin ft	\$46,768.00	4
Loggerhead Park	123	Trail Surface	Trails	Establish protocols for regular and frequent inspection and maintenance of trails to ensure 60" width and 80" overhead clearance.	\$0.00	1	staff time	\$0.00	5
Loggerhead Park	124	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1440	sq ft	\$176,400.00	5
Loggerhead Park	125	Trail Surface	Outdoor - Trails (C)	Correct or repair trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$59.20	450	lin ft	\$26,640.00	5
Loggerhead Park	126	Trail Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to trail signs.	\$59.20	50	lin ft	\$2,960.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	127	North Restrooms - Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	2
Loggerhead Park	128	North Restrooms - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Loggerhead Park	129	North Restrooms - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Loggerhead Park	130	North Restrooms - Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Loggerhead Park	131	North Restrooms - Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Loggerhead Park	132	North Restrooms - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggerhead Park	133	North Restrooms - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	134	North Restrooms - Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	135	North Restrooms - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	136	North Restrooms - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,255.00	1	each	\$3,255.00	1
Loggerhead Park	137	North Restrooms - Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,529.25	1	each	\$2,529.25	3
Loggerhead Park	139	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	2
Loggerhead Park	140	North Restrooms - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	141	North Restrooms - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Loggerhead Park	142	North Restrooms - Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	143	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Loggerhead Park	144	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Loggerhead Park	145	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	146	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Loggerhead Park	146	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Loggerhead Park	147	North Restrooms - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	148	North Restrooms - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
Loggerhead Park	149	Ocean Rescue - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Loggerhead Park	150	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Loggerhead Park	151	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Loggerhead Park	152	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Loggerhead Park	152	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Loggerhead Park	153	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Loggerhead Park	154	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing provided in the previous finding.	\$0.00	2	each	\$0.00	1
Loggerhead Park	155	Ocean Rescue - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	156	Ocean Rescue - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	157	Ocean Rescue - Men's Restroom	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of restroom floor surface.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	158	Ocean Rescue - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	159	Ocean Rescue - Men's Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$5,423.25	1	each	\$5,423.25	1
Loggerhead Park	160	Ocean Rescue - Women's Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$5,423.25	1	each	\$5,423.25	1
Loggerhead Park	161	Ocean Rescue - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Loggerhead Park	162	Ocean Rescue - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Loggerhead Park	163	Ocean Rescue - Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Loggerhead Park	164	Ocean Rescue - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Loggerhead Park	165	Ocean Rescue - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Loggerhead Park	166	Ocean Rescue - Women's Restroom	Toilet and Bathing Rooms	<p>Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).</p> <p>Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.</p>	\$0.00	3	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	167	Ocean Rescue - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Loggerhead Park	168	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Fill gaps at door entries to max .5".</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$4,690.50	7	each	\$32,833.50	3
Loggerhead Park	169	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure rug at door to prevent trip hazard.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$7,928.25	3	each	\$23,784.75	3
Loggerhead Park	170	Employee Spaces	Accessible Routes	Raise surf boards to min 80", or pad/relocate object to prevent hazard in overhead clearance along AR.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	171	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	172	Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Loggerhead Park	173	Lifeguard Office Restroom And Shower	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,037.00	1	each	\$5,037.00	3
Loggerhead Park	174	Lifeguard Office Restroom And Shower	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Loggerhead Park	175	Lifeguard Office Restroom And Shower	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering, mounted on the latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Loggerhead Park	176	Lifeguard Office Restroom And Shower	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Loggerhead Park	177	Employee Spaces	Parking - Off Street	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Loggerhead Park	179	Employee Spaces	Accessible Routes	Relocate or reposition furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	180	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	181	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	3
Loggerhead Park	182	Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Loggerhead Park	183	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	184	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$1,659.50	4	each	\$6,638.00	3
Loggerhead Park	185	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p>	\$3,062.50	1	each	\$3,062.50	3
Loggerhead Park	187	Employee Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Loggerhead Park	188	Employee Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	189	Employee Restroom	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.	\$2,380.00	1	each	\$2,380.00	3
Loggerhead Park	190	Employee Restroom	Plumbing Fixtures & Elements	Fully insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	3
Loggerhead Park	191	Employee Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Loggerhead Park	192	Employee Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggerhead Park	193	Employee Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove storage from grab bar and train staff to keep storage items off of grab bars.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	194	Employee Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Loggerhead Park	195	Employee Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Loggerhead Park	196	Employee Restroom	Plumbing Fixtures & Elements	Replace faucet controls with lever controls.	\$735.00	1	each	\$735.00	3
Loggers' Run Park	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Loggers' Run Park	3	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Loggers' Run Park	4	Parking	Parking - Off Street	Maintain stalls and aisles to free of sand and dirt build up.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	5	Parking	Parking - Off Street	Replace and mount at appropriate heights and locations accessible parking signs for the stalls where signage is faded.	\$210.00	3	each	\$630.00	1
Loggers' Run Park	6	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Loggers' Run Park	7	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint.	\$73.50	6	each	\$441.00	1
Loggers' Run Park	9	Main Parking Between Roller Hockey Rink And Basketball Courts	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Loggers' Run Park	10	Main Parking Between Roller Hockey Rink And Basketball Courts	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
Loggers' Run Park	11	Main Parking Between Roller Hockey Rink And Basketball Courts	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Loggers' Run Park	12	Main Parking Between Roller Hockey Rink And Basketball Courts	Parking - Off Street	Add one van parking sign to one accessible stall at each cluster and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Loggers' Run Park	13	Main Parking Between Roller Hockey Rink And Basketball Courts	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	12	each	\$882.00	1
Loggers' Run Park	14	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Loggers' Run Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggers' Run Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggers' Run Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Loggers' Run Park	18	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Loggers' Run Park	19	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Loggers' Run Park	21	Exterior Accessible Route	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" aff	\$514.50	1	each	\$514.50	1
Loggers' Run Park	22	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	9	each	\$866.25	1
Loggers' Run Park	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Loggers' Run Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Loggers' Run Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Loggers' Run Park	26	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggers' Run Park	27	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loggers' Run Park	28	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggers' Run Park	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Loggers' Run Park	30	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggers' Run Park	31	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggers' Run Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Loggers' Run Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Loggers' Run Park	34	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loggers' Run Park	35	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loggers' Run Park	36	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	20	each	\$1,925.00	1
Loggers' Run Park	37	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Loggers' Run Park	38	Exterior Accessible Route	Accessible Routes	Correct slopes on surface to eliminate water pooling.	\$3,062.50	1	each	\$3,062.50	1
Loggers' Run Park	39	Exterior Accessible Route	Accessible Routes	Train staff to maintain surface to be free of surface debris.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	40	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	1
Loggers' Run Park	41	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Loggers' Run Park	42	Exterior Accessible Route	Accessible Routes	Train staff to keep accessible route free of dirt and debris.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	43	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loggers' Run Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loggers' Run Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	350	sq ft	\$42,875.00	1
Loggers' Run Park	46	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loggers' Run Park	47	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	325	sq ft	\$39,812.50	1
Loggers' Run Park	48	Play Area (5-12)	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	49	Play Area (5-12)	Accessible Routes	Correct or fill gaps to be max .5".  In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	15	each	\$1,443.75	4
Loggers' Run Park	50	Play Area (5-12)	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Loggers' Run Park	53	Play Area (5-12)	Play Area	Add two more GLPC's of a different type to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
Loggers' Run Park	54	Men's Restroom	Plumbing Fixtures & Elements	Lower sink in main restroom to max 34" above the finished floor (AFF) to front of rim.  Leave as is sink in stall citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	1
Loggers' Run Park	55	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	56	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink in stall and sink in main restroom.	\$77.00	2	each	\$154.00	1
Loggers' Run Park	57	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet if constructed after 3/15/2012	\$2,380.00	1	each	\$2,380.00	1
Loggers' Run Park	58	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	59	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	60	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	61	Men's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width to provide 18" pull side clearance at stall.	\$2,749.25	1	each	\$2,749.25	1
Loggers' Run Park	62	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Loggers' Run Park	63	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggers' Run Park	64	Men's Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF if intended for use by the public. If employee only, leave as is.	\$514.50	1	each	\$514.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	65	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted to 34" to 48" AFF. Leave as is if lock is for employee use only.	\$514.50	1	each	\$514.50	1
Loggers' Run Park	66	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Loggers' Run Park	67	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under both sinks.	\$77.00	2	each	\$154.00	1
Loggers' Run Park	68	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet if built after 3/15/2012.	\$2,380.00	1	each	\$2,380.00	1
Loggers' Run Park	69	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Loggers' Run Park	70	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	71	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	72	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	73	Women's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width to provide 18" pull side clearance.	\$2,749.25	1	each	\$2,749.25	1
Loggers' Run Park	74	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Loggers' Run Park	75	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggers' Run Park	78	Sports Storage	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,158.75	1	each	\$3,158.75	1
Loggers' Run Park	79	Sports Storage	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	80	Sports Storage	Turning Space	Relocate obstacles to create turning space in storage.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	81	Sports Storage	Doors	Provide required maneuvering clearance on push side of door  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	84	Park Element	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
Loggers' Run Park	87	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Loggers' Run Park	88	Park Element	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth	\$122.50	12	sq ft	\$1,470.00	2
Loggers' Run Park	89	Picnic Shelter	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Loggers' Run Park	90	Picnic Shelter	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	25	each	\$2,406.25	5
Loggers' Run Park	91	Picnic Shelter	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice.	\$0.00	1	staff time	\$0.00	5
Loggers' Run Park	92	Picnic Shelter	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Loggers' Run Park	93	Picnic Shelter	Shelters/Picnic Areas (C)	Lower garbage cans to be in reach range of max 48" AGL.	\$0.00	1	staff time	\$0.00	5
Loggers' Run Park	94	Picnic Shelter	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	5
Loggers' Run Park	95	Picnic Shelter	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	5
Loggers' Run Park	96	Picnic Shelter	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Loggers' Run Park	99	Sports Courts/Fields	Kitchens, Kitchenettes, And Wet Bars	Lower 50% of shelving, or relocate supplies to within reach range, max 48" AFF.	\$700.00	1	each	\$700.00	1
Loggers' Run Park	100	Sports Courts/Fields	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Loggers' Run Park	101	Sports Courts/Fields	Plumbing Fixtures & Elements	Insulate exposed pipes under sink	\$77.00	1	each	\$77.00	1
Loggers' Run Park	102	Sports Courts/Fields	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	103	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	104	Sports Courts/Fields	Park Site (C)	Widen one door/gate to min 32" clear width and provide a ramp for access to roller hockey.	\$4,272.50	1	each	\$4,272.50	2
Loggers' Run Park	105	Sports Courts/Fields	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Loggers' Run Park	106	Sports Courts/Fields	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Loggers' Run Park	107	Sports Courts/Fields	Accessible Routes	Correct slope along route to prevent water pooling.	\$3,062.50	1	each	\$3,062.50	2
Loggers' Run Park	109	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$59.20	3800	lin ft	\$224,960.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	110	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
Loggers' Run Park	111	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$122.50	800	sq ft	\$98,000.00	4
Loggers' Run Park	112	Trail Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	5
Loggers' Run Park	113	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	114	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	115	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	116	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	117	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	118	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	119	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4
Loggers' Run Park	120	Trail Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County fitness trails and elements accessible.	\$59.20	5	lin ft	\$296.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	121	Office	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Loggers' Run Park	122	Men's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Loggers' Run Park	123	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	124	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Loggers' Run Park	125	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	126	Men's Restroom	Toilet and Bathing Rooms	Relocate partition to provide required 60" clearance around toilet.	\$420.00	1	each	\$420.00	1
Loggers' Run Park	127	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Loggers' Run Park	128	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	129	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	130	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	131	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggers' Run Park	132	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Loggers' Run Park	133	Women's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	134	Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Loggers' Run Park	135	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top. In the alternative, leave as is citing construction tolerance.	\$0.00	1	staff time	\$0.00	4
Loggers' Run Park	136	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Loggers' Run Park	137	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet if constructed after 3/15/2012	\$2,080.00	1	each	\$2,080.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	138	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Loggers' Run Park	139	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	140	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loggers' Run Park	141	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate soap to a location that doesn't interfere with the clearance above the grab bar and in reach range of max 48" AFF.	\$0.00	2	staff time	\$0.00	1
Loggers' Run Park	142	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loggers' Run Park	143	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Loggers' Run Park	144	Break Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	145	Break Room	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	1
Loggers' Run Park	146	Common Spaces	Protruding Object	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Loggers' Run Park	147	Common Spaces	Doors	Provide required maneuvering clearance on push side of door  Relocate obstacles to provide 48" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Loggers' Run Park	148	Shop	Doors	Provide required maneuvering clearance around pull side of door  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	\$1,750.00	1	each	\$1,750.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loggers' Run Park	149	Shop	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	3
Loggers' Run Park	150	Shop	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$253.75	1	each	\$253.75	3
<a href="#">Loxahatchee Groves Park</a>	1	Parking	Parking - Off Street	Ensure there are enough 12' accessible parking stalls, with 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$0.00	5	staff time	\$0.00	1
Loxahatchee Groves Park	2	Parking	Parking - Off Street	Create 5' adjacent access aisles, with proper signage and striping. Cost in next finding.	\$0.00	3	each	\$0.00	1
Loxahatchee Groves Park	3	Parking	Parking - Off Street	Replace surface at accessible parking spaces with a firm and stable surface.	\$2,800.00	5	each	\$14,000.00	1
Loxahatchee Groves Park	4	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint one stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Loxahatchee Groves Park	5	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	2	each	\$420.00	1
Loxahatchee Groves Park	6	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loxahatchee Groves Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Loxahatchee Groves Park	9	Exterior Accessible Route	Turning Space	Correct slope in turning space to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loxahatchee Groves Park	10	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	1
Loxahatchee Groves Park	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loxahatchee Groves Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Loxahatchee Groves Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Loxahatchee Groves Park	14	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Loxahatchee Groves Park	15	Exterior Accessible Route	Accessible Routes	Maintain accessible route to ensure a firm, stable, and slip resistance surface.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	16	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Loxahatchee Groves Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Loxahatchee Groves Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Loxahatchee Groves Park	19	Exterior Accessible Route	Accessible Routes	Maintain accessible route to ensure a firm, stable, and slip resistance surface.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Loxahatchee Groves Park	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Loxahatchee Groves Park	22	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	160	lin ft	\$9,472.00	4
Loxahatchee Groves Park	23	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Loxahatchee Groves Park	24	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Loxahatchee Groves Park	25	Park Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Loxahatchee Groves Park	26	Park Elements	Outdoor Recreation Access Route	Relocate garbage can to be along AR. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loxahatchee Groves Park	27	Park Elements	Shelters, Picnic Facilities (C)	Extend an AR to features and elements in the shelter or picnic area as a smart practice.  Replace two picnic tables with ones of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.  Relocate 20% of garbage cans to be along AR.	\$1,416.00	2	each	\$2,832.00	4
Loxahatchee Groves Park	29	Palomino Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5".	\$96.25	14	each	\$1,347.50	5
Loxahatchee Groves Park	30	Palomino Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5
Loxahatchee Groves Park	31	Palomino Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Loxahatchee Groves Park	32	Palomino Pavilion	Shelters, Picnic Facilities (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	5
Loxahatchee Groves Park	33	Pine Pavilion	Outdoor - Constructed Features (C)	Reposition accessible picnic tables to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Loxahatchee Groves Park	34	Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Loxahatchee Groves Park	35	Play Area	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	5	lin ft	\$296.00	4
Loxahatchee Groves Park	36	Play Area	Accessible Routes	Repair or reset tiles to eliminate change in level.  Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$28.00	100	sq ft	\$2,800.00	4
Loxahatchee Groves Park	37	Play Area	Play Area	Consider adding a second transfer system as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loxahatchee Groves Park	39	Play Area	Play Area	Provide an AR to swings for one of each type accessible. Pricing included with play are surface correction finding.  Add another ground level interactive play component on the route.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Loxahatchee Groves Park	40	Play Area	Play Area	Correct surface and add one more GLPC of a type other than swings and interactive to meet incentive scoping.  Pricing for surface correction and adding another interactive GLPC provided in a previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Loxahatchee Groves Park	42	Trail Surface	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	60	lin ft	\$3,552.00	4
Loxahatchee Groves Park	43	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	2150	lin ft	\$127,280.00	4
Loxahatchee Groves Park	44	Trail Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County fitness amenities accessible.	\$59.20	90	lin ft	\$5,328.00	4
Loxahatchee Groves Park	45	Men's Restroom	Toilet and Bathing Rooms	Raise mirror so top reflective surface is min 74" at the top.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	46	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	47	Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Loxahatchee Groves Park	48	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Loxahatchee Groves Park	51	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	52	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Loxahatchee Groves Park	53	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Loxahatchee Groves Park	54	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Loxahatchee Groves Park	55	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Loxahatchee Groves Park	56	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loxahatchee Groves Park	57	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Loxahatchee Groves Park	58	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Loxahatchee Groves Park	59	Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Loxahatchee Groves Park	60	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
<a href="#">Loxahatchee River Battlefield Park</a>	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Loxahatchee River Battlefield Park	2	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to elements.	\$59.20	1080	lin ft	\$63,936.00	1
Loxahatchee River Battlefield Park	3	Portable Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR at each location.	\$1,092.00	2	each	\$2,184.00	1
Loxahatchee River Battlefield Park	4	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. See route finding for cost reference.	\$0.00	1	staff time	\$0.00	2
Loxahatchee River Battlefield Park	5	Park Elements	Outdoor Recreation Access Route	Replace existing ORAR with a firm and stable material to Isa's Tree elements.	\$59.20	100	lin ft	\$5,920.00	5
Loxahatchee River Battlefield Park	6	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	200	lin ft	\$11,840.00	2
Loxahatchee River Battlefield Park	7	Chickee Shelter	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$59.20	49	lin ft	\$2,900.80	4
Loxahatchee River Battlefield Park	8	Chickee Shelter	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable.  In the alternative, leave as is and designate other County shelters accessible.	\$59.20	2400	sq ft	\$142,080.00	4
Loxahatchee River Battlefield Park	9	Chickee Shelter	Accessible Routes	Raise roof material to min 80", or pad object to prevent hazard in overhead clearance.  In the alternative, leave as is and designate other County shelters accessible.	\$1,500.00	1	each	\$1,500.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Loxahatchee River Battlefield Park	10	Chickee Shelter	Picnic Tables (C)	Replace at least two picnic tables with ones of accessible design as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	2	each	\$2,240.00	4
Loxahatchee River Battlefield Park	12	Trail Surface	Outdoor - Trails (C)	Leave as is - equestrian trails exempt.	\$0.00	1	staff time	\$0.00	4
Loxahatchee River Battlefield Park	13	Trail Surface	Outdoor - Trails (C)	Leave as is, equestrian trails exempt.	\$0.00	1	staff time	\$0.00	4
Loxahatchee River Battlefield Park	14	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. See following finding for cost reference.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Loxahatchee River Battlefield Park	15	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$59.20	316800	sq ft	\$18,754,560.00	4
Loxahatchee River Battlefield Park	16	Trail Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Loxahatchee River Battlefield Park	17	Trail Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Loxahatchee River Battlefield Park	18	Trail Elements	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$59.20	48	sq ft	\$2,841.60	5
Loxahatchee River Battlefield Park	19	Trail Elements	Outdoor - Constructed Features (C)	Correct surface at battle monument to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice	\$59.20	24	sq ft	\$1,420.80	2
Melear Park	1	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	350	lin ft	\$20,720.00	2
Melear Park	2	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	2
Melear Park	3	Park Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$1,120.00	1	each	\$1,120.00	4
Melear Park	4	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	5
Morikami Park	2	Parking - Visitor Center/Museum	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	3	Parking - Visitor Center/Museum	Parking - Off Street	Add van parking sign to 2 accessible stalls and repaint stall and access aisle to 12' and 5'.	\$283.50	2	each	\$567.00	1
Morikami Park	4	Parking - Visitor Center/Museum	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	12	each	\$36,750.00	1
Morikami Park	5	Parking - Staff Lot At Visitor Center/Museum	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Morikami Park	7	Parking - Oki Educational Center	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Morikami Park	8	Parking - Oki Educational Center	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
Morikami Park	9	Parking - Oki Educational Center	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Morikami Park	10	Parking - Oki Educational Center	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Morikami Park	12	Parking - Biwa Shelters	Parking - Off Street	Repaint stalls to be 12' d (144") wide each.	\$73.50	1	each	\$73.50	1
Morikami Park	13	Parking - Biwa Shelters	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	14	Parking - Biwa Shelters	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	2	each	\$5,600.00	1
Morikami Park	15	Parking - Biwa Shelters	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Morikami Park	16	Parking - Biwa Shelters	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Morikami Park	17	Parking - Biwa Shelters	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Morikami Park	19	Parking - Playground/Park	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	2	each	\$147.00	1
Morikami Park	20	Parking - Playground/Park	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Morikami Park	21	Parking - Playground/Park	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Morikami Park	22	Parking - Playground/Park	Parking - Off Street	Add curb ramps at the head of each access aisle connecting to min 44" wide accessible route.	\$1,487.50	3	each	\$4,462.50	1
Morikami Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Morikami Park	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Morikami Park	25	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Morikami Park	26	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%.	\$1,015.00	2	each	\$2,030.00	1
Morikami Park	27	Exterior Accessible Route	Curb Ramps	Correct slope of adjacent street surfaces to max 5%.	\$122.50	25	sq ft	\$3,062.50	1
Morikami Park	28	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Morikami Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	440	sq ft	\$53,900.00	1
Morikami Park	31	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Morikami Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Morikami Park	34	Exterior Accessible Route	Accessible Routes	Trim tree branches to min 80". Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Morikami Park	35	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Morikami Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Morikami Park	37	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Morikami Park	38	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Morikami Park	39	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	1	each	\$350.00	1
Morikami Park	40	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	41	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Morikami Park	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	4	each	\$12,250.00	1
Morikami Park	43	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Morikami Park	44	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
Morikami Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Morikami Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	47	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	6	each	\$750.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	48	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Morikami Park	49	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Morikami Park	50	Exterior Accessible Route	Accessible Routes	Widen EAR to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Morikami Park	51	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
Morikami Park	52	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	53	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  In the alternative, create a ramp with max 8.33% running slope, having compliant landings at top and bottoms of max 30" ramp runs, with compliant handrails on both sides.	\$3,062.50	3	each	\$9,187.50	1
Morikami Park	54	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	55	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	56	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	225	sq ft	\$27,562.50	1
Morikami Park	59	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Morikami Park	61	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, assure that duplicate material is available in the lower racks.	\$0.00	1	staff time	\$0.00	1
Morikami Park	62	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Morikami Park	63	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF. In the alternative, leave as is citing construction tolerance.	\$1,099.00	2	each	\$2,198.00	4
Morikami Park	64	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
Morikami Park	66	Public Spaces	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Morikami Park	67	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of items.	\$350.00	9	each	\$3,150.00	1
Morikami Park	69	Public Spaces	Assembly Areas	Advertise the availability of assisted listening devices, if available, or have resources for acquiring ALDs upon request.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	70	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$280.00	1	each	\$280.00	1
Morikami Park	71	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$280.00	1	each	\$280.00	1
Morikami Park	72	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$2,750.50	3	each	\$8,251.50	1
Morikami Park	74	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Morikami Park	75	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$280.00	1	each	\$280.00	1
Morikami Park	76	Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Morikami Park	77	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	78	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	79	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	1
Morikami Park	82	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	1
Morikami Park	83	Public Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	1
Morikami Park	84	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Morikami Park	85	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$560.00	1	each	\$560.00	1
Morikami Park	86	Public Spaces	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	2	each	\$280.00	1
Morikami Park	87	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Morikami Park	89	Public Spaces	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Morikami Park	90	Public Spaces	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.  Pricing in a previous finding.	\$0.00	2	each	\$0.00	3
Morikami Park	91	Public Spaces	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	1	each	\$525.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	92	Public Spaces	Stairways	<p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	5	each	\$625.00	5
Morikami Park	93	Public Spaces	Stairways	<p>Replace or remount handrails to 34" to 38" AFF.</p>	\$350.00	2	each	\$700.00	1
Morikami Park	94	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$280.00	1	each	\$280.00	1
Morikami Park	95	Public Spaces	Doors	<p>Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	1
Morikami Park	96	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	97	Employee Spaces	Room/Space (C)	<p>Make corrections for compliant 36" wide circulation path.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	98	Employee Spaces	Room/Space (C)	<p>Make corrections for compliant circulation path.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	99	Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$280.00	1	each	\$280.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	100	Employee Spaces	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Morikami Park	101	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Morikami Park	102	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Morikami Park	103	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Provide kick plate on push side of door from floor to 10" AFF.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$527.50	6	each	\$3,165.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	104	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Morikami Park	105	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Morikami Park	106	Employee Spaces	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Morikami Park	107	Employee Spaces	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Morikami Park	108	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Morikami Park	109	Employee Spaces	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Morikami Park	110	Employee Spaces	Toilet and Bathing Rooms	Relocate warming cabinet to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Morikami Park	111	Employee Spaces	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	112	Employee Spaces	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	113	Employee Spaces	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate stored items on bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	114	Employee Spaces	Turning Space	Relocate obstacles to create turning space in Kitchen restroom.	\$0.00	1	staff time	\$0.00	1
Morikami Park	115	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain closing speed on door closers.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	116	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, provide beveled threshold.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.  Extend a pathway away from the building for emergency egress.	\$3,483.75	1	each	\$3,483.75	3
Morikami Park	117	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$280.00	1	each	\$280.00	3
Morikami Park	118	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Morikami Park	119	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$60.00	7	each	\$420.00	3
Morikami Park	120	Employee Spaces	Turning Space	Relocate obstacles to create turning space in kitchenette.	\$3,360.00	1	each	\$3,360.00	3
Morikami Park	121	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide beveled threshold.	\$253.75	1	each	\$253.75	1
Morikami Park	122	Employee Spaces	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Morikami Park	123	Employee Spaces	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Morikami Park	124	Employee Spaces	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	125	Employee Spaces	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	126	Employee Spaces	Toilet and Bathing Rooms	Install rear grab bar that is 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	127	Employee Spaces	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	128	Employee Spaces	Turning Space	Relocate obstacles to create turning space in office men's restroom.	\$0.00	1	staff time	\$0.00	1
Morikami Park	129	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide beveled threshold.	\$253.75	1	each	\$253.75	1
Morikami Park	130	Employee Spaces	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Morikami Park	131	Employee Spaces	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Morikami Park	132	Employee Spaces	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Morikami Park	133	Employee Spaces	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Morikami Park	134	Employee Spaces	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	135	Employee Spaces	Toilet and Bathing Rooms	Install rear grab bar that is 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	136	Employee Spaces	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	137	Employee Spaces	Turning Space	Relocate obstacles to create turning space in office women's restroom.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	138	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Ramp CILs at door entries to max .25".</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, accessed when door is open or closed.</p>	\$11,547.00	1	each	\$11,547.00	3
Morikami Park	139	Employee Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	140	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Replace doors with ones having sidelight viewing windows max 43" AFF.</p>	\$346.50	4	each	\$1,386.00	3
Morikami Park	141	Theater	Doors	<p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$2,772.50	1	each	\$2,772.50	1
Morikami Park	142	Theater	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	143	Theater	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Morikami Park	144	Theater	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Morikami Park	145	Theater	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	2
Morikami Park	146	Theater	Plumbing Fixtures & Elements	Reduce threshold at shower to max .5" that is beveled.	\$96.25	6	each	\$577.50	2
Morikami Park	147	Theater	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2
Morikami Park	148	Theater	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Morikami Park	149	Theater	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening	\$350.00	1	each	\$350.00	2
Morikami Park	150	Theater	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	2
Morikami Park	151	Theater	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Morikami Park	152	Theater	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 44" AFF with reach over bench.	\$0.00	1	staff time	\$0.00	1
Morikami Park	153	Theater	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Morikami Park	154	Theater	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Morikami Park	155	Theater	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	2
Morikami Park	156	Theater	Plumbing Fixtures & Elements	Reduce threshold at shower to max .5" that is beveled.	\$96.25	6	each	\$577.50	1
Morikami Park	157	Theater	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2
Morikami Park	158	Theater	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Morikami Park	159	Theater	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$350.00	1	each	\$350.00	1
Morikami Park	160	Theater	Plumbing Fixtures & Elements	Provide the correct seat based on shower type.	\$840.00	1	each	\$840.00	2
Morikami Park	161	Theater	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Morikami Park	162	Theater	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	163	Theater	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$2,772.50	1	each	\$2,772.50	1
Morikami Park	164	Theater	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	4	each	\$560.00	1
Morikami Park	165	Theater	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats. Individual spaces shall be 36" wide, where two adjacent spaces are provided, they shall be 33" wide. Spaces shall be 48" deep when entered from the front or rear; if entered from the side, they shall be 60" deep.	\$898.75	1	each	\$898.75	1
Morikami Park	166	Theater	Assembly Areas	Provide a retractable arm and designation signage at accessible aisle seats.	\$410.50	4	each	\$1,642.00	1
Morikami Park	167	Theater	Assembly Areas	Provide signage informing patrons of the availability of assistive listening systems.	\$210.00	1	each	\$210.00	1
Morikami Park	168	Theater	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%; leave as is if technically infeasible.	\$6,510.00	2	each	\$13,020.00	3
Morikami Park	169	Theater	Custom/Special	Maintain or replace lift to ensure accessible route to stage and dressing rooms.	\$18,536.00	1	each	\$18,536.00	3
Morikami Park	170	Theater	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Morikami Park	171	Men's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	2	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	172	Men's Restroom	Toilet and Bathing Rooms	Replace signs with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Morikami Park	173	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Morikami Park	174	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Morikami Park	175	Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF. See later finding for recommendation for replacement and costs.	\$0.00	1	each	\$0.00	1
Morikami Park	176	Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Morikami Park	177	Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Morikami Park	178	Men's Restroom	Reach Ranges	Lower baby changer to be max 48" AFF to the handle, and 34" to surface when open.	\$0.00	1	each	\$0.00	1
Morikami Park	179	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Morikami Park	180	Men's Restroom	Toilet and Bathing Rooms	Relocate garbage can and paper towels to provide required 60" clearance around toilet  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	181	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	182	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	183	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	184	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate air freshener unit and paper towel dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	185	Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	186	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Morikami Park	187	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	188	Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Morikami Park	189	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Morikami Park	190	Women's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	2	staff time	\$0.00	1
Morikami Park	191	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Morikami Park	192	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Morikami Park	193	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Morikami Park	194	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Morikami Park	195	Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Morikami Park	196	Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	197	Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Morikami Park	198	Women's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
Morikami Park	199	Women's Restroom	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Morikami Park	200	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.  Pricing provided in the previous finding.	\$0.00	2	each	\$0.00	1
Morikami Park	201	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	202	Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	203	Women's Restroom	Toilet and Bathing Rooms	Relocate garbage can and paper towel dispenser to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	204	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	205	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	206	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	207	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate paper towel dispenser and air freshener unit a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	208	Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	209	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Morikami Park	210	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Morikami Park	211	Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	each	\$0.00	1
Morikami Park	212	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
Morikami Park	213	Cafe	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.	\$1,120.00	2	each	\$2,240.00	3
Morikami Park	214	Cafe	Accessible Routes	Relocate tables and chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Morikami Park	215	Cafe	Turning Space	Relocate obstacles to create turning space in café dining area.	\$0.00	1	staff time	\$0.00	1
Morikami Park	216	Cafe	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	217	Women's Cafe Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Morikami Park	218	Women's Cafe Restroom	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
Morikami Park	219	Women's Cafe Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Morikami Park	220	Women's Cafe Restroom	Toilet and Bathing Rooms	Relocate paper towels and garbage can to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	221	Women's Cafe Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	222	Women's Cafe Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	223	Women's Cafe Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate paper towel dispenser a min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Morikami Park	224	Women's Cafe Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	225	Women's Cafe Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Morikami Park	226	Women's Cafe Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Morikami Park	227	Women's Cafe Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Morikami Park	228	Women's Cafe Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	229	Men's Cafe Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$70.00	2	each	\$140.00	1
Morikami Park	230	Men's Cafe Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Morikami Park	231	Men's Cafe Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Morikami Park	232	Men's Cafe Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	1
Morikami Park	233	Men's Cafe Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Morikami Park	234	Men's Cafe Restroom	Toilet and Bathing Rooms	<p>Relocate paper towels and garbage can to provide required 60" clearance around toilet.</p> <p>Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.</p>	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	235	Men's Cafe Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	236	Men's Cafe Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	237	Men's Cafe Restroom	Toilet and Bathing Rooms	<p>Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.</p> <p>Relocate paper towel dispenser and air freshener unit a min 12" above or 1.5" below grab bar.</p>	\$0.00	3	staff time	\$0.00	1
Morikami Park	238	Men's Cafe Restroom	Toilet and Bathing Rooms	<p>Adjust stall door to be self-closing.</p> <p>Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.</p>	\$210.00	1	each	\$210.00	1
Morikami Park	239	Men's Cafe Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Morikami Park	240	Men's Cafe Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	241	Men's Cafe Restroom	Accessible Routes	Widen AR to urinal to compliant 36" clear width.	\$2,749.25	1	each	\$2,749.25	1
Morikami Park	242	Men's Cafe Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$233.25	3	each	\$699.75	1
				For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.					
				Provide required maneuvering clearance on push and pull side of doors.					
				Secure rug at door to prevent trip hazard.					
				Correct slope in door clearance to max 2.08%.					
				Fill gaps at door entries to max .5".					
				Inspect, adjust, and maintain 5 lbf to open interior doors.					
				Inspect, adjust, and maintain closing speed on door closers.					
				Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.					
Morikami Park	243	Basement	Room/Space (C)	Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$829.00	17	each	\$14,093.00	3
Morikami Park	244	Basement	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Morikami Park	245	Basement	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Morikami Park	246	Basement	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	247	Basement	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	248	Basement	Toilet and Bathing Rooms	Install rear grab bar that is 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	249	Basement	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	250	Basement	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	251	Basement	Turning Space	Relocate obstacles to create turning space in men's basement restroom.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	252	Basement	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Morikami Park	253	Basement	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Morikami Park	254	Basement	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	255	Basement	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	256	Basement	Toilet and Bathing Rooms	Install rear grab bar that is 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	257	Basement	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	258	Basement	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Morikami Park	259	Basement	Turning Space	Relocate obstacles to create turning space in women's basement restroom.	\$0.00	1	staff time	\$0.00	1
Morikami Park	261	Basement	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	4	staff time	\$0.00	3
Morikami Park	262	Signage	Signs	Mount compliant permanent space signage at all applicable locations.	\$210.00	30	each	\$6,300.00	1
Morikami Park	263	Oki Educational Center - Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Morikami Park	264	Oki Educational Center - Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3
Morikami Park	265	Oki Educational Center - Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Morikami Park	266	Oki Educational Center - Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	1	each	\$525.00	3
Morikami Park	267	Oki Educational Center - Exterior Accessible Route	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.	\$59.20	40	lin ft	\$2,368.00	1
Morikami Park	268	Oki Educational Center - Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Morikami Park	269	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	270	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	1
Morikami Park	271	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	1
Morikami Park	272	Public Spaces	Plumbing Fixtures & Elements	Provide required 30" X 48" CFS at accessible sinks	\$0.00	1	staff time	\$0.00	1
Morikami Park	273	Public Spaces	Accessible Routes	Provide a ramp for access to the back patio.	\$6,510.00	1	each	\$6,510.00	1
Morikami Park	274	Public Spaces	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Morikami Park	275	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$5,022.50	1	each	\$5,022.50	1
Morikami Park	276	Public Spaces	Accessible Routes	Relocate tables and chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Morikami Park	277	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Morikami Park	278	Public Spaces	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Morikami Park	279	Public Spaces	Entries (C)	Make corrections to entries to achieve 60% of public entries being accessible.  Pricing provided in a previous finding for entry barriers.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	280	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Provide kick plate on push side of door from floor to 10" AFF.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$2,115.75	2	each	\$4,231.50	3
Morikami Park	281	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	282	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p>	\$0.00	1	staff time	\$0.00	3
Morikami Park	283	Women's Restroom and Shower	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Morikami Park	284	Women's Restroom and Shower	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Morikami Park	285	Women's Restroom and Shower	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	2
Morikami Park	286	Women's Restroom and Shower	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
Morikami Park	287	Women's Restroom and Shower	Toilet and Bathing Rooms	<p>Relocate paper towels and garbage can to provide required 60" clearance around toilet.</p> <p>Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.</p>	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	288	Women's Restroom and Shower	Toilet and Bathing Rooms	Relocate Sanor System Unit a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	289	Women's Restroom and Shower	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	290	Women's Restroom and Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	292	Men's Restroom and Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Morikami Park	293	Men's Restroom and Shower	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	1
Morikami Park	294	Men's Restroom and Shower	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	2	each	\$420.00	1
Morikami Park	295	Men's Restroom and Shower	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Morikami Park	296	Men's Restroom and Shower	Toilet and Bathing Rooms	Relocate paper towels and garbage can to provide required 60" clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	297	Men's Restroom and Shower	Toilet and Bathing Rooms	Replace side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	298	Men's Restroom and Shower	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	299	Men's Restroom and Shower	Toilet and Bathing Rooms	Relocate Sanor System Unit a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	300	Men's Restroom and Shower	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	301	Men's Restroom and Shower	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Morikami Park	302	Men's Restroom and Shower	Plumbing Fixtures & Elements	Enlarge transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Morikami Park	303	Men's Restroom and Shower	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower	\$462.00	1	each	\$462.00	2
Morikami Park	304	Men's Restroom and Shower	Plumbing Fixtures & Elements	Lower shower controls to max 48" AFF.	\$467.25	1	each	\$467.25	2
Morikami Park	305	Men's Restroom and Shower	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Morikami Park	306	Men's Restroom and Shower	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening.	\$350.00	1	each	\$350.00	2
Morikami Park	307	Men's Restroom and Shower	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.  Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	2
Morikami Park	309	Building	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	310	Building	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$253.75	1	each	\$253.75	1
Morikami Park	311	Building	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	313	Building	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of items.	\$350.00	2	each	\$700.00	1
Morikami Park	314	Building	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$253.75	1	each	\$253.75	1
Morikami Park	316	Building	Viewing Areas (C)	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51".	\$0.00	1	staff time	\$0.00	1
Morikami Park	317	Building	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$253.75	1	each	\$253.75	1
Morikami Park	318	Building	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	319	Building	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Morikami Park	320	Building	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	321	Building	Signs	Replace sign with one having contrast and non-glare finish, mounted min. 40" AFF.	\$210.00	1	each	\$210.00	1
Morikami Park	322	Building	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$70.00	5	each	\$350.00	1
Morikami Park	323	Building	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Morikami Park	324	Building	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Morikami Park	325	Building	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	1	each	\$350.00	3
Morikami Park	326	Building	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface.	\$980.00	2	each	\$1,960.00	3
Morikami Park	327	Building	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	328	Building	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	329	Building	Toilet and Bathing Rooms	Remove stored items from grab bars and toilet tank and train staff to keep them unobstructed.	\$0.00	1	staff time	\$0.00	1
Morikami Park	330	Building	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	331	Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	332	Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace door closer with one allowing 80" overhead clearance.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$350.00	1	each	\$350.00	1
Morikami Park	333	Building	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	2
Morikami Park	334	Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Morikami Park	335	Building	Operable Parts	Replace garbage bin with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Morikami Park	337	Building	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	338	Building	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Morikami Park	339	Building	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Morikami Park	340	Building	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Morikami Park	341	Building	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Morikami Park	342	Building	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Morikami Park	343	Building	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	135	each	\$7,992.00	1
Morikami Park	344	Men's Restroom In Park Near Yamato Museum	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.  Remove, or relocate storage and fixtures in clearance around sink.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	345	Men's Restroom In Park Near Yamato Museum	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Morikami Park	346	Men's Restroom In Park Near Yamato Museum	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	1
Morikami Park	347	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	348	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. Adjust stall door to be self-closing.	\$2,749.25	1	each	\$2,749.25	1
Morikami Park	349	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door, mounted 34" to 48".	\$420.00	1	each	\$420.00	1
Morikami Park	350	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
Morikami Park	351	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	352	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	353	Men's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	354	Men's Restroom In Park Near Yamato Museum	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Morikami Park	355	Men's Restroom In Park Near Yamato Museum	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Morikami Park	356	Men's Restroom In Park Near Yamato Museum	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Morikami Park	357	Men's Restroom In Park Near Yamato Museum	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3
Morikami Park	358	Women's Restroom In Park Near Yamato Museum	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,846.25	1	each	\$1,846.25	1
Morikami Park	359	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	360	Women's Restroom In Park Near Yamato Museum	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	361	Women's Restroom In Park Near Yamato Museum	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	1
Morikami Park	362	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights. Adjust stall door to be self-closing.	\$5,510.75	1	each	\$5,510.75	1
Morikami Park	363	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door, mounted 34" to 48".	\$420.00	1	each	\$420.00	1
Morikami Park	364	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	365	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	366	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Replace grab bars in accessible stall with one providing 1.5" of clearance between the grab bar and the wall. Pricing in a previous finding.	\$0.00	1	each	\$0.00	1
Morikami Park	367	Women's Restroom In Park Near Yamato Museum	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	368	Women's Restroom In Park Near Yamato Museum	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Morikami Park	369	Women's Restroom In Park Near Yamato Museum	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Morikami Park	370	Gardens	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Morikami Park	371	Gardens	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Morikami Park	372	Gardens	Accessible Routes	Establish protocols for regular maintenance of surface to and around exhibit.	\$0.00	1	staff time	\$0.00	2
Morikami Park	374	Gardens	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	2
Morikami Park	375	Gardens	Accessible Routes	Trim tree branches to min 80". Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	1
Morikami Park	376	Gardens	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Morikami Park	377	Employee Spaces	Doors	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	378	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Morikami Park	379	Employee Spaces	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	3
Morikami Park	380	Employee Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$995.75	1	each	\$995.75	3
Morikami Park	381	Employee Spaces	Room/Space (C)	Correct or repair slope of ramp to max 8.33% and provide compliant handrails and landings.	\$6,510.00	1	each	\$6,510.00	3
Morikami Park	382	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.	\$253.75	1	each	\$253.75	3
Morikami Park	383	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Repair, provide beveled threshold.	\$2,941.50	3	each	\$8,824.50	3
Morikami Park	384	Park Element	Picnic Tables (C)	Replace both picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
Morikami Park	386	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Morikami Park	387	Park Element	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Morikami Park	388	Park Element	Custom/Special	Ensure that boardwalk is fully compliant when reopened.	\$0.00	1	staff time	\$0.00	1
Morikami Park	390	Park Element	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	392	Picnic Area	Shelters/Picnic Areas (C)	Provide min 2 accessible tables in picnic area to achieve the required number accessible, and provide min 36" clear ground space around all sides of the table as a smart practice.  Extend route to grills nearest the accessible tables and provide min 48" by 48" CGS at grills as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$1,577.00	2	each	\$3,154.00	4
Morikami Park	393	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 5% for surfaces other than concrete, asphalt or board as a smart practice.	\$122.50	525	sq ft	\$64,312.50	5
Morikami Park	394	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	395	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	420	sq ft	\$51,450.00	5
Morikami Park	396	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	540	sq ft	\$66,150.00	5
Morikami Park	397	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	398	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	399	Biwa Pavilion - ORAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	75	sq ft	\$9,187.50	5
Morikami Park	400	Pavilions	Outdoor - Trails (C)	Provide a ramped route for access to pavilion.	\$6,510.00	2	each	\$13,020.00	5
Morikami Park	401	Pavilions	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	402	Pavilions	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	3	each	\$19,530.00	3
Morikami Park	403	Pavilions	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	3
Morikami Park	404	Pavilions	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Morikami Park	405	Pavilions	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of plant overgrowth along ramp and ramp handrails.	\$0.00	1	staff time	\$0.00	3
Morikami Park	406	Pavilions	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	407	Pavilions	Shelters/Picnic Areas (C)	Lower rims of garbage cans at shelter to 15" to 48" AFF. Replace or lower one grill to 34" max height of cooking surface.	\$41.75	6	each	\$250.50	5
Morikami Park	408	Pavilions	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	409	Pavilions	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Morikami Park	410	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
Morikami Park	411	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Morikami Park	412	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	5	lin ft	\$296.00	4
Morikami Park	413	Shelters	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Morikami Park	414	Shelters	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Morikami Park	415	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Morikami Park	416	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	5	lin ft	\$296.00	4
Morikami Park	417	Shelters	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Morikami Park	418	Biwa Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
Morikami Park	419	Biwa Playground	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.	\$350.00	1	each	\$350.00	5
Morikami Park	420	Biwa Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	421	Biwa Playground	Play Area	Lower platform on transfer system to 11" to 18" AFF, in the alternative, add and maintain surface fill level to achieve the same.	\$0.00	1	staff time	\$0.00	2
Morikami Park	422	Biwa Playground	Play Area	See previous finding for surface replacement.	\$0.00	1	each	\$0.00	2
Morikami Park	423	Biwa Playground	Play Area	See previous finding for surface replacement.	\$0.00	1	each	\$0.00	2
Morikami Park	424	Biwa Playground	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.	\$0.00	1	staff time	\$0.00	2
Morikami Park	425	Biwa Playground	Play Area	See previous finding for surface replacement.	\$0.00	1	each	\$0.00	2
Morikami Park	426	Biwa Playground	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Morikami Park	427	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Morikami Park	428	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Morikami Park	429	Biwa Pavilion Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	430	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	431	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	432	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	433	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	434	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	435	Biwa Pavilion Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	436	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$210.00	1	each	\$210.00	1
Morikami Park	437	Biwa Pavilion Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Morikami Park	438	Biwa Pavilion Women's Restroom	Hazards	Reverse stall door to swing out due to lack of required depth for inward swinging door and switch hinge and latch sides; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	439	Biwa Pavilion Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Morikami Park	440	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Morikami Park	441	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Morikami Park	442	Biwa Pavilion Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	443	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Morikami Park	444	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	445	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Morikami Park	446	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Morikami Park	447	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Morikami Park	448	Biwa Pavilion Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Morikami Park	449	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Morikami Park	450	Biwa Pavilion Men's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door and switch hinge and latch sides; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$2,749.25	1	each	\$2,749.25	1
Morikami Park	451	Biwa Pavilion Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Morikami Park	452	Biwa Pavilion Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Morikami Park	453	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface as a smart practice.	\$210.00	1	each	\$210.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	456	Trail Element	Signs	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements.  Remount signage to be along an accessible route with unobstructed text.	\$210.00	1	each	\$210.00	5
Morikami Park	457	Trail Element	Signs	Replace signage with compliant signage, and relocate along an accessible route with level CGS as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	458	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	459	Trail Element	Signs	Replace signage with compliant signage and relocate along an accessible route with level CGS as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	460	Trail Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Morikami Park	462	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface and raise sign to 40" AGL as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	463	Trail Element	Signs	Remount signage to min 40" AFF as a smart practice.	\$0.00	1	staff time	\$0.00	5
Morikami Park	464	Trail Element	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max 2" for surfaces other than concrete, asphalt or boards	\$96.25	3	each	\$288.75	5
Morikami Park	465	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface, mounted 40" AGL as a smart practice.	\$210.00	2	each	\$420.00	5
Morikami Park	466	Trail Element	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Morikami Park	467	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	468	Trail Element	Signs	Remount signage to min 40" AFF as a smart practice.	\$0.00	1	staff time	\$0.00	5
Morikami Park	469	Trail Element	Signs	Remount signage to min 40" AFF as a smart practice.	\$0.00	1	staff time	\$0.00	5
Morikami Park	471	Trail Element	Signs	Replace sign with one having contrasting color and on a non-glare surface and mount min 40" AGL as a smart practice.	\$210.00	1	each	\$210.00	5
Morikami Park	472	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	3300	lin ft	\$195,360.00	4
Morikami Park	473	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Morikami Park	474	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Morikami Park	475	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	15	each	\$1,443.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	476	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Morikami Park	477	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of plants along trail to ensure compliant clear width.	\$0.00	1	staff time	\$0.00	5
Morikami Park	478	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	7	each	\$673.75	5
Morikami Park	479	Trail Surface	Outdoor - Trails (C)	Replace existing surface with an accessible surface such as EWF, boardwalk, crushed stone, or asphalt with compliant slopes and CILs.	\$59.20	15	lin ft	\$888.00	5
Morikami Park	480	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of plants along trail to ensure compliant trail width.	\$0.00	1	staff time	\$0.00	5
Morikami Park	481	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	11	each	\$1,058.75	5
Morikami Park	482	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Morikami Park	483	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	484	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Morikami Park	485	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	486	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	487	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	488	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	489	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Morikami Park	490	Trail Surface	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	27	each	\$3,375.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	491	Trail Surface	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	5	each	\$4,900.00	1
Morikami Park	492	Trail Surface	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	5	each	\$1,750.00	1
Morikami Park	493	Trail Surface	Accessible Routes	Raise entry gate to min 80", or pad object to prevent hazard in overhead clearance.	\$350.00	1	each	\$350.00	3
Morikami Park	494	Trail Surface	Stairways	Leave as is inaccessible stairs; maintain other paths as accessible routes and mount signage indicating accessible route location.	\$210.00	1	each	\$210.00	3
Morikami Park	495	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
Morikami Park	496	Trail Surface	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	3
Morikami Park	497	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Morikami Park	498	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	499	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	500	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Morikami Park	501	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of plants along trial to ensure compliant width and surface.	\$0.00	1	staff time	\$0.00	5
Morikami Park	502	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.	\$0.00	1	staff time	\$0.00	5
Morikami Park	503	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	3	lin ft	\$177.60	5
Morikami Park	504	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Morikami Park	505	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of trail surface to ensure compliant trial width.	\$0.00	1	staff time	\$0.00	5
Morikami Park	506	Educational Center/Maintenance - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	507	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	960	sq ft	\$117,600.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Morikami Park	508	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	35	sq ft	\$4,287.50	5
Morikami Park	509	Educational Center/Maintenance - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Morikami Park	510	Educational Center/Maintenance - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	13	each	\$1,251.25	5
Morikami Park	511	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Morikami Park	512	Educational Center/Maintenance - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Morikami Park	513	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Morikami Park	514	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
Morikami Park	515	Educational Center/Maintenance - Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
Morikami Park	516	Educational Center/Maintenance - Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Morikami Park	517	Educational Center/Maintenance - Trail Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
North County Aquatic Complex	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	5	each	\$367.50	1
North County Aquatic Complex	3	Parking	Parking - Off Street	Add van parking sign to 2 accessible stalls and repaint stalls and access aisles to 11' and 5'.	\$283.50	2	each	\$567.00	1
North County Aquatic Complex	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	10	each	\$30,625.00	1
North County Aquatic Complex	5	Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.  Correct or fill gaps to max .5".  Resurface front entry left accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$6,177.50	1	each	\$6,177.50	1
North County Aquatic Complex	6	Parking	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
North County Aquatic Complex	7	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
North County Aquatic Complex	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
North County Aquatic Complex	10	Exterior Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	1
North County Aquatic Complex	14	Trailhead	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$59.20	700	lin ft	\$41,440.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	15	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
North County Aquatic Complex	16	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
North County Aquatic Complex	17	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.  Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
North County Aquatic Complex	18	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$3,298.75	1	each	\$3,298.75	3
North County Aquatic Complex	19	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$3,500.00	1	each	\$3,500.00	3
North County Aquatic Complex	20	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$3,080.00	1	each	\$3,080.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	21	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$5,545.00	1	each	\$5,545.00	3
North County Aquatic Complex	22	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25".  Provide kick plate on push side of door from floor to 10" AFF.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$236.25	1	each	\$236.25	3
North County Aquatic Complex	23	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25".  Provide kick plate on push side of door from floor to 10" AFF.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$236.25	1	each	\$236.25	3
North County Aquatic Complex	24	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Provide kick plate on push side of door from floor to 10" AFF.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$8,925.00	1	each	\$8,925.00	3
North County Aquatic Complex	25	Employee Spaces	Room/Space (C)	For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	1	each	\$0.00	4
North County Aquatic Complex	26	Employee Spaces	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	3
North County Aquatic Complex	27	Employee Spaces	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	28	Employee Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$1,750.00	1	each	\$1,750.00	3
North County Aquatic Complex	29	Employee Spaces	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room	\$5,498.50	1	each	\$5,498.50	3
North County Aquatic Complex	30	Public Spaces	Accessible Routes	Relocate or reposition tables and chairs to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	31	Public Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
North County Aquatic Complex	32	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	33	Public Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$332.50	1	each	\$332.50	1
North County Aquatic Complex	34	Public Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
North County Aquatic Complex	35	Public Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
North County Aquatic Complex	36	Public Spaces	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	3	each	\$1,260.00	2
North County Aquatic Complex	37	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
North County Aquatic Complex	38	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	39	Men's Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted min 34" and max 48".</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$2,404.50	1	each	\$2,404.50	1
North County Aquatic Complex	40	Men's Restroom	Toilet and Bathing Rooms	<p>Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.</p> <p>Remount signage to the proper location based on the type of door provided.</p>	\$210.00	1	staff time	\$210.00	1
North County Aquatic Complex	41	Men's Restroom	Toilet and Bathing Rooms	<p>Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.</p>	\$350.00	2	each	\$700.00	1
North County Aquatic Complex	42	Men's Restroom	Clear Floor Space	<p>Relocate paper towel dispenser to provide 30" by 48" clear floor space at sink in stall.</p>	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	43	Men's Restroom	Plumbing Fixtures & Elements	<p>Adjust timing of sink faucets to remain on for min. 10 seconds.</p>	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	44	Men's Restroom	Plumbing Fixtures & Elements	<p>Insulate exposed pipes under one sink in main area.</p>	\$77.00	1	each	\$77.00	1
North County Aquatic Complex	45	Men's Restroom	Reach Ranges	<p>Lower baby changing table to max 48" above the finished floor (AFF) to highest operable part.</p> <p>Lower soap dispensers in main area to max 44" above the finished floor (AFF) for a forward reach over sink or counter.</p> <p>Repair lower hand dryer to provide one of each type of element accessible.</p>	\$350.00	1	each	\$350.00	1
North County Aquatic Complex	46	Men's Restroom	Clear Floor Space	<p>Remove, or relocate storage in CFS at fixtures and operable parts along the AR.</p>	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	47	Men's Restroom	Toilet and Bathing Rooms	<p>Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.</p>	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	48	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.  Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
North County Aquatic Complex	49	Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
North County Aquatic Complex	50	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount pipes to provide clearance min 12" above grab bar and min 1.5" below grab bar; leave as is if pipe location is required by another code.	\$393.75	1	each	\$393.75	1
North County Aquatic Complex	51	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	52	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.  Pricing for removing or relocating hand dryer in accessible stall provided in a previous finding.	\$350.00	9	each	\$3,150.00	1
North County Aquatic Complex	53	Men's Restroom	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of restroom floor surface.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	54	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	4	each	\$12,250.00	1
North County Aquatic Complex	55	Men's Locker Room	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$3,202.50	1	each	\$3,202.50	1
North County Aquatic Complex	56	Men's Locker Room	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48".	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	57	Men's Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	58	Men's Locker Room	Plumbing Fixtures & Elements	Acquire and remount grab bars to the correct location in the shower, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	2	each	\$787.50	1
North County Aquatic Complex	59	Men's Locker Room	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
North County Aquatic Complex	60	Men's Locker Room	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF.	\$393.75	1	each	\$393.75	1
North County Aquatic Complex	61	Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
North County Aquatic Complex	62	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
North County Aquatic Complex	63	Women's Restroom	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model	\$2,380.00	1	each	\$2,380.00	1
North County Aquatic Complex	64	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	65	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
North County Aquatic Complex	66	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower baby changing table so work surface is 28" to 34" AFF with required knee and toe clearances.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	67	Women's Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
North County Aquatic Complex	68	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.  Remount toilet pipes to not interfere with grab bar; leave as is if pipe location is required by a different code.	\$393.75	2	each	\$787.50	1
North County Aquatic Complex	69	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	70	Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
North County Aquatic Complex	71	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	72	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	4	each	\$1,400.00	1
North County Aquatic Complex	73	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	3	each	\$9,187.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	74	Women's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	1
North County Aquatic Complex	75	Women's Locker Room	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	76	Women's Locker Room	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	1
North County Aquatic Complex	77	Women's Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
North County Aquatic Complex	78	Women's Locker Room	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	1
North County Aquatic Complex	79	Main Pool	Pool / Spa	Relocate lift to an area providing 36" X 48" CFS having max slope of 2.08%.	\$3,062.50	1	each	\$3,062.50	2
North County Aquatic Complex	80	Main Pool	Pool / Spa	Provide two handrails on pool stairs, mounted 20" to 24" apart.	\$980.00	1	each	\$980.00	2
North County Aquatic Complex	81	Main Pool	Pool / Spa	Install compliant sloped entry in wading pool; if technically infeasible leave as is.	\$7,140.00	1	each	\$7,140.00	2
North County Aquatic Complex	82	Main Pool	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
North County Aquatic Complex	83	Main Pool	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
North County Aquatic Complex	84	Main Pool	Picnic Tables (C)	Replace three picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	3	each	\$3,360.00	5
North County Aquatic Complex	85	Main Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1850	sq ft	\$226,625.00	3
North County Aquatic Complex	86	Main Pool	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	2
North County Aquatic Complex	88	Main Pool	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
North County Aquatic Complex	89	Main Pool	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
North County Aquatic Complex	90	Main Pool	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	2
North County Aquatic Complex	91	Main Pool	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	3	each	\$1,050.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
North County Aquatic Complex	92	Main Pool	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.  Correct or repair slope in CFS to max 2.08%.	\$8,197.00	1	each	\$8,197.00	5
North County Aquatic Complex	93	Children's Wading Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	2
North County Aquatic Complex	94	Children's Wading Pool	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$3,202.50	1	each	\$3,202.50	2
North County Aquatic Complex	95	Children's Wading Pool	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
North County Aquatic Complex	96	Children's Wading Pool	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Cay Park	1	Parking - East Lot	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Ocean Cay Park	2	Parking - East Lot	Parking - Off Street	Relocate the two new and required stalls to be on the shortest AR to the building entry or park features.	\$367.50	2	each	\$735.00	1
Ocean Cay Park	3	Parking - East Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Ocean Cay Park	4	Parking - East Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	6	each	\$18,375.00	1
Ocean Cay Park	5	Parking - East Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	2	each	\$420.00	1
Ocean Cay Park	6	Parking - East Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Ocean Cay Park	7	Parking - West Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Ocean Cay Park	8	Parking - West Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Ocean Cay Park	9	Parking - West Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Ocean Cay Park	10	Parking - West Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Ocean Cay Park	11	Parking - West Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Ocean Cay Park	12	Parking - West Lot	Parking - Off Street	Correct or repair CIL and gaps in access aisle.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Cay Park	14	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	175	sq ft	\$21,437.50	1
Ocean Cay Park	15	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	16	Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Ocean Cay Park	17	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	7	each	\$2,303.00	5
Ocean Cay Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Cay Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Ocean Cay Park	20	Exterior Accessible Route	Curb Ramps	Correct slope of side flares to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Ocean Cay Park	21	Exterior Accessible Route	Curb Ramps	Correct slope of side flares to max 8.33%.	\$1,015.00	2	each	\$2,030.00	1
Ocean Cay Park	22	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Ocean Cay Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Cay Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	355	sq ft	\$43,487.50	1
Ocean Cay Park	25	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Ocean Cay Park	26	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AGL.	\$350.00	1	each	\$350.00	1
Ocean Cay Park	27	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Ocean Cay Park	28	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Cay Park	29	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Ocean Cay Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Cay Park	31	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	5	each	\$481.25	1
Ocean Cay Park	32	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
Ocean Cay Park	33	Exterior Accessible Route	Accessible Routes	Remove sand and plant overgrowth to widen EAR to min 36" clear width.  Establish protocols for regular and frequent inspection and maintenance of walkway surfaces	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	34	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Cay Park	35	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Cay Park	36	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Ocean Cay Park	37	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Ocean Cay Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Cay Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	80	sq ft	\$9,800.00	1
Ocean Cay Park	40	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Cay Park	41	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	42	Sports Fields/Courts	Park Site (C)	Provide an accessible route (AR) to at least two volleyball courts.	\$59.20	10	lin ft	\$592.00	2
Ocean Cay Park	43	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08% at one bike rack.	\$122.50	25	sq ft	\$3,062.50	1
Ocean Cay Park	46	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Cay Park	47	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Ocean Cay Park	48	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Ocean Cay Park	49	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Cay Park	50	Park Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Ocean Cay Park	52	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Ocean Cay Park	55	Roselle & Perry Como Picnic Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.  Correct or repair ORAR cross slope to max 2.08% as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$3,158.75	1	each	\$3,158.75	4
Ocean Cay Park	56	Roselle & Perry Como Picnic Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Ocean Cay Park	57	Roselle & Perry Como Picnic Pavilion	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Ocean Cay Park	58	Roselle & Perry Como Picnic Pavilion	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
Ocean Cay Park	59	Roselle & Perry Como Picnic Pavilion	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Ocean Cay Park	60	Anita Lankler Picnic Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Ocean Cay Park	61	Anita Lankler Picnic Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	62	Anita Lankler Picnic Pavilion	Outdoor - Constructed Features (C)	Relocate accessible tables to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Ocean Cay Park	63	Anita Lankler Picnic Pavilion	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
Ocean Cay Park	64	Anita Lankler Picnic Pavilion	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Replace operable part with one usable without a tight pinch or grasp.	\$560.00	1	each	\$560.00	5
Ocean Cay Park	65	Picnic Shelters	Outdoor - Constructed Features (C)	Replace one table with one of an accessible design as a smart practice.  Relocate accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Ocean Cay Park	66	Picnic Shelters	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	6	lin ft	\$355.20	4
Ocean Cay Park	67	Picnic Shelters	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space.  Replace or lower grill to max height of cooking surface 34", and that can be operated with one hand and with a max force of 5 lbf.  Relocate 20% of garbage cans to be along AR, with max slope in CGS of 2.08%.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$125.00	2	each	\$250.00	4
Ocean Cay Park	68	Picnic Shelters	Accessible Routes	Maintain overhead clearance of min. 80". In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Cay Park	69	Picnic Shelters	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	70	Picnic Shelters	Outdoor - Constructed Features (C)	<p>Replace one table with one of an accessible design as a smart practice.</p> <p>Relocate accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$1,120.00	1	each	\$1,120.00	4
Ocean Cay Park	71	Picnic Shelters	Shelters, Picnic Facilities (C)	<p>Create an ORAR to shelter or picnic area features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$59.20	5	each	\$296.00	4
Ocean Cay Park	72	Picnic Shelters	Clear Floor Space	<p>Relocate 20% of garbage cans to be along AR, with max slope in CGS of 2.08%. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$0.00	1	staff time	\$0.00	4
Ocean Cay Park	73	Picnic Shelters	Outdoor Recreation Access Routes (C)	<p>Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$122.50	25	sq ft	\$3,062.50	4
Ocean Cay Park	74	Picnic Shelters	Outdoor Recreation Access Routes (C)	<p>Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$122.50	50	sq ft	\$6,125.00	4
Ocean Cay Park	75	Picnic Shelters	Outdoor - Constructed Features (C)	<p>Replace one table with one of an accessible design as a smart practice.</p> <p>Relocate accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$1,120.00	1	each	\$1,120.00	4
Ocean Cay Park	76	Picnic Shelters	Shelters, Picnic Facilities (C)	<p>Create an ORAR to shelter or picnic area features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$59.20	10	lin ft	\$592.00	4
Ocean Cay Park	77	Picnic Shelters	Outdoor Recreation Access Routes (C)	<p>Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$96.25	1	each	\$96.25	4
Ocean Cay Park	78	Picnic Shelters	Picnic Tables (C)	<p>Replace one picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$1,120.00	1	each	\$1,120.00	4
Ocean Cay Park	79	Picnic Shelters	Shelters, Picnic Facilities (C)	<p>Create an ORAR to shelter or picnic area features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$59.20	15	lin ft	\$888.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	80	Picnic Shelters	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Cay Park	81	Beach Access Route	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	30	lin ft	\$1,776.00	1
Ocean Cay Park	82	Beach Access Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Ocean Cay Park	83	Beach Access Route	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of ramp surfaces.	\$0.00	1	staff time	\$0.00	3
Ocean Cay Park	84	Beach Access Route	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of ramp landing surface.	\$0.00	1	staff time	\$0.00	3
Ocean Cay Park	85	Beach Access Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	2	each	\$192.50	3
Ocean Cay Park	86	Beach Access Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	2	each	\$192.50	3
Ocean Cay Park	87	Beach Access Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	5	each	\$1,750.00	3
Ocean Cay Park	88	Beach Access Route	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.	\$59.20	280	lin ft	\$16,576.00	5
Ocean Cay Park	89	Playground	Play Area	Create designated entry a min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
Ocean Cay Park	90	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Ocean Cay Park	91	Playground	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs provided	\$2,800.00	1	each	\$2,800.00	2
Ocean Cay Park	92	Playground	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Ocean Cay Park	94	Playground	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.	\$0.00	1	staff time	\$0.00	2
Ocean Cay Park	95	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	96	Men's Restroom	Plumbing Fixtures & Elements	Replace one main area sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Ocean Cay Park	97	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Ocean Cay Park	98	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Ocean Cay Park	99	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last installed before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Ocean Cay Park	100	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Ocean Cay Park	101	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	102	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Cay Park	103	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	104	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Cay Park	105	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	106	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Cay Park	107	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	109	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	110	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	111	Women's Restroom	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Ocean Cay Park	112	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Cay Park	113	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Ocean Cay Park	114	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last installed before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Ocean Cay Park	115	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Ocean Cay Park	116	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Ocean Cay Park	117	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Cay Park	118	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Cay Park	119	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	120	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Cay Park	121	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Cay Park	122	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace doors with ones having sidelight viewing windows max 43" AFF.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$6,061.25	1	each	\$6,061.25	3
Ocean Cay Park	123	Lifeguard Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	3
Ocean Cay Park	124	Lifeguard Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering, mounted on wall latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3
Ocean Cay Park	125	Lifeguard Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$350.00	1	each	\$350.00	3
Ocean Cay Park	126	Lifeguard Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
Ocean Cay Park	128	Employee Spaces	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Ocean Cay Park	129	Employee Spaces	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	1	each	\$420.00	3
Ocean Cay Park	130	Employee Spaces	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Cay Park	131	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Ocean Inlet Park	1	Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Ocean Inlet Park	3	Parking	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	2	each	\$147.00	1
Ocean Inlet Park	4	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	5	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	4	each	\$11,200.00	1
Ocean Inlet Park	7	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Ocean Inlet Park	8	Parking	Parking - Off Street	Add van parking sign to one accessible stall and ensure stall and access aisle are min 12' and 5'	\$283.50	1	each	\$283.50	1
Ocean Inlet Park	9	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Ocean Inlet Park	10	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	11	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	13	Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.  Establish protocols for regular and frequent inspection and maintenance of walkway surfaces leading to and from accessible parking spaces.	\$367.50	1	each	\$367.50	1
Ocean Inlet Park	14	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Ocean Inlet Park	15	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	\$283.50	1	each	\$283.50	1
Ocean Inlet Park	16	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	17	Parking	Parking - Off Street	Regrade or relocate stall to prevent frequent water pooling.  In the alternative, establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$1,589.00	1	each	\$1,589.00	1
Ocean Inlet Park	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	19	Exterior Accessible Route	Curb Ramps	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%.	\$1,487.50	1	each	\$1,487.50	1
Ocean Inlet Park	20	Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%.  Correct or fill gaps to max .5".  Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$1,440.25	1	each	\$1,440.25	1
Ocean Inlet Park	21	Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%	\$1,015.00	1	each	\$1,015.00	1
Ocean Inlet Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Ocean Inlet Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Ocean Inlet Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	26	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Ocean Inlet Park	27	Exterior Accessible Route	Curb Ramps	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%.  Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$1,816.50	2	each	\$3,633.00	1
Ocean Inlet Park	28	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	6	each	\$750.00	5
Ocean Inlet Park	29	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Ocean Inlet Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	75	sq ft	\$9,187.50	1
Ocean Inlet Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	32	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	165	sq ft	\$20,212.50	1
Ocean Inlet Park	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	135	sq ft	\$16,537.50	1
Ocean Inlet Park	35	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Ocean Inlet Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Ocean Inlet Park	37	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	38	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.  Establish protocols for frequent inspection and maintenance of areas where water pools.	\$122.50	75	sq ft	\$9,187.50	1
Ocean Inlet Park	40	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	24	each	\$3,000.00	5
Ocean Inlet Park	41	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Ocean Inlet Park	42	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	43	Exterior Accessible Route	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	13	each	\$1,625.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	44	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	1	each	\$980.00	1
Ocean Inlet Park	45	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Ocean Inlet Park	46	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install compliant handrails on both sides of ramp.	\$980.00	2	each	\$1,960.00	3
Ocean Inlet Park	47	Exterior Accessible Route	Ramps (Not Curb Ramps)	See previous finding for addition of compliant handrails.	\$0.00	1	each	\$0.00	3
Ocean Inlet Park	48	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	49	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	50	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	51	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	52	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	53	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	4	lin ft	\$236.80	1
Ocean Inlet Park	54	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	55	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.  In the alternative, correct slope to max 8.33% and add required landings and handrails to make this path a ramp.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	56	Exterior Accessible Route	Accessible Routes	Maintain route to min 36" clear width	\$1,540.00	1	each	\$1,540.00	1
Ocean Inlet Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Inlet Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	85	sq ft	\$10,412.50	2
Ocean Inlet Park	59	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	60	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	765	sq ft	\$2,342,812.50	2
Ocean Inlet Park	61	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	74	each	\$7,122.50	1
Ocean Inlet Park	62	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element; in the alternative, leave as is and designate other County fishing piers as accessible.	\$6,510.00	1	each	\$6,510.00	4
Ocean Inlet Park	63	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Inlet Park	64	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	65	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Inlet Park	66	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to one bench. Relocate garbage can to be along AR.	\$59.20	25	lin ft	\$1,480.00	5
Ocean Inlet Park	67	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to one bench. Relocate garbage can to be along AR.	\$59.20	25	lin ft	\$1,480.00	5
Ocean Inlet Park	68	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Ocean Inlet Park	69	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4"	\$420.00	1	each	\$420.00	2
Ocean Inlet Park	70	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Ocean Inlet Park	71	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Ocean Inlet Park	72	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
Ocean Inlet Park	73	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to outdoor rinsing shower and one bench. Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR.	\$1,900.00	2	each	\$3,800.00	5
Ocean Inlet Park	74	Park Elements	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice	\$3,062.50	1	each	\$3,062.50	5
Ocean Inlet Park	75	Park Elements	Accessible Routes	Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
Ocean Inlet Park	76	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	2
Ocean Inlet Park	77	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Relocate garbage can to be along AR.	\$0.00	1	staff time	\$0.00	2
Ocean Inlet Park	79	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice. Correct or repair slope in CFS to max 2.08%.	\$3,603.25	1	each	\$3,603.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	81	Park Elements	Outdoor - Constructed Features (C)	Remount or replace one shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Inlet Park	82	Park Elements	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	2
Ocean Inlet Park	84	Park Elements	Accessible Routes	Relocate one fish cleaning station to be along AR.	\$350.00	1	each	\$350.00	2
Ocean Inlet Park	85	Park Elements	Reach Ranges	Remount operable parts of vending machines to be in reach range of 15" min to 48" max. In the alternative, contact vendor to replace machines.	\$350.00	2	each	\$700.00	2
Ocean Inlet Park	86	Shelters	Outdoor Recreation Access Routes (C)	Establish protocols for regular and frequent inspection and maintenance of shelter entry and route surfaces.	\$0.00	1	staff time	\$0.00	5
Ocean Inlet Park	87	Shelters	Shelters, Picnic Facilities (C)	Establish protocols for regular and frequent inspection and maintenance of shelter surfaces.	\$0.00	1	staff time	\$0.00	5
Ocean Inlet Park	88	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Ocean Inlet Park	89	Shelters	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	45	lin ft	\$2,664.00	4
Ocean Inlet Park	90	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Ocean Inlet Park	91	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
Ocean Inlet Park	92	Shelters	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Inlet Park	93	Shelters	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	45	lin ft	\$2,664.00	4
Ocean Inlet Park	94	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Ocean Inlet Park	95	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	96	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
Ocean Inlet Park	97	Shelters	Reach Ranges	Remount garbage bins to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$116.50	3	each	\$349.50	4
Ocean Inlet Park	98	Shelters	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	35	lin ft	\$2,072.00	4
Ocean Inlet Park	99	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Ocean Inlet Park	100	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	20	lin ft	\$1,184.00	4
Ocean Inlet Park	101	Shelters	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	45	lin ft	\$2,664.00	4
Ocean Inlet Park	102	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Ocean Inlet Park	103	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Ocean Inlet Park	104	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	20	lin ft	\$1,184.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	105	Shelters	Reach Ranges	Remount garbage cans to be in reach range of 15" min to 48" max.  Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$116.50	3	each	\$349.50	4
Ocean Inlet Park	106	Shelters	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Ocean Inlet Park	107	Shelters	Reach Ranges	Remount garbage cans to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Inlet Park	108	Shelters	Accessible Routes	Raise beams to min 80", or pad object to prevent hazard in overhead clearance. In the alternative, leave as is and designate other County picnic facilities accessible.	\$140.00	6	each	\$840.00	4
Ocean Inlet Park	109	Shelters	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Ocean Inlet Park	110	Shelters	Reach Ranges	Remount garbage can and cigarette disposal container to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	5
Ocean Inlet Park	111	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Ocean Inlet Park	112	Shelters	Accessible Routes	Raise posts to min 80", or pad object to prevent hazard in overhead clearance. In the alternative, leave as is and designate other County picnic facilities accessible.	\$140.00	6	each	\$840.00	4
Ocean Inlet Park	113	Shelters	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Ocean Inlet Park	114	Shelters	Reach Ranges	Remount fishing line disposal container to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Inlet Park	115	Shelters	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Ocean Inlet Park	116	Shelters	Reach Ranges	Remount garbage can to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Ocean Inlet Park	117	Beach Front	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice	\$59.20	120	lin ft	\$7,104.00	5
Ocean Inlet Park	118	Beach Front	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.	\$59.20	50	lin ft	\$2,960.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	119	Beach Front	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.	\$59.20	120	lin ft	\$7,104.00	5
Ocean Inlet Park	120	Beach Front	Stairways	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible.	\$404.25	1	each	\$404.25	2
Ocean Inlet Park	121	Beach Front	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	8	each	\$1,000.00	5
Ocean Inlet Park	122	Beach Front	Stairways	Repair nosings to be curved or beveled and extend max 1.5" over the tread.	\$84.00	1	each	\$84.00	1
Ocean Inlet Park	123	Beach Front	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	1
Ocean Inlet Park	124	Beach Front	Stairways	See previous finding for addition of two compliant handrails.	\$0.00	1	each	\$0.00	1
Ocean Inlet Park	125	Beach Front	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	100	each	\$98,000.00	3
Ocean Inlet Park	126	Beach Front	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection.	\$525.00	4	each	\$2,100.00	2
Ocean Inlet Park	127	Beach Front	Beach Access Route (C)	Create a beach access route to high tide level of a firm and stable material as a smart practice.	\$59.20	100	lin ft	\$5,920.00	5
Ocean Inlet Park	128	Boat Dock	Custom/Special	Ensure compliance with scoping and technical requirements when boat dock is reopened.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	129	Ocean Overlook	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Ocean Inlet Park	130	Ocean Overlook	Accessible Routes	Remove benches to provide 36" wide route.	\$0.00	2	staff time	\$0.00	3
Ocean Inlet Park	131	Ocean Overlook	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	1	each	\$980.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	132	Ocean Overlook	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	1
Ocean Inlet Park	133	Ocean Overlook	Viewing Areas (C)	Provide an unobstructed view between 32" and 51" as a smart practice.	\$980.00	1	each	\$980.00	2
Ocean Inlet Park	134	Jetty/Fishing Area	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element; in the alternative, leave as is and designate other County fishing areas accessible.	\$6,510.00	1	each	\$6,510.00	4
Ocean Inlet Park	135	Jetty/Fishing Area	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$0.00	1	staff time	\$0.00	5
Ocean Inlet Park	136	Jetty/Fishing Area	Dining, Bar and Work Surfaces	Replace or lower one fish cleaning station work surface to min 28" and max 34". Relocate one fish cleaning station to be along AR.	\$1,120.00	1	each	\$1,120.00	2
Ocean Inlet Park	137	Jetty/Fishing Area	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Ocean Inlet Park	138	Jetty/Fishing Area	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Inlet Park	139	Jetty/Fishing Area	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	14	each	\$13,720.00	4
Ocean Inlet Park	140	Jetty/Fishing Area	Accessible Routes	Raise posts to min 80", or pad object to prevent hazard in overhead clearance.	\$140.00	6	each	\$840.00	3
Ocean Inlet Park	141	Jetty/Fishing Area	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Ocean Inlet Park	142	Jetty/Fishing Area	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Ocean Inlet Park	143	Jetty/Fishing Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	144	Jetty/Fishing Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$7,024.50	1	each	\$7,024.50	3
Ocean Inlet Park	145	Jetty/Fishing Area	Reach Ranges	Remount fishing line disposal container to be in reach range of 15" min to 48" max.  Correct or repair slope in CFS to max 2.08%.	\$1,531.25	2	each	\$3,062.50	2
Ocean Inlet Park	147	5-12 Play Area	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	25	lin ft	\$1,480.00	4
Ocean Inlet Park	148	5-12 Play Area	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Inlet Park	149	5-12 Play Area	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.  Relocate informational signage to be along the AR with a 30" by 48" level CFS for viewing.  In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	1	each	\$350.00	4
Ocean Inlet Park	150	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Ocean Inlet Park	151	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Inlet Park	152	5-12 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	153	5-12 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	154	5-12 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	155	2-5 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  Pricing provided in a previous finding for the 5-12 play area with shared surface.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	156	2-5 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	157	2-5 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	158	2-5 Play Area	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Ocean Inlet Park	159	Loop Trail At West End Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Ocean Inlet Park	160	Loop Trail At West End Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Ocean Inlet Park	161	Loop Trail At West End Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
Ocean Inlet Park	162	Loop Trail At West End Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Ocean Inlet Park	163	Loop Trail At West End Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
Ocean Inlet Park	164	Loop Trail At West End Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Ocean Inlet Park	165	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	166	Women's Restroom Within Observation Deck Area	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Inlet Park	167	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Inlet Park	168	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Ocean Inlet Park	169	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	170	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	171	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Replace side grab bars with ones 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Ocean Inlet Park	172	Women's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	173	Women's Restroom Within Observation Deck Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	174	Women's Restroom Within Observation Deck Area	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Ocean Inlet Park	175	Men's Restroom Within Observation Deck Area	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Inlet Park	176	Men's Restroom Within Observation Deck Area	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Ocean Inlet Park	177	Men's Restroom Within Observation Deck Area	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	178	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Inlet Park	179	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Ocean Inlet Park	180	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Ocean Inlet Park	181	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	182	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Ocean Inlet Park	183	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	184	Men's Restroom Within Observation Deck Area	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	185	Men's Restroom Within Observation Deck Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	186	Men's Restroom Within Observation Deck Area	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remount locking hardware a min 34" and max 48".	\$514.50	1	each	\$514.50	1
Ocean Inlet Park	187	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	188	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Inlet Park	189	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	190	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Ocean Inlet Park	191	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Inlet Park	192	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Install rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Inlet Park	193	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	194	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Ocean Inlet Park	195	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	196	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	197	Womens Restroom On South Lake Worth Inlet Side (Jetty Side)	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Ocean Inlet Park	198	Mens Restroom By Fishing	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	199	Mens Restroom By Fishing	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Ocean Inlet Park	200	Mens Restroom By Fishing	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Ocean Inlet Park	201	Mens Restroom By Fishing	Toilet and Bathing Rooms	Install rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" AFF	\$393.75	1	each	\$393.75	1
Ocean Inlet Park	202	Mens Restroom By Fishing	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Pricing provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	203	Mens Restroom By Fishing	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Inlet Park	204	Mens Restroom By Fishing	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet. In the alternative, leave as is citing construction tolerance.	\$420.00	1	each	\$420.00	4
Ocean Inlet Park	205	Mens Restroom By Fishing	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Ocean Inlet Park	206	Mens Restroom By Fishing	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Inlet Park	207	Mens Restroom By Fishing	Accessible Routes	Correct or repair slope to max 2.08% in restroom. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Inlet Park	208	Mens Restroom By Fishing	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace closer to provide 80" overhead clearance.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount hardware at 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$864.50	1	each	\$864.50	1
Ocean Inlet Park	209	Portable Toilets Outside Of Sheriff's Marine Unit	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Ocean Reef Park	2	Parking - Small North Lot	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1
Ocean Reef Park	3	Parking - Small North Lot	Parking - Off Street	Repaint access aisles to be 5' (60") each.	\$73.50	2	each	\$147.00	1
Ocean Reef Park	4	Parking - Small North Lot	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Ocean Reef Park	5	Parking - Small North Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	1	each	\$210.00	1
Ocean Reef Park	6	Parking - Small North Lot	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Ocean Reef Park	8	Parking - Large South/Main Lot	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1
Ocean Reef Park	9	Parking - Large South/Main Lot	Parking - Off Street	Repaint access aisles to be 5' (60") each.	\$73.50	3	each	\$220.50	1
Ocean Reef Park	10	Parking - Large South/Main Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. Leave as is 2.3% slopes citing construction tolerance.	\$3,062.50	10	each	\$30,625.00	1
Ocean Reef Park	11	Parking - Large South/Main Lot	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	12	Parking - Large South/Main Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	7	each	\$1,470.00	1
Ocean Reef Park	13	Parking - Large South/Main Lot	Parking - Off Street	Add two van parking signs to two accessible stalls and ensure stalls and access aisles are 12' and 5'.	\$210.00	2	each	\$420.00	1
Ocean Reef Park	14	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Ocean Reef Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	105	sq ft	\$12,862.50	1
Ocean Reef Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Ocean Reef Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	140	sq ft	\$17,150.00	1
Ocean Reef Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	7	each	\$673.75	1
Ocean Reef Park	20	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Ocean Reef Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Reef Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Reef Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	13	each	\$1,251.25	1
Ocean Reef Park	25	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	18	each	\$5,922.00	5
Ocean Reef Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	27	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Reef Park	28	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Ocean Reef Park	29	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
Ocean Reef Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Ocean Reef Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1
Ocean Reef Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Ocean Reef Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Reef Park	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	37	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Ocean Reef Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Ocean Reef Park	41	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Ocean Reef Park	42	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Ocean Reef Park	43	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Ocean Reef Park	44	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	45	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	4	lin ft	\$236.80	2
Ocean Reef Park	46	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Ocean Reef Park	48	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Ocean Reef Park	49	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Ocean Reef Park	50	Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Ocean Reef Park	52	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Ocean Reef Park	53	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	6	each	\$577.50	5
Ocean Reef Park	54	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	1	each	\$350.00	5
Ocean Reef Park	55	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	<p>Replace existing amenities with ones of an accessible design and provide required clear ground space.</p> <p>Replace or lower grill to max height of cooking surface 34".</p> <p>Adjust operating mechanism of ash doors and cooking surface to be usable with 5 lbf or less.</p> <p>Replace grill handles with ones usable without a tight pinch or grasp.</p>	\$167.50	4	each	\$670.00	5
Ocean Reef Park	56	Shelters/Picnic Areas	Picnic Tables (C)	<p>Replace four picnic tables with ones of an accessible design as a smart practice.</p> <p>In the alternative, leave as is and designate other County picnic areas accessible.</p>	\$1,120.00	4	each	\$4,480.00	4
Ocean Reef Park	57	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	<p>Create an ORAR to grills and provide accessible features as a smart practice.</p> <p>Relocate 20% of garbage cans to be along AR.</p> <p>In the alternative, leave as is and designate other County picnic areas accessible.</p>	\$59.20	100	lin ft	\$5,920.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	58	Beach	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	10	lin ft	\$592.00	4
Ocean Reef Park	59	Beach	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of ramp surfaces.  In the alternative, leave as is and designate other County beaches accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Reef Park	60	Beach	Beach Access Route (C)	Correct or fill opening along the BAR to be max .5" and travel perpendicular to path of travel as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$96.25	2	each	\$192.50	4
Ocean Reef Park	61	Beach	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$6,510.00	4	each	\$26,040.00	4
Ocean Reef Park	62	Beach	Park Site (C)	Provide an accessible route (AR) to the base of lifeguard towers.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	225	lin ft	\$13,320.00	4
Ocean Reef Park	63	Beach	Beach Access Route (C)	Correct or repair running slopes along the BAR to max 5% for any distance, 8.33% for 50' max or 10% for 30' max as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	870	sq ft	\$106,575.00	4
Ocean Reef Park	64	Beach	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$96.25	10	each	\$962.50	4
Ocean Reef Park	66	Beach	Beach Access Route (C)	Correct or repair running slopes along the BAR to max 5% for any distance, 8.33% for 50' max or 10% for 30' max as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	100	each	\$12,250.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	67	Beach	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of ramp surfaces.  In the alternative, leave as is and designate other County beaches accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Reef Park	68	Beach	Beach Access Route (C)	Correct or fill opening along the BAR to be max .5" and travel perpendicular to path of travel as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$96.25	1	each	\$96.25	4
Ocean Reef Park	69	Beach	Beach Access Route (C)	Create a beach access route to mean high water level level of a firm and stable material as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	335	lin ft	\$19,832.00	4
Ocean Reef Park	70	Parking Lot Guard House	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Provide kick plate on push side of door from floor to 10" AFF.  Extend a pathway away from the building for emergency egress.	\$732.00	1	each	\$732.00	3
Ocean Reef Park	71	5-12 Play Area	Play Area	Correct slope at designated entry to max 5%.  In the alternative, leave as is and designate other County playgrounds accessible.	\$3,062.50	1	each	\$3,062.50	4
Ocean Reef Park	72	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Ocean Reef Park	73	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Ocean Reef Park	75	5-12 Play Area	Play Area	See previous finding for surface correction.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	76	5-12 Play Area	Play Area	Add 1 more GLPC's of any other type to meet incentive scoping. See previous finding for surface recommendation.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Ocean Reef Park	77	South Women's Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	78	South Women's Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	79	South Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	80	South Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Reef Park	81	South Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	82	South Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Reef Park	83	South Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	84	South Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Ocean Reef Park	85	South Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	86	South Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	87	South Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	88	South Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	89	South Men's Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	90	South Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	91	South Men's Restroom	Clear Floor Space	Relocate hand dryer for CFS at fixtures and operable parts .	\$350.00	1	each	\$350.00	1
Ocean Reef Park	92	South Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	93	South Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Reef Park	94	South Men's Restroom	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF. Price included in later finding.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	95	South Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Ocean Reef Park	96	South Men's Restroom	Plumbing Fixtures & Elements	Replace one urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Ocean Reef Park	97	South Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at lowered urinal to max 48" AFF. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
Ocean Reef Park	98	South Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	99	South Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Reef Park	100	South Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	101	South Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Ocean Reef Park	102	South Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	103	South Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	104	South Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	staff time	\$350.00	1
Ocean Reef Park	105	North Women's Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	106	North Women's Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	107	North Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	108	North Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Ocean Reef Park	109	North Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Reef Park	110	North Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Reef Park	111	North Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Ocean Reef Park	112	North Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Ocean Reef Park	113	North Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Reef Park	114	North Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	115	North Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$196.75	2	each	\$393.50	1
Ocean Reef Park	116	North Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	117	North Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$514.50	1	each	\$514.50	1
Ocean Reef Park	118	North Men's Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	119	North Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	120	North Men's Restroom	Clear Floor Space	Relocate hand dryer for CFS at fixtures and operable parts	\$350.00	1	each	\$350.00	1
Ocean Reef Park	121	North Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Ocean Reef Park	122	North Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Ocean Reef Park	123	North Men's Restroom	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Ocean Reef Park	124	North Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Ocean Reef Park	125	North Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at lowered urinal to max 48" AFF. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
Ocean Reef Park	126	North Men's Restroom	Reach Ranges	Remount hand dryer to be in reach range of 15" min to 48" max.  Remount ambulatory stall door hardware to be in reach range of 34" min to 48" max.	\$175.00	2	each	\$350.00	1
Ocean Reef Park	127	North Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Ocean Reef Park	128	North Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Ocean Reef Park	129	North Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Ocean Reef Park	130	North Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Ocean Reef Park	131	North Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	132	North Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	133	North Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Ocean Reef Park	134	North Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Ocean Reef Park	135	Lifeguard Office Employee Restroom and Locker Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,037.00	1	each	\$5,037.00	1
Ocean Reef Park	136	Lifeguard Office Employee Restroom and Locker Room	Signs	Restroom not accessible, acquire and mount signage directing users to accessible restroom.	\$210.00	1	each	\$210.00	1
Ocean Reef Park	137	Lifeguard Office Employee Restroom and Locker Room	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering, mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Ocean Reef Park	138	Lifeguard Office Employee Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice).	\$420.00	1	each	\$420.00	2
Ocean Reef Park	139	Lifeguard Office Employee Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	2
Ocean Reef Park	140	Lifeguard Office Employee Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	2
Ocean Reef Park	141	Lifeguard Office Employee Restroom and Locker Room	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Reef Park	142	Lifeguard Office Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Correct slope in door clearance to max 2.08%.  Repair, provide beveled threshold.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$2,296.50	3	each	\$6,889.50	3
Ocean Ridge Hammock Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Ocean Ridge Hammock Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Ocean Ridge Hammock Park	4	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information	\$210.00	2	each	\$420.00	1
Ocean Ridge Hammock Park	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'	\$210.00	1	each	\$210.00	1
Ocean Ridge Hammock Park	6	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Ocean Ridge Hammock Park	7	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	60	lin ft	\$3,552.00	3
Ocean Ridge Hammock Park	8	Park Elements	Clear Floor Space	Relocate beach clean-up station along an accessible route and provide a 30" by 48" clear floor space with an accessible surface at station.	\$1,225.00	1	each	\$1,225.00	3
Ocean Ridge Hammock Park	9	Park Elements	Clear Floor Space	Relocate 20% of garbage cans to be along AR, with a level and compliant surface in clear ground space.	\$0.00	1	staff time	\$0.00	2
Ocean Ridge Hammock Park	11	Park Elements	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	3
Ocean Ridge Hammock Park	12	Park Elements	Accessible Routes	Replace drain grate with one having max gaps of .5".	\$5,000.00	1	each	\$5,000.00	3
Ocean Ridge Hammock Park	13	Beach Access Route	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	400	lin ft	\$23,680.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Ocean Ridge Hammock Park	14	Beach Access Route	Beach Access Route (C)	Create a beach access route to mean high water level level of a firm and stable material as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$59.20	200	lin ft	\$11,840.00	4
Ocean Ridge Hammock Park	15	Beach Access Route	Beach Access Route (C)	Correct or repair running slopes along the BAR to max 5% for any distance, 8.33% for 50' max or 10% for 30' max as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$217.00	128	lin ft	\$27,776.00	4
Ocean Ridge Hammock Park	16	Beach Access Route	Beach Access Route (C)	Correct or fill opening along the BAR to be max .5" and travel perpendicular to path of travel as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$96.25	1	each	\$96.25	4
Ocean Ridge Hammock Park	17	Beach Access Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.  In the alternative, leave as is and designate other County beaches accessible.	\$122.50	25	sq ft	\$3,062.50	4
Okeeheelee Park	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	6	sq ft	\$18,375.00	1
Okeeheelee Park	4	Parking	Parking - Off Street	Maintain accessible parking stalls and access aisles to be firm, stable, and maneuverable and to be free of debris.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	5	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	6	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	7	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	8	Public Spaces	Accessible Routes	Widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	9	Public Spaces	Turning Space	Relocate obstacles to create turning space in library.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	10	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	11	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	12	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	13	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at accessible work surfaces.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	14	Public Spaces	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	15	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	16	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	17	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	18	Public Spaces	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$840.00	4	each	\$3,360.00	1
Okeeheelee Park	19	Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	20	Public Spaces	Plumbing Fixtures & Elements	Lower sink height to max 34" AFF.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	21	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	22	Public Spaces	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	23	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	24	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	3	each	\$1,050.00	1
Okeeheelee Park	25	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	4	each	\$700.00	1
Okeeheelee Park	26	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	27	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors along the public circulation route, widen doors to 36" for recessed doors.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$4,522.50	1	each	\$4,522.50	1
Okeeheelee Park	28	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	3	each	\$420.00	1
Okeeheelee Park	29	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	30	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF, in the alternative, train staff to come out from around the counter to provide customer service.  Remount operable parts to be in reach range of 15" min to 48" max.	\$599.67	3	each	\$1,799.01	1
Okeeheelee Park	31	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	32	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Okeeheelee Park	33	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	34	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	35	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	36	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4". Pricing addressed in previous finding.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	37	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	38	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$1,894.25	1	each	\$1,894.25	1
Okeeheelee Park	39	Public Spaces	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	40	Public Spaces	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	41	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	42	Public Spaces	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	43	Public Spaces	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	44	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	7	each	\$2,450.00	1
Okeeheelee Park	45	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	46	Public Spaces	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	47	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	48	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).</p>	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	49	Public Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	50	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	51	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	52	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	54	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	12	staff time	\$0.00	1
Okeeheelee Park	55	Public Spaces	Signs	Remount signage to min 40" above the finished floor (AFF).	\$0.00	10	staff time	\$0.00	1
Okeeheelee Park	56	Public Spaces	Turning Space	Provide min 60" turning space at observation area.	\$875.00	1	each	\$875.00	1
Okeeheelee Park	57	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	58	Public Spaces	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" above the finished floor (AFF).	\$980.00	2	each	\$1,960.00	1
Okeeheelee Park	59	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	8	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	60	Public Spaces	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	61	Public Spaces	Doors	Mount signage at entrance designating it as accessible.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	62	Public Spaces	Signs	Mount compliant permanent space signage at all applicable locations.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	63	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	6	staff time	\$0.00	1
Okeeheelee Park	64	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	7	staff time	\$0.00	1
Okeeheelee Park	65	Public Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	66	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	67	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	68	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	3	staff time	\$0.00	3
Okeeheelee Park	69	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 5 lbf to open interior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	70	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain closing speed on door closers.  Provide kick plate on push side of door from floor to 10" AFF.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Okeeheelee Park	71	Employee Spaces	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	1	each	\$1,750.00	3
Okeeheelee Park	72	Employee Spaces	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	3
Okeeheelee Park	73	Employee Spaces	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised characters, mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	74	Employee Spaces	Dining, Bar and Work Surfaces	Relocate storage at work table to provide knee and toe clearance.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	75	Employee Spaces	Plumbing Fixtures & Elements	Lower sink height to max 34" AFF.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	76	Employee Spaces	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	77	Employee Spaces	Accessible Routes	Widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	78	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	79	Employee Spaces	Accessible Routes	Widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	80	Employee Spaces	Turning Space	Relocate obstacles to create turning space in closet.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	81	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	82	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	83	Employee Spaces	Accessible Routes	Create an accessible route (AR) with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.  Repair, bevel or ramp change in level (CIL) to building entrance.	\$1,576.25	1	each	\$1,576.25	3
Okeeheelee Park	84	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	12	each	\$1,155.00	1
Okeeheelee Park	85	Exterior Accessible Route	Accessible Routes	Repair, bevel, or ramp changes in level to max .25".	\$96.25	6	each	\$577.50	1
Okeeheelee Park	86	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	10	each	\$9,800.00	2
Okeeheelee Park	87	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	9	each	\$0.00	2
Okeeheelee Park	88	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	1
Okeeheelee Park	89	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60"	\$875.00	1	each	\$875.00	1
Okeeheelee Park	90	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	3
Okeeheelee Park	91	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	92	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	4	each	\$3,920.00	2
Okeeheelee Park	93	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	4	each	\$0.00	2
Okeeheelee Park	94	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	2
Okeeheelee Park	95	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" above the finished floor. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	96	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Okeeheelee Park	97	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	3
Okeeheelee Park	98	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Okeeheelee Park	99	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	3
Okeeheelee Park	100	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	4	each	\$3,920.00	2
Okeeheelee Park	101	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	4	each	\$0.00	2
Okeeheelee Park	102	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1050	sq ft	\$128,625.00	1
Okeeheelee Park	103	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	21	each	\$2,021.25	1
Okeeheelee Park	104	Exterior Accessible Route	Signs	Remount signage to min 40" above grade.	\$350.00	2	each	\$700.00	5
Okeeheelee Park	105	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	106	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	108	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	109	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	110	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	500	sq ft	\$61,250.00	1
Okeeheelee Park	111	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	112	Exterior Accessible Route	Accessible Routes	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk	\$367.50	1	each	\$367.50	1
Okeeheelee Park	113	Exterior Accessible Route	Curb Ramps	Install required detectable warnings at curb ramps along the public right of way or at curb ramps within a site as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	114	Exterior Accessible Route	Parking - Off Street	Designate an access aisle for the passenger drop off area by painting an aisle that is 60" wide and 20' long.	\$367.50	1	each	\$367.50	1
Okeeheelee Park	115	Exterior Accessible Route	Accessible Routes	Relocate 20% of garbage cans to be along the accessible route (AR) and within reach range between 15" and 48".	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	116	Exterior Accessible Route	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	24	sq ft	\$2,940.00	2
Okeeheelee Park	117	Exterior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	120	Exterior Accessible Route	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	9	each	\$3,150.00	1
Okeeheelee Park	121	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	122	Men's Restroom	Toilet and Bathing Rooms	Install mirror in accessible stall and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	123	Men's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Okeeheelee Park	124	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	125	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
Okeeheelee Park	126	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	127	Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	128	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	129	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	130	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	131	Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including access symbol.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	132	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.  Install mirror in accessible stall with bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	133	Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Okeeheelee Park	134	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
Okeeheelee Park	135	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	136	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$175.00	2	each	\$350.00	1
Okeeheelee Park	137	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	138	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	139	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	140	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	141	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	142	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount sink away from rear grab bar, or min 12" above or 1.5" below grab bar.  Pricing addressed in previous finding.	\$0.00	3	each	\$0.00	1
Okeeheelee Park	143	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	144	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	145	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	146	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	147	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Okeeheelee Park	148	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	149	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	150	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	151	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	152	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	153	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Okeeheelee Park	154	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	155	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	720	sq ft	\$88,200.00	5
Okeeheelee Park	156	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Okeeheelee Park	157	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	185	sq ft	\$22,662.50	5
Okeeheelee Park	158	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	159	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Okeeheelee Park	160	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	1530	lin ft	\$90,576.00	5
Okeeheelee Park	161	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	1320	lin ft	\$78,144.00	5
Okeeheelee Park	162	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	5016	lin ft	\$296,947.20	5
Okeeheelee Park	163	Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	530	lin ft	\$31,376.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	164	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	2	each	\$700.00	5
Okeeheelee Park	165	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	1	each	\$350.00	5
Okeeheelee Park	166	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	1	each	\$350.00	5
				Replace signage with compliant signage.					
Okeeheelee Park	167	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$210.00	1	each	\$210.00	5
Okeeheelee Park	168	Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	170	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	1	each	\$350.00	5
Okeeheelee Park	171	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	1	each	\$350.00	5
Okeeheelee Park	172	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	1	each	\$350.00	5
Okeeheelee Park	173	Trail Elements	Accessible Routes	Raise beam to min 80", or pad object to prevent hazard in overhead clearance.	\$1,540.00	1	each	\$1,540.00	5
Okeeheelee Park	174	Trail Elements	Viewing Areas (C)	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51"	\$980.00	1	each	\$980.00	2
Okeeheelee Park	175	Trail Elements	Outdoor - Constructed Features (C)	Provide required 36" by 48" clear ground space at viewing scope, centered on the eye piece as a smart practice	\$750.00	1	each	\$750.00	5
Okeeheelee Park	176	Trail Elements	Outdoor - Constructed Features (C)	Lower eyepiece on viewing scope to min 43" and max 51"; in the alternative, add a second scope that meets the standard as a smart practice.	\$4,000.00	1	each	\$4,000.00	5
Okeeheelee Park	177	Trail Elements	Clear Floor Space	Provide required 30" by 48" CGS at signs.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	178	Trail Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	10	sq ft	\$1,225.00	2
Okeeheelee Park	179	Trail Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	2
Okeeheelee Park	180	Trail Elements	Signs	Remount signage to min 40" above grade (AGL).	\$350.00	3	each	\$1,050.00	5
Okeeheelee Park	182	Trail Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Okeeheelee Park	183	Trail Elements	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	1	each	\$514.50	5
Okeeheelee Park	184	Trail Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	3
Okeeheelee Park	185	Trail Elements	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$350.00	1	each	\$350.00	5
Okeeheelee Park	187	Maintenance - Employee Parking Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	188	Maintenance - Employee Parking Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	189	Maintenance - Employee Parking Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	190	New Maintenance Building - Employee Spaces	Accessible Routes	Relocate furniture to widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	191	New Maintenance Building - Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	3
Okeeheelee Park	192	New Maintenance Building - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	193	New Maintenance Building - Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Okeeheelee Park	194	New Maintenance Building - Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	195	New Maintenance Building - Employee Spaces	Reach Ranges	Remount first aid kit to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	196	New Maintenance Building - Employee Spaces	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along the accessible route (AR).	\$1,092.00	1	each	\$1,092.00	1
Okeeheelee Park	197	New Maintenance Building - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$2,385.00	7	each	\$16,695.00	3
Okeeheelee Park	198	New Maintenance Building - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	199	New Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	200	New Maintenance Building - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	201	New Maintenance Building - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	202	New Maintenance Building - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at urinal.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	203	New Maintenance Building - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	204	New Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Relocate cabinet and urinal to provide required 60" clearance around toilet.	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	205	New Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	206	New Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	207	New Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	208	New Maintenance Building - Men's Restroom	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	209	New Maintenance Building - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	210	New Maintenance Building - Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	211	New Maintenance Building - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	212	New Maintenance Building - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	213	New Maintenance Building - Women's Restroom and Locker Room	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	214	New Maintenance Building - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	215	New Maintenance Building - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	216	New Maintenance Building - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	217	New Maintenance Building - Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	218	New Maintenance Building - Women's Restroom and Locker Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	219	New Maintenance Building - Women's Restroom and Locker Room	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	220	New Maintenance Building - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" above the finished floor (AFF).	\$420.00	1	each	\$420.00	2
Okeeheelee Park	221	New Maintenance Building - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Provide required 30" by 48" clear floor space (CFS) at designated accessible lockers.	\$840.00	1	each	\$840.00	3
Okeeheelee Park	222	New Maintenance Building - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	223	New Maintenance Building - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" above the finished floor (AFF) and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	224	New Maintenance Building - Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Okeeheelee Park	225	New Maintenance Building - Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Provide appropriate clear floor space (CFS) on the exterior of the transfer shower.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	226	New Maintenance Building - Women's Restroom and Locker Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	227	Old Maintenance Building - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,946.00	3	each	\$8,838.00	3
Okeeheelee Park	228	Old Maintenance Building - Employee Spaces	Accessible Routes	Widen exterior access route (EAR) to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	229	Old Maintenance Building - Employee Spaces	Accessible Routes	Relocate furniture to widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	230	Old Maintenance Building - Employee Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	3
Okeeheelee Park	231	Old Maintenance Building - Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Okeeheelee Park	232	Old Maintenance Building - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	233	Old Maintenance Building - Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$3,955.25	1	each	\$3,955.25	3
Okeeheelee Park	234	Old Maintenance Building - Single User Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	235	Old Maintenance Building - Single User Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille and raised lettering, and mount on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	236	Old Maintenance Building - Single User Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$4,522.50	1	each	\$4,522.50	1
Okeeheelee Park	238	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Okeeheelee Park	239	Parking	Accessible Routes	Widen accessible route or mount signage to prohibit cars from parking and obstructing accessible route.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	240	Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.  Correct or fill gaps in stalls and access aisles.  Maintain accessible stalls and access aisles to be free of debris.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	241	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	11	each	\$33,687.50	1
Okeeheelee Park	242	Parking	Parking - Off Street	Add van parking signs to two accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	243	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	244	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Okeeheelee Park	245	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	246	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	247	Exterior Accessible Route	Accessible Routes	Remove obstruction for 36" clear width along the AR	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	248	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	249	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	3	each	\$9,187.50	1
Okeeheelee Park	250	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%	\$6,510.00	2	each	\$13,020.00	1
Okeeheelee Park	251	Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5"	\$96.25	4	each	\$385.00	1
Okeeheelee Park	252	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	1
Okeeheelee Park	253	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through; in the alternative, correct or fill gap along sides of ramp.	\$525.00	2	each	\$1,050.00	1
Okeeheelee Park	254	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%	\$1,015.00	1	each	\$1,015.00	1
Okeeheelee Park	255	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeehetee Park	256	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Okeehetee Park	257	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeehetee Park	258	Exterior Accessible Route	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	15	each	\$1,875.00	5
Okeehetee Park	259	Exterior Accessible Route	Accessible Routes	Replace drain grate with one having max gaps of .5".	\$5,000.00	1	each	\$5,000.00	1
Okeehetee Park	260	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeehetee Park	261	Exterior Accessible Route	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	20	each	\$2,500.00	5
Okeehetee Park	262	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Okeehetee Park	263	Exterior Accessible Route	Accessible Routes	Secure mat to prevent tripping hazard.	\$140.00	1	each	\$140.00	1
Okeehetee Park	264	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeehetee Park	265	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeehetee Park	266	Exterior Accessible Route	Accessible Routes	Remove obstruction for 36" clear width along the AR	\$0.00	1	staff time	\$0.00	1
Okeehetee Park	267	Exterior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	2
Okeehetee Park	268	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Okeehetee Park	269	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeehetee Park	270	Park Site Amenities	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice.	\$350.00	6	each	\$2,100.00	5
Okeehetee Park	271	Park Site Amenities	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	272	Park Site Amenities	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Okeeheelee Park	273	Park Site Amenities	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	5
Okeeheelee Park	275	Public Spaces	Accessible Routes	Secure mats to prevent tripping hazard.	\$140.00	4	each	\$560.00	1
Okeeheelee Park	276	Public Spaces	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$236.25	1	each	\$236.25	1
Okeeheelee Park	277	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	278	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$140.00	4	each	\$560.00	1
Okeeheelee Park	279	Public Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	280	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	281	Public Spaces	Accessible Routes	Widen AR to compliant 36" clear width	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	282	Public Spaces	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	283	Public Spaces	Dressing / Fitting / Locker Rooms	Enlarge dressing stalls to 60" by 60" clear inside dimension	\$1,036.00	1	each	\$1,036.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	284	Public Spaces	Dressing / Fitting / Locker Rooms	Install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	1
Okeeheelee Park	285	Public Spaces	Accessible Routes	Secure mats to prevent tripping hazard.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	286	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	1
Okeeheelee Park	287	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	288	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances	\$1,120.00	2	each	\$2,240.00	1
Okeeheelee Park	289	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of bar seating with one providing knee and toe clearances and having a dining surface between 28" and 34"	\$1,120.00	1	each	\$1,120.00	1
Okeeheelee Park	290	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	291	Public Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	292	Public Spaces	Signs	Mount compliant signage at all doors along the egress route	\$210.00	2	each	\$420.00	1
Okeeheelee Park	293	Public Spaces	Signs	Mount compliant signage at all doors along the egress route	\$210.00	2	each	\$420.00	1
Okeeheelee Park	294	Public Spaces	Sales and Service Counters/Tables	Keep lowered counter free of storage and display items.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	295	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" aff	\$1,099.00	1	each	\$1,099.00	1
Okeeheelee Park	296	Public Spaces	Reach Ranges	Remount lock hardware to be in reach range of 34" min to 48" max	\$350.00	1	each	\$350.00	1
Okeeheelee Park	298	Public Spaces	Elevators & Lifts	Replace operable part of communication system with one usable without a tight pinch or grasp	\$100.00	1	each	\$100.00	3
Okeeheelee Park	299	Public Spaces	Elevators & Lifts	Adjust re-entry timing so door stays open for min 20 seconds	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	300	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" aff	\$1,099.00	1	each	\$1,099.00	1
Okeeheelee Park	302	Public Spaces	Clear Floor Space	Correct or repair slope in CGS to max 2.08%; in the alternative, relocate items to area with compliant CGS.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	305	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Okeeheelee Park	306	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	307	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	308	Employee Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Okeeheelee Park	309	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	310	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	311	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	312	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$96.25	1	each	\$96.25	3
Okeeheelee Park	313	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	314	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	315	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	316	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	317	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	318	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	319	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	322	Employee Spaces	Kitchens, Kitchenettes, And Wet Bars	Renovate kitchen, or remove objects to provide required 40" clearance through kitchen.	\$3,360.00	1	each	\$3,360.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	323	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	324	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	325	Employee Spaces	Protruding Object	Relocate protruding objects or provide cane detectable bollard at foot of object along the accessible route.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	326	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	327	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$96.25	1	each	\$96.25	3
Okeeheelee Park	328	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted between 34" and 38" AFF.  Provide kick plate on push side of gate from floor to 10" AFF.	\$514.00	2	each	\$1,028.00	3
Okeeheelee Park	329	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	330	Employee Spaces	Room/Space (C)	Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$59.20	15	lin ft	\$888.00	3
Okeeheelee Park	331	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	332	Employee Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	333	Employee Men's Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	334	Employee Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	2	each	\$700.00	3
Okeeheelee Park	335	Employee Men's Restroom	Toilet and Bathing Rooms	Relocate garbage cans and sink to provide required 60" clearance around toilet; leave sink as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	336	Employee Men's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Okeeheelee Park	337	Employee Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	338	Employee Women's Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	339	Employee Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	2	each	\$700.00	3
Okeeheelee Park	340	Employee Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	341	Employee Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Okeeheelee Park	342	Employee Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	343	Employee Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	344	Employee Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	350	Golf Course	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	351	Golf Course	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	356	Golf Course	Clear Floor Space	Relocate washing station or repair slope in CFS to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	2
Okeeheelee Park	357	Golf Course	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Okeeheelee Park	358	Golf Course	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	360	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	361	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	362	Heron Course Restroom At Hole 4 - Left	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	363	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	364	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	365	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Acquire rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	366	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Relocate and store toilet paper.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	367	Heron Course Restroom At Hole 4 - Left	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	368	Heron Course Restroom At Hole 4 - Left	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	369	Heron Course Restroom At Hole 4 - Left	Turning Space	Relocate obstacles to create turning space in stall.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	370	Heron Course Restroom At Hole 4 - Left	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.00	1	each	\$514.00	1
Okeeheelee Park	371	Heron Course Restroom At Hole 4 - Right	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	372	Heron Course Restroom At Hole 4 - Right	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	373	Heron Course Restroom At Hole 4 - Right	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	374	Heron Course Restroom At Hole 4 - Right	Toilet and Bathing Rooms	Acquire rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	375	Heron Course Restroom At Hole 4 - Right	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper and mount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$84.00	1	each	\$84.00	1
Okeeheelee Park	376	Heron Course Restroom At Hole 4 - Right	Turning Space	Relocate obstacles to create turning space in stall.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	377	Heron Course Restroom At Hole 4 - Right	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	378	Heron Course Restroom At Hole 4 - Right	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$514.00	1	each	\$514.00	1
Okeeheelee Park	379	Public Restroom Downstairs - Men	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates .	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	380	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	381	Public Restroom Downstairs - Men	Plumbing Fixtures & Elements	Replace sink with one providing 27" knee clearance that is a min 8" deep.	\$4,436.25	1	each	\$4,436.25	1
Okeeheelee Park	382	Public Restroom Downstairs - Men	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	383	Public Restroom Downstairs - Men	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	384	Public Restroom Downstairs - Men	Clear Floor Space	Remove, or relocate storage in CFS at fixtures to provide required 30" by 48" CFS at operable parts.  See earlier finding for correction to sink knee clearance.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	385	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	386	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	387	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	388	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	389	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	390	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	391	Public Restroom Downstairs - Men	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	392	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	393	Public Restroom Downstairs - Men	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	394	Public Restroom Downstairs - Men	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	395	Public Restroom Downstairs - Men	Accessible Routes	Fill and maintain gaps to max .5"	\$96.25	2	each	\$192.50	1
Okeeheelee Park	396	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	397	Public Restroom Downstairs - Women	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	398	Public Restroom Downstairs - Women	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	399	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	400	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	401	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	402	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	403	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	404	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width Adjust stall door to be self-closing.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	405	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	406	Public Restroom Downstairs - Women	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
Okeeheelee Park	407	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	408	Public Restroom Downstairs - Women	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	409	Public Restroom Downstairs - Women	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Okeeheelee Park	410	Public Restroom Downstairs - Women	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	411	Public Restroom Downstairs - Women	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	412	Eagle Course Restroom At Hole 5 - Left	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	413	Eagle Course Restroom At Hole 5 - Left	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	414	Eagle Course Restroom At Hole 5 - Left	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	415	Eagle Course Restroom At Hole 5 - Left	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	416	Eagle Course Restroom At Hole 5 - Left	Toilet and Bathing Rooms	Acquire rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	417	Eagle Course Restroom At Hole 5 - Left	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	418	Eagle Course Restroom At Hole 5 - Left	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper.	\$84.00	1	each	\$84.00	1
Okeeheelee Park	419	Eagle Course Restroom At Hole 5 - Left	Turning Space	Relocate obstacles to create turning space in stall.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	420	Eagle Course Restroom At Hole 5 - Left	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	421	Eagle Course Restroom At Hole 5 - Left	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$514.00	1	each	\$514.00	1
Okeeheelee Park	422	Eagle Course Restroom At Hole 5 - Right	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$514.00	1	each	\$514.00	1
Okeeheelee Park	423	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	424	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	425	Eagle Course Restroom At Hole 5 - Right	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	426	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Relocate Garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	427	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	428	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Acquire rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	429	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	430	Eagle Course Restroom At Hole 5 - Right	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper.	\$84.00	1	each	\$84.00	1
Okeeheelee Park	431	Eagle Course Restroom At Hole 5 - Right	Turning Space	Relocate obstacles to create turning space in toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	432	Eagle Course Restroom At Hole 5 - Right	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	433	Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$3,577.00	1	each	\$3,577.00	3
Okeeheelee Park	434	Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	435	Maintenance	Accessible Routes	Remove door stop on floor.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	436	Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$20,700.75	1	each	\$20,700.75	3
Okeeheelee Park	437	Maintenance	Room/Space (C)	Make corrections for compliant circulation path.	\$96.25	1	each	\$96.25	3
Okeeheelee Park	438	Maintenance	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	3
Okeeheelee Park	439	Maintenance	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	440	Maintenance	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	441	Maintenance	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	442	Maintenance	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	3
Okeeheelee Park	443	Maintenance	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	444	Maintenance	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	445	Maintenance	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	3
Okeeheelee Park	446	Maintenance	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	447	Maintenance	Toilet and Bathing Rooms	Relocate storage of toilet paper.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	448	Maintenance	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	3
Okeeheelee Park	449	Maintenance	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper	\$84.00	1	each	\$84.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	450	Maintenance	Turning Space	Relocate obstacles to create turning space in stall.	\$0.00	1	N/A	\$0.00	3
Okeeheelee Park	451	Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	452	Maintenance	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	3	each	\$9,187.50	2
Okeeheelee Park	453	Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$514.00	1	each	\$514.00	3
Okeeheelee Park	454	Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	3
Okeeheelee Park	455	Maintenance	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	456	Maintenance	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	5	each	\$1,750.00	3
Okeeheelee Park	457	Maintenance	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	458	Maintenance	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	459	Maintenance	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	460	Maintenance	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	461	Maintenance	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	462	Maintenance	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	463	Maintenance	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	3	each	\$1,050.00	3
Okeeheelee Park	464	Maintenance	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3
Okeeheelee Park	465	Maintenance	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	466	Maintenance	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	467	Maintenance	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	3
Okeeheelee Park	468	Maintenance	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	3
Okeeheelee Park	469	Maintenance	Toilet and Bathing Rooms	Relocate storage of toilet paper.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	470	Maintenance	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	471	Maintenance	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper.	\$84.00	1	each	\$84.00	3
Okeeheelee Park	472	Maintenance	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	473	Maintenance	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	3	each	\$9,187.50	3
Okeeheelee Park	476	Maintenance	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a smart practice. Mount hooks and operating mechanisms max 48" AFF.	\$420.00	1	each	\$420.00	3
Okeeheelee Park	477	Maintenance	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	3
Okeeheelee Park	478	Maintenance	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" aff and shelves to 40" - 48" AFF.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	479	Maintenance	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	3
Okeeheelee Park	480	Maintenance	Plumbing Fixtures & Elements	Enlarge transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	3
Okeeheelee Park	481	Maintenance	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	3
Okeeheelee Park	482	Maintenance	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the transfer shower.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	483	Maintenance	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	3
Okeeheelee Park	484	Maintenance	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower and ensure the front edge is within 3" of the opening.	\$840.00	1	each	\$840.00	3
Okeeheelee Park	485	Maintenance	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a smart practice. Mount hooks and operating mechanisms max 48" AFF.	\$420.00	1	each	\$420.00	3
Okeeheelee Park	486	Maintenance	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	3
Okeeheelee Park	487	Maintenance	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" aff and shelves to 40" - 48" AFF.	\$350.00	3	each	\$1,050.00	3
Okeeheelee Park	488	Maintenance	Dressing / Fitting / Locker Rooms	Acquire and install bench in dressing area having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	3
Okeeheelee Park	489	Maintenance	Plumbing Fixtures & Elements	Enlarge transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	3
Okeeheelee Park	490	Maintenance	Plumbing Fixtures & Elements	Provide appropriate CFS on the exterior of the transfer shower.	\$462.00	1	each	\$462.00	3
Okeeheelee Park	491	Maintenance	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the transfer shower.	\$350.00	1	each	\$350.00	3
Okeeheelee Park	492	Maintenance	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	493	Maintenance	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower					
Okeeheelee Park	493	Maintenance	Plumbing Fixtures & Elements	Remount shower bench so that the front edge is within 3" of the opening	\$350.00	1	each	\$350.00	3
Okeeheelee Park	495	Maintenance Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	496	Maintenance Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	497	Maintenance Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Okeeheelee Park	498	Maintenance Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	499	Maintenance Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	500	Maintenance Parking	Parking - Off Street	Relocate accessible parking stall to provide access to a 44" wide accessible route that connects to the building entry.  In the alternative, stripe a 44" wide path connecting access aisle to the accessible route.	\$1,589.00	1	each	\$1,589.00	3
Okeeheelee Park	501	Maintenance Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	503	Parking - Small Lot by Ball Fields	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	504	Parking - Small Lot by Ball Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Okeeheelee Park	505	Parking - Small Lot by Ball Fields	Parking - Off Street	Maintain accessible stalls and access aisles to be firm, stable, and slip resistant.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	506	Parking - Small Lot by Ball Fields	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	507	Parking - Small Lot by Ball Fields	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	3	staff time	\$0.00	1
Okeeheelee Park	508	Parking - Small Lot by Ball Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	509	Parking - Small Lot by Ball Fields	Parking - Off Street	Relocate accessible parking stall to provide access to a 44" wide accessible route.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	510	Parking - Outer Edge of Ball Fields	Parking - Off Street	Create four or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	4	each	\$6,356.00	1
Okeeheelee Park	511	Parking - Outer Edge of Ball Fields	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Okeeheelee Park	512	Parking - Outer Edge of Ball Fields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	513	Parking - Outer Edge of Ball Fields	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	2	each	\$735.00	1
Okeeheelee Park	514	Parking - Outer Edge of Ball Fields	Parking - Off Street	Fill and maintain gaps in stalls to max .5". Ensure accessible stalls and access aisles are firm, stable, and slip resistant.	\$32.08	3	each	\$96.24	1
Okeeheelee Park	515	Parking - Outer Edge of Ball Fields	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	516	Multi-Purpose Fields	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	517	Multi-Purpose Fields	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Okeeheelee Park	518	Multi-Purpose Fields	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	10	sq ft	\$1,225.00	2
Okeeheelee Park	519	Multi-Purpose Fields	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	N/A	\$2,380.00	2
Okeeheelee Park	520	Multi-Purpose Fields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	1525	lin ft	\$90,280.00	4
Okeeheelee Park	521	Multi-Purpose Fields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	1525	lin ft	\$90,280.00	4
Okeeheelee Park	522	Multi-Purpose Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	70	lin ft	\$4,144.00	4
Okeeheelee Park	523	Multi-Purpose Fields	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$175.00	2	each	\$350.00	3
Okeeheelee Park	524	Multi-Purpose Fields	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	525	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Ensure dugouts comply when construction completed	\$59.20	100	lin ft	\$5,920.00	2
Okeeheelee Park	526	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
Okeeheelee Park	527	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	80	lin ft	\$4,736.00	2
Okeeheelee Park	528	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	110	lin ft	\$6,512.00	2
Okeeheelee Park	529	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	530	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2
Okeeheelee Park	531	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2
Okeeheelee Park	532	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2
Okeeheelee Park	533	Ball Fields	Assembly Areas	Provide wheelchair spaces adjacent to bleachers based on the capacity of the bleachers at each field and include these spaces under the shade canopy.	\$629.50	4	each	\$2,518.00	2
Okeeheelee Park	534	Ball Fields	Assembly Areas	Provide wheelchair spaces adjacent to bleachers based on the capacity of the bleachers at each field and include these spaces under the shade canopy.	\$629.50	4	each	\$2,518.00	2
Okeeheelee Park	535	Ball Fields	Assembly Areas	Provide wheelchair spaces adjacent to bleachers based on the capacity of the bleachers at each field and include these spaces under the shade canopy.	\$629.50	1	each	\$629.50	1
Okeeheelee Park	536	Ball Fields	Assembly Areas	Provide wheelchair spaces adjacent to bleachers based on the capacity of the bleachers at each field and include these spaces under the shade canopy.	\$629.50	1	each	\$629.50	2
Okeeheelee Park	537	Ball Fields	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	1
Okeeheelee Park	539	Ball Fields	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	540	Ball Fields	Assembly Areas	Relocate garbage can to provide clear ground space min 36" by 48" located adjacent to a short end of the player bench in dugout. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	541	Ball Fields	Assembly Areas	Provide a number of wheelchair spaces based on the bleacher capacity at each field. In the alternative, leave as is and designate other County ball fields accessible.	\$629.50	2	each	\$1,259.00	4
Okeeheelee Park	542	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	100	lin ft	\$5,920.00	4
Okeeheelee Park	543	Ball Fields	Assembly Areas	Relocate garbage can to provide clear ground space min 36" by 48" located adjacent to a short end of the player bench in dugout. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	544	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Repair, bevel, or ramp changes in level to max .5".  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	100	lin ft	\$5,920.00	4
Okeeheelee Park	545	Ball Fields	Assembly Areas	Provide a number of wheelchair spaces based on the bleacher capacity at each field. In the alternative, leave as is and designate other County ball fields accessible.	\$629.50	2	each	\$1,259.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	546	Ball Fields	Assembly Areas	Relocate garbage can to provide clear ground space min 36" by 48" located adjacent to a short end of the player bench in dugout. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Okeeheelee Park	547	Ball Fields	Assembly Areas	Provide a number of wheelchair spaces based on the bleacher capacity at each field. In the alternative, leave as is and designate other County ball fields accessible.	\$629.50	2	each	\$1,259.00	4
Okeeheelee Park	548	Ball Fields	Assembly Areas	Repair landing at accessible seating to be level or no more than 2.08% slope in any direction.  Provide a number of wheelchair spaces based on the bleacher capacity at each field.  In the alternative, leave as is and designate other County ball fields accessible.	\$4,199.00	1	each	\$4,199.00	4
Okeeheelee Park	549	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Repair, bevel, or ramp changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	100	lin ft	\$5,920.00	4
Okeeheelee Park	550	Ball Fields	Assembly Areas	Relocate garbage can to provide clear ground space min 36" by 48" located adjacent to a short end of the player bench in dugout. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Okeeheelee Park	551	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Repair, bevel, or ramp changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	100	lin ft	\$5,920.00	4
Okeeheelee Park	552	Ball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Repair, bevel, or ramp changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	325	lin ft	\$19,240.00	4
Okeeheelee Park	554	Ball Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	555	Ball Fields	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	556	Concession/Press Box	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	557	Concession/Press Box	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread .</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	6	each	\$750.00	2
Okeeheelee Park	558	Concession/Press Box	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" above the finished floor (AFF) with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.</p>	\$980.00	1	each	\$980.00	2
Okeeheelee Park	559	Concession/Press Box	Stairways	<p>Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.</p>	\$980.00	1	each	\$980.00	2
Okeeheelee Park	560	Concession/Press Box	Stairways	<p>Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.</p>	\$0.00	1	each	\$0.00	2
Okeeheelee Park	561	Concession/Press Box	Stairways	<p>Provide 80" overhead clearance if the feasible, in the alternative, pad the obstruction to prevent injury.</p>	\$462.00	1	each	\$462.00	2
Okeeheelee Park	562	Concession/Press Box	Accessible Routes	<p>Widen AR to compliant 36" clear width</p>	\$1,099.00	1	each	\$1,099.00	3
Okeeheelee Park	563	Concession/Press Box	Turning Space	<p>Relocate obstacles to create turning space in press box.</p>	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	564	Concession/Press Box	Clear Floor Space	<p>Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).</p> <p>For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here.</p>	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	565	Concession/Press Box	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).</p>	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	566	Concession/Press Box	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Okeeheelee Park	567	Concession/Press Box	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Okeeheelee Park	568	Concession/Press Box	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).</p>	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	569	Concession/Press Box	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	15	each	\$1,875.00	2
Okeeheelee Park	570	Concession/Press Box	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" above the finished floor (AFF) with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	\$980.00	1	each	\$980.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	571	Concession/Press Box	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	2
Okeeheelee Park	572	Concession/Press Box	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	573	Concession/Press Box	Stairways	Provide 80" overhead clearance if the feasible, in the alternative, pad the obstruction to prevent injury.	\$462.00	1	each	\$462.00	2
Okeeheelee Park	574	Concession/Press Box	Accessible Routes	Widen AR to compliant 36" clear width.	\$1,099.00	1	each	\$1,099.00	3
Okeeheelee Park	575	Concession/Press Box	Turning Space	Relocate obstacles to create turning space in press box.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	576	Concession/Press Box	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).  For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	577	Concession/Press Box	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" above the finished floor (AFF).	\$1,099.00	1	each	\$1,099.00	1
Okeeheelee Park	578	Concession/Press Box	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. Pricing addressed in previous finding.	\$2,380.00	1	each	\$2,380.00	3
Okeeheelee Park	579	Concession/Press Box	Kitchens, Kitchenettes, And Wet Bars	Provide required clear floor space (CFS) at appliances.	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	580	Concession/Press Box	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	581	Concession/Press Box	Accessible Routes	Raise vent to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$462.00	1	each	\$462.00	1
Okeeheelee Park	582	Concession/Press Box	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	583	Concession/Press Box	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	3	each	\$288.75	1
Okeeheelee Park	584	Concession/Press Box	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	585	Concession/Press Box	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Okeeheelee Park	586	Concession/Press Box	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" above the finished floor (AFF).	\$1,099.00	1	each	\$1,099.00	1
Okeeheelee Park	587	Concession/Press Box	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	3
Okeeheelee Park	588	Concession/Press Box	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	2	each	\$154.00	1
Okeeheelee Park	589	Concession/Press Box	Kitchens, Kitchenettes, And Wet Bars	Provide required clear floor space at appliances.	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	590	Concession/Press Box	Accessible Routes	Widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	591	Concession/Press Box	Accessible Routes	Relocate bar to prevent hazard in overhead clearance along the accessible route (AR).	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	592	Concession/Press Box	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	593	Concession/Press Box	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	594	Concession/Press Box	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$2,322.25	2	each	\$4,644.50	1
Okeeheelee Park	595	Concession/Press Box	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$2,868.75	1	each	\$2,868.75	1
Okeeheelee Park	596	Baseball - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	597	Baseball - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Okeeheelee Park	598	Baseball - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Fill gaps at door entries to max .5".	\$5,931.25	1	each	\$5,931.25	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	599	Softball - Employee Spaces	Sales and Service Counters/Tables	If concession stand is reopened, lower 36" wide segment of service counter to max 36" above the finished floor (AFF).	\$1,099.00	1	each	\$1,099.00	3
Okeeheelee Park	600	Softball - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Fill gaps at door entries to max .5".  Repair, provide beveled threshold.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, between 34" and 48".	\$2,398.46	6	each	\$14,390.76	3
Okeeheelee Park	601	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	602	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	603	Soccer - Men's Restroom (Building 9)	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	604	Soccer - Men's Restroom (Building 9)	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	605	Soccer - Men's Restroom (Building 9)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	606	Soccer - Men's Restroom (Building 9)	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF). Pricing addressed in different finding.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	607	Soccer - Men's Restroom (Building 9)	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Okeeheelee Park	608	Soccer - Men's Restroom (Building 9)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	609	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	610	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	611	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	612	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees. Adjust stall door to be self-closing.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	613	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	614	Soccer - Men's Restroom (Building 9)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	615	Soccer - Men's Restroom (Building 9)	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$2,100.00	1	each	\$2,100.00	1
Okeeheelee Park	616	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	617	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	618	Soccer - Women's Restroom (Building 9)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	619	Soccer - Women's Restroom (Building 9)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	620	Soccer - Women's Restroom (Building 9)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	621	Soccer - Women's Restroom (Building 9)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	622	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights. Adjust stall door to be self-closing.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	623	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	624	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	625	Soccer - Women's Restroom (Building 9)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	626	Soccer - Women's Restroom (Building 9)	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	627	Baseball - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,522.50	1	each	\$4,522.50	1
Okeeheelee Park	628	Baseball - Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	629	Baseball - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	630	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Leave as is sinks, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	631	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	632	Baseball - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	633	Baseball - Men's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	634	Baseball - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	635	Baseball - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	636	Baseball - Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	637	Baseball - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	638	Baseball - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	639	Baseball - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	640	Baseball - Men's Restroom	Accessible Routes	Raise bar to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	641	Baseball - Men's Restroom	Turning Space	Reconfigure restroom to provide 60" turning space.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	642	Baseball - Men's Restroom	Signs	Restroom not accessible, in the alternative to the recommendations above, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1
Okeeheelee Park	643	Baseball - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	644	Baseball - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	645	Baseball - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	646	Baseball - Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	647	Baseball - Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	648	Baseball - Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Okeeheelee Park	649	Baseball - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	650	Baseball - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	651	Baseball - Women's Restroom	Turning Space	Reconfigure restroom to provide min 60" turning space.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	652	Baseball - Women's Restroom	Room/Space (C)	Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	653	Baseball - Women's Restroom	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$2,772.50	1	each	\$2,772.50	1
Okeeheelee Park	654	Baseball - Women's Restroom	Signs	Restroom not accessible, in the alternative to the recommendations above, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1
Okeeheelee Park	655	Softball - Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	656	Softball - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	657	Softball - Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	658	Softball - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	659	Softball - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	660	Softball - Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	661	Softball - Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	662	Softball - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	663	Softball - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	664	Softball - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	665	Softball - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,522.50	1	each	\$4,522.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	666	Softball - Men's Restroom	Signs	Restroom not accessible, in the alternative to the recommendations above, acquire and mount signage directing patrons to accessible restroom	\$210.00	1	each	\$210.00	1
Okeeheelee Park	667	Softball - Women's Restroom	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	668	Softball - Women's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and without access symbol for non-accessible restroom. Ensure sign is mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	669	Softball - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$4,522.50	1	each	\$4,522.50	1
Okeeheelee Park	670	Baseball Fields - All Gender Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	671	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	672	Baseball Fields - All Gender Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.  Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$175.00	2	each	\$350.00	1
Okeeheelee Park	673	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	674	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	675	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	676	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	677	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	678	Baseball Fields - All Gender Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	679	Baseball Fields - All Gender Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	680	Softball - All Gender Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	681	Softball - All Gender Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	682	Softball - All Gender Restroom	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	683	Softball - All Gender Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	684	Softball - All Gender Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.  Relocated sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	685	Softball - All Gender Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	686	Softball - All Gender Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	687	Softball - All Gender Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	688	Softball - All Gender Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$262.50	3	N/A	\$787.50	1
Okeeheelee Park	689	Softball - All Gender Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	690	Softball - All Gender Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	691	Tennis Courts	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over grass/woodchips.	\$350.00	2	each	\$700.00	2
Okeeheelee Park	692	Tennis Courts	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$3,412.50	1	each	\$3,412.50	1
Okeeheelee Park	693	Tennis Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	694	Tennis Courts	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	695	Tennis Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1
Okeeheelee Park	696	Tennis Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	697	Tennis Courts	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$1,531.25	2	each	\$3,062.50	1
Okeeheelee Park	698	Tennis Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$1,706.25	2	each	\$3,412.50	1
Okeeheelee Park	699	Tennis Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	700	Tennis Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	701	Tennis Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$3,508.50	1	each	\$3,508.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	702	Pickleball Courts	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,206.75	2	each	\$6,413.50	1
Okeeheelee Park	703	Pickleball Courts	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	705	Pickleball Courts	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	708	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	709	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	710	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Okeeheelee Park	711	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	712	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	713	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	714	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Okeeheelee Park	715	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	716	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	717	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	718	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	719	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Okeeheelee Park	720	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	721	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	722	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Okeeheelee Park	723	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Okeeheelee Park	724	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Okeeheelee Park	725	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	360	sq ft	\$44,100.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	726	Men's Restroom	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	727	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	728	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	729	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	730	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	731	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$262.50	3	each	\$787.50	1
Okeeheelee Park	732	Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide a min 42" clear width.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	733	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	734	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	735	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Pricing to relocate hand dryer provided in a previous finding.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	736	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	737	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	738	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	739	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	740	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	741	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	742	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	743	Women's Restroom	Toilet and Bathing Rooms	Relocate hand dryer from stall door clearance.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	744	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	745	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	746	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	747	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	748	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	749	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	754	Equestrian Center Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	10	each	\$735.00	1
Okeeheelee Park	755	Equestrian Center Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	10	each	\$30,625.00	1
Okeeheelee Park	756	Equestrian Center Parking	Parking - Off Street	Ensure accessible stalls and access aisles are firm, stable, and slip resistant.  Correct or fill gaps in stalls and access aisles.  Pricing for deterioration addressed in previous finding.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	757	Equestrian Center Parking	Parking - Off Street	Add van parking signs to three accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	3	each	\$630.00	1
Okeeheelee Park	759	Ring 1 Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features	\$367.50	4	each	\$1,470.00	1
Okeeheelee Park	760	Ring 1 Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Okeeheelee Park	761	Ring 1 Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	7	each	\$514.50	1
Okeeheelee Park	762	Ring 1 Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	11	each	\$33,687.50	1
Okeeheelee Park	763	Ring 1 Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.  Resurface stalls and access aisles to eliminate gaps and cracks.	\$1,448.13	2	each	\$2,896.26	1
Okeeheelee Park	764	Ring 1 Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	765	Ring 1 Parking	Parking - Off Street	Add van parking signs to two accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	767	Building 16 Parking	Parking - Off Street	Disperse accessible stalls to be on the shortest AR to the multiple amenities.	\$367.50	1	each	\$367.50	1
Okeeheelee Park	768	Building 16 Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	769	Building 16 Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Okeeheelee Park	770	Building 16 Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	771	Show Rings (1-6)	Assembly Areas	Provide wheelchair spaces min 36" by 48" based on the number of total seats provided at bleachers.	\$629.50	4	each	\$2,518.00	2
Okeeheelee Park	772	Show Rings (1-6)	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	2
Okeeheelee Park	773	Show Rings (1-6)	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	775	lin ft	\$45,880.00	2
Okeeheelee Park	774	Show Rings (1-6)	Assembly Areas	Repair slope at accessible seating to be level or no more than 2.08% in any direction.	\$1,470.00	4	each	\$5,880.00	2
Okeeheelee Park	776	Show Rings (1-6)	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	2
Okeeheelee Park	777	Show Rings Near Bldg 16	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Okeeheelee Park	778	Show Rings Near Bldg 16	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Okeeheelee Park	779	Show Rings Near Bldg 16	Assembly Areas	Provide wheelchair spaces min 36" by 48" based on the number of total seats provided at bleachers.	\$629.50	2	each	\$1,259.00	2
Okeeheelee Park	780	Show Rings Near Bldg 16	Assembly Areas	Provide wheelchair spaces min 36" by 48" based on the number of total seats provided at bleachers. Repair landing at accessible seating to be level or no more than 2.08% slope in any direction.	\$839.63	4	each	\$3,358.52	2
Okeeheelee Park	781	Show Rings Near Bldg 16	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table.	\$1,120.00	1	each	\$1,120.00	5
Okeeheelee Park	782	Show Rings Near Bldg 16	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	2
Okeeheelee Park	783	Show Rings Near Bldg 16	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
Okeeheelee Park	784	Show Rings Near Bldg 16	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable.	\$59.20	55	lin ft	\$3,256.00	5
Okeeheelee Park	785	Show Rings Near Bldg 16	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Okeeheelee Park	786	Show Rings Near Bldg 16	Shelters, Picnic Facilities (C)	Create an outdoor recreation access route (ORAR) to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Okeeheelee Park	787	Show Rings Near Bldg 16	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
Okeeheelee Park	788	Show Rings Near Bldg 16	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	staff time	\$467.25	5
Okeeheelee Park	789	Show Rings Near Bldg 16	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	3	staff time	\$0.00	2
Okeeheelee Park	790	Practice Ring	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	40	lin ft	\$2,368.00	1
Okeeheelee Park	793	Barns A and B	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	12	each	\$2,100.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	794	Barns A and B	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	12	each	\$2,100.00	1
Okeeheelee Park	795	Barns A and B	Accessible Routes	Tape or bevel a 36" wide portion of the mats to provide a designated entry to the mat area.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	796	Barns A and B	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	115	lin ft	\$6,808.00	1
Okeeheelee Park	797	Barns A and B	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	798	Barns A and B	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	799	Barns A and B	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	55	lin ft	\$3,256.00	1
Okeeheelee Park	800	Barns A and B	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	801	Barns A and B	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	80	lin ft	\$4,736.00	2
Okeeheelee Park	802	Barns A and B	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	8	each	\$1,680.00	1
Okeeheelee Park	803	Barns A and B	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	120	lin ft	\$7,104.00	2
Okeeheelee Park	804	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	805	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Okeeheelee Park	806	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Okeeheelee Park	807	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Okeeheelee Park	808	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	72	sq ft	\$8,820.00	1
Okeeheelee Park	809	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	810	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	108	sq ft	\$13,230.00	1
Okeeheelee Park	811	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	812	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Okeeheelee Park	813	Equestrian Center Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	11	each	\$3,619.00	5
Okeeheelee Park	814	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	815	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	816	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	210	sq ft	\$25,725.00	1
Okeeheelee Park	817	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	818	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Okeeheelee Park	819	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	820	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Okeeheelee Park	821	Equestrian Center Exterior Accessible Route	Accessible Routes	Maintain accessible route to remain stable, firm, and maneuverable.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	822	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Okeeheelee Park	823	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	8	each	\$770.00	1
Okeeheelee Park	824	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	825	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Okeeheelee Park	826	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	450	sq ft	\$55,125.00	1
Okeeheelee Park	827	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1
Okeeheelee Park	828	Equestrian Center Exterior Accessible Route	Accessible Routes	Widen EAR to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	829	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Okeeheelee Park	830	Equestrian Center Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%	\$6,510.00	2	each	\$13,020.00	3
Okeeheelee Park	831	Equestrian Center Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	1	lin ft	\$59.20	3
Okeeheelee Park	832	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	3
Okeeheelee Park	833	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	600	sq ft	\$73,500.00	1
Okeeheelee Park	834	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Okeeheelee Park	835	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	836	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	18	each	\$1,732.50	1
Okeeheelee Park	837	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
Okeeheelee Park	838	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	839	Equestrian Center Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3
Okeeheelee Park	840	Equestrian Center Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	2	each	\$192.50	3
Okeeheelee Park	841	Equestrian Center Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Okeeheelee Park	842	Equestrian Center Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Okeeheelee Park	843	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	844	Equestrian Center Exterior Accessible Route	Accessible Routes	Maintain accessible route to be firm, stable, and maneuverable.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	845	Equestrian Center Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Okeeheelee Park	846	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	847	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	848	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	849	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Okeeheelee Park	850	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	851	Equestrian Center Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	50	lin ft	\$2,960.00	1
Okeeheelee Park	852	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	853	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Okeeheelee Park	854	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	855	Equestrian Center Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Okeeheelee Park	856	Equestrian Center Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Okeeheelee Park	857	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Okeeheelee Park	858	Equestrian Center Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Okeeheelee Park	859	Equestrian Center Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	860	Equestrian Center Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Okeeheelee Park	861	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max above the finished floor (AFF) to the spout.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	862	Park Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	10	sq ft	\$1,225.00	2
Okeeheelee Park	863	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	864	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along the accessible route (AR).	\$0.00	2	staff time	\$0.00	2
Okeeheelee Park	865	Park Elements	Accessible Routes	Create a route to at least one picnic table and replace with one of a compliant model.	\$2,600.00	1	each	\$2,600.00	5
Okeeheelee Park	866	Park Elements	Accessible Routes	Relocate fire extinguishers to be along the accessible route (AR).	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	867	Park Elements	Accessible Routes	Relocate 20% of garbage bins to be along the accessible route (AR) and ensure they are within reach range.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	868	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max above the finished floor (AFF) to the spout.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	869	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	870	Park Elements	Accessible Routes	Replace three picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around table.	\$1,120.00	3	each	\$3,360.00	5
Okeeheelee Park	871	Park Elements	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max above the finished floor (AFF) to the spout.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	872	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	873	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	874	Park Elements	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	875	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	876	Employee Spaces	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors. Repair, provide beveled threshold.	\$2,003.75	1	each	\$2,003.75	3
Okeeheelee Park	877	Employee Spaces	Room/Space (C)	Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Extend accessible route to building entry.	\$1,485.75	1	each	\$1,485.75	3
Okeeheelee Park	878	Building 1	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Secure rug at door to prevent trip hazard.	\$140.00	1	each	\$140.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	879	Building 1	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	880	Building 1	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over counter.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	881	Building 1	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Okeeheelee Park	882	Building 1 Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	883	Building 1 Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	884	Building 1 Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	885	Building 1 Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	886	Building 1 Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	887	Building 1 Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	888	Building 1 Men's Restroom	Toilet and Bathing Rooms	Remove storage items to provide min 12" above and min 1.5" below grab bars.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	889	Building 1 Men's Restroom	Toilet and Bathing Rooms	Remount stall door or relocate partitions to provide min 18" clearance on pull side of stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	890	Building 1 Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	891	Building 1 Men's Restroom	Accessible Routes	Raise beam to min 80", or pad object to prevent hazard in overhead clearance along accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	892	Building 1 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	893	Building 1 Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	894	Building 1 Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	895	Building 1 Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	896	Building 1 Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	897	Building 1 Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	898	Building 1 Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	899	Building 1 Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	900	Building 1 Women's Restroom	Toilet and Bathing Rooms	Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$140.00	1	each	\$140.00	1
Okeeheelee Park	901	Building 1 Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	902	Building 1 Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	903	Building 3	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	3	staff time	\$0.00	3
Okeeheelee Park	904	Building 3	Accessible Routes	Widen accessible route (AR) to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Okeeheelee Park	905	Building 3	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	3
Okeeheelee Park	906	Building 3	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	3
Okeeheelee Park	907	Building 3	Plumbing Fixtures & Elements	Lower sink height to max 34" above the finished floor (AFF).	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	908	Building 3	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	909	Building 3	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	910	Building 3	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	911	Building 3	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$175.00	2	each	\$350.00	1
Okeeheelee Park	912	Building 3	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	3	staff time	\$0.00	1
Okeeheelee Park	913	Building 3	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	914	Building 3	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	915	Building 3	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	916	Building 3	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	917	Building 3	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing addressed in previous finding.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	918	Building 3	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	919	Building 3	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	920	Building 3	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	921	Building 4 Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	922	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	923	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	924	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" to latch side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	925	Building 4 Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	926	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	927	Building 4 Men's Restroom	Accessible Routes	Raise overhead beam to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	928	Building 4 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	929	Building 4 Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	930	Building 4 Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	931	Building 4 Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	932	Building 4 Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	933	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	934	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remove storage from grab bars to provide clearance min 12" above and 1.5" below.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	935	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance on pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	936	Building 4 Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	937	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	938	Building 4 Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	939	Building 4 Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Price to remount hand dryer addressed in previous finding.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	940	Building 12	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.	\$2,003.75	1	each	\$2,003.75	3
Okeeheelee Park	941	Building 12 Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	942	Building 12 Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	943	Building 12 Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	944	Building 12 Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	945	Building 12 Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	946	Building 12 Men's Restroom	Toilet and Bathing Rooms	Remove storage to provide clearance min 12" above and min 1.5" below grab bars.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	947	Building 12 Men's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance to the latch side of the accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	948	Building 12 Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	N/A	\$210.00	1
Okeeheelee Park	949	Building 12 Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	950	Building 12 Men's Restroom	Accessible Routes	Raise the overhead beam to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	951	Building 12 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	952	Building 12 Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	953	Building 12 Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	954	Building 12 Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	955	Building 12 Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	956	Building 12 Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	957	Building 12 Women's Restroom	Toilet and Bathing Rooms	Remove storage to provide clearance min 12" above and min 1.5" below grab bars.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	958	Building 12 Women's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance on pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	959	Building 12 Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	960	Building 12 Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	961	Building 12 Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	962	Building 12 Women's	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	963	Building 13	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	964	Building 14	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain closing speed on door closers.	\$1,750.00	1	each	\$1,750.00	3
Okeeheelee Park	966	Building 14	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%	\$6,510.00	3	each	\$19,530.00	3
Okeeheelee Park	967	Building 14	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	2	each	\$1,750.00	3
Okeeheelee Park	968	Building 14	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Okeeheelee Park	969	Building 14	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface.	\$980.00	1	each	\$980.00	3
Okeeheelee Park	970	Building 15	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, provide beveled threshold.	\$2,003.75	1	each	\$2,003.75	3
Okeeheelee Park	971	Building 15	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max above the finished floor (AFF) to the spout.	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	972	Building 15	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	973	Building 15	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	974	Building 15 Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	975	Building 15 Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	976	Building 15 Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	977	Building 15 Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	978	Building 15 Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	979	Building 15 Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove storage to provide required clearances at grab bars.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	980	Building 15 Men's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide clearance min 18" to latch side on pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	981	Building 15 Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	982	Building 15 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	983	Building 15 Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	984	Building 15 Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" above the finished floor (AFF) and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	985	Building 15 Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	986	Building 15 Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	987	Building 15 Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	988	Building 15 Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	989	Building 15 Women's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance at latch side on pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	990	Building 15 Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	991	Building 15 Women's Restroom	Accessible Routes	Raise overhead beam to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	992	Building 15 Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	993	Building 15 Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	994	Building 16	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	995	Building 16	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	996	Building 16	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$2,100.00	1	each	\$2,100.00	1
Okeeheelee Park	997	Building 16	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	998	Building 16	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	999	Building 16	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1000	Building 16	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1002	Building 16	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1003	Building 16	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1004	Building 16	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Okeeheelee Park	1005	Building 16	Plumbing Fixtures & Elements	Remove base cabinet and lower sink height to max 34" AFF.	\$3,479.00	1	each	\$3,479.00	1
Okeeheelee Park	1006	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	1007	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	1008	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1009	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1010	Parking	Accessible Routes	Relocate accessible parking stalls and stripe a no parking zone at entry to AR to prevent cars from blocking AR	\$210.00	3	each	\$630.00	1
Okeeheelee Park	1011	Parking	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Okeeheelee Park	1012	Parking	Parking - Off Street	Repair or bevel changes in level in parking stalls and access aisles.	\$96.25	3	each	\$288.75	1
Okeeheelee Park	1013	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1014	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1015	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	5	each	\$367.50	1
Okeeheelee Park	1016	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1017	Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5"	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1018	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1019	Park Elements	Boating Facilities	Provide 5%, but not less than one accessible boarding pier at boat launches. In the alternative, leave as is and designate other County boating facilities accessible.	\$6,510.00	1	each	\$6,510.00	4
Okeeheelee Park	1020	Park Elements	Boating Facilities	Provide the required number of boat slips based on the total provided, or for every 40' of boat slip edge. In the alternative, leave as is and designate other County boating facilities accessible.	\$2,800.00	1	each	\$2,800.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1021	Park Elements	Accessible Routes	Create an outdoor accessible route to the boat pier or make corrections for a compliant route.  Correct or repair cross slope to max 2.08%.  In the alternative, leave as is and designate other County boating facilities accessible.	\$5,726.50	1	each	\$5,726.50	4
Okeeheelee Park	1022	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Provide a number of wheelchair spaces based on the total number of seats.	\$5,515.50	1	each	\$5,515.50	2
Okeeheelee Park	1023	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site; if tower is a raised scoring area, leave as is.	\$6,510.00	1	each	\$6,510.00	2
Okeeheelee Park	1024	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1025	Park Elements	Park Site (C)	Relocate 20% of garbage cans to be along the accessible route (AR).	\$0.00	2	staff time	\$0.00	2
Okeeheelee Park	1026	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	100	lin ft	\$5,920.00	4
Okeeheelee Park	1027	Micanopy Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1028	Micanopy Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair outdoor recreation access route (ORAR) cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	1029	Micanopy Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	1	each	\$96.25	4
Okeeheelee Park	1030	Micanopy Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	8	each	\$770.00	4
Okeeheelee Park	1031	Micanopy Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  Ensure there is a 36" route around the accessible tables at shelter.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1032	Micanopy Pavilion	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max.  Replace drinking fountain with a hi-lo bowl fountain.  Raise water spout to 28" to 36" above the ground.  In the alternative, leave as is and designate other County shelters accessible.	\$1,353.10	5	each	\$6,765.50	4
Okeeheelee Park	1033	Shelters	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table at shelter.	\$1,120.00	3	each	\$3,360.00	5
Okeeheelee Park	1034	Playground	Play Area	Frequently inspect and regularly maintain play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1035	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
Okeeheelee Park	1036	Playground	Play Area	Consider adding a second transfer system as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4
Okeeheelee Park	1037	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1038	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1039	Playground	Play Area	Lower or adjust entry point to play component to 11" to 24" above ground level (AGL). In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1040	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1041	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Remount signage to the proper location based on the type of door provided.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1042	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1043	Men's Restroom (Building 7)	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1044	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1045	Men's Restroom (Building 7)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1046	Men's Restroom (Building 7)	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF). Pricing addressed in different finding.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1047	Men's Restroom (Building 7)	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Okeeheelee Park	1048	Men's Restroom (Building 7)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1049	Men's Restroom (Building 7)	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1050	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Replace side grab bar to a 42" wall mounted bar, mounted max 12" from the rear wall and extending min 54" from rear wall, with 1.5" gap between grab bar and wall, and 33" to 36" aff to top of grab bar.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1051	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1052	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance to the latch side on pull side.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1053	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1054	Men's Restroom (Building 7)	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1055	Men's Restroom (Building 7)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1056	Men's Restroom (Building 7)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,158.75	1	each	\$3,158.75	1
Okeeheelee Park	1057	Women's Restroom (Building 7)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1058	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Remount signage to the proper location based on the type of door provided.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1059	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1060	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
Okeeheelee Park	1061	Women's Restroom (Building 7)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1062	Women's Restroom (Building 7)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1063	Women's Restroom (Building 7)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1064	Women's Restroom (Building 7)	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1065	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1066	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1067	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1068	Women's Restroom (Building 7)	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1069	Women's Restroom (Building 7)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1070	Parking	Parking - Off Street	Create three or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Okeeheelee Park	1071	Parking	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Okeeheelee Park	1072	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Okeeheelee Park	1073	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1074	Parking	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Okeeheelee Park	1075	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	5	each	\$15,312.50	1
Okeeheelee Park	1076	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1077	Parking	Parking - Off Street	Relocate accessible stall to connect access aisle to accessible route at pavilion.	\$1,487.50	1	each	\$1,487.50	1
Okeeheelee Park	1078	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1079	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Okeeheelee Park	1080	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1081	Osceola Pavilion	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons. In the alternative, leave as is and designate other County shelters accessible.	\$5,598.25	1	each	\$5,598.25	4
Okeeheelee Park	1082	Osceola Pavilion	Clear Floor Space	Repair, bevel or ramp CIL in CGS to max .25".  Correct or fill gap.  In the alternative, leave as is and designate other County shelters accessible.	\$96.25	2	each	\$192.50	4
Okeeheelee Park	1083	Osceola Pavilion	Plumbing Fixtures & Elements	Remount fountain to provide centered clear ground space. In the alternative, leave as is and designate other County shelters accessible.	\$2,380.00	1	each	\$2,380.00	4
Okeeheelee Park	1084	Osceola Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	10	each	\$962.50	4
Okeeheelee Park	1085	Osceola Pavilion	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County shelters accessible.	\$350.00	1	each	\$350.00	4
Okeeheelee Park	1086	Osceola Pavilion	Outdoor Recreation Access Routes (C)	Widen ORAR to min 36" clear width as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1087	Osceola Pavilion	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$59.20	125	lin ft	\$7,400.00	4
Okeeheelee Park	1088	Osceola Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4
Okeeheelee Park	1089	Shelters	Shelters, Picnic Facilities (C)	Resurface ORAR to eliminate deterioration.	\$59.20	30	lin ft	\$1,776.00	5
Okeeheelee Park	1090	Shelters	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1091	Shelters	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table at shelter.	\$1,120.00	2	each	\$2,240.00	5
Okeeheelee Park	1092	Shelters	Shelters, Picnic Facilities (C)	Relocate garbage bin to be on route at shelter are ensure it is within reach range.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1093	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2
Okeeheelee Park	1094	Playground	Play Area	Widen border or related play components to provide 44" min AR.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1095	Playground	Accessible Routes	Frequently inspect and regularly maintain play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1096	Playground	Play Area	Consider adding a second transfer system as a smart practice	\$4,970.00	1	each	\$4,970.00	5
Okeeheelee Park	1098	Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1099	Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1101	Playground	Park Site (C)	Relocate 20% of garbage cans to be along the accessible route (AR).	\$0.00	3	staff time	\$0.00	2
Okeeheelee Park	1102	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1103	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1104	Men's Restroom (Building 8)	Plumbing Fixtures & Elements	Provide required 30" X 48" CFS at accessible sinks.  Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$2,100.00	1	each	\$2,100.00	1
Okeeheelee Park	1105	Men's Restroom (Building 8)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1106	Men's Restroom (Building 8)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1107	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	1108	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1109	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Okeeheelee Park	1110	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	1111	Men's Restroom (Building 8)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1112	Men's Restroom (Building 8)	Accessible Routes	Raise the overhead beam to min 80", or pad object to prevent hazard in overhead clearance along the accessible route (AR).	\$140.00	1	each	\$140.00	1
Okeeheelee Park	1113	Men's Restroom (Building 8)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1114	Men's Restroom (Building 8)	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and between 34 inches minimum and 48 inches maximum above the finish floor or ground.	\$3,122.50	1	each	\$3,122.50	3
Okeeheelee Park	1115	Men's Restroom (Building 8)	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1116	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1117	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1118	Women's Restroom (Building 8)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1119	Women's Restroom (Building 8)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1120	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Okeeheelee Park	1121	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1122	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Okeeheelee Park	1123	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Okeeheelee Park	1124	Women's Restroom (Building 8)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1125	Women's Restroom (Building 8)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1126	Women's Restroom (Building 8)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1127	Parking	Parking - Off Street	Relocate accessible stall so that access aisle connects to an accessible route.	\$1,487.50	1	each	\$1,487.50	1
Okeeheelee Park	1129	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1131	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1132	Parking	Accessible Routes	Mount signage to prohibit cars from parking and obstructing accessible route	\$210.00	2	each	\$420.00	1
Okeeheelee Park	1133	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1134	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	3	staff time	\$0.00	1
Okeeheelee Park	1135	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1136	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Okeeheelee Park	1137	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	22	each	\$67,375.00	1
Okeeheelee Park	1138	Exterior Accessible Route	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1139	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Okeeheelee Park	1140	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Okeeheelee Park	1141	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Okeeheelee Park	1142	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Okeeheelee Park	1143	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Okeeheelee Park	1144	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%.	\$1,015.00	2	each	\$2,030.00	1
Okeeheelee Park	1145	Exterior Accessible Route	Accessible Routes	Maintain route to firm, stable, and free of debris.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1146	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1147	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Okeeheelee Park	1148	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1149	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1150	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1151	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Okeeheelee Park	1152	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1154	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Okeeheelee Park	1155	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1156	Alligator Pavilion	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance. In the alternative, leave as is and designate other County shelters accessible.	\$140.00	56	each	\$7,840.00	4
Okeeheelee Park	1157	Alligator Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$350.00	4	each	\$1,400.00	4
Okeeheelee Park	1158	Alligator Pavilion	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	2	each	\$2,240.00	4
Okeeheelee Park	1159	Alligator Pavilion	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max. Replace grill with a compliant unit. In the alternative, leave as is and designate other County shelters accessible.	\$175.00	2	each	\$350.00	4
Okeeheelee Park	1160	Alligator Pavilion	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Construct a firm, stable, and slip resistant pad at least 30" by 48", adjacent to spigot.  Replace spout hardware with hardware operable without a tight pinch or grasp.  In the alternative, leave as is and designate other County shelters accessible.	\$721.00	1	each	\$721.00	4
Okeeheelee Park	1161	Alligator Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	10	each	\$962.50	4
Okeeheelee Park	1162	Alligator Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$122.50	1000	sq ft	\$122,500.00	4
Okeeheelee Park	1163	Picnic Area Along Water	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Okeeheelee Park	1164	Picnic Area Along Water	Shelters/Picnic Areas (C)	Relocate 20% of garbage cans to be along the accessible route (AR).  Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1165	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	7000	sq ft	\$490,000.00	4
Okeeheelee Park	1166	Playground	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs. Cost in previous finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1167	Playground	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs. Cost in previous finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1168	Playground	Play Area	Provide level 30" x 48" minimum CGS centered and parallel to the 24" side of the transfer platform. In the alternative, leave as is and designate other County playgrounds accessible.	\$154.00	1	each	\$154.00	4
Okeeheelee Park	1169	Playground	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,604.00	1	each	\$2,604.00	4
Okeeheelee Park	1170	Playground	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and min 36" wide. In the alternative, leave as is and designate other County playgrounds accessible.	\$875.00	1	each	\$875.00	4
Okeeheelee Park	1171	Playground	Play Area	Replace ramp landing platform with one 60" by 60". In the alternative, leave as is and designate other County playgrounds accessible.	\$875.00	1	each	\$875.00	4
Okeeheelee Park	1172	Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1173	Playground	Play Area	Add 1 more GLPCs of 1 types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Okeeheelee Park	1174	Playground	Play Area	Provide an AR to element for one of each type accessible. Cost in previous finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1175	Playground	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	50	lin ft	\$2,960.00	4
Okeeheelee Park	1176	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1177	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1178	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1179	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF). Pricing addressed in different finding.	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	1180	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$2,749.25	1	each	\$2,749.25	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1181	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Okeeheelee Park	1182	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1183	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1184	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1185	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Install 36" long rear grab bar, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1186	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1187	Men's Restroom (Building 1)	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1188	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance to the latch side on the pull side of the accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1189	Men's Restroom (Building 1)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1190	Men's Restroom (Building 1)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1191	Men's Restroom (Building 1)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1192	Men's Restroom (Building 1)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,255.00	1	each	\$3,255.00	1
Okeeheelee Park	1193	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1194	Women's Restroom (Building 1)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1195	Women's Restroom (Building 1)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1196	Women's Restroom (Building 1)	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1197	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1198	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1199	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1200	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Install min 36" long rear grab bar, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1201	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1202	Women's Restroom (Building 1)	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1203	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.					
Okeeheelee Park	1203	Women's Restroom (Building 1)	Toilet and Bathing Rooms	Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1204	Women's Restroom (Building 1)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1205	Women's Restroom (Building 1)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1207	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1208	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Okeeheelee Park	1209	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Okeeheelee Park	1210	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	4	each	\$11,200.00	1
Okeeheelee Park	1211	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1212	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	1213	Parking	Parking - Off Street	Widen accessible stall to min 12' and keep free of overgrowth and debris.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1214	Parking	Parking - Off Street	Create one or more 5' adjacent access aisle, with proper signage and striping	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	1215	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1216	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1217	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1218	Parking	Parking - Off Street	Relocate accessible parking stall to connect to an accessible route.	\$1,386.00	1	each	\$1,386.00	1
Okeeheelee Park	1219	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1221	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1
Okeeheelee Park	1222	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	3	each	\$4,767.00	1
Okeeheelee Park	1223	Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and ensure stall and access aisle to 12' and 5'	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1224	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Okeeheelee Park	1225	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	3	staff time	\$0.00	1
Okeeheelee Park	1226	Parking	Accessible Routes	Relocate parking and mount signage or stripe a no parking zone at entry to AR to prevent cars from blocking AR.	\$367.50	2	each	\$735.00	1
Okeeheelee Park	1227	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Okeeheelee Park	1228	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1229	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	2	each	\$3,178.00	1
Okeeheelee Park	1230	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1231	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	1232	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1234	Northwest Restrooms (Building 3) Parking	Parking - Off Street	Relocate stalls to connect to an accessible route.	\$367.50	2	each	\$735.00	1
Okeeheelee Park	1235	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	15	each	\$1,443.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1236	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
Okeeheelee Park	1237	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1238	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1239	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1240	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1241	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
Okeeheelee Park	1242	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1243	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	320	sq ft	\$39,200.00	1
Okeeheelee Park	1244	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1245	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	280	sq ft	\$34,300.00	1
Okeeheelee Park	1246	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1247	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1248	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1249	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1250	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	1
Okeeheelee Park	1251	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1252	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1253	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	270	sq ft	\$33,075.00	1
Okeeheelee Park	1254	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Okeeheelee Park	1255	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	1
Okeeheelee Park	1256	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Okeeheelee Park	1257	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	1
Okeeheelee Park	1258	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	960	sq ft	\$117,600.00	1
Okeeheelee Park	1259	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1260	Southeast Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1261	Southeast Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1262	Southeast Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1263	Northwest Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1264	Northwest Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1265	Northwest Park Elements	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	9	each	\$8,820.00	4
Okeeheelee Park	1266	Northwest Park Elements	Fishing Piers And Platforms	Provide 2" high curb or 12" extended surface beyond railing for edge protection. In the alternative, leave as is and designate other County fishing areas accessible.	\$525.00	1	each	\$525.00	4
Okeeheelee Park	1267	Tuskegee Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice. Correct or repair cross slopes to max 2.08% as a smart practice.	\$59.20	415	sq ft	\$24,568.00	5
Okeeheelee Park	1268	Tuskegee Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Okeeheelee Park	1269	Tuskegee Pavilion	Accessible Routes	Raise supports to min 80", or pad object to prevent hazard in overhead clearance.	\$140.00	56	each	\$7,840.00	5
Okeeheelee Park	1270	Tuskegee Pavilion	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max. Replace grill with a compliant unit. Replace operable part with one usable without a tight pinch or grasp that requires no more than 5 lbf to operate. Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$303.33	3	each	\$909.99	5
Okeeheelee Park	1271	Picnic Area With Covered Picnic Tables At Base Of Tuskegee Pavilion Hill	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	1272	Picnic Area With Covered Picnic Tables At Base Of Tuskegee Pavilion Hill	Shelters, Picnic Facilities (C)	Relocate 20% of garbage cans to be along the accessible route (AR).	\$0.00	3	staff time	\$0.00	2
Okeeheelee Park	1273	Picnic Area With Covered Picnic Tables At Base Of Tuskegee Pavilion Hill	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	6	staff time	\$0.00	2
Okeeheelee Park	1274	Picnic Area At Restroom 3	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Okeeheelee Park	1275	Picnic Area At Restroom 3	Shelters, Picnic Facilities (C)	Relocate 20% of garbage cans to be along the accessible route (AR). In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1276	Picnic Area At Restroom 3	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1277	Playground	Play Area	Correct or repair cross slope of designated entry to max 2.08%.  Frequently inspect and regularly maintain play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$122.50	125	sq ft	\$15,312.50	2
Okeeheelee Park	1278	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70.00	1000	sq ft	\$70,000.00	2
Okeeheelee Park	1279	Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1280	Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1281	Playground	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1282	Playground	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	5
Okeeheelee Park	1283	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1284	Southeast Men's Restroom (Building 2)	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" clear floor space (CFS) for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1285	Southeast Men's Restroom (Building 2)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1286	Southeast Men's Restroom (Building 2)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1287	Southeast Men's Restroom (Building 2)	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1288	Southeast Men's Restroom (Building 2)	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Okeeheelee Park	1289	Southeast Men's Restroom (Building 2)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1290	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1291	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1292	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1293	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1294	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1295	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance to pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1296	Southeast Men's Restroom (Building 2)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1297	Southeast Men's Restroom (Building 2)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1298	Southeast Men's Restroom (Building 2)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1299	Southeast Men's Restroom (Building 2)	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Okeeheelee Park	1300	Southeast Men's Restroom (Building 2)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1
Okeeheelee Park	1301	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1302	Southeast Women's Restroom (Building 2)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1303	Southeast Women's Restroom (Building 2)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1304	Southeast Women's Restroom (Building 2)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1305	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1306	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1307	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1308	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1309	Southeast Women's Restroom (Building 2)	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1310	Southeast Women's Restroom (Building 2)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1311	Southeast Women's Restroom (Building 2)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1312	Southeast Women's Restroom (Building 2)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1313	Southeast Women's Restroom (Building 2)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%. For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,255.00	1	each	\$3,255.00	1
Okeeheelee Park	1314	Northwest Men's Restroom (Building 3)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1315	Northwest Men's Restroom (Building 3)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1316	Northwest Men's Restroom (Building 3)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1317	Northwest Men's Restroom (Building 3)	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	1318	Northwest Men's Restroom (Building 3)	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1319	Northwest Men's Restroom (Building 3)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1320	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1321	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1322	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1323	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1324	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1325	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" to the pull side of accessible stall door.  Remount hand dryer to provide push side maneuvering clearance at accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1326	Northwest Men's Restroom (Building 3)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1327	Northwest Men's Restroom (Building 3)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1328	Northwest Men's Restroom (Building 3)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1329	Northwest Men's Restroom (Building 3)	Room/Space (C)	Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Okeeheelee Park	1330	Northwest Men's Restroom (Building 3)	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1331	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1332	Northwest Women's Restroom (Building 3)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1333	Northwest Women's Restroom (Building 3)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1334	Northwest Women's Restroom (Building 3)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
Okeeheelee Park	1335	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1336	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1337	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1338	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1339	Northwest Women's Restroom (Building 3)	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1340	Northwest Women's Restroom (Building 3)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1341	Northwest Women's Restroom (Building 3)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1342	Northwest Women's Restroom (Building 3)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1343	Northwest Women's Restroom (Building 3)	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5". For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$192.50	1	each	\$192.50	1
Okeeheelee Park	1344	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	sq ft	\$0.00	1
Okeeheelee Park	1345	Building 4 Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1346	Building 4 Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
Okeeheelee Park	1347	Building 4 Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1348	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1349	Building 4 Women's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1350	Building 4 Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1351	Building 4 Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1352	Building 4 Women's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1353	Building 4 Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1354	Building 4 Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1355	Building 4 Women's Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, between 34 inches minimum and 48 inches maximum above the finished floor or ground.	\$3,218.75	1	each	\$3,218.75	1
Okeeheelee Park	1356	Building 4 Men's Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1
Okeeheelee Park	1357	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1358	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout	\$2,380.00	1	each	\$2,380.00	2
Okeeheelee Park	1359	Building 4 Men's Restroom	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1360	Building 4 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1361	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1362	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1363	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	1364	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	2	each	\$154.00	1
Okeeheelee Park	1365	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	1366	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1367	Building 4 Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1368	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1369	Building 4 Men's Restroom	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1370	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1371	Building 4 Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1372	Building 4 Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1373	Building 4 Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	1374	Building 4 Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1376	Dog Park Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Okeeheelee Park	1377	Dog Park Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	1378	Dog Park Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	4	staff time	\$0.00	1
Okeeheelee Park	1379	Dog Park Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1381	Disc Golf Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1382	Disc Golf Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1383	Disc Golf Parking	Accessible Routes	Relocate parking and mount sign or stripe a no parking zone at entry to AR to prevent cars from blocking AR.	\$367.50	1	each	\$367.50	1
Okeeheelee Park	1384	Disc Golf Parking	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Okeeheelee Park	1385	Disc Golf Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1386	Disc Golf Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	1	each	\$2,800.00	1
Okeeheelee Park	1388	Boat Ramp Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1389	Boat Ramp Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1390	Boat Ramp Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1391	Boat/bike Rental Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Okeeheelee Park	1392	Boat/bike Rental Parking	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features	\$367.50	1	each	\$367.50	1
Okeeheelee Park	1393	Boat/bike Rental Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1394	Boat/bike Rental Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	2	each	\$420.00	1
Okeeheelee Park	1395	Boat/bike Rental Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Okeeheelee Park	1396	Boat/bike Rental Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1397	Boat/bike Rental Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Okeeheelee Park	1398	Dog Park Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
Okeeheelee Park	1399	Dog Park Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1400	Park Elements	Accessible Routes	Create a route to at least one picnic table and replace with one of a compliant model.	\$2,600.00	1	each	\$2,600.00	5
Okeeheelee Park	1401	Park Elements	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	1	each	\$875.00	2
Okeeheelee Park	1402	Park Elements	Accessible Routes	Create an accessible route to the boat pier or make corrections for a compliant route.	\$59.20	75	lin ft	\$4,440.00	2
Okeeheelee Park	1403	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1404	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1405	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1406	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1409	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1410	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	8	lin ft	\$473.60	2
Okeeheelee Park	1411	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along the accessible route (AR).  Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1412	Park Elements	Accessible Routes	Relocate 20% of dog waste bag dispensers to be along the accessible route (AR).	\$0.00	1	staff time	\$0.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1413	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs.	\$5,598.25	1	each	\$5,598.25	2
Okeeheelee Park	1414	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Okeeheelee Park	1415	Dog Park Common Space	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" above the finished floor (AFF).	\$3,427.00	1	each	\$3,427.00	1
Okeeheelee Park	1416	Dog Park Common Space	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	10	sq ft	\$1,225.00	2
Okeeheelee Park	1417	Dog Park Common Space	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$5,133.25	1	each	\$5,133.25	1
Okeeheelee Park	1418	Dog Park Common Space	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$5,037.00	1	each	\$5,037.00	1
Okeeheelee Park	1419	Small Dog Park	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	180	sq ft	\$22,050.00	5
Okeeheelee Park	1420	Small Dog Park	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	40	lin ft	\$2,368.00	5
Okeeheelee Park	1421	Small Dog Park	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	45	lin ft	\$2,664.00	5
Okeeheelee Park	1422	Small Dog Park	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	60	lin ft	\$3,552.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1428	Dog Park Far Right	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	895	sq ft	\$109,637.50	5
Okeeheelee Park	1430	Dog Park Far Right	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$2,404.50	1	each	\$2,404.50	1
Okeeheelee Park	1431	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1432	Dog Park Mens Restroom (Building 6)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1433	Dog Park Mens Restroom (Building 6)	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1434	Dog Park Mens Restroom (Building 6)	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF).	\$2,978.50	1	each	\$2,978.50	1
Okeeheelee Park	1435	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1436	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1437	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1438	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1439	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1440	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance at pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1441	Dog Park Mens Restroom (Building 6)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1442	Dog Park Mens Restroom (Building 6)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1443	Dog Park Mens Restroom (Building 6)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1444	Dog Park Mens Restroom (Building 6)	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$192.50	1	each	\$192.50	1
Okeeheelee Park	1445	Dog Park Mens Restroom (Building 6)	Doors	Provide required maneuvering clearance around pull side of door	\$1,750.00	1	each	\$1,750.00	1
Okeeheelee Park	1446	Dog Park Womens Restroom (Building 6)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1447	Dog Park Womens Restroom (Building 6)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1448	Dog Park Womens Restroom (Building 6)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1449	Dog Park Womens Restroom (Building 6)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1450	Dog Park Womens Restroom (Building 6)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1451	Dog Park Womens Restroom (Building 6)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1452	Dog Park Womens Restroom (Building 6)	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1453	Dog Park Womens Restroom (Building 6)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1454	Dog Park Womens Restroom (Building 6)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1455	Dog Park Womens Restroom (Building 6)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1456	Disc Golf Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	10	each	\$962.50	1
Okeeheelee Park	1457	Disc Golf	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Okeeheelee Park	1458	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1459	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1460	Disc Golf Men's Restroom (Building 5)	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1461	Disc Golf Men's Restroom (Building 5)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1462	Disc Golf Men's Restroom (Building 5)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1463	Disc Golf Men's Restroom (Building 5)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1464	Disc Golf Men's Restroom (Building 5)	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" above the finished floor (AFF).	\$1,704.50	1	each	\$1,704.50	1
Okeeheelee Park	1465	Disc Golf Men's Restroom (Building 5)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1466	Disc Golf Men's Restroom (Building 5)	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1467	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1468	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1469	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1470	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1471	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1472	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1473	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance on the pull side at accessible stall door.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1474	Disc Golf Men's Restroom (Building 5)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1475	Disc Golf Men's Restroom (Building 5)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1476	Disc Golf Men's Restroom (Building 5)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1477	Disc Golf Men's Restroom (Building 5)	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	each	\$0.00	1
Okeeheelee Park	1478	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1479	Disc Golf Women's Restroom (Building 5)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1480	Disc Golf Women's Restroom (Building 5)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1481	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1482	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Okeeheelee Park	1483	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1484	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1485	Disc Golf Women's Restroom (Building 5)	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Okeeheelee Park	1486	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1487	Disc Golf Women's Restroom (Building 5)	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1488	Disc Golf Women's Restroom (Building 5)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1489	Disc Golf Women's Restroom (Building 5)	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$3,158.75	1	each	\$3,158.75	1
Okeeheelee Park	1490	Disc Golf Women's Restroom (Building 5)	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1491	Bike/Boat Rental EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1492	Bike/Boat Rental EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Okeeheelee Park	1493	Bike/Boat Rental EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
Okeeheelee Park	1494	Bike/Boat Rental EAR	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	75	lin ft	\$4,440.00	2
Okeeheelee Park	1495	Bike/Boat Rental EAR	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Okeeheelee Park	1496	Bike/Boat Rental EAR	Park Site (C)	Relocate 20% of garbage cans to be along AR and remount to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1497	Boat Ramps	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1498	Boat Ramps	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County boating facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
Okeeheelee Park	1499	Boat Ramps	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'. In the alternative, leave as is and designate other County boating facilities accessible.	\$875.00	1	each	\$875.00	4
Okeeheelee Park	1500	Boat Ramps	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1501	Boat Ramps	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Okeeheelee Park	1502	Boat Ramps	Curb Ramps	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp.	\$875.00	1	each	\$875.00	1
Okeeheelee Park	1503	Boat Ramps	Curb Ramps	Correct slope of adjacent street surfaces to max 5%.	\$122.50	25	sq ft	\$3,062.50	1
Okeeheelee Park	1504	Waterski Areas	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Provide vertical access to viewing area.	\$7,650.00	1	each	\$7,650.00	2
Okeeheelee Park	1505	Waterski Areas	Accessible Routes	Raise roof structure or pad object in overhead clearance to prevent injury.	\$525.00	1	each	\$525.00	2
Okeeheelee Park	1506	Waterski Areas	Stairways	Install kick plates on all stairs or replace with ones having closed risers	\$84.00	38	each	\$3,192.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1507	Waterski Areas	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	38	each	\$4,750.00	5
Okeeheelee Park	1508	Waterski Areas	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	4	each	\$3,920.00	2
Okeeheelee Park	1509	Waterski Areas	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	4	each	\$0.00	2
Okeeheelee Park	1510	Waterski Areas	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" above the finished floor (AFF) with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing addressed in previous finding.	\$0.00	1	each	\$0.00	2
Okeeheelee Park	1511	Waterski Areas	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" above the finished floor (AFF) with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing addressed in previous finding.	\$0.00	4	each	\$0.00	2
Okeeheelee Park	1512	Waterski Areas	Stairways	Provide 80" overhead clearance if the feasible, in the alternative, pad the obstruction to prevent injury.	\$462.00	1	each	\$462.00	2
Okeeheelee Park	1513	Waterski Areas	Stairways	Replace handrails with ones have a smooth surface. Pricing addressed in previous finding.	\$0.00	4	each	\$0.00	2
Okeeheelee Park	1514	Waterski Areas	Assembly Areas	Extend accessible route to the bleachers and provide required number of wheelchair spaces based on the number of seats provided in bleachers.	\$629.50	4	each	\$2,518.00	2
Okeeheelee Park	1515	Waterski Areas	Accessible Routes	Resurface AR or compact and maintain surface to be free of loose gravel and debris.	\$59.20	35	lin ft	\$2,072.00	2
Okeeheelee Park	1516	Waterski Areas	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1517	Waterski Areas	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1518	Waterski Areas	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Okeeheelee Park	1519	Waterski Areas	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the area.	\$59.20	35	lin ft	\$2,072.00	2
Okeeheelee Park	1520	Waterski Areas	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	110	lin ft	\$6,512.00	2
Okeeheelee Park	1521	Waterski Areas	Clear Floor Space	Repair, bevel or ramp CIL in CGS to max .25".	\$96.25	1	each	\$96.25	2
Okeeheelee Park	1522	Waterski Areas	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	120	lin ft	\$7,104.00	2
Okeeheelee Park	1523	Waterski Areas	Assembly Areas	Provide required amount of wheelchair seats based on the capacity of the bleachers.	\$629.50	4	each	\$2,518.00	2
Okeeheelee Park	1524	Waterski Areas	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	18	each	\$7,276.50	2
Okeeheelee Park	1525	Waterski Areas	Stairways	Install kick plates on all stairs or replace with ones having closed risers.	\$84.00	16	each	\$1,344.00	2
Okeeheelee Park	1526	Waterski Areas	Stairways	<p>SMART PRACTICE</p> <p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p>	\$125.00	18	each	\$2,250.00	5
Okeeheelee Park	1527	Waterski Areas	Stairways	Install handrails on both sides of stairway mounted 34" to 38" above the finished floor (AFF), with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	2
Okeeheelee Park	1528	Waterski Areas	Stairways	Replace or remount handrails to 34" to 38" above the finished floor (AFF). Pricing addressed in previous finding.	\$0.00	2	each	\$0.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1529	Waterski Areas	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" above the finished floor (AFF) with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing addressed in previous finding.	\$0.00	2	each	\$0.00	2
Okeeheelee Park	1530	Waterski Areas	Stairways	Replace handrails with ones have a smooth surface. Pricing addressed in previous finding.	\$0.00	2	each	\$0.00	2
Okeeheelee Park	1531	Waterski Areas	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Provide vertical access to raised viewing area.	\$14,206.00	1	each	\$14,206.00	2
Okeeheelee Park	1532	Waterski Areas	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table.	\$1,120.00	2	each	\$2,240.00	5
Okeeheelee Park	1533	Waterski Areas	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	75	lin ft	\$4,440.00	2
Okeeheelee Park	1534	Waterski Areas	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	60	lin ft	\$3,552.00	2
Okeeheelee Park	1535	Waterski Areas	Accessible Routes	Create an accessible route to the boat pier or make corrections for a compliant route.  Correct slope of transition plates to max 8.33% and provide landings on pier.  In the alternative, leave as is and designate other County boating facilities accessible.	\$6,614.50	1	each	\$6,614.50	4
Okeeheelee Park	1536	Waterski Areas	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	2
Okeeheelee Park	1537	BMX Area Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1538	BMX Area Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
Okeeheelee Park	1539	BMX Area Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1540	BMX Area Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1541	BMX Area Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1542	BMX Area Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1543	BMX Area Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1544	BMX Area Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1545	BMX Area Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1547	BMX Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1548	BMX Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
Okeeheelee Park	1549	BMX Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1550	BMX Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Okeeheelee Park	1551	BMX Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1552	BMX Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1553	BMX Women's Restroom	Toilet and Bathing Rooms	Remount stall door or reconfigure partitions to provide min 18" clearance pull side of accessible stall door.	\$2,749.25	1	each	\$2,749.25	1
Okeeheelee Park	1554	BMX Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1555	BMX Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1556	BMX Women's Restroom	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Okeeheelee Park	1558	Restroom Building By Boat Ramp Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
Okeeheelee Park	1559	Restroom Building By Boat Ramp Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Okeeheelee Park	1560	Restroom Building By Boat Ramp Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1561	Restroom Building By Boat Ramp Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1562	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Okeeheelee Park	1563	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1564	Canoe/Kayak Launch	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of boarding pier surface.	\$0.00	1	staff time	\$0.00	2
Okeeheelee Park	1565	Canoe/Kayak Launch	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	30	lin ft	\$1,776.00	1
Okeeheelee Park	1566	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1567	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1568	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1569	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1570	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1571	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1572	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1573	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1574	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	1575	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Okeeheelee Park	1576	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	1577	Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1578	Women's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1579	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1580	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Okeeheelee Park	1581	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1582	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1583	Women's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1584	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1585	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1586	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Okeeheelee Park	1587	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Okeeheelee Park	1588	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1589	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Okeeheelee Park	1590	Family Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1591	Family Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1592	Family Restroom	Plumbing Fixtures & Elements	Leave as is sink, citing construction tolerance.	\$0.00	1	each	\$0.00	4
Okeeheelee Park	1593	Family Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1594	Family Restroom	Reach Ranges	Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1595	Family Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1596	Family Restroom	Toilet and Bathing Rooms	Relocate soap dispenser and spigot to provide required 60" clearance around toilet.	\$175.00	2	each	\$350.00	1
Okeeheelee Park	1597	Family Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Okeeheelee Park	1598	Family Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1599	Family Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Okeeheelee Park	1600	Family Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Okeeheelee Park	1602	Employee Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1
Okeeheelee Park	1603	Heart Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	5280	lin ft	\$312,576.00	4
Okeeheelee Park	1604	Heart Trail Elements	Park Site (C)	Extend accessible surface to each fitness station. In the alternative, leave as is and designate other County fitness amenities accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1605	Heart Trail Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County trails accessible.	\$59.20	60	lin ft	\$3,552.00	4
Okeeheelee Park	1606	South Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	600	sq ft	\$73,500.00	4
Okeeheelee Park	1607	South Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	3	each	\$288.75	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1608	South Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	1240	sq ft	\$151,900.00	4
Okeeheelee Park	1609	South Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	465	sq ft	\$56,962.50	4
Okeeheelee Park	1610	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	130	lin ft	\$7,696.00	4
Okeeheelee Park	1611	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	15	lin ft	\$888.00	4
Okeeheelee Park	1612	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	200	sq ft	\$24,500.00	4
Okeeheelee Park	1613	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	200	sq ft	\$24,500.00	4
Okeeheelee Park	1614	South Trail Loop At South End Of Paved Trail - Surface	Trails	Correct or fill gaps to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
Okeeheelee Park	1615	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	80	sq ft	\$9,800.00	4
Okeeheelee Park	1616	South Trail Loop At South End Of Paved Trail - Surface	Trails	Correct or fill gaps to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
Okeeheelee Park	1617	South Trail Loop At South End Of Paved Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$329.00	2	each	\$658.00	4
Okeeheelee Park	1618	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	160	sq ft	\$19,600.00	4
Okeeheelee Park	1619	South Trail Loop At South End Of Paved Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	25	sq ft	\$3,062.50	4
Okeeheelee Park	1620	Eagle Trail Surface	Outdoor - Trails (C)	Correct trail width to min 36" clear width with 60" turning spaces every 1000'. In the alternative, leave as is and designate other County trails accessible.	\$875.00	1	each	\$875.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1621	Eagle Trail Surface	Outdoor - Trails (C)	<p>Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.</p> <p>Frequently maintain trail surface in identified washout areas to assure CILs remain 2" or less and gaps are filled as a smart practice.</p> <p>In the alternative, leave as is and designate other County trails accessible.</p>	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1622	Eagle Trail Elements	Accessible Routes	<p>Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County trails accessible.</p>	\$59.20	90	lin ft	\$5,328.00	4
Okeeheelee Park	1623	Eagle Trail (Shell-rock Surfaced Outer Trail - Moving Counter-clockwise From Kayak Ramp Restroom Are	Outdoor - Trails (C)	<p>Create 60" level turning space every 1000' along the trail. In the alternative, leave as is and designate other County trails accessible.</p>	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1624	Eagle Trail (Shell-rock Surfaced Outer Trail - Moving Counter-clockwise From Kayak Ramp Restroom Are	Outdoor - Trails (C)	<p>Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice. In the alternative, leave as is and designate other County trails accessible.</p>	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1625	Eagle Trail (Shell-rock Surfaced Outer Trail - Moving Counter-clockwise From Kayak Ramp Restroom Are	Outdoor - Trails (C)	<p>Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.</p>	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1626	Eagle Trail (Shell-rock Surfaced Outer Trail - Moving Counter-clockwise From Kayak Ramp Restroom Are	Accessible Routes	<p>Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County trails accessible.</p>	\$59.20	5	lin ft	\$296.00	4
Okeeheelee Park	1627	South Shell-rock Trails - Surface (Near South Paved Trail Loop)	Outdoor - Trails (C)	<p>Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.</p> <p>Frequently maintain trail surface in identified washout areas to assure CILs remain 2" or less and gaps are filled as a smart practice.</p> <p>In the alternative, leave as is and designate other County trails accessible.</p>	\$0.00	1	staff time	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1628	South Shell-rock Trails At Interior Of Eagle Trail Outer Loop) - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Frequently maintain trail surface in identified washout areas to assure CILs remain 2" or less and gaps are filled as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Okeeheelee Park	1629	Shellrock Trails Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$161.00	1	each	\$161.00	4
Okeeheelee Park	1630	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	320	sq ft	\$39,200.00	5
Okeeheelee Park	1631	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Okeeheelee Park	1632	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4000	sq ft	\$490,000.00	5
Okeeheelee Park	1633	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
Okeeheelee Park	1634	Tuskegee Section Surface	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	5	lin ft	\$296.00	5
Okeeheelee Park	1635	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
Okeeheelee Park	1636	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4080	sq ft	\$499,800.00	5
Okeeheelee Park	1637	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1040	sq ft	\$127,400.00	5
Okeeheelee Park	1638	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	1639	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2080	sq ft	\$254,800.00	5
Okeeheelee Park	1640	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2600	sq ft	\$318,500.00	5
Okeeheelee Park	1641	Tuskegee Section Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Okeeheelee Park	1642	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	1643	Tuskegee Section Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1035	sq ft	\$126,787.50	5
Okeeheelee Park	1644	Tuskegee Section Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	2	each	\$322.00	5
Okeeheelee Park	1645	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1646	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
Okeeheelee Park	1647	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	19760	sq ft	\$2,420,600.00	5
Okeeheelee Park	1648	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Okeeheelee Park	1649	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1650	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1651	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1652	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1440	sq ft	\$176,400.00	5
Okeeheelee Park	1653	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1560	sq ft	\$191,100.00	5
Okeeheelee Park	1654	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1440	sq ft	\$176,400.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1655	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1656	Road Crossing To Tuskegee Pavilion To Tennis/pickleball To Trail Intersection With Trail Along Eshle	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	2	each	\$322.00	5
Okeeheelee Park	1657	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2400	sq ft	\$294,000.00	5
Okeeheelee Park	1658	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1320	sq ft	\$161,700.00	5
Okeeheelee Park	1659	Osceola Area Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1660	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4920	sq ft	\$602,700.00	5
Okeeheelee Park	1661	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2080	sq ft	\$254,800.00	5
Okeeheelee Park	1662	Osceola Area Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	8	each	\$2,632.00	5
Okeeheelee Park	1663	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair running slope along trail to max 12.5% for 10 ft max, with resting intervals at each end.	\$122.50	50	sq ft	\$6,125.00	5
Okeeheelee Park	1664	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	480	sq ft	\$58,800.00	5
Okeeheelee Park	1665	Osceola Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Okeeheelee Park	1666	Osceola Area Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1667	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4800	sq ft	\$588,000.00	5
Okeeheelee Park	1668	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	5400	sq ft	\$661,500.00	5
Okeeheelee Park	1669	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair trail running slope to not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	1670	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair trail running slope to not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Okeeheelee Park	1671	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4800	sq ft	\$588,000.00	5
Okeeheelee Park	1672	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	5600	sq ft	\$686,000.00	5
Okeeheelee Park	1673	Disc Golf Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1425	sq ft	\$174,562.50	5
Okeeheelee Park	1674	Disc Golf Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1675	Disc Golf Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	3	each	\$483.00	5
Okeeheelee Park	1676	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1677	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	800	sq ft	\$98,000.00	5
Okeeheelee Park	1678	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	35	lin ft	\$2,072.00	5
Okeeheelee Park	1679	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	720	sq ft	\$88,200.00	5
Okeeheelee Park	1680	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1920	sq ft	\$235,200.00	5
Okeeheelee Park	1681	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	4	each	\$385.00	5
Okeeheelee Park	1682	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	10400	sq ft	\$1,274,000.00	5
Okeeheelee Park	1683	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Resurface trail to eliminate deterioration as a smart practice.	\$59.20	30	lin ft	\$1,776.00	5
Okeeheelee Park	1684	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1680	sq ft	\$205,800.00	5
Okeeheelee Park	1685	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1686	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1687	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1688	Micanopy Boat Ramp Parking Entry Drive To Road To Maintenance - Elements	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4400	sq ft	\$539,000.00	5
Okeeheelee Park	1689	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1080	sq ft	\$132,300.00	5
Okeeheelee Park	1690	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1691	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1692	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1693	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	17600	sq ft	\$2,156,000.00	5
Okeeheelee Park	1694	Boat Rental Bridge To Alligator Pavilion To Road Crossing At Soccer Field 14 - Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	2	each	\$322.00	5
Okeeheelee Park	1695	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1040	sq ft	\$127,400.00	5
Okeeheelee Park	1696	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2840	sq ft	\$347,900.00	5
Okeeheelee Park	1697	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1545	sq ft	\$189,262.50	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1698	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2400	sq ft	\$294,000.00	5
Okeeheelee Park	1699	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2400	sq ft	\$294,000.00	5
Okeeheelee Park	1700	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1320	sq ft	\$161,700.00	5
Okeeheelee Park	1701	West Trail Around Ball Fields Surface	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	5
Okeeheelee Park	1702	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair running slope along trail to max 8.33% for 200 ft max, with resting intervals at each end.	\$59.20	50	sq ft	\$2,960.00	5
Okeeheelee Park	1703	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2905	sq ft	\$355,862.50	5
Okeeheelee Park	1704	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3040	sq ft	\$372,400.00	5
Okeeheelee Park	1705	West Trail Around Ball Fields Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	840	sq ft	\$102,900.00	5
Okeeheelee Park	1706	West Trail Around Ball Fields Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1707	West Trail Around Ball Fields Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1708	West Trail Around Ball Fields Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Okeeheelee Park	1709	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	1710	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Okeeheelee Park	1711	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	1712	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2680	sq ft	\$328,300.00	5
Okeeheelee Park	1713	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	staff time	\$96.25	5
Okeeheelee Park	1714	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1715	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Okeeheelee Park	1716	Okeeheelee Park Rd (Golf Course Park Entry) To SE Corner Of Park - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Okeeheelee Park	1717	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Okeeheelee Park	1718	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	520	sq ft	\$63,700.00	5
Okeeheelee Park	1719	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	640	sq ft	\$78,400.00	5
Okeeheelee Park	1720	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1320	sq ft	\$161,700.00	5
Okeeheelee Park	1721	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	3	each	\$288.75	5
Okeeheelee Park	1722	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1723	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	5880	sq ft	\$720,300.00	5
Okeeheelee Park	1724	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Okeeheelee Park	1725	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Okeeheelee Park	1726	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	4320	sq ft	\$529,200.00	5
Okeeheelee Park	1727	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	240	sq ft	\$29,400.00	5
Okeeheelee Park	1728	Okeeheelee Park Rd (Golf Course Park Entry) To Eshleman Trail Park Entry - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	360	sq ft	\$44,100.00	5
Okeeheelee Park	1729	Along Entry Drive At Alligator Area Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1730	Along Entry Drive At Alligator Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1120	sq ft	\$137,200.00	5
Okeeheelee Park	1731	Along Entry Drive At Alligator Area Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Okeeheelee Park	1732	Along Entry Drive At Alligator Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1360	sq ft	\$166,600.00	5
Okeeheelee Park	1733	Along Entry Drive At Alligator Area Trail Surface	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	5
Okeeheelee Park	1734	Along Dog Park Area Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1735	Along Dog Park Area Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	5760	sq ft	\$705,600.00	5
Okeeheelee Park	1736	Along Dog Park Area Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.	\$161.00	1	each	\$161.00	5
Okeeheelee Park	1737	Eshleman Trail Park Entry To BMX Area Restrooms - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	7200	sq ft	\$882,000.00	5
Okeeheelee Park	1738	Eshleman Trail Park Entry To BMX Area Restrooms - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Okeeheelee Park	1739	Eshleman Trail Park Entry To BMX Area Restrooms - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	600	sq ft	\$73,500.00	5
Okeeheelee Park	1740	Eshleman Trail Park Entry To BMX Area Restrooms - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	7200	sq ft	\$882,000.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Old Trail Park	1	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Old Trail Park	2	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
Old Trail Park	3	Play Area (2-5)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.  Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Old Trail Park	4	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	1000	sq ft	\$70,000.00	4
Old Trail Park	5	Play Area (2-5)	Accessible Routes	Repair, bevel or ramp change in level along accessible route. See previous finding for cost.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Old Trail Park	11	Play Area (5-12)	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Old Trail Park	12	Play Area (5-12)	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Old Trail Park	13	Park Element	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Park Ridge Golf Course	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	6	each	\$441.00	1
Park Ridge Golf Course	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	8	each	\$24,500.00	1
Park Ridge Golf Course	4	Parking	Parking - Off Street	Reinstall existing accessible parking sign, so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Park Ridge Golf Course	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	7	each	\$673.75	1
Park Ridge Golf Course	7	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Park Ridge Golf Course	8	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	9	Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Park Ridge Golf Course	10	Exterior Accessible Route	Protruding Object	Continue to wrap handrail around top of ramp to prevent protrusion into the route.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	11	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Park Ridge Golf Course	12	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%. Cost included in previous finding.	\$0.00	1	each	\$0.00	3
Park Ridge Golf Course	13	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Park Ridge Golf Course	14	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Park Ridge Golf Course	15	Exterior Accessible Route	Ramps (Not Curb Ramps)	Establish protocols for regular and frequent inspection and maintenance of plants adjacent to ramp.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	16	Exterior Accessible Route	Accessible Routes	Relocate carts to prevent obstruction of 36" clear width along the AR.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	17	Exterior Accessible Route	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	2	each	\$700.00	1
Park Ridge Golf Course	18	Exterior Accessible Route	Accessible Routes	Remove cones for 36" clear width along the AR.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	19	Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,015.00	1	each	\$1,015.00	1
Park Ridge Golf Course	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Park Ridge Golf Course	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	9	each	\$27,562.50	1
Park Ridge Golf Course	22	Golf Course	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
Park Ridge Golf Course	23	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	25	Park Elements	Custom/Special	Acquire an accessible single rider golf cart and advertise its availability on course and County websites as a smart practice.	\$14,000.00	1	each	\$14,000.00	5
Park Ridge Golf Course	26	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Park Ridge Golf Course	27	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	28	Public Spaces	Dining, Bar and Work Surfaces	Remove merchandise and items from lowered section of service counter.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	29	Public Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	30	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, mount signage directing patrons using mobility devices to an accessible egress door.	\$245.00	2	each	\$490.00	1
Park Ridge Golf Course	31	Public Spaces	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Park Ridge Golf Course	32	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	33	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	35	Public Spaces	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	2	each	\$280.00	1
Park Ridge Golf Course	36	Public Spaces	Reach Ranges	Relocate at least on of each type of beverage offered to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	37	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.  Remove items from lowered section of counter.	\$1,120.00	2	each	\$2,240.00	1
Park Ridge Golf Course	38	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$280.00	2	each	\$560.00	1
Park Ridge Golf Course	39	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
Park Ridge Golf Course	40	Public Spaces	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	41	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	\$118.25	2	each	\$236.50	3
Park Ridge Golf Course	42	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Park Ridge Golf Course	43	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Park Ridge Golf Course	44	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Park Ridge Golf Course	45	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	2	staff time	\$0.00	3
Park Ridge Golf Course	46	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.  Mount compliant signage at all doors along the egress route	\$210.00	2	each	\$420.00	3
Park Ridge Golf Course	47	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	48	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Park Ridge Golf Course	49	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Correct slope in door clearance to max 2.08%.  Ramp CILs at door entries to max .25".  Remount hardware a min 34" and max 48".	\$9,808.75	1	each	\$9,808.75	3
Park Ridge Golf Course	50	Club House Men's Restroom	Toilet and Bathing Rooms	Install mirror in wheelchair stall and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	51	Club House Men's Restroom	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Park Ridge Golf Course	52	Club House Men's Restroom	Plumbing Fixtures & Elements	Install urinal having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Park Ridge Golf Course	53	Club House Men's Restroom	Reach Ranges	Remount baby changing table and paper towel dispenser so operable parts are in reach range of 15" min to 48" max.  Remount baby changing table so work surface is a min 28" and max 34".	\$0.00	2	staff time	\$0.00	1
Park Ridge Golf Course	54	Club House Men's Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Park Ridge Golf Course	55	Club House Men's Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser, soap dispenser, and trash can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	56	Club House Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Park Ridge Golf Course	57	Club House Men's Restroom	Toilet and Bathing Rooms	Replace or remount rear grab bar with a 1.5" spacing between gripping surface and wall.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	58	Club House Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Park Ridge Golf Course	59	Club House Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	60	Club House Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	3	staff time	\$0.00	1
Park Ridge Golf Course	61	Club House Men's Restroom	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	1	each	\$140.00	1
Park Ridge Golf Course	62	Club House Women's Restroom	Reach Ranges	Remount baby changing table so handle is in reach range of 15" min to 48" max, and work surface when open is a min 28" and max 34".	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	63	Club House Women's Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser and garbage to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	64	Club House Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Park Ridge Golf Course	65	Club House Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Park Ridge Golf Course	66	Club House Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	67	Club House Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	68	Club House Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	1	each	\$140.00	1
Park Ridge Golf Course	69	Course Mens Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	70	Course Mens Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Park Ridge Golf Course	71	Course Mens Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Park Ridge Golf Course	72	Course Mens Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Park Ridge Golf Course	73	Course Mens Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	74	Course Mens Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Park Ridge Golf Course	75	Course Mens Restroom	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$768.25	1	each	\$768.25	1
Park Ridge Golf Course	76	Course Womens Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Park Ridge Golf Course	77	Course Womens Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	78	Course Womens Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	79	Course Womens Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Park Ridge Golf Course	80	Course Womens Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Park Ridge Golf Course	81	Course Womens Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Park Ridge Golf Course	82	Course Womens Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Park Ridge Golf Course	83	Course Womens Restroom	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remount hardware a min 34" and max 48".	\$768.25	1	each	\$768.25	1
Paul Rardin Park	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Paul Rardin Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	4	each	\$12,250.00	1
Paul Rardin Park	4	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	5	each	\$367.50	1
Paul Rardin Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Paul Rardin Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Paul Rardin Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Paul Rardin Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Paul Rardin Park	9	Exterior Accessible Route	Turning Space	Correct cross slopes to max 2.08% in turning space.	\$3,062.50	1	each	\$3,062.50	1
Paul Rardin Park	10	Exterior Accessible Route	Turning Space	Correct cross slopes to max 2.08% in turning space.	\$3,062.50	1	each	\$3,062.50	1
Paul Rardin Park	11	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. Relocate garbage can to be along AR.	\$59.20	5	lin ft	\$296.00	5
Paul Rardin Park	12	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Paul Rardin Park	13	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.	\$3,062.50	1	each	\$3,062.50	5
Paul Rardin Park	14	Shelters/Picnic Areas	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	5
Paul Rardin Park	15	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Paul Rardin Park	16	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. Relocate garbage can to be along AR.	\$59.20	20	lin ft	\$1,184.00	5
Paul Rardin Park	17	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Paul Rardin Park	18	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Paul Rardin Park	19	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. Relocate garbage can to be along AR.	\$444.00	2	each	\$888.00	5
Paul Rardin Park	20	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.	\$3,062.50	1	each	\$3,062.50	5
Paul Rardin Park	21	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	5
Paul Rardin Park	22	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Paul Rardin Park	24	Picnic Pavilion	Outdoor Recreation Access Routes (C)	Correct or repair ORAR slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$122.50	25	sq ft	\$3,062.50	4
Paul Rardin Park	25	Picnic Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
Paul Rardin Park	26	Picnic Pavilion	Picnic Tables (C)	Replace 1 more picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Paul Rardin Park	27	Picnic Pavilion	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.  Remount garbage can to be in reach range of 15" min to 48" max.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$105.00	2	each	\$210.00	4
Paul Rardin Park	28	Picnic Pavilion	Outdoor Recreation Access Route	Relocate 20% of garbage cans to be along AR. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Paul Rardin Park	30	Park Elements	Reach Ranges	Lower operating mechanisms to max 48" aff to highest operable part.	\$0.00	2	staff time	\$0.00	2
Paul Rardin Park	31	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Paul Rardin Park	34	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	35	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. Leave as is sink in stall citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	1
Paul Rardin Park	36	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Paul Rardin Park	37	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Paul Rardin Park	38	Men's Restroom	Toilet and Bathing Rooms	Acquire and install side grab bar that is 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Paul Rardin Park	39	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Paul Rardin Park	40	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	2	each	\$420.00	1
Paul Rardin Park	41	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	42	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Paul Rardin Park	43	Women's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Paul Rardin Park	44	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	45	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	2	each	\$4,760.00	1
Paul Rardin Park	46	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	47	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Paul Rardin Park	48	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	49	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Paul Rardin Park	50	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Paul Rardin Park	51	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Paul Rardin Park	52	Women's Restroom	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Paul Rardin Park	53	Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Paul Rardin Park	54	Playground	Clear Floor Space	Remount or relocate signage to provide 30" x 48" clear space along an accessible route. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Paul Rardin Park	55	Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Paul Rardin Park	56	Playground	Accessible Routes	Fill and compact playground surfaces to be level with adjacent surfaces and walkways. Price included in previous finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Paul Rardin Park	57	Playground	Play Area	Lower platform on transfer system to 11" to 18" AFF, in the alternative, add and maintain surface fill level to achieve the same. Price included in earlier finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Paul Rardin Park	58	Playground	Play Area	Make corrections to surface to provide access to 50% of EPCs. Price included in earlier finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Paul Rardin Park	59	Playground	Play Area	Make corrections to surface to provide AR to GLPCs. See earlier finding for costs.  Add another interactive on the route.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Paul Rardin Park	60	Playground	Play Area	Make corrections to surface to meet incentive scoping. Price included in earlier finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Paul Rardin Park	61	Playground	Play Area	Install play table with knee clearance and locate along an accessible route. Price included in earlier finding. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
<u>Peanut Island Park</u>	1	Exterior Accessible Route	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3
Peanut Island Park	2	Exterior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Peanut Island Park	3	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	\$96.25	1	each	\$96.25	3
Peanut Island Park	4	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF	\$980.00	2	each	\$1,960.00	3
Peanut Island Park	5	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Peanut Island Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Peanut Island Park	7	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Peanut Island Park	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	25	each	\$2,406.25	1
Peanut Island Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	20	each	\$1,925.00	1
Peanut Island Park	10	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Peanut Island Park	11	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Peanut Island Park	12	Exterior Accessible Route	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.	\$980.00	2	each	\$1,960.00	1
Peanut Island Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Peanut Island Park	14	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
Peanut Island Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Peanut Island Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
Peanut Island Park	17	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Peanut Island Park	18	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	2	each	\$1,750.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	19	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	3
Peanut Island Park	20	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	2	each	\$1,750.00	3
Peanut Island Park	21	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Peanut Island Park	22	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Peanut Island Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Peanut Island Park	24	Park Elements	Park Site (C)	Provide an accessible route (AR) to one of each element within the site.	\$59.20	10	lin ft	\$592.00	2
Peanut Island Park	25	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	26	Park Elements	Outdoor - Constructed Features (C)	Correct surface at outdoor rinsing shower to firm, stable, and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Peanut Island Park	27	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Peanut Island Park	28	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.  Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$890.75	1	each	\$890.75	5
Peanut Island Park	29	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.  Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$890.75	1	each	\$890.75	5
Peanut Island Park	30	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$1,470.00	1	each	\$1,470.00	5
Peanut Island Park	31	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	32	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.  Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$890.75	1	each	\$890.75	5
Peanut Island Park	33	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Peanut Island Park	34	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Peanut Island Park	35	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Peanut Island Park	36	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	10	lin ft	\$592.00	5
Peanut Island Park	37	Park Elements	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	1
Peanut Island Park	38	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Peanut Island Park	39	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Peanut Island Park	40	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	41	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	42	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Peanut Island Park	43	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	25	lin ft	\$1,480.00	2
Peanut Island Park	44	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Peanut Island Park	45	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	46	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	3	lin ft	\$177.60	2
Peanut Island Park	47	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to one of each type of element.	\$59.20	10	lin ft	\$592.00	2
Peanut Island Park	48	Park Elements	Reach Ranges	Remount operable parts to one dog bag dispenser to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2
Peanut Island Park	49	Park Elements	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	20	each	\$1,925.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	51	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice.	\$59.20	3	lin ft	\$177.60	5
Peanut Island Park	52	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	\$350.00	1	each	\$350.00	5
Peanut Island Park	53	Shelters/Picnic Areas	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$8,160.00	1	each	\$8,160.00	4
Peanut Island Park	54	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Establish protocols for regular and frequent inspection and maintenance of walkway and accessible picnic area surfaces.	\$0.00	1	staff time	\$0.00	5
Peanut Island Park	55	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Peanut Island Park	56	Shelters/Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	3	each	\$7,458.00	5
Peanut Island Park	57	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$122.50	25	sq ft	\$3,062.50	4
Peanut Island Park	58	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
Peanut Island Park	59	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice, in each pavilion. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Peanut Island Park	60	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	3	lin ft	\$177.60	4
Peanut Island Park	61	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	2	each	\$700.00	4
Peanut Island Park	62	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	63	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$28.00	950	sq ft	\$26,600.00	4
Peanut Island Park	64	Shelters/Picnic Areas	Picnic Tables (C)	Replace 20% of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	3	each	\$3,360.00	4
Peanut Island Park	65	Shelters/Picnic Areas	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	30	lin ft	\$1,776.00	4
Peanut Island Park	66	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4
Peanut Island Park	67	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$28.00	360	sq ft	\$10,080.00	4
Peanut Island Park	68	Shelters/Picnic Areas	Accessible Routes	Raise roof material to min 80".  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,540.00	1	each	\$1,540.00	4
Peanut Island Park	69	Shelters/Picnic Areas	Picnic Tables (C)	Replace both picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Peanut Island Park	70	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Relocate garbage can to be along AR. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Peanut Island Park	71	Beaches	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches as accessible.	\$59.20	225	lin ft	\$13,320.00	4
Peanut Island Park	72	Beaches	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	73	Beaches	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches as accessible.	\$59.20	225	lin ft	\$13,320.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	74	Beaches	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches as accessible.	\$59.20	25	lin ft	\$1,480.00	4
Peanut Island Park	75	Beaches	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	76	Beaches	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Peanut Island Park	77	Beaches	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other County beaches as accessible.	\$59.20	200	lin ft	\$11,840.00	4
Peanut Island Park	78	Fishing	Accessible Routes	Correct or fill gaps to be max .5". In the alternative, leave as is and designate other County fishing areas as accessible.	\$96.25	2	each	\$192.50	4
Peanut Island Park	79	Fishing	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34". In the alternative, leave as is and designate other County fishing areas as accessible.	\$980.00	72	each	\$70,560.00	4
Peanut Island Park	80	Fishing	Dining, Bar and Work Surfaces	Replace one fish cleaning station with one max 34" to surface and allowing knee and toe clearance. In the alternative, leave as is and designate other County fishing areas as accessible.	\$1,120.00	1	each	\$1,120.00	4
Peanut Island Park	81	Boating	Custom/Special	Ensure the dock is fully compliant when reopened.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	82	Boating	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	2
Peanut Island Park	83	Boating	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	2
Peanut Island Park	84	Boating	Accessible Routes	Correct or repair running slope along AR to max 5%. Correct or fill 1" gap along AR.	\$3,158.75	1	each	\$3,158.75	2
Peanut Island Park	85	Boating	Accessible Routes	Create an accessible route to the fishing pier or make corrections for a compliant route. Correct or fill 1" gap along AR. Establish protocols for regular and frequent inspection and maintenance of pier/dock surfaces.	\$96.25	1	each	\$96.25	2
Peanut Island Park	86	Boating	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$980.00	35	each	\$34,300.00	2
Peanut Island Park	88	SE - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	89	SE - Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	2	staff time	\$0.00	1
Peanut Island Park	90	SE - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Peanut Island Park	91	SE - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	92	SE - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Peanut Island Park	93	SE - Women's Restroom	Reach Ranges	Remount hook and baby changing table handle to be in reach range of 15" min to 48" max, and so baby changing table work surface is max 34" AFF when open.	\$0.00	2	staff time	\$0.00	1
Peanut Island Park	94	SE - Women's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Peanut Island Park	95	SE - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF). In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Peanut Island Park	96	SE - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Peanut Island Park	97	SE - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	98	SE - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Peanut Island Park	99	SE - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	100	SE - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Peanut Island Park	101	SE - Men's Restroom	Toilet and Bathing Rooms	Relocate signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	102	SE - Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	2	staff time	\$0.00	1
Peanut Island Park	103	SE - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	104	SE - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Peanut Island Park	105	SE - Men's Restroom	Reach Ranges	Remount hook and baby changing table handle to be in reach range of 15" min to 48" max, and so work surface of baby changing table is max 34" when open.	\$0.00	2	staff time	\$0.00	1
Peanut Island Park	106	SE - Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Peanut Island Park	107	SE - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Peanut Island Park	108	SE - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	109	SE - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be fully self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	110	SE - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Repair baby changer to remain closed when not in use.	\$350.00	2	each	\$700.00	1
Peanut Island Park	111	SE - Men's Restroom	Doors	Replace closer with a different model that provide min 78" overhead clearance.	\$350.00	1	each	\$350.00	1
Peanut Island Park	113	West - Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Peanut Island Park	114	West - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Peanut Island Park	115	West - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.  Faucet not functioning - unable to test. Assure sink faucets remain on for min. 10 seconds when reopened.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	116	West - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Peanut Island Park	117	West - Women's Restroom	Reach Ranges	Lower hook and baby changing table to max 48" above the finished floor (AFF) to highest operable part, and so work surface of baby changing table is max 34" when open.  Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$116.50	3	each	\$349.50	1
Peanut Island Park	118	West - Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Peanut Island Park	119	West - Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF). In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Peanut Island Park	120	West - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Peanut Island Park	121	West - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	122	West - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Peanut Island Park	123	West - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	124	West - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	125	West - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Peanut Island Park	126	West - Men's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Peanut Island Park	127	West - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Peanut Island Park	128	West - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	2	staff time	\$0.00	1
Peanut Island Park	129	West - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Peanut Island Park	130	West - Men's Restroom	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Peanut Island Park	131	West - Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at lower urinal to max 48" AFF. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
Peanut Island Park	132	West - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Peanut Island Park	133	West - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	134	West - Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Peanut Island Park	135	West - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Peanut Island Park	136	West - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Peanut Island Park	137	West - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	138	West - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Peanut Island Park	139	West - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Peanut Island Park	140	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Peanut Island Park	141	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Peanut Island Park	142	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	520	sq ft	\$63,700.00	5
Peanut Island Park	143	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2640	sq ft	\$323,400.00	5
Peanut Island Park	144	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2640	sq ft	\$323,400.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	145	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	880	sq ft	\$107,800.00	5
Peanut Island Park	146	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Peanut Island Park	147	Trail Surface	Outdoor - Trails (C)	Repair and reset pavers to eliminate CIL and gaps.	\$28.00	180	sq ft	\$5,040.00	5
Peanut Island Park	148	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Peanut Island Park	149	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
Peanut Island Park	150	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Peanut Island Park	151	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	5	each	\$481.25	5
Peanut Island Park	152	Trail Surface	Outdoor - Trails (C)	Repair and reset pavers to eliminate CIL and gaps.	\$28.00	150	sq ft	\$4,200.00	5
Peanut Island Park	153	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5
Peanut Island Park	154	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	160	sq ft	\$19,600.00	5
Peanut Island Park	155	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	3600	sq ft	\$441,000.00	5
Peanut Island Park	156	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1200	sq ft	\$147,000.00	5
Peanut Island Park	157	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	40	sq ft	\$4,900.00	5
Peanut Island Park	158	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Peanut Island Park	159	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	6	each	\$577.50	5
Peanut Island Park	160	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	50	sq ft	\$2,960.00	5
Peanut Island Park	161	Trail Surface	Outdoor - Trails (C)	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Peanut Island Park	162	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Peanut Island Park	165	CG - EAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	80	sq ft	\$9,800.00	5
Peanut Island Park	166	CG - EAR	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	167	CG - EAR	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%	\$6,510.00	1	each	\$6,510.00	3
Peanut Island Park	168	CG - EAR	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	2	each	\$1,750.00	3
Peanut Island Park	169	CG - EAR	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	3
Peanut Island Park	170	CG - EAR	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Peanut Island Park	171	CG - Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	172	CG - Campsites	Outdoor - Constructed Features (C)	Remount two water spouts (one near accessible site and one near pavilion) to 28" min or 36" max above the ground as a smart practice.	\$350.00	2	each	\$700.00	5
Peanut Island Park	174	CG - Campsites	Outdoor - Constructed Features (C)	Provide required firm and stable 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$950.00	1	each	\$950.00	5
Peanut Island Park	176	CG - Restrooms and Showers	Custom/Special	Ensure that the campground restrooms and showers are fully compliant when reopened. Restrooms likely have issues similar to the other restrooms at this site.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	177	CG - Maintenance	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$1,192.25	3	each	\$3,576.75	3
Peanut Island Park	178	CG - Maintenance	Room/Space (C)	Ensure compliant circulation path when room is reopened for use.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	179	CG - Park Ranger Office/Residence	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Peanut Island Park	180	CG - Park Ranger Office/Residence	Doors	Remove or secure mat at door to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Peanut Island Park	181	CG - Park Ranger Office/Residence	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Peanut Island Park	182	CG - Park Ranger Office/Residence	Toilet and Bathing Rooms	Acquire and mount signage, including access symbol.  Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Peanut Island Park	183	CG - Park Ranger Office/Residence	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	184	CG - Park Ranger Office/Residence	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	185	CG - Park Ranger Office/Residence	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	186	CG - Park Ranger Office/Residence	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF), with no obstructions a min 12" above or 1.5" below grab bar.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$196.75	2	each	\$393.50	1
Peanut Island Park	187	CG - Park Ranger Office/Residence	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Peanut Island Park	188	CG - Park Ranger Office/Residence	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	189	CG - Park Ranger Office/Residence	Turning Space	Widen restroom to allow for turning space.	\$4,620.00	1	each	\$4,620.00	3
Peanut Island Park	190	CG - Park Ranger Office/Residence	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Peanut Island Park	191	CG - Park Ranger Office/Residence	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	194	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$5,248.25	1	each	\$5,248.25	3
Peanut Island Park	195	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
Peanut Island Park	196	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Peanut Island Park	197	Lifeguard Building	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$768.25	1	each	\$768.25	1
Peanut Island Park	198	Lifeguard Building	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	199	Lifeguard Building	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	1	staff time	\$0.00	1
Peanut Island Park	200	Lifeguard Building	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	2
Peanut Island Park	201	Lifeguard Building	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.  Correct or repair slope of clear ground space to max 2.08%.  Widen outdoor rinsing shower area to min 60" by 60".  Lower latch to max 48" AGL.	\$6,683.25	1	each	\$6,683.25	3
Phil Foster Park	1	Parking - Boat Trailer	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	3	each	\$4,767.00	1
Phil Foster Park	2	Parking - Boat Trailer	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Phil Foster Park	3	Parking - Boat Trailer	Parking - Off Street	Raise obstructions over van stalls to provide 98" vertical clearance.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	4	Parking - Boat Trailer	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Phil Foster Park	5	Parking - Boat Trailer	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	1	each	\$367.50	1
Phil Foster Park	6	Parking - Boat Trailer	Parking - Off Street	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	2	each	\$5,600.00	1
Phil Foster Park	7	Parking - Boat Trailer	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Phil Foster Park	8	Parking - Boat Trailer	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswal	\$367.50	1	each	\$367.50	1
Phil Foster Park	9	Parking - Boat Trailer	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Phil Foster Park	11	Parking - Standard/Main Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Phil Foster Park	12	Parking - Standard/Main Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. Leave as is 2.3% slope citing construction tolerance.	\$3,062.50	5	each	\$15,312.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	13	Parking - Standard/Main Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	14	Parking - Standard/Main Parking	Parking - Off Street	Add two van parking sign to two accessible stalls and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Phil Foster Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Phil Foster Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Phil Foster Park	17	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Phil Foster Park	18	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	19	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Phil Foster Park	20	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Phil Foster Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Phil Foster Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Phil Foster Park	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	240	sq ft	\$29,400.00	1
Phil Foster Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Phil Foster Park	26	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	3	each	\$288.75	1
Phil Foster Park	27	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	28	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	29	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Phil Foster Park	30	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	3	each	\$9,187.50	1
Phil Foster Park	33	Exterior Accessible Route	Accessible Routes	Trim foliage to maintain route to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	34	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	220	sq ft	\$26,950.00	1
Phil Foster Park	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Phil Foster Park	37	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	38	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	39	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Phil Foster Park	40	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	41	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	42	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Phil Foster Park	44	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	805	sq ft	\$98,612.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	46	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	47	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	48	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	49	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Phil Foster Park	50	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surfaces.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	51	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	330	sq ft	\$40,425.00	1
Phil Foster Park	52	Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,015.00	1	each	\$1,015.00	1
Phil Foster Park	53	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	1	each	\$875.00	1
Phil Foster Park	54	Exterior Accessible Route	Accessible Routes	Trim foliage to maintain route to min 36" clear width.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	55	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	56	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	58	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	60	Park Elements	Clear Floor Space	Relocate drinking fountain to provide 30" wide by 48" deep clear ground space.	\$2,380.00	1	each	\$2,380.00	2
Phil Foster Park	61	Park Elements	Plumbing Fixtures & Elements	Remount fountain to provide centered clear floor space. Pricing provided in a previous finding.	\$350.00	1	each	\$350.00	2
Phil Foster Park	63	Park Elements	ATM's and Fare Machines	Contact provider to replace pay stations with compliant models.	\$5,000.00	2	each	\$10,000.00	2
Phil Foster Park	64	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	each	\$3,062.50	2
Phil Foster Park	65	Park Elements	ATM's and Fare Machines	Replace ATM or fare machine with one that has compliant features. Pricing provided in a previous finding.	\$0.00	2	N/A	\$0.00	2
Phil Foster Park	66	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$4,080.00	1	each	\$4,080.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	67	Shelters/Picnic Areas	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$3,520.00	2	each	\$7,040.00	4
Phil Foster Park	68	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	15	lin ft	\$888.00	4
Phil Foster Park	69	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	4	each	\$1,400.00	4
Phil Foster Park	70	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	3	each	\$3,360.00	4
Phil Foster Park	71	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4
Phil Foster Park	72	Shelters/Picnic Areas	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Phil Foster Park	73	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	4	each	\$385.00	4
Phil Foster Park	74	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	4	each	\$1,400.00	4
Phil Foster Park	75	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Phil Foster Park	76	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	77	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Replace or lower grill to max height of cooking surface 34".  Remount garbage cans so rims are in reach range of 15" min to 48" max.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$850.00	1	each	\$850.00	4
Phil Foster Park	78	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	4	each	\$385.00	4
Phil Foster Park	79	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	4	each	\$1,400.00	4
Phil Foster Park	80	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Phil Foster Park	81	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	6	lin ft	\$355.20	4
Phil Foster Park	82	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max.  Relocate garbage cans to be along AR, with max slope of 2.08% in clear ground space.  Replace or lower grill to max height of cooking surface 34".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$850.00	1	each	\$850.00	4
Phil Foster Park	83	Shelters/Picnic Areas	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	4	each	\$1,400.00	4
Phil Foster Park	84	Shelters/Picnic Areas	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Phil Foster Park	85	Shelters/Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	26	lin ft	\$1,539.20	4
Phil Foster Park	86	Shelters/Picnic Areas	Shelters/Picnic Areas (C)	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	87	Beach	Outdoor - Constructed Features (C)	Remount or replace shower head on one shower with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Phil Foster Park	90	Beach	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice	\$59.20	100	lin ft	\$5,920.00	5
Phil Foster Park	91	Beach	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	200	lin ft	\$11,840.00	2
Phil Foster Park	92	Beach	Beach Access Route (C)	Create a beach access route to mean high water level level of a firm and stable material as a smart practice.	\$6,990.00	1	each	\$6,990.00	5
Phil Foster Park	93	Beach	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	10	each	\$1,250.00	5
Phil Foster Park	94	Beach	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
Phil Foster Park	95	Beach	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
Phil Foster Park	96	Beach	Park Site (C)	Provide an accessible route (AR) to each element within the site, or relocate sign to be along the route.	\$59.20	50	lin ft	\$2,960.00	2
Phil Foster Park	97	Beach	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Phil Foster Park	98	Beach	Park Site (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Phil Foster Park	99	Beach	Park Site (C)	Relocate beach clean-up station to be along AR.	\$0.00	1	staff time	\$0.00	2
Phil Foster Park	100	Fishing	Dining, Bar and Work Surfaces	Replace fish cleaning station table with one with max 34" to surface and allowing knee and toe clearance.  Replace operable parts with ones usable without a tight pinch or grasp.	\$665.00	2	each	\$1,330.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	101	Fishing	Fishing Piers And Platforms	Lower 25% of the railing at SW fishing area; dispersed through pier, to max 34". Relocate fish cleaning station for access to existing lowered area. Leave as is NW fishing area.	\$980.00	3	each	\$2,940.00	2
Phil Foster Park	102	Fishing	Dining, Bar and Work Surfaces	Replace fish cleaning station table with one with max 34" to surface and allowing knee and toe clearance. Replace operable parts with ones usable without a tight pinch or grasp.	\$665.00	2	each	\$1,330.00	2
Phil Foster Park	103	Fishing	Accessible Routes	Correct or fill gaps to be max .5".	\$5,192.50	1	each	\$5,192.50	1
Phil Foster Park	104	Fishing	Accessible Routes	Correct or fill gaps to be max .5".	\$5,096.25	1	each	\$5,096.25	1
Phil Foster Park	105	Fishing	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	106	Fishing	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Phil Foster Park	107	Fishing	Ramps (Not Curb Ramps)	Provide handrail extensions that project 12" onto the ramp landing.	\$217.00	2	each	\$434.00	3
Phil Foster Park	108	Fishing	Ramps (Not Curb Ramps)	Replace handrails with ones that are free of obstructions, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
Phil Foster Park	109	Fishing	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Phil Foster Park	110	Fishing	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
Phil Foster Park	111	Fishing	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	2	each	\$1,750.00	3
Phil Foster Park	112	Fishing	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	3
Phil Foster Park	113	Fishing	Ramps (Not Curb Ramps)	Provide handrail extensions that project 12" onto the ramp landing.	\$217.00	6	each	\$1,302.00	3
Phil Foster Park	114	Fishing	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through	\$525.00	6	each	\$3,150.00	3
Phil Foster Park	115	Fishing	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	80	each	\$7,700.00	1
Phil Foster Park	116	Fishing	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".	\$785.00	69	each	\$54,165.00	3
Phil Foster Park	117	Fishing	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	24	each	\$2,310.00	1
Phil Foster Park	118	Fishing	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Phil Foster Park	119	Fishing	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Phil Foster Park	120	Fishing	Dining, Bar and Work Surfaces	Replace fish cleaning station table with one with max 34" to surface and allowing knee and toe clearance. Replace operable parts with ones usable without a tight pinch or grasp.	\$665.00	2	each	\$1,330.00	2
Phil Foster Park	121	Boating	Dining, Bar and Work Surfaces	Replace fish cleaning station table with one with max 34" to surface and allowing knee and toe clearance.	\$1,120.00	1	each	\$1,120.00	2
Phil Foster Park	122	Boating	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	123	Boating	Accessible Routes	Correct slope of pier accessible route to max 5% running and max 2.08% cross.  Correct or fill gaps on piers and on accessible routes to piers.  Resurface accessible route where deterioration occurs.	\$59.20	150	lin ft	\$8,880.00	2
Phil Foster Park	124	Boating	Accessible Routes	Correct or repair cross slope of accessible route to max 2.08%.  Correct or fill gaps to max .5".  Repair, bevel, or ramp changes in level to max .25".	\$59.20	65	lin ft	\$3,848.00	2
Phil Foster Park	125	2-5 Play Area	Custom/Special	Ensure playground is compliant when reopened. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Phil Foster Park	126	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain closing speed on door closers.	\$48.25	2	each	\$96.50	3
Phil Foster Park	127	SB - EAR	Curb Ramps	Correct slope of side flares to max 8.33%.	\$1,015.00	2	each	\$2,030.00	1
Phil Foster Park	128	SB - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Phil Foster Park	129	SB - EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Phil Foster Park	130	SB - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Phil Foster Park	131	SB - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Phil Foster Park	132	SB - EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Phil Foster Park	133	SB - EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$20,825.00	1	each	\$20,825.00	1
Phil Foster Park	134	SB - Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	135	SB - Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Phil Foster Park	136	SB - Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Phil Foster Park	137	SB - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Phil Foster Park	138	SB - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	139	SB - Women's Restroom	Toilet and Bathing Rooms	Provide 18" pull side clearance at stall door or reverse swing to inward if stall has required additional depth.	\$2,749.25	1	each	\$2,749.25	1
				Adjust stall door to be self-closing.					
Phil Foster Park	140	SB - Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Phil Foster Park	141	SB - Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	142	SB - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Phil Foster Park	143	SB - Women's Restroom	Accessible Routes	Maintain floor surface to be slip resistant. In the alternative; resurface or repair floors to be firm, stable and slip resistant.	\$0.00	1	staff time	\$0.00	1
				Provide required maneuvering clearance around pull side of door.					
Phil Foster Park	144	SB - Women's Restroom	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	145	SB - Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Phil Foster Park	146	SB - Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Phil Foster Park	147	SB - Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	148	SB - Men's Restroom	Toilet and Bathing Rooms	Provide 18" pull side clearance at stall door or reverse to swing inward if stall has required additional depth.	\$2,749.25	1	each	\$2,749.25	1
Phil Foster Park	149	SB - Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Phil Foster Park	150	SB - Men's Restroom	Accessible Routes	Maintain floor surface to be slip resistant. In the alternative; resurface or repair floors to be firm, stable and slip resistant.	\$0.00	1	staff time	\$0.00	1
				Provide required maneuvering clearance around pull side of door.					
Phil Foster Park	151	SB - Men's Restroom	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	152	LGO - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$46.50	3	each	\$139.50	3
Phil Foster Park	153	LGO - Employee Restroom And Shower Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Phil Foster Park	154	LGO - Employee Restroom And Shower Room	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	155	LGO - Employee Restroom And Shower Room	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts	\$350.00	1	each	\$350.00	1
Phil Foster Park	156	LGO - Employee Restroom And Shower Room	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	4
Phil Foster Park	157	LGO - Employee Restroom And Shower Room	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Phil Foster Park	158	LGO - Employee Restroom And Shower Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove or relocate storage from grab bar.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	159	LGO - Employee Restroom And Shower Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.  Pricing for relocating hand dryer provided in a previous finding.	\$116.75	3	each	\$350.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	160	LGO - Employee Restroom And Shower Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Pricing to relocate hand dryer provided in a previous finding.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$771.75	2	each	\$1,543.50	1
Phil Foster Park	161	LGO - Employee Restroom And Shower Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$514.50	1	each	\$514.50	1
Phil Foster Park	162	LGO - Employee Restroom And Shower Room	Plumbing Fixtures & Elements	Provide the required folding or non-folding seat in the transfer shower.	\$840.00	1	each	\$840.00	2
Phil Foster Park	164	LGO - Public Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area, and sink in stall.	\$77.00	2	each	\$154.00	1
Phil Foster Park	165	LGO - Public Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	166	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Relocate fixtures to provide required 60" clearance around toilet.	\$175.00	2	each	\$350.00	1
Phil Foster Park	167	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF). In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Phil Foster Park	168	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Phil Foster Park	169	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate hand dryer to prevent being in clearance of toilet and grab bars Pricing provided in a previous finding.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	170	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Provide 18" pull side clearance at stall door or reverse to swing inward if required extra depth is provided.	\$2,749.25	1	each	\$2,749.25	1
Phil Foster Park	171	LGO - Public Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Phil Foster Park	172	LGO - Public Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	173	LGO - Public Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Phil Foster Park	174	LGO - Public Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Phil Foster Park	175	LGO - Public Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	176	LGO - Public Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Phil Foster Park	177	LGO - Public Men's Restroom	Reach Ranges	Lower hook and soap dispenser in stall to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser in main area to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	178	LGO - Public Men's Restroom	Toilet and Bathing Rooms	Relocate fixtures to provide required 60" clearance around toilet.	\$175.00	2	each	\$350.00	1
Phil Foster Park	179	LGO - Public Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Phil Foster Park	180	LGO - Public Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	181	LGO - Public Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Phil Foster Park	182	LGO - Public Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Phil Foster Park	183	LGO - Public Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Phil Foster Park	184	LGO - Public Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Pinewoods Park	2	Parking	Parking - Off Street	Relocate one or more stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Pinewoods Park	3	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Pinewoods Park	4	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Pinewoods Park	5	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	8	each	\$24,500.00	1
Pinewoods Park	6	Parking	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	7	each	\$19,600.00	1
Pinewoods Park	7	Parking	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls including violation sign.	\$210.00	2	each	\$420.00	1
Pinewoods Park	8	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Pinewoods Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	20	each	\$1,925.00	1
Pinewoods Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Pinewoods Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Pinewoods Park	12	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	10	each	\$962.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Pinewoods Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1040	sq ft	\$127,400.00	1
Pinewoods Park	14	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	4	each	\$385.00	1
Pinewoods Park	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Pinewoods Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Pinewoods Park	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Pinewoods Park	18	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Pinewoods Park	19	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Pinewoods Park	20	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Pinewoods Park	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	1
Pinewoods Park	22	Exterior Accessible Route	Accessible Routes	Provide cane detectable bollard at base of object along the AR.	\$350.00	1	each	\$350.00	1
Pinewoods Park	23	Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,942.50	1	each	\$1,942.50	1
Pinewoods Park	24	Concessions	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	25	Concessions	Turning Space	Relocate obstacles to create turning space in storage room.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	26	Concessions	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	27	Concessions	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of floor surface.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	28	Concessions	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	29	Concessions	Accessible Routes	Provide vertical access to all levels of the building.	\$43,631.00	1	each	\$43,631.00	3
Pinewoods Park	30	Concessions	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	31	Concessions	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Pinewoods Park	32	Concessions	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Pinewoods Park	33	Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Pinewoods Park	34	Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Pinewoods Park	35	Concessions	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	36	Concessions	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	37	Concessions	Accessible Routes	Resurface or repair floors to be firm, stable and slip resistant.	\$122.50	12	sq ft	\$1,470.00	3
Pinewoods Park	38	Concessions	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	39	Concessions	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	1
Pinewoods Park	40	Concessions	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	41	Concessions	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$747.25	1	each	\$747.25	1
Pinewoods Park	43	Concessions	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	2	each	\$700.00	5
Pinewoods Park	44	Concessions	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	5
Pinewoods Park	45	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".	\$192.50	1	each	\$192.50	3
Pinewoods Park	46	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Pinewoods Park	47	Park Elements	Drinking Fountains	Adjust spout location to be within 5" of the front of the unit	\$2,380.00	1	each	\$2,380.00	2
Pinewoods Park	48	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Pinewoods Park	49	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Pinewoods Park	51	Picnic Area	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
Pinewoods Park	52	Picnic Area	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	5
Pinewoods Park	53	Picnic Area	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Pinewoods Park	54	Ballfield 1	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$4,529.00	1	each	\$4,529.00	2
Pinewoods Park	55	Ballfield 1	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	180	lin ft	\$10,656.00	2
Pinewoods Park	60	Ballfield 2	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	180	lin ft	\$10,656.00	2
Pinewoods Park	63	Ballfield 2	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Pinewoods Park	64	Ballfield 2	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.	\$9,045.00	1	each	\$9,045.00	2
Pinewoods Park	68	Ballfield 3	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	180	lin ft	\$10,656.00	2
Pinewoods Park	69	Ballfield 3	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$9,559.50	1	each	\$9,559.50	2
Pinewoods Park	70	Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	250	lin ft	\$14,800.00	2
Pinewoods Park	71	Elements	Reach Ranges	Remount operable parts of at least 1 more garbage can to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Pinewoods Park	72	Mens Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	73	Mens Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Pinewoods Park	74	Mens Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Pinewoods Park	75	Mens Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Pinewoods Park	76	Mens Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	77	Mens Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Pinewoods Park	78	Mens Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Pinewoods Park	79	Mens Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Pinewoods Park	80	Mens Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Pinewoods Park	81	Mens Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Pinewoods Park	82	Mens Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	83	Mens Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	0	staff time	\$0.00	1
Pinewoods Park	84	Mens Restroom	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
Pinewoods Park	85	Mens Restroom	Doors	Replace closer with one mounted min of 78" AFF.	\$2,772.50	1	each	\$2,772.50	1
Pinewoods Park	86	Mens Restroom	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Pinewoods Park	87	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	88	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	89	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Pinewoods Park	90	Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Pinewoods Park	91	Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	\$2,749.25	1	each	\$2,749.25	1
Pinewoods Park	92	Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Pinewoods Park	93	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Pinewoods Park	94	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Pinewoods Park	95	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Pinewoods Park	96	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Pinewoods Park	97	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Pinewoods Park	98	Women's Restroom	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Pinewoods Park	99	5-12 Play Area	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$3,673.25	1	each	\$3,673.25	2
Pinewoods Park	100	5-12 Play Area	Accessible Routes	Relocate garbage can along AR.	\$0.00	1	staff time	\$0.00	2
Pinewoods Park	101	5-12 Play Area	Play Area	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$7,000.00	1	each	\$7,000.00	2
Pinewoods Park	102	5-12 Play Area	Play Area	Establish protocols for regular and frequent inspection and maintenance of playground surface.  Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Pinewoods Park	103	5-12 Play Area	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Pinewoods Park	104	5-12 Play Area	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Pinewoods Park	105	5-12 Play Area	Play Area	Lower the seat, or raise the surface fill level to achieve entry height of 11" to 24" AGL to swing.	\$0.00	1	staff time	\$0.00	2
Pinewoods Park	106	5-12 Play Area	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
R.G. Kreusler Park	2	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
R.G. Kreusler Park	3	Parking	Parking - Off Street	Add one van parking sign to two accessible stalls and ensure stalls and access aisles are 12' and 5'.	\$210.00	2	each	\$420.00	1
R.G. Kreusler Park	4	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	6	staff time	\$0.00	1
R.G. Kreusler Park	5	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
R.G. Kreusler Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	7	Exterior Accessible Route	Accessible Routes	Repair, or reset pavers to eliminate change in level along accessible route.	\$28.00	1	each	\$28.00	1
R.G. Kreusler Park	8	Exterior Accessible Route	Accessible Routes	Repair or reset pavers to eliminate gaps and CIL.	\$28.00	1	each	\$28.00	1
R.G. Kreusler Park	9	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	10	Exterior Accessible Route	Accessible Routes	Repair or reset pavers to eliminat gaps and changes in level.	\$28.00	1	each	\$28.00	1
R.G. Kreusler Park	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	12	Exterior Accessible Route	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	13	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	14	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	180	sq ft	\$22,050.00	1
R.G. Kreusler Park	15	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	16	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
R.G. Kreusler Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
R.G. Kreusler Park	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
R.G. Kreusler Park	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
R.G. Kreusler Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
R.G. Kreusler Park	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
R.G. Kreusler Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
R.G. Kreusler Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
R.G. Kreusler Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
R.G. Kreusler Park	26	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	27	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
R.G. Kreusler Park	28	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
R.G. Kreusler Park	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
R.G. Kreusler Park	30	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	10	lin ft	\$592.00	1
R.G. Kreusler Park	31	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
R.G. Kreusler Park	32	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
R.G. Kreusler Park	33	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
R.G. Kreusler Park	34	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
R.G. Kreusler Park	35	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
R.G. Kreusler Park	36	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	1	each	\$6,510.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
R.G. Kreusler Park	38	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
R.G. Kreusler Park	39	Park Elements	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
R.G. Kreusler Park	40	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along AR, with level CGS, and rims of garbage cans within reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
R.G. Kreusler Park	42	Park Elements	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	2	each	\$700.00	5
R.G. Kreusler Park	43	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
R.G. Kreusler Park	44	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$3,062.50	5	each	\$15,312.50	2
R.G. Kreusler Park	45	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.  Remount signage to min 40" AFF as a smart practice.	\$59.20	3	each	\$177.60	5
R.G. Kreusler Park	46	Park Elements	Plumbing Fixtures & Elements	Replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
R.G. Kreusler Park	47	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	each	\$3,062.50	2
R.G. Kreusler Park	48	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
R.G. Kreusler Park	49	Park Elements	ATM's and Fare Machines	Contact provider to replace ATM with a compliant model	\$5,000.00	5	each	\$25,000.00	3
R.G. Kreusler Park	50	Beach	Park Site (C)	Relocate 20% of garbage cans to be along AR. In the alternative, leave as is and designate other beaches in the county as accessible.	\$0.00	1	staff time	\$0.00	4
R.G. Kreusler Park	51	Beach	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other beaches in the county as accessible.	\$59.20	150	lin ft	\$8,880.00	4
R.G. Kreusler Park	52	Beach	Beach Access Route (C)	Create a beach access route to normal recreational water level of a firm and stable material as a smart practice. In the alternative, leave as is and designate other beaches in the county as accessible.	\$59.20	175	lin ft	\$10,360.00	4
R.G. Kreusler Park	53	Beach	Stairways	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible. In the alternative, leave as is and designate other beaches in the county as accessible.	\$404.25	18	each	\$7,276.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
R.G. Kreusler Park	54	Beach	Stairways	<p>Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.</p> <p>Establish protocols for regular and frequent inspection and maintenance of stair surfaces.</p> <p>In the alternative, leave as is and designate other beaches in the county as accessible.</p>	\$404.25	1	each	\$404.25	4
R.G. Kreusler Park	55	Beach	Stairways	<p>Install contrasting strip along front 2" of each tread.</p> <p>The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.</p> <p>In the alternative, leave as is and designate other beaches in the county as accessible.</p>	\$125.00	18	each	\$2,250.00	4
R.G. Kreusler Park	56	Beach	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall.</p> <p>In the alternative, leave as is and designate other beaches in the county as accessible.</p>	\$980.00	6	each	\$5,880.00	4
R.G. Kreusler Park	57	Beach	Stairways	<p>Replace or remount handrails to 34" to 38" AFF. In the alternative, leave as is and designate other beaches in the county as accessible.</p>	\$350.00	6	each	\$2,100.00	4
R.G. Kreusler Park	58	Beach	Stairways	<p>Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Priced in previous finding. In the alternative, leave as is and designate other beaches in the county as accessible.</p>	\$0.00	6	each	\$0.00	4
R.G. Kreusler Park	59	Employee Spaces	Reach Ranges	<p>Remount operable parts to be in reach range of 15" min to 48" max.</p>	\$350.00	1	each	\$350.00	3
R.G. Kreusler Park	60	Employee Spaces	Clear Floor Space	<p>Remove, or relocate storage in CFS at fixtures and operable parts along the AR.</p>	\$0.00	1	staff time	\$0.00	3
R.G. Kreusler Park	61	Employee Spaces	Reach Ranges	<p>Remount operable parts to be in reach range of 15" min to 48" max.</p>	\$350.00	1	each	\$350.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
R.G. Kreusler Park	62	Employee Spaces	Dining, Bar and Work Surfaces	Provide an accessible table having required knee and toe clearance of 30" wide min.	\$1,120.00	1	each	\$1,120.00	3
R.G. Kreusler Park	63	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	64	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
R.G. Kreusler Park	65	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$5,327.00	1	each	\$5,327.00	3
R.G. Kreusler Park	67	Employee Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	68	Employee Spaces	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	69	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	70	Employee Spaces	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	71	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	72	Employee Spaces	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
R.G. Kreusler Park	73	Women's Restroom	Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level landing.	\$3,062.50	1	each	\$3,062.50	1
R.G. Kreusler Park	74	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top. In the alternative, leave as is citing construction tolerance.	\$0.00	1	staff time	\$0.00	4
R.G. Kreusler Park	75	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
R.G. Kreusler Park	76	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
R.G. Kreusler Park	77	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
R.G. Kreusler Park	78	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
R.G. Kreusler Park	79	Men's Restroom	Plumbing Fixtures & Elements	Lower one sink in main area to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
R.G. Kreusler Park	80	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
R.G. Kreusler Park	81	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
R.G. Kreusler Park	82	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
R.G. Kreusler Park	83	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
R.G. Kreusler Park	84	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
R.G. Kreusler Park	85	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
R.G. Kreusler Park	86	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Reverend Leon Camel, Jr. Park	1	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Reverend Leon Camel, Jr. Park	2	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Reverend Leon Camel, Jr. Park	3	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Reverend Leon Camel, Jr. Park	4	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Reverend Leon Camel, Jr. Park	5	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Reverend Leon Camel, Jr. Park	6	Exterior Accessible Route	Accessible Routes	Trim tree branches to min 80". Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Reverend Leon Camel, Jr. Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Reverend Leon Camel, Jr. Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Reverend Leon Camel, Jr. Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Reverend Leon Camel, Jr. Park	10	Play Area - 2-5	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  Replace surface with a compliant surface such as EWF or tiles.	\$7,000.00	1	each	\$7,000.00	2
Reverend Leon Camel, Jr. Park	12	Play Area - 2-5	Play Area	Make correction to surface to provide one of each type of GLPC compliant. Price included in 5 to 12 play area finding.	\$0.00	1	each	\$0.00	2
Reverend Leon Camel, Jr. Park	14	Play Area - 5 to 12	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
Reverend Leon Camel, Jr. Park	15	Play Area - 5 to 12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Reverend Leon Camel, Jr. Park	16	Play Area - 5 to 12	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Reverend Leon Camel, Jr. Park	17	Play Area - 5 to 12	Play Area	Install transfer supports on transfer platform/transfer steps.	\$560.00	1	each	\$560.00	2
Reverend Leon Camel, Jr. Park	18	Play Area - 5 to 12	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Reverend Leon Camel, Jr. Park	19	Play Area - 5 to 12	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Reverend Leon Camel, Jr. Park	20	Play Area - 5 to 12	Play Area	See previous finding for surface recommendation.	\$0.00	1	each	\$0.00	2
Reverend Leon Camel, Jr. Park	22	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Reverend Leon Camel, Jr. Park	24	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Reverend Leon Camel, Jr. Park	25	Park Elements	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,890.00	1	each	\$1,890.00	1
Reverend Leon Camel, Jr. Park	26	Gazebo	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Riverbend Park	1	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Riverbend Park	2	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Repaint access aisles to be 5' each	\$73.50	1	each	\$73.50	1
Riverbend Park	3	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	4	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Riverbend Park	5	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	1	each	\$367.50	1
Riverbend Park	6	Parking - Hal R. Valeché Portico & Kayak Bike Rental	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Riverbend Park	7	Parking - Canoe and Kayak Launch within Picnic Loop	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Riverbend Park	9	Parking - Entry Flag Pole Pull Off	Parking - Off Street	Repaint stalls to be 12' (144") wide each as a smart practice for parallel stalls.	\$73.50	1	each	\$73.50	5
Riverbend Park	10	Parking - Entry Flag Pole Pull Off	Parking - On Street	Leave as is lack of adjacent access aisle, parallel stall is next to curb ramp.	\$0.00	1	N/A	\$0.00	4
Riverbend Park	11	Parking - Entry Flag Pole Pull Off	Parking - Off Street	Add van parking sign to 1 accessible stall and ensure stall and access aisle to 12' and 5'.	\$210.00	1	each	\$210.00	1
Riverbend Park	12	Parking - Restroom Building on Picnic Island	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Riverbend Park	14	Parking - Pull Off Parking Throughout Park	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Riverbend Park	15	Parking - Pull Off Parking Throughout Park	Parking - Off Street	Create two or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Riverbend Park	16	Building/ Office Space	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	17	Building/ Office Space	Turning Space	Relocate obstacles to create turning space in office.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	18	Building/ Office Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	19	Building/ Office Space	Doors	Provide required maneuvering clearance on push side of door.  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	20	Building/ Office Space	Accessible Routes	Relocate obstacles such as storage to create an accessible route (AR) and turning space through room.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	21	Building/ Office Space	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	22	Building/ Office Space	Doors	Provide required maneuvering clearance around pull side of door.	\$1,750.00	1	each	\$1,750.00	3
Riverbend Park	24	Building/ Office Space	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	3
Riverbend Park	25	Building/ Office Space	Toilet and Bathing Rooms	Relocate garbage bin and paper towel dispenser to provide required 60" clearance around toilet.	\$0.00	2	staff time	\$0.00	3
Riverbend Park	26	Building/ Office Space	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	27	Building/ Office Space	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	3
Riverbend Park	29	Building/ Office Space	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	3
Riverbend Park	30	Building/ Office Space	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	31	Building/ Office Space	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Riverbend Park	32	Building/ Office Space	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" above the finished floor (AFF).	\$1,099.00	1	each	\$1,099.00	1
Riverbend Park	33	Building/ Office Space	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is citing construction tolerance.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	34	Building/ Office Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Secure rug at door to prevent trip hazard.	\$70.00	2	each	\$140.00	3
Riverbend Park	35	Building/ Office Space	Turning Space	Relocate obstacles to create turning space in room.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	36	Building/ Office Space	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	37	Building/ Office Space	Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.  For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	38	Building/ Office Space	Accessible Routes	Relocate obstacles such as furniture to create an accessible route (AR) through indicated rooms.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	39	Building/ Office Space	Accessible Routes	Secure mats to prevent trip hazard.	\$140.00	2	each	\$280.00	3
Riverbend Park	40	Building/ Office Space	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Remount items requiring a reach over an obstacle to max 46".	\$70.00	5	each	\$350.00	3
Riverbend Park	41	Building/ Office Space	Dining, Bar and Work Surfaces	Remove storage and other items to provide knee clearance at table.	\$0.00	1	staff time	\$0.00	3
Riverbend Park	42	Building/ Office Space	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the common use path, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the common use path, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$258.13	2	each	\$516.26	3
Riverbend Park	43	Family Restroom	Toilet and Bathing Rooms	Raise mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	44	Family Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	45	Family Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Riverbend Park	46	Men's Restroom	Toilet and Bathing Rooms	Replace one mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top in main area.  Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top in stall.	\$350.00	1	each	\$350.00	1
Riverbend Park	47	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	48	Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Riverbend Park	49	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	50	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Riverbend Park	51	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$1,846.25	1	each	\$1,846.25	1
Riverbend Park	52	Womens Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	53	Womens Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Riverbend Park	54	Womens Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Riverbend Park	55	Womens Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Riverbend Park	56	Womens Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$1,960.00	1	each	\$1,960.00	1
Riverbend Park	58	Park Elements	Accessible Routes	Create a route to at least one picnic table and replace with one of an accessible desgn.	\$2,600.00	1	each	\$2,600.00	5
Riverbend Park	59	Kayak And Boat Rental (3rd Party Vendor On Site)	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to and throughout the shop.	\$87,024.00	1	each	\$87,024.00	3
Riverbend Park	60	Kayak And Boat Rental (3rd Party Vendor On Site)	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" aff.	\$1,099.00	1	each	\$1,099.00	2
Riverbend Park	61	Kayak And Boat Rental (3rd Party Vendor On Site)	Accessible Routes	Create a route to at least one picnic table and replace with one of a complinat model.	\$2,600.00	1	sq ft	\$2,600.00	5
Riverbend Park	62	Kayak And Boat Rental (3rd Party Vendor On Site)	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	15	lin ft	\$888.00	2
Riverbend Park	63	Kayak And Boat Rental (3rd Party Vendor On Site)	Plumbing Fixtures & Elements	Replace one outdoor shower with compliant shower as a smart practice.	\$2,749.25	1	each	\$2,749.25	5
Riverbend Park	64	Kayak And Boat Rental (3rd Party Vendor On Site)	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	20	lin ft	\$1,184.00	2
Riverbend Park	65	Kayak And Boat Rental (3rd Party Vendor On Site)	Dressing / Fitting / Locker Rooms	Enlarge dressing stalls to 60" by 60" clear inside dimension	\$1,036.00	1	each	\$1,036.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	66	Kayak And Boat Rental (3rd Party Vendor On Site)	Dressing / Fitting / Locker Rooms	Remove door or reverse swing to provide required clear floor space in dressing room.	\$420.00	1	each	\$420.00	2
Riverbend Park	67	Kayak And Boat Rental (3rd Party Vendor On Site)	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Riverbend Park	68	Kayak And Boat Rental (3rd Party Vendor On Site)	Boating Facilities	Provide 5%, but not less than one accessible boarding pier at boat launches.	\$6,510.00	1	each	\$6,510.00	2
Riverbend Park	69	Picnic Island Restroom Building - Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Riverbend Park	70	Picnic Island Restroom Building - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Riverbend Park	71	Picnic Island Restroom Building - Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Riverbend Park	72	Picnic Island Restroom Building - Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Riverbend Park	73	Picnic Island - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Riverbend Park	74	Picnic Island - Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	75	Picnic Island - Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Riverbend Park	76	Picnic Island - Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet. Leave as is if built or altered prior to March 15, 2012.	\$2,380.00	1	each	\$2,380.00	1
Riverbend Park	77	Picnic Island - Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Riverbend Park	78	Picnic Island - Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Install stall hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Riverbend Park	79	Picnic Island - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide beveled threshold.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$96.25	1	each	\$96.25	1
Riverbend Park	80	Picnic Island - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Riverbend Park	81	Picnic Island - Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	82	Picnic Island - Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Riverbend Park	83	Picnic Island - Women's Restroom	Toilet and Bathing Rooms	Widen AR to stall to min 42" clear width, having 18" clearance adjacent to the latch on the pull side.	\$2,749.25	1	each	\$2,749.25	1
Riverbend Park	84	Picnic Island - Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Riverbend Park	85	Picnic Island - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$1,950.00	1	each	\$1,950.00	1
Riverbend Park	86	Picnic Island Family Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Riverbend Park	87	Picnic Island Family Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Riverbend Park	88	Portable Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
Riverbend Park	89	Portable Toilets	Accessible Routes	Extend AR to the portable toilet or relocate portable toilet to be along the accessible route.	\$67.20	5	lin ft	\$336.00	1
Riverbend Park	90	Portable Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR	\$1,092.00	1	each	\$1,092.00	1
Riverbend Park	91	Portable Toilets	Accessible Routes	Extend AR to the portable toilet or relocate portable toilet to be along the accessible route.	\$67.20	35	lin ft	\$2,352.00	1
Riverbend Park	92	Portable Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR	\$1,092.00	1	each	\$1,092.00	1
Riverbend Park	93	Portable Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along accessible route (AR).	\$1,092.00	1	each	\$1,092.00	1
Riverbend Park	94	Park Elements	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.	\$59.20	120	lin ft	\$7,104.00	5
Riverbend Park	95	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	54	lin ft	\$3,196.80	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	96	Boating	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County boating facilities accessible.	\$59.20	38	lin ft	\$2,249.60	4
Riverbend Park	97	Boating	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County boating facilities accessible.	\$59.20	56	lin ft	\$3,315.20	4
Riverbend Park	98	Maintenance	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	3
Riverbend Park	99	Maintenance	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	212	lin ft	\$12,550.40	3
Riverbend Park	100	Along Riverbend Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	875	sq ft	\$51,800.00	4
Riverbend Park	101	Along Riverbend Trail	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80"  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4
Riverbend Park	102	Along Riverbend Trail	Turning Space	Relocate obstacles or reconfigure tables to create turning space in large chickee pavilion. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	103	Along Riverbend Trail	Picnic Tables (C)	Replace both picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	104	Along Riverbend Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	875	sq ft	\$51,800.00	4
Riverbend Park	105	Along Riverbend Trail	Picnic Tables (C)	Replace both picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	106	Along Reece Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	242	lin ft	\$14,326.40	4
Riverbend Park	107	Along Reece Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	600	sq ft	\$35,520.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	108	Along Reece Trail	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4
Riverbend Park	109	Along Reece Trail	Picnic Tables (C)	Replace both picnic tables with tables of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	110	Along Reece Trail	Shelters/Picnic Areas (C)	Reconfigure table placement within shelter to provide required clear ground space at kiosks. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	111	Along Picnic Island Loop Trail	Outdoor Recreation Access Route	Correct surface of ORAR to be firm and stable, a min 36" wide and having gaps and changes in level of max .5". In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	80	lin ft	\$4,736.00	4
Riverbend Park	112	Along Picnic Island Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	875	sq ft	\$51,800.00	4
Riverbend Park	113	Along Picnic Island Loop Trail	Picnic Tables (C)	Include two or more additional picnic tables of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	114	Along Picnic Island Loop Trail	Shelters, Picnic Facilities (C)	Create an ORAR from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	7	lin ft	\$414.40	4
Riverbend Park	115	Along Picnic Island Loop Trail	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to at least two shelters or picnic area as a smart practice. See trail findings for cost reference. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	120	lin ft	\$7,104.00	4
Riverbend Park	116	Along Picnic Island Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface of at least two shelters to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	312	sq ft	\$18,470.40	4
Riverbend Park	117	Along Picnic Island Loop Trail	Accessible Routes	Raise roof materials of at least two shelters to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	2	each	\$3,000.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	118	Along Picnic Island Loop Trail	Turning Space	Relocate obstacles to create turning space in at least two of the small chickee picnic pavilions (8). In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	2	staff time	\$0.00	4
Riverbend Park	119	Along Picnic Island Loop Trail	Picnic Tables (C)	Replace picnic table in at least two shelters with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	120	Within Equestrian Open Run Area	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	122	lin ft	\$7,222.40	4
Riverbend Park	121	Within Equestrian Open Run Area	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	875	sq ft	\$51,800.00	4
Riverbend Park	122	Within Equestrian Open Run Area	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Riverbend Park	123	Within Equestrian Open Run Area	Shelters, Picnic Facilities (C)	Create an AR and required clear ground space at one of each type of feature in accessible shelters and picnic areas and provide accessible tables. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	17	lin ft	\$1,006.40	4
Riverbend Park	124	Within Equestrian Open Run Area	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	16	lin ft	\$947.20	4
Riverbend Park	125	Along Big Hammock Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	60	lin ft	\$3,552.00	4
Riverbend Park	126	Along Big Hammock Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	1000	sq ft	\$59,200.00	4
Riverbend Park	127	Along Big Hammock Loop Trail	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4
Riverbend Park	128	Along Big Hammock Loop Trail	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	129	Along Big Hammock Loop Trail	Shelters, Picnic Facilities (C)	Create an outdoor recreation access route (ORAR) from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4
Riverbend Park	130	Along Big Hammock Loop Trail	Outdoor - Constructed Features (C)	Provide required level 36" clear ground space around all usable portions of the table as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$2,486.00	1	each	\$2,486.00	4
Riverbend Park	131	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	20	lin ft	\$1,184.00	4
Riverbend Park	132	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$28.00	1000	sq ft	\$28,000.00	4
Riverbend Park	133	Along Cow Pen Picnic Loop	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	staff time	\$1,500.00	4
Riverbend Park	134	Along Cow Pen Picnic Loop	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable warning or bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	135	Along Cow Pen Picnic Loop	Picnic Tables (C)	Replace 20% but no less than 2 picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	136	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create an outdoor recreation access route (ORAR) from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
Riverbend Park	137	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	10	lin ft	\$592.00	4
Riverbend Park	138	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	156	sq ft	\$9,235.20	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	139	Along Cow Pen Picnic Loop	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4
Riverbend Park	140	Along Cow Pen Picnic Loop	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Riverbend Park	141	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	25	lin ft	\$1,480.00	4
Riverbend Park	142	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	156	sq ft	\$9,235.20	4
Riverbend Park	143	Along Cow Pen Picnic Loop	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	staff time	\$1,500.00	4
Riverbend Park	144	Along Cow Pen Picnic Loop	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Riverbend Park	145	Along Cow Pen Picnic Loop	Doors	Trim straw roof to provide 80" overhead clearance for 32". In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	146	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	156	sq ft	\$9,235.20	4
Riverbend Park	147	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
Riverbend Park	148	Along Cow Pen Picnic Loop	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	149	Along Cow Pen Picnic Loop	Shelters, Picnic Facilities (C)	Create an outdoor recreation access route (ORAR) from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	8	lin ft	\$473.60	4
Riverbend Park	150	Along Hunter's Loop Trail	Shelters, Picnic Facilities (C)	Establish protocols for regular and frequent inspection and maintenance of accessible ORAR surface as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	151	Along Hunter's Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$28.00	1000	sq ft	\$28,000.00	4
Riverbend Park	152	Along Hunter's Loop Trail	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4
Riverbend Park	153	Along Hunter's Loop Trail	Picnic Tables (C)	Replace both picnic tables with ones of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	2	each	\$2,240.00	4
Riverbend Park	154	Along Hunter's Loop Trail	Shelters, Picnic Facilities (C)	Create an outdoor recreation access route (ORAR) from shelter or picnic area to accessible features as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	40	lin ft	\$2,368.00	4
Riverbend Park	155	Along Hunter's Loop Trail	Shelters, Picnic Facilities (C)	Establish protocols for regular and frequent inspection and maintenance of accessible ORAR surface as a smart practice.  Frequently maintain ORAR surface in identified washout areas to assure CILs remain 2" or less and gaps are filled as a smart practice.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	156	Along Hunter's Loop Trail	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable. In the alternative, leave as is and designate other County picnic facilities accessible.	\$28.00	500	sq ft	\$14,000.00	4
Riverbend Park	157	Along Hunter's Loop Trail	Accessible Routes	Raise roof materials to min 80", or pad object to prevent hazard in overhead clearance  Maintain overhead clearance of min. 80".  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,500.00	1	each	\$1,500.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	158	Along Hunter's Loop Trail	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Riverbend Park	159	Along Farmstead Loop / Sawmill Trail	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice; in the alternative, leave as is and designate other County shelters accessible.	\$59.20	20	lin ft	\$1,184.00	4
Riverbend Park	160	Along Farmstead Loop / Sawmill Trail	Shelters, Picnic Facilities (C)	<p>Replace or correct surface to be firm and stable.</p> <p>Replace two picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around table.</p> <p>Raise or trim straw roof to provide 80" overhead clearance for min 32" wide entry.</p> <p>Repair, bevel or ramp CIL on shelter interior.</p> <p>In the alternative, leave as is and designate other shelters as accessible.</p>	\$31,936.25	1	each	\$31,936.25	4
Riverbend Park	161	Along Farmstead Loop / Sawmill Trail	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other shelters as accessible.	\$59.20	240	lin ft	\$14,208.00	4
Riverbend Park	162	Along Ocean Lake/Florida Trail	Accessible Routes	<p>Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.</p> <p>If fixtures provided are intended to be used as tables, provide accessible tables with knee and toe clearance in each shelter.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$45,220.00	1	each	\$45,220.00	4
Riverbend Park	163	Along Military Trail	Shelters, Picnic Facilities (C)	<p>Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice.</p> <p>Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around the table at shelter.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$1,712.00	1	each	\$1,712.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	164	Big Hammock Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  Frequently maintain trail surface in identified washout areas to assure CILs remain 2" or less and gaps are filled as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	168	Reese Blvd - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	18	each	\$1,732.50	4
Riverbend Park	169	Reese Blvd - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	170	Reese Blvd - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	171	Reese Blvd - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	172	Reese Blvd - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	173	Reese Blvd - Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice.  Trim straw roof to provide 80" overhead clearance.  In the alternative, leave as is and designate other County trails accessible.	\$161.00	1	each	\$161.00	4
Riverbend Park	174	Reese Blvd - Trail Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County trails accessible.	\$59.20	75	lin ft	\$4,440.00	4
Riverbend Park	175	Riverwalk - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	176	Riverwalk - Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	200	sq ft	\$24,500.00	4
Riverbend Park	177	Riverwalk - Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	480	sq ft	\$58,800.00	4
Riverbend Park	178	Riverwalk - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	179	Riverwalk - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	180	Riverwalk - Trail Elements	Outdoor - Constructed Features (C)	Correct surface at kiosk to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	181	Riverwalk - Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$161.00	1	each	\$161.00	4
Riverbend Park	182	Riverwalk - Trail Elements	Room/Space (C)	For employee spaces, provide approach, enter and exit at the employee space.  Ramp entry for access.  Remount handrails to max 34" to 38" AFF.  In the alternative, leave as is and designate other County trails accessible.	\$2,352.25	1	each	\$2,352.25	4
Riverbend Park	183	Riverbend - Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	25	sq ft	\$3,062.50	4
Riverbend Park	184	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	185	Riverbend - Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	25	sq ft	\$3,062.50	4
Riverbend Park	186	Riverbend - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	25	lin ft	\$1,480.00	4
Riverbend Park	187	Riverbend - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	100	lin ft	\$5,920.00	4
Riverbend Park	188	Riverbend - Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Riverbend Park	189	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	190	Riverbend - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	50	lin ft	\$2,960.00	4
Riverbend Park	191	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	192	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	193	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	194	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	195	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	196	Riverbend - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	197	Riverbend - Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Riverbend Park	198	Riverbend - Trail Surface	Outdoor - Trails (C)	Create landing or connect accessible surface to other side of crosswalk. In the alternative, leave as is and designate other County trails accessible.	\$161.00	1	each	\$161.00	4
Riverbend Park	199	Riverbend - Trail Elements	Accessible Routes	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" accessible route (AR) around table. In the alternative, leave as is and designate other County trails accessible.	\$1,120.00	1	each	\$1,120.00	4
Riverbend Park	200	Riverbend - Trail Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. In the alternative, leave as is and designate other County trails accessible.	\$59.20	5	lin ft	\$296.00	4
Riverbend Park	201	Riverbend - Trail Elements	Viewing Areas (C)	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51". In the alternative, leave as is and designate other County trails accessible.	\$785.00	4	each	\$3,140.00	4
Riverbend Park	202	Riverbend - Trail Elements	Accessible Routes	Relocate 20% of trash bag dispensers to be along accessible route (AR). In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	203	Military Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	204	Cow Pen Picnic Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	205	Long Battlefield/Riverbend Divide - Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
Riverbend Park	206	Long Battlefield/Riverbend Divide - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	207	Trail Across From Battlefield Trail Entry - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	25	lin ft	\$1,480.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	208	Trail Across From Battlefield Trail Entry - Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max 2" for surfaces other than concrete, asphalt or boards. In the alternative, leave as is and designate other County trails accessible.	\$96.25	1	each	\$96.25	4
Riverbend Park	209	Picnic Island Loop - Trail Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$122.50	480	sq ft	\$58,800.00	4
Riverbend Park	210	Picnic Island Loop - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	250	lin ft	\$14,800.00	4
Riverbend Park	211	Picnic Island Loop - Trail Surface	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable and extend to bench as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	25	lin ft	\$1,480.00	4
Riverbend Park	212	Picnic Island Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	213	Picnic Island Loop - Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	25	lin ft	\$1,480.00	4
Riverbend Park	214	East Slough Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	215	East Slough Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	216	Ocean Lake/Florida Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	217	Hunter's Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	218	Grove Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Riverbend Park	220	Grove Trail - Trail Elements	Accessible Routes	Trim straw roof to provide 80" overhead clearance for 32". In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	221	Dark Hammock Loop - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	222	Big Grove Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	223	Farmstead Loop / Sawmill Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	224	Indian Hammock / Pond Trail - Trail Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
Riverbend Park	225	Indian Hammock / Pond Trail - Trail Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an accessible route (AR) as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$161.00	1	each	\$161.00	4
San Castle Community Park	2	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
San Castle Community Park	3	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
San Castle Community Park	4	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
San Castle Community Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
San Castle Community Park	6	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
San Castle Community Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	50	sq ft	\$6,125.00	1
San Castle Community Park	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
San Castle Community Park	9	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$77.85	2	each	\$155.70	1
San Castle Community Park	12	Park Elements	Plumbing Fixtures & Elements	Replace drinking fountain with hi-lo bowl.	\$5,598.25	1	each	\$5,598.25	2
San Castle Community Park	16	Play Area 2-5	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
San Castle Community Park	17	Play Area 2-5	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
San Castle Community Park	21	Play Area 5-12	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
<u>San Castle Neighborhood Park</u>	1	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$4,952.50	1	each	\$4,952.50	1
San Castle Neighborhood Park	2	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$4,952.50	1	each	\$4,952.50	1
San Castle Neighborhood Park	3	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
San Castle Neighborhood Park	4	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	8	each	\$770.00	1
San Castle Neighborhood Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
San Castle Neighborhood Park	6	2 to 5 Playground	Play Area	Replace tire swing area existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
San Castle Neighborhood Park	7	2 to 5 Playground	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
San Castle Neighborhood Park	10	2 to 5 Playground	Play Area	Lower or adjust entry point of swings to 11" to 24" AGL.  Raise maze panel so the majority of the tactile portions of play panel are min 20" and max 36" AGL.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
San Castle Neighborhood Park	11	2 to 5 Playground	Play Area	Make corrections to surface and GLPCs noted in previous findings to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
San Castle Neighborhood Park	12	5 to 12 Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
San Castle Neighborhood Park	13	5 to 12 Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
San Castle Neighborhood Park	14	5 to 12 Playground	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
San Castle Neighborhood Park	18	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
San Castle Neighborhood Park	19	Park Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	8	lin ft	\$473.60	2
San Castle Neighborhood Park	20	Park Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$1,120.00	1	each	\$1,120.00	4
San Castle Neighborhood Park	21	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
San Castle Neighborhood Park	22	Park Elements	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
San Castle Neighborhood Park	23	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
<u>Sandalfoot Cove Park</u>	2	South Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	3	each	\$220.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	3	South Parking	Parking - Off Street	Add one van parking sign to one accessible stall,	\$210.00	1	each	\$210.00	1
Sandalfoot Cove Park	5	North Parking Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Sandalfoot Cove Park	6	North Parking Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Sandalfoot Cove Park	7	North Parking Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Sandalfoot Cove Park	8	North Parking Lot	Parking - Off Street	Provide a 44" clear width route and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
Sandalfoot Cove Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Sandalfoot Cove Park	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5". Replace manhole cover with one having max gaps of .5".	\$190.70	9	each	\$1,716.30	1
Sandalfoot Cove Park	11	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Sandalfoot Cove Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Sandalfoot Cove Park	13	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	14	Exterior Accessible Route	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	15	Exterior Accessible Route	Accessible Routes	Maintain overhead clearance of min. 80"	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Sandalfoot Cove Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Sandalfoot Cove Park	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	20	Exterior Accessible Route	Accessible Routes	Maintain pathway to be free of mud and dirt build up.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	22	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	23	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%	\$1,015.00	1	each	\$1,015.00	1
Sandalfoot Cove Park	24	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Sandalfoot Cove Park	25	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%	\$1,015.00	2	each	\$2,030.00	1
Sandalfoot Cove Park	26	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%	\$1,015.00	1	each	\$1,015.00	1
Sandalfoot Cove Park	27	Exterior Accessible Route	Accessible Routes	Maintain accessible route to be free of mud and dirt build up.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	28	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Sandalfoot Cove Park	29	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	30	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Sandalfoot Cove Park	31	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	32	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sandalfoot Cove Park	33	Exterior Accessible Route	Accessible Routes	Maintain accessible route to be free of dirt and mud build up.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	34	Exterior Accessible Route	Accessible Routes	Maintain accessible route to be free of dirt and mud build up.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	35	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Sandalfoot Cove Park	36	Men's Restroom - South	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1
Sandalfoot Cove Park	37	Men's Restroom - South	Plumbing Fixtures & Elements	Lower sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Sandalfoot Cove Park	38	Men's Restroom - South	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Sandalfoot Cove Park	39	Men's Restroom - South	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Sandalfoot Cove Park	40	Men's Restroom - South	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	41	Men's Restroom - South	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	42	Men's Restroom - South	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Sandalfoot Cove Park	43	Men's Restroom - South	Toilet and Bathing Rooms	Remove grab bar to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	44	Men's Restroom - South	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Sandalfoot Cove Park	45	Men's Restroom - South	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	46	Men's Restroom - South	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	47	Men's Restroom - South	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Sandalfoot Cove Park	48	Men's Restroom - South	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Sandalfoot Cove Park	49	Men's Restroom - South	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	50	Men's Restroom - South	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	51	Men's Restroom - South	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	52	Men's Restroom - North	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	53	Men's Restroom - North	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Sandalfoot Cove Park	54	Men's Restroom - North	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Sandalfoot Cove Park	55	Men's Restroom - North	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Sandalfoot Cove Park	56	Men's Restroom - North	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls or 16" to 18" in new wheelchair stall.	\$1,828.40	1	each	\$1,828.40	1
Sandalfoot Cove Park	57	Men's Restroom - North	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$840.00	1	N/A	\$840.00	1
Sandalfoot Cove Park	58	Men's Restroom - North	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. In the alternative, remove and add rear grab bar in new wheelchair stall.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	59	Men's Restroom - North	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	60	Men's Restroom - North	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	61	Men's Restroom - North	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted 34" to 48" AFF.	\$5,327.00	1	each	\$5,327.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	62	Women's Restroom - South	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,158.75	1	each	\$3,158.75	1
Sandalfoot Cove Park	63	Women's Restroom - South	Plumbing Fixtures & Elements	Lower sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Sandalfoot Cove Park	64	Women's Restroom - South	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Sandalfoot Cove Park	65	Women's Restroom - South	Reach Ranges	Lower soap to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	66	Women's Restroom - South	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
Sandalfoot Cove Park	67	Women's Restroom - South	Toilet and Bathing Rooms	Remove grab bar to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	68	Women's Restroom - South	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Sandalfoot Cove Park	69	Women's Restroom - South	Toilet and Bathing Rooms	Replace side grab bar with a 42" long bar mounted to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	70	Women's Restroom - South	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	71	Women's Restroom - South	Toilet and Bathing Rooms	Relocate flush control to be min. 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	72	Women's Restroom - South	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit. Cost included in previous finding.	\$0.00	1	each	\$0.00	1
Sandalfoot Cove Park	73	Women's Restroom - South	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Sandalfoot Cove Park	74	Women's Restroom - South	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	75	Women's Restroom - South	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	76	Women's Restroom - North	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted 34" to 48" AFF.	\$2,264.50	1	each	\$2,264.50	1
Sandalfoot Cove Park	77	Women's Restroom - North	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	78	Women's Restroom - North	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Sandalfoot Cove Park	79	Women's Restroom - North	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Sandalfoot Cove Park	80	Women's Restroom - North	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Sandalfoot Cove Park	81	Women's Restroom - North	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls, or 16" to 18" in new wheelchair stall.	\$1,828.40	1	each	\$1,828.40	1
Sandalfoot Cove Park	82	Women's Restroom - North	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$840.00	1	each	\$840.00	1
Sandalfoot Cove Park	83	Women's Restroom - North	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Sandalfoot Cove Park	84	Women's Restroom - North	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	staff time	\$393.75	1
Sandalfoot Cove Park	85	Women's Restroom - North	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Sandalfoot Cove Park	86	Women's Restroom - North	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Sandalfoot Cove Park	87	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted 34" to 48" AFF.	\$610.75	1	each	\$610.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	88	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted 34" to 48" AFF.	\$3,578.00	1	each	\$3,578.00	3
Sandalfoot Cove Park	89	Park Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
Sandalfoot Cove Park	90	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Sandalfoot Cove Park	91	Park Element	Plumbing Fixtures & Elements	Replace drinking fountain with a hi-lo bowl fountain. See previous finding for cost.	\$0.00	1	each	\$0.00	2
Sandalfoot Cove Park	92	Park Element	Plumbing Fixtures & Elements	Remount fountain to provide centered clear floor space.	\$122.50	12	sq ft	\$1,470.00	1
Sandalfoot Cove Park	93	Park Element	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Sandalfoot Cove Park	94	Park Element	Outdoor - Constructed Features (C)	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	\$350.00	1	each	\$350.00	5
Sandalfoot Cove Park	95	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Sandalfoot Cove Park	96	Park Element	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	1
Sandalfoot Cove Park	97	Park Element	Clear Floor Space	Correct slope in CGS at fountain to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	1
Sandalfoot Cove Park	98	Park Element	Plumbing Fixtures & Elements	Consider replacing drinking fountain with a hi-lo bowl fountain. See previous finding for cost.	\$0.00	1	each	\$0.00	2
Sandalfoot Cove Park	99	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	2
Sandalfoot Cove Park	100	Park Element	Reach Ranges	Remount garbage cans to be in reach range of 15" min to 48" max	\$0.00	3	staff time	\$0.00	1
Sandalfoot Cove Park	101	Park Element	Operable Parts	Provide an accessible entry into batting cage that doesn't require a tight pinch or grasp and allows for a full 32" wide opening that extends to the ground.	\$514.50	1	each	\$514.50	2
Sandalfoot Cove Park	102	Sports Fields	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from walkway to both bleachers. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	263	lin ft	\$15,569.60	4
Sandalfoot Cove Park	103	Sports Fields	Reach Ranges	Lower garbage can to be in reach range of 48" max.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	104	Sports Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County ball field amenities accessible.	\$59.20	15	lin ft	\$888.00	4
Sandalfoot Cove Park	105	Ball Field 1	Park Site (C)	Widen door/gate to min 32" clear width, or 36" if maneuvering clearance isn't provided.  In the alternative, leave as is and designate other County ball fields accessible.	\$1,750.00	2	each	\$3,500.00	4
Sandalfoot Cove Park	106	Ball Field 1	Clear Floor Space	Provide CGS that is min 30" clear width and 48" deep at benches in dugouts.  In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
Sandalfoot Cove Park	107	Ball Field 1	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	90	lin ft	\$5,328.00	4
Sandalfoot Cove Park	108	Ball Field 2	Clear Floor Space	Provide CGS that is min 30" clear width and 48" deep at benches in dugouts.  In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
Sandalfoot Cove Park	109	Ball Field 2	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	90	lin ft	\$5,328.00	4
Sandalfoot Cove Park	110	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Sandalfoot Cove Park	111	Play Area (2-5)	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Sandalfoot Cove Park	114	Play Area (2-5)	Play Area	Add one more GLPC's of a different type to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	116	Play Area Elements	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%. In the alternative, leave as is citing construction tolerance.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, remount hardware to 34" to 48" AGL.	\$192.50	1	each	\$192.50	2
Sandalfoot Cove Park	117	Play Area Elements	Reach Ranges	Lower garbage can to be in reach range of 1 48" max.	\$0.00	1	staff time	\$0.00	1
Sandalfoot Cove Park	118	Press Box	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	2
Sandalfoot Cove Park	119	Press Box	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$1,846.25	1	each	\$1,846.25	3
Sandalfoot Cove Park	120	Press Box	Stairways	Install kick plates on all stairs or replace with ones having closed risers	\$84.00	14	each	\$1,176.00	2
Sandalfoot Cove Park	121	Press Box	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	\$980.00	2	each	\$1,960.00	2
Sandalfoot Cove Park	122	Concession	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	2
Sandalfoot Cove Park	123	Concession	Turning Space	Relocate obstacles to create turning space in concession.	\$0.00	1	staff time	\$0.00	2
Sandalfoot Cove Park	124	Concession	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Sandalfoot Cove Park	125	Concession	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, provide beveled threshold.	\$6,088.75	1	each	\$6,088.75	1
Sanders Drive Park	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Sanders Drive Park	2	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sanders Drive Park	3	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	250	sq ft	\$30,625.00	1
Sanders Drive Park	4	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	1
Sanders Drive Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Sanders Drive Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Sanders Drive Park	8	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Sanders Drive Park	11	2-12 Play Area	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Sanders Drive Park	12	2-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Sanders Drive Park	13	2-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Sanders Drive Park	15	2-12 Play Area	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
<a href="#">Santalucas Athletic and Aquatic Complex</a>	1	Parking - Ballfields	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
Santalucas Athletic and Aquatic Complex	2	Parking - Ballfields	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Santalucas Athletic and Aquatic Complex	3	Parking - Ballfields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Santalucas Athletic and Aquatic Complex	4	Parking - Ballfields	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
Santalucas Athletic and Aquatic Complex	6	Parking - Pool	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	1	staff time	\$0.00	1
Santalucas Athletic and Aquatic Complex	7	Parking - Pool	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Santalucas Athletic and Aquatic Complex	8	Exterior Accessible Route	Doors	For all doors along the public circulation route, remount hardware 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Santalucas Athletic and Aquatic Complex	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Santalucas Athletic and Aquatic Complex	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1
Santalucas Athletic and Aquatic Complex	11	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Santalucas Athletic and Aquatic Complex	12	Exterior Accessible Route	Accessible Routes	Consider replacement of surface to a surface that is firm and stable as this is a shorter route to the playground for many site users.  In the alternative, leave as is if only intended for vehicle use.	\$500.00	890	lin ft	\$445,000.00	3
Santalucas Athletic and Aquatic Complex	14	Park Element	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Santalucas Athletic and Aquatic Complex	15	Park Element	Accessible Routes	Create a route to at least one picnic table and replace with one of a complinat model.	\$2,600.00	2	each	\$5,200.00	5
Santalucas Athletic and Aquatic Complex	16	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	70	lin ft	\$4,144.00	2
Santalucas Athletic and Aquatic Complex	17	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	70	lin ft	\$4,144.00	2
Santalucas Athletic and Aquatic Complex	18	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	70	lin ft	\$4,144.00	2
Santalucas Athletic and Aquatic Complex	19	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	70	lin ft	\$4,144.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santalucas Athletic and Aquatic Complex	20	Fishing Area	Accessible Route - Slope (C)	Correct running slopes to max 5%.  In the alternative, leave as is and designate other County fishing areas accessible.	\$3,062.50	1	each	\$3,062.50	4
Santalucas Athletic and Aquatic Complex	21	Fishing Area	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".  In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	14	each	\$13,720.00	4
Santalucas Athletic and Aquatic Complex	22	Fishing Area	Fishing Piers And Platforms	Provide 2" high curb for edge protection.  In the alternative, leave as is and designate other County fishing areas accessible.	\$525.00	5	each	\$2,625.00	4
Santalucas Athletic and Aquatic Complex	23	Fishing Area	Accessible Routes	Correct or fill gaps to be max .5".  In the alternative, leave as is and designate other County fishing areas accessible.	\$96.25	1	each	\$96.25	4
Santalucas Athletic and Aquatic Complex	24	5-12 Play Area	Play Area	Provide a designated entry min 36" wide that is free of CIL and gaps.	\$700.00	1	each	\$700.00	5
Santalucas Athletic and Aquatic Complex	25	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Santalucas Athletic and Aquatic Complex	26	5-12 Play Area	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.	\$0.00	1	staff time	\$0.00	2
Santalucas Athletic and Aquatic Complex	27	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Santalucas Athletic and Aquatic Complex	28	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Santalucas Athletic and Aquatic Complex	29	5-12 Play Area	Play Area	Lower the seat, or raise the surface fill level to achieve entry height of 11" to 24" AGL to swing.	\$0.00	1	staff time	\$0.00	2
Santalucas Athletic and Aquatic Complex	30	5-12 Play Area	Play Area	See previous finding for surface correction.	\$0.00	1	each	\$0.00	2
Santalucas Athletic and Aquatic Complex	31	5-12 Play Area	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Santalucas Athletic and Aquatic Complex	33	Trail Element	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Santalucas Athletic and Aquatic Complex	34	Trail Element	Accessible Routes	Raise surface fill to be level with adjacent surface.	\$96.25	1	each	\$96.25	1
Santalucas Athletic and Aquatic Complex	35	Trail Element	Clear Floor Space	Provide clear ground space at each fitness station and connect clear ground space to accessible route. In the alternative, leave as is and designate other County fitness amenities accessible.	\$161.00	7	each	\$1,127.00	4
Santalucas Athletic and Aquatic Complex	36	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	30	sq ft	\$3,675.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	37	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
Santaluces Athletic and Aquatic Complex	38	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	120	sq ft	\$14,700.00	5
Santaluces Athletic and Aquatic Complex	39	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Santaluces Athletic and Aquatic Complex	40	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	2100	sq ft	\$257,250.00	5
Santaluces Athletic and Aquatic Complex	41	Trail Surface	Trails	Correct or fill gaps to max .5" as a smart practice.	\$96.25	6	each	\$577.50	5
Santaluces Athletic and Aquatic Complex	42	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1680	sq ft	\$205,800.00	5
Santaluces Athletic and Aquatic Complex	43	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1680	sq ft	\$205,800.00	5
Santaluces Athletic and Aquatic Complex	44	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
Santaluces Athletic and Aquatic Complex	45	Trail Surface	Accessible Routes	Widen EAR to min 36" clear width	\$350.00	2	each	\$700.00	5
Santaluces Athletic and Aquatic Complex	46	Trail Surface	Accessible Routes	Widen EAR to min 36" clear width.	\$350.00	2	each	\$700.00	5
Santaluces Athletic and Aquatic Complex	47	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	1375	lin ft	\$81,400.00	4
Santaluces Athletic and Aquatic Complex	48	Field 1	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	1	each	\$96.25	4
Santaluces Athletic and Aquatic Complex	49	Field 1	Doors	For all doors along the public circulation route, remount hardware 34" to 48" AFF.  In the alternative, leave as is and designate other County ball fields accessible.	\$514.50	1	each	\$514.50	4
Santaluces Athletic and Aquatic Complex	50	Field 1	Assembly Areas	Correct or repair slope in CFS to max 2.08%.  In the alternative, leave as is and designate other County ball fields accessible.	\$1,470.00	1	each	\$1,470.00	4
Santaluces Athletic and Aquatic Complex	51	Field 1	Park Site (C)	Provide an accessible route (AR) to each element within the site and repair changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$4,432.75	1	each	\$4,432.75	4
Santaluces Athletic and Aquatic Complex	52	Field 1	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	53	Field 2	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	1	each	\$96.25	4
Santaluces Athletic and Aquatic Complex	54	Field 2	Doors	For all doors along the public circulation route, remount hardware 34" to 48" AFF.  In the alternative, leave as is and designate other County ball fields accessible.	\$514.50	1	each	\$514.50	4
Santaluces Athletic and Aquatic Complex	55	Field 2	Accessible Route - Slope (C)	Correct running slopes to max 5%.  In the alternative, leave as is and designate other County ball fields accessible.	\$3,062.50	1	each	\$3,062.50	4
Santaluces Athletic and Aquatic Complex	56	Field 2	Park Site (C)	Provide an accessible route (AR) to each element within the site. Repair changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$4,336.50	1	each	\$4,336.50	4
Santaluces Athletic and Aquatic Complex	57	Field 2	Assembly Areas	Correct or repair slope in CGS to max 2.08%.	\$1,470.00	1	each	\$1,470.00	2
Santaluces Athletic and Aquatic Complex	58	Field 3	Park Site (C)	Provide an accessible route (AR) to each element within the site. Repair changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$4,336.50	2	each	\$8,673.00	4
Santaluces Athletic and Aquatic Complex	59	Field 3	Assembly Areas	Correct or repair slope in CFS to max 2.08%.	\$1,470.00	1	each	\$1,470.00	2
Santaluces Athletic and Aquatic Complex	60	Field 3	Picnic Tables (C)	Replace picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Santaluces Athletic and Aquatic Complex	61	Field 4	Park Site (C)	Provide an accessible route (AR) to each element within the site. Repair changes in level to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$4,336.50	2	each	\$8,673.00	4
Santaluces Athletic and Aquatic Complex	62	Field 4	Assembly Areas	Correct or repair slope in CFS to max 2.08%.	\$1,470.00	1	each	\$1,470.00	2
Santaluces Athletic and Aquatic Complex	63	Concession Building	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
Santaluces Athletic and Aquatic Complex	64	Concession Building	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Santaluces Athletic and Aquatic Complex	65	Concession Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
Santaluces Athletic and Aquatic Complex	66	Public Spaces	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	67	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Santaluces Athletic and Aquatic Complex	68	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	69	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	70	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	71	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors. In the alternative, leave as is as correction may be technically infeasible.	\$1,750.00	2	each	\$3,500.00	4
Santaluces Athletic and Aquatic Complex	72	Maintenance Building	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$3,518.75	1	each	\$3,518.75	3
Santaluces Athletic and Aquatic Complex	73	Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	74	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Santaluces Athletic and Aquatic Complex	75	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink in stall.	\$77.00	1	each	\$77.00	1
Santaluces Athletic and Aquatic Complex	76	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Santaluces Athletic and Aquatic Complex	77	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	78	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Santaluces Athletic and Aquatic Complex	79	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	80	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
				For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.					
				For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.					
Santaluces Athletic and Aquatic Complex	81	Men's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Santaluces Athletic and Aquatic Complex	82	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	83	Women's Restroom	Plumbing Fixtures & Elements	Lower sink in stall and one sink in main area to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is sink in stall citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	1
Santaluces Athletic and Aquatic Complex	84	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Santaluces Athletic and Aquatic Complex	85	Women's Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Santaluces Athletic and Aquatic Complex	86	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	87	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Santaluces Athletic and Aquatic Complex	88	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Santaluces Athletic and Aquatic Complex	89	Women's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$2,749.25	1	each	\$2,749.25	1
Santaluces Athletic and Aquatic Complex	90	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Santaluces Athletic and Aquatic Complex	91	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
				For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Priced in Men's restroom finding.					
Santaluces Athletic and Aquatic Complex	92	Women's Restroom	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	each	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	93	Pool Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Santaluces Athletic and Aquatic Complex	94	Pool Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Santaluces Athletic and Aquatic Complex	95	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Santaluces Athletic and Aquatic Complex	96	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$3,447.50	1	each	\$3,447.50	3
Santaluces Athletic and Aquatic Complex	97	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$3,158.75	1	each	\$3,158.75	3
Santaluces Athletic and Aquatic Complex	98	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$5,293.75	1	each	\$5,293.75	3
Santaluces Athletic and Aquatic Complex	99	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Repair, bevel, or ramp CILs at door entries to max .25".	\$288.75	1	each	\$288.75	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	100	Employee Spaces	Accessible Routes	No AR to employee area, leave as is, and reassign duties if an employee with disabilities requires access here.	\$0.00	1	N/A	\$0.00	4
Santaluces Athletic and Aquatic Complex	101	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$5,293.75	1	each	\$5,293.75	3
Santaluces Athletic and Aquatic Complex	102	Employee Spaces	Doors	Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	1	staff time	\$0.00	3
Santaluces Athletic and Aquatic Complex	103	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	3
Santaluces Athletic and Aquatic Complex	103	Employee Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
Santaluces Athletic and Aquatic Complex	104	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts.	\$0.00	1	staff time	\$0.00	3
Santaluces Athletic and Aquatic Complex	105	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	3
Santaluces Athletic and Aquatic Complex	106	Employee Spaces	Toilet and Bathing Rooms	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	\$24,928.75	1	each	\$24,928.75	3
Santaluces Athletic and Aquatic Complex	107	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Replace operable parts with ones that are operable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3
Santaluces Athletic and Aquatic Complex	108	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".	\$481.25	1	each	\$481.25	3
Santaluces Athletic and Aquatic Complex	109	Employee Spaces	Sales and Service Counters/Tables	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.  Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	110	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".	\$1,846.25	1	each	\$1,846.25	3
Santaluces Athletic and Aquatic Complex	111	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".	\$1,846.25	1	each	\$1,846.25	3
Santaluces Athletic and Aquatic Complex	112	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$4,522.00	1	each	\$4,522.00	3
Santaluces Athletic and Aquatic Complex	113	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount signage to the right side of entryway.  Remove storage from CFS of tactile wall sign.	\$210.00	1	staff time	\$210.00	1
Santaluces Athletic and Aquatic Complex	114	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Santaluces Athletic and Aquatic Complex	115	Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Santaluces Athletic and Aquatic Complex	116	Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Santaluces Athletic and Aquatic Complex	117	Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Santaluces Athletic and Aquatic Complex	118	Men's Restroom and Locker Room	Reach Ranges	Remount at least one hook and one hair dryer to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
Santaluces Athletic and Aquatic Complex	119	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Santaluces Athletic and Aquatic Complex	120	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Santaluces Athletic and Aquatic Complex	121	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	122	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Santaluces Athletic and Aquatic Complex	123	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Santaluces Athletic and Aquatic Complex	124	Men's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	125	Men's Restroom and Locker Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
Santaluces Athletic and Aquatic Complex	126	Men's Restroom and Locker Room	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Santaluces Athletic and Aquatic Complex	127	Men's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	2
Santaluces Athletic and Aquatic Complex	128	Men's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Santaluces Athletic and Aquatic Complex	129	Men's Restroom and Locker Room	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	2
Santaluces Athletic and Aquatic Complex	131	Men's Restroom and Locker Room	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Santaluces Athletic and Aquatic Complex	132	Men's Restroom and Locker Room	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	5	each	\$481.25	1
Santaluces Athletic and Aquatic Complex	133	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount signage to the right side of entryway.	\$210.00	1	each	\$210.00	1
Santaluces Athletic and Aquatic Complex	134	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Santaluces Athletic and Aquatic Complex	135	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Santaluces Athletic and Aquatic Complex	136	Women's Restroom and Locker Room	Reach Ranges	Remount hook to be in reach range of 48" max.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	137	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Santaluces Athletic and Aquatic Complex	138	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Santaluces Athletic and Aquatic Complex	139	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Santaluces Athletic and Aquatic Complex	140	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	141	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Santaluces Athletic and Aquatic Complex	142	Women's Restroom and Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	143	Women's Restroom and Locker Room	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Santaluces Athletic and Aquatic Complex	144	Women's Restroom and Locker Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
Santaluces Athletic and Aquatic Complex	145	Women's Restroom and Locker Room	Reach Ranges	Remount at least one hook and one dryer to be in reach range of 15" min to 48" max	\$233.25	2	each	\$466.50	2
Santaluces Athletic and Aquatic Complex	146	Women's Restroom and Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Santaluces Athletic and Aquatic Complex	147	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Santaluces Athletic and Aquatic Complex	148	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the transfer shower.	\$350.00	1	each	\$350.00	2
Santaluces Athletic and Aquatic Complex	149	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2
Santaluces Athletic and Aquatic Complex	150	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Provide the required folding or non-folding seat in the transfer shower.	\$840.00	1	each	\$840.00	2
Santaluces Athletic and Aquatic Complex	151	Women's Restroom and Locker Room	Plumbing Fixtures & Elements	Remount shower grab bar to 33" min. and 36" max. AFF. Priced in previous finding.	\$0.00	1	each	\$0.00	2
Santaluces Athletic and Aquatic Complex	152	Women's Restroom and Locker Room	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	5	each	\$481.25	1
Santaluces Athletic and Aquatic Complex	153	Pool Deck	Pool / Spa	Repair or replace pool lift and make it available every hour the pool is open.	\$8,400.00	1	each	\$8,400.00	2
Santaluces Athletic and Aquatic Complex	154	Pool Deck	Pool / Spa	Relocate lift to an area providing 36" X 48" CFS having max slope of 2.08%.	\$1,470.00	1	each	\$1,470.00	2
Santaluces Athletic and Aquatic Complex	155	Pool Deck	Pool / Spa	Correct pool stair treads to be min 11" deep and riser heights to be uniform if feasible.	\$404.25	5	each	\$2,021.25	3
Santaluces Athletic and Aquatic Complex	156	Pool Deck	Pool / Spa	Provide two handrails on one set pool stairs, mounted 20" to 24" apart.	\$980.00	1	each	\$980.00	2
Santaluces Athletic and Aquatic Complex	157	Pool Deck	Pool / Spa	Install compliant sloped entry in wading pool; if technically infeasible leave as is.	\$7,140.00	1	each	\$7,140.00	3
Santaluces Athletic and Aquatic Complex	158	Pool Deck	Pool / Spa	Maintain an accessible route along the pool deck that is min 36" clear width and having 80" overhead clearance and turning spaces and free of gaps and CIL. Provide a guard rail or barrier at protruding objects.	\$122.50	480	sq ft	\$58,800.00	3
Santaluces Athletic and Aquatic Complex	159	Pool Elements	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain and assure that clear ground space has max slope of 2.08%	\$5,598.25	1	each	\$5,598.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Santaluces Athletic and Aquatic Complex	160	Pool Elements	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain and assure that clear ground space has max slope of 2.08%.	\$5,598.25	1	each	\$5,598.25	2
Santaluces Athletic and Aquatic Complex	161	Pool Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Santaluces Athletic and Aquatic Complex	162	Pool Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	5
Santaluces Athletic and Aquatic Complex	163	Pool Elements	Clear Floor Space	Correct or repair slope in CGS to max 2.08% at both ends of bleachers for wheelchair seating.	\$122.50	150	sq ft	\$18,375.00	2
<u>Seminole Palms Park</u>	2	Parking - Main Lot Between Water Park And Ballfields	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	8	each	\$588.00	1
Seminole Palms Park	3	Parking - Main Lot Between Water Park And Ballfields	Parking - Off Street	Add van parking sign to two accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	2	each	\$567.00	1
Seminole Palms Park	4	Parking - Main Lot Between Water Park And Ballfields	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	7	each	\$21,437.50	1
Seminole Palms Park	5	Parking - Main Lot Between Water Park And Ballfields	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	4	each	\$294.00	1
Seminole Palms Park	7	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Seminole Palms Park	8	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	\$1,589.00	2	each	\$3,178.00	1
Seminole Palms Park	9	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'. Repainting cost in previous finding.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	10	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Seminole Palms Park	11	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surface. Resurface right stall to eliminate gaps and cracks. Cost included in slope correction.	\$0.00	1	each	\$0.00	1
Seminole Palms Park	12	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including penalty information.	\$210.00	2	each	\$420.00	1
Seminole Palms Park	13	Parking - Lot Between Waterpark And Maintenance	Parking - Off Street	Provide a 44" wide accessible route that connects to an existing route.	\$59.20	100	lin ft	\$5,920.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	14	Parking - Maintenance	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
Seminole Palms Park	15	Parking - Maintenance	Parking - Off Street	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	\$367.50	1	each	\$367.50	1
Seminole Palms Park	16	Parking - Maintenance	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	17	Parking - Maintenance	Parking - Off Street	Relocate sign for employee of the month to another stall.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	18	Parking - Maintenance	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
Seminole Palms Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Seminole Palms Park	22	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
Seminole Palms Park	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Seminole Palms Park	24	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	480	sq ft	\$58,800.00	1
Seminole Palms Park	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Seminole Palms Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	560	sq ft	\$68,600.00	1
Seminole Palms Park	27	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Seminole Palms Park	28	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	115	sq ft	\$14,087.50	1
Seminole Palms Park	29	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	30	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	31	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	32	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	30	sq ft	\$3,675.00	1
Seminole Palms Park	33	Exterior Accessible Route	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of walkway surface.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	34	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Seminole Palms Park	35	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Seminole Palms Park	36	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	37	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Seminole Palms Park	38	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	600	sq ft	\$73,500.00	1
Seminole Palms Park	39	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Seminole Palms Park	40	Exterior Accessible Route	Accessible Route - Slope (C)	Fill depression to correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	41	Exterior Accessible Route	Accessible Route - Slope (C)	Resurface path to eliminate water pooling.	\$122.50	100	sq ft	\$12,250.00	2
Seminole Palms Park	42	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
Seminole Palms Park	43	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	44	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	45	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	46	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	15	lin ft	\$888.00	1
Seminole Palms Park	47	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
Seminole Palms Park	48	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08% to prevent water pooling.	\$875.00	1	each	\$875.00	3
Seminole Palms Park	49	Exterior Accessible Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF. In the alternative, leave as is citing construction tolerance	\$350.00	2	each	\$700.00	4
Seminole Palms Park	50	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Seminole Palms Park	51	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	2	each	\$1,050.00	3
Seminole Palms Park	52	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Seminole Palms Park	53	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Seminole Palms Park	54	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Seminole Palms Park	55	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	56	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	57	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	45	sq ft	\$5,512.50	1
Seminole Palms Park	58	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	95	sq ft	\$11,637.50	1
Seminole Palms Park	59	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Seminole Palms Park	60	Exterior Accessible Route	Curb Ramps	Correct slope of curb ramp side flares to max 10%.	\$1,015.00	2	each	\$2,030.00	1
Seminole Palms Park	61	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Seminole Palms Park	62	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	63	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Seminole Palms Park	64	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	160	sq ft	\$19,600.00	1
Seminole Palms Park	65	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	66	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	320	sq ft	\$39,200.00	1
Seminole Palms Park	67	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	175	sq ft	\$21,437.50	1
Seminole Palms Park	68	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	16	lin ft	\$947.20	1
Seminole Palms Park	69	Park Element	Plumbing Fixtures & Elements	Repair existing high bowl or add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Seminole Palms Park	70	Park Element	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Seminole Palms Park	72	Park Element	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
Seminole Palms Park	73	Park Element	Plumbing Fixtures & Elements	Replace spout and ensure spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	74	Park Element	Plumbing Fixtures & Elements	Fountain inoperable - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Seminole Palms Park	75	Park Element	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	76	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	15	lin ft	\$888.00	2
Seminole Palms Park	77	Park Element	Outdoor - Constructed Features (C)	Relocate accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Seminole Palms Park	79	Multipurpose Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	200	lin ft	\$11,840.00	4
Seminole Palms Park	80	Multipurpose Fields	Assembly Areas	Widen CGS for wheelchair seating space to min 36". In the alternative, leave as is and designate other County rectangular fields accessible.	\$1,225.00	1	each	\$1,225.00	4
Seminole Palms Park	81	Multipurpose Fields	Assembly Areas	Provide level clear ground space adjacent to bleachers, 30" by 48". In the alternative, leave as is and designate other County rectangular fields accessible.	\$1,225.00	1	each	\$1,225.00	4
Seminole Palms Park	82	Multipurpose Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	215	lin ft	\$12,728.00	4
Seminole Palms Park	83	Multipurpose Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	20	lin ft	\$1,184.00	4
Seminole Palms Park	84	Pavilion	Outdoor - Constructed Features (C)	Relocate picnic accessible picnic table to provide required 36" clear ground space around all usable portions of the table as a smart practice. Add a second accessible table.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Seminole Palms Park	85	Picnic Area	Picnic Tables (C)	Replace one of picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table. Relocate accessible tables to provide 36" route around. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
Seminole Palms Park	86	Picnic Area	Shelters, Picnic Facilities (C)	Relocate 20% of garbage cans to be along AR. In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	87	Picnic Area	Shelters/Picnic Areas (C)	<p>Replace or correct grill on west side so cooking surface faces accessible route.</p> <p>Replace or lower grill to max height of cooking surface 34".</p> <p>Remount garbage can rim to be in reach range of 15" min to 48" max.</p> <p>Correct or repair slope in CFS of grill on east side to max 2.08%.</p> <p>In the alternative, leave as is and designate other County picnic facilities accessible.</p>	\$940.50	4	each	\$3,762.00	4
Seminole Palms Park	88	Play Area (2-5)	Accessible Routes	<p>Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$59.20	10	lin ft	\$592.00	4
Seminole Palms Park	89	Play Area (2-5)	Play Area	<p>Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$700.00	1	each	\$700.00	4
Seminole Palms Park	90	Play Area (2-5)	Accessible Routes	<p>Correct or repair cross slope along accessible route to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70.00	240	sq ft	\$16,800.00	4
Seminole Palms Park	91	Play Area (2-5)	Accessible Routes	<p>Raise fill to be level with adjacent surface.</p> <p>Correct or fill gaps to be max .5".</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70.00	25	each	\$1,750.00	4
Seminole Palms Park	92	Play Area (2-5)	Play Area	<p>Consider adding a second transfer system as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$4,970.00	1	each	\$4,970.00	4
Seminole Palms Park	95	Play Area (2-5)	Clear Floor Space	<p>Correct or repair slope in CFS to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70.00	25	sq ft	\$1,750.00	4
Seminole Palms Park	96	Play Area (2-5)	Play Area	<p>Add two more GLPC's of two types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$2,800.00	2	each	\$5,600.00	4
Seminole Palms Park	97	Play Area (5-12)	Play Area	<p>Correct or fill gap along at designated entry. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$96.25	1	each	\$96.25	4
Seminole Palms Park	98	Play Area (5-12)	Play Area	<p>Correct or repair ground ramp slope to be max 6.25%. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70.00	25	sq ft	\$1,750.00	4
Seminole Palms Park	99	Play Area (5-12)	Accessible Routes	<p>Correct or repair cross slope along accessible route to max 2.08%. In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70.00	350	sq ft	\$24,500.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	100	Play Area (5-12)	Accessible Routes	Repair surface where torn.  Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  In the alternative, leave as is and designate other County playgrounds accessible.	\$72.25	4	each	\$289.00	4
Seminole Palms Park	101	Play Area (5-12)	Play Area	Provide level 30" x 48" minimum CFS centered and parallel to the 24" side of the transfer platform. In the alternative, leave as is and designate other County playgrounds accessible.	\$3,062.50	1	each	\$3,062.50	4
Seminole Palms Park	102	Play Area (5-12)	Play Area	Correctly remount handrails along both sides of ramp at 20" to 28" AFF. In the alternative, leave as is and designate other County playgrounds accessible.	\$350.00	2	each	\$700.00	4
Seminole Palms Park	103	Play Area (5-12)	Play Area	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,604.00	1	each	\$2,604.00	4
Seminole Palms Park	105	Play Area (5-12)	Play Area	Add another manipulable ground level play component on the route. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Seminole Palms Park	106	Play Area (5-12)	Play Area	Add three more GLPCs of three types to meet incentive scoping. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	3	each	\$8,400.00	4
Seminole Palms Park	107	Play Area (2-12)	Accessible Routes	Create an AR to the play area within the site. In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	6	lin ft	\$355.20	4
Seminole Palms Park	108	Play Area (2-12)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Seminole Palms Park	109	Play Area (2-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Seminole Palms Park	110	Play Area (2-12)	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.  Cost included in previous finding.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	100	sq ft	\$0.00	4
Seminole Palms Park	111	Play Area (2-12)	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	112	Men's Restroom Near Play Area	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.  For all doors/gates along the public circulation route, remount hardware to min 34" and max 48".	\$514.50	1	each	\$514.50	1
Seminole Palms Park	113	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	114	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Seminole Palms Park	115	Men's Restroom Near Play Area	Plumbing Fixtures & Elements	Lower one sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	116	Men's Restroom Near Play Area	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Seminole Palms Park	117	Men's Restroom Near Play Area	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	118	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline. In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Seminole Palms Park	119	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	120	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	121	Men's Restroom Near Play Area	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	122	Men's Restroom Near Play Area	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Seminole Palms Park	123	Men's Restroom Near Play Area	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	124	Women's Restroom At Playground (Bldg 5)	Doors	For all doors along the public circulation route, remount lever hardware where indicated to 34" to 48" AFF.	\$514.50	1	each	\$514.50	1
Seminole Palms Park	125	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	126	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Seminole Palms Park	127	Women's Restroom At Playground (Bldg 5)	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	128	Women's Restroom At Playground (Bldg 5)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	129	Women's Restroom At Playground (Bldg 5)	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	130	Women's Restroom At Playground (Bldg 5)	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	131	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	132	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	133	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	134	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Adjust partition to provide 18" pull side clearance.	\$420.00	1	each	\$420.00	1
Seminole Palms Park	135	Women's Restroom At Playground (Bldg 5)	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	136	Women's Restroom At Playground (Bldg 5)	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	137	Concession Building	Accessible Routes	Provide vertical access to press box.	\$46,631.00	1	each	\$46,631.00	3
Seminole Palms Park	138	Concession Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	139	Concession Building	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	2
Seminole Palms Park	141	Concession Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Leave as is stairs, may be infeasible to correct.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$2,275.00	1	each	\$2,275.00	1
Seminole Palms Park	142	Concession Building	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	15	each	\$6,063.75	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	143	Concession Building	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	15	each	\$1,875.00	5
Seminole Palms Park	144	Concession Building	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks. Handrails may curve around bottom to avoid hazard.	\$980.00	2	each	\$1,960.00	2
Seminole Palms Park	145	Ball Fields	Park Site (C)	Remove objects to required clear space min 36" x 48".	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	146	Ball Fields	Park Site (C)	Remove objects to required clear space min 36" x 48".	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	147	Ball Fields	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$1,470.00	2	each	\$2,940.00	2
Seminole Palms Park	148	Ball Fields	Park Site (C)	Remove objects to required clear space min 36" x 48".	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	149	Ball Fields	Park Site (C)	Remove objects to required clear space min 36" x 48".	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	150	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	151	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	152	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Seminole Palms Park	153	Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Seminole Palms Park	154	Men's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	155	Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Seminole Palms Park	156	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	157	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	158	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	159	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	160	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Seminole Palms Park	161	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	162	Men's Restroom	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$2,772.50	1	each	\$2,772.50	1
Seminole Palms Park	163	Women's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	164	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR. Adjust stall door to be self-closing	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	165	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	166	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	167	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Seminole Palms Park	168	Women's Restroom	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	169	Women's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Seminole Palms Park	170	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	171	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	172	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	173	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	174	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Seminole Palms Park	175	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	176	Women's Restroom	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top in main area and in stall.	\$350.00	2	staff time	\$700.00	1
Seminole Palms Park	177	Women's Restroom	Doors	Replace closer with one mounted min of 78" AFF.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	178	Women's Restroom	Custom/Special	Install the same types of amenities serving the handwashing task in the stall as are provided in the main area.	\$350.00	2	each	\$700.00	1
Seminole Palms Park	179	Concession Building	Accessible Routes	Provide vertical access to press box.	\$46,631.00	1	each	\$46,631.00	3
Seminole Palms Park	180	Concession Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	181	Concession Building	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Seminole Palms Park	182	Concession Building	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
Seminole Palms Park	183	Concession Building	Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$253.75	1	each	\$253.75	1
Seminole Palms Park	184	Concession Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Leave as is stairs, correction may be technically infeasible.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$2,275.00	1	each	\$2,275.00	1
Seminole Palms Park	185	Concession Building	Stairways	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible.	\$404.25	15	each	\$6,063.75	4
Seminole Palms Park	186	Concession Building	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	15	each	\$1,875.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	187	Concession Building	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks. Handrails can curve around building to avoid hazard.	\$980.00	2	each	\$1,960.00	2
Seminole Palms Park	188	Ballfields 1-4 EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	630	sq ft	\$77,175.00	2
Seminole Palms Park	189	Ballfields 1-4 EAR	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	2
Seminole Palms Park	190	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	191	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	192	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	193	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	194	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	195	Ballfields 1-4 EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	2
Seminole Palms Park	196	Ballfields 1-4 EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	2
Seminole Palms Park	197	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	198	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
Seminole Palms Park	199	Ballfields 1-4 EAR	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	11	each	\$1,058.75	2
Seminole Palms Park	200	Ballfields 1-4 EAR	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
Seminole Palms Park	201	Ballfields 1-4 EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	2
Seminole Palms Park	202	Ballfields 1-4 EAR	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	2
Seminole Palms Park	204	Ballfields 1-4 Elements	Reach Ranges	Remount at least 2 of 8 garbage cans located along an accessible route to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	205	Ballfield 1	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	20	lin ft	\$1,184.00	4
Seminole Palms Park	206	Ballfield 1	Park Site (C)	Remove objects to required clear space min 36" x 48". In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Seminole Palms Park	207	Ballfield 1	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of dugout surfaces. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	1	staff time	\$0.00	4
Seminole Palms Park	209	Ballfield 1	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	45	lin ft	\$2,664.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	210	Ballfield 1	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.</p> <p>In the alternative, leave as is and designate other County ball fields accessible.</p>	\$3,988.25	2	each	\$7,976.50	4
Seminole Palms Park	211	Ballfield 2	Accessible Routes	<p>Establish protocols for regular and frequent inspection and maintenance of crushed granite route to dugouts. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	212	Ballfield 2	Park Site (C)	<p>Remove objects to required clear space min 36" x 48". In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	213	Ballfield 2	Accessible Routes	<p>Establish protocols for regular and frequent inspection and maintenance of dugout surfaces. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	215	Ballfield 2	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>In the alternative, leave as is and designate other County ball fields accessible.</p>	\$3,062.50	2	each	\$6,125.00	4
Seminole Palms Park	216	Ballfield 2	Park Site (C)	<p>Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$59.20	35	lin ft	\$2,072.00	4
Seminole Palms Park	217	Ballfield 3	Accessible Routes	<p>Establish protocols for regular and frequent inspection and maintenance of dugout surfaces. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	219	Ballfield 3	Accessible Routes	<p>Establish protocols for regular and frequent inspection and maintenance of crushed granite route to dugouts. In the alternative, leave as is and designate other County ball fields accessible.</p>	\$0.00	2	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	220	Ballfield 3	Park Site (C)	Remove objects to required clear space min 36" x 48". In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	221	Ballfield 3	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	40	lin ft	\$2,368.00	4
Seminole Palms Park	222	Ballfield 3	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  In the alternative, leave as is and designate other County ball fields accessible.	\$3,158.75	2	each	\$6,317.50	4
Seminole Palms Park	223	Ballfield 4	Park Site (C)	Remove objects to required clear space min 36" x 48". In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	224	Ballfield 4	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of dugout surfaces. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	226	Ballfield 4	Accessible Routes	Establish protocols for regular and frequent inspection and maintenance of crushed granite route to dugouts. In the alternative, leave as is and designate other County ball fields accessible.	\$0.00	2	staff time	\$0.00	4
Seminole Palms Park	227	Ballfield 4	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.  In the alternative, leave as is and designate other County ball fields accessible.	\$3,367.75	2	each	\$6,735.50	4
Seminole Palms Park	229	Parking - Waterpark	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	5	each	\$367.50	1
Seminole Palms Park	230	Parking - Waterpark	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	5	each	\$367.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	231	Parking - Waterpark	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks. Cost included in slope corrections.	\$0.00	3	each	\$0.00	1
Seminole Palms Park	232	Parking - Waterpark	Parking - Off Street	Add two van parking signs to two accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	2	each	\$420.00	1
Seminole Palms Park	233	Waterpark Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	234	Waterpark Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Seminole Palms Park	235	Waterpark Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	236	Waterpark Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Seminole Palms Park	237	Public Spaces	Signs	Replace Braille on sign and place Braille below the entire text, Braille shall not be broken up by line.	\$210.00	10	each	\$2,100.00	1
Seminole Palms Park	240	Public Spaces	Accessible Routes	Relocate 20% of garbage cans to be along AR, with max 2.08% slopes in CGS, and rims lowered to max 48".	\$0.00	3	staff time	\$0.00	2
Seminole Palms Park	241	Public Spaces	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	3	each	\$1,260.00	2
Seminole Palms Park	242	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
Seminole Palms Park	243	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$236.25	1	each	\$236.25	3
Seminole Palms Park	244	Employee Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
Seminole Palms Park	245	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	246	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p>	\$0.00	1	staff time	\$0.00	3
Seminole Palms Park	247	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Secure rug at door to prevent trip hazard.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain closing speed on door closers.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.</p> <p>Provide kick plate on push side of door from floor to 10" AFF.</p> <p>Remove door holder to provide a smooth surface on the push side of door</p>	\$1,949.50	5	each	\$9,747.50	3
Seminole Palms Park	248	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p>	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	249	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$514.50	1	each	\$514.50	3
Seminole Palms Park	250	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Remount lock hardware to be 34" to 48" AFF.</p>	\$514.50	1	each	\$514.50	3
Seminole Palms Park	253	Employee Spaces	Dining, Bar and Work Surfaces	<p>Replace 5% of the tables with ones providing required knee and toe clearances. In the alternative, leave as is citing construction tolerance.</p>	\$1,120.00	1	each	\$1,120.00	4
Seminole Palms Park	255	Party Rooms	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$3,202.50	1	each	\$3,202.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	256	Party Rooms	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$3,250.50	2	each	\$6,501.00	1
Seminole Palms Park	257	Party Rooms	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	258	Concessions	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$4,195.50	2	each	\$8,391.00	1
Seminole Palms Park	259	Concessions	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	260	Concessions	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Fill gaps at door entries to max .5".  Inspect, adjust, and maintain closing speed on door closers.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.  Provide kick plate on push side of door from floor to 10" AFF.  Replace doors with ones having sidelight viewing windows max 43" AFF.  Remount lock hardware to be 34" to 48" AFF.	\$1,039.85	5	each	\$5,199.25	3
Seminole Palms Park	261	Concessions	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Seminole Palms Park	262	Concessions	Kitchens, Kitchenettes, And Wet Bars	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	\$3,360.00	1	each	\$3,360.00	3
Seminole Palms Park	263	Concessions	Accessible Routes	Raise exhaust hood to min 80", or pad object to prevent hazard in overhead clearance along AR.	\$140.00	1	each	\$140.00	3
Seminole Palms Park	264	Concessions	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	5	each	\$1,050.00	1
Seminole Palms Park	265	Concessions	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
Seminole Palms Park	266	Concessions	Custom/Special	Consider providing picture on menu or provide material in a alternative format.	\$250.00	1	each	\$250.00	5
Seminole Palms Park	267	Concessions	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	3
Seminole Palms Park	268	Lap Pool	Accessible Routes	Correct or fill gaps to be max .5".  Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.	\$96.25	5	each	\$481.25	1
Seminole Palms Park	269	Lap Pool	Accessible Route - Slope (C)	In the alternative, leave as is citing constuction tolerance.	\$122.50	200	sq ft	\$24,500.00	4
Seminole Palms Park	270	Lap Pool	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48".	\$1,470.00	4	each	\$5,880.00	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	271	Lap Pool	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	272	Interactive Water Playground	Pool / Spa	Relocate pool lift to make it available every hour the pool is open.	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	273	Interactive Water Playground	Pool / Spa	Relocate lift to an area providing 36" X 48" CFS having max slope of 2.08%.	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	274	Interactive Water Playground	Pool / Spa	Correct pool stair treads to be min 11" deep and riser heights to be uniform if feasible.	\$404.25	6	each	\$2,425.50	2
Seminole Palms Park	275	Interactive Water Playground	Plumbing Fixtures & Elements	Add a high bowl fountain for standing persons. In the alternative, raise one of the existing fountains so spout is between 38" and 43" AGL.	\$5,598.25	1	each	\$5,598.25	2
Seminole Palms Park	276	Interactive Water Playground	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	277	Interactive Water Playground	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	4	each	\$12,250.00	2
Seminole Palms Park	278	Interactive Water Playground	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
Seminole Palms Park	279	Interactive Water Playground	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
Seminole Palms Park	280	Interactive Water Playground	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Seminole Palms Park	281	Interactive Water Playground	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	282	Interactive Water Playground	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground at one shower; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Seminole Palms Park	283	Interactive Water Playground	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	2
Seminole Palms Park	284	Interactive Water Playground	Play Area	Acquire and install intended user signage and mount at designated entry as a smart practice.	\$350.00	1	each	\$350.00	5
Seminole Palms Park	285	Interactive Water Playground	Play Area	Install compliant transfer system for access to elevated play elements.	\$5,800.00	1	each	\$5,800.00	3
Seminole Palms Park	287	Interactive Water Playground	Play Area	Provide another climber on the route having entry point of 11" to 24" AGL.	\$2,800.00	1	each	\$2,800.00	2
Seminole Palms Park	290	Interactive Water Playground	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	2
Seminole Palms Park	291	Water Slides	Signs	Relocate sign along an accessible route, unobstructed, and mount signage to be a min of 40" AGL (above ground level).	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	292	Water Slides	Accessible Route - Slope (C)	Correct running slopes to max 5%. Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	2
Seminole Palms Park	293	Water Slides	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	6	each	\$5,880.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	294	Water Slides	Accessible Route - Slope (C)	Correct running slopes to max 8.33%.  Install one handrail that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$21,455.00	1	each	\$21,455.00	3
Seminole Palms Park	295	Water Slides	Accessible Routes	Correct ramp landing slope to max 2.08%. For changes in level 6" or greater, provide a ramp for access.	\$6,510.00	1	each	\$6,510.00	3
Seminole Palms Park	296	River Ride	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	2
Seminole Palms Park	297	River Ride	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	2
Seminole Palms Park	298	River Ride	Accessible Routes	For changes in level 6" or greater, provide a ramp for access.  Pricing provided in a previous finding.	\$0.00	1	each	\$0.00	2
Seminole Palms Park	299	River Ride	Outdoor - Constructed Features (C)	Relocate accessible picnic tables to provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$0.00	1	staff time	\$0.00	5
Seminole Palms Park	300	River Ride	Pool / Spa	Provide a sloped entry into the river ride if feasible.	\$6,510.00	1	each	\$6,510.00	3
Seminole Palms Park	301	Employee Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Seminole Palms Park	302	Employee Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	303	Employee Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	304	Employee Restroom	Plumbing Fixtures & Elements	Fully insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Seminole Palms Park	305	Employee Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. Leave as is if installed prior to March 15, 2012 citing safe harbor.	\$175.00	2	each	\$350.00	1
Seminole Palms Park	306	Employee Restroom	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Seminole Palms Park	307	Employee Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	308	Employee Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	309	Employee Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	310	Employee Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove stored items from grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	311	Employee Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	312	Men's Locker Room/Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	313	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	2	each	\$420.00	1
Seminole Palms Park	314	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including access symbol where missing.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	315	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Replace one mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	316	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Lower sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	317	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Seminole Palms Park	318	Men's Locker Room/Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	319	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Seminole Palms Park	320	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Seminole Palms Park	321	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	322	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Remount side grab bars to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Seminole Palms Park	323	Men's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	324	Men's Locker Room/Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
Seminole Palms Park	325	Men's Locker Room/Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	2	each	\$6,125.00	1
Seminole Palms Park	326	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" AFF.	\$420.00	2	each	\$840.00	2
Seminole Palms Park	327	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	2	each	\$840.00	2
Seminole Palms Park	328	Men's Locker Room/Restroom	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	2
Seminole Palms Park	329	Men's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace one bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	330	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Seminole Palms Park	331	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Remount shower controls to the correct height in the transfer shower.	\$467.25	1	each	\$467.25	2
Seminole Palms Park	332	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Provide the required folding or non-folding seat in the transfer shower.	\$840.00	1	each	\$840.00	2
Seminole Palms Park	333	Men's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Seminole Palms Park	334	Men's Locker Room/Restroom	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	335	Men's Locker Room/Restroom	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	2	each	\$420.00	1
Seminole Palms Park	336	Family Restroom within Men's Locker Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	337	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	338	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Acquire and mount signage, including access symbol. Priced in previous finding.	\$0.00	1	each	\$0.00	1
Seminole Palms Park	339	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	340	Family Restroom within Men's Locker Room	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	341	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline. In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Seminole Palms Park	342	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	343	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	344	Family Restroom within Men's Locker Room	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	345	Family Restroom within Men's Locker Room	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	346	Family Restroom within Men's Locker Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.  Pricing for relocating hand dryer provided in a previous finding.	\$175.00	2	each	\$350.00	1
Seminole Palms Park	347	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.  Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	2	each	\$420.00	1
Seminole Palms Park	348	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
Seminole Palms Park	349	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Lower one sink to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Seminole Palms Park	350	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	351	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Seminole Palms Park	352	Women's Locker Room/Restroom	Reach Ranges	Lower hooks to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.  Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$87.50	4	each	\$350.00	1
Seminole Palms Park	353	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	354	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Seminole Palms Park	355	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Seminole Palms Park	356	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	357	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Relocate garbage to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	358	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	359	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	360	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	361	Women's Locker Room/Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	362	Women's Locker Room/Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	6	each	\$2,100.00	1
Seminole Palms Park	363	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice). Mount hooks and operating mechanisms max 48" aff.	\$420.00	4	each	\$1,680.00	2
Seminole Palms Park	364	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	4	each	\$1,680.00	2
Seminole Palms Park	365	Women's Locker Room/Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Seminole Palms Park	366	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Seminole Palms Park	367	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Provide the required folding or non-folding seat in the transfer shower.	\$840.00	1	each	\$840.00	2
Seminole Palms Park	368	Women's Locker Room/Restroom	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	2
Seminole Palms Park	369	Women's Locker Room/Restroom	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less.	\$0.00	1	staff time	\$0.00	2
Seminole Palms Park	370	Main Maintenance Building - Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Inspect, adjust, and maintain closing speed on door closers.	\$601.50	8	each	\$4,812.00	3
Seminole Palms Park	371	Main Maintenance Building - Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Seminole Palms Park	372	Main Maintenance Building - Employee Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances	\$1,120.00	1	each	\$1,120.00	3
Seminole Palms Park	373	Main Maintenance Building - Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	3
Seminole Palms Park	374	Main Maintenance Building - Shower	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	3
Seminole Palms Park	375	Main Maintenance Building - Shower	Plumbing Fixtures & Elements	Provide the required folding or non-folding seat in the transfer shower.	\$840.00	1	each	\$840.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	376	Main Maintenance Building - Shower	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	3
Seminole Palms Park	377	Main Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door. 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Seminole Palms Park	378	Main Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Seminole Palms Park	379	Main Maintenance Building - Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$116.50	3	each	\$349.50	1
Seminole Palms Park	380	Main Maintenance Building - Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	381	Main Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Relocate urinal to provide required 60" clearance around toilet. Leave as is if constructed before Marh 15, 2012 citing safe harbor.	\$2,380.00	1	each	\$2,380.00	2
Seminole Palms Park	382	Main Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	383	Main Maintenance Building - Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF), with 1.5" min spacing between bar and objects below.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remove stored objects on grab bar.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	384	Main Maintenance Building - Men's Restroom	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	385	Main Maintenance Building - Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Seminole Palms Park	386	Main Maintenance Building - Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  Pricing to relocate hand dryer in a previous finding.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	387	Main Maintenance Building - Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	388	Main Maintenance Building - Women's Restroom	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	389	Main Maintenance Building - Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	390	Main Maintenance Building - Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	391	Main Maintenance Building - Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$116.50	3	each	\$349.50	1
Seminole Palms Park	392	Main Maintenance Building - Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	393	Main Maintenance Building - Women's Restroom	Toilet and Bathing Rooms	Relocate garbage can and towel dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	394	Main Maintenance Building - Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	395	Main Maintenance Building - Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	396	Main Maintenance Building - Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Replace rear bar with a split bar to allow for existing plumbing.  Pricing provided in a previous finding.  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	397	Main Maintenance Building - Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Seminole Palms Park	398	Main Maintenance Building - Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Seminole Palms Park	399	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	400	Small Maintenance Building Near Water Park Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Seminole Palms Park	401	Small Maintenance Building Near Water Park Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$175.00	4	each	\$700.00	1
Seminole Palms Park	402	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Relocate cabinet and shelf to provide required 60" clearance around toilet.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Seminole Palms Park	403	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Seminole Palms Park	404	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	405	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Seminole Palms Park	406	Small Maintenance Building Near Water Park Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Seminole Palms Park	407	Small Maintenance Building Near Water Park Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
<u>South Bay RV Park</u>	2	Parking - Pavlion	Parking - Off Street	Relocate stalls to be on the shortest AR to the building entry or park features.	\$367.50	1	each	\$367.50	1
South Bay RV Park	3	Parking - Pavlion	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
South Bay RV Park	4	Parking - Pavlion	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls, including a van accessible sign.	\$210.00	1	each	\$210.00	1
South Bay RV Park	5	Parking - Pavlion	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
South Bay RV Park	6	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
South Bay RV Park	7	Exterior Accessible Route	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	2
South Bay RV Park	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
South Bay RV Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
South Bay RV Park	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
South Bay RV Park	11	Play Area at Camping near Levee Rd.	Accessible Routes	Create an AR to the play area within the site.  In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	15	lin ft	\$888.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	12	Play Area at Camping near Levee Rd.	Play Area	<p>Create designated entry by removing 36" portion of play area boundary as a smart practice.</p> <p>Provide designated entry min 36" wide that is free of CIL and gaps.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$700.00	1	each	\$700.00	4
South Bay RV Park	13	Play Area at Camping near Levee Rd.	Play Area	<p>Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70,000.00	1	each	\$70,000.00	4
South Bay RV Park	14	Play Area at Camping near Levee Rd.	Play Area	<p>Provide an AR to element for one of each type accessible. Price included in earlier findings.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$0.00	1	each	\$0.00	4
South Bay RV Park	15	Play Area at Entry	Play Area	<p>Repair, bevel or ramp CIL at playground entry/border.</p> <p>Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$7,000.00	1	each	\$7,000.00	4
South Bay RV Park	16	Play Area at Entry	Play Area	<p>Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$70,000.00	1	each	\$70,000.00	4
South Bay RV Park	17	Play Area at Entry	Play Area	<p>Lower platform on transfer system to 11" to 18" above ground level (AGL), in the alternative, add and maintain surface fill level to achieve the same.</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$0.00	1	staff time	\$0.00	4
South Bay RV Park	20	Play Area at Entry	Play Area	<p>Lower or adjust entry point to play component to 11" to 24" above ground level (AGL).</p> <p>In the alternative, leave as is and designate other County playgrounds accessible.</p>	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	22	Play Area at Entry	Outdoor - Constructed Features (C)	Resurface playground or construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$750.00	1	each	\$750.00	4
South Bay RV Park	23	Play Area at Camping near Shuffleboard	Accessible Routes	Create an accessible route (AR) to the play area within the site.  In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	15	lin ft	\$888.00	4
South Bay RV Park	24	Play Area at Camping near Shuffleboard	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.  Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
South Bay RV Park	25	Play Area at Camping near Shuffleboard	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
South Bay RV Park	26	Play Area at Camping near Shuffleboard	Play Area	Provide an AR to element for one of each type accessible. Price included in earlier findings.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
South Bay RV Park	27	Campsites	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	28	Campsites	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	29	Campsites	Accessible Routes	Widen AR to compliant 36" clear width.  Widen room to provide 60" turning space within.	\$1,540.00	2	each	\$3,080.00	1
South Bay RV Park	30	Campsites	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	2	each	\$2,198.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	31	Campsites	Room/Space (C)	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp, between 34" and 48" above the finished floor (AFF).	\$514.50	1	each	\$514.50	3
South Bay RV Park	32	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	33	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	34	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
South Bay RV Park	35	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice	\$950.00	1	each	\$950.00	5
South Bay RV Park	36	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	37	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
South Bay RV Park	38	Campsites	Camping (C)	Correct RV parking space to be 20' wide minimum; or a single spaces can be minimum 16' when two adjacent spaces are provided as a smart practice.	\$5,600.00	1	each	\$5,600.00	5
South Bay RV Park	39	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	40	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	41	Campsites	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and at least two fire rings.	\$59.20	100	lin ft	\$5,920.00	5
South Bay RV Park	42	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	43	Campsites	Camping (C)	Correct RV parking space to be 20' wide minimum; or a single spaces can be minimum 16' when two adjacent spaces are provided as a smart practice.	\$5,600.00	1	each	\$5,600.00	5
South Bay RV Park	44	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	45	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	46	Campsites	Camping (C)	Refer to corrections cited in findings for Site 158.	\$5,023.25	8	each	\$40,186.00	5
South Bay RV Park	47	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	48	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
South Bay RV Park	49	Campsites	Camping (C)	Correct RV parking space to be 20' wide minimum; or a single spaces can be minimum 16' when two adjacent spaces are provided as a smart practice.	\$5,600.00	1	each	\$5,600.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	50	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	51	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	52	Campsites	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.  Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted on both sides 34" to 38" above the finished floor (AFF).	\$8,470.00	1	each	\$8,470.00	3
South Bay RV Park	53	Campsites	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	150	lin ft	\$8,880.00	5
South Bay RV Park	54	Campsites	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and at least two fire rings.	\$59.20	100	lin ft	\$5,920.00	5
South Bay RV Park	55	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	56	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
South Bay RV Park	57	Campsites	Camping (C)	Correct RV parking space to be 20' wide minimum; or a single spaces can be minimum 16' when two adjacent spaces are provided as a smart practice.	\$5,600.00	1	each	\$5,600.00	5
South Bay RV Park	58	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	59	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	60	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	61	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5
South Bay RV Park	62	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	63	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	64	Campsites	Camping (C)	Refer to corrections cited in findings for Site 78.	\$5,023.25	3	each	\$15,069.75	5
South Bay RV Park	65	Campsites	Outdoor Recreation Access Route	Repair, bevel or ramp change in level (CIL) along ORAR.	\$96.25	1	each	\$96.25	5
South Bay RV Park	66	Campsites	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
South Bay RV Park	67	Campsites	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	1	each	\$2,486.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	68	Campsites	Camping (C)	Correct RV parking space to be 20' wide minimum; or a single spaces can be minimum 16' when two adjacent spaces are provided as a smart practice.	\$5,600.00	1	each	\$5,600.00	5
South Bay RV Park	69	Campsites	Outdoor - Constructed Features (C)	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice.	\$950.00	1	each	\$950.00	5
South Bay RV Park	70	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	71	Campsites	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	85	lin ft	\$5,032.00	5
South Bay RV Park	72	Campsites	Outdoor Recreation Access Routes (C)	Relocate benches to widen ORAR to min 36" clear width as a smart practice.	\$0.00	1	staff time	\$0.00	5
South Bay RV Park	73	Campsites	Outdoor - Constructed Features (C)	Provide required 48" clear ground space centered along usable side of fire ring, grill, fireplace, or woodstove as a smart practice.	\$0.00	1	staff time	\$0.00	5
South Bay RV Park	74	Campsites	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$350.00	1	each	\$350.00	5
South Bay RV Park	75	Campsites	Outdoor Constructed Feature	Provide ORAR and level clear ground space (CGS) for 20% of the grills in the area.	\$59.20	40	lin ft	\$2,368.00	5
South Bay RV Park	76	Campsites	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	55	lin ft	\$3,256.00	5
South Bay RV Park	77	Campsites	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	\$467.25	1	each	\$467.25	5
South Bay RV Park	78	Park Elements	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
South Bay RV Park	79	Pavilion	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	5
South Bay RV Park	80	Pavilion	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	110	sq ft	\$13,475.00	5
South Bay RV Park	81	Pavilion	Doors	Replace thresholds at doors with beveled ADA thresholds.  In the alternative, leave as is and designate other County shelters accessible.	\$253.75	1	each	\$253.75	4
South Bay RV Park	82	Pavilion	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  In the alternative, leave as is and designate other County shelters accessible.	\$350.00	1	each	\$350.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	83	Pavilion	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.  In the alternative, leave as is and designate other County shelters accessible.	\$210.00	1	each	\$210.00	4
South Bay RV Park	84	Pavilion	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4
South Bay RV Park	85	Pavilion	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	2	each	\$2,240.00	4
South Bay RV Park	86	Pavilion	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.  In the alternative, leave as is and designate other County shelters accessible.	\$514.50	2	each	\$1,029.00	4
South Bay RV Park	87	Pavilion	Accessible Routes	Raise light fixture to min 80", or pad object to prevent hazard in overhead clearance along accessible route (AR).  In the alternative, leave as is and designate other County shelters accessible.	\$350.00	1	each	\$350.00	4
South Bay RV Park	88	South Laundry Building	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
South Bay RV Park	89	South Laundry Building	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF.	\$2,380.00	1	each	\$2,380.00	2
South Bay RV Park	90	South Laundry Building	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	50	sq ft	\$6,125.00	1
South Bay RV Park	91	South Laundry Building	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	92	South Laundry Building	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	93	South Laundry Building	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
South Bay RV Park	94	South Laundry Building	Dining, Bar and Work Surfaces	Replace table with one providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
South Bay RV Park	95	North Laundry Bldg	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
South Bay RV Park	96	North Laundry Bldg	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	97	North Laundry Bldg	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated.	\$514.50	2	each	\$1,029.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	98	Men's Restroom and Shower South	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Pricing addressed in different finding.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$350.00	1	each	\$350.00	1
South Bay RV Park	99	Men's Restroom and Shower South	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
South Bay RV Park	100	Men's Restroom and Shower South	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
South Bay RV Park	101	Men's Restroom and Shower South	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	102	Men's Restroom and Shower South	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
South Bay RV Park	103	Men's Restroom and Shower South	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South Bay RV Park	104	Men's Restroom and Shower South	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	105	Men's Restroom and Shower South	Clear Floor Space	Relocate operable part to provide required 30" by 48" CFS.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	106	Men's Restroom and Shower South	Toilet and Bathing Rooms	Relocate sink and garbage bin to provide required 60" clearance around toilet.	\$1,190.00	2	each	\$2,380.00	1
South Bay RV Park	107	Men's Restroom and Shower South	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
South Bay RV Park	108	Men's Restroom and Shower South	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
South Bay RV Park	109	Men's Restroom and Shower South	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount soap dispenser 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	110	Men's Restroom and Shower South	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
South Bay RV Park	111	Men's Restroom and Shower South	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
South Bay RV Park	112	Men's Restroom and Shower South	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
South Bay RV Park	113	Men's Restroom and Shower South	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	114	Men's Restroom and Shower South	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
South Bay RV Park	115	Men's Restroom and Shower South	Plumbing Fixtures & Elements	Provide grab bars in the shower mounted in the correct locations for the shower type.	\$603.75	1	each	\$603.75	1
South Bay RV Park	116	Men's Restroom and Shower South	Plumbing Fixtures & Elements	Replace grab bars with ones providing 1.5" gap between bar and wall and mount so no objects interfere within 1.5" below and 12" above bar.	\$603.75	1	each	\$603.75	2
South Bay RV Park	117	Men's Restroom and Shower South	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	118	Women's Restroom and Shower South	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	119	Women's Restroom and Shower South	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	2
South Bay RV Park	120	Women's Restroom and Shower South	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
South Bay RV Park	121	Women's Restroom and Shower South	Plumbing Fixtures & Elements	Replace rear wall grab bar with one that is continuous, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
South Bay RV Park	122	Women's Restroom and Shower South	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
South Bay RV Park	123	Women's Restroom and Shower South	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
South Bay RV Park	124	Women's Restroom and Shower South	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	125	Women's Restroom and Shower South	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
South Bay RV Park	126	Women's Restroom and Shower South	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South Bay RV Park	127	Women's Restroom and Shower South	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).  Lower paper towel dispensers to max 48" above the finished floor (AFF) to highest operable part.  Lower soap dispenser to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$0.00	4	staff time	\$0.00	1
South Bay RV Park	128	Women's Restroom and Shower South	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	129	Women's Restroom and Shower South	Toilet and Bathing Rooms	Relocate garbage bin to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	130	Women's Restroom and Shower South	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	131	Women's Restroom and Shower South	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	132	Women's Restroom and Shower South	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount soap dispenser 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	133	Women's Restroom and Shower South	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
South Bay RV Park	134	Women's Restroom and Shower South	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
South Bay RV Park	135	Women's Restroom and Shower South	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
South Bay RV Park	136	Women's Restroom and Shower South	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
South Bay RV Park	137	Women's Restroom and Shower South	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
South Bay RV Park	138	Men's Restroom and Shower North	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
South Bay RV Park	139	Men's Restroom and Shower North	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
South Bay RV Park	140	Men's Restroom and Shower North	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	141	Men's Restroom and Shower North	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	142	Men's Restroom and Shower North	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	143	Men's Restroom and Shower North	Clear Floor Space	Relocate paper towel dispenser to a location where there is the required 30" by 48" CFS.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	144	Men's Restroom and Shower North	Toilet and Bathing Rooms	Relocate sink and garbage bin to provide required 60" clearance around toilet.	\$1,190.00	2	each	\$2,380.00	1
South Bay RV Park	145	Men's Restroom and Shower North	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
South Bay RV Park	146	Men's Restroom and Shower North	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	147	Men's Restroom and Shower North	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	148	Men's Restroom and Shower North	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount paper towel and soap dispensers to 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	3	staff time	\$0.00	1
South Bay RV Park	149	Men's Restroom and Shower North	Toilet and Bathing Rooms	Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
South Bay RV Park	150	Men's Restroom and Shower North	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
South Bay RV Park	151	Men's Restroom and Shower North	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
South Bay RV Park	152	Men's Restroom and Shower North	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	153	Men's Restroom and Shower North	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
South Bay RV Park	154	Men's Restroom and Shower North	Plumbing Fixtures & Elements	Install grab bars that are continuous along the length of the walls, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
South Bay RV Park	155	Men's Restroom and Shower North	Plumbing Fixtures & Elements	Replace grab bars with ones providing 1.5" gap between bar and wall and mount so no objects interfere within 1.5" below and 12" above bar.	\$603.75	2	each	\$1,207.50	2
South Bay RV Park	156	Men's Restroom and Shower North	Toilet and Bathing Rooms	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.  In the alternative, remount shower head to be 48" max above the finished floor (AFF)	\$540.75	1	each	\$540.75	2
South Bay RV Park	157	Men's Restroom and Shower North	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Price to relocate hand dryer addressed in previous finding.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	158	Men's Restroom and Shower North	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	159	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
South Bay RV Park	160	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
South Bay RV Park	161	Women's Restrooms and Shower North	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	162	Women's Restrooms and Shower North	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	163	Women's Restrooms and Shower North	Clear Floor Space	Relocate paper towel dispenser to a location where there is the required 30" by 48" CFS.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	164	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Relocate sink and garbage bin to provide required 60" clearance around toilet.	\$1,190.00	2	each	\$2,380.00	1
South Bay RV Park	165	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
South Bay RV Park	166	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	167	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
South Bay RV Park	168	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate paper towel and soap dispensers 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	3	staff time	\$0.00	1
South Bay RV Park	169	Women's Restrooms and Shower North	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
South Bay RV Park	170	Women's Restrooms and Shower North	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
South Bay RV Park	171	Women's Restrooms and Shower North	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	172	Women's Restrooms and Shower North	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. Price to remount hand dryer addressed in previous finding.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	173	Women's Restrooms and Shower North	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	174	Women's Restrooms and Shower North	Dressing / Fitting / Locker Rooms	Remount at least one hook to max 48" AFF and shelves to 40" - 48" AFF.	\$0.00	1	staff time	\$0.00	2
South Bay RV Park	175	Women's Restrooms and Shower North	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" above the finished floor (AFF) and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
South Bay RV Park	176	Women's Restrooms and Shower North	Plumbing Fixtures & Elements	Install grab bars that are continuous along the length of the walls, mounted 33" to 36" AFF and max 6" from adjacent walls.	\$393.75	1	each	\$393.75	2
South Bay RV Park	177	Women's Restrooms and Shower North	Plumbing Fixtures & Elements	Replace grab bars with ones providing 1.5" gap between bar and wall and mount so no objects interfere within 1.5" below and 12" above bar.	\$603.75	2	each	\$1,207.50	2
South Bay RV Park	178	Women's Restrooms and Shower North	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
South Bay RV Park	180	Parking and Exterior Accessible Route	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
South Bay RV Park	181	Parking and Exterior Accessible Route	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
South Bay RV Park	182	Parking and Exterior Accessible Route	Curb Ramps	Correct curb ramp running slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
South Bay RV Park	183	Parking and Exterior Accessible Route	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
South Bay RV Park	184	Parking and Exterior Accessible Route	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	2	each	\$147.00	1
South Bay RV Park	186	Parking and Exterior Accessible Route	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
South Bay RV Park	187	Public Spaces	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	188	Public Spaces	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	2	staff time	\$0.00	1
South Bay RV Park	189	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
South Bay RV Park	190	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	192	Public Spaces	Clear Floor Space	Provide an outlet over lowered portion of kitchen counter.	\$3,479.00	1	each	\$3,479.00	1
South Bay RV Park	193	Public Spaces	Reach Ranges	Lower operating mechanisms to max 46" above the finished floor (AFF) for a side reach over sink or counter.	\$350.00	1	each	\$350.00	1
South Bay RV Park	194	Public Spaces	Dining, Bar and Work Surfaces	Lower counter height to max 34" above the finished floor (AFF).	\$1,099.00	1	each	\$1,099.00	1
South Bay RV Park	195	Employee Spaces	Custom/Special	If facility is made available for public use in the future, ensure site is fully compliant and if made available for employee use, ensure compliant approach, entry, and exit of the facility.	\$0.00	1	staff time	\$0.00	3
South Bay RV Park	196	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
South Bay RV Park	197	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
South Bay RV Park	198	Men's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	199	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
South Bay RV Park	200	Men's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.  Raise mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$175.00	2	each	\$350.00	1
South Bay RV Park	201	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	202	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	203	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	204	Men's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
South Bay RV Park	205	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
South Bay RV Park	206	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	207	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	208	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.  Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$175.00	2	each	\$350.00	1
South Bay RV Park	209	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	210	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	211	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	212	Women's Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
South Bay RV Park	213	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	214	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	215	Women's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	216	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
South Bay RV Park	217	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	218	Trail Surface	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice.	\$59.20	700	lin ft	\$41,440.00	5
South Bay RV Park	219	Trail Surface	Outdoor - Trails (C)	Correct or repair running slope along trail to max 10% for 30 ft max, with resting intervals at each end.	\$875.00	1	each	\$875.00	5
South Bay RV Park	220	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	125	sq ft	\$15,312.50	5
South Bay RV Park	221	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
South Bay RV Park	222	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	350	sq ft	\$42,875.00	5
South Bay RV Park	223	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
South Bay RV Park	224	Trail Surface	Outdoor - Trails (C)	Repair, bevel or ramp tread obstacle along pathway to max .5" as a smart practice.	\$59.20	20	lin ft	\$1,184.00	5
South Bay RV Park	225	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
South Bay RV Park	226	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	200	sq ft	\$24,500.00	5
South Bay RV Park	227	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	300	sq ft	\$36,750.00	5
South Bay RV Park	228	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	50	sq ft	\$6,125.00	5
South Bay RV Park	229	Trail Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	500	sq ft	\$61,250.00	5
South Bay RV Park	230	Trail Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
South Bay RV Park	231	Trail Elements	Accessible Routes	Relocate 20% of dog waste bag dispensers to be along AR.	\$0.00	1	staff time	\$0.00	2
South Bay RV Park	233	Standard-sized Vehicle Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
South Bay RV Park	234	Standard-sized Vehicle Parking	Parking - Off Street	Add van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'. Pricing for restriping access aisle in a previous finding.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Bay RV Park	235	Standard-sized Vehicle Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
South Bay RV Park	236	Standard-sized Vehicle Parking	Parking - Off Street	Widen accessible route to min 44" clear width and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
South Bay RV Park	238	Oversized Vehicle/Boat Ramp Trailer Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
South Bay RV Park	239	Oversized Vehicle/Boat Ramp Trailer Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
South Bay RV Park	240	Oversized Vehicle/Boat Ramp Trailer Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
South Bay RV Park	241	Oversized Vehicle/Boat Ramp Trailer Parking	Parking - Off Street	Widen accessible route to min 44" clear width and assure connection to access aisle.	\$1,487.50	1	each	\$1,487.50	1
South Bay RV Park	242	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	3
South Bay RV Park	243	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp cross slope to max 2.08%.	\$6,510.00	4	each	\$26,040.00	3
South Bay RV Park	244	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct ramp landing slope to max 2.08%.	\$875.00	5	each	\$4,375.00	3
South Bay RV Park	245	Exterior Accessible Route	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" above ground level (AGL).	\$350.00	1	each	\$350.00	3
South Bay RV Park	246	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
South Bay RV Park	247	Exterior Accessible Route	Ramps (Not Curb Ramps)	Replace handrails with ones having a smooth surface.	\$980.00	1	each	\$980.00	3
South Bay RV Park	248	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through.	\$525.00	46	each	\$24,150.00	3
South Bay RV Park	249	Park Site	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$2,486.00	1	each	\$2,486.00	4
South Bay RV Park	251	Park Site	Accessible Routes	Relocate 20% of garbage cans to be along accessible route (AR) and 48" max above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
South Bay RV Park	252	Park Site	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
South Bay RV Park	253	Boat Ramps	Accessible Routes	Widen AR to one of the boarding piers to min 36".  Correct or repair slopes of one boarding pier to max 5% running and 2.08% cross.  In the alternative, leave as is and designate other County boat ramps accessible.	\$6,510.00	3	each	\$19,530.00	4
South County Civic Center	2	Parking - North Lot	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
South County Civic Center	3	Parking - North Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	4	Parking - North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	9	each	\$27,562.50	1
South County Civic Center	5	Parking - North Lot	Parking - Off Street	Correct or fill gap to max .5"	\$96.25	1	each	\$96.25	1
South County Civic Center	6	Parking - North Lot	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
South County Civic Center	7	Parking - North Lot	Parking - Off Street	Repaint access aisle border using a high quality paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
South County Civic Center	8	Parking - South Lot	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
South County Civic Center	9	Parking - South Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
South County Civic Center	10	Parking - South Lot	Accessible Routes	Mount signage to prohibit cars from parking and obstructing accessible route.  Relocate parking and stripe a no parking zone at entry to AR to prevent cars from blocking AR.	\$283.50	1	each	\$283.50	1
South County Civic Center	11	Parking - South Lot	Parking - Off Street	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 12' and 5'.  Pricing for restriping access aisle provided in a previous finding.	\$210.00	1	each	\$210.00	1
South County Civic Center	12	Parking - South Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
South County Civic Center	13	Parking - South Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.  Pricing for restriping access aisle provided in a previous finding.	\$73.50	1	each	\$73.50	1
South County Civic Center	14	Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,487.50	1	each	\$1,487.50	1
South County Civic Center	15	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
South County Civic Center	16	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
South County Civic Center	17	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
South County Civic Center	18	Exterior Accessible Route	Parking - Off Street	Designate an access aisle for the passenger drop off area by painting an aisle that is 60" wide and 20' long.	\$73.50	1	each	\$73.50	1
South County Civic Center	19	Exterior Accessible Route	Detectable Warnings	Replace detectable warning with one that contrasts light on dark or dark on light.	\$329.00	2	each	\$658.00	5
South County Civic Center	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5"	\$96.25	1	each	\$96.25	1
South County Civic Center	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	125	sq ft	\$15,312.50	1
South County Civic Center	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
South County Civic Center	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	24	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
South County Civic Center	25	Exterior Elements	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table.	\$1,120.00	1	each	\$1,120.00	5
South County Civic Center	27	Public Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$1,750.00	1	each	\$1,750.00	1
South County Civic Center	28	Public Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$1,750.00	1	each	\$1,750.00	1
South County Civic Center	29	Public Rooms	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	32	Employee Rooms	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
South County Civic Center	35	Employee Rooms	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
South County Civic Center	36	Employee Rooms	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	38	Offices	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
South County Civic Center	40	Offices	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
South County Civic Center	41	Offices	Turning Space	Relocate obstacles to create turning space in break room.	\$0.00	1	staff time	\$0.00	3
South County Civic Center	42	Offices	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	3
South County Civic Center	43	Offices	Reach Ranges	Remount first aide box to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
South County Civic Center	44	Offices	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	3
South County Civic Center	45	Offices	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
South County Civic Center	46	Offices	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
South County Civic Center	47	Offices	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, mounted on the wall on the latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
South County Civic Center	48	Offices	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,500.00	1	each	\$3,500.00	1
South County Civic Center	49	Offices	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	50	Assembly Area	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.	\$5,835.00	1	each	\$5,835.00	1
South County Civic Center	51	Assembly Area	Doors	Relocate storage, furniture and other obstacles to create maneuvering clearance on pull side of door.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	52	Assembly Area	Assembly Areas	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats, base off the number of seats set up for each event.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	53	Assembly Area	Assembly Areas	Ensure wheelchair seating provides line of sight over standing spectators or other seats as needed, depending on how the seating is arranged for each event.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	54	Assembly Area	Assembly Areas	Provide signage informing patrons of the availability of assistive listening systems.	\$210.00	2	each	\$420.00	1
South County Civic Center	55	Assembly Area	Assembly Areas	Create an accessible route connecting assembly seating directly to performance area.	\$6,510.00	1	each	\$6,510.00	1
South County Civic Center	56	Assembly Area	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	4	each	\$3,920.00	1
South County Civic Center	57	Assembly Area	Stairways	Replace or remount handrails to 34" to 38" AFF.	\$350.00	4	each	\$1,400.00	1
South County Civic Center	58	Assembly Area	Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds.	\$253.75	2	each	\$507.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	59	Assembly Area	Doors	<p>For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$2,772.50	1	each	\$2,772.50	1
South County Civic Center	60	Assembly Area	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$0.00	1	staff time	\$0.00	1
South County Civic Center	61	Assembly Area	Doors	<p>For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$2,772.50	1	each	\$2,772.50	1
South County Civic Center	62	Assembly Area	Doors	<p>For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$2,772.50	1	each	\$2,772.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	63	Assembly Area	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$4,522.50	1	each	\$4,522.50	1
South County Civic Center	64	Assembly Area	Doors	<p>For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$2,772.50	1	each	\$2,772.50	1
South County Civic Center	65	Men's Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$1,750.00	1	each	\$1,750.00	1
South County Civic Center	66	Men's Restroom	Plumbing Fixtures & Elements	<p>Replace one sink with one providing 27" knee clearance that is a min 8" deep.</p> <p>Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.</p>	\$4,436.25	1	each	\$4,436.25	1
South County Civic Center	67	Men's Restroom	Toilet and Bathing Rooms	Relocate items to provide CFS with knee and toe clearance under sink.	\$4,436.25	1	each	\$4,436.25	1
South County Civic Center	68	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South County Civic Center	69	Men's Restroom	Reach Ranges	Remount one paper towel dispenser to be in reach range of 15" min to 48" max.	\$0.00	1	each	\$0.00	1
South County Civic Center	70	Men's Restroom	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	1
South County Civic Center	71	Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	72	Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
South County Civic Center	73	Men's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Replace or adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$840.00	1	each	\$840.00	1
South County Civic Center	74	Men's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
South County Civic Center	75	Men's Restroom	Toilet and Bathing Rooms	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
South County Civic Center	76	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	77	Men's Restroom	Toilet and Bathing Rooms	Relocate baby changing table to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
South County Civic Center	78	Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
South County Civic Center	79	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
South County Civic Center	80	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
South County Civic Center	81	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Pricing provided in a previous finding.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	82	Men's Restroom	Toilet and Bathing Rooms	Relocate toilet seat cover dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	83	Men's Restroom	Plumbing Fixtures & Elements	Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	84	Men's Restroom	Toilet and Bathing Rooms	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
South County Civic Center	85	Men's Restroom	Accessible Routes	Remount one toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	86	Women's Restroom	Doors	Correct or repair slope to max 2.08% in restroom.  For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$3,062.50	1	each	\$3,062.50	1
South County Civic Center	86	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$1,750.00	1	each	\$1,750.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	87	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	88	Women's Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
South County Civic Center	89	Women's Restroom	Toilet and Bathing Rooms	Install compliant sink in wheelchair accessible toilet stall unless doing so would reduce the required clearance at the toilet.	\$4,436.25	1	each	\$4,436.25	1
South County Civic Center	90	Women's Restroom	Plumbing Fixtures & Elements	Remount sink in main area providing 27" knee clearance that is a min 8" deep.	\$4,436.25	2	each	\$8,872.50	1
South County Civic Center	91	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South County Civic Center	92	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	93	Women's Restroom	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).  Lower toilet seat cover dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	2	staff time	\$0.00	1
South County Civic Center	94	Women's Restroom	Reach Ranges	Lower paper towel dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	95	Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
South County Civic Center	96	Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
South County Civic Center	97	Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees.  Replace or adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
South County Civic Center	98	Women's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
South County Civic Center	99	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
South County Civic Center	100	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser a max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount trash container 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
South County Civic Center	101	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	102	Women's Restroom	Toilet and Bathing Rooms	Relocate sink, soap dispenser, and paper towel dispenser to provide required 60" clearance around toilet.	\$2,730.00	1	each	\$2,730.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	103	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount seat cover dispenser 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$196.75	2	each	\$393.50	1
South County Civic Center	104	Women's Restroom	Toilet and Bathing Rooms	Replace or adjust stall door of accessible stall with one that is self-closing.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	105	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
South County Civic Center	106	Kitchen	Kitchens, Kitchenettes, And Wet Bars	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	\$3,360.00	1	each	\$3,360.00	1
South County Civic Center	107	Kitchen	Kitchens, Kitchenettes, And Wet Bars	Lower 50% of shelving, or relocate supplies to within reach range, max 48" AFF.	\$700.00	1	each	\$700.00	1
South County Civic Center	108	Kitchen	Kitchens, Kitchenettes, And Wet Bars	Remove base cabinet.	\$1,099.00	2	each	\$2,198.00	1
South County Civic Center	109	Kitchen	Accessible Routes	Relocate hand cart to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	110	Kitchen	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	111	Kitchen	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$210.00	5	each	\$1,050.00	1
South County Civic Center	112	Kitchen	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$2,964.50	1	each	\$2,964.50	1
South County Civic Center	113	Kitchen	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$2,772.50	1	each	\$2,772.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	115	Interior Accessible Route	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
South County Civic Center	116	Interior Accessible Route	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,405.25	1	each	\$1,405.25	1
South County Civic Center	117	Interior Accessible Route	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1
South County Civic Center	118	Interior Accessible Route	Accessible Routes	Remove door stops to prevent trip hazard.	\$0.00	11	staff time	\$0.00	1
South County Civic Center	119	Interior Accessible Route	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
South County Civic Center	120	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	10	each	\$3,500.00	1
South County Civic Center	121	Interior Accessible Route	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
South County Civic Center	122	Interior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
South County Civic Center	123	Interior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$3,136.00	1	each	\$3,136.00	1
South County Civic Center	124	Interior Accessible Route	Reach Ranges	Remount light switches to be in reach range of 15" min to 48" max.	\$350.00	4	each	\$1,400.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	125	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$1,309.00	1	each	\$1,309.00	1
South County Civic Center	126	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$4,564.00	1	each	\$4,564.00	1
South County Civic Center	127	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$4,467.75	1	each	\$4,467.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South County Civic Center	128	Interior Accessible Route	Doors	Mount signage at entrance designating it as accessible.	\$210.00	4	each	\$840.00	1
South County Civic Center	129	Interior Accessible Route	Signs	Mount compliant permanent space signage at all applicable locations.	\$210.00	9	each	\$1,890.00	1
South County Civic Center	130	Interior Accessible Route	Signs	Replace Braille on sign and place Braille below the entire text, Braille shall not be broken up by line.	\$210.00	4	each	\$840.00	1
South County Civic Center	131	Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	6	staff time	\$0.00	1
South County Civic Center	132	Interior Accessible Route	Signs	Replace sign with one having pictogram field of min 6" high.	\$210.00	2	each	\$420.00	1
South County Civic Center	133	Interior Accessible Route	Signs	Remount signage at all permanent rooms/spaces to proper location based on the type of door.	\$0.00	11	staff time	\$0.00	1
South County Civic Center	134	Interior Accessible Route	Plumbing Fixtures & Elements	Remount or replace fountain to provide 15" from vertical support to the spout.	\$2,380.00	1	each	\$2,380.00	2
South County Civic Center	135	Interior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
South County Civic Center	136	Ramps	Ramps (Not Curb Ramps)	Provide landings min 60" by 60" at turns.	\$875.00	2	each	\$1,750.00	3
South County Civic Center	137	Ramps	Ramps (Not Curb Ramps)	Enlarge landing to be 60" deep and as wide as the ramp.	\$875.00	1	each	\$875.00	3
South County Civic Center	138	Ramps	Ramps (Not Curb Ramps)	Relocate storage and replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	1	each	\$980.00	3
South Inlet Park	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
South Inlet Park	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
South Inlet Park	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
South Inlet Park	4	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$210.00	1	each	\$210.00	1
South Inlet Park	5	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	1	each	\$96.25	5
South Inlet Park	6	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	25	each	\$2,406.25	5
South Inlet Park	7	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice	\$122.50	50	sq ft	\$6,125.00	5
South Inlet Park	8	Exterior Accessible Route	Accessible Routes	Maintain route to be free of sand and debris.	\$0.00	1	staff time	\$0.00	1
South Inlet Park	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	375	sq ft	\$45,937.50	1
South Inlet Park	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5" .	\$96.25	4	each	\$385.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Inlet Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	600	sq ft	\$73,500.00	1
South Inlet Park	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	3	each	\$9,187.50	1
South Inlet Park	13	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice.	\$122.50	150	sq ft	\$18,375.00	5
South Inlet Park	14	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or repair pathway running slope along AR to max 5% for any distance, 8.33% for 50' or 10% for 30' with level resting areas as a smart practice.	\$122.50	60	sq ft	\$7,350.00	1
South Inlet Park	15	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	28	each	\$2,695.00	5
South Inlet Park	16	Exterior Accessible Route	Ramps (Not Curb Ramps)	Install handrails that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" AFF.	\$980.00	2	each	\$1,960.00	1
South Inlet Park	17	Exterior Accessible Route	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%. See previous finding for handrail recommendation.	\$6,510.00	1	each	\$6,510.00	1
South Inlet Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
South Inlet Park	19	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
South Inlet Park	20	Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
South Inlet Park	21	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South Inlet Park	22	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
South Inlet Park	23	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
South Inlet Park	24	Men's Restroom	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
South Inlet Park	25	Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
South Inlet Park	26	Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
South Inlet Park	27	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
South Inlet Park	28	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
South Inlet Park	29	Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Inlet Park	30	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
				For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.					
				For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.					
				For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.					
				For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.					
South Inlet Park	31	Men's Restroom	Doors		\$3,062.50	1	each	\$3,062.50	1
South Inlet Park	32	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
South Inlet Park	33	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
South Inlet Park	34	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
South Inlet Park	35	Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
South Inlet Park	36	Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
South Inlet Park	37	Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls, or 16" to 18" in new wheelchair stall.	\$1,828.40	1	each	\$1,828.40	1
South Inlet Park	38	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
South Inlet Park	39	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
South Inlet Park	40	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
South Inlet Park	41	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
South Inlet Park	42	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Inlet Park	43	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
South Inlet Park	44	Play Area (5-12)	Play Area	Repair, bevel or ramp CIL at playground entry/border.  Correct slope at entry to max 5% running.	\$700.00	1	each	\$700.00	2
South Inlet Park	45	Play Area (5-12)	Play Area	Consider adding a second transfer system as a smart practice	\$2,800.00	1	each	\$2,800.00	5
South Inlet Park	51	Park Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
South Inlet Park	52	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site and lower to be within reach range of max 48" AGL.	\$59.20	15	lin ft	\$888.00	2
South Inlet Park	53	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	25	lin ft	\$1,480.00	2
South Inlet Park	54	Park Element	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	60	lin ft	\$3,552.00	2
South Inlet Park	55	Park Element	ATM's and Fare Machines	Contact provider to replace ATM with compliant models.	\$0.00	3	each	\$0.00	1
South Inlet Park	56	Park Element	ATM's and Fare Machines	Replace ATM or fare machine with one that has compliant features. See previous finding.	\$0.00	3	each	\$0.00	1
South Inlet Park	57	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	1
South Inlet Park	58	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%	\$122.50	12	sq ft	\$1,470.00	1
South Inlet Park	59	Park Element	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	12	sq ft	\$1,470.00	1
South Inlet Park	60	Park Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
South Inlet Park	61	Park Element	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	2	each	\$1,081.50	5
South Inlet Park	62	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
South Inlet Park	63	Park Element	Plumbing Fixtures & Elements	Replace fountain with one that provides required knee and toe clearance.	\$2,380.00	1	each	\$2,380.00	2
South Inlet Park	64	Park Element	Plumbing Fixtures & Elements	See previous finding for recommendation.	\$0.00	1	each	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Inlet Park	66	Park Element	Clear Floor Space	Maintain 30" by 48" CFS at operable parts to be free of sand overflow.	\$0.00	1	staff time	\$0.00	2
South Inlet Park	68	Park Element	Reach Ranges	Remount at least two garbage cans to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	2
South Inlet Park	69	Picnic Areas	Shelters, Picnic Facilities (C)	Replace or correct surface to be firm and stable or maintain to be same.	\$59.20	50	lin ft	\$2,960.00	5
South Inlet Park	70	Picnic Areas	Accessible Routes	Maintain overhead clearance of min. 80".	\$0.00	1	staff time	\$0.00	5
South Inlet Park	71	Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	3	each	\$7,458.00	5
South Inlet Park	72	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter accessible features as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5
South Inlet Park	73	Picnic Areas	Shelters/Picnic Areas (C)	Lower at least two garbage cans to be in reach range of max 48" AGL.	\$0.00	2	staff time	\$0.00	2
South Inlet Park	74	Eshleman Pavilion	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
South Inlet Park	75	Eshleman Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	10	each	\$962.50	5
South Inlet Park	76	Eshleman Pavilion	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
South Inlet Park	77	Eshleman Pavilion	Shelters/Picnic Areas (C)	Lower at least one garbage can to be in reach range of max 48" AGL.	\$0.00	1	staff time	\$0.00	2
South Inlet Park	78	Beach	Beach Access Route (C)	Create a beach access route to mean high water level level at one access point using a firm and stable material as a smart practice.	\$59.20	375	lin ft	\$22,200.00	5
South Inlet Park	79	Beach	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to elements.	\$59.20	150	lin ft	\$8,880.00	5
South Inlet Park	80	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	3
South Inlet Park	81	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, provide beveled threshold.	\$3,026.25	1	each	\$3,026.25	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
South Inlet Park	82	Employee Spaces	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	2
South Inlet Park	84	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width. Leave as is guard tower - exempt space due to the essential function.	\$2,772.50	1	each	\$2,772.50	3
South Inlet Park	85	Employee Spaces	Room/Space (C)		\$0.00	1	each	\$0.00	4
Southwinds Golf Course	2	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	3	each	\$220.50	1
Southwinds Golf Course	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	1	each	\$3,062.50	1
Southwinds Golf Course	4	Parking	Parking - Off Street	Resurface access aisles to eliminate deterioration.	\$2,800.00	1	each	\$2,800.00	1
Southwinds Golf Course	5	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	5	each	\$367.50	1
Southwinds Golf Course	6	Maintenance Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Southwinds Golf Course	7	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Southwinds Golf Course	8	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Southwinds Golf Course	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Southwinds Golf Course	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Southwinds Golf Course	11	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Southwinds Golf Course	12	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Southwinds Golf Course	13	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Southwinds Golf Course	14	Exterior Accessible Route	Passenger Loading Zones	Paint access aisles to be 5' wide and the length of pull-up space using high quality paint.	\$73.50	1	each	\$73.50	1
Southwinds Golf Course	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Southwinds Golf Course	18	Golf Course	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is citing safe harbor.	\$350.00	1	each	\$350.00	4
Southwinds Golf Course	20	Park Element	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	17	each	\$3,570.00	2
Southwinds Golf Course	21	Park Element	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	4	each	\$840.00	2
Southwinds Golf Course	22	Park Element	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	23	Park Element	Operable Parts	Replace cup dispense with one usable without a tight pinch or grasp.	\$210.00	4	each	\$840.00	2
Southwinds Golf Course	24	Park Element	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$1,470.00	1	each	\$1,470.00	5
Southwinds Golf Course	25	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Southwinds Golf Course	26	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Southwinds Golf Course	27	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Southwinds Golf Course	28	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	2
Southwinds Golf Course	29	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	2
Southwinds Golf Course	31	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max. In the alternative, leave as is citing safe harbor if built prior to March 15, 2012.	\$350.00	1	each	\$350.00	3
Southwinds Golf Course	32	Public Spaces	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	33	Public Spaces	Dressing / Fitting / Locker Rooms	Remount hook to max 48" AFF.	\$0.00	1	staff time	\$0.00	2
Southwinds Golf Course	34	Public Spaces	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Southwinds Golf Course	35	Public Spaces	Doors	Mount signage at entrances designating them as accessible.	\$210.00	3	each	\$630.00	1
Southwinds Golf Course	36	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Southwinds Golf Course	37	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Southwinds Golf Course	38	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	2	each	\$280.00	1
Southwinds Golf Course	39	Public Spaces	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	3	each	\$630.00	1
Southwinds Golf Course	40	Public Spaces	Accessible Routes	Relocate storage from lowered section of service counter.	\$0.00	1	staff time	\$0.00	2
Southwinds Golf Course	41	Public Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.  Lower 5% of bar seating areas to max 34" with knee and toe clearance.	\$1,120.00	2	each	\$2,240.00	2
Southwinds Golf Course	42	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Southwinds Golf Course	43	Public Spaces	Doors	Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Southwinds Golf Course	44	Public Spaces	Accessible Routes	Relocate or reposition practice tent to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	45	Public Spaces	Accessible Routes	Replace mat or carpet with one having max pile or edge of 1/4".	\$140.00	1	each	\$140.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	46	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$2,912.50	2	each	\$5,825.00	1
Southwinds Golf Course	47	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$995.75	1	each	\$995.75	1
Southwinds Golf Course	48	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$2,404.50	1	each	\$2,404.50	1
Southwinds Golf Course	49	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p>	\$5,037.00	1	each	\$5,037.00	1
Southwinds Golf Course	50	Public Spaces	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	51	Public Spaces	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	52	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	20	staff time	\$0.00	1
Southwinds Golf Course	54	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
Southwinds Golf Course	56	Employee Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Southwinds Golf Course	57	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3
Southwinds Golf Course	58	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Provide kick plate on push side of door from floor to 10" AFF.	\$140.00	1	each	\$140.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	59	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	3
Southwinds Golf Course	60	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$5,412.50	1	each	\$5,412.50	3
Southwinds Golf Course	61	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	62	Employee Spaces	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	63	Clubhouse Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	64	Clubhouse Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Southwinds Golf Course	65	Clubhouse Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Southwinds Golf Course	66	Clubhouse Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Southwinds Golf Course	67	Clubhouse Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	68	Clubhouse Men's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).  Adjust stall door to be self-closing.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	69	Clubhouse Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	70	Clubhouse Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Southwinds Golf Course	71	Clubhouse Men's Restroom	Accessible Routes	Raise partition horizontal support bars to min 80", or pad object to prevent hazard in overhead clearance along AR.	\$140.00	1	each	\$140.00	1
Southwinds Golf Course	72	Clubhouse Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	73	Clubhouse Men's Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Southwinds Golf Course	74	Clubhouse Women's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	each	\$0.00	1
Southwinds Golf Course	75	Clubhouse Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Southwinds Golf Course	76	Clubhouse Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	\$393.75	2	each	\$787.50	1
Southwinds Golf Course	77	Clubhouse Women's Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser to widen AR to stall to min 42" clear width.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	78	Clubhouse Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	79	Clubhouse Women's Restroom	Hazards	Relocate protruding objects or place cane detectable	\$350.00	1	each	\$350.00	1
Southwinds Golf Course	80	Clubhouse Women's Restroom	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Southwinds Golf Course	81	Men's Locker Room/Restroom At Maintenance	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	82	Men's Locker Room/Restroom At Maintenance	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character. Remount signage to the proper location based on the type of door provided.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	83	Men's Locker Room/Restroom At Maintenance	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice).	\$420.00	1	each	\$420.00	3
Southwinds Golf Course	84	Men's Locker Room/Restroom At Maintenance	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	3
Southwinds Golf Course	85	Men's Locker Room/Restroom At Maintenance	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Southwinds Golf Course	86	Men's Locker Room/Restroom At Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	87	Women's Locker Room/Restroom At Maintenance	Signs	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	88	Women's Locker Room/Restroom At Maintenance	Plumbing Fixtures & Elements	Create an accessible shower in locker/bathing room.	\$5,498.50	1	each	\$5,498.50	3
Southwinds Golf Course	89	Women's Locker Room/Restroom At Maintenance	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$3,500.00	1	each	\$3,500.00	3
				For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.					
				For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.					
				For all doors/gates along the public circulation route, provide beveled threshold.					
Southwinds Golf Course	90	Women's Locker Room/Restroom At Maintenance	Doors	For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$4,345.25	1	each	\$4,345.25	3
Southwinds Golf Course	91	Course Restroom Near Hole 1 Green - Men's	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	92	Course Restroom Near Hole 1 Green - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Southwinds Golf Course	93	Course Restroom Near Hole 1 Green - Men's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	94	Course Restroom Near Hole 1 Green - Men's	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	95	Course Restroom Near Hole 1 Green - Men's	Toilet and Bathing Rooms	Provide min 12" clear above and min 1.5" clear below grab bars if feasible.	\$350.00	1	each	\$350.00	1
Southwinds Golf Course	96	Course Restroom Near Hole 1 Green - Men's	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
				For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.					
Southwinds Golf Course	97	Course Restroom Near Hole 1 Green - Men's	Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	98	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Southwinds Golf Course	99	Course Restroom Near Hole 1 Green - Women's	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	100	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	101	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Southwinds Golf Course	102	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	103	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	104	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Provide min 12" clear above and min 1.5" clear below grab bars if feasible.	\$350.00	1	each	\$350.00	1
Southwinds Golf Course	105	Course Restroom Near Hole 1 Green - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	106	Course Restroom Near Hole 1 Green - Women's	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Southwinds Golf Course	107	Course Restroom Near Hole 1 Green - Women's	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	108	Course Restroom Near Hole 6 Tee Boxes - Men's	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	109	Course Restroom Near Hole 6 Tee Boxes - Men's	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	110	Course Restroom Near Hole 6 Tee Boxes - Men's	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	111	Course Restroom Near Hole 6 Tee Boxes - Men's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Southwinds Golf Course	112	Course Restroom Near Hole 6 Tee Boxes - Men's	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	113	Course Restroom Near Hole 6 Tee Boxes - Men's	Toilet and Bathing Rooms	Provide min 12" clear above and min 1.5" clear below grab bars if feasible.	\$350.00	1	each	\$350.00	1
Southwinds Golf Course	114	Course Restroom Near Hole 6 Tee Boxes - Men's	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Southwinds Golf Course	115	Course Restroom Near Hole 6 Tee Boxes - Men's	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	116	Course Restroom Near Hole 6 Tee Boxes - Women's	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	117	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	118	Course Restroom Near Hole 6 Tee Boxes - Women's	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	119	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	120	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Southwinds Golf Course	121	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Southwinds Golf Course	122	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Provide min 12" clear above and min 1.5" clear below grab bars if feasible.	\$350.00	1	each	\$350.00	1
Southwinds Golf Course	123	Course Restroom Near Hole 6 Tee Boxes - Women's	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Southwinds Golf Course	124	Course Restroom Near Hole 6 Tee Boxes - Women's	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	2	each	\$700.00	1
Southwinds Golf Course	125	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$3,577.00	1	each	\$3,577.00	3
Southwinds Golf Course	126	Employee Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" min and 48" max.	\$610.75	1	each	\$610.75	3
Southwinds Golf Course	127	Employee Spaces	Accessible Routes	Relocate equipment to create an AR to door within the site.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	128	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	129	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3
Southwinds Golf Course	130	Employee Spaces	Room/Space (C)	Make corrections for compliant 36" wide circulation path.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	131	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	3
Southwinds Golf Course	132	Employee Spaces	Accessible Routes	Raise light fixture to min 80" along AR.	\$350.00	1	each	\$350.00	3
Southwinds Golf Course	133	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	134	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	135	Employee Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
Southwinds Golf Course	136	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,900.50	1	each	\$1,900.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Southwinds Golf Course	137	Employee Spaces	Doors	Provide required maneuvering clearance on push side of door  Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	138	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3
Southwinds Golf Course	139	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$192.50	1	each	\$192.50	3
Southwinds Golf Course	140	Employee Spaces	Room/Space (C)	Make corrections for compliant 36" wide circulation path.	\$0.00	1	staff time	\$0.00	3
Southwinds Golf Course	141	Employee Spaces	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
Stacy Street Park	1	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	5	each	\$15,312.50	1
Stacy Street Park	2	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	150	sq ft	\$18,375.00	1
Stacy Street Park	3	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and operable with one hand.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$2,404.50	1	each	\$2,404.50	1
Stacy Street Park	4	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Stacy Street Park	5	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Stacy Street Park	6	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Stacy Street Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	150	sq ft	\$18,375.00	1
Stacy Street Park	8	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Stacy Street Park	9	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	1
Stacy Street Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Stacy Street Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	120	sq ft	\$14,700.00	1
Stacy Street Park	12	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Stacy Street Park	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Stacy Street Park	14	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.00	1	each	\$3,062.00	1
Stacy Street Park	15	Park Element	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4
Stacy Street Park	18	Park Element	Drinking Fountains	Replace drinking fountain with a hi-lo bowl fountain.	\$5,598.25	1	each	\$5,598.25	2
Stacy Street Park	21	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$3,062.50	1	each	\$3,062.50	4
Stacy Street Park	22	Play Area (2-5)	Play Area	Create designated entry as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Stacy Street Park	23	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Stacy Street Park	24	Play Area (2-5)	Play Area	Raise platform on transfer system to 11" to 18" AFF, in the alternative, remove and maintain surface fill level to achieve the same.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Stacy Street Park	25	Play Area (2-5)	Play Area	See previous finding for surface recommendation.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Stacy Street Park	26	Play Area (2-5)	Play Area	Add 1 more GLPC's of any other type to meet incentive scoping and replace surface for access to existing GLPC.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Stacy Street Park	27	Play Area (2-5)	Play Area	See previous finding for surface recommendation.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Stacy Street Park	28	Play Area (5-12)	Play Area	Create designated entry as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Stacy Street Park	29	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Stacy Street Park	30	Play Area (5-12)	Play Area	Consider adding a second transfer system as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$4,970.00	1	each	\$4,970.00	4
Stacy Street Park	31	Play Area (5-12)	Play Area	Raise platform on transfer system to 11" to 18" AFF, in the alternative, remove and maintain surface fill level to achieve the same.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	staff time	\$0.00	4
Stacy Street Park	32	Play Area (5-12)	Play Area	See previous finding for surface recommendation.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Stacy Street Park	33	Play Area (5-12)	Play Area	See previous finding for surface recommendation.  In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Stacy Street Park	34	Play Area (5-12)	Play Area	Add two more GLPC's of two other types to meet incentive scoping. Make surface corrections for access to existing GLPCs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Stub Canal Park	1	Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Stub Canal Park	2	Boat Ramp	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	1	each	\$875.00	2
Stub Canal Park	3	Boat Ramp	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	each	\$296.00	1
Stub Canal Park	4	Boat Ramp	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	each	\$296.00	1
Stub Canal Park	5	Boat Ramp	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Stub Canal Park	6	Boat Ramp	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Stub Canal Park	7	Boat Ramp	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Stub Canal Park	8	Boat Ramp	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	1	each	\$875.00	2
Stub Canal Park	9	Boat Ramp	Boating Facilities	Provide 60" wide clearance at accessible slips and a 60" wide opening every 10'.	\$875.00	1	each	\$875.00	2
Stub Canal Park	10	Park Elements	Reach Ranges	Lower operating mechanisms to max 48" AFF to highest operable part.  Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	2	Parking	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	5	each	\$367.50	1
Therapeutic Recreation Center	3	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	5	each	\$367.50	1
Therapeutic Recreation Center	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	7	each	\$21,437.50	1
Therapeutic Recreation Center	5	Parking	Parking - Off Street	Correct or fill gap to max .5"  Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	\$2,800.00	4	each	\$11,200.00	1
Therapeutic Recreation Center	6	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	5	lin ft	\$296.00	1
Therapeutic Recreation Center	7	Exterior Accessible Route	Detectable Warnings	Install compliant detectable warnings with visual contrast at curb ramps and transitions from walkways to vehicular ways as a smart practice.	\$329.00	2	each	\$658.00	5
Therapeutic Recreation Center	8	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	3	each	\$987.00	5
Therapeutic Recreation Center	9	Exterior Accessible Route	Accessible Routes	Maintain vegetation to provide required clear width along route.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	10	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Therapeutic Recreation Center	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Therapeutic Recreation Center	12	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	13	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Therapeutic Recreation Center	14	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Therapeutic Recreation Center	15	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	72	sq ft	\$8,820.00	1
Therapeutic Recreation Center	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Therapeutic Recreation Center	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	100	sq ft	\$12,250.00	1
Therapeutic Recreation Center	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	200	sq ft	\$24,500.00	1
Therapeutic Recreation Center	19	Exterior Accessible Route	Detectable Warnings	Install compliant detectable warnings with visual contrast at curb ramps and transitions from walkways to vehicular ways as a smart practice.	\$329.00	4	each	\$1,316.00	5
Therapeutic Recreation Center	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Therapeutic Recreation Center	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	60	sq ft	\$7,350.00	1
Therapeutic Recreation Center	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	168	sq ft	\$20,580.00	1
Therapeutic Recreation Center	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
Therapeutic Recreation Center	24	Exterior Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Therapeutic Recreation Center	25	Exterior Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Therapeutic Recreation Center	26	Exterior Elements	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	2
Therapeutic Recreation Center	27	Exterior Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Therapeutic Recreation Center	29	Exterior Elements	Picnic Tables (C)	Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
Therapeutic Recreation Center	31	Interior Accessible Route	Doors	Mount signage at entrance designating it as accessible.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	32	Interior Accessible Route	Signs	Replace Braille on sign and place Braille below the entire text, Braille shall not be broken up by line.	\$210.00	6	each	\$1,260.00	1
Therapeutic Recreation Center	33	Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	34	Interior Accessible Route	Signs	Relocate objects to provide CFS for approach to sign.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	35	Interior Accessible Route	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	3	each	\$630.00	1
Therapeutic Recreation Center	36	Public Spaces	Doors	Leave as is as sensor provides access.	\$1,750.00	1	each	\$1,750.00	4
Therapeutic Recreation Center	37	Public Spaces	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	each	\$0.00	1
Therapeutic Recreation Center	38	Public Spaces	Picnic Tables (C)	Replace two picnic tables with ones of an accessible design as a smart practice.	\$1,120.00	2	each	\$2,240.00	5
Therapeutic Recreation Center	39	Public Spaces	Turning Space	Relocate obstacles to create turning space in 030A.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	40	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	41	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	42	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	45	Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Therapeutic Recreation Center	46	Employee Spaces	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	47	Employee Spaces	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	48	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	49	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	3
Therapeutic Recreation Center	50	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Therapeutic Recreation Center	51	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	2	each	\$420.00	1
Therapeutic Recreation Center	52	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	4	each	\$1,575.00	1
Therapeutic Recreation Center	53	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	54	Women's Restroom	Toilet and Bathing Rooms	Relocate paper towels and hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	55	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	56	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	57	Women's Restroom	Toilet and Bathing Rooms	Remount paper towel dispenser to max 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate storage from grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	58	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	59	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Therapeutic Recreation Center	60	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	61	Women's Restroom	Toilet and Bathing Rooms	Replace toilet paper dispenser with one that provides continuous flow of paper.	\$84.00	1	each	\$84.00	1
Therapeutic Recreation Center	62	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	63	Women's Restroom	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	64	Men's Restroom	Doors	Provide required maneuvering clearance around pull side of door.  Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	65	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Therapeutic Recreation Center	66	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	67	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Therapeutic Recreation Center	68	Men's Restroom	Toilet and Bathing Rooms	Remove storage from bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	69	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	70	Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	71	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	72	Men's Restroom	Toilet and Bathing Rooms	Remove storage from grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	73	Men's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	74	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Therapeutic Recreation Center	75	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	76	Men's Restroom	Toilet and Bathing Rooms	See recommendations for other ambulatory stalls.	\$2,945.00	1	each	\$2,945.00	1
Therapeutic Recreation Center	78	Art Gallery	Signs	Consider alternative method of providing information about the art on display.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	79	Art Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	80	Art Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	81	Art Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	82	Art Rooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	83	Art Rooms	Plumbing Fixtures & Elements	Relocate items to provide CFS at sink.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	84	Art Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	85	Computer Lab	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	86	Computer Lab	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	89	Training Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	90	Training Room	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	92	Conference Room	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	93	Conference Room	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Therapeutic Recreation Center	94	Conference Room	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	96	Unisex Restroom	Plumbing Fixtures & Elements	Relocate trash can to provide required 30" by 48" CFS for a forward approach to sink.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	97	Unisex Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser and hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	98	Unisex Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	99	Unisex Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF. Remove storage from grab bar.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	100	Office Women's Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	101	Office Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	102	Office Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	103	Office Women's Restroom	Doors	Provide required maneuvering clearance on push side of door Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	104	Office Men's Restroom	Toilet and Bathing Rooms	Relocate paper towel dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	105	Office Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	106	Office Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	107	Office Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	108	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	109	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	110	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$350.00	1	staff time	\$350.00	1
Therapeutic Recreation Center	111	Interior Accessible Route	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	113	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton      Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	114	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p>	\$428.75	1	each	\$428.75	1
Therapeutic Recreation Center	115	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, repair and maintain automatic door openers or remove these openers and the stickers and other hardware for the automatic openers.</p>	\$708.75	1	each	\$708.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	116	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, repair and maintain automatic door openers or remove these openers and the stickers and other hardware for the automatic openers.</p>	\$612.50	1	each	\$612.50	1
Therapeutic Recreation Center	117	Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	7	staff time	\$0.00	1
Therapeutic Recreation Center	118	Interior Accessible Route	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	119	Interior Accessible Route	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	3	each	\$630.00	1
Therapeutic Recreation Center	120	Public Spaces	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
Therapeutic Recreation Center	121	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	122	Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	123	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	124	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Therapeutic Recreation Center	125	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Therapeutic Recreation Center	126	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	1
Therapeutic Recreation Center	127	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	128	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	129	Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
Therapeutic Recreation Center	130	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Remove storage from behind door so it opens to 90 degrees.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	131	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.	\$0.00	2	staff time	\$0.00	3
Therapeutic Recreation Center	132	Employee Spaces	Doors	Replace doors with ones having sidelight viewing windows max 43" AFF	\$1,386.00	1	each	\$1,386.00	3
Therapeutic Recreation Center	133	Women's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	134	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Therapeutic Recreation Center	135	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	2	staff time	\$0.00	1
Therapeutic Recreation Center	136	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR, or relocate fixtures to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	137	Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	138	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	5	each	\$1,050.00	1
Therapeutic Recreation Center	139	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount garbage containers a min 12" above or 1.5" below grab bar.	\$0.00	10	staff time	\$0.00	1
Therapeutic Recreation Center	140	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	5	staff time	\$0.00	1
Therapeutic Recreation Center	141	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	142	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	143	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and remount TP dispenser, toilet pipes, and garbage container a min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Therapeutic Recreation Center	144	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	145	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	146	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
Therapeutic Recreation Center	147	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	148	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	2	each	\$700.00	1
Therapeutic Recreation Center	149	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR, or relocate fixtures to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	150	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	151	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	152	Men's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	153	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet. In the alternative, leave as is citing safe harbor.	\$0.00	1	staff time	\$0.00	4
Therapeutic Recreation Center	154	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	155	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and ensure TP dispenser and storage are a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	156	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	157	Men's Restroom	Accessible Routes	Adjust ambulatory door to be self-closing to ensure a compliant 36" clear width to urinals.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	158	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	3	each	\$1,050.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	159	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	160	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	161	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	162	Gymnasium	Assembly Areas	Provide assistive listening system and signage informing patrons of the availability of assistive listening systems.	\$10,485.00	1	each	\$10,485.00	3
Therapeutic Recreation Center	164	Gymnasium	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	2	each	\$13,020.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	165	Gymnasium	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	2	each	\$1,750.00	1
Therapeutic Recreation Center	166	Gymnasium	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF. In the alternative, leave as is citing construction tolerance.	\$350.00	1	each	\$350.00	4
Therapeutic Recreation Center	167	Gymnasium	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	168	Performance Stage	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	169	Performance Stage	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
Therapeutic Recreation Center	171	Concessions	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$3,276.00	1	each	\$3,276.00	1
Therapeutic Recreation Center	172	Concessions	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	173	Concessions	Accessible Routes	Relocate or reposition table to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	174	Concessions	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	175	Changing Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF. Relocate storage from CFS of changing bench.	\$840.00	1	each	\$840.00	2
Therapeutic Recreation Center	176	Changing Room	Plumbing Fixtures & Elements	Relocate bench to provide appropriate CFS on the exterior of the transfer shower.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	177	Changing Room	Plumbing Fixtures & Elements	Remount grab bars to the correct location in the transfer shower.	\$350.00	1	each	\$350.00	2
Therapeutic Recreation Center	178	Changing Room	Plumbing Fixtures & Elements	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held.	\$540.75	1	each	\$540.75	1
Therapeutic Recreation Center	179	Changing Room	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	180	Changing Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	181	Changing Room	Toilet and Bathing Rooms	Lower mirror not over a sink or counter to max 35" AFF to the bottom reflective surface and 74" to the top.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	182	Single User Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	183	Single User Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline. In the alternative, leave as is citing construction tolerance.	\$1,828.40	1	each	\$1,828.40	4
Therapeutic Recreation Center	184	Single User Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	185	Single User Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	186	Single User Restroom	Toilet and Bathing Rooms	See previous finding for TP placment.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	187	Single User Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	188	Single User Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	189	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$1,981.00	5	each	\$9,905.00	1
Therapeutic Recreation Center	190	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$9,615.00	1	each	\$9,615.00	1
Therapeutic Recreation Center	191	Interior Accessible Route	Signs	Mount compliant signage at all doors along the egress route.	\$210.00	5	each	\$1,050.00	1
Therapeutic Recreation Center	192	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	3	each	\$1,050.00	1
Therapeutic Recreation Center	193	Public Spaces	Accessible Routes	Widen AR to compliant 36" clear width by relocation of storage if feasible.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	194	Public Spaces	Accessible Routes	Raise elevated water heater to min 80", or pad object to prevent hazard in overhead clearance along AR.	\$140.00	1	each	\$140.00	1
Therapeutic Recreation Center	195	Public Spaces	Turning Space	Relocate obstacles to create turning space in janitor closet.	\$0.00	1	staff time	\$0.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	196	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	197	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	198	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	199	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	200	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	202	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	203	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	204	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	205	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Therapeutic Recreation Center	208	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	209	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	210	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	211	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	212	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	213	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	214	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	215	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	216	Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Therapeutic Recreation Center	217	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	218	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	219	Public Spaces	Plumbing Fixtures & Elements	Remount fountain for standing persons to 38" min and 43" max AFF to the spout.	\$2,380.00	1	each	\$2,380.00	2
Therapeutic Recreation Center	220	Public Spaces	Clear Floor Space	Remove objects or enlarge CFS to min 48" depth.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	221	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance, or remove mat.	\$2,380.00	1	each	\$2,380.00	2
Therapeutic Recreation Center	222	Employee Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace door closer to provide required 80" overhead clearance.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$350.00	1	each	\$350.00	3
Therapeutic Recreation Center	223	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Therapeutic Recreation Center	224	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, provide beveled threshold.	\$3,316.25	1	each	\$3,316.25	1
Therapeutic Recreation Center	225	Women's Restroom	Toilet and Bathing Rooms	Correct or repair slope in CFS of sign to max 2.08%.  Relocate drinking fountain or remount signage to the push face of the door without hold open device..	\$5,442.50	1	each	\$5,442.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	226	Women's Restroom	Plumbing Fixtures & Elements	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model. Remove shower seat from CFS to provide 8" deep knee clearance.	\$2,380.00	1	each	\$2,380.00	1
Therapeutic Recreation Center	227	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and pipes under sink in stall.	\$77.00	2	each	\$154.00	1
Therapeutic Recreation Center	228	Women's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	229	Women's Restroom	Toilet and Bathing Rooms	Widen stall doors to 32" when opened to 90 degrees. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$630.00	1	each	\$630.00	1
Therapeutic Recreation Center	230	Women's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing. Pricing in a previous finding.	\$0.00	1	each	\$0.00	1
Therapeutic Recreation Center	231	Women's Restroom	Toilet and Bathing Rooms	Replace and add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1
Therapeutic Recreation Center	232	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	233	Women's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	234	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	235	Women's Restroom	Toilet and Bathing Rooms	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF). Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	236	Women's Restroom	Toilet and Bathing Rooms	Remove or relocate shower seat in stall to provide door clearance.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	237	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	238	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item. Pricing for moving hand dryer in stall in a previous finding.	\$350.00	1	each	\$350.00	1
Therapeutic Recreation Center	239	Women's Restroom	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	240	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,890.00	1	each	\$1,890.00	1
Therapeutic Recreation Center	241	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Therapeutic Recreation Center	242	Men's Restroom	Plumbing Fixtures & Elements	Raise one sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model.	\$2,380.00	1	each	\$2,380.00	1
Therapeutic Recreation Center	243	Men's Restroom	Toilet and Bathing Rooms	Enlarge toilet compartments to provide turning space.	\$2,749.25	1	each	\$2,749.25	1
Therapeutic Recreation Center	244	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Therapeutic Recreation Center	245	Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
Therapeutic Recreation Center	246	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	247	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .  Pricing in a previous finding.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	248	Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	\$2,749.25	1	each	\$2,749.25	1
Therapeutic Recreation Center	249	Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	250	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	251	Men's Restroom	Toilet and Bathing Rooms	Replace stall door of ambulatory stall with one that swings out and is self-closing.	\$420.00	1	each	\$420.00	1
Therapeutic Recreation Center	252	Men's Restroom	Toilet and Bathing Rooms	Replace and add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	\$393.75	2	each	\$787.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	253	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	254	Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet. In the alternative, leave as is citing safe harbor.	\$350.00	1	each	\$350.00	4
Therapeutic Recreation Center	255	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Therapeutic Recreation Center	256	Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Therapeutic Recreation Center	257	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate hand dryer a min 12" above or 1.5" below grab bar. Pricing in a previous finding.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	258	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Therapeutic Recreation Center	259	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
Therapeutic Recreation Center	260	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	261	Men's Restroom	Accessible Routes	Remove door stop from floor to eliminate CIL.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	262	Women's Locker Room	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	263	Women's Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker of each size as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice).	\$420.00	2	each	\$840.00	2
Therapeutic Recreation Center	264	Women's Locker Room	Dressing / Fitting / Locker Rooms	Replace or remount 1 tall locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	2
Therapeutic Recreation Center	265	Women's Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Therapeutic Recreation Center	266	Women's Locker Room	Plumbing Fixtures & Elements	Renovate transfer shower to compliant 36" by 36" clear inside dimension.	\$5,498.50	1	each	\$5,498.50	2
Therapeutic Recreation Center	267	Women's Locker Room	Plumbing Fixtures & Elements	Remove shower chair and floor mat from CFS on the exterior of the transfer shower.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	268	Women's Locker Room	Plumbing Fixtures & Elements	Remount shower controls to the correct location in the transfer shower.	\$467.25	1	each	\$467.25	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Therapeutic Recreation Center	269	Women's Locker Room	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
Therapeutic Recreation Center	270	Men's Locker Room	Dressing / Fitting / Locker Rooms	Designate 5% or no less than 1 locker as accessible with accessible hardware. Mount signage with the access symbol as a (smart practice).	\$420.00	1	each	\$420.00	2
Therapeutic Recreation Center	271	Men's Locker Room	Dressing / Fitting / Locker Rooms	Replace or remount locker to max 48" to the hooks and 15" to 48" to the storage shelves.	\$420.00	1	each	\$420.00	2
Therapeutic Recreation Center	272	Men's Locker Room	Dressing / Fitting / Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" AFF and provide required clear floor space on the short axis of the bench.	\$840.00	1	each	\$840.00	2
Therapeutic Recreation Center	273	Men's Locker Room	Plumbing Fixtures & Elements	Establish protocols for regular and frequent inspection of adjustable shower head height to ensure it is 48" max.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	274	Men's Locker Room	Plumbing Fixtures & Elements	Remount shower seat to the correct location and height in the shower.	\$350.00	1	each	\$350.00	2
Therapeutic Recreation Center	275	Men's Locker Room	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	276	Men's Locker Room	Dressing / Fitting / Locker Rooms	Relocate lockers to provide required 30" by 48" CFS at designated accessible lockers.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	277	Pool	Sales and Service Counters/Tables	Relocate storage from lowered section of service counter and train staff to keep it clear for customers.	\$0.00	1	staff time	\$0.00	1
Therapeutic Recreation Center	278	Pool	Pool / Spa	Ensure pool lift ready for independent, unassisted use by pool patrons.	\$0.00	1	staff time	\$0.00	2
Therapeutic Recreation Center	279	Pool	Pool / Spa	Relocate lift to an area providing 36" X 48" CFS having max slope of 2.08% or repair slope in existing location.	\$3,062.50	1	each	\$3,062.50	2
Therapeutic Recreation Center	280	Pool	Pool / Spa	Replace pool lift with one designed to submerge to min water depth of 18".	\$7,000.00	1	each	\$7,000.00	2
Therapeutic Recreation Center	281	Pool	Pool / Spa	Correct pool stair treads to be min 11" deep and riser heights to be uniform if feasible.	\$404.25	5	each	\$2,021.25	2
Therapeutic Recreation Center	282	Pool	Pool / Spa	Maintain an accessible route along the pool deck that is min 36" clear width and having 80" overhead clearance and turning spaces and free of gaps and CIL.  Correct cross slopes to max 2.08%.	\$26,460.00	1	each	\$26,460.00	3
Therapeutic Recreation Center	283	Pool	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Triangle Park	2	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
Triangle Park	3	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Triangle Park	4	Exterior Accessible Route	Accessible Routes	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
Triangle Park	5	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Triangle Park	6	Exterior Accessible Route	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Triangle Park	7	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Triangle Park	8	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Triangle Park	9	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.	\$1,750.00	1	each	\$1,750.00	1
Triangle Park	10	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
Triangle Park	11	Men's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Triangle Park	12	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Triangle Park	13	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Triangle Park	14	Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Triangle Park	15	Men's Restroom	Turning Space	Reconfigure restroom to provide min 60" diameter or t-shaped turning space.	\$8,295.00	1	each	\$8,295.00	1
Triangle Park	16	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Triangle Park	17	Women's Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts .	\$0.00	1	staff time	\$0.00	1
Triangle Park	18	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Triangle Park	19	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Triangle Park	20	Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Triangle Park	21	Women's Restroom	Turning Space	Reconfigure restroom to provide min 60" diameter or t-shaped turning space.	\$8,295.00	1	each	\$8,295.00	1
Triangle Park	22	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Triangle Park	23	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Triangle Park	24	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$1,750.00	1	each	\$1,750.00	1
Triangle Park	25	All Gender Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
Triangle Park	26	All Gender Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
Triangle Park	27	All Gender Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$0.00	1	staff time	\$0.00	1
Triangle Park	28	All Gender Restroom	Clear Floor Space	Relocate paper towel dispenser to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
Triangle Park	29	All Gender Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet.	\$2,380.00	1	each	\$2,380.00	1
Triangle Park	30	All Gender Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Triangle Park	31	All Gender Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
Triangle Park	32	All Gender Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
Triangle Park	33	All Gender Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Triangle Park	34	All Gender Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$4,812.50	1	each	\$4,812.50	1
Triangle Park	35	Shelters	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.  Relocate garbage can to be along AR.	\$59.20	25	lin ft	\$1,480.00	5
Triangle Park	36	Shelters	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.  Remount rim of garbage can to be in reach range of 15" min to 48" max.	\$105.00	2	each	\$210.00	5



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Triangle Park	38	Picnic Area	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
Veteran's Memorial Park	2	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Veteran's Memorial Park	3	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Veteran's Memorial Park	4	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
Veteran's Memorial Park	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Veteran's Memorial Park	7	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
Veteran's Memorial Park	8	Parking	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Veteran's Memorial Park	9	Parking	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
Veteran's Memorial Park	10	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	1	each	\$73.50	1
Veteran's Memorial Park	11	Parking At Youth Activity Center	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
Veteran's Memorial Park	12	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	13	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Veteran's Memorial Park	14	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	15	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	16	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	5	each	\$481.25	1
Veteran's Memorial Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Veteran's Memorial Park	18	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
Veteran's Memorial Park	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	6	each	\$577.50	1
Veteran's Memorial Park	20	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
Veteran's Memorial Park	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	22	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	23	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Veteran's Memorial Park	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Veteran's Memorial Park	25	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	4	each	\$1,316.00	5
Veteran's Memorial Park	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%. In the alternative, install compliant ramp in this location.	\$3,062.50	1	each	\$3,062.50	1
Veteran's Memorial Park	27	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Veteran's Memorial Park	28	Exterior Accessible Route	Accessible Routes	Repair or reset caps to eliminate change in level.	\$28.00	36	each	\$1,008.00	2
Veteran's Memorial Park	29	GLPC-only Play Area (5-12)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.	\$700.00	1	each	\$700.00	5
Veteran's Memorial Park	30	GLPC-only Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Veteran's Memorial Park	31	GLPC-only Play Area (5-12)	Accessible Routes	Raise fill to eliminate CIL at border.	\$70.00	100	sq ft	\$7,000.00	2
Veteran's Memorial Park	33	GLPC-only Play Area (2-5)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice. See finding in 5-12 area.	\$0.00	1	each	\$0.00	5
Veteran's Memorial Park	34	GLPC-only Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.	\$70,000.00	1	each	\$70,000.00	2
Veteran's Memorial Park	35	GLPC-only Play Area (2-5)	Accessible Routes	Raise fill to eliminate CIL at border. See cost in 5-12 finding.	\$0.00	100	sq ft	\$0.00	2
Veteran's Memorial Park	37	Sports Courts/Fields	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, remount hardware to 34" to 48" AFF.	\$3,769.70	1	each	\$3,769.70	2
Veteran's Memorial Park	40	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site.  In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	50	lin ft	\$2,960.00	4
Veteran's Memorial Park	41	Picnic Areas	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$2,486.00	2	each	\$4,972.00	5
Veteran's Memorial Park	42	Picnic Areas	Shelters, Picnic Facilities (C)	Create an ORAR to shelter or picnic area and provide accessible features as a smart practice.	\$59.20	1	each	\$59.20	5
Veteran's Memorial Park	43	Picnic Areas	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space. Lower 20% of garbage cans to be in reach at max 48" AFF.	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Veteran's Memorial Park	44	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or repair ORAR cross slope to max 2.08% as a smart practice. In the alternative, leave as is citing construction tolerance.	\$122.50	12	sq ft	\$1,470.00	4
Veteran's Memorial Park	45	Picnic Areas	Picnic Tables (C)	See previous finding for recommendation and cost.	\$0.00	2	each	\$0.00	5
Veteran's Memorial Park	46	Picnic Areas	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	2	each	\$192.50	5
Veteran's Memorial Park	49	Park Elements	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
Veteran's Memorial Park	50	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
Veteran's Memorial Park	52	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Veteran's Memorial Park	53	Park Elements	Plumbing Fixtures & Elements	Correct slope in clear ground space to max 2.08%.	\$2,380.00	1	each	\$2,380.00	2
Veteran's Memorial Park	54	Park Elements	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	2
Veteran's Memorial Park	56	Park Elements	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Veteran's Memorial Park	57	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$0.00	1	staff time	\$0.00	2
Veteran's Memorial Park	58	Park Elements	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Veteran's Memorial Park	60	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Veteran's Memorial Park	61	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	400	sq ft	\$49,000.00	5
Veteran's Memorial Park	62	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	900	sq ft	\$110,250.00	5
Veteran's Memorial Park	63	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Veteran's Memorial Park	64	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	1150	sq ft	\$140,875.00	5
Veteran's Memorial Park	65	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Veteran's Memorial Park	66	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Veteran's Memorial Park	67	Trail - Surface	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Veteran's Memorial Park	68	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	450	sq ft	\$55,125.00	5
Veteran's Memorial Park	69	Trail - Surface	Outdoor - Trails (C)	Correct or repair pathway cross slope to max 2.08% as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Veteran's Memorial Park	70	Trail - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	10	lin ft	\$592.00	5
Veteran's Memorial Park	71	Picnic Area Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Veteran's Memorial Park	72	Picnic Area Men's Restroom	Plumbing Fixtures & Elements	Lower one urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Veteran's Memorial Park	73	Picnic Area Men's Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS	\$2,749.25	1	each	\$2,749.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Veteran's Memorial Park	74	Picnic Area Men's Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" AFF.	\$2,978.50	1	each	\$2,978.50	1
Veteran's Memorial Park	75	Picnic Area Men's Restroom	Reach Ranges	Lower hook to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	76	Picnic Area Men's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Veteran's Memorial Park	77	Picnic Area Men's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Veteran's Memorial Park	78	Picnic Area Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	2	each	\$840.00	1
Veteran's Memorial Park	79	Picnic Area Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	80	Picnic Area Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Veteran's Memorial Park	81	Picnic Area Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, remount hardware to max 48" AFF.	\$2,360.75	1	each	\$2,360.75	1
Veteran's Memorial Park	82	Picnic Area Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Veteran's Memorial Park	83	Picnic Area Women's Restroom	Reach Ranges	Lower hook in stall to max 48" above the finished floor (AFF).	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	84	Picnic Area Women's Restroom	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Veteran's Memorial Park	85	Picnic Area Women's Restroom	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Veteran's Memorial Park	86	Picnic Area Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	2	each	\$840.00	1
Veteran's Memorial Park	87	Picnic Area Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	88	Picnic Area Women's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Veteran's Memorial Park	89	Picnic Area Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, remount hardware to max 48" AFF.	\$2,360.75	1	each	\$2,360.75	1
Veteran's Memorial Park	90	Picnic Area Restroom Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Correct slope in door clearance to max 2.08%.  Replace doors with doors having 80" overhead clearance and 32" clear width.  Repair, bevel, or ramp CILs at door entries to max .25".  Remount hardware to max 48" AFF.	\$6,734.50	1	each	\$6,734.50	3
Veteran's Memorial Park	91	Men's Restroom Near Tennis	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
Veteran's Memorial Park	92	Men's Restroom Near Tennis	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Veteran's Memorial Park	93	Men's Restroom Near Tennis	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
Veteran's Memorial Park	94	Men's Restroom Near Tennis	Plumbing Fixtures & Elements	Lower urinal so that rim height is max 17" AFF.	\$1,704.50	1	each	\$1,704.50	1
Veteran's Memorial Park	95	Men's Restroom Near Tennis	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF. Cost in previous finding.	\$0.00	1	each	\$0.00	1
Veteran's Memorial Park	96	Men's Restroom Near Tennis	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Veteran's Memorial Park	97	Men's Restroom Near Tennis	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Veteran's Memorial Park	98	Men's Restroom Near Tennis	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Veteran's Memorial Park	99	Men's Restroom Near Tennis	Toilet and Bathing Rooms	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls, or 16" to 18" in new wheelchair stall.	\$1,828.40	1	each	\$1,828.40	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Veteran's Memorial Park	100	Men's Restroom Near Tennis	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
Veteran's Memorial Park	101	Men's Restroom Near Tennis	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Veteran's Memorial Park	102	Women's Restroom Near Tennis	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	103	Women's Restroom Near Tennis	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Veteran's Memorial Park	104	Women's Restroom Near Tennis	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Veteran's Memorial Park	105	Women's Restroom Near Tennis	Toilet and Bathing Rooms	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep. In the alternative, use existing ambulatory stall to create required wheelchair stall.	\$2,749.25	1	each	\$2,749.25	4
Veteran's Memorial Park	106	Women's Restroom Near Tennis	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	2	each	\$840.00	1
Veteran's Memorial Park	107	Women's Restroom Near Tennis	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Veteran's Memorial Park	108	Women's Restroom Near Tennis	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
Veteran's Memorial Park	109	Women's Restroom Near Tennis	Doors	For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$3,062.50	1	each	\$3,062.50	1
<a href="#">Watergate Estates Park</a>	1	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,577.00	1	each	\$3,577.00	2
Watergate Estates Park	3	Play Area (2-5)	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Watergate Estates Park	4	Play Area (2-5)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Watergate Estates Park	5	Play Area (2-5)	Accessible Routes	Raise fill to eliminate CIL at border.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	100	sq ft	\$7,000.00	4
Watergate Estates Park	9	Play Area (5-12)	Play Area	Create designated entry by removing 36" portion of play area boundary as a smart practice.  In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Watergate Estates Park	10	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Watergate Estates Park	11	Play Area (5-12)	Accessible Routes	Raise fill to eliminate CIL at border.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70.00	100	sq ft	\$7,000.00	4
Watergate Estates Park	13	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	5	lin ft	\$296.00	2
Watergate Estates Park	14	Park Element	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Watergate Estates Park	15	Park Element	Plumbing Fixtures & Elements	Remount fountain so spout outlet is max 36" AFF. In the alternative, leave as is citing construction tolerance.	\$2,380.00	1	each	\$2,380.00	4
Watergate Estates Park	16	Park Element	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
Watergate Estates Park	18	Fitness	Accessible Routes	Maintain surface at fitness elements to be firm and stable.  In the alternative, leave as is and designate other County fitness areas accessible.	\$0.00	1	staff time	\$0.00	4
Watergate Estates Park	19	Fitness	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Consider replacing the surface at fitness with one that is firm and stable.  In the alternative, leave as is and designate other County fitness areas accessible.	\$70.00	100	sq ft	\$7,000.00	4
Waterway Park	2	Parking - Boat Trailer	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
Waterway Park	3	Parking - Boat Trailer	Parking - Off Street	Relocate access aisle to the passenger side of the stall.	\$367.50	1	each	\$367.50	1
Waterway Park	4	Parking - Boat Trailer	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Waterway Park	5	Parking - Boat Trailer	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	6	each	\$441.00	1
Waterway Park	7	Parking - Restrooms	Parking - Off Street	Repaint stalls to be 12' (144") wide each.	\$73.50	1	each	\$73.50	1
Waterway Park	8	Parking - Restrooms	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
Waterway Park	9	Parking - Restrooms	Parking - Off Street	Add van parking sign to one accessible stall and repaint stall and access aisle to 12' and 5'.	\$283.50	1	each	\$283.50	1
Waterway Park	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	540	sq ft	\$66,150.00	1
Waterway Park	11	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	90	sq ft	\$11,025.00	1
Waterway Park	12	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Waterway Park	13	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	3	each	\$288.75	1
Waterway Park	14	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Waterway Park	15	Exterior Accessible Route	Curb Ramps	Correct curb ramp slope to max 8.33%.	\$1,015.00	1	each	\$1,015.00	1
Waterway Park	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	2	each	\$6,125.00	1
Waterway Park	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	420	sq ft	\$51,450.00	1
Waterway Park	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Waterway Park	19	Park Elements	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Waterway Park	20	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Waterway Park	21	Park Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Waterway Park	22	Park Elements	ATM's and Fare Machines	Contact provider to replace parking pay kiosk with a compliant model.	\$5,000.00	1	each	\$5,000.00	2
Waterway Park	23	Park Elements	ATM's and Fare Machines	Replace parking pay kiosk with one that has compliant features. Pricing in a previous finding.	\$0.00	1	each	\$0.00	2
Waterway Park	25	Park Elements	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Waterway Park	26	Fishing/Boating	Accessible Routes	Correct or fill gaps to be max .5".  In the alternative, leave as is and designate other County fishing areas accessible.	\$96.25	6	each	\$577.50	4
Waterway Park	27	Fishing/Boating	Fishing Piers And Platforms	Lower 25% of the railing; dispersed through pier, to max 34".  In the alternative, leave as is and designate other County fishing areas accessible.	\$980.00	5	each	\$4,900.00	4
Waterway Park	28	Fishing/Boating	Accessible Routes	Correct running slopes to max 5%.  Correct cross slopes to max 2.08%.  In the alternative, leave as is and designate other County boating areas accessible.	\$15,312.50	1	each	\$15,312.50	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Waterway Park	29	Women's Restroom	Doors	Provide required maneuvering clearance on push side of door. Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
Waterway Park	30	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Waterway Park	31	Women's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Waterway Park	32	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
Waterway Park	33	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Waterway Park	34	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Waterway Park	35	Women's Restroom	Toilet and Bathing Rooms	See previous finding for TP placement.	\$0.00	1	staff time	\$0.00	1
Waterway Park	36	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	2	each	\$700.00	1
Waterway Park	37	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate. For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
Waterway Park	38	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
Waterway Park	39	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Waterway Park	40	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
Waterway Park	41	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
Waterway Park	42	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Waterway Park	43	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item. Pricing for relocating one hand dryer is in a previous finding.	\$350.00	2	each	\$700.00	1
Waterway Park	44	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
West Boynton Park and Recreation Center	1	Parking - East Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	4	each	\$294.00	1
West Boynton Park and Recreation Center	2	Parking - East Lot	Parking - Off Street	Add van parking sign to 2 accessible stalls and repaint stalls and access aisles to 12' and 5'.	\$283.50	2	each	\$567.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	3	Parking - East Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	9	each	\$27,562.50	1
West Boynton Park and Recreation Center	4	Parking - East Lot	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks and repaint international symbol of accessibility.	\$169.75	2	each	\$339.50	1
West Boynton Park and Recreation Center	5	Parking - East Lot	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	6	Parking - East Lot	Parking - Off Street	Maintain accessible route to min 44" clear width and assure connection to access aisle.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	7	Parking - East Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	8	each	\$588.00	1
West Boynton Park and Recreation Center	9	Parking - North Lot	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	8	each	\$588.00	1
West Boynton Park and Recreation Center	10	Parking - North Lot	Parking - Off Street	Resurface stalls and access aisles to eliminate gaps and cracks.	\$2,800.00	5	each	\$14,000.00	1
West Boynton Park and Recreation Center	11	Parking - North Lot	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	9	each	\$27,562.50	1
West Boynton Park and Recreation Center	12	Parking - North Lot	Parking - Off Street	Add two van parking signs to two accessible stalls and ensure stalls and access aisles are 12' and 5'.	\$210.00	2	each	\$420.00	1
West Boynton Park and Recreation Center	13	Parking - North Lot	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
West Boynton Park and Recreation Center	15	Exterior Accessible Route	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice.	\$96.25	8	each	\$770.00	5
West Boynton Park and Recreation Center	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
West Boynton Park and Recreation Center	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	4	each	\$385.00	1
West Boynton Park and Recreation Center	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	19	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	280	sq ft	\$34,300.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	21	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	2	each	\$6,125.00	1
West Boynton Park and Recreation Center	22	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	160	sq ft	\$19,600.00	1
West Boynton Park and Recreation Center	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	560	sq ft	\$68,600.00	1
West Boynton Park and Recreation Center	24	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	25	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1312	lin ft	\$160,720.00	1
West Boynton Park and Recreation Center	26	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	400	sq ft	\$49,000.00	1
West Boynton Park and Recreation Center	27	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	5	each	\$1,645.00	5
West Boynton Park and Recreation Center	28	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	29	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	30	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	31	Exterior Accessible Route	Custom/Special	Correct accessible route to eliminate water pooling.	\$3,062.50	1	each	\$3,062.50	1
West Boynton Park and Recreation Center	32	Exterior Accessible Route	Accessible Routes	Remove obstruction for 36" clear width along the AR.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	33	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	34	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1040	sq ft	\$127,400.00	1
West Boynton Park and Recreation Center	35	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	40	sq ft	\$4,900.00	1
West Boynton Park and Recreation Center	36	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	50	sq ft	\$6,125.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	37	Play Area (2-5)	Play Area	Correct or repair running slope of designated entry to max 5%.	\$3,062.50	1	each	\$3,062.50	2
West Boynton Park and Recreation Center	38	Play Area (2-5)	Play Area	Consider adding a second transfer system as a smart practice.	\$4,970.00	1	each	\$4,970.00	5
West Boynton Park and Recreation Center	41	Play Area (2-5)	Play Area	Lower or adjust entry point to play component to 11" to 24" AFF.	\$0.00	1	staff time	\$0.00	2
West Boynton Park and Recreation Center	43	Play Area (5-12)	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%. In the alternative, leave as is and designate other County playgrounds accessible.	\$6,510.00	1	each	\$6,510.00	4
West Boynton Park and Recreation Center	44	Play Area (5-12)	Play Area	Repair, bevel or ramp CIL at playground entry/border. In the alternative, leave as is and designate other County playgrounds accessible.	\$96.25	1	each	\$96.25	4
West Boynton Park and Recreation Center	45	Play Area (5-12)	Play Area	Raise overhead clearance to yellow egress ladders components to min 80" or remove or relocate components to achieve accessible route to egress of each component. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	2	each	\$5,600.00	4
West Boynton Park and Recreation Center	47	Play Area (5-12)	Play Area	Provide an AR to element for one of each type accessible.  In the alternative, add another ground level play component on the route.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
West Boynton Park and Recreation Center	48	Play Area (5-12)	Play Area	Add 6 more types of GLPCs such as climbers, spinners or rockers, to meet incentive scoping.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	6	each	\$16,800.00	4
West Boynton Park and Recreation Center	49	Play Area (5-12)	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
West Boynton Park and Recreation Center	50	Play Area (5-12)	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$350.00	3	each	\$1,050.00	1
West Boynton Park and Recreation Center	51	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	52	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	53	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	54	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink.	\$77.00	1	each	\$77.00	1
West Boynton Park and Recreation Center	55	Women's Restroom	Reach Ranges	Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	56	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	57	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	58	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	59	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	60	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	61	Men's Restroom	Reach Ranges	Lower hand dryer to max 48" above the finished floor (AFF) to highest operable part. Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	2	each	\$700.00	1
West Boynton Park and Recreation Center	62	Men's Restroom	Toilet and Bathing Rooms	Relocate soap dispenser to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	63	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	64	Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	65	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar. Remount hand dryer 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	66	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	67	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	68	Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	69	Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	70	Men's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	71	Park Element	Accessible Routes	Create an AR to the play area within the site.	\$59.20	10	lin ft	\$592.00	2
West Boynton Park and Recreation Center	72	Park Element	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
West Boynton Park and Recreation Center	73	Park Element	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
West Boynton Park and Recreation Center	74	Park Element	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	75	Park Element	Outdoor - Constructed Features (C)	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Replace operable part with one usable without a tight pinch or grasp.	\$677.25	1	each	\$677.25	5
West Boynton Park and Recreation Center	76	Park Element	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
West Boynton Park and Recreation Center	77	Park Element	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	5	lin ft	\$296.00	2
West Boynton Park and Recreation Center	78	Park Element	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
West Boynton Park and Recreation Center	79	Park Element	Accessible Routes	Relocate 20% of garbage cans to be along AR.  Remount garbage cans to be in reach range of 15" min to 48" max.	\$0.00	6	staff time	\$0.00	2
West Boynton Park and Recreation Center	81	Park Element	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County volleyball courts accessible.	\$59.20	40	lin ft	\$2,368.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	82	Roller Hockey Rink	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	1	each	\$980.00	2
West Boynton Park and Recreation Center	83	Roller Hockey Rink	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	3
West Boynton Park and Recreation Center	84	Roller Hockey Rink	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	3
West Boynton Park and Recreation Center	85	Roller Hockey Rink	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	3
West Boynton Park and Recreation Center	86	Roller Hockey Rink	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	1	each	\$875.00	3
West Boynton Park and Recreation Center	87	Roller Hockey Rink	Ramps (Not Curb Ramps)	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	3
West Boynton Park and Recreation Center	88	Roller Hockey Rink	Gates	Widen gates or barriers to min 32" clear width. Correct or repair CIL to max .25" or to a threshold max .5".	\$980.00	2	each	\$1,960.00	2
West Boynton Park and Recreation Center	89	Roller Hockey Rink	Gates	Widen gates or barriers to min 32" clear width. Correct or repair CIL to max .25" or to a threshold max .5".	\$980.00	2	each	\$1,960.00	2
West Boynton Park and Recreation Center	90	Roller Hockey Rink	Gates	Widen gates or barriers to min 32" clear width. Correct or repair CIL to max .25" or to a threshold max .5".	\$980.00	2	each	\$1,960.00	2
West Boynton Park and Recreation Center	91	Roller Hockey Rink	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	92	Roller Hockey Rink	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	93	Roller Hockey Rink	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	94	Roller Hockey Rink	Gates	Widen gates or barriers to min 32" clear width. Correct or repair CIL to max .25" or to a threshold max .5".	\$980.00	1	each	\$980.00	2
West Boynton Park and Recreation Center	95	Skate Park	Ramps (Not Curb Ramps)	Correct slope of ramp to max 8.33%.	\$6,510.00	1	each	\$6,510.00	2
West Boynton Park and Recreation Center	96	Skate Park	Ramps (Not Curb Ramps)	Enlarge landing on ramp where directions change to 60" by 60".	\$875.00	1	each	\$875.00	2
West Boynton Park and Recreation Center	97	Skate Park	Ramps (Not Curb Ramps)	Remount handrails to 34" to 38" AFF.	\$350.00	1	each	\$350.00	2
West Boynton Park and Recreation Center	98	Skate Park	Ramps (Not Curb Ramps)	Replace handrail with one that is continuous along the full length of the ramp and having required top and bottom extensions.	\$980.00	2	each	\$1,960.00	2
West Boynton Park and Recreation Center	99	Skate Park	Ramps (Not Curb Ramps)	Replace handrails with ones that are rounded and/or extend to the ground. Pricing provided in a previous finding.	\$0.00	4	each	\$0.00	2
West Boynton Park and Recreation Center	100	Skate Park	Ramps (Not Curb Ramps)	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	2
West Boynton Park and Recreation Center	101	Skate Park	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	2
West Boynton Park and Recreation Center	102	Skate Park	Stairways	Install handrails on both sides of stairway, mounted 34" to 38" AFF with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall. Pricing provided in a previous finding.	\$0.00	2	each	\$0.00	2
West Boynton Park and Recreation Center	103	Skate Park	Gates	Widen gates or barriers to min 32" clear width. Correct or repair CIL to max .25" or to a threshold max .5".	\$980.00	1	each	\$980.00	2
West Boynton Park and Recreation Center	104	Skate Park	Viewing Areas (C)	Lower a 32" wide portion of railing to max 32" for unobstructed viewing.	\$980.00	1	each	\$980.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	106	Oak Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	2	each	\$192.50	4
West Boynton Park and Recreation Center	107	Oak Pavilion	Outdoor Recreation Access Routes (C)	Relocate protruding objects along the ORAR or place cane detectable bollard at foot of objects as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	3	each	\$1,050.00	4
West Boynton Park and Recreation Center	108	Oak Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
West Boynton Park and Recreation Center	109	Oak Pavilion	Shelters/Picnic Areas (C)	Replace existing amenities with ones of an accessible design and provide required clear ground space. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
West Boynton Park and Recreation Center	110	Shelter #1 (By Oak Pavilion)	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	3	each	\$288.75	4
West Boynton Park and Recreation Center	111	Shelter #1 (By Oak Pavilion)	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
West Boynton Park and Recreation Center	112	Shelter #1 (By Oak Pavilion)	Clear Floor Space	Correct or repair slope in CFS to max 2.08%. In the alternative, leave as is and designate other County picnic facilities accessible.	\$122.50	25	sq ft	\$3,062.50	4
West Boynton Park and Recreation Center	113	Shelter #2 (By Sand Volleyball Court)	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	2	each	\$192.50	4
West Boynton Park and Recreation Center	114	Shelter #2 (By Sand Volleyball Court)	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.  Establish protocols for regular and frequent inspection and maintenance of shelter surface and at accessible picnic tables.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
West Boynton Park and Recreation Center	115	Shelter #2 (By Sand Volleyball Court)	Shelters, Picnic Facilities (C)	Relocate garbage can to be along AR.  Remount garbage can to be in reach range of 15" min to 48" max.  In the alternative, leave as is and designate other County picnic facilities accessible.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	116	Shelter #2 (By Sand Volleyball Court)	Outdoor - Constructed Features (C)	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$350.00	1	each	\$350.00	4
West Boynton Park and Recreation Center	117	Shelter #3 (By Baseball Field)	Outdoor Recreation Access Routes (C)	Repair, bevel or ramp change in level along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	4	each	\$385.00	4
West Boynton Park and Recreation Center	118	Shelter #3 (By Baseball Field)	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$96.25	1	each	\$96.25	4
West Boynton Park and Recreation Center	119	Shelter #3 (By Baseball Field)	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$1,120.00	1	each	\$1,120.00	4
West Boynton Park and Recreation Center	120	Picnic Area By Shelters And Playgrounds	Shelters, Picnic Facilities (C)	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area as a smart practice. In the alternative, leave as is and designate other County picnic facilities accessible.	\$59.20	50	lin ft	\$2,960.00	4
West Boynton Park and Recreation Center	121	Baseball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	122	Baseball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	123	Baseball Fields	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	124	Baseball Fields	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	126	Baseball Fields	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%. In the alternative, leave as is and designate other County ball fields accessible.	\$122.50	150	sq ft	\$18,375.00	4
West Boynton Park and Recreation Center	127	Baseball Fields	Accessible Routes	Correct or fill gaps to be max .5". In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	12	each	\$1,155.00	4
West Boynton Park and Recreation Center	128	Baseball Fields	Accessible Routes	Correct or fill gaps to be max .5". In the alternative, leave as is and designate other County ball fields accessible.	\$96.25	3	each	\$288.75	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	129	Baseball Fields	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$1,470.00	3	each	\$4,410.00	4
West Boynton Park and Recreation Center	130	Baseball Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	131	Baseball Fields	Assembly Areas	Provide level clear ground space adjacent to team bench, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	132	Baseball Fields	Assembly Areas	Repair landing at accessible seating to be level or no more than 2.08% slope in any direction and free of gaps and CIL and ensure it prevents water from pooling. In the alternative, leave as is and designate other County ball fields accessible.	\$122.50	30	sq ft	\$3,675.00	4
West Boynton Park and Recreation Center	133	Baseball Fields	Reach Ranges	Remount garbage can rims to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	2
West Boynton Park and Recreation Center	134	Baseball Fields	Assembly Areas	Provide level clear ground space adjacent to team bench, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	135	Baseball Fields	Assembly Areas	Provide level clear ground space adjacent to team bench, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$1,470.00	2	each	\$2,940.00	4
West Boynton Park and Recreation Center	136	Concession Building	Elevators & Lifts	Provide standby power for the lift in the event of power loss.	\$2,500.00	1	each	\$2,500.00	3
West Boynton Park and Recreation Center	137	Concession Building	Elevators & Lifts	Assure power doors remain open for min 20 seconds.	\$1,500.00	1	each	\$1,500.00	3
West Boynton Park and Recreation Center	138	Concession Building	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	17	each	\$2,125.00	5
West Boynton Park and Recreation Center	139	Concession Building	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	140	Concession Building	Viewing Areas (C)	Lower a 36" wide portion of railing to max 32" for unobstructed viewing as a smart practice.	\$980.00	1	each	\$980.00	5
West Boynton Park and Recreation Center	141	Concession Building	Accessible Routes	Relocate storage to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	142	Concession Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	143	Concession Building	Stairways	Install handrails on both sides of stairway mounted 34" to 38" AFF, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
West Boynton Park and Recreation Center	144	Concession Building	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
West Boynton Park and Recreation Center	145	Concession Building	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
West Boynton Park and Recreation Center	146	Concession Building	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
West Boynton Park and Recreation Center	147	Men's Restroom	Toilet and Bathing Rooms	Replace mirror and mount at one main area mirror and mirror in stall to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
West Boynton Park and Recreation Center	148	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	149	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	150	Men's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.  Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,730.00	1	each	\$2,730.00	1
West Boynton Park and Recreation Center	151	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	152	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	153	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	154	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	155	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	156	Men's Restroom	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$542.50	1	each	\$542.50	1
West Boynton Park and Recreation Center	157	Women's Restroom	Toilet and Bathing Rooms	Replace mirror and mount at one main area mirror and mirror in stall to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
West Boynton Park and Recreation Center	158	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	159	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
West Boynton Park and Recreation Center	160	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	161	Women's Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.  Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,730.00	1	each	\$2,730.00	1
West Boynton Park and Recreation Center	162	Women's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
West Boynton Park and Recreation Center	163	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	164	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar. Remount hand dryer at 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	165	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	166	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	167	Women's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$2,749.25	1	each	\$2,749.25	1
West Boynton Park and Recreation Center	168	Women's Restroom	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25". For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers. For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	169	Little League Park Site Elements	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
West Boynton Park and Recreation Center	171	Little League Park Site Elements	Plumbing Fixtures & Elements	Adjust spout flow to max 30 degrees measured from the front of the unit.	\$420.00	1	each	\$420.00	2
West Boynton Park and Recreation Center	172	Little League Park Site Elements	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$0.00	1	staff time	\$0.00	2
West Boynton Park and Recreation Center	173	Little League Park Site Elements	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	2
West Boynton Park and Recreation Center	174	Little League Park Site Elements	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	175	Little League Park Site Elements	Signs	Replace sign with one having contrasting color and on a non-glare surface.	\$210.00	1	each	\$210.00	2
West Boynton Park and Recreation Center	176	Little League Park Site Elements	Signs	Replace sign with one having contrasting color and on a non-glare surface.	\$210.00	1	each	\$210.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	177	Little League Exterior Route	Accessible Routes	Replace drain grate with one having max gaps of .5".	\$140.00	1	each	\$140.00	1
West Boynton Park and Recreation Center	178	Little League Exterior Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
West Boynton Park and Recreation Center	179	Little League Exterior Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	50	each	\$4,812.50	1
West Boynton Park and Recreation Center	180	Little League Exterior Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	50	each	\$4,812.50	1
West Boynton Park and Recreation Center	181	Baseball Complex	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	182	Baseball Complex	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	2	each	\$192.50	2
West Boynton Park and Recreation Center	183	Baseball Complex	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	45	lin ft	\$2,664.00	2
West Boynton Park and Recreation Center	184	Concession Building	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	185	Concession Building	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
West Boynton Park and Recreation Center	186	Concession Building	Doors	Relocate obstacles to provide 48" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	187	Concession Building	Accessible Routes	Replace grate with one having max openings of 1/2 inch.	\$140.00	1	each	\$140.00	1
West Boynton Park and Recreation Center	188	Concession Building	Reach Ranges	Lower outlet and other items to max 44" above the finished floor (AFF) for a forward reach over sink or counter.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	189	Concession Building	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	190	Concession Building	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	191	Concession Building	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36" AGL.	\$1,099.00	1	each	\$1,099.00	1
West Boynton Park and Recreation Center	192	Press Box	Stairways	Install handrails on both sides of stairway mounted 34" to 38" aff, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	\$980.00	2	each	\$1,960.00	1
West Boynton Park and Recreation Center	193	Press Box	Stairways	Install contrasting strip along front 2" of each tread.  The stripe shall be a minimum of 2 inches wide to a maximum of 4 inches wide placed parallel to, and not more than 1 inch from, the nose of the step or upper approach. The stripe shall extend the full width of the step or upper approach and shall be of material that is at least as slip resistant as the other treads of the stair. A painted stripe shall be acceptable. Grooves shall not be used to satisfy this requirement.	\$125.00	15	each	\$1,875.00	5
West Boynton Park and Recreation Center	195	Press Box	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	196	Press Box	Elevators & Lifts	Leave key at lift or provide other means for the lift to be operated independently.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	197	Press Box	Elevators & Lifts	Provide standby power for the lift into the event of power loss.	\$2,500.00	1	each	\$2,500.00	3
West Boynton Park and Recreation Center	198	Press Box	Elevators & Lifts	Remove garbage from required 30" by 48" clear floor space.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	199	Field 4	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	200	Field 4	Assembly Areas	Provide level clear ground space adjacent to team bench, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	201	Field 4	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	202	Field 4	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.	\$350.00	1	each	\$350.00	4
West Boynton Park and Recreation Center	203	Field 5	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	204	Field 5	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	205	Field 5	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	206	Field 5	Doors	Provide required maneuvering clearance around pull side of door. In the alternative, leave as is and designate other County ball fields accessible.	\$1,750.00	1	each	\$1,750.00	4
West Boynton Park and Recreation Center	207	Field 6	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	208	Field 6	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	209	Field 6	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	210	Field 6	Doors	Provide required maneuvering clearance around pull side of door. In the alternative, leave as is and designate other County ball fields accessible.	\$1,750.00	1	each	\$1,750.00	4
West Boynton Park and Recreation Center	211	Field 7	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	10	lin ft	\$592.00	4
West Boynton Park and Recreation Center	212	Field 7	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" AFF. In the alternative, leave as is and designate other County ball fields accessible.	\$350.00	1	each	\$350.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	213	Field 7	Custom/Special	Provide required number of accessible seats that include the same level of amenities as other seats provided. In the alternative, leave as is and designate other County ball fields accessible.	\$161.00	2	each	\$322.00	4
West Boynton Park and Recreation Center	214	Field 7	Assembly Areas	Provide level clear ground space adjacent to bleachers, 36" by 48". In the alternative, leave as is and designate other County ball fields accessible.	\$840.00	2	each	\$1,680.00	4
West Boynton Park and Recreation Center	215	Men's Restroom	Toilet and Bathing Rooms	Replace mirror and mount at one main area mirror and mirror in stall to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1
West Boynton Park and Recreation Center	216	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	217	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
West Boynton Park and Recreation Center	218	Men's Restroom	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	219	Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
West Boynton Park and Recreation Center	220	Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	221	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	222	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	223	Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	224	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	225	Women's Restroom	Toilet and Bathing Rooms	Replace mirror and mount at one main area mirror and mirror in stall to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	2	each	\$700.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	226	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	227	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
West Boynton Park and Recreation Center	228	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	229	Women's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
West Boynton Park and Recreation Center	230	Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	231	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	232	Women's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	233	Women's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	234	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	235	Employee Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$48.25	2	each	\$96.50	3
West Boynton Park and Recreation Center	236	Employee Area	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	237	Employee Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Correct slope in door clearance to max 2.08%.  Repair, bevel, or ramp CILs at door entries to max .25".	\$3,158.75	1	each	\$3,158.75	3
West Boynton Park and Recreation Center	238	Employee Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Repair, bevel, or ramp CILs at door entries to max .25".	\$192.50	1	each	\$192.50	3
West Boynton Park and Recreation Center	239	Employee Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	240	Employee Area	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	241	Employee Area	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	246	Men's Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	247	Men's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	248	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	249	Men's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	250	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate hand dryer 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	251	Men's Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	252	Men's Restroom	Plumbing Fixtures & Elements	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	253	Men's Restroom	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	254	Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	255	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	256	Women's Restroom	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1
West Boynton Park and Recreation Center	257	Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
West Boynton Park and Recreation Center	258	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	259	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	260	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Adjust stall door to be self-closing.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	261	Women's Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	262	Women's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	263	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	264	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
West Boynton Park and Recreation Center	265	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	266	Heart Trail Elements and Surface (Wood Chip)	Outdoor - Trails (C)	Replace surface of trail with one that is firm and stable as a smart practice. In the alternative, leave as is and designate other County trails accessible.	\$59.20	5544	lin ft	\$328,204.80	4
West Boynton Park and Recreation Center	267	Heart Trail Elements and Surface (Wood Chip)	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element. Cost in trail surface finding. In the alternative, leave as is and designate other County fitness amenities accessible.	\$0.00	1	each	\$0.00	4
West Boynton Park and Recreation Center	268	Public Spaces	Plumbing Fixtures & Elements	Relocate vending machine to provide 30" wide clear floor space centered on the low bowl drinking fountain.	\$0.00	1	staff time	\$0.00	2
West Boynton Park and Recreation Center	269	Public Spaces	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$994.50	1	each	\$994.50	1
West Boynton Park and Recreation Center	270	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	271	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	1	each	\$2,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	272	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$1,756.25	1	each	\$1,756.25	1
West Boynton Park and Recreation Center	273	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	3	each	\$1,050.00	1
West Boynton Park and Recreation Center	274	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$1,690.00	1	each	\$1,690.00	1
West Boynton Park and Recreation Center	275	Public Spaces	Doors	<p>For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.</p>	\$0.00	2	staff time	\$0.00	1
West Boynton Park and Recreation Center	276	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$693.00	2	each	\$1,386.00	1
West Boynton Park and Recreation Center	277	Public Spaces	Accessible Routes	Relocate items to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	278	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	279	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	280	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
West Boynton Park and Recreation Center	281	Public Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim. Replace grate with one having max openings of 1/2 inch.	\$2,520.00	1	each	\$2,520.00	1
West Boynton Park and Recreation Center	282	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$1,690.00	1	each	\$1,690.00	1
West Boynton Park and Recreation Center	283	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	284	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	285	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, provide beveled threshold.</p>	\$630.00	2	each	\$1,260.00	1
West Boynton Park and Recreation Center	286	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$3,202.50	1	each	\$3,202.50	1
West Boynton Park and Recreation Center	287	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p>	\$3,202.50	1	each	\$3,202.50	1
West Boynton Park and Recreation Center	288	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p>	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	289	Employee Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	290	Employee Spaces	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	3
West Boynton Park and Recreation Center	291	Employee Spaces	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.  Remove, or relocate storage in CFS at fixtures and operable parts along the AR.	\$2,380.00	1	each	\$2,380.00	3
West Boynton Park and Recreation Center	292	Employee Spaces	Doors	Provide required maneuvering clearance on push and pull side of doors/gate.  Correct slope in door/gate clearance to max 2.08%.  Repair, bevel, or ramp CILs at entries to max .25".  Inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$3,255.00	1	each	\$3,255.00	3
West Boynton Park and Recreation Center	293	Employee Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$1,482.25	1	each	\$1,482.25	3
West Boynton Park and Recreation Center	294	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain closing speed on door closers.	\$1,750.00	1	each	\$1,750.00	3
West Boynton Park and Recreation Center	295	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	296	Employee Spaces	Room/Space (C)	Inspect, adjust, and maintain 5 lbf to open interior doors. Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	297	Employee Spaces	Doors	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	298	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors.	\$0.00	2	staff time	\$0.00	3
West Boynton Park and Recreation Center	299	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	1	each	\$1,386.00	3
West Boynton Park and Recreation Center	300	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Remount hardware to be 34" to 48" AFF.	\$350.00	1	each	\$350.00	3
West Boynton Park and Recreation Center	301	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Remount hardware to be 34" to 48" AFF.	\$350.00	1	each	\$350.00	3
West Boynton Park and Recreation Center	302	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	303	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$3,648.75	1	each	\$3,648.75	1
West Boynton Park and Recreation Center	304	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$490.00	1	each	\$490.00	1
West Boynton Park and Recreation Center	305	Interior Accessible Route	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
West Boynton Park and Recreation Center	306	Interior Accessible Route	Accessible Routes	<p>Fill and maintain gaps to max .5".</p> <p>Repair, bevel or ramp CIL along accessible route (AR) to max .25".</p>	\$96.25	4	each	\$385.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	308	Interior Accessible Route	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	2
West Boynton Park and Recreation Center	309	Interior Accessible Route	Reach Ranges	Remount flyer holder shelves to be in reach range of 15" min to 48" max.	\$350.00	1	staff time	\$350.00	1
West Boynton Park and Recreation Center	310	Interior Accessible Route	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	311	Interior Accessible Route	Dining, Bar and Work Surfaces	Replace 5% of the tables with ones providing the required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
West Boynton Park and Recreation Center	312	Interior Accessible Route	Accessible Routes	Fill and maintain gaps to max .5".	\$96.25	1	each	\$96.25	1
West Boynton Park and Recreation Center	313	Game Room	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	314	Game Room	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	315	Game Room	Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	316	Game Room	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	2	staff time	\$0.00	3
West Boynton Park and Recreation Center	317	Game Room	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,666.00	1	each	\$1,666.00	1
West Boynton Park and Recreation Center	318	Gym	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	319	Gym	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	320	Gym	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	321	Gym	Doors	Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	2	each	\$2,772.00	1
West Boynton Park and Recreation Center	322	Gym	Accessible Routes	Secure rug to prevent trip hazard.	\$140.00	1	each	\$140.00	1
West Boynton Park and Recreation Center	323	Gym	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	324	Gym	Doors	Remove door hold open device to provide a smooth surface on the push side of door from floor to 10" AFF. Cost in next finding.	\$0.00	2	staff time	\$0.00	1
West Boynton Park and Recreation Center	325	Gym	Doors	Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,386.00	2	each	\$2,772.00	1
West Boynton Park and Recreation Center	327	Gym	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.	\$2,912.00	1	each	\$2,912.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	328	Gym	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$2,912.00	1	each	\$2,912.00	1
West Boynton Park and Recreation Center	329	Gym	Protruding Object	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	5	each	\$1,750.00	1
West Boynton Park and Recreation Center	330	Gym	Doors	<p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$306.25	1	each	\$306.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	331	Gym	Doors	For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$306.25	1	each	\$306.25	1
West Boynton Park and Recreation Center	332	Women's Lobby Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	333	Women's Lobby Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	334	Women's Lobby Restroom	Toilet and Bathing Rooms	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	335	Women's Lobby Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	336	Women's Lobby Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area.	\$77.00	1	each	\$77.00	1
West Boynton Park and Recreation Center	337	Women's Lobby Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
West Boynton Park and Recreation Center	338	Women's Lobby Restroom	Toilet and Bathing Rooms	Relocate hand dryer to provide required 60" clearance around toilet.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	339	Women's Lobby Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	340	Women's Lobby Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	341	Women's Lobby Restroom	Toilet and Bathing Rooms	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	342	Women's Lobby Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	343	Women's Lobby Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	344	Women's Lobby Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$233.25	3	each	\$699.75	1
West Boynton Park and Recreation Center	345	Men's Lobby Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.  Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	346	Men's Lobby Restroom	Plumbing Fixtures & Elements	Relocate privacy wall at urinal to provide 30" CFS.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	347	Men's Lobby Restroom	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
West Boynton Park and Recreation Center	348	Men's Lobby Restroom	Toilet and Bathing Rooms	Relocate lavatory to provide required 60" clearance around toilet.	\$2,749.25	1	each	\$2,749.25	1
West Boynton Park and Recreation Center	349	Men's Lobby Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	350	Men's Lobby Restroom	Toilet and Bathing Rooms	Remount hand dryer 15" to 48" above the finished floor (AFF) and min 12" above grab bar.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	351	Men's Lobby Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
West Boynton Park and Recreation Center	352	Men's Lobby Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$420.00	1	each	\$420.00	1
West Boynton Park and Recreation Center	353	Men's Lobby Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	354	Men's Lobby Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$233.25	3	each	\$699.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	355	Men's Lobby Restroom	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	356	Men's Lobby Restroom	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	357	Staff Only Women's Restroom By Room B	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	358	Staff Only Women's Restroom By Room B	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	359	Staff Only Women's Restroom By Room B	Toilet and Bathing Rooms	Relocate trash bin & paper towels to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	360	Staff Only Women's Restroom By Room B	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	361	Staff Only Women's Restroom By Room B	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	362	Staff Only Women's Restroom By Room B	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	363	Staff Only Women's Restroom By Room B	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	364	Staff Only Women's Restroom By Room B	Doors	Provide required maneuvering clearance on push side of door.	\$1,750.00	1	each	\$1,750.00	1
West Boynton Park and Recreation Center	365	Staff Only Men's Restroom By Room B	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
West Boynton Park and Recreation Center	366	Staff Only Men's Restroom By Room B	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	367	Staff Only Men's Restroom By Room B	Toilet and Bathing Rooms	Relocate garbage bin and paper towel dispenser to provide required 60" clearance around toilet.	\$0.00	2	staff time	\$0.00	1
West Boynton Park and Recreation Center	368	Staff Only Men's Restroom By Room B	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	369	Staff Only Men's Restroom By Room B	Turning Space	Relocate obstacles to create turning space in restroom.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	370	Staff Only Men's Restroom By Room B	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	371	Staff Only Men's Restroom By Room B	Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	1
West Boynton Park and Recreation Center	372	Office Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	373	Office Men's Restroom	Reach Ranges	Remount outlet to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	374	Office Men's Restroom	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	375	Office Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	376	Office Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	377	Office Men's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	378	Office Men's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	379	Office Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	380	Office Women's Restroom	Toilet and Bathing Rooms	Relocate items to provide required 60" clearance around toilet.	\$175.00	2	each	\$350.00	1
West Boynton Park and Recreation Center	381	Office Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	382	Office Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	383	Office Women's Restroom	Reach Ranges	Remount outlet to be in reach range of 15" min to 48" max	\$350.00	1	each	\$350.00	1
West Boynton Park and Recreation Center	384	Office Women's Restroom	Doors	Inspect, adjust, and maintain 5 lbf to open doors.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	385	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	386	Employee Spaces	Accessible Routes	Widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	387	Employee Spaces	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	3
West Boynton Park and Recreation Center	388	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	390	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3
West Boynton Park and Recreation Center	391	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$1,750.00	1	each	\$1,750.00	3
West Boynton Park and Recreation Center	392	Men's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	393	Men's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	394	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Boynton Park and Recreation Center	395	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate extra toilet paper rolls 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Boynton Park and Recreation Center	396	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	397	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	398	Women's Restroom	Reach Ranges	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	399	Women's Restroom	Toilet and Bathing Rooms	Relocate scale to provide required 60" clearance around toilet.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	400	Women's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Boynton Park and Recreation Center	401	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Relocate extra toilet paper rolls 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	402	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	403	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Boynton Park and Recreation Center	404	Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.	\$3,500.00	1	each	\$3,500.00	1
West Boynton Park and Recreation Center	405	Women's Restroom	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Replace doors with doors having 80" overhead clearance and 32" clear width.	\$2,772.50	1	each	\$2,772.50	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Delray Regional Park	1	Group Camping Area - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
West Delray Regional Park	2	Group Camping Area - Picnic Area	Outdoor - Constructed Features (C)	Provide required 36" clear ground space around all usable portions of the table as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$2,486.00	2	each	\$4,972.00	4
West Delray Regional Park	3	Group Camping Area - Picnic Area	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (two tables, 1 grill, garbage, water spigots).  In the alternative, leave as is and designate other County picnic areas accessible.	\$59.20	50	lin ft	\$2,960.00	4
West Delray Regional Park	4	Group Camping Area - Portable Restroom	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	5	Group Camping Area - Camping	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to camp sites and one of each type of amenity.	\$59.20	70	lin ft	\$4,144.00	5
West Delray Regional Park	6	Group Camping Area - Camping	Outdoor - Constructed Features (C)	Correct fire building surface to be 9" min above the ground as a smart practice. In the alternative, replace fire ring with a compliant accessible fire ring.	\$750.00	1	each	\$750.00	5
West Delray Regional Park	7	Group Camping Area - Camping	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
West Delray Regional Park	8	Disk Golf	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
West Delray Regional Park	9	Disk Golf	Park Site (C)	Relocate 20% of garbage cans to be along AR.	\$0.00	1	staff time	\$0.00	2
West Delray Regional Park	10	Disk Golf	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	1	each	\$840.00	5
West Delray Regional Park	11	Disk Golf	Picnic Tables (C)	Replace both picnic tables with ones with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table.	\$1,120.00	2	each	\$2,240.00	5
West Delray Regional Park	12	Disk Golf	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
West Delray Regional Park	13	Picnic Area Near South Mountain Bike Trail Entrance	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (two tables, 2 grills, garbage, water spigots).  In the alternative, leave as is and designate other County picnic areas accessible.	\$59.20	100	lin ft	\$5,920.00	4
West Delray Regional Park	14	Picnic Area Near South Mountain Bike Trail Entrance	Clear Floor Space	Correct or repair slope in CFS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Delray Regional Park	15	Picnic Area Near South Mountain Bike Trail Entrance	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	16	Picnic Area Near South Mountain Bike Trail Entrance	Parking - Off Street	Create two or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	2	each	\$3,178.00	1
West Delray Regional Park	17	Park Elements	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
West Delray Regional Park	18	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	450	lin ft	\$26,640.00	2
West Delray Regional Park	19	Park Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	330	lin ft	\$19,536.00	2
West Delray Regional Park	21	Parking - RC Helipads	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
West Delray Regional Park	22	Parking - RC Helipads	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	23	Parking - RC Helipads	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	2	each	\$6,125.00	1
West Delray Regional Park	24	Parking - RC Helipads	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1
West Delray Regional Park	25	Parking - RC Helipads	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	27	Parking - RC Airfield	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	2	each	\$147.00	1
West Delray Regional Park	28	Parking - RC Airfield	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	29	Parking - RC Airfield	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction. In the alternative, leave as is citing construction tolerance.	\$3,062.50	1	each	\$3,062.50	4
West Delray Regional Park	30	Parking - RC Airfield	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	31	Parking - RC Airfield	Parking - Off Street	Raise existing accessible parking signs so lowest end of bottom sign is min 60" above ground level (AGL) measured from the surface of the stall.	\$0.00	2	staff time	\$0.00	1
West Delray Regional Park	32	RC Auto Racing Site - Parking	Parking - Off Street	Create one or more 12' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	\$1,589.00	1	each	\$1,589.00	1
West Delray Regional Park	33	RC Boating	Park Site (C)	Provide an accessible route (AR) to each element within the site.  Remount operable parts to be in reach range of 15" min to 48" max.	\$59.20	5	lin ft	\$296.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Delray Regional Park	34	RC Boating	Park Site (C)	Provide an accessible route (AR) to each element within the site. Replace surface in shelter with one that is firm and stable.	\$10,262.00	1	each	\$10,262.00	3
West Delray Regional Park	35	RC Airfield	Outdoor - Constructed Features (C)	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	\$840.00	3	each	\$2,520.00	5
West Delray Regional Park	36	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site. Remount operable parts to be in reach range of 15" min to 48" max.	\$59.20	5	lin ft	\$296.00	2
West Delray Regional Park	37	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	40	lin ft	\$2,368.00	2
West Delray Regional Park	38	RC Airfield	Doors	For all doors along the public circulation route, replace hardware with hardware operable without a tight pinch or grasp.	\$514.50	1	each	\$514.50	1
West Delray Regional Park	39	RC Airfield	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
West Delray Regional Park	41	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site.	\$59.20	100	lin ft	\$5,920.00	2
West Delray Regional Park	42	RC Airfield	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".	\$12,345.00	1	each	\$12,345.00	1
West Delray Regional Park	43	RC Airfield	Turning Space	Widen space within building to provide 60" turning space if feasible.	\$25,000.00	1	each	\$25,000.00	3
West Delray Regional Park	44	RC Airfield	Park Site (C)	Provide an accessible route (AR) to each element within the site. Replace surface in shelter with one that is firm and stable.	\$29,884.00	1	each	\$29,884.00	3
West Delray Regional Park	45	RC Airfield	Picnic Tables (C)	Replace one standard picnic table with one of an accessible design as a smart practice.  Provide required 36" clear ground space around all usable portions of the table as a smart practice.	\$3,606.00	1	each	\$3,606.00	5
West Delray Regional Park	46	RC Airfield	Outdoor Recreation Access Routes (C)	Repair surface or ORAR to be firm and stable as a smart practice.	\$59.20	25	lin ft	\$1,480.00	5





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Delray Regional Park	47	RC Airfield	Dining, Bar and Work Surfaces	Replace two tables in space with ones max 34" to surface and allowing knee and toe clearance.  Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$5,200.00	1	each	\$5,200.00	2
West Delray Regional Park	48	RC Airfield	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
West Delray Regional Park	49	RC Airfield Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	50	RC Airfield Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	51	RC Airfield Toilets	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	52	RC Auto Racing Site - Elements	Toilet and Bathing Rooms	Replace 5% of portable toilets with compliant models and place along AR.	\$1,092.00	1	each	\$1,092.00	1
West Delray Regional Park	53	RC Auto Racing Site - Elements	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to element.	\$59.20	200	lin ft	\$11,840.00	2
West Delray Regional Park	54	RC Auto Racing Site - Elements	Dining, Bar and Work Surfaces	Replace one table in indicated rooms with one max 34" to surface and allowing knee and toe clearance.	\$1,120.00	1	each	\$1,120.00	2
West Delray Regional Park	55	RC Auto Racing Site - Picnic Area	Picnic Units	Provide a firm and stable route within the picnic unit, connecting all associated elements (grills, garbage, water spigots).  Replace picnic table with one of an accessible design as a smart practice.  In the alternative, leave as is and designate other County picnic areas accessible.	\$2,896.00	1	each	\$2,896.00	4
West Delray Regional Park	57	Amateur Radio Operators Area - Parking Along Palm Beach Downs Road	Parking - Off Street	Relocate 1 stall to be on the shortest route to the building entry or park features.	\$367.50	1	each	\$367.50	1
West Delray Regional Park	58	Amateur Radio Operators Area - Parking Along Palm Beach Downs Road	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1
West Delray Regional Park	59	Amateur Radio Operators Area - Parking Along Palm Beach Downs Road	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
West Delray Regional Park	60	Amateur Radio Operators Area - Parking Along Palm Beach Downs Road	Parking - Off Street	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls.	\$210.00	2	each	\$420.00	1
West Delray Regional Park	61	Amateur Radio Operators Area - Parking Along Palm Beach Downs Road	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	63	Parking - Radio Operators Bldg	Parking - Off Street	Repaint access aisles to be 5' each.	\$73.50	1	each	\$73.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Delray Regional Park	64	Parking - Radio Operators Bldg	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
West Delray Regional Park	65	Radio Operators/Maintenance	Picnic Tables (C)	Replace one picnic table with one of an accessible design as a smart practice.	\$1,120.00	1	each	\$1,120.00	5
West Delray Regional Park	66	Trail - Surface	Outdoor - Trails (C)	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
West Delray Regional Park	67	Trail - Surface	Outdoor - Trails (C)	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice.  In the alternative, leave as is and designate other County trails accessible.	\$0.00	1	staff time	\$0.00	4
West Delray Regional Park	68	Maintenance Shed	Accessible Routes	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance.	\$59.20	100	lin ft	\$5,920.00	3
West Jupiter Recreation Center	2	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	1	each	\$73.50	1
West Jupiter Recreation Center	3	Parking	Parking - Off Street	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	\$3,062.50	3	each	\$9,187.50	1
West Jupiter Recreation Center	4	Parking	Parking - Off Street	Repair, bevel and ramp CIL in stalls and access aisles.	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
West Jupiter Recreation Center	6	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	7	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	8	Exterior Accessible Route	Curb Ramps	Correct curb ramp cross slope to max 2.08%.	\$1,015.00	1	each	\$1,015.00	1
West Jupiter Recreation Center	9	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.  Correct or fill gaps to be max .5".	\$96.25	2	each	\$192.50	1
West Jupiter Recreation Center	10	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
West Jupiter Recreation Center	11	Exterior Accessible Route	Accessible Routes	Resurface accessible route where deterioration occurs.	\$59.20	10	lin ft	\$592.00	1
West Jupiter Recreation Center	12	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
West Jupiter Recreation Center	13	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	14	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	15	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
West Jupiter Recreation Center	16	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
West Jupiter Recreation Center	17	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
West Jupiter Recreation Center	18	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	19	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	135	sq ft	\$16,537.50	1
West Jupiter Recreation Center	20	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	50	sq ft	\$6,125.00	1
West Jupiter Recreation Center	21	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	22	Exterior Accessible Route	Accessible Routes	Repair, bevel or ramp change in level along accessible route.	\$96.25	1	each	\$96.25	1
West Jupiter Recreation Center	23	Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$122.50	540	sq ft	\$66,150.00	1
West Jupiter Recreation Center	26	Exterior Elements At Recreation Center	Clear Floor Space	Relocate garbage cans along an accessible route with level CFS with slopes max 2.08%.	\$0.00	1	staff time	\$0.00	2
West Jupiter Recreation Center	27	Exterior Elements At Recreation Center	Outdoor Recreation Access Route	Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to picnic area/shelter and one of each type of amenity.	\$59.20	2	lin ft	\$118.40	5
West Jupiter Recreation Center	28	Exterior Elements At Recreation Center	Operable Parts	Adjust operating mechanism to be usable with 5 lbf or less as a smart practice.	\$210.00	1	each	\$210.00	5
West Jupiter Recreation Center	29	Exterior Elements At Recreation Center	Accessible Routes	Create an accessible route with crushed stone or other outdoor material from parking or walkway to garden.  Replace picnic table with one of an accessible design as a smart practice.  Create an outdoor recreation access route with crushed and compacted stone or similar outdoor material to at least one bench and picnic table as a smart practice.	\$11,776.00	1	each	\$11,776.00	2
West Jupiter Recreation Center	30	Exterior Elements At Recreation Center	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, remount hardware min 34" and max 48" AGL.	\$2,264.50	1	each	\$2,264.50	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	32	Park Elements	Plumbing Fixtures & Elements	Add second low bowl fountain for persons using wheelchairs	\$5,598.25	1	each	\$5,598.25	2
West Jupiter Recreation Center	33	Park Elements	Reach Ranges	Relocate garbage can along an accessible route and remount it so rim is in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
West Jupiter Recreation Center	35	Park Elements	Accessible Routes	Create a route to at least one picnic table and replace with one of a compliant model.	\$2,600.00	1	each	\$2,600.00	5
West Jupiter Recreation Center	36	Park Elements	Room/Space (C)	Replace doors with doors having 32" clear width.  Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	\$3,287.00	1	each	\$3,287.00	3
West Jupiter Recreation Center	37	5-12 Play Area	Play Area	Correct or repair running slope of designated entry to max 5%.  In the alternative, leave as is and designate other County playgrounds accessible.	\$122.50	50	sq ft	\$6,125.00	4
West Jupiter Recreation Center	38	5-12 Play Area	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
West Jupiter Recreation Center	39	5-12 Play Area	Play Area	Extend accessible play surface to provide AR to all GLPCs and EPCs.  In the alternative, leave as is and designate other County playgrounds accessible.	\$59.20	30	lin ft	\$1,776.00	4
West Jupiter Recreation Center	42	5-12 Play Area	Play Area	Add one or more GLPC of one or more additional types to meet incentive scoping.  Create route and correct surface type at swings. See previous findings for cost reference for swing corrections.  In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
West Jupiter Recreation Center	43	Park Women's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door (closer to door opening), 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	44	Park Women's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
West Jupiter Recreation Center	45	Park Women's Restroom	Toilet and Bathing Rooms	Remount toilet to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Jupiter Recreation Center	46	Park Women's Restroom	Toilet and Bathing Rooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" above the finished floor (AFF).	\$1,828.40	1	each	\$1,828.40	1
West Jupiter Recreation Center	47	Park Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	48	Park Women's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, remount hardware min 34" and max 48".	\$9,667.50	1	each	\$9,667.50	1
West Jupiter Recreation Center	49	Park Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted a min 34" and max 48".	\$9,667.50	1	each	\$9,667.50	1
West Jupiter Recreation Center	50	Park Men's Restroom	Toilet and Bathing Rooms	Remount signage on wall, latch side of the door (closer to door opening), 48" to baseline of lowest character and 60" to baseline of highest character.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	51	Park Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	52	Park Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under sink.	\$77.00	1	each	\$77.00	1
West Jupiter Recreation Center	53	Park Men's Restroom	Plumbing Fixtures & Elements	Widen accessible stalls to min. 60" clear width, 56" depth.	\$2,749.25	1	each	\$2,749.25	1
West Jupiter Recreation Center	54	Park Men's Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.  Pricing in the previous finding.	\$0.00	1	N/A	\$0.00	1
West Jupiter Recreation Center	55	Park Men's Restroom	Toilet and Bathing Rooms	Remount toilet to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Jupiter Recreation Center	56	Park Men's Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Jupiter Recreation Center	57	Park Men's Restroom	Plumbing Fixtures & Elements	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
West Jupiter Recreation Center	58	Park Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	59	Park Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	60	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$612.50	1	each	\$612.50	1
West Jupiter Recreation Center	61	Interior Accessible Route	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$612.50	1	each	\$612.50	1
West Jupiter Recreation Center	62	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
West Jupiter Recreation Center	63	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	2
West Jupiter Recreation Center	64	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	1	each	\$350.00	2
West Jupiter Recreation Center	65	Public Spaces	Protruding Object	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$350.00	1	each	\$350.00	1
West Jupiter Recreation Center	66	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	2
West Jupiter Recreation Center	67	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max	\$0.00	1	staff time	\$0.00	2



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	68	Public Spaces	Doors	Mount signage at entrance designating it as accessible.	\$210.00	1	each	\$210.00	1
West Jupiter Recreation Center	69	Public Spaces	Signs	Replace Braille on sign and place Braille below the entire text, Braille shall not be broken up by line.	\$210.00	4	each	\$840.00	1
West Jupiter Recreation Center	70	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	71	Public Spaces	Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the right side of the door.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	72	Public Spaces	Signs	Mount compliant tactile exit signage at all doors along the egress route.	\$210.00	8	each	\$1,680.00	1
West Jupiter Recreation Center	73	Public Spaces	Sales and Service Counters/Tables	Lower 36" wide segment of service counter to max 36".	\$1,099.00	1	each	\$1,099.00	1
West Jupiter Recreation Center	74	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,380.00	1	each	\$1,380.00	3
West Jupiter Recreation Center	75	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Replace doors with ones having sidelight viewing windows max 43" AFF.	\$1,380.00	1	each	\$1,380.00	3
West Jupiter Recreation Center	76	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	77	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$3,230.00	1	each	\$3,230.00	1
West Jupiter Recreation Center	78	Gymnasium	Doors	Inspect, adjust, and maintain closing speed on door closers.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	79	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$2,900.00	1	each	\$2,900.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	80	Gymnasium	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$2,900.00	1	each	\$2,900.00	1
West Jupiter Recreation Center	81	Gymnasium	Accessible Routes	Relocate storage and bleachers to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	82	Gymnasium	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	83	Gymnasium	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
West Jupiter Recreation Center	84	Gymnasium	Clear Floor Space	Remove objects or widen CFS to min 30" clear width.	\$0.00	1	staff time	\$0.00	2
West Jupiter Recreation Center	85	Gymnasium	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
West Jupiter Recreation Center	86	Gymnasium	Assembly Areas	Relocate items to provide a number of wheelchair accessible spaces with companion seats based on the capacity of the bleachers.	\$629.50	4	each	\$2,518.00	2
West Jupiter Recreation Center	87	Meeting Rooms	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p>	\$140.00	1	each	\$140.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	88	Meeting Rooms	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$3,230.00	1	each	\$3,230.00	1
West Jupiter Recreation Center	89	Meeting Rooms	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$1,380.00	1	each	\$1,380.00	1
West Jupiter Recreation Center	90	Meeting Rooms	Hazards	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	91	Meeting Rooms	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	92	Meeting Rooms	Operable Parts	Replace operable part with one usable without a tight pinch or grasp	\$210.00	1	each	\$210.00	1
West Jupiter Recreation Center	93	Meeting Rooms	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" AFF with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
West Jupiter Recreation Center	94	Meeting Rooms	Plumbing Fixtures & Elements	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	\$2,380.00	3	each	\$7,140.00	1
West Jupiter Recreation Center	95	Meeting Rooms	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.</p>	\$1,380.00	1	each	\$1,380.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	96	Meeting Rooms	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$3,702.50	1	each	\$3,702.50	1
West Jupiter Recreation Center	97	Meeting Rooms	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	98	Men's Multiuser Restroom	Toilet and Bathing Rooms	Restroom not accessible, leave as is until next altered as users are directed to accessible restroom.	\$0.00	1	staff time	\$0.00	4
West Jupiter Recreation Center	99	Men's Multiuser Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p>	\$1,750.00	1	each	\$1,750.00	1
West Jupiter Recreation Center	100	Women's Multiuser Restroom	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>Reverse the doors to swing opposite from each other to provide required maneuvering space.</p>	\$5,395.25	1	each	\$5,395.25	1
West Jupiter Recreation Center	101	Women's Multiuser Restroom	Toilet and Bathing Rooms	Restroom not accessible, leave as is until next altered as users are directed to accessible restroom.	\$0.00	1	staff time	\$0.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	102	Men's Single User Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	103	Men's Single User Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
West Jupiter Recreation Center	104	Men's Single User Restroom	Reach Ranges	Lower operating mechanisms to max 44" above the finished floor (AFF) for a forward reach over toilet.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	105	Men's Single User Restroom	Toilet and Bathing Rooms	Remount toilet to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
West Jupiter Recreation Center	106	Men's Single User Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Jupiter Recreation Center	107	Men's Single User Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Jupiter Recreation Center	108	Men's Single User Restroom	Toilet and Bathing Rooms	Remount grab bar so it has min 1.5" clearance under bar and min 12" above bar. Pricing for remounting rear grab bar in previous finding.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	109	Men's Single User Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF, and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	110	Men's Single User Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	111	Men's Single User Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  Relocate toilet seat cover dispenser to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	112	Men's Single User Restroom	Toilet and Bathing Rooms	Relocate garbage can and hand dryer to provide required 60" clearance around toilet.  Relocate sink to provide required 60" by 56" clearance at toilet; leave as if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,730.00	1	each	\$2,730.00	1
West Jupiter Recreation Center	113	Men's Single User Restroom	Signs	Mount proper signage identifying the employee identified restroom as "open for public use for individuals with disabilities". Ensure the accessible restroom has the same hours of operation and process for use as other public restrooms within the facility. In the alternative, remove the 'employees only' sign to provide accessible toileting for public use.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
West Jupiter Recreation Center	114	Women's Single User Restroom	Toilet and Bathing Rooms	Replace mirror mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
West Jupiter Recreation Center	115	Women's Single User Restroom	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR.  Relocate toilet seat cover dispenser to provide required 30" by 48" CFS at operable parts.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	116	Women's Single User Restroom	Toilet and Bathing Rooms	Relocate garbage can to provide required 60" clearance around toilet.  Relocate sink to provide required 60" by 56" clearance at toilet; leave as if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
West Jupiter Recreation Center	117	Women's Single User Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Jupiter Recreation Center	118	Women's Single User Restroom	Toilet and Bathing Rooms	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	\$393.75	1	each	\$393.75	1
West Jupiter Recreation Center	119	Women's Single User Restroom	Toilet and Bathing Rooms	Remount toilet seat cover dispenser a min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	120	Women's Single User Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	121	Women's Single User Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	122	Women's Single User Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
West Jupiter Recreation Center	123	Women's Single User Restroom	Signs	Mount proper signage identifying the employee identified restroom as "open for public use for individuals with disabilities". Ensure the accessible restroom has the same hours of operation and process for use as other public restrooms within the facility. In the alternative, remove the 'employees only' sign to provide accessible toileting for public use.	\$210.00	1	each	\$210.00	1
<a href="#">Westgate Park and Recreation Center</a>	2	Parking	Parking - Off Street	Consider relocating at least one stall to closer to the recreation building and provide curb ramp connecting access aisle to accessible route.	\$1,855.00	1	each	\$1,855.00	5
Westgate Park and Recreation Center	3	Parking	Parking - Off Street	Repaint stalls to be 12' wide each.	\$73.50	2	each	\$147.00	1
Westgate Park and Recreation Center	4	Parking	Parking - Off Street	Establish protocols for regular and frequent inspection and maintenance of parking surfaces.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	5	Parking	Parking - Off Street	Add one van parking sign to one accessible stall and ensure stall and access aisle are 12' and 5'.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	6	Parking	Parking - Off Street	Repaint stall and access aisle using a high quality blue paint. Paint access aisle with diagonal lines to indicate no parking.	\$73.50	3	each	\$220.50	1
Westgate Park and Recreation Center	7	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$4,812.50	1	each	\$4,812.50	1
Westgate Park and Recreation Center	8	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Westgate Park and Recreation Center	9	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	300	sq ft	\$36,750.00	1
Westgate Park and Recreation Center	10	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	1000	sq ft	\$122,500.00	1
Westgate Park and Recreation Center	11	Exterior Accessible Route	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	12	Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.	\$2,100.00	1	each	\$2,100.00	1
Westgate Park and Recreation Center	13	Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$3,062.50	1	each	\$3,062.50	1
Westgate Park and Recreation Center	14	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Westgate Park and Recreation Center	15	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	1	each	\$329.00	5
Westgate Park and Recreation Center	16	Exterior Accessible Route	Detectable Warnings	Install detectable warning where accessible route crosses the vehicular way as a smart practice.	\$329.00	2	each	\$658.00	5
Westgate Park and Recreation Center	17	Exterior Accessible Route	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	1
Westgate Park and Recreation Center	18	Park Elements	Accessible Routes	Relocate 20% of garbage cans to be along accessible route (AR).	\$0.00	1	staff time	\$0.00	2
Westgate Park and Recreation Center	20	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County rectangular fields accessible.	\$59.20	35	lin ft	\$2,072.00	4
Westgate Park and Recreation Center	21	Sports Courts/Fields	Park Site (C)	Provide an accessible route (AR) to each element within the site. In the alternative, leave as is and designate other County ball fields accessible.	\$59.20	575	lin ft	\$34,040.00	4





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	23	Pavilion	Outdoor Recreation Access Routes (C)	Correct or fill gaps along the ORAR to max .5" as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$96.25	1	each	\$96.25	4
Westgate Park and Recreation Center	24	Pavilion	Picnic Tables (C)	Replace picnic table with one of an accessible design as a smart practice. In the alternative, leave as is and designate other County shelters accessible.	\$1,120.00	1	each	\$1,120.00	4
Westgate Park and Recreation Center	25	Pavilion	Shelters/Picnic Areas (C)	Replace or lower grill to max height of cooking surface 34" as a smart practice.  Remount or add garbage bin at max 48" to opening.  In the alternative, leave as is and designate other County shelters accessible.	\$175.00	2	each	\$350.00	4
Westgate Park and Recreation Center	26	Splash Pad	Accessible Routes	Correct or fill gaps to be max .5".	\$96.25	1	each	\$96.25	2
Westgate Park and Recreation Center	27	Splash Pad	Outdoor - Constructed Features (C)	Correct surface at table to firm, stable and having max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.	\$122.50	25	sq ft	\$3,062.50	5
Westgate Park and Recreation Center	28	Splash Pad	Clear Floor Space	Correct or repair slope in CFS to max 2.08%. Pricing addressed in another finding.	\$0.00	1	each	\$0.00	2
Westgate Park and Recreation Center	29	Splash Pad	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	875	sq ft	\$107,187.50	2
Westgate Park and Recreation Center	30	Splash Pad	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$1,890.00	1	each	\$1,890.00	2
Westgate Park and Recreation Center	31	Splash Pad	Outdoor - Constructed Features (C)	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	\$540.75	1	each	\$540.75	5
Westgate Park and Recreation Center	33	Play Area (2-5)	Play Area	Create designated entry min 36" wide as a smart practice.	\$700.00	1	each	\$700.00	5
Westgate Park and Recreation Center	34	Play Area (2-5)	Play Area	Correct or repair ground ramp slope to be max 6.25%.	\$122.50	25	sq ft	\$3,062.50	2
Westgate Park and Recreation Center	35	Play Area (2-5)	Accessible Routes	Correct or repair cross slope along accessible route to max 2.08%.	\$122.50	75	sq ft	\$9,187.50	2
Westgate Park and Recreation Center	37	Play Area (5-12)	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	38	Play Area (5-12)	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Westgate Park and Recreation Center	39	Play Area (5-12)	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$7,000.00	1	each	\$7,000.00	4
Westgate Park and Recreation Center	40	Play Area (5-12)	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Westgate Park and Recreation Center	41	Childcare Area Playground	Play Area	Provide designated entry min 36" wide that is free of CIL and gaps. In the alternative, leave as is and designate other County playgrounds accessible.	\$700.00	1	each	\$700.00	4
Westgate Park and Recreation Center	42	Childcare Area Playground	Play Area	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs. In the alternative, leave as is and designate other County playgrounds accessible.	\$70,000.00	1	each	\$70,000.00	4
Westgate Park and Recreation Center	43	Childcare Area Playground	Accessible Routes	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces. In the alternative, leave as is and designate other County playgrounds accessible.	\$7,000.00	1	each	\$7,000.00	4
Westgate Park and Recreation Center	44	Childcare Area Playground	Play Area	See previous finding for surface correction. In the alternative, leave as is and designate other County playgrounds accessible.	\$0.00	1	each	\$0.00	4
Westgate Park and Recreation Center	45	Childcare Area Playground	Play Area	Install raised sand table with knee clearance or provide a means of transfer to the sand surface as a smart practice. In the alternative, leave as is and designate other County playgrounds accessible.	\$2,800.00	1	each	\$2,800.00	4
Westgate Park and Recreation Center	46	Play Area Exterior Accessible Route	Accessible Route - Slope (C)	Correct cross slopes to max 2.08%.	\$122.50	115	sq ft	\$14,087.50	1
Westgate Park and Recreation Center	47	Play Area Exterior Accessible Route	Accessible Route - Slope (C)	Correct running slopes to max 5%.	\$3,062.50	1	each	\$3,062.50	1
Westgate Park and Recreation Center	48	Play Area Exterior Accessible Route	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.	\$6,562.50	1	each	\$6,562.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	49	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, correct slope in door/gate clearance to max 2.08%.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$4,121.25	1	each	\$4,121.25	1
Westgate Park and Recreation Center	50	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates as a smart practice.</p> <p>For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.</p>	\$332.50	1	each	\$332.50	1
Westgate Park and Recreation Center	51	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	52	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	53	Public Spaces	Operable Parts	Replace operable part with one usable without a tight pinch or grasp.	\$210.00	2	each	\$420.00	1
Westgate Park and Recreation Center	54	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	4	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	55	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.  Leave as is locks on cabinets if operated by employees only.	\$210.00	2	each	\$420.00	1
Westgate Park and Recreation Center	56	Public Spaces	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	57	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	3	staff time	\$0.00	1
Westgate Park and Recreation Center	58	Public Spaces	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	1	each	\$140.00	1
Westgate Park and Recreation Center	59	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	4	staff time	\$0.00	1
Westgate Park and Recreation Center	60	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$200.00	7	each	\$1,400.00	1
Westgate Park and Recreation Center	61	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$350.00	2	each	\$700.00	1
Westgate Park and Recreation Center	62	Public Spaces	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	5	each	\$700.00	1
Westgate Park and Recreation Center	64	Public Spaces	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Westgate Park and Recreation Center	65	Public Spaces	Clear Floor Space	Relocate drinking fountain to an area where clear space does not overlap door swings.	\$2,380.00	1	each	\$2,380.00	1
Westgate Park and Recreation Center	66	Public Spaces	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Westgate Park and Recreation Center	67	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	68	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	69	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Westgate Park and Recreation Center	71	Public Spaces	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	72	Public Spaces	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, replace doors/gates with ones having sidelight viewing windows max 43" AFF.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$580.50	4	each	\$2,322.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	73	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$735.00	1	each	\$735.00	1
Westgate Park and Recreation Center	74	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.</p> <p>For all doors along the public circulation route, remount hardware to be 34" to 48" AFF.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.</p>	\$5,895.00	1	each	\$5,895.00	1
Westgate Park and Recreation Center	75	Public Spaces	Doors	<p>For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p>	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	76	Employee Spaces	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	\$0.00	2	staff time	\$0.00	3
Westgate Park and Recreation Center	77	Employee Spaces	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	78	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" above the finished floor (AFF).</p>	\$0.00	1	staff time	\$0.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	79	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Replace doors with doors having 80" overhead clearance and 32" clear width.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.</p> <p>Remount hardware to height between 34" and 48" AFF.</p>	\$4,604.25	3	each	\$13,812.75	3
Westgate Park and Recreation Center	80	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p>	\$1,846.25	1	each	\$1,846.25	3
Westgate Park and Recreation Center	81	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Repair, bevel, or ramp CILs at door entries to max .25".</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Where exit signage exists, mount compliant exit signage at all doors along the egress route.</p> <p>Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.</p>	\$3,615.00	1	each	\$3,615.00	3
Westgate Park and Recreation Center	82	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p>	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	83	Employee Spaces	Room/Space (C)	<p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Remount hardware to be 34" to 48" AFF.</p>	\$350.00	1	each	\$350.00	3



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	84	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p> <p>Correct slope in door clearance to max 2.08%.</p> <p>Inspect, adjust, and maintain 5 lbf to open interior doors.</p> <p>Inspect, adjust, and maintain 8.5 lbf to open exterior doors.</p> <p>Replace hardware with lever hardware or hardware operable without a tight pinch or grasp and having a max profile of 4".</p> <p>Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.</p>	\$4,546.50	3	each	\$13,639.50	3
Westgate Park and Recreation Center	85	Employee Spaces	Room/Space (C)	<p>For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.</p> <p>Provide required maneuvering clearance on push and pull side of doors.</p>	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	86	Men's Restroom	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	87	Men's Restroom	Plumbing Fixtures & Elements	Insulate exposed pipes under one sink in main area and sink in stall.	\$77.00	2	each	\$154.00	1
Westgate Park and Recreation Center	88	Men's Restroom	Plumbing Fixtures & Elements	Relocate or add a urinal in a location that provides 30" X 48" CFS for a forward approach.	\$2,978.50	1	each	\$2,978.50	1
Westgate Park and Recreation Center	89	Men's Restroom	Plumbing Fixtures & Elements	Lower flush handle at urinal to max 48" AFF.	\$1,704.50	1	each	\$1,704.50	1
Westgate Park and Recreation Center	90	Men's Restroom	Reach Ranges	<p>Lower paper towel dispenser in stall and 1 of 2 in main area to max 48" above the finished floor (AFF) to highest operable part.</p> <p>Lower soap dispenser and fixed paper towel dispenser to max 44" above the finished floor (AFF) for a forward reach over sink or counter.</p> <p>Lower the baby changer to max 48" to the handle and 34" to the work surface when open.</p>	\$70.00	5	each	\$350.00	1
Westgate Park and Recreation Center	91	Men's Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	92	Men's Restroom	Toilet and Bathing Rooms	Relocate changing table to provide required min 59" deep clearance around toilet.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15 2012 as this meets safe harbor.	\$2,730.00	1	each	\$2,730.00	1
Westgate Park and Recreation Center	93	Men's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Westgate Park and Recreation Center	94	Men's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Westgate Park and Recreation Center	95	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount soap dispenser a min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	96	Men's Restroom	Toilet and Bathing Rooms	Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	97	Men's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out an switch latch and hinge sides due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$420.00	1	each	\$420.00	1
Westgate Park and Recreation Center	98	Men's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	99	Men's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Westgate Park and Recreation Center	100	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Westgate Park and Recreation Center	101	Men's Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	102	Women's Restroom	Toilet and Bathing Rooms	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	\$0.00	1	staff time	\$0.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	103	Women's Restroom	Reach Ranges	Lower paper towel dispenser to max 48" above the finished floor (AFF) to highest operable part.  Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$175.00	2	each	\$350.00	1
Westgate Park and Recreation Center	104	Women's Restroom	Toilet and Bathing Rooms	Relocate changing table to provide required min 59" deep clearance around toilet. Pricing provided in a previous finding.  Relocate sink to provide required clearance around toilet; leave as is if restroom constructed or last renovated before March 15 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Westgate Park and Recreation Center	105	Women's Restroom	Toilet and Bathing Rooms	Remount toilets to 16" to 18" from the side wall to centerline.	\$1,828.40	1	each	\$1,828.40	1
Westgate Park and Recreation Center	106	Women's Restroom	Toilet and Bathing Rooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Westgate Park and Recreation Center	107	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.  Remount soap dispenser a min 12" above or 1.5" below grab bar.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	108	Women's Restroom	Plumbing Fixtures & Elements	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	\$295.75	1	each	\$295.75	1
Westgate Park and Recreation Center	109	Women's Restroom	Toilet and Bathing Rooms	Mount hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	110	Women's Restroom	Toilet and Bathing Rooms	Reverse stall door to swing out and to change hinge and latch sides due to lack of required depth for inward swinging door; in the alternative, enlarge stall to 92" depth for wall mounted toilet or 95" depth for floor mounted toilet.	\$420.00	1	each	\$420.00	1
Westgate Park and Recreation Center	111	Women's Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	112	Women's Restroom	Accessible Routes	Widen accessible route AR to compliant 36" clear width and provide min 48" deep clearance at sinks in main area.	\$2,749.25	1	each	\$2,749.25	1
Westgate Park and Recreation Center	113	Women's Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	114	Women's Restroom	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	115	Women's Restroom	Doors	For all doors/gates along the public circulation route, replace with doors/gates having 80" overhead clearance and 32" clear width.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$2,772.50	1	each	\$2,772.50	1
Westgate Park and Recreation Center	116	Daycare/Classrooms	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	117	Daycare/Classrooms	Dining, Bar and Work Surfaces	Adjust children's tables and work surfaces at 26" to 30" AFF with required knee clearance of 24" min AFF.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	118	Daycare/Classrooms	Toilet and Bathing Rooms	Provide CFS at sink with knee and toe clearance or provide a parallel approach for children 5 and under.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	119	Daycare/Classrooms	Dining, Bar and Work Surfaces	Ensure adjustable tables and work surfaces can be used at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	120	Daycare/Classrooms	Accessible Routes	Relocate furniture to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	121	Daycare/Classrooms	Accessible Routes	Relocate storage to widen AR to compliant 36" clear width.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	122	Daycare/Classrooms	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	124	Daycare/Classrooms	Plumbing Fixtures & Elements	Add second high bowl fountain for standing persons.	\$5,598.25	1	each	\$5,598.25	2
Westgate Park and Recreation Center	125	Daycare/Classrooms	Plumbing Fixtures & Elements	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	\$420.00	1	each	\$420.00	2
Westgate Park and Recreation Center	126	Daycare/Classrooms	Clear Floor Space	Correct or repair slope in CGS to max 2.08%.	\$122.50	25	sq ft	\$3,062.50	2
Westgate Park and Recreation Center	127	Daycare/Classrooms	Plumbing Fixtures & Elements	Raise drinking fountain to provide required 27" knee clearance.	\$2,380.00	1	each	\$2,380.00	2
Westgate Park and Recreation Center	128	Childcare Area Restroom (Classroom A Side)	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	129	Childcare Area Restroom (Classroom A Side)	Toilet and Bathing Rooms	Replace mirror and mount to max 40" AFF to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	130	Childcare Area Restroom (Classroom A Side)	Plumbing Fixtures & Elements	Adjust timing of sink faucets to remain on for min. 10 seconds.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	131	Childcare Area Restroom (Classroom A Side)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Westgate Park and Recreation Center	132	Childcare Area Restroom (Classroom A Side)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Westgate Park and Recreation Center	133	Childcare Area Restroom (Classroom A Side)	Doors	<p>For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.</p> <p>For all doors/gates along the public circulation route, repair, bevel, or ramp CILs at entries to max .25".</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).</p>	\$96.25	1	each	\$96.25	1
Westgate Park and Recreation Center	134	Childcare Area Restroom (Classroom A Side)	Reach Ranges	Remount hook to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	135	Childcare Area Restroom (Classroom B Side)	Doors	<p>For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.</p> <p>For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).</p>	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	136	Childcare Area Restroom (Classroom B Side)	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	137	Childcare Area Restroom (Classroom B Side)	Toilet and Bathing Rooms	Replace mirror mount to max 40" above the finished floor (AFF) to the bottom reflective surface and 74" to the top.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	138	Childcare Area Restroom (Classroom B Side)	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	139	Childcare Area Restroom (Classroom B Side)	Toilet and Bathing Rooms	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Westgate Park and Recreation Center	140	Childcare Area Restroom (Classroom B Side)	Accessible Routes	Correct or repair slope to max 2.08% in restroom.	\$3,062.50	1	each	\$3,062.50	1
Westgate Park and Recreation Center	141	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	142	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" above the finished floor (AFF).  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" AFF.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$490.00	1	each	\$490.00	1
Westgate Park and Recreation Center	144	Public Spaces	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	\$3,230.00	1	each	\$3,230.00	1
Westgate Park and Recreation Center	145	Public Spaces	Sales and Service Counters/Tables	Relocate fixed seating to ensure 36" wide segment of service counter to max 36" AFF.	\$1,099.00	1	each	\$1,099.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	146	Public Spaces	Reach Ranges	Lower fire extinguisher, vending machine controls, AED box handle, and brochures to max 48" above the finished floor (AFF) to highest operable part.	\$140.00	5	each	\$700.00	1
Westgate Park and Recreation Center	147	Public Spaces	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$175.00	2	each	\$350.00	1
Westgate Park and Recreation Center	148	Public Spaces	Accessible Routes	Secure edges of carpeting or mats to prevent trip hazard.	\$140.00	4	each	\$560.00	1
Westgate Park and Recreation Center	149	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	150	Public Spaces	Plumbing Fixtures & Elements	Adjust spout flow height to min. 4".	\$420.00	1	each	\$420.00	2
Westgate Park and Recreation Center	151	Public Spaces	Doors	For all doors/gates along the public circulation route, fill gaps at door/gate entries to max .5".  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, provide kick plate on push side of door/gate from floor to 10" AFF.	\$376.25	1	each	\$376.25	1
Westgate Park and Recreation Center	152	Public Spaces	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	153	Public Spaces	Dining, Bar and Work Surfaces	Provide tables and work surfaces at 28" to 34" above the finished floor (AFF) with required knee and toe clearances.	\$1,120.00	1	each	\$1,120.00	1
Westgate Park and Recreation Center	154	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  For all doors/gates along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$3,440.00	2	each	\$6,880.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	155	Public Spaces	Doors	For all doors/gates along the public circulation route, secure rug in door/gate clearance to prevent trip hazard.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.	\$140.00	3	each	\$420.00	1
Westgate Park and Recreation Center	156	Public Spaces	Doors	For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, remove door holder to provide a smooth surface on the push side of door/gate from floor to 10" above the finished floor (AFF).  Remount signage to 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	157	Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	158	Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Remove door holder to provide a smooth surface on the push side of door from floor to 10" AFF.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	159	Employee Space	Turning Space	Relocate obstacles to create turning space in panty room.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	160	Employee Space	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	161	Employee Space	Clear Floor Space	Remove, or relocate storage in CFS at fixtures and operable parts along the accessible route (AR).	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	162	Employee Space	Reach Ranges	Remount operable parts to be in reach range of 15" min to 48" max.	\$0.00	1	staff time	\$0.00	3





**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	163	Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Inspect, adjust, and maintain 5 lbf to open interior doors.  Inspect, adjust, and maintain 8.5 lbf to open exterior doors/gates.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$105.00	2	each	\$210.00	3
Westgate Park and Recreation Center	164	Employee Space	Room/Space (C)	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.  Provide required maneuvering clearance on push and pull side of doors.  Where exit signage exists, mount compliant exit signage at all doors along the egress route.	\$1,960.00	1	each	\$1,960.00	3
Westgate Park and Recreation Center	165	Employee Space	Room/Space (C)	Make corrections for compliant circulation path.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	166	Employee Space	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.  For all doors/gates along the public circulation route, inspect, adjust, and maintain closing speed on door/gate closers.  Remount signage to 48" to baseline of lowest character and 60" to baseline of highest character and on the latch side of the door.	\$0.00	1	staff time	\$0.00	3
Westgate Park and Recreation Center	167	Boys Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	168	Boys Restroom	Plumbing Fixtures & Elements	Remove under sink cabinets/boards to provide knee and toe clearances under sinks and insulate exposed pipes.	\$1,176.00	1	each	\$1,176.00	1
Westgate Park and Recreation Center	169	Boys Restroom	Plumbing Fixtures & Elements	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" above the finished floor (AFF)/	\$2,978.50	1	each	\$2,978.50	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	170	Boys Restroom	Reach Ranges	Lower light switch to max 48" above the finished floor (AFF).  Lower the baby changer to max 48" to the handle and 34" to the work surface when open.	\$350.00	2	each	\$700.00	1
Westgate Park and Recreation Center	171	Boys Restroom	Toilet and Bathing Rooms	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last renovated before March 15, 2012 as this meets safe harbor.	\$2,380.00	1	each	\$2,380.00	1
Westgate Park and Recreation Center	172	Boys Restroom	Plumbing Fixtures & Elements	Provide toe clearance at the front and side partitions, or enlarge stall to provide the same.	\$2,749.25	1	each	\$2,749.25	1
Westgate Park and Recreation Center	173	Boys Restroom	Toilet and Bathing Rooms	Remount rear grab bar to behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" above the finished floor (AFF).	\$393.75	1	each	\$393.75	1
Westgate Park and Recreation Center	174	Boys Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	175	Boys Restroom	Toilet and Bathing Rooms	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.	\$350.00	1	each	\$350.00	1
Westgate Park and Recreation Center	176	Boys Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	177	Boys Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	178	Boys Restroom	Hazards	Relocate protruding objects or place cane detectable bollard at foot of item.	\$0.00	2	staff time	\$0.00	1
Westgate Park and Recreation Center	179	Boys Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1
Westgate Park and Recreation Center	180	Girls Restroom	Toilet and Bathing Rooms	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	181	Girls Restroom	Plumbing Fixtures & Elements	Remove face board to provide 8" deep knee clearance.  Relocate or recess hand dryer to not interfere with clear floor space at the sink, protrusions can't be greater than 4".	\$763.00	2	each	\$1,526.00	1



**PALM BEACH COUNTY  
PARKS AND RECREATION DEPARTMENT  
TRANSITION PLAN**

Responsible Person: Bob A. Hamilton Phone: (561)966-6651

Site	Finding #	Area	Type of correction	Recommendation	Price/unit	# of units	unit type	Total cost	Phase
Westgate Park and Recreation Center	182	Girls Restroom	Toilet and Bathing Rooms	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	\$5,510.75	1	each	\$5,510.75	1
Westgate Park and Recreation Center	183	Girls Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	184	Girls Restroom	Toilet and Bathing Rooms	Adjust stall door to be self-closing.  Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	\$210.00	1	each	\$210.00	1
Westgate Park and Recreation Center	185	Girls Restroom	Toilet and Bathing Rooms	Remount toilet paper dispenser 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	\$0.00	1	staff time	\$0.00	1
Westgate Park and Recreation Center	186	Girls Restroom	Hazards	Repair baby changing table to stay closed to eliminate protruding object.  Relocate protruding objects or place cane detectable bollard at foot of item.	\$175.00	2	each	\$350.00	1
Westgate Park and Recreation Center	187	Girls Restroom	Doors	For all doors/gates along the public circulation route, provide required maneuvering clearance on push and pull side of doors/gate.  For all doors/gates along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors/gates.	\$1,750.00	1	each	\$1,750.00	1