

SUBURBAN FULLSIZE 4X4 SUV

Workorder:	V240			
In Date: Close Date: Problem?	10/17/2005 10/18/2005	Meter Reading:		
	START DC10			
Task perfori	med:		Parts	Quantity
			NO PARTS USED	
Workorder:	V260			
In Date: Close Date: Problem?	10/17/2005 10/18/2005	Meter Reading:		
	HAS DEAD BA	ATTERY DC-10		
Task perform	med:		Parts	Quantity
			NO PARTS USED	
Workorder:	V527			
In Date: Close Date: Problem?	11/09/2005 11/21/2005	Meter Reading:		
	TIME DRIVING	LIGHT OUT D/C10		
Task perfori	med:		Parts	Quantity
			3157TAIL LIGHT BULBS	1
Workorder:	V641			
In Date: Close Date: Problem?	11/21/2005 12/02/2005	Meter Reading:		
DEAD BAT	TERY, DC-10			
Task perfori	med:		Parts	Quantity

NO PARTS USED



12/17/2018

Palm Beach County Fire Rescue **Fleet Maintenance Asset History**

10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V679

In Date: 11/23/2005

12/12/2005 Close Date:

Problem? cranking slow Meter Reading:

Meter Reading:

Task performed:

Parts Quantity

78-72BATTERY GROUP 78

2

Workorder: V933

In Date: 12/14/2005

Close Date: 01/11/2006

Problem?

B INSPECTION DC10

Task performed:

Parts Quantity 1

2421095658608 TRANSFILTER 4L80 DEEP PAN 2 8201L17-3428 ESTER OIL E7 1 CA875642487 FILTER AIR G372733481 FUEL FILTER L/F G481 WIX

K040378BELT SUBURBANS 2002/2003 K060930BELT

PH3506OIL FILTER 51042

Workorder: V1239

01/19/2006 In Date:

Close Date: 01/23/2006

Problem?

several lights out d/c 10

Meter Reading:

Task performed:

Parts Quantity 2 01046301700S30HACP STROBE CLEAR

50R03ZCRLIGHT LED RED TIR 6

1

1

1

1

Workorder: V1501

In Date: 02/14/2006 Close Date: 03/02/2006

Meter Reading:

Problem?

Replace temp. control DC10

Task performed:

Parts Quantity

10370034AC CLUSTER 2006 SUBURBAN NS

1



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V2039

In Date: 03/30/2006 Close Date:

04/05/2006

Meter Reading:

Meter Reading:

Problem?

STROBE OUT IN LEFT FRONT D/C10

Task performed:	Parts	Quantity
	01046301700S30HACP STROBE CLEAR	1
	9-2669 FLOOR MAT	1

30,619.00

Workorder: V2574

In Date: 05/11/2006

05/18/2006 Close Date:

Problem?

B INSPECTION DC-10

Task performed:	Parts	Quantity
See B Inspection pre-printed form	22127653PUMP WINDSHIELD WIPER 89025062 NEW #	1
	3157TAIL LIGHT BULBS	1
	8095063WASHER PUMP REAR	1
	CA875642487 FILTER AIR	1
	PH3506OIL FILTER 51042	1

Workorder: V3320

07/06/2006 In Date: 07/12/2006

Meter Reading:

Close Date: **Problem?**

L.E.D. LIGHT OUT DC 10 AT 23

Task performed:	Parts	Quantity
	50R03ZCRLIGHT LED RED TIR 6	1
	5FLANGEC5FLANGEC FLANGE CHROME	1

Workorder: V3943

08/15/2006 In Date:

Meter Reading: 08/21/2006

Close Date: **Problem?**

DC 10 VEHICLE HAS A LEFT REAR RED STROBE LIGHT OUT AND A LEFT FRONT PARKING LIGHT OUT

Task performed:	Parts	Quantity
	15306157PIG TAIL FOR 4114	1
	4114DAYLITE BULB 15199562	1



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V4139

In Date: 08/27/2006 Close Date:

09/06/2006

Meter Reading:

Problem?

A/C in DC10 started blowing hot air after turning the corner into station 24. Breaker for the A/C compresser, manually manipulated It now blows cold air. Can it be check to make sure that was the only problem. Thanks DC10

Task performed: Quantity **Parts**

NO PARTS USED

Workorder: V4396

In Date: 09/12/2006 36,828.00 Meter Reading:

Close Date: 09/28/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC10

Task performed:	Parts	Quantity
1. PERFORMED B-INSPECTION.	12487671WASHER RESERVOR	1
2. R/R BATTERY TRAYS AND BATTERIES. CLEAN TRAYS PAINT ALL RUST.	12487672WASHER BOTLE HOSE	1
3. R/R WASHER BOTTLE AND PUMPS	12494846SWITCH FLUID LEVEL	1
REPLACELINES ECT.	151709553RD BRAKE LITE LED	1
4. R/R CHMSL AND REWIRE.	15244130BATTERY TRAY STOCK	1
	15705102BAT TRAY NEW # 15246518 2005 SUBURBAN	1
	22-51950-000HEADLINER RETAINER PLUG	3
	78-72BATTERY GROUP 78	2
	89025062WASHER PUMP	1
	89025063WASER PUMP REAR	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2
	CA875642487 FILTER AIR	1
	PH3506OIL FILTER 51042	1

Workorder: V4387

In Date: 09/11/2006 36,828.00 Meter Reading:

10/06/2006 Close Date:

Problem?

FLAT REPAIR AT CALLAGHAN TIRE DC10

Task performed: **Parts** Quantity

VEHICLE SENT TO OUT SIDE AGENCY FOR NEW

TIRE.

NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V4422

In Date: 09/13/2006 **Close Date:**

10/06/2006

Meter Reading:

36,828.00

Problem?

DETAIL UNIT AT TIP TOP DC10

Task performed: **Parts** Quantity

PO WAS CANCELLED NO PARTS USED

Workorder: V4439

In Date: 09/14/2006 Meter Reading: 36,828.00

10/10/2006 Close Date:

Problem?

RPLACE BAD VALVE STEM AT CALLAGHAN ENT.

Task performed: **Parts** Quantity

1. REPLACCE BAD VALVE STEM AT CALLAGHAN

ENT.

NO PARTS USED

Workorder: V5253

In Date: 11/06/2006 40,111.00 Meter Reading:

11/27/2006 Close Date:

Problem?

REPAIR ACCIDENT DAMAGE PER ESTIMATE DC10

Task performed: **Parts** Quantity

1. REPAIR DAMAGE FORM ACCIDENT DC-10 NO PARTS USED

SEBOK'S Vendor?

Workorder: V5635

In Date: 12/01/2006 40,111.00 Meter Reading:

12/04/2006 Close Date:

Problem?

REPLACE PUSH BUMPER DAMAGED IN ACCIDENT DC10

Task performed: **Parts** Quantity

1. tall new push bumper to replace one damaged in

accident

3096CPUSH BAR

1



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V6464

In Date: 01/25/2007 Close Date:

01/29/2007

Problem?

repair strobe / led lights

Task performed:	Parts	Quantity

43,287.00

1. TRACE AND REPAIR INTERMITTIN STROBE LIGHT

PROBLEM. TEST/ OK.

01046301700S30HACP STROBE CLEAR

4

1

0332002156USE 380830 RELAY 12V 75A RLY5491

Workorder: V6375

In Date: 01/20/2007 01/30/2007 Close Date:

Meter Reading: 2,397.10

Problem?

dc 10 scout gas monitor does not start up/shut off properly. DC-10

Meter Reading:

Task performed: **Parts** Quantity

1. TRAVELED TO STN 23. CREW STATES THAT THEY

WILL HANDLE REPAIRS OF THE UNIT.

NO PARTS USED

FREIGHTSHIPPING CHARGES

Workorder: V6852

In Date: 02/20/2007 Close Date:

02/26/2007

Meter Reading:

45,815.00

Problem?

install seat cover parts only

Task performed: Quantity **Parts**

PARTS ONLY- CHIEF GRIBBLE INSTALLED

COVSS1339SEAT COVER 1



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V7004

03/01/2007 In Date: Close Date:

Vendor? CALLAGHAN ENT

03/09/2007

Meter Reading: 47,470.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC10

Task performed:	Parts	Quantity
 B Inspection Replaced front and rear brakes Replaced all belts Removed complete dash assy. R&R E-core and 	15705102BAT TRAY NEW # 15246518 2005 SUBURBAN 15769077HOSE RADIATOR 18041762FRONT PADS SUBURBAN 356668USE 14005061 BAT HOLD DOWN 88964201MKD784 FRONT PADS SUBURBAN 89018296EVAPORATOR 05 SUBURBAN	1 1 1 1
heater core		
5. Replaced right rear LED light		
Reinstalled dash assembly		1
	89018424ACUUMULATOR 05 SUBURBAN	1
	CA875642487 FILTER AIR	1
	K040378BELT SUBURBANS 2002/2003	1
	K060930BELT	1
	PH3506OIL FILTER 51042	1
In Date: 03/12/2007 Meter Reading: 4 Close Date: 03/13/2007 Problem? on call dc10 no siren	7,647.00	
Task performed:	Parts	Quantity
Sirens inop; repaired power wire to siren	NO PARTS USED	
Workorder: V6992		
In Date: 02/28/2007 Meter Reading: 4. Close Date: 03/14/2007 Problem? replace 4 tires (outside agency callaghan tire)	5,815.00	
Task performed:	Parts	Quantity
Replaced 4 tires at Callaghan Ent	NO PARTS USED	



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V8244

05/14/2007 In Date: 06/01/2007 Close Date:

Problem?

batteries innop D/C 10

52,385.00 Meter Reading:

Meter Reading:

Meter Reading:

Task performed:	Parts	Quantity
Replaced (2) batteries	78-72BATTERY GROUP 78	2
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2

54,485.00

56,513.00

Workorder: V9217

In Date: 07/09/2007 Close Date:

07/16/2007

Problem? WILL NOT START DC/10

Task performed:	<u>Parts</u>	Quantity
Replaced batteries; clean cable ends	78-72BATTERY GROUP 78	2
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2

Workorder: V9436

In Date: 07/19/2007

07/19/2007 Close Date:

Problem?

starting problem D/C10

Task performed:	Parts	Quantity
DDAW FOUND 4/2//OLT LOAD TESTED	78-72BATTERY GROUP 78 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2 2

Workorder: V9446

CHARGING SYSTEM.

07/20/2007 In Date: Meter Reading: 56,513.00

Close Date: 08/07/2007

Problem? flat repair dc10

Task performed: **Parts** Quantity

NO PARTS USED

CALLAGHAN TIRE Vendor?



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V10078

In Date: 08/23/2007 Close Date:

09/07/2007

58,277.00

Problem?

ON CALL SIREN 10-7 DC10

Parts Task performed: Quantity

On-call; zDia siren; fnd bad unit; R/R/ siren head NO PARTS USED

Meter Reading:

Workorder: V9901

In Date: 08/14/2007 57,633.00 Meter Reading:

Close Date: 09/11/2007

Problem?

Detail vehicle D/C10 (outside agency-tip-top car wash)

Task performed: **Parts** Quantity

Detail vehicle - Tip-Top Car Wash NO PARTS USED

TIP-TOP CAR WASH Vendor?

Workorder: V6942

In Date: 02/26/2007 45,815.00 Meter Reading:

10/15/2007 Close Date:

Problem?

need straps per chief gribble (D/c 10)

Task performed: **Parts** Quantity

1 89018297HEATER CORE 3 CYBS18206011STRAP 3 CYBS21237011CYBS21237011 STRAP



10160673

SUBURBAN FULLSIZE 4X4 SUV

12/17/2018

Workorder: V11080

10/17/2007 In Date: Close Date:

10/23/2007

Meter Reading:

61,189.00

Problem?

Task performed:

1. Drive to Sta. installed control head, test OK.

b inspection and repairs as needed dc10

Task performed:	Parts Quantity
 b inspection. air in tires. add p/s fluid. pick up engine at central auto trim and bring back to shop. r/r batteries. remove battery tray. remove rust and corrosion from trays, treat corrosion and paint. re-install. replace tray bolts +terminal bolts. removed washer bottle. replace front and rear motors. replace tubbing. install missing speed nuts and secure. 	12463086WASHER HOSE 1 12487672WASHER BOTLE HOSE 1 15716479F-BUMPER 1 89025062WASHER PUMP 1 89025063WASER PUMP REAR 1 CA875642487 FILTER AIR 1 PH3506OIL FILTER 51042 1
Workorder: V11111 In Date: 10/18/2007 Meter Reading: 61,18 Close Date: 11/13/2007 Problem? replace tires at callaghan ent dc10	89.00
Task performed:	Parts Quantity
replace tires at callaghan ent dc10	NO PARTS USED
Vendor? CALLAGHAN TIRES	
Workorder: V11728 In Date: 11/22/2007 Close Date: 11/30/2007 Problem? Meter Reading:	

AC suddenly began blowing hot. Contact with on duty mechanic 11/21. Does not have part needed due to description of problem.

NO PARTS USED

Quantity

Parts

Will order. AC suddenly working after starting vehicle again under mechanics direction dc10



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V11900

In Date: 12/04/2007 **Close Date:**

12/06/2007

Meter Reading:

61,189.00

Problem?

a/c 10-7 speedometer 10-7 dc10

Task performed: **Parts** Quantity

Truack run at scene long time; discharge of batry. NO PARTS USED

Workorder: V12672

01/18/2008 In Date: 65,671.00 Meter Reading:

Close Date: 01/25/2008

Problem?

b inspection and repairs as neeeded dc 10

Tas	sk perfor	med:					
1.	Replace	left and	l right	front	wheel	hubs.	lubercate

- е brake slots and pins remount tires.
- 2. Install power brake booster, test drive.
- 3. Test drive "B" inspection, change oil and filter, replace air filter, replace wiper blades.
- 4. Repair base reatator over flow bottle, replace left front turn signal assembly and install strobe light, replace running light.
- 5. Test strobe pack found to be good replace all strobe bulbs, replace hood light.
- 6. Replace R "A" frame bumper.

Parts	Quantity
15054178HINDGE BOLT W/SHOULDER	1
15199558TURNSIGNAL LAMP LF	1
15535666FRAME BUMPER	1
15854059BRAKE BOOSTER 05 SUBURBAN	1
15946732WHEEL BRG FRT	2
3157NAAMBER BULB	1
PH3506OIL FILTER 51042	1

Workorder: V12665

01/17/2008 In Date: Meter Reading:

02/01/2008 Close Date:

Problem?

dc 10 suburban; 1. left head light loose. 2. change oil message.

Task performed: **Parts** Quantity

Replc turn signal; cln oil; change light as part of "B"

inspection.

NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V13233

02/13/2008 In Date: Close Date: 02/14/2008

69,641.00 Meter Reading:

Problem?

Task performed:

1. installed and wired battery charger

A/C WILL NOT SHUT OFF DC-10

A/C WILL NOT SHOT OFF, DC-10			
Task performed:	Parts	Quantity	
 Check out A/C, left and right Blend Doors not the same, need to go to GM for BCM reflash. Check out service engine light on, p0455 code, large evp leak, check out system, lines, cap ect, reset code, didn't store again 	NO PARTS USED		
Workorder: V12926			
In Date: 01/30/2008 Meter Reading: 65,67 Close Date: 03/04/2008 Problem? REPAIR STEERING COLUMN DC10	1.00		
Task performed:	Parts	Quantity	
Repair steering column DC10 - Roger Dean j	NO PARTS USED		
Vendor? ROGER DEAN			
Workorder: V14056			
In Date: 03/24/2008 Meter Reading: Close Date: 03/27/2008 Problem?			
Vehicle won't start, charging battiries dc10			
Task performed:	Parts	Quantity	
drive to station, charger to 2 batt, called Building & Maint to install plug start check volt ok	NO PARTS USED		
Workorder: V14026			
In Date: 03/20/2008 Meter Reading: Close Date: 04/22/2008 Problem?			
1. drive to station, charger to 2 batt, called Building & Maint to install plug start check volt ok Workorder: V14026 In Date: 03/20/2008 Meter Reading: Close Date: 04/22/2008	NO PARTS USED	Quanti	

Parts

NO PARTS USED

Quantity



SUBURBAN FULLSIZE 4X4 SUV

10160673

Workorder: V14027

In Date: 03/20/2008 Close Date:

04/22/2008

Meter Reading:

Problem?

Engine service light is on. DC-10

Task performed: **Parts** Quantity

Parts

1. installed battery charger. NO PARTS USED

Workorder: V15843

In Date: 06/19/2008 78,599.00 Meter Reading:

Close Date: 07/01/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC10

Task performed:

- 1. test drive B inspection change oil/filter, replace fuel filter. replace wiper blades.
- 2. replace batteries x 2
- 3. install front / rear brake pads . polish all light covers , replace broken light lens, replace strobe light.
- 4. install front/ rear shocks
- 5. install r/ rear brake caliber & bleed.

	<u> </u>
01046301700S30HACP STROBE CLEAR	1
15016308CALIPER BOLT	2
15W40BSYN OIL BULK QTS	6
18040100BRAKE CALIPER REAR	1
18041762FRONT PADS SUBURBAN	1
50R03ZCRLIGHT LED RED TIR 6	1
54-870PL558-60 CIRCUIT BREAKER 60 AMP	1
78-72BATTERY GROUP 78	1
88964201MKD784 FRONT PADS SUBURBAN	1
91-22WIPER BLADE	2
911168SHOCK 05 SURBURBAN	2
911181SHOCK 05 SURBURBAN	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	1
CA875642487 FILTER AIR	1
FREIGHTSHIPPING CHARGES	1
PH3506OIL FILTER 51042	1

Quantity

Workorder: V15917

In Date: 06/23/2008 78,599.00 Meter Reading:

Close Date: Problem?

repair and paint hood dc 10

07/02/2008

Task performed: Quantity **Parts**

Repair and paint hood DC10 - Alvin Matthews Paint

NO PARTS USED

Vendor? ALVIN MATTHEWS



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V15618

In Date: 06/09/2008

07/03/2008 Close Date:

Meter Reading:

77,756.00

Problem?

REPAIR FLAT TIRE DC10

Task performed: **Parts** Quantity Repair flat tire DC10 - Callaghan NO PARTS USED **CALLAGHAN** Vendor? Workorder: V15844 In Date: 06/19/2008 78,599.00 Meter Reading: Close Date: 07/11/2008 Problem? REPAIR FLAT CALLAGHAN ENT Task performed: **Parts** Quantity Repair flat - Callaghan NO PARTS USED Vendor? CALLAGHAN Workorder: V16063 In Date: 06/30/2008 78,599.00 Meter Reading: Close Date: 07/21/2008 Problem? replace tires at callaghan dc10 Task performed: **Parts** Quantity Replace tires DC10 - Callaghan NO PARTS USED Vendor? CALLAGHAN Workorder: V14958

05/08/2008 In Date: Meter Reading: 74,268.00 08/11/2008

Close Date: **Problem?**

Need TIC camera installed in DC10 vehicle.

Task performed: **Parts** Quantity

NO PARTS USED

1. install TIC in DC 10 charger LED out, try to get new charger check out old one ok to use for now.



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V17223

In Date: 08/21/2008

Close Date: 08/25/2008

Vendor? CALLAGHAN

Meter Reading: 80,909.00

Problem?

HOOK PORTABLE CHARGER TO HOT BATT, REPAIR WIRE AT BATTERY CHARGER DC-10

Task performed: **Parts** Quantity Rewire battery power to hot, not ING; cleanup wiring at NO PARTS USED battery charger. Workorder: V17318 08/25/2008 In Date: 4,557.30 Meter Reading: Close Date: 09/16/2008 **Problem?** Front brakes starting to "squeak" when braking at low speed. DC10 Task performed: **Parts** Quantity 1. PULLED LEFT FRONT WHEEL TO CHECK BRAKES NO PARTS USED NPF AT THIS TIME Workorder: V17734 In Date: 09/16/2008 33,254.00 Meter Reading: Close Date: 09/29/2008 **Problem?** replace wiper blades dc9 Task performed: Quantity **Parts** 2 1. drive to sta replace wipers 91-22WIPER BLADE Workorder: V17814 In Date: 09/19/2008 82,989.00 Meter Reading: 10/02/2008 Close Date: Problem? front end alignment Task performed: **Parts** Quantity Front end alignment - Callaghan NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V15167

In Date: 05/19/2008 **Close Date:**

10/20/2008

Meter Reading:

Problem?

Check engine oil light stays on DC10

Parts Task performed: Quantity

NO PARTS USED

Workorder: V18283

10/11/2008 In Date: Meter Reading:

Close Date: 10/21/2008

Problem?

Front left strob is out on D/C 10. Condensation is built up inside ...

Task performed: **Parts** Quantity

1 Drive to Stn; replace strobe bulb; test ok. 01046301700S30HACP STROBE CLEAR

84,094.00

Workorder: V18754

10/31/2008 In Date: Meter Reading: 85,455.00

Close Date: 11/05/2008

Problem?

NO TAIL LIGHTS OR REAR ACCESORIES DC10

Task performed: **Parts** Quantity

2 repair tail light; wiring for radio charger & map light wiring. 3157TAIL LIGHT BULBS j 1

5648056480 PLUG-POWER/ACESS.



10160673

SUBURBAN FULLSIZE 4X4 SUV

1

Workorder: V19036

In Date: 11/13/2008 Meter Reading:

Close Date: 12/05/2008

86,287.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC10 STEERING SHAKES ON BRAKE APPLICATION

Task performed:	Parts	Quantity
B-Inspection & voltage fault.	151709553RD BRAKE LITE LED	1
2. Test low voltage; fnd (1) bad btry; replc bad btry.	15W40BSYN OIL BULK QTS	6
3. Frnt vibration on application of brakes; diss/inspect;	19136087ALT 145 AMP	1
fnd rotor & caliper damage; install rotor, caliper & pads; bleed brake sys & road test.	211-2BULB	1
4. Coolant low; no leak fnd; no tool available to chk cap	2421095658608 TRANSFILTER 4L80 DEEP PAN	1
pressure on sys; tool on order; top off cooling sys.	37000003722-44816-001 DOME LIGHT RECT	1
5.Replace A/C & eng belts.	50R03ZCRLIGHT LED RED TIR 6	1
6. A/C blowing cool; chk pressures; low/high side normal; no freezing of lines; vac sys; poss mositure in	78-72BATTERY GROUP 78	1
sys; recharge unit; cooling to 21 degrees.	91-22WIPER BLADE	2
7. Wiper blade & fluid svc.	9476BELT	1
8. L-side frnt LED 50% out; rem/install new LED asy.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	1
9. R-frnt turn signal out; bulb blown; rem/install new bulb	BD126036ROTOR	2
10. lift gate light out; fnd bulb asy grnd out & burnt; fnd fault rep & install new asy.	CA875642487 FILTER AIR	1
11. Third light (brake light) asy full w/water; bulbs blown;	K040378BELT SUBURBANS 2002/2003	1
rem asy; reassemble/install new lighting asy.	K060930BELT	1
12. Charging sys inop; fnd alt weak; rem bad alt; install	PH3506OIL FILTER 51042	1
new alt; chk sys under load 14.2V-13.9V with full load. 13. Trans svc.	TQ25432CALIPER	1
13. 110113 376.		

Workorder: V19338

In Date: 11/25/2008 Meter Reading:

14. Rep brkn wheel weld shroud & secure.

Close Date: 01/14/2009

Problem?

REPAIR FLAT DC 10

Task performed:

Parts Quantity

Parts Quantity

86,287.00

TQ25433CALIPER

Repair flat DC10 - Callaghan j NO PARTS USED

Vendor? CALLAGHAN



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V20265

01/09/2009 In Date: Close Date:

02/05/2009

Meter Reading:

Problem?

check engine light on. dc10

Task performed:	Parts	Quantity
Run Scan; clear code (Rvap leak); tighten fuel cap; scan. j	NO PARTS USED	
Workorder: V20260		
In Date: 01/09/2009 Meter Reading: 88,7 Close Date: 02/18/2009 Problem? REPAIR AIR BAG SYSTEM DC10	772.00	
Task performed:	Parts	Quantity
Repair air bag sys DC10 - Roger Dean j	NO PARTS USED	
Vendor? ROGER DEAN		
Workorder: V18663		
In Date: 10/28/2008 Meter Reading: 84,8 Close Date: 02/19/2009 Problem? balance tires dc10	660.00	
Task performed:	Parts	Quantity
Balance tires DC10 - Callaghan j	NO PARTS USED	
Vendor? CALLAGHAN		
Workorder: V16985		
In Date: 08/12/2008 Meter Reading: 80,6 Close Date: 03/02/2009 Problem? TIC CHARGER INOP, DC-10	35.00	
Task performed:	Parts	Quantity
1 rewire battery charger system. checkout TIC, ok for 12	NO PARTS USED	



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V22260

In Date: 04/01/2009

Close Date: 04/01/2009

Meter Reading: 93,480.00

Problem?

Task performed:

Vendor?

Repair exh sys DC10 - Al Packer j

AL PACKER FORD

B INSPECTION AND REPAIRS AS NEEDED DC10

Task performed: **Parts** Quantity 1. B INSPECTION COMPLETED AT AL PACKER NO PARTS USED Workorder: V22376 In Date: 04/07/2009 93,645.00 Meter Reading: Close Date: 04/17/2009 Problem? need floormats D/C 10 Task performed: **Parts** Quantity 2 Parts only 9-2669 FLOOR MAT Workorder: V22932 04/30/2009 In Date: Meter Reading: 95,378.00 Close Date: 05/05/2009 **Problem?** Nails in both front tires... DC-10 Task performed: **Parts** Quantity driv e to Stn; fill tires; send to tire co. j NO PARTS USED Workorder: V22595 In Date: 04/16/2009 94,270.00 Meter Reading: 05/08/2009 Close Date: Problem? repair exhaust system dc 10 al packer

Parts

NO PARTS USED

Quantity



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V22259

In Date: 04/01/2009 **Close Date:**

05/11/2009

Meter Reading:

93,480.00

Problem?

b inspection al packer ford

Task performed: **Parts** Quantity

B-Inspection - Al Packer NO PARTS USED

AL PACKER Vendor?

Workorder: V22356

In Date: 04/06/2009 93,645.00 Meter Reading:

05/11/2009 Close Date:

Problem?

balance tires callaghan dc10

Task performed: **Parts** Quantity

Balance tires DC10 - Callaghan NO PARTS USED

CALLAGHAN Vendor?

Workorder: V23005

In Date: 05/04/2009 Meter Reading: 95,689.00

Close Date: 05/14/2009

Problem?

batterys dead on call dc10

Task performed: **Parts** Quantity

Replace power core end from stn damages in stn & unplugged; chk truck charger up; call out; btry chk;

charging sys ok. j

NO PARTS USED

Workorder: V23030

In Date: 05/04/2009 95,689.00 Meter Reading:

Close Date: **Problem?**

replace tires at callaghan dc10

06/05/2009

Task performed: Quantity **Parts**

NO PARTS USED

Vendor? **CALLAGHAN**



10160673 **SUBURBAN FULLSIZE 4X4 SUV**

12/17/2018

Workorder: V25607

In Date: 08/18/2009 **Close Date:**

09/03/2009

Meter Reading:

Meter Reading:

99,910.00

103,139.00

Problem?

Close Date:

Problem?

replace wiper blades DC 10

Task performed: **Parts** Quantity 2 Drive to Stn; replc wiper blades. j 91-22WIPER BLADE

Workorder: V25978

In Date: 09/02/2009

09/09/2009

B inspection and repairs, check vehicle for low voltage during cranking D/C 10 (the low voltage shuts off computor modem)(work

performed at al packer ford)

Task performed: **Parts** Quantity

B inspection and repairs (work performed by al packer

ford)

01046301700S30HACP STROBE CLEAR

2

Workorder: V26152

In Date: 09/09/2009

09/16/2009 Close Date:

Meter Reading:

102,983.00

Problem?

replace all light bar lenses (faded) D/C 10

Task performed: **Parts** Quantity 1 Replace all light bar lenses. j 6807600070HANDLE DOOR EXT L/H 1 6807600170HANDLE DOOR EXT. R/H

Workorder: V26514

In Date: 09/28/2009 104,059.00 Meter Reading:

09/30/2009 Close Date:

Problem?

repair a/c dc 10

Task performed: **Parts** Quantity

Fnd blower map; ck fuses; R/R "S" case fuse; rem dash panel & kick panel; fnd connection possibly loose;

blowers work ok; reassembled; ck ok.

NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V25739

In Date: 08/24/2009

Close Date: 10/07/2009

Problem? siren 10-7

Task performed:

Meter Reading: 99,910.00

 Dia siren failure; fnd internal sys failure; rem siren/install; rep siren in unit; operating normal.
 Several LED foggy -breyond rep; install new

2. Several LED foggy -breyond rep; install new LEDs/lens.

3. C/O light bar; tried to get set #; cannot find; ordered new lens for light bar. j

Parts Quantity

50R03ZCRLIGHT LED RED TIR 6

WS-295HFSM1USE 295SLSA1 SIREN

6

1

Workorder: V26041

In Date: 09/04/2009 Meter Reading: 102,983.00

Close Date: 10/15/2009

Problem?B inspection and repairs (outside agency-al packer ford)

Task performed: Parts Quantity

B-Inspection/repairs - Al Packer Ford j NO PARTS USED

Vendor? AL PACKER FORD

Workorder: V26642

In Date: 10/02/2009 Meter Reading: 104,264.00

Close Date: 10/19/2009

Problem?

A/C innop D/C 10

Task performed: Parts Quantity

Fnd A/C belt had come off; inspected compressor &

pulleys; installed new belt; test drove & ran A/C.

K040378BELT SUBURBANS 2002/2003

1

Workorder: V27247

In Date: 10/28/2009 Meter Reading: 105,918.00

Close Date: 11/02/2009

Problem?

electronic fed-Q 10-7

Task performed: Parts Quantity

C/O power head with fed-Q opn; NOTE: the cntrl head in center console doesn't have this function; C/O spares in yard & fnd one; swoop out cntrl heads in veh. j

NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Quantity

Quantity

Workorder: V28412

In Date: 12/16/2009 Close Date: 01/05/2010

Meter Reading: 108,900.00

DC 10 check engine light on. All gauges showing normal. No obvious vehicle problems. DC10

Problem?

Problem?

Task performed:

Chkd - fnd no codes.

Task performed:

driver complaint growling noise in eng

 R/R alternator. C/O problem; fnd alt bad; didnt have one; order new; start to pull one off spare to install on trk; get spare for driver. j 	15263859ALTERNATOR	
Workorder: V28476		
In Date: 12/18/2009 Meter Reading: 108,96 Close Date: 01/08/2010 Problem? B inspection and repairs D/C 10	00.00	
Task performed:	Parts	Quantity
B-Inspection	15W40BSYN OIL BULK QTS	6
2. Ckd eng codes ; all for low voltage; cleared codes.	3157NAAMBER BULB	1
3. Replc wiper blades & added washer fluid.4. Replc marker light bulb.	516TIRE INFLATOR	1
5. Replict halker light builb.	6010760-107 BACK-UP ALARM OE	1
6. Sec motor mnt bolts.	78-72BATTERY GROUP 78	2
7. Svc rear diff; added limited slip add. & adj tire press.	91-22WIPER BLADE	2
8. Replc btrys. j	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2
	CA875642487 FILTER AIR	1
	PH3506OIL FILTER 51042	1
	S448GAUGE TIRE TREAD DEPTH	1
	S777COUPLING NIPPLE	1
	XL-3FRICTION MODIFIER 4 OZ	1
Workorder: V27846		
In Date: 11/22/2009 Meter Reading: Close Date: 01/13/2010		

Parts

NO PARTS USED

Parts



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V28837

In Date: 01/05/2010

Close Date: 01/27/2010

Problem? no heat dc10

Meter Reading: 109,741.00

Task performed:

Parts

Quantity

C/O no heat problem; fnd water lines to heater core cut &

capped.

Sent to Al Packer for repair. j

NO PARTS USED

Workorder: V29533

In Date: 01/29/2010

Meter Reading: 110,462.00

Close Date: 02/24/2010

Problem?

Flat repair D/C10 (outside agency-boulevard tire)

Task performed:

Parts

Quantity

Flat repari DC10 - Boulevard Tire j

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V29254

In Date: 01/19/2010

Meter Reading: 109,741.00

Close Date: 02/25/2010

Problem?

repair heater D/C 10 (outside agency-al packer ford)

Task performed:

Parts

Quantity

Repair heater DC10 - Al Packer j

NO PARTS USED

Vendor? AL PACKER

Workorder: V30493

In Date: 03/05/2010

Close Date: 03/25/2010

Meter Reading: 112,319.00

Problem?

Engine light on D/C10

Task performed:

Parts

Quantity

CHKD CODES; FND EVAP CODE; SWAPPED FUEL CAPS W/ANOTHER UNIT; CLEARED CODES. OK.

NO PARTS USED

J



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V31160

In Date: 03/30/2010

Close Date: 05/11/2010

Meter Reading: 113,997.00

Problem?

replace all 4 tires at boulevard tire ems10 (outside agency-boulevard tire)

Task performed:	Parts	Quantity
Replace all (4) tires EMS10 - Boulevard j	NO PARTS USED	
Vendor? BOPULEVARD		
Workorder: V31976		
In Date: 05/04/2010 Meter Reading: 11 Close Date: 05/17/2010 Problem? 11	6,066.00	
Check out 4 wheel drive light comming on. DC10		
Task performed:	Parts	Quantity
Inspect t-case; chk fluid-good; inspect wiring WPF a this time.	t NO PARTS USED	
Workorder: V31569		
Close Date: 05/19/2010	3,997.00	
Problem? replace all 4 tires at TCI tire ems10 (outside agency-T	CI tire)	
Task performed:	Parts	Quantity
Replace all (4) tires EMS10 - TCi j	NO PARTS USED	
Vendor? TCI		
Workorder: V32363		
In Date: 05/21/2010 Meter Reading: 11 Close Date: 05/25/2010 Problem? Check eme Its and siren DC10	6,748.00	
Task performed:	Parts	Quantity
Right front grill light strobe inop; blown bulb; rem/insta new bulb; chk - operating normal. j	II 01046301700S30HACP STROBE CLEAR	1



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V32239

In Date: 05/17/2010 06/04/2010

Close Date:

Problem?

rear taillight out D/C10

116,748.00 Meter Reading:

Task performed: **Parts** Quantity

A/C inop; replcd A/C fan clutch. 15710101FAN CLUTCH

Workorder: V32313

In Date: 05/19/2010 Meter Reading: 117,273.00

Close Date: 06/14/2010

Problem?

B inspection and repairs D/C 10(outside agency-schumacher)

Task performed: **Parts** Quantity

B-Inspection/repairs DC10 - Schmumacher NO PARTS USED

SCHUMACHER Vendor?

V32417 Workorder:

In Date: 05/25/2010 116,748.00 Meter Reading:

06/14/2010 Close Date:

Problem?

REPAIR COMAND CENTER DC10

Task performed: **Parts** Quantity

NO PARTS USED

1. R/R rear seat flaps to trim & fit around command

2. Rep command center door hinges & installlaches.

3. Installed drawer safety latch on command center to keep drawer from opening during transit.

Repair command center DC10 - Callaghan j?

CALLAGHAN Vendor?

Workorder: V33199

In Date: 06/28/2010 116,748.00 Meter Reading:

Close Date: 07/14/2010

Problem?

check engine light on DC10

Task performed: **Parts** Quantity

Chk eng light; fnd fault code for fuel cap; no cap in stock;

ordered cap. j

2582733520915842 FUEL CAP SUBURBAN

1

1



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V33213

In Date: 06/29/2010

Close Date: 07/28/2010

Meter Reading: 119,336.00

Problem?

check engine light on, checked at shop, needs new gas cap. dc 10

Task performed: Parts Quantity

Went to 23; replcd gas cap; cleared eng codes; ran/ck

ok.

NO PARTS USED

Workorder: V34188

In Date: 08/11/2010 Meter Reading: 110,685.00

Close Date: 08/27/2010

Problem?

A inspection and repairs check batteries and charger, a/c blows hot on left, cold on right, repair shelf and hinges on command

center

Task performed:

1. Replc btrys X 2.

Parts

1. Resplc btrys X 2.

15832315A/C CONTROL

1

4. Replc A/C control in dash. ja

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

Workorder: V34162

In Date: 08/10/2010 Meter Reading: 119,336.00

Close Date: 09/07/2010

Problem?

check emergency lights and siren dc 10

Task performed: Parts Quantity

Replc strobe; bulb & hookup disconnected wire. js S30HACSTROBE BULB

Workorder: V34187

In Date: 08/11/2010 Meter Reading: 110,685.00

Close Date: 09/07/2010

Problem?

battery dead DC3

Task performed: Parts Quantity

No start - btry dead; jump start. js NO PARTS USED



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V34089

In Date: 08/06/2010

09/08/2010 Close Date:

Problem?

engine overheating dc 10

Task performed: **Parts** Quantity

119,336.00

110,685.00

Overheating - crack in radiator; replc radiator to be done

Meter Reading:

Meter Reading:

by outside vendor.

NO PARTS USED

Workorder: V34491

In Date: 08/24/2010 Close Date:

09/08/2010

Problem?

1 siren intermittant D/C10

Task performed: **Parts** Quantity

Chk siren; fnd bad spkr; R/R spkr; still inop; no power now; chk siren head on; chek wiring; fnd open in grnd

side; replc wire at head ok.

SD-210RSIREN DRIVER

1

Workorder: V34090

In Date: 08/06/2010

Close Date: 09/10/2010 Meter Reading:

120,834.00

Problem?

engine overheating dc 10 (outside agency-schumacher)

Task performed: **Parts** Quantity

Engine overheating DC10 - Schumacher j NO PARTS USED

SCHUMACHER Vendor?

Workorder: V34563

In Date: 08/27/2010 Meter Reading: 110,685.00

09/27/2010 Close Date:

Problem?

tag lights 10-7, and lenses broken D/C10

Task performed:	Parts	Quantity
Tag lights 10-7; lenses brkn DC10 - Schumacher j	01046301700S30HACP STROBE CLEAR	1
O. D/E strake in any sepled holls	15805196TAG LAMP	3
2. R/F strobe inop; replcd bulb.3. Taglights inop - sockets/bulbs; replcd light asy &	194BULB	4
bulbs. j	UMVS-0811-11STRAP ZICO	1

UMVS111611STRAP

SCHUMACHER Vendor?



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V30803

Repair weather strip.

j

03/17/2010 In Date: Close Date:

10/04/2010

Meter Reading: 113,238.00

Problem?

repair sliding tray in command center D/C10

Task perfori	med:			Parts	Quantity
Dia problem w/slide out tray; fnd brkn track/staples pulled out of board. rem track; replc left track; drill, screw & countersink. j				NO PARTS USED	. <u>Quantity</u>
Workorder:	V31557				
In Date: Close Date: Problem? won't start I	04/15/2010 10/19/2010 D/C10	Meter Reading:	113,23	8.00	
Task perfori	med:			Parts	Quantity
Completed j			78-72BATTERY GROUP 78	2	
				BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2
Workorder:	V35379				
In Date: Close Date: Problem? weather str	10/04/2010 10/27/2010 ipping in hatch	Meter Reading: back of DC 10 torn ar	122,46		
Task perform	med:			Parts	Quantity

NO PARTS USED



SUBURBAN FULLSIZE 4X4 SUV

Workorder: V35797

In Date: 10/20/2010 10/29/2010 **Close Date:**

Meter Reading:

124,501.00

Problem?

B inspection and repairs D/C 10

Parts	Quantity
01046301700S30HACP STROBE CLEAR	1
15W40BSYN OIL BULK QTS	6
25873812AIR FILTER BOX	1
78-72BATTERY GROUP 78	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2
CA875642487 FILTER AIR	1
PH3506OIL FILTER 51042	1
	01046301700S30HACP STROBE CLEAR 15W40BSYN OIL BULK QTS 25873812AIR FILTER BOX 78-72BATTERY GROUP 78 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF CA875642487 FILTER AIR

Workorder: V37306

12/20/2010 In Date:

Close Date: 12/30/2010

Meter Reading: 128,067.00

Problem? wiper DC 10

Task performed:

(1) TRAVELED TO ST23 TO REPLACE WIPER BLADES ON DC10 VEHICLE. REPLACED BOTH

BLADES WITH NEW ONES AND TOPPED OFF FLUID.

J.W.

Parts Quantity 2

91-22WIPER BLADE

Workorder: V37054

In Date: 12/09/2010 122,469.00 Meter Reading:

01/11/2011 Close Date:

Problem?

repair flat tire on R/R DC 10 (outside agency-TCI Tire)

Task performed: Quantity **Parts**

Rep flat tire on R/R DC10 - TCi j NO PARTS USED

Vendor? TCTI



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V37358

In Date: 12/22/2010 **Close Date:**

01/11/2011

Meter Reading:

128,214.00

Problem?

dash warning message: Service 4 wheel drive. DC10

Task performed: **Parts** Quantity

NO PARTS USED

(1) TRAVELED TO ST-23 TO REPAIR SERVICE LIGHT ON . FOUND THE LIGHT NOT ON AT THIS TIME. 4 WHEEL DRIVE WORKING PROPERLY.

J.W.

Workorder: V37723

In Date: 01/10/2011

Meter Reading: 128,067.00

Close Date: 01/18/2011

Problem?

check engine light on DC 10

Task performed: **Parts** Quantity

Chkd eng codes; fnd codes for evap; cleared codes; also

added eng oil/coolant low.

NO PARTS USED

Workorder: V38231

In Date: 02/08/2011

Close Date: 02/17/2011 Meter Reading:

131,580.00

Problem?

B inspection and repairs D/C 10

Task performed:

Perform B-Inspection

- 2. Rem rear hatch inner cvr; replc brkn dome light in hatch door; rewired, traced wires back & replc fuse.
- 3. Replcd rear hatch weatherstrip/seal torn/leaking.
- 4. Clnd, sanded & painted wheels; also replcd center caps.
- 5. T-shoot forwarn backup sys; rep sys with DNI parts.

Parts	Quantity
15779843HATCH SEAL SURBABAN	1
15W40BSYN OIL BULK QTS	6
37000003722-44816-001 DOME LIGHT RECT	2
9597961HUB CAP SUBURBAN	4
PH3506OIL FILTER 51042	1



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V38405

In Date: 02/09/2011

Close Date: 03/08/2011

Meter Reading: 113,997.00

Problem?

replace all 4 tires at TCI tire D/C10 (outside agency-TCI tire)

Task performed: Parts Quantity

Replc all (4) tires DC10 - TCI j NO PARTS USED

Vendor? TCI TIRE

Workorder: V40032

In Date: 04/20/2011

04/25/2011

Meter Reading: 135,902.00

Close Date: Problem?

A/C INOP D/C10

Task performed:

C/O truck; fnd A/C compressor locking up; needs new;

D/D A/C compressor % accumulator % orifice tubes name

15-10422ACCUMULATOR

R/R A/C compressor & accumulator & orifice tube; pump down & charged sys.

down & charged sys.

15-20940A/C COMPRESSOR 05 SURB 1 15-31101A/C SEAL 1 15-5378ORIFICE TUBE 05 SURB 1

Workorder: V40115

In Date: 04/25/2011

Close Date: 04/27/2011

Meter Reading: 135,902.00

Problem?

ON CALL DC 10 COOLANT LEAK

Task performed: Parts Quantity

Travel to 23; dia problem; fnd coolant leak L/side & heater tubes by wheel well; travel to shop & swap out

veh; travel home. j

NO PARTS USED

Workorder: V40214

In Date: 04/27/2011 Meter Reading: 135,902.00

Close Date: 05/03/2011

Problem?

detail (outside agency-tip-top car wash)

Task performed: Parts Quantity

Detail - Tip-Top Car Wash j NO PARTS USED

Vendor? TIP-TOP CAR WASH



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V40413

In Date: 05/04/2011 Close Date:

05/10/2011

Meter Reading:

136,557.00

Problem?

REPLACE FIRE RESCUE GRAPHICS DC10

Task performed: **Parts** Quantity

Travel to Stn23 - not there; go back R/R graphics on truck and reinstall new.

NO PARTS USED

Workorder: V40123

In Date: 04/25/2011

135,902.00 Meter Reading:

Close Date: 05/20/2011

Problem?

repair coolant leak (outside agency-roger dean)

Task performed: **Parts** Quantity

Repair coolant leak - Roger Dean NO PARTS USED

ROGERN DEAN Vendor?

Workorder: V40727

05/19/2011 In Date: 137,585.00 Meter Reading:

Close Date: 05/24/2011

Problem?

unit over heating west of 20 mile bend. ems 10.

Task performed: **Parts** Quantity

travel to unit EMS10 on SR80; C/O trk overheating; cld not problem; drive to shop to get driver swapped out. j

NO PARTS USED

Workorder: V40809

In Date: 05/23/2011 Meter Reading: 138,121.00

Close Date: 06/07/2011

Problem?

B Inspection at Roger Dean

Task performed: **Parts** Quantity

B-Inspection - Roger Dean NO PARTS USED

ROGER DEAN Vendor?



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V41356

In Date: 06/15/2011 **Close Date:**

06/16/2011

Meter Reading: 137,585.00

Problem?

Service 4 wheel drive comes on when vehicle is started

Task performed: **Parts** Quantity

C/O, svc (4) wheel drive indicator warning coming on;

truck will have to go to dealer.

NO PARTS USED

Workorder: V41416

In Date: 06/17/2011 Close Date: 07/18/2011

137,585.00 Meter Reading:

Problem? Repairs

Task performed: Quantity **Parts**

Repaired oil leak. Replaced oil pan, oil pan gasket, and rear main seal. Noise found in dry line. Transfer case was replaced with a rebuilt one. Shaft bearing was bad.

ROGER DEAN Vendor?

NO PARTS USED

V42082 Workorder:

07/18/2011 In Date:

Close Date: 07/18/2011

Meter Reading:

137,585.00

Problem?

Check oil pan in rear main, transfer case, emergency lights and tires

Task performed: **Parts** Quantity

PUT TRUCK ON LIFT CHECKED ENGINE AND DRIVETRAIN REPAIRS CHECKED FLUIDS CHECKED

TIRES AND LIGHTS AK

NO PARTS USED

Workorder: V42512

08/03/2011 In Date: 140,453.00 Meter Reading:

08/08/2011 Close Date:

Problem?

Check engine, anti lock, and brake light are on. The transmission shifts hard going from first to second gear.

Task performed: **Parts** Quantity

Repaired ABS wiring harness for rear wheel sensors and

cleared all codes

Vendor? **ROGER DEAN** NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V42480

08/02/2011 In Date:

08/22/2011 Close Date:

Meter Reading:

140,453.00

Problem?

Brake ABS amber dash light on. Inside cab hood release handle missing. Check engine light is also on. DC10

Table weets w				Dout	0
Task performed: WENT TO 23 CK ABS SENSORS FOR DAMAGE CK OK CK FUSES SCANNED COMPTER NO CODES UNPLUGGED ABS COMP CLEARED EN CODES LT STILL ON OK TO RUN RETURN HOME				Parts 15142953CABLE ASSY HOOD RELEASE CHEVY 19181872ABS SENSOR CHEVY	Quantity 1 2
Workorder:	V41219				
In Date: Close Date: Problem? Install ident	06/09/2011 09/01/2011 ification plates.	Meter Reading:	137,585	5.00	
Task performed:				Parts	Quantity
installed small # plates				L PLACARDLARGE SIDE PLACARD	2
Workorder:	V44085				
In Date: Close Date: Problem? no start.	10/03/2011 10/03/2011	Meter Reading:	144,681	1.00	
Task performed:				Parts	Quantity
engine no start possible fuel pump towed to shop had dc swap				NO PARTS USED	
Workorder:	V44086				
In Date: Close Date:	10/03/2011 10/12/2011	Meter Reading:	144,681	1.00	

Problem?

repair flashlite charger

Task performed: Quantity **Parts**

remount stream light and charger NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V44362

In Date: 10/13/2011 **Close Date:**

10/18/2011

Meter Reading:

144,959.00

Problem?

B inspection and repairs roger dean

Task performed: **Parts** Quantity B-Inspection - roger dean NO PARTS USED ROGER DEAN Vendor? Workorder: V44646 In Date: 10/24/2011 Meter Reading: 145,467.00 10/27/2011 Close Date: Problem? auto eject /charger 10-7 dc10 Task performed: **Parts** Quantity Rep wire to plug on rear; reinstall panel on back door. NO PARTS USED Workorder: V44661 10/25/2011 In Date: 145,467.00 Meter Reading: Close Date: 10/28/2011 Problem? Check battery. Task performed: **Parts** Quantity 2 went to shop and met dc 10, found batt bad, r&r batt, ran 78-72BATTERY GROUP 78 and ck charging system ck ok return home 2 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

Workorder: V44745

In Date: 10/28/2011 Meter Reading: 146,059.00

Close Date: 10/28/2011

Problem?

Brake lights out.

Task performed: **Parts** Quantity

replaced left brake light bulb, checked all other lights **NO PARTS USED**



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V44782

In Date: 10/31/2011 Close Date:

11/01/2011

Meter Reading:

146,261.00

Problem?

on call rt rear tail light 10-7 dc10

Task performed: **Parts** Quantity

talked to dc - rob ordered part on another work order no

labor

NO PARTS USED

Workorder: V44783

In Date: 10/31/2011 Close Date: 11/02/2011

Meter Reading:

146,261.00

Problem?

replace tail light ass dc10

Task performed: Quantity **Parts**

Replc RR tail light. 15832092RIGHT REAR LAMP ASSBY

Workorder: V46100

In Date: 12/27/2011 Close Date:

12/28/2011

149,199.00 Meter Reading:

Problem? Swap tires.

Task performed: **Parts** Quantity

SWAP TIRES ON FRONT AND REAR AND TEST

WHEEL BEARING MAKING NOISE.

NO PARTS USED

Workorder: V46112

In Date: 12/27/2011

12/29/2011 Close Date:

Meter Reading:

149,199.00

Problem?

CHECK ENG LT ON REPAIR LIGHT IN LT BAR

Task performed: **Parts** Quantity

 CHECKED AND ERASED EVAP CODE. 25932571VALVE EVAP SYSTEM 1

REPLACED STROBE IN LIGHT BAR.

50R00FRRFLASHER RED LED FLANGED

1

TESTED EVAP SYSTEM WITH SMOKE MACHINE. TRACED LEAK TO SOLENOID VALVE. ORDER NEW VALVE. INSTALLED NEW EVAP SOLENIOD AND ROAD TESTED. CHECK ENGINE LIGHT, DID NOT

REAPPEAR.



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V46110

In Date: 12/27/2011

Close Date: 01/10/2012

Meter Reading: 149,199.00

Problem? Alignment.

Task performed: Parts Quantity

ALIGNMENT NO PARTS USED

Vendor? CALLAGHAN TIRE

Workorder: V45873

In Date: 12/14/2011 Meter Reading: 148,342.00

Close Date: 01/11/2012

Problem?

B inspection and repairs DC10 roger dean

Task performed: Parts Quantity

Oil and filter change

B inspection

Vendor? AL PACKER

NO PARTS USED

Workorder: V48754

In Date: 04/18/2012 Meter Reading: 153,886.00

Close Date: 05/01/2012

Problem?

Check engine light, a/c inop

Task performed: Parts Quantity

CHECK ENGINE LIGHT, A/C INOP

NO PARTS USED

Vendor? ROGER DEAN CHEVROLE

Workorder: V49498

In Date: 05/20/2012 Meter Reading: 153,886.00

Close Date: 06/11/2012

Problem?

A/C NOT WORKING

Task performed: Parts Quantity

A/C NOT WORKING.

NO PARTS USED

Vendor? ROGER DEAN CHEVROLE



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V50088

In Date: 06/12/2012

07/18/2012 **Close Date:**

Problem?

Keys were NOT in vehicle. Need to send keys to Sta. 42

Task performed: **Parts** Quantity

completed by LD NO PARTS USED

Meter Reading:

Workorder: V50537

In Date: 07/02/2012 Meter Reading: 154,263.00

Close Date: 07/18/2012

Problem?

REPAIR A/C ROGER DEAN

Task performed: **Parts** Quantity

REPAIR A/C ROGER DEAN NO PARTS USED

ROGER DEAN Vendor?

Workorder: V51777

In Date: 08/21/2012 154,263.00 Meter Reading: 08/21/2012

Close Date: Problem?

door locks inop, BC-900

Task performed: **Parts** Quantity

1. check door locks, found driver door lock inop, remove door panel and adjust rods for remote door lock, test

door lock and reassemble door panel

NO PARTS USED

Workorder: V52153

In Date: 09/04/2012 Meter Reading:

09/05/2012 Close Date:

Problem?

A/C not working AGAIN. Siren not working.

Task performed: **Parts** Quantity

1. check a/c found nothing wrong, blows cold out of vents.

2. check siren, also found windshield wipers inop, check fuses and wiper motor, found power for siren head tied into the winshield wiper fuse, replace fuse and install power wire for siren on different ign. fuse.

NO PARTS USED



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V55097

In Date: 01/16/2013 Close Date: 01/16/2013

Problem?

will not start, BC-900

Meter Reading: 155,947.00

rask performed:	Parts	Quantity
1. check for no start, test battery's, replace both	78-72BATTERY GROUP 78	2
batterys, test for draw, test charging system, all ok.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2

Workorder: V55532

In Date: 02/04/2013 Meter Reading: 155,947.00 Close Date: 02/07/2013

Problem?

noise comming from engine compt. BC-900

Task performed:	Parts	Quantity
1. check for noise, found p/s empty and fluid all over,	15295838HOSE P/S PUMP TO BOOSTER 05 SURB	1
degrease engine compt. and refill p/s and check for leak, found high pressure hose fron pump to brake booster leaking, order new hose	15295850P/S HOSE 02 SUBURBAN	1
2. replace pressure hose from p/s box to booster, remove fan belt. remove p/s pump pulley, remove p/s hose on pump, (had to remove pump could not loosen fitting)		

Workorder: V56374

In Date: 03/13/2013 Meter Reading: 15,659.00

replace pressure hose from pump to booster, reinstall pump, pully, and belt, refill pump, bleed system, road

Close Date: 03/13/2013

Problem?

test. ok

windshield washer inop, BC-900

Task performed:	Parts	Quantity
•		

check windshield washer, found hose came off of washer bottle, remove battery and replace dried out washer hose, fill w/fluid and test ok reinstall battery

NO PARTS USED



SUBURBAN FULLSIZE 4X4 SUV

In Date: 06/12/2012

Workorder: V50086

Close Date: 04/04/2013

Meter Reading:

Problem?

A/C not coming out vents. Only on top of dash. Vol 42

Task performed: Parts Quantity

repaired on 50537 NO PARTS USED

Workorder: V56920

In Date: 04/09/2013 Meter Reading: 15,659.00

Close Date: 04/09/2013

Problem?

install battery charger, BC-900

Task performed: Parts Quantity

1. remove interior panels, find wires that were disconnected when charger was removed from vehicle, install charger, battery indicator panel and wiring. install 2 new 30amp fuses inline with batterys reinstall panels, check charger ok

NO PARTS USED

PT308HARNESS KNOCK SENSOR

Workorder: V57563

In Date: 05/08/2013 Meter Reading: 15,659.00

Close Date: 05/14/2013

Problem?

check engine lite on, BC-900

Task performed:

- 1. check engine lite on, hook up laptop, had active code PO332 knock sensor #2
- order 2 knock sensors. will install when they come in
- 2. remove hoses, fuel rails, emission control sensors, and intake manifold. clean intake manifold and intake ports on head. waiting on sensors (ordered)
- 3. install both #1 and #2 knock sensors and new harness, install new intake manifold gaskets and install manifold, fuel rails, emission control sensors, air filter housing, run engine and have computer learn new knock sensors, road test vehicle. runs good

Parts	Quantity
213-3521KNOCK SENSOR	2
MS98016TMANIFOLD SET	1

2



10160673

SUBURBAN FULLSIZE 4X4 SUV

Workorder: V57914

In Date: 06/17/2013 Close Date:

06/17/2013

Meter Reading:

Meter Reading:

Problem?

Task performed:

wiper's intermittint, BC-900

ruen perrenneur
1. wipers intermittint, check, found fuse pins loose in
fuse panel trace out wires for wipers and bypass fuse
panel. install 20 amp inline fuse, run wiper's they stay on
all the time now.

Parts	Quantity
54177 TO 4 TRAILER WIRE CONNECTOR	2
TC45PLUG TRAILER CONNECTOR	1

Workorder: V60135

In Date: 08/28/2013

Close Date: 09/10/2013

Problem?

rear brakes down to metal, BC-900

Task performed:

- 1. remove rear wheels, brake pads down to metal, remove calibers, brake pads, rotors were rusted on spindle from salt water, heat up rotors and beat rotors off of spindle, order parts
- 2. install new rotors, calipers, brake pads, bleed system, install wheels and road test.
- 3. found master cylinder leaking, bleed new cylinder and install, road test

Parts	Quantity
121-66043ROTOR	2
13066045MASTER CYLINDER SURBURBAN	1
173-0549CALIPER	1
173-0550CALIPER	1
PD785REAR BRAKE PADS 02 SUBURBAN	1

Workorder: V60348

09/06/2013 In Date:

09/11/2013

Meter Reading:

Close Date: **Problem?**

A/C only runs on dial position 4. All other positions do not work.

Task performed:

- 1. check a/c blower control, remove blower motor cover found resitor inop, order new resitor
- 2. replace resitor, install new connector, reinstall blower cover, test a/c blower speeds, all work ok

Parts	Quantity
22807123MODULE BLOWER CONTROL	1



SUBURBAN FULLSIZE 4X4 SUV

12/17/2018

Workorder: V61903

11/08/2013 In Date: 11/08/2013 Close Date:

Meter Reading:

159,680.00

Problem?

Air bag warning on

Task performed:	Parts Parts	Quantity

NO PARTS USED

Replaced air bag module Replaced valve cover gasket Replaced left axle seal Serviced transmission

Replaced coolant hose to throttle body

Vendor? ROGER DEAN

Workorder: V61904

11/08/2013 In Date: **Close Date:** 11/08/2013

Meter Reading:

159,459.00

Problem?

Task performed: Quantity **Parts**

B-inspection NO PARTS USED

Meter Reading:

ROGER DEAN Vendor?

Workorder: V62110

11/18/2013 In Date:

Close Date: 11/25/2013

Problem? replace tires

Task performed: **Parts** Quantity

REPLACE TIRE. NO PARTS USED

Vendor? ELPEX



10160673 **SUBURBAN FULLSIZE 4X4 SUV**

12/17/2018

Workorder: V64428

02/21/2014 In Date: Close Date:

03/03/2014

Meter Reading:

Problem?

Task performed:

PARTS ONLY NO LABOR.

windshield washer tank cracked, BC-900

Task performed:			Parts	Quantity	
battery tray, windshield wellevel sensor, fender well, a clock on radio	remove driver asher tank, insta install new tank and install new	ove driver side battery a side fender well, remo all washer motors and wa , install battery tray, batte washer hoses, test ok, s rd to remove	ove ter ery,	12487671WASHER RESERVOR	1
Workorder:	V59901				
In Date: Close Date: Problem? bike rack	08/19/2013 03/19/2014	Meter Reading:			
Task perfori	med:			Parts	Quantity
PARTS ONL	Y NO LABOR.			59400BIKE RACK BY REESE	1
Workorder:	V64879				
In Date: Close Date: Problem? seat covers	03/12/2014 03/19/2014	Meter Reading:	160,459	9.00	
Task perfori	med:			Parts	Quantity
PARTS ONL	Y NO LABOR.			C1123-T91SEAT COVER FREIGHTSHIPPING CHARGES	1
Workorder:	V65205				
In Date: Close Date: Problem? hitch pins	04/09/2014 04/09/2014	Meter Reading:	161,088	3.00	

Parts

2560HITCH PIN/CLIP

Quantity 2



SUBURBAN FULLSIZE 4X4 SUV

10160673

12/17/2018

Workorder: V67119

In Date: 06/10/2014

06/12/2014 **Close Date:**

Meter Reading:

162,095.00

Problem? B-inspection

Task	performed	d: Parts Qu	ıanti [,]	ty
	•			_

NO PARTS USED

B-inspection

Inspect brakes and rotate tires Replaced air bag control unit

Replace a/c door actuators and control head

Vendor? AL PACKER

Workorder: V67284

06/17/2014 In Date: 06/17/2014 Close Date:

Meter Reading:

Meter Reading:

Problem?

brake light and abs light on, BC-900

Task performed: **Parts** Quantity

1. travel to sta-48, check vehicle, check brake fluid it was full, check for leaks, check brakes, road test vehicle, vehicle stopped ok, called john murray, I/duty f/f to pick up and bring to dealer for repair, travel back to s/shop

NO PARTS USED

Workorder: V67411

In Date: 06/24/2014

07/10/2014 Close Date:

Problem? ABS light on

Task performed: **Parts** Quantity

162.360.00

Replaced output speed sensor

ReplacedElectronic brake control module

Vendor? AL PACKER NO PARTS USED

V70352 Workorder:

In Date: 10/22/2014

10/22/2014 Close Date:

Meter Reading: 165,485.00

Problem?

Check eng light

Task performed: **Parts** Quantity

Replaced output speed sensor NO PARTS USED

Vendor? AL PACKER



SUBURBAN FULLSIZE 4X4 SUV

Quantity

Workorder: V72086

In Date: 01/06/2015

01/07/2015 Close Date:

Problem?

overheating, BC-900

Meter Reading:

Task performed:

fill radiator, pressure check found water pump leaking,

per john murray, will have towed to dealer

Meter Reading:

Workorder: V72131

In Date: 01/08/2015

01/13/2015 Close Date:

Problem?

Westway towing

Task performed: **Parts** Quantity

Parts

NO PARTS USED

REPAIRS AS REQUESTED. NO PARTS USED

Meter Reading:

WEST WAY TOWING Vendor?

Workorder: V72174

In Date: 01/09/2015

Close Date: 01/20/2015

Problem?

Al Packer B - Inspection

Task performed: **Parts** Quantity

167,077.00

WORK REPAIRS AS REQUESTED. NO PARTS USED

Vendor? AL PACKER

Workorder: V72563

In Date: 01/23/2015 167,147.00 Meter Reading:

02/02/2015 Close Date:

Problem?

runs rough, BC-900

Task performed:	Parts	Quantity
1. hook up scan tool, found code for o2 sensor on bank	12572705O2 SENSOR	2
#2, order both o2 sensors	19209808O2 SENSOR	1
2. replace all 4 o2 sensors, had to heat up exhaust system to remove they were frozen in exhaust pipe.	19209812O2 SENSOR	1



Asset: (10160673) 2004 - CHEVROLET SUBURBAN Fullsize 4X4 Suv

1	0	16	0	6	7	3

CSHOP-2015-1829

Comments: BC900 REAR TAIL LIGHT OUT

> Date Opened 7-20-2015 8-7-2015 Date Finished Meter 1 Reading: 168,145

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER

FAULT CODE ELECTRICAL

PARTS

TBA GASKET

NO PARTS USED

LAMP; RIGHT REAR LAMP ASSBY

LIGHT; TAIL LIGHT ASSBY

CSHOP-2015-3632

B-INSPECTION AL PACKER Comments:

> Date Opened 10-28-2015 Date Finished

10-28-2015 172,049 Meter 1 Reading:

TASKS PERFORMED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-1489

Date Opened 3-29-2016

Date Finished

5-3-2016

Meter 1 Reading:

174,924

TASKS PERFORMED

PARTS

DIAGNOSE ELECTRICAL

NEWPART; DASH CLUSTER

CSHOP-2016-3037

Comments:

WILL SEND TO PACKER

Date Opened 6-24-2016

Date Finished

7-28-2016

95,598 Meter 1 Reading:

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

AL PACKER **VENDOR?**

CSHOP-2016-5019

Comments: CHARGE AND TEST BATTERIES

> Date Opened 10-21-2016 Date Finished

10-24-2016

Meter 1 Reading: 128,219

TASKS PERFORMED

PARTS

BATTERY

2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

BATTERY; **BATTERY** GROUP 78

Asset Work Order History 10160673

CSHOP-2018-2051

Comments: CHECK UNIT OUT FOR TIM LEWIS TO USE FOR SPECIAL EVENT ALSO CHECK AC INOP

Date Opened 4-12-2018 Date Finished 4-19-2018 Meter 1 Reading: 175,700

TASKS PERFORMED Q PARTS

HEADLIGHTS LOW BEAM 1 9IP; 9006 BULB ASSY

RADIO-2016-543

Date Opened 9-9-2016 Date Finished 9-9-2016 Meter 1 Reading: 175,700

TASKS PERFORMED NO PARTS USED

RADIO

Service Requests:

09/09/2016 RADIO / /

SSHOP-2015-27

Comments: BC 900 BELT CAME OFF @ ST 58 CHECK TO MAKE SURE NOTHING IS LOCKED UP THANKS

Date Opened 4-28-2015 Date Finished 5-20-2015 Meter 1 Reading: 168,145

BELT; BELT

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

ENGINE AND ACCESSORIES