10181157 2011 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: Problem:	1009796 Pre Delivery	Meter: Inspection	0			In Date:	09/07/2010	Closed:	09/07/20	10
- Pre Delivery	Inspection									
,	•	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1009908 Install brush	<b>Meter:</b> guards.	383			In Date:	09/09/2010	Closed:	09/23/20	10
- Fabricate ar	nd install new l	orush guard	ds.drill and sec	cure	Parts Li	st				Qty
camper toppe	-	outer stand	and wiring.		Shop Su	upplies				1.00
- Shop Suppli	ies				Brush G	aurd Grille	Kit			1.00
					Gaurd H	lead Lights				1.00
	Hou :	rs 5.00		Labor:	300.00	Parts:	560.00	Total:	860.00	
Workorder: Problem:	1103256 Pm service.	Meter:	6542			In Date:	03/24/2011	Closed:	03/29/20	11
- Perform pm	service.				Parts Li	st				Qty
	balance all fou	r tires.			Shop Su	upplies				1.00
- Inspect and	perform powe	r winch ser	vice.		1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
- Shop Suppli	ies				5w20 Er	ngine Oil				7.00
					Floor Ma	ats				1.00
	Hou	rs 4.75		Labor:	285.00	Parts:	77.52	Total:	362.52	
Workorder: Problem:	1110419 Pm service a	Meter: nd left strol	12570 be light mount			In Date:	09/29/2011	Closed:	09/30/20	11
- P.m. Service	e.				Parts Li	st				Qty
	nd repair brack	et for left s	ide strobe ligh	t.	Big G D	egreaser St	ock# 4851800	002		1.00
- Inspect and	service winch		J		Shop Su	_				1.00
- Rotate and I	balance all tire	S.			Ca1026	2 Air Filter N	∕ltc Fa1883 W	/ix 49883		1.00
- Shop Suppli	ies				1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
					L0135-0 Lube,03		te Chain&cab	le		1.00
					5w20 Er	ngine Oil				8.00
					31-22 W	iper Blades/	22" Wiper Bl	ade		2.00
					Used Fi	rex Refurbe	d Fire Extings	shers		1.00
	Hou	rs 5.75		Labor:	345.00	Parts:	68.18	Total:	413.18	
Workorder: Problem:	1202072 wash	Meter:	17838			In Date:	02/29/2012	Closed:	03/01/20	12
- wash mud fr	rom truck				Parts Li	st				Qty
- Shop Suppli							ock #4853601	04		1.00
					Shop Su	-				1.00
	Hou	rs 1.50		Labor:			10.02	Total:	100.02	
	:									

Workorder:	1202246	Meter:	17936			In Date:	02/29/2012	Closed:	03/05/2	112
	winch out/tov			stomer atte	empting t			Oioseu.	03/03/2	<i>J</i> 1 ∠
	Off North Lake				. •	-				
		ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1202335 2nd Tow truc	Meter: ck used to re	17936 emove truck f	rom natur	al area	In Date:	03/07/2012	Closed:	03/07/2	012
- Tow From: o	off nl blvd w of	441								
	Hou	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1203055 P.M. service.	Meter:	19195			In Date:	03/29/2012	Closed:	04/18/2	012
- P.m. Service	е.				Parts L	ist				Qty
- Replace bro	ken left and ri	ght side rur	ning boards.		Shop Si	upplies				1.00
- Secure right	t strobe light b	racket to to	pper.		1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
	and charging			st		ngine Oil				8.00
battery,fail loa	id test.replace iler plug.fabrica		•	d		emale Conne				1.00
bracket.	iei piug.iabiica	ate and rep	iace wires ari	u		550aa Tag L	• , ,	۵)		1.00
- Rotate and I	balance all tire	es.			•	• `	ntc Bxt-65-85	0)		1.00
- Shop Suppli	ies				-	Board R/h				1.00
	Hou	ırs 8.25		Labor:	495.00	Board L/h Parts:	1,128.82	Total:	1,623.8	
Workorder:	1203895	Meter:	19768			In Date:	04/25/2012	Closed:	04/26/2	212
	Right front tir		19700			iii Date.	04/23/2012	Ciosea.	04/20/2	J12
- Repair and	balance right f	ront tire.			Parts L	ist				Qty
- Shop Suppli	ies				Shop Si	upplies				1.00
	Hou	ırs 1.00								1.00
		113 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	1.00
Workorder: Problem:	1204286	Meter:	20533 and is in back				2.00	Total:	62.00 05/10/2	
Problem:	: 1204286 Winch cable	Meter: pulled out a	and is in back	of topper		Parts:				012
Problem:	: 1204286 Winch cable ads on drum fo	Meter: pulled out a	and is in back	of topper	Parts L	Parts: In Date:				012 <b>Qty</b>
Problem: - Repair threa	: 1204286 Winch cable ads on drum fo able back on to	Meter: pulled out a	and is in back	of topper		Parts: In Date:				012
Problem: - Repair threa and respool ca	: 1204286 Winch cable ads on drum fo able back on to ies	Meter: pulled out a	and is in back	of topper	Parts L Shop Si	Parts: In Date:	05/07/2012	Closed:		012 <b>Qty</b>
Problem: - Repair threa and respool ca	: 1204286 Winch cable ads on drum fo able back on to ies	Meter: pulled out a or winch cat o reel.	and is in back	of topper	Parts L Shop Si	Parts:  In Date:  ist  upplies	05/07/2012	Closed:	05/10/2	012 <b>Qty</b> 1.00
Problem: - Repair threa and respool ca - Shop Suppli	: 1204286 Winch cable ads on drum fo able back on to ies Hou :	Meter: pulled out a or winch cab o reel.  ars 1.00  Meter:	and is in back ble anchor the 28280	of topper en secure Labor:	Parts L Shop Si 60.00	Parts:  In Date:  ist  upplies  Parts:	05/07/2012	Closed:	05/10/2 62.00	012 <b>Qty</b> 1.00
Problem: - Repair threa and respool ca - Shop Suppli	: 1204286 Winch cable ads on drum for able back on to ies Hou: 1210286 P.M. service	Meter: pulled out a or winch cab o reel.  ars 1.00  Meter:	and is in back ble anchor the 28280	of topper en secure Labor:	Parts L Shop Si 60.00	Parts:  In Date:  ist  upplies  Parts:  In Date:	05/07/2012	Closed:	05/10/2 62.00	O12 Qty 1.00
Problem: - Repair threa and respool ca - Shop Suppli  Workorder: Problem: - P.m. Service	: 1204286 Winch cable ads on drum for able back on to ies Hou: 1210286 P.M. service	Meter: pulled out a or winch cab o reel.  urs 1.00  Meter: and topper	and is in back ble anchor the 28280	of topper en secure Labor:	Parts L Shop Si 60.00 p. Parts L	Parts:  In Date:  ist  upplies  Parts:  In Date:	05/07/2012	Closed:	05/10/2 62.00	O12 Qty 1.00 O12 Qty
Problem: - Repair threa and respool ca - Shop Suppli  Workorder: Problem: - P.m. Service - Replace top - Remove right	: 1204286 Winch cable ads on drum for able back on to ies Hou: 1210286 P.M. service e. oper door strut	Meter: pulled out a or winch cab o reel.  Irs 1.00  Meter: and topper	and is in back ble anchor the 28280 struts for rea	of topper en secure Labor:	Parts L 60.00  p. Parts L 5w20 E	Parts: In Date: ist upplies Parts: In Date:	05/07/2012 2.00 10/25/2012	Closed:	05/10/2 62.00	O12 O12 O12 O12 O12 Rety 8.00
Problem: - Repair threa and respool ca - Shop Suppli  Workorder: Problem: - P.m. Service - Replace top - Remove right straighten.rep	: 1204286 Winch cable ads on drum for able back on to see the service 1210286 P.M. service e. oper door strutht side strobe lace tag light be	Meter: pulled out a or winch cab o reel.  Irs 1.00  Meter: and topper  i. light bracke oulb.	and is in back ble anchor the 28280 struts for rea	of topper en secure Labor:	Parts L Shop Si 60.00  p. Parts L 5w20 Ei Ph2 Oil	Parts:  In Date:  ist upplies Parts:  In Date:  ist ngine Oil	05/07/2012 2.00 10/25/2012	Closed:	05/10/2 62.00	O12  Qty 1.00  O12  Qty 8.00 1.00
Problem: - Repair threa and respool care and respool care Shop Suppli  Workorder: Problem: - P.m. Service: - Replace top: - Remove rightstraighten.replication.replication.	: 1204286 Winch cable ads on drum for able back on to able back of ab	Meter: pulled out a or winch cab o reel.  Irs 1.00  Meter: and topper  i. light bracke oulb.	and is in back ble anchor the 28280 struts for rea	of topper en secure Labor:	Parts L Shop Si 60.00  p. Parts L 5w20 Ei Ph2 Oil 31-22 W	Parts:  In Date:  ist  upplies  Parts:  In Date:  ist  ngine Oil  Filter Lbf Pr	05/07/2012 2.00 10/25/2012	Closed:	05/10/2 62.00	O12 O12 O12 O12 O12 O12 012 012 012 012
Problem: - Repair threa and respool care and respool care Shop Suppli  Workorder: Problem: - P.m. Service: - Replace top: - Remove rightstraighten.replication.replication.replication.	: 1204286 Winch cable ads on drum for able back on traiting ites House 1210286 P.M. service e. oper door struth side strobe lace tag light be service winch balance tires.	Meter: pulled out a or winch cab o reel.  Irs 1.00  Meter: and topper  i. light bracke oulb.	and is in back ble anchor the 28280 struts for rea	of topper en secure Labor:	Parts L Shop Si 60.00  p. Parts L 5w20 Ei Ph2 Oil 31-22 W	Parts:  In Date:  ist  upplies  Parts:  In Date:  ist  ngine Oil  Filter Lbf Pr /iper Blades rex Refurbe	05/07/2012 2.00 10/25/2012	Closed:	05/10/2 62.00	O12  Qty 1.00  Qty 8.00 1.00 2.00 1.00
Problem: - Repair threa and respool care and respool care Shop Suppli  Workorder: Problem: - P.m. Service: - Replace top: - Remove rightstraighten.replication.replication.	: 1204286 Winch cable ads on drum for able back on to ies Houring: 1210286 P.M. service e. oper door strutt ht side strobe lace tag light be service winch balance tires.	Meter: pulled out a or winch cab o reel.  Irs 1.00  Meter: and topper  i. light bracke oulb.	and is in back ble anchor the 28280 struts for rea	of topper en secure Labor: r door ino	Parts L Shop Si 60.00  p. Parts L 5w20 Ei Ph2 Oil 31-22 W Used Fi	Parts:  In Date:  ist  upplies  Parts:  In Date:  ist  ngine Oil  Filter Lbf Ph /iper Blades rex Refurbe	05/07/2012 2.00 10/25/2012	Closed:	05/10/2 62.00	012 <b>Qty</b> 1.00

Workorder: 1 Problem: P	304676 Pm service	Meter:	34338		lr	n Date:	05/09/2013	Closed:	05/31/2013
- P.m. Service.					Parts List				Qty
- Replace broke	en fuel tank s	shield.			5w20 Engi	ne Oil			8.00
- Resurface rea			ear pads.serv	vice and	Napagold (	Oil Filter			1.00
lube rear brake of	calipers.fl;us	sh and blee	d system.		Napagold /				1.00
- Replace broke	en running b	oards with i	nerf bars.		Stg Wheel	Cov - Fo	rd		1.00
- Replace and b					31-22 Wipe	er Blades	3 22		2.00
- Inspect and se		.dis-asseml	ble winch gea	ars and	Heat Shiel				1.00
<ul><li>clean rust and re</li><li>Shop Supplies</li></ul>					Rear Pads				1.00
- Shop Supplies	•				Brake Clea	aner			1.00
					Step Bar				1.00
					179535492	2 Lt265-7	0r17		4.00
					Gdy Wrang	gler Silen	t Armor		4.00
					Shield				1.00
					Lt265/70r1	7 Gdy Si	lent Armor		4.00
					Lt265/70r1	7 Gdy Si	lent Armor		4.00
					Shop Supp	olies			1.00
					Tire Dispos	sal Fee			4.00
					0 = .0 p 0 .				
	Hou :	ırs 14.75		Labor:	885.00		6,160.66	Total:	7,045.66
Workorder: 1 Problem: H	310094	Meter:	38544	Labor:	885.00		6,160.66	Total:	7,045.66
Problem: H - Recharge batte	: 310094 Had to jump tery and test	Meter: start in AM.			885.00 Ir	Parts:	-		
Problem: H - Recharge batte test.replace defe	: 310094 Had to jump tery and test ective batter	Meter: start in AM.			885.00 Ir	Parts:	-		10/16/2013
Problem: H	: 310094 Had to jump tery and test ective batter	Meter: start in AM.			885.00 Ir	Parts:	-		10/16/2013 Qty
Problem: H - Recharge batte test.replace defe	: 310094 Had to jump tery and test ective batter	Meter: start in AM.			Parts List Battery Shop Supp	Parts:  n Date:  olies	-	Closed:	10/16/2013 Qty 1.00
Problem: H - Recharge batte test.replace defe - Shop Supplies	: 310094 Had to jump tery and test ective batter s Hou : 312535	Meter: start in AM. charging s y. ars 1.00 Meter:		y fail load	Parts List Battery Shop Supp	Parts:  n Date:  olies	10/07/2013	Closed:	10/16/2013 Qty 1.00
Problem: H - Recharge batte test.replace defe - Shop Supplies Workorder: 1	: 310094 Had to jump stery and test ective batters  Hou : 312535 P.M. service.	Meter: start in AM. charging s y. ars 1.00 Meter:	ystem.battery	y fail load	Parts List Battery Shop Supp	Parts:  n Date:  plies     Parts:  n Date:	10/07/2013	Closed:	10/16/2013 Qty 1.00 1.00 181.61
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P	: 310094 Had to jump tery and test ective batter  Hou : 312535 P.M. service.	Meter: start in AM. charging s y. ars 1.00 Meter:	ystem.battery 40344	y fail load	Parts List Battery Shop Supp 60.00	Parts:  Date:  Parts:  Parts:	10/07/2013	Closed:	10/16/2013  Qty 1.00 1.00 181.61
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ace failed tag and inspect	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys	ystem.battery 40344 with new.	y fail load Labor:	Parts List Battery Shop Supp 60.00  In	Parts:  n Date:  Parts:  n Date:	10/07/2013	Closed:	10/16/2013  Qty 1.00 1.00 181.61  12/30/2013
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h	: 310094 Had to jump tery and test ective batters  Hou : 312535 P.M. service. ervice. ace failed tag and inspect heater hose	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys to correct c	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin	Parts:  Date:  Parts:  Date:  Date:  Date:  Date:  Parts:	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013  Qty 1.00 1.00 181.61  12/30/2013  Qty 8.00
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h radiator core from	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ervice. ace failed tag and inspect heater hose m debri and	Meter: start in AM. charging s y. ars 1.00 Meter: glamp bulb cooling sys to correct c top off coo	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin	Parts:  n Date:  Parts:  n Date:  n Date:  ne Oil Oil Filter Air Filter	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013  Qty 1.00 181.61  12/30/2013  Qty 8.00 1.00
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h radiator core from - Inspect and se	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ace failed tag and inspect neater hose m debri and ervice power	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys to correct c top off coo	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin Napagold ( Napagold (	Parts:  Date:  Date:  Date:  Date:  Date:  Date:  Dil Filter  Dil Filter	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013 Qty 1.00 181.61 12/30/2013 Qty 8.00 1.00 1.00
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h radiator core from - Inspect and se - Rotate and bal	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ace failed tag and inspect neater hose m debri and ervice power	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys to correct c top off coo	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin Napagold ( Napagold / Wiper Blad	Parts:  n Date:  Diles Parts:  n Date:  ne Oil Oil Filter Air Filter de X Refurb	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013  Qty 1.00 181.61  12/30/2013  Qty 8.00 1.00 2.00
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h radiator core from - Inspect and se	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ace failed tag and inspect neater hose m debri and ervice power	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys to correct c top off coo	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin Napagold ( Napagold ( Wiper Blad Used Fire 2)	Parts:  n Date:  Diles Parts:  n Date:  ne Oil Oil Filter Air Filter de X Refurb	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013 Qty 1.00 181.61  12/30/2013  Qty 8.00 1.00 2.00 1.00
Problem: H - Recharge batte test.replace defe - Shop Supplies  Workorder: 1 Problem: P - Perform pm se - Test and repla - Pressure test a hose clamp on h radiator core from - Inspect and se - Rotate and bal	: 310094 Had to jump tery and test ective batter s Hou : 312535 P.M. service. ervice. ace failed tag and inspect neater hose m debri and ervice power	Meter: start in AM. charging s y. irs 1.00 Meter: glamp bulb cooling sys to correct c top off coo	ystem.battery 40344 with new. stem.replace toolant leak.cl	y fail load Labor:	Parts List Battery Shop Supp 60.00  In  Parts List 5w20 Engin Napagold ( Napagold ( Wiper Blad Used Fire ( Stg Wheel	Parts:  n Date:  Diles Parts:  n Date:  ne Oil Oil Filter Air Filter de X Refurb Cov - Fo	10/07/2013 121.61 12/17/2013	Closed:	10/16/2013  Qty 1.00 181.61  12/30/2013  Qty 8.00 1.00 2.00 1.00 1.00 1.00

Workorder: Problem:	1404031 Pm service.Ac	Meter: 4786 inop.Stalls after		In	Date:	04/24/2014	Closed:	05/08/2014
test and replace codes with scare - Clean and dand replace far - Inspect and	iagnose for stall ce failed mass a an tool and road	air flow sensor voltest.  /aporator core a c	and housing.test	Parts List 5w20 Engir Napagold A Wiper Blad Evap Odor Sensor Asy	Oil Filter Air Filter e Elinitato	r		Qty 8.00 1.00 1.00 2.00 1.00
- Shop Suppli		mes.		fan and mo Shop Supp	otor			1.00
	Hours	9.25	Labor:	555.00	Parts:	335.35	Total:	890.35
Workorder: Problem:	1409964 P.M. Service.C	Meter: 5437 Check a/c and re	70 ear camper door.		Date:	10/02/2014	Closed:	10/27/2014
- Replace bot rear differential - Inspect and - Replace from rotors.replace contamination - Ac performal actuators with - Inspect and	plugs and ignition h rear leaking a al. service front different brake pads and rear parking brace, service calipers unce and leak te scan tool. service power we balance all four	on wires.  xle seals.insper  ferential.  nd resurface boake shoes due sand bleed hyd  st.recalibrate m	th front brake to oil Iraulic system.	Parts List Wheel Sea Reman Bra Wire 5w20 Engir Napagold ( Used Fire ) Wiper Blad Washer Flu Coil Spark Plug 1qt Syngea Friction Mo Napa Gear Pads 1401 Brak Brake Clea 75w140 Fo Coil	ne Oil Dil Filter X Refurbi e uid Conce ar Oil 75- difier 80w-90 e Fluid B	ished entr 90 Qt		2.00 1.00 8.00 1.00 1.00 2.00 1.00 2.00 16.00 4.00 2.00 3.00 1.00 1.00 4.00 1.00
	Hours :	3 23.25	Labor:	Shop Supp 1,395.0 0		973.31	Total:	1.00 2,368.31

Workorder:											
Problem:	1502531 P.M. Ser	vice.C	Meter: heck end	58474 jine light,stalls	s and stro	bes work	In Date: s intermitter	03/10/2015 nly.	Closed:	03/20/20	015
- Pm service.				, - 5 ,		Parts Li		,			Qty
- Inspect and	diagnosa	for no	war etaar	ing look no n	ower		Led Strobe	, CI			1.00
assist.test and	•	•		•			ngine Oil	; CI			8.00
assembly.						Napago	ld Oil Filter				1.00
- Test and rep				•	lb.	Wiper B					2.00
- Computer d						•	Trans Fluid	S			2.00
stalling.codes test and replace						•	Steering Pur				1.00
tool.roadtest.	00 00100111	o puis	go varvo.	ologi oogoo w	Tur oour	Brake C	O	пр			1.00
- Inspect and	service wi	nch.									
- Rotate and I			ires.			Valve A	-				1.00
- Shop Suppli						Shop Su	applies				1.00
опор оцерп		Hours	10.50		Labor:	630.00	Parts:	487.30	Total:	1,117.30	0
Workorder:	1504737	:	Meter:	59937			In Date:	05/11/2015	Closed:	05/12/20	 015
Problem:		r tire f	lat.								
- Repair and	balance ri	ght rea	ar tire.			Parts Li	st				Qty
- Shop Suppli	ies					Shop Su	upplies				1.00
		Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1505387	•	Meter:	60550			In Date:	05/29/2015	Closed:	06/08/20	<u></u>
							iii Dato.		Olocou.	00,00,=	515
Problem:	Rear doo	r lock	outer ha	ndle.			iii Dato.		Olooou.	00,00,=	313
Problem: - Replace def						Parts Li			Olooou.	03,03,=	Qty
	fective rea							ndle	Giocoai	03,03,=	
- Replace def	fective rea						i <b>st</b> or Lock Har	ndle	Giocoai	00,00,2	Qty
- Replace def	fective rea					Real Do	i <b>st</b> or Lock Har upplies	ndle	olossu.		<b>Qty</b> 1.00
- Replace def	fective real		door ha		Labor:	Real Do Shop Su Freight 0	i <b>st</b> or Lock Har upplies Charge	ndle 67.30		127.30	<b>Qty</b> 1.00 1.00
- Replace def - Shop Suppli	fective realies	r outer Hours :	1.00 Meter:	ndle. 60949	Labor:	Real Do Shop Su Freight 0	i <b>st</b> or Lock Har upplies Charge Parts:	67.30		127.30	<b>Qty</b> 1.00 1.00
- Replace def - Shop Suppli Workorder: Problem:	fective real ies 1506160 Jump sta	r outer Hours : rt.Dea	1.00  Meter: d battery	60949		Real Do Shop Su Freight 6	or Lock Har upplies Charge Parts:	67.30	Total:	127.30	Qty 1.00 1.00 1.00
- Replace def - Shop Suppli Workorder: Problem: - Test battery	fective real ies 1506160 Jump sta	r outer Hours : rt.Dea	1.00  Meter: d battery	60949		Real Do Shop Su Freight ( 60.00	or Lock Har upplies Charge Parts:	67.30	Total:	127.30	Qty 1.00 1.00 1.00
- Replace def - Shop Suppli Workorder: Problem:	fective real ies 1506160 Jump sta	r outer Hours : rt.Dea	1.00  Meter: d battery	60949		Real Do Shop Su Freight 6 60.00 Parts Li Battery	or Lock Har upplies Charge Parts: In Date:	67.30	Total:	127.30	Qty 1.00 1.00 1.00 015 Qty 1.00
- Replace def - Shop Suppli Workorder: Problem: - Test battery	fective real ies 1506160 Jump sta and chargies	r outer Hours : rt.Dea ging sy	1.00  Meter: d battery	60949	ery.	Real Do Shop Su Freight ( 60.00 Parts Li Battery Shop Su	or Lock Har upplies Charge Parts: In Date:	67.30 06/18/2015	Total:	127.30	Qty 1.00 1.00 1.00
- Replace def - Shop Suppli Workorder: Problem: - Test battery	fective real ies 1506160 Jump sta and chargies	r outer Hours : rt.Dea	1.00  Meter: d battery	60949		Real Do Shop Su Freight ( 60.00 Parts Li Battery Shop Su	or Lock Har upplies Charge Parts: In Date:	67.30	Total:	127.30	Qty 1.00 1.00 1.00 015 Qty 1.00
- Replace def - Shop Suppli Workorder: Problem: - Test battery	1506160 Jump star and chargies	r outer Hours : rt.Dea ging sy	1.00  Meter: d battery	60949	ery.	Real Do Shop Su Freight ( 60.00 Parts Li Battery Shop Su	or Lock Har upplies Charge Parts: In Date:	67.30 06/18/2015	Total:	127.30	Qty 1.00 1.00 1.00 015 Qty 1.00
- Replace def - Shop Suppli  Workorder: Problem: - Test battery - Shop Suppli  Workorder:	1506160 Jump star and chargies 1506211 No start	Hours: : rt.Dea ging sy Hours:	1.00  Meter: d battery vstem.rep 1.00  Meter:	60949 blace bad batt	ery. Labor:	Real Do Shop Su Freight 0 60.00 Parts Li Battery Shop Su 60.00	or Lock Har upplies Charge Parts: In Date: st upplies Parts:	67.30 06/18/2015 120.41	Total: Closed: Total:	127.30 06/22/20 180.41	Qty 1.00 1.00 1.00 015 Qty 1.00

Workorder: Problem:	1509418 Pm service.T		1026 and low tire pres		n Date:	09/17/2015 shing.Noise ov	Closed: rer bumps.	10/13/2015	
- Pm service.			·	Parts List		_	•	C	Qty
	smission.repla	ace filter.flush a	and replace fluid.	5w20 Eng					.00
	service transfe			Napagold					.00
·	d balance all fo			Napagold					.00
· ·		ent.and roadte	est.	Wiper Blad				2.	.00
·	service power			Used Fire		ished		1.	.00
- Shop Suppli	es			Bulb				1.	.00
				Transmiss	ion Filter			1.	.00
				Syn-atf Tra	ans Fluid	S		20.	.00
				Ford Trans	sfer Case	Fluid		2.	.00
				Lt265/70r1	17 Gdy Si	ilent Armor		4.	.00
				Shop Supp	plies			1.	.00
				Tire Dispo	sal Fee			4.	.00
	Hou :	rs 11.75	Labo	r: 705.00	Parts:	1,425.01	Total:	2,130.01	
Workorder:	1602891		9725		n Date:	03/17/2016	Closed:	03/31/2016	<del></del>
Problem:	Pm service.N	loise in front ei	nd.Truck crabing	down the road	d.				
- Pm service.				Parts List	:			C	Qty
			ock absorbers.als	o 5w20 Eng	ine Oil			7.	.00
replace defect	_	•		Napagold	Oil Filter			1.	.00
•	service winch			Napagold	Air Filter			1.	.00
	palance all fou			22" Wiper	Blade			2.	.00
	nt end alignme	nt.		Used Fire	X Refurb	ished		1.	.00
- Shop Suppli	es			Gas Grand	de Shock			2.	.00
				Gas Grand	de Shock			2.	.00
				Steering S	Stabilizer			1.	.00
				Stg Wheel	Cov - Fo	ord		1.	.00
				Shop Supp	plies			1.	.00
	Hou :	rs 10.00	Labo	r: 600.00	Parts:	345.85	Total:	945.85	
Workorder: Problem:	1606931 P.M. service	Meter: 75 and body dam	6035 age in rear.	lı	n Date:	07/11/2016	Closed:	07/25/2016	;
- P.m. Service	э.			Parts List	:			C	Qty
- Replace tag	lamp bulb.			5w20 Eng	ine Oil			7.	.00
- Replace cor	roded trailer c	onnector.fabric	ate and replace	Napagold	Oil Filter			1.	.00
wiring.				22" Wiper	Blade			2.	.00
	palance all tire			Bulb				1.	.00
	service winch			trailer plug	]			1.	.00
- Shop Suppli	es			Drain Plug	]			1.	.00
				Shop Supp	plies			1.	.00
	Hou	rs 6.50	Labo	r: 390.00	Parts:	41.38	Total:	431.38	

Workorder: Problem:	1608165 <b>Meter:</b> 7 Noise from blower motor.	75441		In Date:	08/09/2016	Closed:	08/25/20	)16
- Diagnose no - Shop Supplie	ise in dash.replace defecti es	ve blower motor.	Parts Li Blower M Shop Su	/lotor				<b>Qty</b> 1.00
	Hours 1.50	Labor:	•	• •	169.75	Total:	259.75	1.00
Workorder: Problem:	1608275 <b>Meter:</b> 7 Damage to rear bumper, t	75046 ire holder, topper doc	ors, right i	In Date: ear fender	07/15/2016 & right tail ligh	Closed:	08/11/20	)16
- Damage to r fender & right t	ear bumper, tire holder, top ail light.	oper doors, right rear						
	Hours 0.00 :	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1609442 <b>Meter:</b> 7 Squealing noise with RPM	76822 Ms and knocking nois	e over bu	In Date: mps.	09/12/2016	Closed:	09/28/20	)16
mounts Diagnose sq assemble - Shop Supplie	Hours 9.00 : 1610603 <b>Meter:</b> 7	Labor:	Insulator Insulator Insulator Insulator	onuts  d Lck Blue bunt . haft pplies	Lg 1,229.50 10/13/2016	Total:	1,769.50	
			Parts Li Bulb Rpl Bulb Shop Su 60.00		3.64	Total:	63.64	<b>Qty</b> 1.00 1.00
Workorder: Problem:	1611044 <b>Meter:</b> 7 Right front tire going flat.	78281		In Date:	10/26/2016	Closed:	10/31/20	)16
	balance right front tire.	Labor:	Shop Su Tire Disp	or17 Gdy Sil opplies oosal Fee	lent Armor 291.31	Total:	321.31	<b>Qty</b> 1.00 1.00 1.00

Workorder:	1701147 P.M. service	Meter:	82636	ard and o	ramner to	In Date:	02/02/2017	Closed:	02/22/20	17
- P.m. Service		ana Avo do	ics not blow no	ara aria c	Parts Li		•			Qty
	s. semble and re	onlaco clos	and overnoreto	.r	5w20 Er					7.00
core,accumula						•				1.00
specs.			,			d Oil Filter				1.00
	nd install moun	iting bracke	ets for camper	topper	22" Wipe	d Air Filter				2.00
rear door strut					•	e X Refurbi	shed			1.00
- Rotate and b					Evapora		Silou			1.00
- Shop Suppli	es				Accumu					1.00
					Seal Kits					3.00
					Seal	•				2.00
					Kit O					1.00
					Freon L	/ Shop 2				2.00
					Support					2.00
						With Stud				2.00
					Washer	Nozzle				1.00
					Shop Su	pplies				1.00
	Hou :	rs 16.75		Labor:	1,005.0 0	Parts:	593.00	Total:	1,598.00	
Workorder: Problem:	1702409 Fuel cap brok	Meter: ken.	84013			In Date:	03/09/2017	Closed:	03/21/20	17
- Replace bro	ken fuel cap.				Parts Li	st				Qty
•	nd test battery	replace ba	d battery.		Gas Car	Non-lockir	ng			1.00
- Shop Suppli	-	•	·		Battery					1.00
					Shop Su	pplies				1.00
	Hou	rs 1.25		Labor:			135.86	Total:	210.86	
Workorder: Problem:	1702675 tried jumping	Meter: wont start	83719			In Date:	03/13/2017	Closed:	03/15/20	17
- Tow From: 1 2601 vista	40 carina dr o	off indianton	w of turnpike	To:						
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
							06/13/2017	Olasa ala	06/45/20	
Workorder: Problem:	1705850 Left front tire	Meter: going flat.	87531			In Date:	00/13/2017	Closed:	06/15/20	17
Problem:		going flat.			Parts Li		00/13/2017	Closea:	06/15/20	Qty
Problem:	Left front tire ont tire and ba	going flat.			Parts Li Shop Su	st	06/13/2017	Closea:		

Workorder: Problem:	1705971 P.M. service.	Meter:	88307		In D	Date:	06/16/2017	Closed:	07/10/20	)17
- P.m. Service	e.				Parts List					Qty
- Replace righ	ht headlamp a	nd melted s	socket.		Washer Fluid	Conce	entr			1.00
- Replace lea	king left rear a	xle seal.			5w20 Engine	Oil				7.00
- Rotate and	balance tires.				Napagold Oil	Filter				1.00
- Inspect and	service winch				22" Wiper Bla	ade				3.00
- Shop Suppli	ies				Mac Wite Lith	hium G	res			1.00
					Halogen Cap	sule				1.00
					Wire Asy					1.00
					Seal					1.00
					Axle O Ring					1.00
					Shop Supplie	es				1.00
	Hou	irs 7.75		Labor:	465.00	Parts:	138.47	Total:	603.47	
vorkoraer:	1709034	Meter:	91389							
Problem: - Battery faile	Had to jump	start at vista	a parking gara natic charge te	est	Parts List					-
Problem: - Battery faile replace bad b	Had to jump	start at vistar rform auton ck starting a	a parking gara natic charge te	est	Battery	26				<b>Qty</b> 1.00
Problem:  - Battery faile replace bad be service call at	Had to jump and load test Per pattery. Rechest t vista parking	start at vistar rform auton ck starting a	a parking gara natic charge te	est		es				1.00
Problem: - Battery faile replace bad be service call at	Had to jump ad load test Pe pattery. Reche t vista parking ies	start at vistar rform auton ck starting a	a parking gara natic charge te	est system	Battery Shop Supplie		126.43	Total:	246.43	1.00
Problem: - Battery faile replace bad be service call at - Shop Suppli	Had to jump ad load test Pe pattery. Reche t vista parking ies	start at vistarform automock starting a garage.  Irs 2.00  Meter:	a parking gara natic charge te	est system	Battery Shop Supplie 120.00		126.43	Total:	246.43	1.00
Problem:  - Battery faile replace bad be service call at - Shop Suppli	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922	start at vistarform automock starting a garage.  Irs 2.00  Meter: going flat.	a parking gara natic charge to and charging s	est system	Battery Shop Supplie 120.00	Parts:				1.00
Problem: - Battery faile replace bad be service call at - Shop Suppli	Had to jump ad load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and ba	start at vistarform automock starting a garage.  Irs 2.00  Meter: going flat.	a parking gara natic charge to and charging s	est system	Battery Shop Supplie 120.00 In D	Parts:  Date:				1.00 1.00 1.00 017
Problem: - Battery faile replace bad be service call at - Shop Suppli	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies	start at vistarform automock starting a garage.  Irs 2.00  Meter: going flat.	a parking gara natic charge to and charging s	est system	Battery Shop Supplied 120.00 In D Parts List Shop Supplied	Parts:  Date:	10/11/2017	Closed:		1.00 1.00 1.00 017
Problem: - Battery faile replace bad be service call at Shop Supplied Problem: - Repair left results - Shop Supplied Problem: - Repair left results - Shop Supplied Problem:	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies	rform automock starting a garage.  Irs 2.00  Meter: going flat. Ilance .nitro	a parking garanatic charge to and charging some some some some some some some some	est system Labor: Labor:	Battery Shop Supplied 120.00  In D  Parts List Shop Supplied 60.00	Parts:  Date:	10/11/2017	Closed:	10/17/20	1.00 1.00 1.00 017 Qty
Problem: - Battery faile replace bad be service call at Shop Supplied Problem: - Repair left results - Shop Supplied Problem: - Problem: - Replace left	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies Hou : 1711027 Tire light on ,	rform automock starting a garage.  Irs 2.00  Meter: going flat. Ilance .nitro Irs 1.00  Meter: left front and repair left fro	a parking gara natic charge to and charging s  92089  92089  92915 nd left rear tire	est system  Labor:  Labor:	Battery Shop Supplied 120.00  In D  Parts List Shop Supplied 60.00	Parts:  Date:  es  Parts:	10/11/2017	Closed:	10/17/20	1.00 1.00 017 Qty 1.00
Problem:  - Battery faile replace bad be service call at service replace bad be service call at replace be service call at replace left	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies Hou : 1711027 Tire light on , erear tire and res.reset Tpms	rform automock starting a garage.  Irs 2.00  Meter: going flat. Ilance .nitro Irs 1.00  Meter: left front and repair left fro	a parking gara natic charge to and charging s  92089  92089  92915 nd left rear tire	est system  Labor:  Labor:	Battery Shop Supplied 120.00  In D  Parts List Shop Supplied 60.00  In D  at.	Parts:  Date:  Parts:  Date:	2.00	Closed:	10/17/20	1.00 1.00 1.00 017 1.00 017
Problem: - Battery faile replace bad be service call at - Shop Supplication of the service service replace for the service service replace left replace left nitrogen fill time.	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies Hou : 1711027 Tire light on , erear tire and res.reset Tpms	rform automock starting a garage.  Irs 2.00  Meter: going flat. Ilance .nitro Irs 1.00  Meter: left front and repair left fro	a parking gara natic charge to and charging s  92089  92089  92915 nd left rear tire	est system  Labor:  Labor:	Battery Shop Supplied 120.00  In D  Parts List Shop Supplied 60.00  In D  at.  Parts List	Parts:  Date:  Parts:  Date:  Gdy Sil	2.00	Closed:	10/17/20	1.00 1.00 1.00 017 Qty 1.00
- Battery faile replace bad be service call at a service at a serv	Had to jump ed load test Per pattery. Recher t vista parking ies Hou : 1709922 Left rear tire ear tire and basies Hou : 1711027 Tire light on , erear tire and res.reset Tpms	rform automock starting a garage.  Irs 2.00  Meter: going flat. Ilance .nitro Irs 1.00  Meter: left front and repair left fro	a parking gara natic charge to and charging s  92089  92089  92915 nd left rear tire	est system  Labor:  Labor:	Battery Shop Supplied 120.00  In D  Parts List Shop Supplied 60.00  In D  at.  Parts List Lt265/70r17 (	Parts:  Date:  Parts:  Oate:  Gdy Siles	2.00	Closed:	10/17/20	1.00 1.00 1.00 1.00 1.00 1.00

Workorder:	1800922	Meter:	95040			In Date:	01/25/2018	Closed:	02/05/2018
Problem:	P.M. servi	ce and right st	robe inop,rig	ght brake li	ght inop,t	topper door	won't stay shu	ut.	
- P.m.service					Parts Li	ist			Qty
		emove lamp a		ew bulb.	5w20 Er	ngine Oil			7.00
Right side stro	be beacon	inop .r&r with	new.		Napago	ld Oil Filter			1.00
- Two new tire	es on front	high speed ba	alance and n	itrogen fill	Napago	ld Air Filter			1.00
	ar braka nad	ds and service	calinare and	l rocurfoco	22" Wip	er Blade			2.00
rear rotors .te			calipers and	resuriace	Used Fi	re X Refurbi	ished		1.00
- Camper doo	or open bys	elf .fabericate	and install m	netal	Bulb				1.00
shims to keep					Strobe L	_p Led			1.00
- Inspect and	service wir	nch.			Lt265/70	Or17 Gdy Si	lent Armor		2.00
- Complete fr	ont end alig	ınment.			Brake P	ad			1.00
- Shop Suppl	ies				Shop Su	upplies			1.00
					Tire Dis	posal Fee			2.00
	F .	Hours 15.05		Labor:	903.00	Parts:	850.40	Total:	1,753.40
Workorder: Problem:	1802958 Replace to	Meter: ail light	95250			In Date:	03/20/2018	Closed:	03/23/2018
- Replace rigl	ht tail marke	er light bulb ai	nd socket.		Parts Li	ist			Qty
					Boxed N	/liniatures			1.00
					Stp Trn	TI Lgt Sock	et		1.00
	F	lours 0.50		Labor:	30.00	Parts:	7.32	Total:	37.32
Workorder: Problem:	1807226 P.M. servi	Meter:	99712			In Date:	07/17/2018	Closed:	07/24/2018
- P.m. service	Э.				Parts Li	ist			Qty
- Inspect and	service wir	nch.			Napago	ld Oil Filter			1.00
- Rotate and	high speed	balance all for	ur tires.		5w20 Er	ngine Oil			7.00
- Shop Suppl	ies				22" Wip	er Blade			2.00
					Used Fi	re X Refurbi	ished		1.00
					Shop Su	upplies			1.00
	F ·	lours 4.75		Labor:	285.00	Parts:	41.02	Total:	326.02
Workorder:	1809347	Meter:	101224			In Date:	09/11/2018	Closed:	09/11/2018
Problem:	Transition	Prep Charge							
- Transition P		ours 2.00		Labor	120.00	Parts:	0.00	Total	120.00
	:	10u15 2.00		Labul.	120.00	rans.	0.00	TOIdl.	120.00