10187832	2012 F	FORD F250	Cab & Cha	ssis, 3/4 1	ron, 4X4, 8	8 Ft Flatbed E	dy-Stee		
1210159 1061 - Pre De					In Date:	10/23/2012	Closed:	10/23/2012	
/ Inspection									
Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
1210526 Install battery			rear of truck		In Date:	10/31/2012	Closed:	11/26/2012	
		install wiring	and quick	Parts Lis	st			ເ	
-	nicle.			Ucb-8 Ci	r Brkr			1.	
ies				Pwr Conv	v			1.	
				Cs00rv B	Battery Cab	ble		25.	
				Cs00l Ba	ttery Cable	e 2		10.	
				Batt Cab	le Connec	tor		1.	
				Protectiv	e Caps			1.	
					82-2178 Circuit Break				
					able Lug			8.	
				60 40 Ro		1.			
				06133 3r		1.			
				Fuse Hol		1.			
				60 40 Ro	s Cor SI 1	4		1.	
				Floor Ma	t-2pc Rub	Bk		1.	
					•			1.	
Hour	s 5.00		Labor:			547.22	Total:	847.22	
1300862 Need quick di					In Date:	01/24/2013	Closed:	02/21/2013	
nd make up cab	oles and o	quick discon	nect plug	Parts Lis	st			ເ	
pment auxiliary	battery.i								
	∍m.			Plua	1.				
ies				-	6.				
						6.			
					s Core Slo	11		1.	
				Electrical	Tape			2.	
				Electrical Shop Su	•			2. 1.	
	1210159 1061 - Pre De / Inspection Hour : 1210526 Install battery ry isolator.fabric g at rear of ver ies Hour : 1300862 Need quick dis ment auxiliary t charging syste	1210159 Meter: 1061 - Pre Delivery Ins / Inspection Hours 2.00 1210526 Meter: Install battery isolator and ug at rear of vehicle. ies Hours 5.00 1300862 Meter: Need quick disconnect nd make up cables and opment auxiliary battery.it t charging system.	1210159 Meter: 400 1061 - Pre Delivery Inspection / Inspection Hours 2.00 : 1210526 Meter: 414 Install battery isolator and cable to ry isolator.fabricate and install wiring at rear of vehicle. ies Hours 5.00 : 1300862 Meter: 605 Need quick disconnect end. nd make up cables and quick discon pment auxiliary battery.insulate and t charging system.	1210159 Meter: 400 1061 - Pre Delivery Inspection / Inspection Hours 2.00 Labor: : 1210526 Meter: 414 Install battery isolator and cable to rear of truck ry isolator.fabricate and install wiring and quick 1000000000000000000000000000000000000	1210159 Meter: 400 1061 - Pre Delivery Inspection / Inspection Hours 2.00 Labor: 120.00 1210526 Meter: 414 Install battery isolator and cable to rear of truck. ry isolator.fabricate and install wiring and quick ga t rear of vehicle. Parts Lis ucb-8 Ci ug at rear of vehicle. Ucb-8 Ci ies Pwr Com Cs001 Ba Batt Cab Protectiv 82-2178 Battery C 60 40 Rc 06133 3r Fuse Hol 60 40 Rc 060 40 Rc 1300862 Meter: 605 Need quick disconnect end. nd make up cables and quick disconnect plug pment auxiliary battery.insulate and secure tcharging system. ies Parts Lis 84-9632 Plug Cs4rv Re	1210159 Meter: 400 In Date: 1061 - Pre Delivery Inspection Hours 2.00 Labor: 120.00 Parts: 1210526 Meter: 414 In Date: Install battery isolator and cable to rear of truck. Parts List ug at rear of vehicle. Ucb-8 Cir Brkr ies Pwr Conv Cs001 Battery Cable Batt Cable Connect Protective Caps 82-2178 Circuit Bre Battery Cable Lug 60 40 Ros Cor SI 1 06133 3m Electric Fuse Holder 60 40 Ros Cor SI 1 Ioor Mat-2pc Rub Shop Supplies Jool And Ros Cor SI 1 1300862 Meter: 605 In Date: Need quick disconnect end. In Date: nd make up cables and quick disconnect plug pment auxiliary battery.insulate and secure tcharging system. Parts List as 84-9632 Connector Plug	1210159 Meter: 400 In Date: 10/23/2012 1061 - Pre Delivery Inspection Hours 2.00 Labor: 120.00 Parts: 0.00 1210526 Meter: 414 In Date: 10/31/2012 Install battery isolator and cable to rear of truck. In Date: 10/31/2012 Install battery isolator and cable to rear of truck. Parts List ug at rear of vehicle. Ucb-8 Cir Brkr jes Pwr Conv CS00r Battery Cable Cs00l Battery Cable 2 Batt Cable Connector Protective Caps 82-2178 Circuit Break Battery Cable Lug 60 40 Ros Cor Sl 1 4 06133 3m Electric Tap Fuse Holder 60 40 Ros Cor Sl 1 4 1300862 Meter: 605 Hours 5.00 Labor: 300.00 Parts: 547.22 1300862 Meter: 605 In Date: 01/24/2013 Need quick disconnect end. Parts List and make up cables and quick disconnect plug prent auxiliary battery.insulate and secure t charging system. Parts List ies In Date: 01/24/2013	1210159 Meter: 400 In Date: 10/23/2012 Closed: 1061 - Pre Delivery Inspection Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 1210526 Meter: 414 In Date: 10/31/2012 Closed: 120052 Meter: 605 Parts List Battery Cable 2 Battery Cable 2<	

		and install	running board	ds/steps o	n both side	I n Date: es of truck	04/04/2013	Closed:	04/10/20	/10
- Perform pm	service.				Parts Lis	t				Qty
- Fabricate an		steps on bo	th sides of tru	uck asper	Custom B			1.00		
request.					Used Fire	x Refurbe	d F			1.00
- Rotate and b		1372 Oil F	Filter				1.00			
- Fabricate an	ounting	5w20 Eng	jine Oil				7.00			
bracket.	Wd40 Spi	ray Lube S	Stock			1.00				
- Shop Supplie		Step Asy					1.00			
					Shop Sup	plies				1.00
	Hou :	rs 6.25		Labor:	375.00	Parts:	529.67	Total:	904.67	
Workorder: Problem:	1307735 Pm service.	Meter:	5885		I	In Date:	08/02/2013	Closed:	08/13/20)13
- P.m. Service		Parts Lis		Qty						
- Rotate and b		5w20 Eng		7.00						
- Shop Supplie	- Shop Supplies									1.00
					Shop Sup			1.00		
	Hou :	rs 3.75		Labor:	225.00	Parts:	24.73	Total:	249.73	
Workorder: Problem:	1311959 Right rear tire	Meter: a flat and rig	11752 ght front has	a nail in it.		In Date:	12/02/2013	Closed:	12/10/20)13
- Repair right	front tire,repla	ce one tire	and dismoun	nt spare	Parts Lis		Qty			
tire and mount	on vehiclerim	.balance a	II.	•	17963649		1.00			
- Shop Supplie	es				Shop Sup	plies				1.00
					Tire Dispo	osal Fee				1.00
	Hou	rs 2.00		Labor:	120.00	Parts:	249.19	Total:	369.19	
Workorder: Problem:	1312226 Pm service.	Meter:	11774		l	In Date:	12/06/2013	Closed:	12/13/20)13
- Perform pm	service.				Parts Lis	t				Qty
- Rotate and b		r tires.			5w20 Eng		7.00			
- Shop Supplie	es				Napagold					1.00
					Wiper Bla					2.00
					Shop Sup					1.00
							32.38			

 P.m. Service. Rotate and balance all tires. Transport vehicle to dealer for leaking a/c codensor. Shop Supplies Hours 5.75 Hours 5.75 Labor: 345.00 Parts: 49.75 Morkorder: 1405269 Meter: 22164 Problem: P.M. service and pulls to the right. P.m. Service. Test battery and charging system.recharge and retest battery for the system statery for the system statery for the system statery for the system statery for the system.recharge and retest for the system statery for the system statery for the system statery for the system statery for the system.recharge and retest for the system statery for	Total: Closed:	Qty 7.00 1.00 2.00 1.00 1.00 1.00 : 394.75 06/11/2014					
 Transport vehicle to dealer for leaking a/c codensor. Shop Supplies Shop Supplies Hours 5.75 Labor: 345.00 Parts: 49.75 Workorder: 1405269 Meter: 22164 Problem: P.M. service and pulls to the right. P.m. Service. Test battery and charging system.recharge and retest battery, fail load test.replace defective battery. Replace two tires, rotate and balance all four. Replace two tires, rotate and balance all four. Shop Supplies Shop Supplies Tre Disposal Fee Hours 9.25 In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. Shop Supplies Shop Supplies Thours 9.25 In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. P.m. Service. Problem: Pm service and check over for rear battery not staying charged P.m. Service. Shop Supplies Shop Supplies In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. Parts List Sw20 Engine Oil Napagold Oil Filter Sw20 Engine Oil Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Tire Disposal Fee Shop Supplies Tire Disposal Fee Shop Supplies Tire Disposal Fee Shop Supplies <		7.00 1.00 2.00 1.00 1.00 1.00 : 394.75 06/11/2014					
- Shop Supplies Wiper Blade Used Fire X Refurbished Washer FI Shop Supplies Hours 5.75 Labor: 345.00 Parts: 49.75 Hours 5.75 Labor: 345.00 Parts: 49.75 In Date: 05/30/2014 Problem: P.M. service and pulls to the right. - P.m. Service. - Test battery and charging system.recharge and retest battery, fail load test.replace defective battery. - Replace two tires,rotate and balance all four. - Replace leaking rear shocks. - Complete wheel alignment.test drive. - Shop Supplies - Shop Supplies - Shop Supplies - Hours 9.25 Hours 9.25 - P.m. Service. - P.m. Service. - P.m. Service. - P.m. Service. - P.m. Service. - Replace two tires,rotate and balance all four. - P.m. Service. - P.m. Service. - Shop Supplies - Tire Disposal Fee - Shop Supplies - Tire Disposal Fee		2.00 1.00 1.00 1.00 : 394.75 06/11/2014					
- Shop Supplies Wiper Blade Used Fire X Refurbished Washer FI Shop Supplies Hours 5.75 Labor: 345.00 Parts: 49.75 Workorder: 1405269 Meter: 22164 Problem: P.M. service and pulls to the right. - P.m. Service. - Test battery and charging system.recharge and retest battery, fail load test.replace defective battery. - Replace two tires, rotate and balance all four. - Replace leaking rear shocks. - Complete wheel alignment.test drive. - Shop Supplies - Shop Supplies - Shop Supplies - Hours 9.25 - P.m. Service. - Shop Supplies - P.m. Service. - Shop Supplies - P.m. Service. - Shop Supplies - Shop Supplies - Shop Supplies - P.m. Service. - Shop Supplies - Tire Disposal Fee - Shop		1.00 1.00 1.00 : 394.75 06/11/2014					
Used Fire X Refurbished Washer FI Shop Supplies Hours 5.75 Labor: 345.00 Parts: 49.75 Workorder: 1405269 Meter: 22164 Problem: P.M. service and pulls to the right. - P.m. Service. - Test battery and charging system.recharge and retest battery,fail load test.replace defective battery. - Replace two tires,rotate and balance all four. - Replace leaking rear shocks. - Complete wheel alignment.test drive. - Shop Supplies Hours 9.25 Problem: Pm service and check over for rear battery not staying charged - P.m. Service. - Replace two tires,rotate and balance all four. - Replace two tires,rotate and check over for rear battery not staying charged - P.m. Service. - Replace two tires,rotate and balance all four. - Replace two tires,rotate and balance all four. - Replace two tires, rotate and balance all four. - Replace two tires, rotate and balance all four. - Check battery isolator per request.reset circuit breaker and check charging system. - Shop Supplies - Tire Disposal Fee - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supp		1.00 1.00 : 394.75 06/11/2014					
Hours 5.75 Hours 5.75 Hours 5.75 Hours 5.75 Hours 5.75 Hours 5.75 Hours 2.164 Problem: P.M. service and pulls to the right. P.m. Service. Parts List Parts List Sw20 Engine Oil Napagold Oil Filter Napagold Air Filter Napagold Air Filter Napagold Air Filter Replace leaking rear shocks. Complete wheel alignment.test drive. Shop Supplies Hours 9.25 Hours 9.25 Parts List Morkorder: 1409885 Meter: 29528 Hours 9.25 Parts List Morkorder: 1409885 Meter: 29528 Neter: 29528 Hours 9.25 Shop Supplies Tire Disposal Fee Napagold Oil Filter Napagold Oil Filter Napagold Air		1.00 : 394.75 06/11/2014					
Hours 5.75Labor:345.00Parts:49.75Workorder:1405269Meter:22164In Date:05/30/2014Problem:P.M. service and pulls to the rightParts List5w20 Engine Oil- Test battery and charging system.recharge and retest battery,fail load test.replace defective batteryParts List5w20 Engine Oil- Replace two tires,rotate and balance all fourNapagold Oil FilterNapagold Air Filter- Replace leaking rear shocksMac Wite Lithium GresBattery 65- Shop Supplies179636492 Lt245-75r17Shock AbsoShop Supplies- Hours 9.25Labor:555.00Parts:745.38Workorder:1409885Meter:29528In Date:10/01/2014Problem:Pm service and check over for rear battery not staying charged-Parts List- P.m. ServiceSw20 Engine OilNapagold Oil Filter- Replace two tires,rotate and balance all fourSw20 Engine Oil Check battery isolator per request.reset circuit breaker and check charging systemSw20 Engine OilNapagold Oil Filter- Shop SuppliesSw20 Engine Oil Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Sup		: 394.75 06/11/2014					
Hours 5.75Labor:345.00Parts:49.75Workorder:1405269Meter:22164In Date:05/30/2014Problem:P.M. service and pulls to the rightParts List5w20 Engine Oil- Test battery and charging system.recharge and retest battery,fail load test.replace defective batteryParts List5w20 Engine Oil- Replace two tires,rotate and balance all fourNapagold Oil FilterNapagold Air Filter- Replace leaking rear shocksMac Wite Lithium GresBattery 65- Shop Supplies179636492 Lt245-75r17Shock AbsoShop Supplies- Hours 9.25Labor:555.00Parts:745.38Workorder:1409885Meter:29528In Date:10/01/2014Problem:Pm service and check over for rear battery not staying charged-Parts List- P.m. ServiceSw20 Engine OilNapagold Oil Filter- Replace two tires,rotate and balance all fourSw20 Engine Oil Check battery isolator per request.reset circuit breaker and check charging systemSw20 Engine OilNapagold Oil Filter- Shop SuppliesSw20 Engine Oil Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Sup		06/11/2014					
Problem: P.M. service and pulls to the right. - P.m. Service. - - Test battery and charging system.recharge and retest battery,fail load test.replace defective battery. - - Replace two tires,rotate and balance all four. - - Replace leaking rear shocks. - - Complete wheel alignment.test drive. - - Shop Supplies - Hours 9.25 Labor: - Workorder: 1409885 Meter: 29528 In Date: 10/01/2014 Problem: Pms Evrice and balance all four. - Check battery isolator per request.reset circuit breaker and check charging system. - - Shop Supplies - - Shop Supplies - - P.m. Service. - - Replace two tires,rotate and balance all four. - - Shop Supplies	Closed:						
 Test battery and charging system.recharge and retest battery, fail load test.replace defective battery. Replace two tires, rotate and balance all four. Replace leaking rear shocks. Complete wheel alignment.test drive. Shop Supplies Hours 9.25 Hours 9.25 Morkorder: 1409885 Replace two tires, rotate and balance all four. Replace two tires, rotate and balance all four. P.m. Service. Replace two tires, rotate and balance all four. Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Test battery and charging system. Shop Supplies 		e /					
battery,fail load test.replace defective battery. - Replace two tires,rotate and balance all four. - Replace leaking rear shocks. - Complete wheel alignment.test drive. - Shop Supplies - Shop Supplies - Mac Wite Lithium Gres - Shop Supplies - T79636492 Lt245-75r17 Shock Abso Shop Supplies - Hours 9.25 - Hours 9.25 - Workorder: 1409885 - Problem: Pm service and check over for rear battery not staying charged - P.m. Service. - Replace two tires,rotate and balance all four. - Check battery isolator per request.reset circuit breaker and check charging system. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Tire Disposal Fee - Mours 9.25 - Labor: 555.00 - Parts List - Replace two tires,rotate and balance all four. - Check battery isolator per request.reset circuit breaker and check charging system. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Tire Disposal Fee - Shop Supplies - Shop Supplies		Qty					
 Replace two tires, rotate and balance all four. Replace leaking rear shocks. Complete wheel alignment.test drive. Shop Supplies Shop Supplies Hours 9.25 Hours 9.25 Labor: Stop Service. Problem: Pm service and check over for rear battery not staying charged P.m. Service. Replace two tires, rotate and balance all four. Shop Supplies Mac Wite Lithium Gress Battery 65 Shop Supplies Tire Disposal Fee In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. Replace two tires, rotate and balance all four. Sw20 Engine Oil Shop Supplies Shop Supplies Washer Fluid Concentr Ti79636492 Lt245-75r17 Shop Supplies Tire Disposal Fee 		5.00					
 Replace leaking rear shocks. Complete wheel alignment test drive. Shop Supplies Shop Supplies Hours 9.25 Hours 9.25 Labor: Stop Supplies: Hours 9.25 In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. Replace two tires, rotate and balance all four. Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Shop Supplies Tire Disposal Fee Value: Value:		1.00					
 Complete wheel alignment.test drive. Shop Supplies Shop Supplies Hours 9.25 Hours 9.25 Labor: 555.00 Parts: 745.38 Workorder: 1409885 Meter: 29528 In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged P.m. Service. Replace two tires, rotate and balance all four. Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Wite Utilitatin Ores Battery 65 179636492 Lt245-75r17 Shock Abso Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee 							
- Shop Supplies 179636492 Lt245-75r17 Shock Abso Shop Supplies Tire Disposal Fee Hours 9.25 Hours	Mac Wite Lithium Gres						
Hours 9.25 Labor: 555.00 Parts: 745.38 Image: Structure Hours 9.25 Labor: 555.00 Parts: 745.38 Image: Structure Hours 9.25 Labor: 555.00 Parts: 745.38 Image: Structure Image: Structure 10/01/2014 Problem: Pm service and check over for rear battery not staying charged Parts List - P.m. Service. Parts List - Replace two tires, rotate and balance all four. 5w20 Engine Oil - Check battery isolator per request.reset circuit breaker and check charging system. Napagold Oil Filter - Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee Tire Disposal Fee		1.00					
Shop Supplies Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 745.38 Workorder: 1409885 Meter: 29528 In Date: 10/01/2014 Problem: Pm service and check over for rear battery not staying charged - P.m. Service. - Replace two tires,rotate and balance all four. - Check battery isolator per request.reset circuit breaker and check charging system. - Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee		2.00					
Tire Disposal FeeHours 9.25Labor:555.00Parts:745.38Workorder:1409885Meter:29528In Date:10/01/2014Problem:Pm service and check over for rear battery not staying charged- P.m. Service.Parts List- Replace two tires,rotate and balance all four.5w20 Engine Oil- Check battery isolator per request.reset circuit breaker and check charging system.Napagold Oil Filter- Shop SuppliesWasher Fluid Concentr179636492 Lt245-75r17Shop SuppliesTire Disposal Fee		2.00					
Hours 9.25Labor:555.00Parts:745.38Workorder:1409885Meter:29528In Date:10/01/2014Problem:Pm service and check over for rear battery not staying charged- P.m. Service.Parts List- Replace two tires, rotate and balance all four.5w20 Engine Oil- Check battery isolator per request.reset circuit breaker and check charging system.Napagold Oil Filter Wiper Blade- Shop SuppliesWasher Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee		1.00					
Hours 9.25Labor:555.00Parts:745.38Workorder:1409885Meter:29528In Date:10/01/2014Problem:Pm service and check over for rear battery not staying charged- P.m. Service.Parts List- Replace two tires, rotate and balance all four.5w20 Engine Oil- Check battery isolator per request.reset circuit breaker and check charging system.Napagold Oil Filter Wiper Blade- Shop SuppliesWasher Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee		2.00					
Problem:Pm service and check over for rear battery not staying charged- P.m. Service.Parts List- Replace two tires, rotate and balance all four.5w20 Engine Oil- Check battery isolator per request. reset circuit breaker and check charging system.Napagold Oil Filter- Shop SuppliesWiper Blade- Shop SuppliesVasher Fluid Concentr179636492 Lt245-75r17Shop Supplies- Tire Disposal FeeStep Supplies	Total:	: 1,300.38					
 Replace two tires,rotate and balance all four. Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee 	Closed:	10/27/2014					
 Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee 		Qty					
 Check battery isolator per request.reset circuit breaker and check charging system. Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee 							
- Shop Supplies Washer Fluid Concentr 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee							
179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee		2.00					
Shop Supplies Tire Disposal Fee	•						
Shop Supplies Tire Disposal Fee		2.00					
Tire Disposal Fee		1.00					
		2.00					
	Total:	: 872.54					
Workorder: 1500506 Meter: 33443 In Date: 01/14/2015 Problem: Left front tire flat.		01/15/2015					
- Repair and balance left front tire. Parts List	Closed:	Qty					
- Shop Supplies Shop Supplies	Closed:	1.00					
Hours 1.00 Labor: 60.00 Parts: 2.00	Closed:	: 62.00					

	02024 Mete M. service and left		lat.	In	Date:	02/25/2015	Closed:	03/18/20	015
- Pm service.				Parts List					Qty
- Perform transm	ission fluid flush.			Rear Pads		1.00			
	ake pads and resu			5w20 Engine	ə Oil				7.00
	pers.flush and ble	•	drive.	Napagold Oi			1.00		
•	tire.rotate and bala	ance all four.		Napagold Ai	r Filter				1.00
- Shop Supplies	Washer Flui	d Conce	entr			1.00			
				Used Fire X	Refurb	shed			1.00
				Floor Mat-2p	oc Rub	Bk			1.00
				Syn-atf Tran	s Fluid	S			18.00
				1401 Brake	Fluid B	ra			2.00
				Brake Clean	er				1.00
				Shop Suppli	es				1.00
	Hours 10.2	5	Labor:	615.00	Parts:	257.11	Total:	872.11	
	04489 Mete ft front tire flat.Bat		off.	In	Date:	05/01/2015	Closed:	05/07/20	015
- Repair and bal	ance left front tire.			Parts List					Qty
	d charging system		adtest	Group 65 Ba	attery M	tc			1.00
after recharge.rep - Shop Supplies	lace defective bat	tery.		Shop Suppli		1.00			
	Hours 2.00 :		Labor:	120.00	Parts:	145.61	Total:	265.61	
	05497 Metern service.Check ch			In I	Date:	06/02/2015	Closed:	06/24/20	015
- Pm service.				Parts List					
- Ronlace front h							Qty		
- INEPIACE HUILD	rake pads and res	rs.service	Battery 65					Qty 1.00	
calipers and test	rake pads and res drive.	urface front roto	rs.service	Battery 65 Battery 65					-
calipers and test of - Repair left front					e Oil				1.00
calipers and test of - Repair left front four.	drive. and right rear tires	s.rotate and bala	ance all	Battery 65					1.00 1.00
calipers and test of - Repair left front four. - Check and char	drive. and right rear tires ge battery.test for	s.rotate and bala	ance all	Battery 65 5w20 Engine	il Filter				1.00 1.00 7.00
 calipers and test of Repair left front four. Check and char test .replace defended 	drive. and right rear tires ge battery.test for	s.rotate and bala	ance all	Battery 65 5w20 Engine Napagold Oi	il Filter	entr			1.00 1.00 7.00 1.00
calipers and test of - Repair left front four. - Check and char	drive. and right rear tires ge battery.test for	s.rotate and bala	ance all	Battery 65 5w20 Engine Napagold Oi Wiper Blade	il Filter	entr			1.00 1.00 7.00 1.00 2.00
 calipers and test of Repair left front four. Check and char test .replace defended 	drive. and right rear tires ge battery.test for	s.rotate and bala	ance all	Battery 65 5w20 Engine Napagold O Wiper Blade Washer Flui	il Filter	entr			1.00 1.00 7.00 1.00 2.00 1.00
calipers and test of - Repair left front four. - Check and char test .replace defe	drive. and right rear tires ge battery.test for	s.rotate and bala	ance all	Battery 65 5w20 Engine Napagold Oi Wiper Blade Washer Fluie Brake Pads	il Filter d Conce	entr			1.00 1.00 7.00 1.00 2.00 1.00 1.00

Workorder: Problem:	1509975 Pm service.	Meter:	48948			n Date:	10/01/2015	Closed:	10/20/20	015
- Pm service.					Parts List	t				Qty
- Replace two	o tires.rotate ar	nd balance	all four.		5w20 Eng	ine Oil				8.00
	eel alignment.				Napagold					1.00
- Shop Suppl	•				Wiper Bla					2.00
					Wd40 16c					1.00
					Shop Sup	plies				1.00
					Lt245/75r	17 Tire				2.00
	Hou :	ırs 7.25		Labor:	435.00	Parts:	343.97	Total:	778.97	
Workorder: Problem:	1601759 Pm service.	Meter:	56140		I	n Date:	02/19/2016	Closed:	03/02/20	016
- Pm service.					Parts List	t				Qty
- Perform engine coolant flush and refill.					5w20 Engine Oil					
- Replace two tires.rotate and balance all four.					Napagold Oil Filter					1.00
- Shop Suppl	ies				Used Fire	X Refurb	ished			1.00
					Silicone S	pray 10oz	2			1.00
					22" Wiper	Blade				2.00
					Rubber Fl	ар				1.00
					Napagold	Air Filter				1.00
					Peak Glob					2.00
					Shop Sup					1.00
					Lt245/75r					2.00
	Hou :	ırs 6.75		Labor:	405.00	Parts:	461.96	Total:	866.96	
Workorder: Problem:	1607838 bolt and scre	Meter: w in tire	60372		I	n Date:	07/26/2016	Closed:	08/01/20	016
- Tire Service	mosquito con Hou	itrol - bolt a irs 0.00	nd screw in t	tire Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:		Meter:	61629			n Date:	08/09/2016	Closed:	08/23/20	016
Problem:	P.M. service	and towed	in for battery	/ not charg	ing.					
- P.m. Service	э.				Parts List	t				Qty
	and charging	system.rep	lace bad ba	ttery	5w20 Engine Oil					8.00
isolator.	holonoc ell tim				Napagold Oil Filter					1.00
	balance all tire	5.			20" Wiper			2.00		
- Shop Suppl	62				Used Fire		ished			1.00
					Pwr Conv					1.00
					Stg Whee	l Cov - Fo	ord			1.00
		ırs 4.75			Shop Sup 285.00		147.35			1.00

Workorder: Problem:	1608249 No start	Meter:	61120			In Date:	08/09/2016	Closed:	08/10/20	016
- Tow From: 5	5640 Coach H	ouses Circl	e Unit C,I	Boca Raton						
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1610092 Right rear tir	Meter: e going flat.	64397			In Date:	09/27/2016	Closed:	09/28/20	016
- Replace lea	king right rear	valve stem	.reprogran	n sensor.	Parts L	ist				Qty
- Shop Suppli	es				Tpms12	2 Sensor Tire	e Pr			1.00
					Shop S	upplies				1.00
	Hou :	ırs 1.00		Labor:	60.00	Parts:	83.71	Total:	143.71	
Workorder:	1611564	Meter:	66917			In Date:	11/09/2016	Closed:	11/29/20)16
Problem:	P.M. service	and right fr	ont tire goo	oing flat.						
- P.m. Service	Э.				Parts L	ist				Qty
- Replace and balance four new tires.						ngine Oil				7.00
- Resurface rear brake rotors, replace pads and calipers. flush						old Oil Filter				1.00
and bleed system.						old Air Filter				1.00
- Inspect and					Pedal F	ad				1.00
- Complete w		t.test drive.			Lt245 7	5r17 At Tire				4.00
- Shop Suppli	es				Caliper	w/ Hardware	e - Right Rear	(eclips		1.00
					Caliper	w/ Hardware	e - Left Rear (eclipse		1.00
					Brk Flui	d Dot 4-12o	Z			2.00
					Non-ch	lor Brake Clr	٦r			1.00
					Ford Tr	ansfer Case	Fluid			2.00
					Brake F	Pad				1.00
					Shop S	upplies				1.00
					Tire Dis	posal Fee				4.00
	Hou :	ırs 12.25		Labor:	735.00	Parts:	1,264.11	Total:	1,999.11	1
Workorder: Problem:	1611915 Rear Noises	Meter: from wheel	66917			In Date:	11/17/2016	Closed:	11/17/20	016
- Tow From: N	Aosquito Cont	trol To: Lv s	shop							
	•	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1612916 Damage to r	Meter: ear bumper	66917 step & hite	ch may be		In Date:	11/21/2016	Closed:	12/16/20	016
- Damage to r	ear bumper s	tep & hitch	may be							
20	•	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: 17 Problem: P.N		ter: 71927		In	Date:	03/20/2017	Closed:	03/31/20)17
- P.m. Service.				Parts List					Qty
- R&r left door pa	nel and replace	broken check str	rap.	5w20 Engir	ne Oil				7.00
- Inspect and ser	•		-1	Napagold C					1.00
- Inspect and serv				22" Wiper E					2.00
- Rotate and bala	nce tires.			Bulb					1.00
- Shop Supplies				Check Asy					1.00
				1qt Syngea	r Oil 75-	90			3.00
				75w140 Fo	rd Axle L	_ube			3.00
				Ptex Ultra (Grey 3oz	<u>.</u>			1.00
				Non-chlor E	Brake Cli	nr			1.00
				left door ch	eck asy				1.00
				Shop Supp	lies				1.00
	Hours 6.7	5	Labor:	405.00	Parts:	271.63	Total:	676.63	
		ter: 71959 bed, 7" from bulk	whead & cer		Date:	05/23/2017	Closed:	05/31/20	017
- Secure sprayer				Parts List					Qty
- Shop Supplies			у	Battery					1.00
									1.00
				-	lies				1.00
	Hours 4.0	0	Labor:	Shop Supp 240.00		62.11	Total:	302.11	1.00
Workorder: 17	:	0 ter: 73742	Labor:	Shop Supp 240.00		62.11 08/07/2017	Total: Closed:	302.11 08/14/20	
Workorder: 17	: 07697 Me d to jump start.	ter: 73742		Shop Supp 240.00	Parts:	-)17
Workorder: 17 Problem: Ha	: 07697 Me d to jump start. fully.test battery	ter: 73742 and charging sys		Shop Supp 240.00	Parts:	-			017 Qty
Workorder: 17 Problem: Ha - Charge battery	: 07697 Me d to jump start. fully.test battery	ter: 73742 and charging sys		Shop Supp 240.00 In Parts List	Parts:	-			017 Qty 1.00
Workorder: 17 Problem: Ha - Charge battery production of the sector of t	: 07697 Me d to jump start. fully.test battery	ter: 73742 and charging sys t .002amps.ok.	stem.r&r	Shop Supp 240.00 In Parts List Battery	Parts: Date:	-	Closed:		1.00 017 Qty 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me	ter: 73742 and charging sys t .002amps.ok.	stem.r&r Labor:	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00	Parts: Date:	08/07/2017	Closed:	08/14/20	017 Qty 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402	stem.r&r Labor:	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00	Parts: Date: lies Parts:	08/07/2017 130.64	Closed: Total:	08/14/20	017 Qty 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17 Problem: P.f - P.m. service. - Check performa	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00	Parts: Date: lies Parts: Date:	08/07/2017 130.64	Closed: Total:	08/14/20	017 Qty 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17 Problem: P.f - P.m. service. - Check performa system.pinpoint te	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl ince of A/c syste	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List	Parts: Date: lies Parts: Date:	08/07/2017 130.64	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty
 Workorder: 17 Problem: Hat Charge battery for defective battery.p Shop Supplies Workorder: 17 Problem: P.N P.m. service. Check performation system.pinpoint tee max speed.replace 	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl nce of A/c syste est eletronic cool e faulty eletronic	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List 5w20 Engir	Parts: Date: lies Parts: Date: Date:	08/07/2017 130.64 10/16/2017	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty 7.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17 Problem: P.1 - P.m. service. - Check performa system.pinpoint te max speed.replac - Rotate and bala	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl nce of A/c syste est eletronic cool e faulty eletronic	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List 5w20 Engir Napagold O	Parts: Date: lies Parts: Date: Date: ne Oil Dil Filter (Refurb	08/07/2017 130.64 10/16/2017 ished	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty 7.00 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery.p - Shop Supplies Workorder: 17 Problem: P.f - P.m. service. - Check performa system.pinpoint te max speed.replac	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl nce of A/c syste est eletronic cool e faulty eletronic	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List 5w20 Engir Napagold O Used Fire 2	Parts: Date: lies Parts: Date: Date: Date: Call Filter Call Filter Call Conce	08/07/2017 130.64 10/16/2017 ished	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty 7.00 1.00 1.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17 Problem: P.1 - P.m. service. - Check performa system.pinpoint te max speed.replac - Rotate and bala	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl nce of A/c syste est eletronic cool e faulty eletronic	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List 5w20 Engir Napagold C Used Fire > Washer Flu	Parts: Date: lies Parts: Date: Date: Date: Call Filter Call Filter Call Conce	08/07/2017 130.64 10/16/2017 ished	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty 7.00 1.00
Workorder: 17 Problem: Ha - Charge battery f defective battery f - Shop Supplies Workorder: 17 Problem: P.1 - P.m. service. - Check performa system.pinpoint te max speed.replac - Rotate and bala	: 07697 Me d to jump start. fully.test battery berform draw tes Hours 1.0 : 10124 Me M. service and cl nce of A/c syste est eletronic cool e faulty eletronic	ter: 73742 and charging sys t .002amps.ok. 0 ter: 74402 neck A/C warm a m and cooling ing fan clutch no	stem.r&r Labor: at times.	Shop Supp 240.00 In Parts List Battery Shop Supp 60.00 In Parts List 5w20 Engir Napagold C Used Fire 2 Washer Flu 22" Wiper E	Parts: Date: lies Parts: Date: Date: Date: Call Filter Call Filter Call Conce Blade	08/07/2017 130.64 10/16/2017 ished	Closed: Total:	08/14/20	017 Qty 1.00 1.00 017 Qty 7.00 1.00 1.00 1.00 2.00

Workorder: Problem:	1711322 Towed in for I	Meter: rear brakes	75646 locking up.			In Date:	11/16/2017	Closed:	11/21/201	7
- Diagnoise re	ar brakes lock	ing up.resi	urface rear ro	tors	Parts L	ist				Qty
.replace calipe					Brake P	ad				00.1
drive.					Caliper				1	00.1
- Shop Suppli	es				Caliper				1	00.1
					B Fluid	Dot 3-32oz			1	00.1
					Non-chl	or Brake Clr	٦r		1	00.1
					Caliper	Washer			4	1.00
						c Brake Lub	е		1	00.1
					Shop S	upplies			1	00.1
	Hour	rs 4.00		Labor:	240.00	••	442.37	Total:	682.37	
Workorder: Problem:	1711372 Rear Brake Ic	Meter:	75546			In Date:	11/16/2017	Closed:	11/17/201	7
- Tow From: F plaz	ga and Militar	y Trail in th	e publix shop	ping						
	Houi :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1804185 P.M. service.	Meter:	79044			In Date:	04/23/2018	Closed:	04/27/201	8
- P.m. service					Parts L	ist			(Qty
- Balance and	rotate all four	tires. Nitro	fill.		Napago	1	00.1			
- Shop Suppli	es				5w20 E	ngine Oil				7.00
						er Blade				2.00
						old Air Filter				00.1
					Shop S					00.1
	Houi :	rs 3.75		Labor:	225.00	Parts:	36.49	Total:	261.49	
Workorder: Problem:	1804510 No sound fror	Meter: m AM/ FM	79070 radio.			In Date:	05/01/2018	Closed:	05/03/201	8
- Diagnoise no	o sound from r	adio .r&r d	efective radio		Parts L	ist			(Qty
.program and	retest.				Radio		1	00.1		
- Shop Suppli	es				Shop Supplies				1	00.1
	Hour	rs 1.00		Labor:	60.00	Parts:	168.98	Total:	228.98	
Workorder: Problem:	1805431 Right rear tire	Meter: going flat.	80403			In Date:	05/29/2018	Closed:	05/29/201	8
	rear tire and b	alance .niti	ogen fill tires	and	Parts L	ist			(Qty
reset Tpms. - Shop Suppli	es				Shop S	upplies			1	00.1
		rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1809630 Remove spr	Meter: ay unit	83235			In Date:	09/18/2018	Closed:	10/24/2018
- remove spray rig for transfer					Parts L		Qty		
- Shop Supplies					Shop Su	upplies			1.00
	Ho :	urs 5.00		Labor:	335.00	Parts:	3.00	Total:	338.00
Workorder: Problem:	1811261 Transition P	Meter: rep Charge	83235			In Date:	10/31/2018	Closed:	10/31/2018
- Transition P	rep Charge								
	Ho :	urs 2.00		Labor:	134.00	Parts:	0.00	Total:	134.00