Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 436115	Problem:	WASH VEHICLE
-------------------	----------	--------------

Meter Reading: 0LaborPartsIn Date: 02/26/2004Close Date: 02/26/2004HoursDescriptionQuantity

- Wash Vehicle 5.00

- Pre-Delivery Inspection

- Make Duplicate Keys For New Vehicle

Parts Charge: 0.00 Labor Charge: 250.00

Workorder: 439343 Problem: PINTLE LOCK

Meter Reading: 225 Labor Parts

 In Date: 03/26/2004
 Close Date: 03/30/2004
 Hours
 Description
 Quantity

 - Install Hitch Lock
 0.30
 2571 RECEIVER LOCK 5/8"
 1.00

Parts Charge: 14.09 Labor Charge: 15.00

Workorder: 453957 Problem: P.M.

Meter Reading: 3424 Labor Parts

 In Date: 08/13/2004
 Close Date: 08/20/2004
 Hours
 Description
 Quantity

 - Pm Service
 2.00
 31-22 WIPER BLADES 22" WIPER BLADE
 2.00

 10W30 MOTOR OIL
 5.00

 PH3387A OIL FILTER LBF PH47 WIX 51040
 1.00

Parts Charge: 25.11 Labor Charge: 100.00

Workorder: 455473 Problem: 001 WASH TICKET ISSUED OUT 08/26/04

Meter Reading: 0 Labor Parts

In Date: 08/26/2004 Close Date: 08/27/2004 Hours Description Quantity

001 Wash Ticket Issued Out 08/26/04

Replaced L Side Mirror Assembly

Parts Charge: 0.00 Labor Charge: 0.00 Commercial Charge: 7.14

1.00

Workorder: 457332 Problem: DRIVERS SIDE MIRROR CRACKED

Meter Reading: 5506 Labor Parts

In Date: 09/22/2004 Close Date: 09/29/2004 Hours Description Quantity

L/H MIRROR 15106007

Parts Charge: 100.81 Labor Charge: 50.00

1.00

06/07/05

Parts Charge:

0.00

Labor Charge:

001 Detail Vehicle

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Problem: CHECK ENGINE LIGHT ON Workorder: 464496 Meter Reading: 7511 Labor **Parts** In Date: 12/14/2004 Close Date: 12/15/2004 Hours Description Quantity Computer Sys Analysis.(Pass)Test Drive To Verify 1.00 Complaint. Found No Problem At This Time. 0.00 50.00 Parts Charge: Labor Charge: Problem: P.M. Workorder: 464516 Meter Reading: 7511 Labor **Parts** In Date: 12/14/2004 Hours Quantity Close Date: 12/20/2004 Description Pm Service 3.50 10W30 MOTOR OIL 5.00 Replace Lr Tire PH3387A OIL FILTER LBF PH47 WIX 51040 1.00 Test Drive 31-22 WIPER BLADES 22" WIPER BLADE 2.00 773430430 235/75R16 WRANGLER ST SL 1.00 3481 FUEL FILTER FRM G3727 WIX 33481 1.00 AF1519 AIR FILTER USE LAF1520 FRM CA8755A 1.00 116.08 175.00 Parts Charge: Labor Charge: DUPLICATE KEY(LOST) Workorder: 537945 Problem: Meter Reading: 8369 Labor **Parts** In Date: 03/03/2005 Close Date: 03/07/2005 **Hours** Description Quantity Make Key 0.30 0.00 15.00 Parts Charge: Labor Charge: 001 DETAIL VEHICLE 06/07/05 Workorder: 546960 Problem: Meter Reading: 0 Labor **Parts** Close Date: 06/07/2005 In Date: 06/07/2005 Hours Description Quantity

0.00

Commercial Charge:

72.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 548210 Problem: P.M.

Meter Reading: 11031			Labor	Parts	
In Date: 06/21/2005	Close Date: 07	/11/2005	Hours	Description	Quantity
Pm Service			2.50	31-22 WIPER BLADES 22" WIPER BLADE	2.00
Test Run				15319477 FUSE 30 AMP GMC	1.00
				1066 WHITE LITHIUM (CRC 05037)	1.00
				1401 BRAKE FLUID BRAKE FLUID	1.00
				10W30 MOTOR OIL	5.00
				PH3387A OIL FILTER LBF PH47 WIX 51040	1.00
	Parts Charge:	31.75	Labor Charge	e: 125.00	

Workorder: 557945 Problem: POSSIBLE SERVICE LIGHT ON IN TRUCK-TEST DRIVE TOVALIDATE

Meter Reading: 14105 Labor Parts

In Date: 11/10/2005 Close Date: 11/17/2005 Hours Description Quantity

- Tighten Fuel Cap-Engine Light Would Not Come Back On 1.00

- Test Run

Parts Charge: 0.00 Labor Charge: 50.00

Workorder: 559335 Problem: NEEDS R/REAR TIRE

 Meter Reading: 15284
 Labor
 Parts

 In Date: 12/08/2005
 Close Date: 12/09/2005
 Hours
 Description
 Quantity

 - R&R Damaged R/R Tire; Reinstall Spare Tire
 1.00
 773430430 235/75R16 WRANGLER ST SL
 1.00

Parts Charge: 101.84 Labor Charge: 50.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

	A5561. 1015102	29 2004	GIVIC 1300 FICKU	p, 1/2 TOH			
Workorder: 632420	Problem:	P.M.					
Meter Reading: 16464			Labor		Parts		
In Date: 01/06/2006	Close Date: 01/27/2	2006	Hours	Description			Quantity
- Pm Service			5.50	AF1519 AIR FILTER US	SE LAF1520 FRM CA8755A		1.00
 Rear Brake Service 			F	PH3387A OIL FILTER I	_BF PH47 WIX 51040		1.00
 Test Run 			1	0W30 MOTOR OIL			5.00
 Travel To Dealer Warrant 	y (Door Lock)		3	31-22 WIPER BLADES	22" WIPER BLADE		2.00
				PH3387A OIL FILTER I			-1.00
				036 OIL FILTER FRM			1.00
				3481 FUEL FILTER FF			1.00
		50.44		-	ED FIRE EXTINGSHERS		1.00
	Parts Charge:	53.14	Labor Charge:	50.00			
Workorder: 633348	Problem:	NEEDS .	ALIGNMENT				
Meter Reading: 16464			Labor		Parts		
In Date: 01/26/2006	Close Date: 01/27/2	2006	Hours	Description			Quantity
- Complete Alignment,Test	Drive.		2.00	•			-
	Parts Charge:	0.00	Labor Charge:	100.00			
Workorder: 637503	Problem:	001 DET	TAIL VEHICLE	04/14/06			
Meter Reading: 0			Labor		Parts		
In Date: 04/14/2006	Close Date: 05/03/2	2006	Hours	Description			Quantity
- 001 Detail Vehicle	04/14/06			•			-
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	72.00	
W I I 040400		004 DET	-AII	00/05/00			
Workorder: 640433	Problem:	UUIDEI	AIL VEHICLE	06/05/06	Paret.		
Meter Reading: 0	Ol D-4 00/00/	2000	Labor	December (1	Parts		O
In Date: 06/05/2006	Close Date: 06/06/2	2006	Hours	Description			Quantity
- 001 Detail Vehicle	06/05/06						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	72.00	

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

	A55EL 1015	1029 2004	GIVIC 1500 FICKUL	J, 1/2 1 UII			
Workorder: 643117	Probler	n: P.M.					
Meter Reading: 22306			Labor		Parts		
In Date: 07/27/2006	Close Date: 08/1	15/2006	Hours	Description			Quantity
- Pm			4.50 10	036 OIL FILTER FRM	PH3980 WIX 51036		1.00
- Rear Brake Service				1-22 WIPER BLADES			2.00
 Front Tires 			Т	IRE DISPOSAL FEE			2.00
- Test Run			10	0W30 MOTOR OIL			5.00
					WRANGLER ST SL		2.00
					1 CA8755A WIX 46678		1.00
		000.47		/D40 SPRAY LUBE S	TOCK# 405540002		1.00
	Parts Charge:	262.47	Labor Charge:	25.00			
Workorder: 645449	Probler	n : 001 DET	AIL VEHICLE	09/12/06			
Meter Reading: 0			Labor		Parts		
In Date: 09/12/2006	Close Date: 09/1	12/2006	Hours	Description			Quantity
- 001 Detail Vehicle	09/12/06						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	84.00	
Workorder: 646312	Probler	n: TIRESO	LES OF BROWARD	INC			
Meter Reading: 0	i iobiei	II. TINEGO	Labor		Parts		
In Date: 09/26/2006	Close Date: 09/2	28/2006	Hours	Description	i uits		Quantity
- Tiresoles Of Broward Inc	Ologe Bate: 00/2	-0/2000	Hours	Description			Quantity
riiosolos el Browald ille	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	54.00	
		DEINGT	ALL CDADE LINDED	VELIIOLE			
Workorder: 646708	Probler	n: KEINSI	ALL SPARE UNDER	VEHICLE	D a vita		
Meter Reading: 24127	Ol D-4 40/4	14/0000	Labor	D	Parts		0
In Date: 10/04/2006	Close Date: 10/1		Hours	Description			Quantity
- Install New Tire For Flat-F	•	re		IRE DISPOSAL FEE			1.00
Wheel-L/R Wheel, Install	•		7	73430430 235/75R16	WRANGLER ST SL		1.00
Wheel-Install Old Tire On	Spare Wheel						
- Nitro Tires							
- Road Test	-	400.45		07.50			
	Parts Charge:	109.15	Labor Charge:	27.50			

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Problem: 001 WASH TICKET ISSUED OUT 11/09/06 Workorder: 648657

in Date: 17/09/2000 Close Date: 17/14/2000 nours Description Quantity	In Date: 11/09/2006	Close Date: 11/14/2006	Hours	Description	Quantity
---	---------------------	------------------------	-------	-------------	----------

Labor

001 Wash Ticket Issued Out 11/09/06

Meter Reading: 0

0.00 0.00 7.14 Parts Charge: Labor Charge: **Commercial Charge:**

Workorder: 734599 Problem: P.M.

> Meter Reading: 26432 Labor **Parts**

	In Date: 02/22/2007	Close Date: 02/27/2007	Hours	Description	Quantity
-	- Pm Service		2.50	85/140 GEAR OIL GEAR LUBE	1.00
-	Road Test			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
				31-22 WIPER BLADES 22" WIPER BLADE	2.00
				10W30 MOTOR OIL	5.00
				1036 OIL FILTER FRM PH3980 WIX 51036	1.00

45.99 Parts Charge: Labor Charge: 27.50

001 WASH TICKET ISSUED OUT 04/03/07 Workorder: 736678 Problem:

Meter Reading: 0 Labor **Parts**

In Date: 04/03/2007 Close Date: 04/04/2007 Description Quantity Hours

001 Wash Ticket Issued Out 04/03/07

Commercial Charge: 7.14 0.00 0.00 Parts Charge: Labor Charge:

Parts

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 743586 Problem: P.M SERVICE

Meter Reading: 33287		Labor	Parts	
In Date: 09/05/2007	Close Date: 09/12/2007	Hours	Description	Quantity
- Pm Service		12.50	131-151 THERMOSTAT	1.00
Transmission Service Filte	er Kit & Flush Transmission Sys		911150 REAR SHOCKS	2.00
Service Rear Differential			SHOP SUPPLIES	1.00
Inspect Cooling Sys.Press	sure Test Find Thermostat		911149 FRONT SHOCKS	2.00
Housing Leaking.Replac			10W30 MOTOR OIL	5.00
0 1	Shocks Leaking.Replae Front		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
And Rearshocks	onoono Edding. Ropido i Toni		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
Alignment			31-22 WIPER BLADES 22" WIPER BLADE	2.00
0	- Est Time - Masse Death - On		765-1589 BLACK SILICONE	1.00
• .	es.Frt Tires Worn Badly On		10020 INJECTOR CLEANER DON'T REORDER	1.00
Outside Edges.Rotate Fr	rt To Rear		SYN/ATF TRANS FLUID SYNTHETIC	14.00
Shop Supplies			12345841 GEAR OIL SYNTHETIC 75W-90	3.00
			FT1217 TRANS FILTER ATP B-165 WIX DON'T USE	1.00

Parts Charge: 400.07 Labor Charge: 55.00

Workorder: 832483 Problem: P.M SERVICE

Meter Reading: 39463		Labor	Parts	
In Date: 01/08/2008	Close Date: 01/18/2008	Hours	Description	Quantity
 Pm Service R&R Four Tires And High W/Nitrogen Air And Road Check Battery And Chargi Clunking Noise Is Heard In Shaftand Lubricate Stroke 	Speed Balance,Refill Test. ing Sys. R&R Defective Battery. n The Intermediate Shaft.Remv	6.00	773430430 235/75R16 WRANGLER ST SL 88891787 DRAIN PLUG GMC/CHEVY GROUP 78 BATTERY (ACD 78PS) 10W30 MOTOR OIL SHOP SUPPLIES 31-22 WIPER BLADES 22" WIPER BLADE TIRE DISPOSAL FEE	4.00 1.00 1.00 6.00 1.00 2.00 4.00
Reinstall.Road Test Shop Supplies			10020 INJECTOR CLEANER DON'T REORDER 6678 AIR FILTER FRM CA8755A WIX 46678 1036 OIL FILTER FRM PH3980 WIX 51036	1.00 1.00 1.00

Parts Charge: 595.42 Labor Charge: 60.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 838773 Problem: CHECK ENGINE LIGHT ON.RUNS ROUGH.

	Meter Reading: 43922		Labor	Parts	
	In Date: 05/20/2008	Close Date: 05/22/2008	Hours	Description	Quantity
-	- Scan-Lean Codes.Run Fuel Pressure Test.Drain Fuel		5.70	3481 FUEL FILTER FRM G3727 WIX 33481	1.00
	Tank.Remv Tank.Repl Fu	el Pump Splice In New		FUEL PUMP	1.00
	Connector.Clear Codes.Repl Fuel Filter.Test			SHOP SUPPLIES	1.00
-	Shop Supplies				

Parts Charge: 299.66 Labor Charge: 72.00

Workorder: 841198 Problem: R/R TIRE FLAT

Meter Reading: 45509		Labor		Parts	
In Date: 07/10/2008	Close Date: 07/11/2008	Hours	Description		Quantity
- Repair Flat Tire On R/Rear		2.50	SHOP SUPPLIES		1.00

Ck Eng Light On P0455,Ck & Diag Evaporative Emission Evap Sys,Repair Broken Hose And Clean All Codes.

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 90.00

Workorder: 841303 Problem: P.M SERVICE

Meter Reading: 45622		er Reading: 45622 Labor		Parts	
In Date: 07/14/2008	Close Date: 07	/21/2008	Hours	Description	Quantity
Pm Service			5.00	10W30 MOTOR OIL	5.00
Pressure Test Cooling Sys	stem.Inspect Flush S	ystem And		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
Renewed Coolant.				3481 FUEL FILTER FRM G3727 WIX 33481	1.00
High Speed Balance All 4	Tires. Nitro Fill All 4	Tires.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Shop Supplies				ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
				SHOP SUPPLIES	1.00
				1036 OIL FILTER FRM PH3980 WIX 51036	1.00
	Parts Charge:	83.89	Labor Charge:	60.00	

8

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 932967 Problem: P.M. SERVICE.

Meter Reading: 47171	Meter Reading: 47171		Parts	
In Date: 01/21/2009	Close Date: 01/30/2009	Hours	Description	Quantity
- Pm Service		4.05	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Checked Balt.Replace Dry	/ And Worn Belt.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Ck Vehicle Interior, Repl M	Ck Vehicle Interior, Repl Missing Parking Brake Pedal		PARKING BRAKE PEDAL PAD	1.00
Rubber Pad.	5 0		K060950 SERP BELT	1.00
- Rotate & Hi Speed Baland	ce 4 Tires.Nitrofill Tires.		10W30 MOTOR OIL	5.00
- Shop Supplies			SHOP SUPPLIES	1.00
Shop supplies			3481 FUEL FILTER FRM G3727 WIX 33481	1.00
			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
			1036 OIL FILTER FRM PH3980 WIX 51036	1.00

Parts Charge: 107.11 Labor Charge: 243.00

Workorder: 940251 Problem: L.R. signel lite out

 Meter Reading: 49084
 Labor
 Parts

 In Date: 07/02/2009
 Close Date: 07/13/2009
 Hours
 Description
 Quantity

 - L/R Signal Inop,Replace L/R Bulb
 0.30
 SHOP SUPPLIES
 1.00

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 18.00

Workorder: 940647 Problem: p/m swervice

Meter Reading: 49257	·	Labor	Parts	
In Date: 07/13/2009	Close Date: 07/20/2009	Hours	Description	Quantity
- P/M Service		11.50	SHOP SUPPLIES	1.00
- No Start Jump Start Vehicle	e Charge Battery For Two		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
Hours, Load Test And Che	ck Alt.Ok		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Replaced Missing Dome Li	ght Bulb,Found A Current Draw		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
	d Wiring At Rear Spraying Unit		10W30 MOTOR OIL	2.00
	d Secure Wiring Recheck For		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
Draw Ok			10W30 MOTOR OIL	5.00

- P/M Service On Ap System
- Test Drive Vehicle
- Shop Supplies

Parts Charge: 73.81 Labor Charge: 690.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 944329 Problem: P.M. Service

Meter Reading: 51349		Labor	Parts	
In Date: 10/08/2009	Close Date: 10/16/2009	Hours	Description	Quantity
- P.M. Service		5.00	1036 OIL FILTER FRM PH3980 WIX 51036	1.00
 Aux.Spray Unit P.M. Servi 	ce		10W30 MOTOR OIL	5.00
 Remount Spare Tire & Ball 	lance		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies			1348 OIL FILTER FRM PH3614 WIX 51348	1.00
			10W30 MOTOR OIL	2.00
			AIR FRESHENER	1.00
			SHOP SUPPLIES	1.00
	Danta Charres 59.05	l abar Cha	300.00	

Parts Charge: 58.95 Labor Charge: 300.00

Workorder: 944821 Problem: DIC reads in german.

Meter Reading: 51414 Labor Parts

In Date: 10/20/2009 Close Date: 10/21/2009 Hours Description Quantity

- Reset Digital Instrument Cluster To Read English. **0.50**

Parts Charge: 0.00 Labor Charge: 30.00

Workorder: 1004048 Problem: PM SERVICE

Meter Reading: 51909		Labor	Parts	
In Date: 04/20/2010	Close Date: 05/03/2010	Hours	Description	Quantity
- Pm Service .		7.50	1348 OIL FILTER FRM PH3614 WIX 51348	1.00
 Aps Pm Service. 			SHOP SUPPLIES	1.00
- Replace Rear Brake Pads	Clean & Adjust .		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Charge Battery Check Ch	arging System .		10W30 MOTOR OIL	2.00
- Road Test .			REAR BRAKE PADS / D1417D792CH	1.00
- Shop Supplies			6678 AIR FILTER FRM CA8755A WIX 46678	1.00
			10W30 MOTOR OIL	5.00
			31-22 WIPER BLADES 22" WIPER BLADE	2.00

Parts Charge: 132.76 Labor Charge: 450.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1005308 Problem: DEAD BATTERY MUST JUMP START.

	Meter Reading: 51982		Labor		Parts	
	In Date: 05/24/2010	Close Date: 06/02/2010	Hours	Description	Quantity	
_	Check Charging System	& Check Battery .	1.50	SHOP SUPPLIES	1.00	
-	Replace Deff Battery & To	est .		GROUP 78 BATTERY (ACD 78PS)	1.00	
	Chan Cumpling			· · · · · · · · · · · · · · · · · · ·		

- Shop Supplies

Parts Charge: 99.99 Labor Charge: 90.00

Workorder: 1006876 Problem: 9203/ APS ENGINE FUEL PUMP.

Meter Reading: 52074 Labor Parts

	In Date: 06/30/2010	Close Date: 09/	29/2010	Hours	Description	Quantity
-	R&R Fuel Pump.			1.50	FUEL PUMP KIT / 52-559-03	1.00
-	Shop Supplies				SHOP SUPPLIES	1.00
		Parts Charge:	92.50	Labor Charge	90.00	

Workorder: 1012315 Problem: replace flat tire.

Meter Reading: 53795 **Parts** Labor In Date: 11/02/2010 Close Date: 12/01/2010 Quantity Hours Description Replace Tire / Mount & Ballance. 1.00 TIRE DISPOSAL FEE 1.00 **Shop Supplies** P 235/75R16XL LONG TOURING(USE 179745217 0/NEED) 1.00 SHOP SUPPLIES 1.00 137.26 60.00 Labor Charge: Parts Charge:

Workorder: 1012591 Problem: pm service

Meter Reading: 53952 Labor **Parts** In Date: 11/09/2010 Close Date: 11/16/2010 Hours Description Quantity Pm Service 4.50 1348 OIL FILTER FRM PH3614 WIX 51348 1.00 Service SHOP SUPPLIES 1.00 Test Drive USED FIREX REFURBED FIRE EXTINGSHERS 1.00 Shop Supplies 10W30 MOTOR OIL 5.00 31-22 WIPER BLADES 22" WIPER BLADE 2.00 2.00 10W30 MOTOR OIL 1036 OIL FILTER FRM PH3980 WIX 51036 1.00

Parts Charge: 68.26 Labor Charge: 270.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1105438 Problem: P.M. service and check for rattle in front end.

Meter Reading: 5423	7	Labor	Parts	
In Date: 05/23/2011	Close Date: 06/06/2011	Hours	Description	Quantity
- Perform Pm Service.		4.75	OIL FILTER (USE PH3980)	1.00
- Diagnose Noise In Stee	ring.Inspect And Replace Failed		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
Steering Intermediate S	ector Shaft With New		10W30 MOTOR OIL	5.00
- Test And Replace Faile	d Right Back Up Lamp Bulb With		STEERING INTERMEDIATE SHAFT	1.00
New.			BATTERY RETAINER	1.00
- Rotate And Balance All	Four Tires.		3157 TAIL LIGHT BULBS	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
- Onop Supplies				

Parts Charge: 117.38 Labor Charge: 285.00

Workorder: 1107576 Problem: dead battery on sprayer

	Meter Reading: 54312			Labor		Parts	
	In Date: 07/19/2011	Close Date: 07	/21/2011	Hours	Description		Quantity
-	Replaced Battery			1.00	GROUP 24 BATTERY (ACD 24PS)		1.00
-	Shop Supplies				SHOP SUPPLIES		1.00
		Parts Charge:	94.48	Labor Charge	e: 60.00		

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1113287 Problem: PM Service

Meter Reading: 57982			Labor		Parts		
In Date: 12/19/2011	Close Date: 0)2/14/2012	Hours	Description			Quantity
- Pm Service			11.80	SHOP SUPPLIES			1.00
Replace Tires				GROUP 75 BATTERY	' (ACD 75PS)		1.00
Replace Battery				1036 OIL FILTER FRI	M PH3980 WIX 51036		1.00
Throttle Body Service				5LB FIREX ABC STO	CK# 340280001		1.00
Trans Flush				6678 AIR FILTER FR	M CA8755A WIX 46678		1.00
Service Engine Aps				P 235/75R16XL LONG	G TOURING(USE 179745217 0	/NEED)	3.00
Replace Mufflers				3481 FUEL FILTER F	FRM G3727 WIX 33481		1.00
Replace Spark Plugs				10W30 MOTOR OIL			5.00
Replace Cluster				DASH CLUSTER / 15	114649		1.00
•				SPARK PLUG / 6630			1.00
Front End Alignment				1348 OIL FILTER FR	M PH3614 WIX 51348		1.00
Shop Supplies				10W30 MOTOR OIL			2.00
				TIRE DISPOSAL FEE			3.00
				091343 CARB CLEAR	NER		1.00
				MUFFLER / 7-03670			2.00
				SYN/ATF TRANS FLU	JID SYNTHETIC		12.00
	Parts Charge:	1,156.72	Labor Charge	: 708.00	Commercial Charge:	82.20	

Workorder: 1200475 Problem: Replace and reprogram instrument cluster.

Meter Reading: 57918 Labor Parts

In Date: 01/13/2012 Close Date: 01/19/2012 Hours Description Quantity
- Replace Instrument Cluster With New And Reprogram 2.50 SHOP SUPPLIES 1.00

With Tech 2 Pass Thru.

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 150.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Problem: Pm service. **Workorder:** 1209115

Meter Reading: 58907			Labor	F	Parts
In Date: 09/24/2012	Close Date: 1	1/26/2012	Hours	Description	Quantity
- P.M. Service			5.50	OIL FILTER PH3980	1.00
- Test Battery And Charging	System.Replace B	ad Battery.		10W30 MOTOR OIL	5.00
- Replace Both Leaking Rea	ır Shocks.			31-22 WIPER BLADES 22	2.00
- Replace Left Front Marker	Light And Missing	Cargo Lamp		SHOP SUPPLIES	1.00
Fuse.	0			MAC WITE LITHIUM GRES	1.00
- Rotate And Balance All Tir	es.			G3727 FUEL FILTER LBF	1.00
- Shop Supplies				SENSA-TRAC LT TRUCK S	2.00
- Griop Guppiles				MINIATURE BULB	1.00
				ENGINE SEAL 120Z	1.00
				GROUP 78 ACD	1.00
	Parts Charge:	272.05	Labor Char	ne: 330.00	

Problem: Pm service Workorder: 1310045

Meter Reading: 63321		Labor	Parts	S
In Date: 10/04/2013	Close Date: 10/22/2013	Hours	Description	Quantity
- P.M. Service.		4.00	USED FIRE X REFURBISHED	1.00
 Install Fire Extinguisher W 	ith Bracket Behind		NAPAGOLD FUEL FILTER	1.00
Seat.Replace Tail Gate La	atch Bezel.		SHOP SUPPLIES	1.00
- Rotate And Balance All Tir	res.		WIPER BLADE	2.00
- Shop Supplies			CUSTOM BRACKET FIRE EX	1.00
			22514722 O-RING SEAL	2.00
			10W30 MOTOR OIL	5.00
			NAPAGOLD OIL FILTER	1.00
			TAIL GATE HANDLE BEZEL	1.00

Parts Charge: 140.92 Labor Charge: 240.00

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1403759 Problem: Pm service and check radio

Meter Reading: 67114		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Labor	Parts	
In Date: 04/17/2014	Close Date: 0)4/30/2014	Hours	Description	Quantity
 Perform Pm Service. Inspect And Replace Both Hoses With New And Flus Hydraulic System With Sc Computer Diagnose For C Replace Failed Thermosta 	h Brake Fluid.Autor an Tool And Roadte check Engine Light	mated Bleed est. On.Test And	11.35	THERMOSTAT PEAK GLOBAL GAS CAP NON-LOCKING BRAKE HOSE BRAKE HOSE PWR STEERING FL-QUART	1.00 2.00 1.00 1.00 1.00 1.00
Cap.Reverse Flush And R Diagnose For Radio Inop. And Both Left And Right S New Radio With Tech 2 Diagnose For Oil Leak.Ins Steering Cooler With New	enew Engine Coola Test And Replace F Speakers With New. pect And Replace F	ant. Failed Radio Reprogram Failed Power		cap cooler SPEAKER WIPER BLADE 10W30 MOTOR OIL BRAKE CLEANER WD40 16OZ	1.00 1.00 2.00 2.00 5.00 1.00
Steering Fluid Rotate And Balance All Formula Shop Supplies	our Tires.			2232 BRAKE FLUID QUAR SHOP SUPPLIES NAPAGOLD OIL FILTER RADIO	1.00 1.00 1.00 1.00
	Parts Charge:	569.17	Labor Char	ge: 681.00	

Workorder: 1405270 Problem: Truck stalled and hard to start and runs rough.

Meter Reading: 67753 Labor Parts	TTOIRDIACI. 1700270	1100	CIII. Hack ou	anoa ana nara to ot			
- Diagnose Stalling And Hard Start Concern.Replace Distributor Cap,Rotor And Plug Wires Shop Supplies 2.50 SHOP SUPPLIES PREMIUM PLUG WIRE SET ROTOR DISTRIBUTOR CAP	Meter Reading: 67753			Labor		Parts	
Distributor Cap,Rotor And Plug Wires. - Shop Supplies - ROTOR DISTRIBUTOR CAP	In Date: 05/30/2014	Close Date: 0	6/11/2014	Hours	Description		Quantity
- Shop Supplies ROTOR DISTRIBUTOR CAP	- Diagnose Stalling And Har	d Start Concern.Re	place	2.50	SHOP SUPPLIES		1.00
DISTRIBUTOR CAP	Distributor Cap,Rotor And	Plug Wires.			PREMIUM PLUG WIRE SET		1.00
400.00	 Shop Supplies 				ROTOR		1.00
Parts Charge: 108.82 Labor Charge: 150.00					DISTRIBUTOR CAP		1.00
		Parts Charge:	108.82	Labor Charge	: 150.00		

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1410546 Problem: Pm service.Ac air flow intermittent.

Meter Reading: 71574			Labor		Parts	
In Date: 10/22/2014	Close Date: 11/	10/2014	Hours	Description		Quantity
P.M. Service.Test Battery And Charging SReplace Broken Tag Light L	•	d Battery.		WIPER BLADE USED FIRE X REFURBISHED GROUP 78 BATTERY		2.00 1.00 1.00
 Replace Broken Tag Light L Check A/C System.Replace And Blower Harness. 		Controller		LP LENS BULB		2.00 2.00
Rotate And Balance All TiresShop Supplies	S.			BLOWER MOTOR BLOWER MOTOR RESISTOR		1.00 1.00
				10W30 MOTOR OIL PIGTAIL NAPAGOLD OIL FILTER		5.00 1.00 1.00
F	Parts Charge:	351.71	Labor Charge:	SHOP SUPPLIES 420.00		1.00

Workorder: 1504798 Problem: Pm service.

Meter Reading: 76416			Labor		Parts	
In Date: 05/12/2015	Close Date: 05	/20/2015	Hours	Description		Quantity
- Pm Service.			7.25	WIPER BLADE		2.00
 Replace And Balance All Fe 	our Tires.			183680418 P235-75R16		4.00
- Test And Replace Defective	e Right Side Day Tir	ne Running		TIRE DISPOSAL FEE		4.00
Light Bulb And Socket.	· ·	· ·		NAPAGOLD FUEL FILTER		1.00
 Complete Front End Alignn 	nent.			WASHER FLUID CONCENTR		1.00
- Shop Supplies				PIGTAILS SOCKETS		1.00
				NAPAGOLD AIR FILTER		1.00
				NAPAGOLD OIL FILTER		1.00
				TIRE		4.00
				10W30 MOTOR OIL		5.00
				SHOP SUPPLIES		1.00
				SIGNAL STOP LAMP		1.00
	Parts Charge:	836.63	Labor Charg	je: 435.00		

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1510384 Problem: Pm service.

Meter Reading: 82228		Labor		Parts	
In Date: 10/14/2015 Close Date: 1	0/28/2015	Hours	Description		Quantity
 Pm Service. Check Battery And Charging System.Replace Battery.Also Replace Defective Right Drl Bulk Socket.Replace Defective Cigarette Lighter S Diagnose And Perform Pinpoint Test.Replace Park/Neutral Safety Switch Assembly And Ad Replace Front Brake Calipers,Pads And Brak Rotors.Bleed Brake System. Replace Two Defective Rear Bump Stops. Rotate And Balance All Four Tires. Shop Supplies 	o And ocket. e Defective just.	E F F S S S S	NAPAGOLD OIL FILTER ENGINE SEAL 12OZ PIGTAILS SOCKETS REMAN BRAKE CALIPER REMAN BRAKE CALIPER BRAKE ROTOR ONLY 10W30 MOTOR OIL SIGNAL STOP LAMP SWITCH-NEUTRAL BACKUP SHOP SUPPLIES B FLUID DOT 3-32OZ CIG LIGHTER ASSM BUMP STOPERS GROUP 78 BATTERY WIPER BLADE		1.00 1.00 1.00 1.00 1.00 2.00 5.00 1.00 1.00 1.00 1.00 2.00
Parts Charge:	537.97	Labor Charge:	690.00		

Workorder: 1512696 Problem: P.M. Service.Left rear tire slow leak.

Meter Reading: 87730		Labor		Parts	
In Date: 12/16/2015 Close	Date: 01/05/2016	Hours	Description		Quantity
- Pm Service.		6.75	NAPAGOLD OIL FILTER		1.00
 Replace Left Daytime Run Lamp Sock 	ret And Two Bulbs		SHOP SUPPLIES		1.00
- Diagnose Park Brake Not Holding.Insp	pect And Replace		22" WIPER BLADE		2.00
Worn Parking Brake Shoes On Both S	Sides.Adjust		10W30 MOTOR OIL		5.00
System.	,		SIGNAL STOP LAMP		2.00
- Repair Left Rear Tire.Rotate And Bala	nce All Four.		REMAN BRAKE SHOES		1.00
- Shop Supplies			PIGTAILS SOCKETS		1.00
- Onop cuppileo			NAPAGOLD FUEL FILTER		1.00
			USED FIRE X REFURBISHED		1.00
Parts Char	rge: 132.41	Labor Charg	ge: 405.00		

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Problem: Pm service. Workorder: 1601584

Meter Reading: 92889		Labor		Parts
In Date: 02/16/2016	Close Date: 02/24/2016	Hours	Description	Quantity
Pm Service.		7.50	22" WIPER BLADE	2.00
Diagnose For Shift Indicat	tor Will Not Return To Park And		10W30 MOTOR OIL	5.00
Gauges Intermittent.Repla	ace Defective Cluster And Repair		INSTRUMENT CLUSTER	1.00
Wiring Between P/N Switch	ch And Pcm.Reprogram Cluster		EXHAUST PIPE GASKET	1.00
With Scan Tool.	. 3		SHOP SUPPLIES	1.00
Diagnose Exhaust Leak R	Replace Defective Left Bank		EXHAUST GASKET	1.00
Exhaust Gasket Between	·		NAPAGOLD OIL FILTER	1.00
Pipe.Test Drive.				
Rotate And Balance All Fo	our Tires.			

Shop Supplies

Parts Charge: Labor Charge: 450.00 464.38

Problem: Right front tire flat.Cranks slow to start. **Workorder:** 1603130

Meter Reading: 96912			Labor		Parts	
In Date: 03/24/2016	Close Date: 03	3/30/2016	Hours	Description		Quantity
- Replace And Balance Rig	ht Front Tire.		2.00 TI	RE DISPOSAL FEE		1.00
- Check Battery, Charging A	nd Starting System.	Replace	SI	HOP SUPPLIES		1.00
Defective Starter Motor As	ssembly.		N	EW STARTER		1.00
Shop Supplies		18	33680418 P235-75R16		1.00	
	Parts Charge:	359.55	Labor Charge:	120.00		

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1604043 Problem: P.M. Service.Check brakes.

Meter Reading: 99497		Labor		Parts	
In Date: 04/18/2016	Close Date: 04/26/2016	Hours	Description		Quantity
P.M. Service.		4.50	NAPAGOLD AIR FILTER		1.00
Replace Left Qaytime Runn	ing Lamp Bulb And Socket.		10W30 MOTOR OIL		5.00
Replace Two Tires, Rotate And Balance All Four.			LONG LIFE SMALL BULB		1.00
Shop Supplies			22" WIPER BLADE		2.00
			183680418 P235-75R16		2.00
			TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			PIGTAILS SOCKETS		1.00
			NAPAGOLD OIL FILTER		1.00

Parts Charge: 413.71 Labor Charge: 270.00

Workorder: 1605899 Problem: P.M. service.

Meter Reading: 105130			Labor		Parts	
In Date: 06/08/2016	Close Date: 0	6/21/2016	Hours	Description		Quantity
- P.M. Service.			3.50	10W30 MOTOR OIL		5.00
- Replace Stripped Battery Bolts				NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Tires.				WASHER FLUID CONCENTR		1.00
- Shop Supplies				BATTERY CABLE BOLT		1.00
				SHOP SUPPLIES		1.00
				22" WIPER BLADE		2.00
Par	ts Charge:	29.62	Labor Charge	210.00		

Workorder: 1609782 Problem: Right rear tire going flat.

	Meter Reading: 112589				Parts	
	In Date: 09/19/2016	Close Date: 09/27/2016	Hours	Description		Quantity
-	Repair And Balance Right R	ear Tire.	1.00	SHOP SUPPLIES		1.00

Shop Supplies

Parts Charge: 2.00 Labor Charge: 60.00

1/3/2017 12:16:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10151829 2004 GMC 1500 Pickup, 1/2 Ton

Workorder: 1610569 Problem: Transition Prep Charge

Meter Reading: 113421 Labor Parts

In Date: 10/13/2016 Close Date: 10/13/2016 Hours Description Quantity

- Transition Prep Charge 2.00

Parts Charge: 0.00 Labor Charge: 0.00

Total Parts Charges: 8,603.63 Total Labor Charges: 9,352.00 Total Comm. Charges: 457.62