



3/8/2019

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V15954

In Date: 06/24/2008
Close Date: 07/21/2008

Meter Reading: 20.00

Problem?

INSTALL EQUIPMENT NEW VEHICLE SET UP EMS-7

Task performed:

1. Set up new truck.
2. Install 3rd brake light on rear of cab roof.
3. Install side step railing.
4. Remove rear seat.
5. Set up new trucks & mount equipment. j

Parts	Quantity
0913912CHARGER 2000	1
251315STEP SIDES	1
2560HITCH PIN/CLIP	1
29837-ULTSIMULATOR F350 17" SET 2008	1
5025TERMINAL BOX	1
PP601508SLIDE ASSY. FOR BACK-UP RADAR	1
YC3Z13A613BABRAKE LIGHT	1

Workorder: V16461

In Date: 07/19/2008
Close Date: 09/30/2008

Meter Reading:

Problem?

left alley light out EMS 7

Task performed:

1. Disassembled light bar. test & remove (4s) alley lit. parts dept has none in stock-bring to shop for sample. Parts ordered 8/7/08. parts not in 8/20/08.
2. Remove all lenses. remove (4) cover LTs, remove top assy, r & r fuse, r & r r/s ally LT socket + pig tail assy + light bulb assy. Wrong part made it work need to order correct one.

(R.T.)

Parts	Quantity
46-0763846-13LAMP HOLDER MR11	1
MR1135 WATT BULB	1

Workorder: V18902

In Date: 11/06/2008
Close Date: 11/19/2008

Meter Reading:

Problem?

EMS7 needs cradle charger for MSA Thermal imager.

Task performed:

1. Mount TIC & wire.
2. Secure btry charger.
3. install bolt cutters. j

Parts	Quantity
NO PARTS USED	



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V19763

In Date: 12/15/2008
Close Date: 01/07/2009

Meter Reading: 8,576.40

Problem?

b inspection and repairs as needed ems 7

Task performed:

B-Service
2. Rotate tires. j

Parts

Quantity

15W40BSYN OIL BULK QTS	16
33950USE 33963 FUEL FILTER	1
3C3Z6731AA57314 NEW 57312 OIL FILTER 6.0 DIESEL	1
49886AIR FILTER	1

Workorder: V19930

In Date: 12/23/2008
Close Date: 01/15/2009

Meter Reading: 8,807.00

Problem?

FRONT END ALIGNMENT EMS 7

Task performed:

Front end alignment EMS7 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V20292

In Date: 01/12/2009
Close Date: 02/19/2009

Meter Reading: 9,816.00

Problem?

install fog lts ems 7

Task performed:

Installed & wired fog lights. j

Parts

Quantity

64093-5FOG LIGHT KIT	1
----------------------	---

Workorder: V20432

In Date: 01/18/2009
Close Date: 02/23/2009

Meter Reading:

Problem?

remote control lock for the exterior compartments not working EMS-7

Task performed:

Chkd locks; tested ok. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V21385

In Date: 02/27/2009

Meter Reading: 13,325.00

Close Date: 03/02/2009

Problem?

cat stuck in engine belts EMS7

Task performed:

Parts

Quantity

Drive to Stn74 & take fan cover apart; rem cat; cln truck; inspect belts & fan ok. j

NO PARTS USED

Workorder: V21802

In Date: 03/14/2009

Meter Reading:

Close Date: 03/23/2009

Problem?

The warning light on the driver's side of the brush guard (under the driver's side fog light) is being held on by one screw, the other screw became dislodged. This is causing this one light to hang partially down. ems 7

Task performed:

Parts

Quantity

Drive to Stn73; wait for EMS; rep light mount; replc w/bolts & nuts; drill out push bar. j

NO PARTS USED

Workorder: V22510

In Date: 04/09/2009

Meter Reading: 16,384.00

Close Date: 04/21/2009

Problem?

replace tire ems7

Task performed:

Parts

Quantity

Replace tire on right frnt; j

NO PARTS USED

Workorder: V23065

In Date: 05/05/2009

Meter Reading: 17,752.30

Close Date: 05/05/2009

Problem?

B inspection and repairs (outside agency-al packer ford)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V22044

In Date: 03/24/2009
Close Date: 05/11/2009

Meter Reading: 14,820.00

Problem?

need wiper blades EMS7

Task performed:

Parts	Quantity
91-20WIPER BLADE 20 IN	2

Workorder: V22456

In Date: 04/10/2009
Close Date: 05/11/2009

Meter Reading: 16,258.00

Problem?

replace 1 tire EMS7 (outside agency-callaghan tire)

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor? CALLAGHAN

Workorder: V23019

In Date: 05/04/2009
Close Date: 05/13/2009

Meter Reading: 17,908.00

Problem?

C inspection and related repairs

Task performed:

Parts	Quantity
P/m service performed by al packer ford j 15W40BSYN OIL BULK QTS	6

Workorder: V23040

In Date: 05/04/2009
Close Date: 05/19/2009

Meter Reading: 17,752.30

Problem?

REPLACE BROKEN SPOTLIGHTS ON FRONT PUSH BUMPER, EMS-7

Task performed:

Parts	Quantity
1. Install seat covers. j 5291FOG LIGHTS	1
2. Install fog lights. j SS2388PCCHSEAT COVER	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V23164

In Date: 05/08/2009

Meter Reading:

Close Date: 05/20/2009

Problem?

radio battery charger not lighting up, TIC not charging, handlite not charging, shoreline battery charge only show battery 2 charging ems 7

Task performed:

Parts

Quantity

Repair wire in shore charger; out of power from charger; reinstalled; charging at this time. j

NO PARTS USED

Workorder: V23419

In Date: 05/20/2009

Meter Reading: 18,750.80

Close Date: 06/05/2009

Problem?

REPLACE REAR TIRES AT CALLAGHAN EMS 7

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V23987

In Date: 06/11/2009

Meter Reading: 20,107.90

Close Date: 06/19/2009

Problem?

install strap for fridge ems 7

Task performed:

Parts

Quantity

Strapped down cooler for meds. j

CYBS27299011 STRAP 36IN

1

UMVS254411STRAP 46 IN

1

Workorder: V24986

In Date: 07/22/2009

Meter Reading:

Close Date: 07/23/2009

Problem?

Windshield wipers do not entirely scrape away the water. They just kind of push it around. It is almost impossible to see in a rainstorm. Visibility is very bad and even worse when it is raining at night. ems7

Task performed:

Parts

Quantity

parts only no labor

91-20WIPER BLADE 20 IN

2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V25725

In Date: 08/24/2009
Close Date: 08/25/2009

Meter Reading: 24,319.00

Problem?

OJN CALL EMS 7 FRIDGE NOT WORKING

Task performed:

Call out to Stn73; go to shop; PU cooler; go to Stn73 & swap cooler out; chk opn & return to shop. j

Parts

Quantity

NO PARTS USED

Workorder: V25834

In Date: 08/27/2009
Close Date: 08/27/2009

Meter Reading: 24,495.00

Problem?

B inspection and repairs (work performed by Al Packer Ford)

Task performed:

work performed by Al Packer Ford

Parts

Quantity

NO PARTS USED

Workorder: V25766

In Date: 08/25/2009
Close Date: 09/03/2009

Meter Reading: 24,319.00

Problem?

replace front tires callaghan

Task performed:

See W/O 25765 j

Parts

Quantity

NO PARTS USED

Workorder: V25835

In Date: 08/27/2009
Close Date: 09/14/2009

Meter Reading: 24,319.00

Problem?

B inspection and repairs, engine runs poorly(outside agency-Al Packer ford)

Task performed:

B-Inspection & repairs, engine runs pooly - Al Packer j

Parts

Quantity

NO PARTS USED

Vendor? AL PACKER FORD



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V25890

In Date: 08/30/2009

Meter Reading:

Close Date: 10/15/2009

Problem?

Hood release cable is disconnected so hood will not open. Please change vehicle location to station 73. EMS 7

Task performed:

Parts

Quantity

Fnd safety latch not opening; manually released hood; reconnected cable asy; ck opn; ck ok. j

NO PARTS USED

Workorder: V26733

In Date: 10/07/2009

Meter Reading: 26,218.00

Close Date: 11/16/2009

Problem?

repair flat tire callaghan

Task performed:

Parts

Quantity

Repair flat tire - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V27282

In Date: 10/29/2009

Meter Reading: 28,469.00

Close Date: 11/16/2009

Problem?

rplace front tires ems 7 callaghan

Task performed:

Parts

Quantity

Replc frt tires EMS7 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V27598

In Date: 11/12/2009

Meter Reading: 29,415.50

Close Date: 11/23/2009

Problem?

batterys dead at 73 ems 7

Task performed:

Parts

Quantity

Put btrys on charge & tested truck charger ok. j

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V22975

In Date: 05/01/2009
Close Date: 12/01/2009

Meter Reading: 17,623.00

Problem?

INSTALL SPOT LIGHTS ON PUSH GUARD, INSTALL SEAT COVERS EMS-7

Task performed:

see 23040

Parts

Quantity

NO PARTS USED

Workorder: V28504

In Date: 12/21/2009
Close Date: 01/05/2010

Meter Reading: 31,824.00

Problem?

REPAIR BATTERY CHARGER EMS 7

Task performed:

Ck btry charger; fnd melted wiring; R/R wiring at charger;
replc grn wire; ck opn; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V28646

In Date: 12/28/2009
Close Date: 01/08/2010

Meter Reading: 32,250.00

Problem?

install strap for fridge mount EMS7

Task performed:

Drilled/mounted strap for fridge mount. j

Parts

Quantity

UMVS254411STRAP 46 IN

1

Workorder: V28973

In Date: 01/11/2010
Close Date: 01/27/2010

Meter Reading: 33,028.90

Problem?

on call wiper blades ems 7

Task performed:

Driver advsd he needed new wiper blades; installed (2)
20" blades. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V29535

In Date: 01/29/2010

Meter Reading: 34,151.00

Close Date: 01/29/2010

Problem?

B inspection and repairs EMS7 (performed by- al packer ford)

Task performed:

B inspection performed by al packer ford

Parts

NO PARTS USED

Quantity

Workorder: V29112

In Date: 01/13/2010

Meter Reading:

Close Date: 02/01/2010

Problem?

EMS 7's battery often dies, had to be jumped several times this week.

Task performed:

1. TRAVEL TO sTN73; CHKD BTRY SHORELINE CHARGER - OK; START VEH & CHK CHARGING SYS-OK; REM BTRY CABLES & TEST BTRYS; FND BAD BTRY; CLN TERMS & REPLC LEFT BTRY.
2. TRAVEL TO sSHOP & RESTOCK TRUCK WITH BTRYS. J

Parts

65-72BXT65750 BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

Quantity

1

1

Workorder: V29536

In Date: 01/29/2010

Meter Reading: 34,151.00

Close Date: 02/12/2010

Problem?

Add diamond plate to front of cargo bed just behind cab EMS7

Task performed:

1. Cut, fab/install diamond plate on box forward corners to protect body frm rocks & other road debris that are denting & chiping paint.
2. Install SCBA brkts in L/1 compt.
3. Rep latch on tailgate to latch on both sides. j

Parts

NO PARTS USED

Quantity

Workorder: V26481

In Date: 09/26/2009

Meter Reading:

Close Date: 02/16/2010

Problem?

Request that Diamond Plate be installed on the front panels of the cargo bed as this area is subjected to alot of chips and scratch from driving in Batt 7. Also, need an EMS 7 license plate issued.

Task performed:

Repaired on W.O. 29536 j

Parts

NO PARTS USED

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V29515

In Date: 01/28/2010
Close Date: 02/24/2010

Meter Reading: 34,070.90

Problem?

B inspection and repairs EMS7 (outside agency- al packer ford)

Task performed:

B-Inspection/repairs EMS7 - Al Packer j

Parts

NO PARTS USED

Quantity

Vendor? AL PACKER

Workorder: V29910

In Date: 02/11/2010
Close Date: 03/18/2010

Meter Reading: 34,595.00

Problem?

Left head lamp burned out. Needs replacement. EMS 73

Task performed:

R/R headlight right front. j

Parts

9008HEAD LAMP

H6054USE CV TYPE SEALED BEAM

Quantity

1

1

Workorder: V30825

In Date: 03/18/2010
Close Date: 04/02/2010

Meter Reading: 36,853.40

Problem?

License plate is about to fall off of the back of the truck ... one of the bolts holding in to the bracket came out. EMS 7

Task performed:

rep by stn guy. j

Parts

NO PARTS USED

Quantity

Workorder: V30941

In Date: 03/22/2010
Close Date: 04/20/2010

Meter Reading: 37,079.00

Problem?

headlight out EMS7

Task performed:

R/R headlight on EMS7 truck left front. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V32294

In Date: 05/19/2010
Close Date: 06/03/2010

Meter Reading: 40,495.50

Problem?

check engine light illuminated. ems

Task performed:

Parts

Quantity

C/O fnd check eng light on w/bank 2 running hot; clear codes; have driver watch for it to come on; looks ok at this time. j

NO PARTS USED

Workorder: V32830

In Date: 06/11/2010
Close Date: 06/21/2010

Meter Reading: 32,250.00

Problem?

check all emergency lights, siren and fast idle EMS7

Task performed:

Parts

Quantity

1. Deliver truck to Belle Glade.
2. Chk all lights. j

NO PARTS USED

Workorder: V32801

In Date: 06/10/2010
Close Date: 06/30/2010

Meter Reading: 42,509.00

Problem?

B inspection and repairs EMS7 (outside agency- al packer ford)

Task performed:

Parts

Quantity

B-Inspection/repairs EMS7 - Al Packer j

NO PARTS USED

Vendor? AL PACKER FORD

Workorder: V33514

In Date: 07/13/2010
Close Date: 07/26/2010

Meter Reading: 44,398.00

Problem?

12 volt system batt,starter draws to much take out MDT Ems 7

Task performed:

Parts

Quantity

Went to stn73; rem cables; load tested btry; fnd btry bad; R/R both btrys; started/ran; ck charging sys; ck ok; returned to WPB. j

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V33251

In Date: 06/30/2010

Meter Reading: 43,292.00

Close Date: 07/28/2010

Problem?

Back up alarm sensor on rearer of ems7 is missing a screw and hanging. unit was unplugged and placed inside vehicle. needs to be re mounted. ems 7

Task performed:

Remntd sensor; ran/ck opn; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V33722

In Date: 07/22/2010

Meter Reading: 45,199.00

Close Date: 08/12/2010

Problem?

repair door wont open EMS 7

Task performed:

All doors in rear will not open; fnd that eqmpt over transmitter makes it not to read key fob; works ok at this time. ja

Parts

Quantity

NO PARTS USED

Workorder: V33934

In Date: 07/31/2010

Meter Reading: 45,844.20

Close Date: 09/02/2010

Problem?

One of the marker lights above the windshield is blown out. It is the 2nd from the driver's side (if the tech turns on the headlights, I will see it).EMS 73

Task performed:

C/O lights & replc one on top. js

Parts

Quantity

NO PARTS USED

Workorder: V34341

In Date: 08/17/2010

Meter Reading: 47,027.00

Close Date: 09/10/2010

Problem?

B inspection and repairs EMS7 (outside agency-al packer)

Task performed:

B-Inspection/repairs EMS7 - Al Packer j

Parts

Quantity

NO PARTS USED

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V34036

In Date: 08/05/2010
Close Date: 09/15/2010

Meter Reading: 45,964.00

Problem?

RADIO SHOP***** All 12 VOLT PLUGS ARE NOT WORKING. THIS DISABLES GPS AND REFRIGERATOR AND CHARGING C OTHER EQUIPMENT. VEHICLE IS LOCATED AT STATION 73 ems 7

Task performed:

Parts

Quantity

1. C/O power to plugs-all out; trace down power; fnd fuse in front of center consoled bad; replc w/____ 15 AMP fuse; all work ok at this time.
2. Both power point on dash were blown; trace fuses to both units -chk; mk fuse holes to replc them till get to shop for right type.
3. install (2) new Ford type 20 AMP fuse in panel outside; all ok at this time.

NO PARTS USED

Workorder: V34368

In Date: 08/18/2010
Close Date: 09/15/2010

Meter Reading: 26,218.00

Problem?

replace all 6 tires EMS7 (outside agency-TCI Tire Center)

Task performed:

Parts

Quantity

Replace all (6) tires EMS7 - TCI Tire j

NO PARTS USED

Vendor? TCI TIRE

Workorder: V34463

In Date: 08/23/2010
Close Date: 09/15/2010

Meter Reading: 45,844.20

Problem?

install dust cap EMS 73

Task performed:

Parts

Quantity

Installed dust cap on truck right front. j

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V33162

In Date: 06/26/2010
Close Date: 10/20/2010

Meter Reading: 43,292.00

Problem?

check engine light illuminated. on going problem, previous diagnostic indicated o2 sensor problem. vehicle located at station 73. sensor(s) needs replacement. EMS72

Task performed:

- Loosened O2 sensors; fnd (4) sensors in sys; ck codes; truck didn't start; ck starter; no power to solenoid; compr shut truck down for 30 min.
- C/O no light at this time; it was rep at Ford when truck was in. j

Parts	Quantity
8C3Z12B591AO2 SENSOR	1
8C3Z12B591DO2 SENSOR	2
8C3Z12B591EO2 SENSOR	1

Workorder: V35033

In Date: 09/17/2010
Close Date: 10/20/2010

Meter Reading: 48,817.60

Problem?

blown fuses for cigarette lighters necessary for auxillary devices EMS 7

Task performed:

- check for blown fuses, found 3 blown fuses, r&r fuses checks ok. j

Parts	Quantity
01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	1
KR-CCLCATHODE COMPARTMENT LIGHT	1

Workorder: V35825

In Date: 10/21/2010
Close Date: 11/03/2010

Meter Reading: 50,643.20

Problem?

Tow truck to al packer ford. EMS7

Task performed:

Tow truck EMS7 to Al Paacker Ford j

Parts	Quantity
NO PARTS USED	

Vendor? MOSS TOWING

Workorder: V35824

In Date: 10/21/2010
Close Date: 11/16/2010

Meter Reading: 50,696.00

Problem?

Repair engine (low power) EMS 7 (outside agency-al packer)

Task performed:

Rep eng-low power EMS7 - Al Packer j

Parts	Quantity
NO PARTS USED	

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V36222

In Date: 11/05/2010

Meter Reading: 50,643.20

Close Date: 11/17/2010

Problem?

check emergency lights and siren EMS7

Task performed:

C/O truck; R/R tir 6 & rewire. j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V36242

In Date: 11/06/2010

Meter Reading: 50,643.20

Close Date: 11/18/2010

Problem?

Emergency LED light is out, located passenger side front on brush guard EMS7

Task performed:

1. Rear compt latch inop - rod bent; rem/straightened rod.
2. C/O light on unit; fnd wires off of light on frnt brush guard; rewire - all lights working. j

Parts

NO PARTS USED

Quantity

Workorder: V36833

In Date: 12/02/2010

Meter Reading: 52,413.00

Close Date: 12/30/2010

Problem?

the tubing that attaches the windshield wiper reservoir to the sprayers will not stay connected. this is a very high priority in Batt 7 where the bugs are out of control. appears the heat has stretched the ends to loose ems7

Task performed:

- (1) TRAVELED TO ST72 TO REPAIR WIND SHIELD WASHER SYSTEM. DID TEMP FIX AND ORDERED NEW SPRAYERS FROM FORD.
- (2) TRAVELED TO ST73. INSTALLED NEW WIND SHIELD SPRAYERS. OK NOW. J.W.

Parts

7C3Z17603AWASHER NOZZLES

Quantity

2



3/8/2019

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V37521

In Date: 12/31/2010
Close Date: 01/07/2011

Meter Reading: 53,967.20

Problem?

Roof clearance light on passenger side of vehicle is out and no longer working.EMS 7

Task performed:

(1) ROOF CLEARANCE LIGHTS ON RIGHT SIDE OF EMS7 VEHICLE IS 10-7. TRAVELED TO ST-73 TO REPAIR CLEARANCE LIGHTS ON EMS7. PULLED COVER OFF AND FOUND THE BULB WAS BAD. REPLACED WITH A NEW ONE. ALL WORKING OK. J.W.

Parts

194BULB

Quantity

10

Workorder: V37927

In Date: 01/20/2011
Close Date: 01/21/2011

Meter Reading: 55,401.00

Problem?

check emergency lights and siren, fob for compt. locks innop, test drive for vibration 60-70 mph EMS7

Task performed:

(1) EMS7. CHECKED AT SHOP EMERGENCY LIGHTS & SIREN, ALL OK. FOB GOOD. TEST DROVE AND NOTICED SLIGHT VIBRATION IN FRONT END. J.W

Parts

NO PARTS USED

Quantity

Workorder: V37892

In Date: 01/19/2011
Close Date: 01/27/2011

Meter Reading: 55,401.00

Problem?

B inspection and repairs EMS7 (outside agency-al packer)

Task performed:

B-inspection/repairs EMS7 - Al Packer j

Parts

NO PARTS USED

Quantity

Vendor? AL PACKER

Workorder: V38566

In Date: 02/16/2011
Close Date: 02/23/2011

Meter Reading: 57,100.00

Problem?

The next time you are out here please install a spanner and hydrant wrench on Capt.7. L1 compartment.

Task performed:

installed spanner wrench & hydrant wrench in L-1 compt of EMS7 unit. j

Parts

NO PARTS USED

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V38178

In Date: 01/31/2011

Meter Reading: 56,027.00

Close Date: 02/28/2011

Problem?

1) location is wrong - this truck is assigned to station 73 2) the headlights are inadequate and they are not illuminating the dark roads out here (not even in bright mode) EMS7

Task performed:

Parts

Quantity

Clen off both headlights - lots of bugs both are working at this time; may need fog light installed. j

NO PARTS USED

Workorder: V39402

In Date: 03/23/2011

Meter Reading: 59,105.80

Close Date: 04/01/2011

Problem?

please install better head lamp bulbs. we can not see at night. capt 7

Task performed:

Parts

Quantity

travel to Stn73; R/R headlight bulbs; let Capt know to let us know how they work. j

H6054USE CV TYPE SEALED BEAM

2

Workorder: V39520

In Date: 03/29/2011

Meter Reading: 59,402.00

Close Date: 04/05/2011

Problem?

Headlight is out !! EMS 7

Task performed:

Parts

Quantity

Travel to Stn73; R/R headlight; chk wiring; replc headlight. j

NO PARTS USED

Workorder: V39555

In Date: 03/30/2011

Meter Reading: 59,402.00

Close Date: 04/05/2011

Problem?

The new right headlight is out. sta 73.

Task performed:

Parts

Quantity

Rep on WO 39520

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V40552

In Date: 05/11/2011
Close Date: 05/13/2011

Meter Reading: 62,231.80

Problem?

2 things, the Left 2nd compartment opens on its own when you drive. The top slide has a rust spot on the leading edge. Feel free call me. 767.0618, Sta 72.

Task performed:

1. Test drove; fnd truck pulling to the right; rem all wheels; rotated front tires to rear; ck/adj tire press; test drove; ck ok.
2. Fnd rust spot onsliding rear cvr; sanded out rust; painted spot; resealed rear folding door on cvr; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V40733

In Date: 05/19/2011
Close Date: 06/09/2011

Meter Reading: 62,591.70

Problem?

rear doors wont close. Sta 73.

Task performed:

Rep/adj rear door latch. j

Parts

Quantity

NO PARTS USED

Workorder: V40940

In Date: 05/28/2011
Close Date: 06/13/2011

Meter Reading: 63,211.40

Problem?

The passenger side fog light seems to be burned out. Capt 7

Task performed:

Travel to Stn73; R/R bulb on fog lamp. j

Parts

Quantity

H3-100WBP1210H3 BULB

2

Workorder: V41159

In Date: 06/06/2011
Close Date: 06/13/2011

Meter Reading: 63,557.00

Problem?

Vehicle batteries went dead while truck sat for under 3 hours. Had to be jump started. Sta 72.

Task performed:

Travel to Stn72 - not there; travel to Stn73; chk E11 sys; btry bad;; R/R btrys; return to shop. j

Parts

Quantity

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

2



3/8/2019

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V41289

In Date: 06/13/2011
Close Date: 06/15/2011

Meter Reading: 63,889.00

Problem?

replace front tires ems 7

Task performed:

Replace front tires EMS7 - Elpex j

Parts

Quantity

NO PARTS USED

Vendor? ELPEX

Workorder: V41299

In Date: 06/13/2011
Close Date: 06/15/2011

Meter Reading: 63,889.00

Problem?

balance front tires

Task performed:

Balance front tires - Robbie j

Parts

Quantity

NO PARTS USED

Vendor? ROBBIE TIRE

Workorder: V40546

In Date: 05/11/2011
Close Date: 07/12/2011

Meter Reading: 62,231.80

Problem?

B Inspection.

Task performed:

B Inspection @ Al Packer. Left side door on box would open while driving- problem was fixed

Parts

Quantity

NO PARTS USED

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V41483

In Date: 06/21/2011
Close Date: 07/19/2011

Meter Reading: 64,434.90

Problem?

Install rumber on capt 7

Task performed:

TRAVEL TO STA 73 INSTALL RUMBLER ON EMS 7
MOUNT SPEAKERS CONTROL SWITCH ELT. WIRE
UP SYSTEM AND TEST OK TRY TO SET SIREN TO Q
ON SWITCH #4 PER CAPT.

FOUND COOLANT LEAK TRY TO REPAIR NEED NEW
HOSE ORER HOSE TRAVEL TO 73 R&R LOWER
HOSE AND REFILLSS AK

Parts

Quantity

AC3Z8286AHOSE RADIATOR F350 08	1
ANTICOOLANT ANTIFREEZE GAL	5
HOWLERSIREN	1
SWT54916V2D1000B-00000-000 SW ROCKER SPST NON-	2

Workorder: V42422

In Date: 08/01/2011
Close Date: 08/04/2011

Meter Reading: 66,352.90

Problem?

The left rear strobe light is OOS. Sta 73.

Task performed:

repaired on wo 42476 the lights were all ok

Parts

Quantity

NO PARTS USED

Workorder: V42476

In Date: 08/01/2011
Close Date: 08/30/2011

Meter Reading: 66,618.70

Problem?

Driver's side headlight needs to be replaced. The low beams work fine, but the high beams will not come on - driver's side only. E1
7

Task performed:

travel to st 73 check out head light need to order new
one

check out strobes out will get and return home travel to
hq r&r tire lights and rewire

travel to st 73 r&r head light

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6	4
H6054BLH6054CVC1 HEADLIGHT EXTRA BRIGHT	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V43099

In Date: 08/27/2011

Meter Reading: 67,948.40

Close Date: 08/30/2011

Problem?

The plug will not connect to charge the vehicle Capt 73

Task performed:

Parts

Quantity

went to 73 ck fuses and connection sfound connection at charger poor repaired wire and connction ck operation ck ok r&r center cab marker lt bulb went to st 27

NO PARTS USED

Workorder: V43680

In Date: 09/14/2011

Meter Reading: 69,000.50

Close Date: 09/27/2011

Problem?

Right LED on the truck bed was knocked off. The LED and case need to be replaced. EMS 7

Task performed:

Parts

Quantity

removed damaged parts drilled new holes for different -and install on rear of truck travel to station

5TSMACMOUNT 500 TIR SER CHROME

2

6819634283068-1963428-30 LENS CLR

2

Workorder: V44111

In Date: 10/03/2011

Meter Reading: 69,869.00

Close Date: 10/04/2011

Problem?

The front end shakes when going between 50 and 70 mph. Was told the last time this happened that it was the tires. Michelens fixed the problem before. Sta 73.

Task performed:

Parts

Quantity

JOHN FISHER NOTIFIED @ AL PACKER FORD CHECK SUSP.

NO PARTS USED

NO ASSISGMENT, HOURS, OR CHARGE SHOWN ON WO



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V43955

In Date: 09/27/2011
Close Date: 10/11/2011

Meter Reading: 69,963.00

Problem?

Outside B inspection.

Task performed:

AL PACKER
B INSPECTION WITH ROAD TEST
OIL AND FILTER CHANGE
PERFORM RECALL 11B23 POWERTRAIN CONTROL
MODULE RECALIBRATION
REPLACE FUEL FILTER DIESEL
ELEMENT ASY AIR CLEANER
BALANCE AND ROTATE 6 DUALY TIRES
INSTALL FRONT WIPER BLADES
Vendor? AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V44299

In Date: 10/11/2011
Close Date: 10/11/2011

Meter Reading: 70,054.00

Problem?

Won't run.

Task performed:

AL PACKER
WRENCH WARNING LAMP CAME ON AND THE
VEHICLE HAD REDUCED POWER, VERIFIED
CONCERN PERFORM VISUAL INSPECTION OK
PERFORM DIESEL PERFORMANCE DIAG EEC TEST
KOE PASS KOER PASS CMDTC REF PPT ENGINE
PERFORMANCE DIAG, DIESEL
CAB ASSEMBLY REMOVE AND NSTALL
COOLER OIL REMOVE AND INSTALL
R&R WORN FRONT SHOCKS AND STEERING
DAMPNER
NOTE FRONT TIRES HAVE HI RUN OUT
Vendor? AL PAKCER

Parts

Quantity

NO PARTS USED

Workorder: V36610

In Date: 10/12/2011
Close Date: 10/12/2011

Meter Reading: 51,790.00

Problem?

2 spanner wrench 73 sta

Task performed:

GIVEN TO STATION

Parts

Quantity

AS75807OXM1757-01 OXYGEN WRENCH

2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V44223

In Date: 10/07/2011
Close Date: 10/12/2011

Meter Reading: 69,869.00

Problem?

CHECK TIRES AND LIGHTS

Task performed:

CHECKED TIRES AND LIGHTS ROAD TESTED

Parts

NO PARTS USED

Quantity

Workorder: V44525

In Date: 10/19/2011
Close Date: 10/24/2011

Meter Reading:

Problem?

The "Rumbler" speakers under the bumper are loose. The mounts need to be tightened. R 73

Task performed:

travel to st 73 check out rumbler speakers, bolts all tight
ok for now

Parts

NO PARTS USED

Quantity

Workorder: V45495

In Date: 11/29/2011
Close Date: 11/30/2011

Meter Reading:

Problem?

When the parking brake is applied, the high-idle starts and immediately stops, and a "check engine" ("wrench" symbol) is displayed by the speedometer. The symbol goes away upon restart of the vehicle. Sta 73

Task performed:

repair fast idle circuit al packer

Parts

NO PARTS USED

Quantity

Vendor? AL PACKER

Workorder: V45482

In Date: 11/29/2011
Close Date: 12/09/2011

Meter Reading:

Problem?

The LED warning light on the passenger side of the brush guard (facing sideways) is not working correctly. It is very dim and probably needs to be replaced. Sta 73

Task performed:

TRAVEL TO ST.74 CHECK OUT LIGHT CHECK
POWER AND GROUND R&R TIR 3 LIGHT RETURN TO
SHOP.

Parts

RSR03ZCRLIGHT LED RED TIR3 SERIES

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V45483

In Date: 11/29/2011

Meter Reading:

Close Date: 12/09/2011

Problem?

The box marker light on the rear driver's side (to the left of the shoreline charging indicator lights) is out. EMS 7

Task performed:

Parts

Quantity

TRAVEL TO ST-73 REPAIR BAD GRESANDS DRILL OUT AND REPLACE POP REVITS ON LIGHT FIXTURES RETEST OK.

NO PARTS USED

Workorder: V45712

In Date: 12/07/2011

Meter Reading:

Close Date: 12/19/2011

Problem?

The three red marker lights above the trailer hitch intermittently work. You have to bang on them to get them to work. If they are working, banging them makes them go off.

Task performed:

Parts

Quantity

TRAVEL TO STA 73 CHECK OUT MARKER LIGHT ON REAR OF TRUCK. BAD GROUND REMOUNT LIGHT REPLACE SCREWS REPAIR BAD GROUND.

NO PARTS USED

Workorder: V45878

In Date: 12/15/2011

Meter Reading:

Close Date: 12/19/2011

Problem?

The LED strobe over the rear driver's side wheel well on the "box" is not lighting completely. EMS 7

Task performed:

Parts

Quantity

TRAVEL TO STA 73 CHECK OUT LIGHT R&R LIGHT REWIRE NEW LIGHT.

50R03ZCRLIGHT LED RED TIR 6

1

Workorder: V46586

In Date: 01/15/2012

Meter Reading: 75,664.00

Close Date: 01/30/2012

Problem?

Orange marker light is OOS on the roof of the cab. ems 7

Task performed:

Parts

Quantity

TRAVEL TO ST 73 CHECK OUT CAB LIGHT R&R LENS CHECK FOR POWER AND GROUND OR R&R BULB OK. RETURN TO SHOP.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V46981

In Date: 01/31/2012
Close Date: 02/02/2012

Meter Reading: 76,416.00

Problem?

The vehicle will not start. It has been on the shoreline all night and morning, and is showing 1 "bar" on each side on the charging indicator. Sta 73

Task performed:

1. TRAVEL TO ST 73 CHECK OUT BATTES. OK RECHARGE. CHECK OUT PLUGIN CHARGER. R&R BATTES SERVICE CABLES. RETEST CHARGER AND CHECK CHARGING SYSTEM ON TK.
2. REPLACE LENS ON FRONT STROBE LIGHT.

Parts	Quantity
65-72BXT65750 BATTERY	2
6819634283068-1963428-30 LENS CLR	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2

Workorder: V47083

In Date: 02/04/2012
Close Date: 02/14/2012

Meter Reading: 76,588.00

Problem?

The shoreline plug is not connecting, causing intermittent charging problems. We are using a temporary pigtail which is working fine. This problem is on the cable plug, not the truck itself.Sta 73

Task performed:

- TRAVEL TO ST 73 CHECK OUT SHORELINE NO POWER MAKE SURE BRAKES WAS OFF R&R PLUG FOUND ON POWER CORD FROM CEILING. RESET BRAKES STILL NO POWER AND TOLD DRIVER TO CALL BUILDING DEPT.

Parts	Quantity
NO PARTS USED	

Workorder: V47140

In Date: 02/07/2012
Close Date: 02/14/2012

Meter Reading: 76,588.00

Problem?

Auto-eject receptacle for shoreline does not eject. Please update vehicle location to 73. Sta 73

Task performed:

- TRAVEL TO ST 73 CHECKOUT AUTO EJECT ON TK. WORKING STICKS LUBE AUTO EJECT UNIT.

Parts	Quantity
NO PARTS USED	



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V47382

In Date: 02/17/2012

Meter Reading: 77,163.00

Close Date: 02/17/2012

Problem?

B inspection (AL Packer)

Task performed:

Parts

Quantity

b inspection
oil and filter change
rear brake job
replaced rear brake rotors and wheel seals

NO PARTS USED

Vendor? AL PACKER

Workorder: V47507

In Date: 02/22/2012

Meter Reading: 77,163.00

Close Date: 02/27/2012

Problem?

replace rear tires

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor? *

Workorder: V47373

In Date: 02/16/2012

Meter Reading: 77,163.00

Close Date: 02/28/2012

Problem?

TIC charger is not charging TIC but does charge the spare battery.

Task performed:

Parts

Quantity

CHECK TIC CHARGER FOUND LIGHT COME ON WHEN CAMERA IS PLUGGED IN TO TELL YOU IT IS CHARGING AND I TOOK BATTERY OUT OF CAMERA AND PUT IT IN SPARE BATTERY CHARGER AND LIGHT COME ON TO TELL YOU SPARE BATTERY IS CHARGING.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V47544

In Date: 02/24/2012
Close Date: 02/29/2012

Meter Reading: 77,163.00

Problem?

Vibration at 65 mph

Task performed:

Parts

Quantity

CHECK OVER TRUCK, FOUND LITTLE VIBRATION IN DRIVING BUT IT OK, CHECK ALL LIGHTS, READY FOR SERVICE .

NO PARTS USED

Vendor? AL PACKER FORD

Workorder: V47563

In Date: 02/25/2012
Close Date: 03/01/2012

Meter Reading: 77,394.30

Problem?

There seems to be a problem with the vehicles suspension. There is way too much sway when driving down the road. Just came back from having work on the front end and new tires. Very noticable over 50mph. DANGEROUS!!! Sta 72

Task performed:

Parts

Quantity

TRAVEL TO ST 73 CHECK OUT THE SUSPENSION. LOOKS OK NEEDS HARDER SIDE WALL TIRES TOO MUCH MOVEMENT.

NO PARTS USED

Workorder: V47753

In Date: 03/05/2012
Close Date: 03/07/2012

Meter Reading: 77,782.90

Problem?

DRIVABILATY PROBLEM EMS 7

Task performed:

Parts

Quantity

ROAD TESTED FOR DRIVE ABILITY PROBLEM, FOUND NO PROBLEMS. SWAPPED TRUCK OUT AS PER MIKE L.

NO PARTS USED

Workorder: V45614

In Date: 12/04/2011
Close Date: 03/12/2012

Meter Reading:

Problem?

Left rear red marker light is out. EMS 7

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V47959

In Date: 03/14/2012
Close Date: 03/26/2012

Meter Reading: 77,782.90

Problem?

replace front tires

Task performed:

ROAD TESTED TRUCK, REPLACED FRONT TIRES AND ROAD TESTED AGAIN.

Parts

NO PARTS USED

Quantity

Workorder: V47762

In Date: 03/05/2012
Close Date: 03/27/2012

Meter Reading: 77,782.90

Problem?

REPAIR SUSPENSION EMS 7

Task performed:

REPAIR SUSPENSION EMS 7.

Parts

NO PARTS USED

Quantity

Vendor? TOTAL TRUCK PARTS

Workorder: V48461

In Date: 04/05/2012
Close Date: 05/02/2012

Meter Reading: 78,668.00

Problem?

Marker light has a loose ground, Sta 73

Task performed:

- TRAVEL TO ST 73 CHECK OUT MARKER DRILL OUT BOLTS REPLACE BOLTS REINSTALL LIGHT TEST OK.
- DOMELIGHT OUT REPLACE DOME LIGHT ON CAB ALSO TRAVEL TO ST.

Parts

211-2BULB

Quantity

10

Workorder: V48675

In Date: 04/14/2012
Close Date: 05/02/2012

Meter Reading: 79,157.00

Problem?

Can you send us some chrome lug nut covers for the Cpt. 7 Truck please.

Task performed:

CHECK OUT COVER WILL TRY TO ORDER NEW CAP PAINT FOR NOW.

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

Quantity

3



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V48834

In Date: 04/23/2012
Close Date: 05/09/2012

Meter Reading: 79,626.00

Problem?

Please send out a 7 prong to 4 prong trailer light adapter and a three way trailer hitch.batt 7 EMS

Task performed:

DROP OFF TRAILER HITCH AND ADAPTER TO CHIEF
LUPO FOR EMS 7

Parts

Quantity

2485BALL MOUNT WITH 3 BALLS

1

54177 TO 4 TRAILER WIRE CONNECTOR

1

Workorder: V49199

In Date: 05/08/2012
Close Date: 05/15/2012

Meter Reading: 80,755.00

Problem?

The auto eject plug cover is broker. Big John already replaced it.

Task performed:

R&R AUTO EJECT COVER ON TRUCK.

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT

1

Workorder: V49252

In Date: 05/10/2012
Close Date: 05/15/2012

Meter Reading: 80,755.00

Problem?

Wiper blades need to be replaced ASAP please on the CP7 Truck and the AirBoat pick-up truck. The AirBoat truck will be OOS until.

Task performed:

TRAVEL TO ST 73 CHECK OUT WIPERS ON TRUCKS
R&R WIPERS ON BOTH TRUCKS REINSTALL ARM.

Parts

Quantity

NO PARTS USED

Workorder: V49431

In Date: 05/17/2012
Close Date: 05/30/2012

Meter Reading: 81,051.00

Problem?

The refrigerator needs to be hard wired to the truck. The cigarette lighter adapted keeps popping out and ruining our drugs.

Task performed:

TRAVEL TO ST 73 WIRE UP FRIGE TO TK AND
INSTALL FUSE.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V49641

In Date: 05/26/2012
Close Date: 07/20/2012

Meter Reading: 81,759.50

Problem?

Please install the new light in the back of our truck. Thank you CAPT 7

Task performed:

ON W.O. #49705

Parts

Quantity

NO PARTS USED

Workorder: V49705

In Date: 05/29/2012
Close Date: 07/20/2012

Meter Reading: 81,759.50

Problem?

INSTALL ADDITIONAL LIGHTING IN REAR OF UNIT EMS 7

Task performed:

TRAVEL TO ST 73 INSTALL LIGHTS TO THE BACK OF TRUCK FOR COMAND BOARD AND WIRE UP.

Parts

Quantity

KR-CCLCATHODE COMPARTMENT LIGHT

2

Workorder: V51250

In Date: 07/31/2012
Close Date: 08/02/2012

Meter Reading: 85,235.10

Problem?

B inspection

Task performed:

B INSPECTION
FUEL FILTER

Vendor? AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V51701

In Date: 08/18/2012
Close Date: 09/06/2012

Meter Reading:

Problem?

The right PIAA fog light is OOS. CAPT. 7

Task performed:

1.TRAVEL TO ST73 R&R PIAA LIGHT BULB

Parts

Quantity

H3-100WBP1210H3 BULB

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V52579

In Date: 09/23/2012
Close Date: 10/02/2012

Meter Reading: 880,055.00

Problem?

The strobe light in the left front orange blinker is OOS and the head lights only wig not wag. The left doesn't flash.capt 73

Task performed:

- CHECK OUT LIGHTS NEED WHELAN WIGWAG AND BAD 2 SCREW HIDE AWAY LIGHT.
- TRAVEL TO ST 73 PULL FRONT DRIVE SIDE HEAD LIGHT BUCKET PULL APART AND R&R STROBE BULD R&R WIGWAG UNIT AND REWIRE.

Parts	Quantity
S30HARRED STROBE 01-0461403-RON	1
UHF-2150AFLASHER-WHELEN HEADLIGHT HIGH BEAM	1

Workorder: V53191

In Date: 10/18/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

The shoreline auto-ejector is sticking, not ejecting the shoreline. CP7

Task performed:

- TRAVEL TO ST 73 R&R AUTO REJECT ON UNIT AND REWIRE.

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1
0915520120AUTO EJECT 20 AERO OTL3925	1

Workorder: V53413

In Date: 10/30/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

The shore line does not disconnect when the engine starts. CAPT 7

Task performed:

- REPAIRED ON WO #53191

Parts	Quantity
NO PARTS USED	



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V53481

In Date: 11/01/2012

Meter Reading:

Close Date: 11/20/2012

Problem?

Left rear inside tire is flat. It's a Michelin and it's seperated from the tread. I had to limp it 10-15 miles back to the station

Task performed:

Parts

Quantity

R&R TIRE TO SHOP

NO PARTS USED

LEFT REAR INSIDE TIRE IS FLAT. IT'S A MICHELIN AND IT'S SEPERATED FROM THE TREAD. I HAD TO LIMP IT 10-15 MILES BACK TO THE STATION.

Vendor? BOULEVARD TIRE CENTE

Workorder: V53931

In Date: 11/20/2012

Meter Reading:

Close Date: 11/28/2012

Problem?

The driver's side headlight is out. Capt 7

Task performed:

Parts

Quantity

WENT TO 73- R/R LEFT HAED LT BULB CHK OK.

H6054BLH6054CVC1 HEADLIGHT EXTRA BRIGHT

1

Workorder: V54048

In Date: 11/28/2012

Meter Reading:

Close Date: 12/03/2012

Problem?

Front left Led light on the push bar is missing the lenz cover. The light still works. capt 7

Task performed:

Parts

Quantity

CHANGED LED LIGHT ON PUSH BAR OF EMS CAPT TRUCK.

50R03ZCRLIGHT LED RED TIR 6

2

50R03ZRRLIGHT 500 TIR LED

1

60R00FRR600 SERIES RED LED W/O FLANGE

2

RSR03ZCRLIGHT LED RED TIR3 SERIES

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V54433

In Date: 12/13/2012

Meter Reading:

Close Date: 12/19/2012

Problem?

Flat left rear tire. AT 14 contacted and the repair is in progress.

Task performed:

Parts

Quantity

FLAT LEFT REAR TIRE. AT 14 CONTACTED AND THE REPAIR IS IN PROGRESS.

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V54117

In Date: 12/01/2012

Meter Reading:

Close Date: 01/11/2013

Problem?

Left PIAA Fog light is out. Please bring one extra for Jeff's locked cabinet. EMS 7

Task performed:

Parts

Quantity

REPAIRED ON WO#54572

NO PARTS USED

Workorder: V54572

In Date: 12/22/2012

Meter Reading:

Close Date: 01/17/2013

Problem?

driver side fog light is out and is need of repair. EMS 7

Task performed:

Parts

Quantity

TRAVEL TO ST 73 R&R FOG LIGHT BULB.

NO PARTS USED

Workorder: V55194

In Date: 01/22/2013

Meter Reading:

94,020.00

Close Date: 01/23/2013

Problem?

body door locks inop

Task performed:

Parts

Quantity

DRILLED OUT HANDLE TO COMPARTMENT DOOR
RESET CONTROLLER CLEANED TUMBLER SO KEY
WOULD WORK.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V55463

In Date: 01/31/2013
Close Date: 02/06/2013

Meter Reading: 94,617.00

Problem?

The PIAA fog lights do not come on. There is power to the switch but not to the lights.EMS-7

Task performed:

CHECK OUT FOG LIGHTS ON TRUCK. CHECK SWITCH ON CONSOLE OF TRUCK. CHECK FOR POWER AND GROUND. CHECK WIRING AND RELAY ETC. NO POWER OUT OF CONTROL BOX TO LIGHTS. REMOVE BOX CHECKOUT BOX CHECK BOARD BROKEN R&R CONTROL BOX. RETURN TO SHOP

Parts

Quantity

5291FOG LIGHTS

1

Workorder: V55482

In Date: 02/01/2013
Close Date: 02/06/2013

Meter Reading: 94,617.00

Problem?

The trucks batteries need to be replaced. it was unplugged for an hour and was dead.EMS-7

Task performed:

TRAVEL TO ST 73 R&R BATTES AND RETURN.

Parts

Quantity

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

2

Workorder: V55483

In Date: 02/01/2013
Close Date: 02/08/2013

Meter Reading:

Problem?

Compartment lights are not working CAPT 7

Task performed:

TRAVEL TO ST 73 CHECK OUT LIGHTS CHECK SWITCHES ECT. POWER OF SWITCHS AND RELAY FOUND WIRE IN FROM RAIL SHORTED OUT REPIAR CONNECTION.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V55668

In Date: 02/09/2013

Meter Reading:

Close Date: 02/14/2013

Problem?

Wiper blades were replaced on 2/8/13 by John Vasko. CAPT 7

Task performed:

Parts

Quantity

ADJUSTED REAR LINKAGE ON R33 LEVELED OUT BODY.

91-22WIPER BLADE

2

Workorder: V55217

In Date: 01/22/2013

Meter Reading: 94,020.00

Close Date: 03/07/2013

Problem?

B-inspection AI Packer

Task performed:

Parts

Quantity

B-pm/Replace fuel filter/Rotate frt tires to rear/Replace frt brakes & rotors
Replace air filter

NO PARTS USED

Vendor? AL PACKER

Workorder: V56331

In Date: 03/11/2013

Meter Reading: 96,813.00

Close Date: 03/25/2013

Problem?

Rear square large emergency lights not working. Rear of vehicle only has small strobes. EMS-7

Task performed:

Parts

Quantity

TRAVEL TO ST 72 CHECK OUT STROBES FOUND BLOWN FUSE IN STROBE BACK REPAIR TEST OK.

NO PARTS USED

Workorder: V56444

In Date: 03/16/2013

Meter Reading: 97,031.00

Close Date: 04/04/2013

Problem?

Right rear red marker light is OOS EMS 7

Task performed:

Parts

Quantity

REPAIR BAD GROUND ON LIGHT.

19200R46742 RED MARK/LIGHT 4 IN MARKER LIGHT

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V52731

In Date: 09/30/2012
Close Date: 04/05/2013

Meter Reading:

Problem?

Engine check light is on. Oil and transmission fluid is full, Nothing is overheating, pressures are good. I tried to reset the computer by disconnecting the battery, but Engine Check light is still on. CAPT 7

Task performed:

Parts

Quantity

TRAVEL TO ST 73 CHECK OUT EMS TRUCK HOOK UP LAPTAP CHECK FOR CODES EGR CODES EGR CODE CLEAR CODES WILL WATCH.

NO PARTS USED

Workorder: V56601

In Date: 03/23/2013
Close Date: 04/09/2013

Meter Reading: 97,336.00

Problem?

The driver's side headlight needs to be aimed/adjusted. It shines directly into the rearview mirror of the vehicle in front of it. EMS-7

Task performed:

Parts

Quantity

ADJUST HEADLIGHTS AND TRAVEL TO ST 73.

NO PARTS USED

Workorder: V57231

In Date: 04/23/2013
Close Date: 04/25/2013

Meter Reading: 98,861.00

Problem?

Auto-eject not functioning EMS-7

Task performed:

Parts

Quantity

TRAVEL TO ST 73 CHECK OUT AUTO EJECT. NO POWER TO UNIT FOUND FUSE BLOWN TO EJECT REPAIR.

NO PARTS USED

Workorder: V57499

In Date: 05/06/2013
Close Date: 05/20/2013

Meter Reading:

Problem?

Lock on RIC bag compartment sticking and lock is spinning on CP7.

Task performed:

Parts

Quantity

TRAVEL TO ST 73 CHECK OUT COMPT ADJUST LOCK AND LATCH TEST OK.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V58122

In Date: 06/01/2013

Meter Reading:

Close Date: 06/07/2013

Problem?

- 1. Batteries are not charging. 2. Auto-eject not working CAPT 7

Task performed:

Parts

Quantity

TRAVEL TO STA 73 REPLACED AUTO EJECT.

NO PARTS USED

Workorder: V58522

In Date: 06/18/2013

Meter Reading: 101,805.00

Close Date: 06/18/2013

Problem?

- B inspection CAP7

Task performed:

Parts

Quantity

b inspection
oil and filter change
replace fuel filter
installed wiper blades

NO PARTS USED

Vendor? AL PACKER

Workorder: V58138

In Date: 06/03/2013

Meter Reading: 101,206.00

Close Date: 06/28/2013

Problem?

- When the truck goes in for PM the top of the rear deck needs to have all of the rust removed. CAPT 7

Task performed:

Parts

Quantity

- 1. WORK ON RUST ON TOP OF TRUCK, SAND DOWN BAD SPOTS, CLEAN UP GET READY TO SEAL OUT RUST.
- 2. WORK ON RUST, TAPE OFF AND SEAL OUT WITH BED LION RUST AWAY.
- 3. SAND DOWN LEATHER IN SEALER TO GET READY TO PART WITH WHITE PAINT, PAINT ALL SPOTS ON TOP OF TRUCK AND BLEND IN BODY.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V60457

In Date: 09/12/2013
Close Date: 09/17/2013

Meter Reading: 104,835.00

Problem?

Replace steering box

Task performed:

Replaced steering box

Parts

Quantity

NO PARTS USED

Vendor? AL PACKER

Workorder: V61224

In Date: 10/12/2013
Close Date: 10/18/2013

Meter Reading: 52,736.00

Problem?

Replace front tires and L/R/I R/R/O

Task performed:

- CHECK FEDERAL Q- AS PER COMPLAIN OF NOT WORKING - UNABLE TO DUPLICATE FAULT - FEDERAL Q OPERATE WITH EMERGENCY LIGHT MASTER SWITCH ON ONLY.
- COMPLAIN OF PRIMER INOP - CHECK, ELECTRICAL CONNECTION, FUSE AND SWITCH, ALL SYSTEM WORKING NORMAL - UNABLE TO HAVE SYSTEM FAIL. SYSTEM WORKING NORMAL.

Parts

Quantity

NO PARTS USED

Workorder: V61227

In Date: 10/28/2013
Close Date: 10/31/2013

Meter Reading:

Problem?

Replace 4 tires

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN TIRE



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V61515

In Date: 10/25/2013

Meter Reading:

Close Date: 11/04/2013

Problem?

The driver's side wiper flew off while in use. It was temporarily fixed but needs to be replaced.

Task performed:

DRIVER COMPLAINT WIPERS 10-7 REPLACED
WIPER BLADES.

Parts

Quantity

91-20WIPER BLADE 20 IN

2

91-22WIPER BLADE

2

Workorder: V62088

In Date: 11/17/2013

Meter Reading:

Close Date: 11/21/2013

Problem?

Left headlight shines into the median. It needs to be brought more to the right. EMS 7

Task performed:

ADJUST FRONT LEFT HEAD LIGHT TO FACTORY
SPECTS. IS OK NOW. ALSO CHECK E73 FOR AIR
LEAKS CAPTAIN SEAT.

Parts

Quantity

NO PARTS USED

Workorder: V60280

In Date: 10/11/2013

Meter Reading: 106,170.00

Close Date: 12/19/2013

Problem?

B-inspection

Task performed:

B-inspection
Inspect brakes and rotate tires

Vendor? AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V64267

In Date: 02/16/2014

Meter Reading:

Close Date: 03/03/2014

Problem?

Auto ejector on back of vehicle not ejecting. EMS 7

Task performed:

AUTO EJECT INOP, WORN OUT REPLACED AUTO
EJECT.

Parts

Quantity

0915520120AUTO EJECT 20 AERO OTL3925

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V64327

In Date: 02/18/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

The rear white strobes do not work... Please check and make sure the rear brake, flashers and tail lights are working as they should be. ems 7

Task performed:

Parts

Quantity

1. REAR STROBES INOP, STROBE PACK FUSE HOLDER LOOSE. LOCATE STROBE PACK AND REPAIRED.

NO PARTS USED

2. REAR COMPARTMENT WILL NOT CLOSE, LATCH RODS BENT. REPAIRED RODS.

Workorder: V65008

In Date: 03/17/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

Auto eject not always ejecting. The truck had to be jumpstarted this morning after being unplugged for only 1 hour. EMS 3

Task performed:

Parts

Quantity

EDDIE SAID TRUCK WAS REPAIRED AT SHOP.

NO PARTS USED

Workorder: V65022

In Date: 03/18/2014

Meter Reading: 113,377.00

Close Date: 03/19/2014

Problem?

Auto eject inop

Task performed:

Parts

Quantity

COULD NOT FIND ANY PROBLEM. OK AT THIS TIME. CHECKED AND TESTED CONNECTION AT AUTO EJECT FOR STARTER CIRCUIT. REPLACED BATTERY FUSE HOLDER FOUND BURNT CUT OFF #2 BATTERY CHARGE WIRE CORRODED AT CHARGER AND CUT WIRE BACK AND REINSTALLED NO PROBLEM FOUND AUTO EJECT CIRCUIT.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V65412

In Date: 04/02/2014

Meter Reading: 114,802.00

Close Date: 04/02/2014

Problem?

B INSPECTION AL PACKER

Task performed:

B INSPECTION
FUEL FILTERS
REPAIRED A/C REPLACE AIR CLEANER ROTATE
TIRES

Vendor? AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V66650

In Date: 05/21/2014

Meter Reading: 117,206.00

Close Date: 05/22/2014

Problem?

No start

Task performed:

DRIVER COMPLAINT NO START REPLACED
BATTERIES AND CHECKED SHORE CHARGER OK.

Parts

Quantity

65-72BXT65750 BATTERY

2

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

2

Workorder: V66736

In Date: 05/25/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

Left rumbler speaker is loose. Hugo is going to do a temp fix.....

Task performed:

TRAVEL TO 73 REMOVED RUMBLER.

Parts

Quantity

NO PARTS USED

Workorder: V66737

In Date: 05/25/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

The locking system for the bed of the truck no longer works.

Task performed:

CHECKED LOCK ON BED WILL ORDER NEW LOCK.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V66900

In Date: 07/09/2014

Meter Reading:

Close Date: 07/09/2014

Problem?

The rumber is still hanging down from its bracket. It needs to be mounted to the bottom of the push bar.....

Task performed:

Parts

Quantity

1. removed rumber from truck broken.
2. fab, new braket for rumber and installed wired up test ck, ok.

HOWLERSIREN

1

Workorder: V67327

In Date: 06/18/2014

Meter Reading:

Close Date: 07/09/2014

Problem?

Rumbler disconnected EMS 7 Backup light OOS

Task performed:

Parts

Quantity

WORK COMPLETED ON V66900

NO PARTS USED

Workorder: V67798

In Date: 07/09/2014

Meter Reading: 102,526.00

Close Date: 07/11/2014

Problem?

No start

Task performed:

Parts

Quantity

Charge Batteries . Move vehicle to share time charger.

NO PARTS USED

Workorder: V67352

In Date: 06/20/2014

Meter Reading: 118,799.00

Close Date: 07/17/2014

Problem?

B inspection CAP 7

Task performed:

Parts

Quantity

B inspection repaired a/c system, replaced evap and accumulator

NO PARTS USED

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V69472

In Date: 09/18/2014
Close Date: 09/18/2014

Meter Reading: 116,376.00

Problem?

Replace seat covers

Task performed:

removed old seat covers tried two different styles none fit order custom covers.

Parts

NO PARTS USED

Quantity

Workorder: V69486

In Date: 09/18/2014
Close Date: 09/19/2014

Meter Reading: 118,808.00

Problem?

Replace floor liner

Task performed:

B-inspection
Replaced rubber mat
Replaced steering wheel
Replaced floor mats
Vendor? AL PACKER

Parts

NO PARTS USED

Quantity

Workorder: V69501

In Date: 09/19/2014
Close Date: 09/22/2014

Meter Reading:

Problem?

Right side orange marker light is out

Task performed:

replaced right side marker light tested ok.

Parts

19275RLAMP LED RED

19275YLAMP LED AMBER

Quantity

1

1

Workorder: V69483

In Date: 09/18/2014
Close Date: 10/14/2014

Meter Reading: 116,376.00

Problem?

Remount bracket in I-1 compt

Task performed:

Repair hydrant wrench mount in L-1 compartment. Replace SMS with nut and bolt set up. Repair wiring at front howler sirens. Replace 3 emergency light lenses.

Parts

6819634283068-1963428-30 LENS CLR

Quantity

3



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V70808

In Date: 11/09/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Right rear tail light is out. We could use new windshield wipers as well... EMS 7

Task performed:

Parts

Quantity

1. Check up back up light out-found bulb bad power and ground Ok. Order new light.
2. R/R wiperblades 20"

91-20WIPER BLADE 20 IN

4

Workorder: V71557

In Date: 12/10/2014

Meter Reading: 123,328.00

Close Date: 12/29/2014

Problem?

install seat covers

Task performed:

Parts

Quantity

Installed seat covers

F419-C3SEAT COVER

1

FRT 65616FREIGHT CHARGE

1

Workorder: V70216

In Date: 10/17/2014

Meter Reading: 122,381.00

Close Date: 01/23/2015

Problem?

Right rear backup light and tail light out

Task performed:

Parts

Quantity

1. Travel to station 73. R & R back up lights and repair light rewire.

45204BACKUP LIGHT

2

Workorder: V73957

In Date: 03/17/2015

Meter Reading: 129,103.00

Close Date: 03/17/2015

Problem?

B-inspection

Task performed:

Parts

Quantity

B-inspection
Wiper blades

NO PARTS USED

Vendor? AL PACKER



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175539

F-350 XLT SUPERDUTY TRUCK EMS OR RESCUE

Workorder: V74641

In Date: 04/13/2015
Close Date: 04/14/2015

Meter Reading: 130,299.00

Problem?
coolant leak

Task performed:

Parts ----- Quantity

NO PARTS USED

Vendor? AL PACKER

Workorder: V74570

In Date: 04/10/2015
Close Date: 05/08/2015

Meter Reading: 130,299.00

Problem?
Coolant leak

Task performed:

Parts ----- Quantity

1. Travel to ST-73. Check out derate and over heat temp guage high. Check and fill coolant. Test drive unit radiator leaking. Swap out truck, bring driver to shop.

NO PARTS USED



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10175539) 2008 - FORD F350 Truck Ems Or Rescue Captain Vehicle

10175539

CSHOP-2015-1273

Date Opened 6-19-2015 Date Finished 6-19-2015 Meter 1 Reading: 133,263

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

VENDOR? AL PACKER

CSHOP-2015-1692

Comments: **TAILLIGHT COVER REQUIRES REPLACEMENT. METAL COVER RUSTED WITH HOLES EMS73**

Date Opened 7-10-2015 Date Finished 8-5-2015 Meter 1 Reading: 133,263

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIGHT; 60151 GROTE T/L 26330 TAG LIGHT

CSHOP-2015-2066

Comments: **PASS. MIRROR RUSTED OUT EMS 7**

Date Opened 8-3-2015 Date Finished 8-6-2015 Meter 1 Reading: 133,263

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
MIRRORS

1 MIRROR ASSY L/S
1 MIRROR ASSY R/S

CSHOP-2015-2699

Date Opened 9-3-2015 Date Finished 9-8-2015 Meter 1 Reading: 133,263

TASKS PERFORMED

NO PARTS USED

MIRRORS

CSHOP-2015-4526

Comments: **REPAIR ACCIDENT DAMAGE**

Date Opened 12-17-2015 Date Finished 12-17-2015 Meter 1 Reading: 133,263

TASKS PERFORMED

NO PARTS USED

BODY DAMAGE ACCIDENT

VENDOR? SOUTHEAST TRUCK

Asset Work Order History 10175539

CSHOP-2015-4616

Comments: **SMES73 B INSPECTION**

Date Opened 12-23-2015 Date Finished 12-23-2015 Meter 1 Reading: 136,340

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2015-742

Comments: **ENGINE OVERHEATING**

Date Opened 5-20-2015 Date Finished 5-20-2015 Meter 1 Reading: 132,155

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

VENDOR? AL PACKER

CSHOP-2015-906

Comments: **CHECK ENGINE LIGHT ON, TRUCK RUNS BUT SEEMS ROUGH**

Date Opened 6-1-2015 Date Finished 6-3-2015 Meter 1 Reading: 132,155

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2016-1230

Comments: **EMS73**

Date Opened 3-15-2016 Date Finished 3-20-2016 Meter 1 Reading: 136,578

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM
BATTERY

1 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

03/14/2016 LIGHTS / 19: LOOSE / REPAIR
PASSENGER HEADLIGHT OOS

CSHOP-2016-1248

Comments: **STARTER NOT WORKING INTERMITTENTLY**

Date Opened 3-15-2016 Date Finished 3-17-2016 Meter 1 Reading: 136,548

TASKS PERFORMED

Q PARTS

STARTER

1 STARTER; STARTER

Asset Work Order History 10175539

CSHOP-2016-1593

Comments: EMS73

Date Opened 4-4-2016 Date Finished 4-15-2016 Meter 1 Reading: 138,027

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM

Service Requests:

04/04/2016 ALARMS / 12: BROKEN / LUBRICATE
WHILE PLUGGED IN THE BATTERY LIGHTS (ON THE REAR) WON'T COME ABOVE 2 BARS.

CSHOP-2016-4881

Date Opened 10-12-2016 Date Finished 10-12-2016 Meter 1 Reading: 139,970

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-5349

Comments: EMS73

Date Opened 11-15-2016 Date Finished 12-1-2016 Meter 1 Reading: 142,645

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

1 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

11/15/2016 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING. LEFT HEADLIGHT IS NOT WORKING.

CSHOP-2016-56

Date Opened 1-5-2016 Date Finished 1-5-2016 Meter 1 Reading: 136,340

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10175539

CSHOP-2016-5671

Date Opened 12-5-2016 Date Finished 12-19-2016 Meter 1 Reading: 143,526

TASKS PERFORMED

Q PARTS

REAR DOOR LATCH ASSEMBLY
WIPER BLADES

2 WIPER; WIPER BLADE

Service Requests:

12/03/2016 DOOR / 11: BINDS/STICKS / INSPECT
VEHICLE DOORS: FRONT/FORWARD PASSENGER SIDE COMPARTMENT DOOR WHEN CLOSED DOES NOT ALWAYS CATCH AS THE OTHER COMPARTMENT DOORS DO. IT LOOKS CLOSED BUT SOMETIMES IS ACTUALLY STILL OPEN.

CSHOP-2016-6128

Comments: **SPARE EMS TRUCK AT 28**

Date Opened 12-30-2016 Date Finished 1-4-2017 Meter 1 Reading: 144,834

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

Service Requests:

12/30/2016 SERVICE REQUEST / 38: SHORTED / REPAIR
TIC CHARGER ON EMS 28 SPARE TRUCK 10175539, NOT CHARGING TIC OR BACK UP BATTERY

CSHOP-2017-1262

Date Opened 3-1-2017 Date Finished 3-1-2017 Meter 1 Reading: 147,786

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-2846

Date Opened 5-15-2017 Date Finished 6-5-2017 Meter 1 Reading: 153,060

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT
ELECTRICAL

1 6KU; AUTO EJECT 20A

Service Requests:

05/14/2017 SERVICE REQUEST / 23: NOT CONNECTED / REPAIR
THE TIC CHARGER HAS NO POWER GOING TO IT.

05/14/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST THE AUTO EJECT FOR THE SHORE LINE APPEARS TO BE JAMMED AND IS NOT WORKING.

05/18/2017 SERVICE REQUEST / 11: BINDS/STICKS / EXCHANGE - NEW
SERVICE REQUEST AUTO EJECT

Asset Work Order History 10175539

CSHOP-2017-3021

Comments: **SPARE EMS TRUCK AT STATION 28**
Date Opened 5-22-2017 Date Finished 5-30-2017 Meter 1 Reading: 152,827

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

Service Requests:

05/22/2017 ENGINE / 12: BROKEN / REPAIR
ENGINE. AUTO EJECT IS NOT WORKING WHEN YOU START THE TRUCK

CSHOP-2017-3051

Comments: **SPARE EMS AT 28**
Date Opened 5-23-2017 Date Finished 6-8-2017 Meter 1 Reading: 153,060

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS

Service Requests:

05/23/2017 LIGHTS / 10: BENT / REPAIR
PLEASE MOVE OR ADJUST THE FRONT BUMPER LED EMERGENCY LIGHTS. THE LIGHT BRACKET FOR THE EMERGENCY LIGHTS IS OLD AND BENT DOWN PUTTING THE EMERGENCY LIGHTS IN A POSITION OF THEM NOT BEING VISIBLE.

CSHOP-2017-3138

Date Opened 5-30-2017 Date Finished 5-31-2017 Meter 1 Reading: 153,060

TASKS PERFORMED

NO PARTS USED

A/C CONDENSER FAN

CSHOP-2017-3269

Date Opened 6-5-2017 Date Finished 6-8-2017 Meter 1 Reading: 153,060

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT
ELECTRICAL

Service Requests:

06/04/2017 SERVICE REQUEST / 38: SHORTED / REPAIR
THE TIC AND FLASH LIGHT CHARGER ARE NOT GETTING ANY POWER TO CHARGE THEM. THIS HAS BEEN FIXED TWICE IN THE LAST TWO WEEKS AND IS NOT NOT WORKING AGAIN. CAN YOU PLEASE CHECK THE TRUCKS ELECTRICAL SYSTEM SINCE THE FUSES KEEP GOING ON THESE CHARGERS. THIS APPEARS TO BE MORE THEN A FUSE PROBLEM.

06/04/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
THE SHORE LINE AUTO EJECT IS NOT WORKING AGAIN. I BELIEVE IT IS NOT WORKING BECAUSE OF THE ELECTRICAL SHORT CAUSING THE TIC AND FLASHLIGHT NOT CHARGING. PLEASE DO A PROPER ELECTRICAL DIAGNOSTIC AND NOT JUST REPLACE ANOTHER FUSE THAT WILL ONLY LAST A DAY OR TWO.

Asset Work Order History 10175539

CSHOP-2017-3374

Date Opened 6-8-2017 Date Finished 6-8-2017 Meter 1 Reading: 153,060

TASKS PERFORMED

NO PARTS USED

BRAKE LIGHTS

Service Requests:

06/08/2017 LIGHTS / 38: SHORTED / REPAIR
VEHICLE LIGHTS NOT WORKING: THE LEFT BRAKE LIGHTS ARE VERY DIM AND IN A CONTINUOUS FAST FLASH JUST AS IF THE TURN SIGNAL IS ON.

CSHOP-2017-3667

Date Opened 6-21-2017 Date Finished 6-22-2017 Meter 1 Reading: 154,716

TASKS PERFORMED

NO PARTS USED

AUTO-EJECT
AIR CONDITIONING

CSHOP-2017-3687

Date Opened 6-22-2017 Date Finished 7-26-2017 Meter 1 Reading: 155,705

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FRONT TIRES

Service Requests:

06/22/2017 TIRES / 44: WORN / INSPECT
BAD TIRES. VEHICLE NEEDS NEW TIRES, ESPECIALLY LEFT FRONT.

Asset Work Order History 10175539

CSHOP-2017-4050

Date Opened 7-10-2017 Date Finished 10-5-2017 Meter 1 Reading: 160,238

TASKS PERFORMED

Q PARTS

COMMERCIAL WORK - OUTSIDE AGENCY

QUARTZ LIGHT

IGNITION SWITCH

BATTERY CABLE

TIRE

REPAIR FROM PM - DECALS/CLEANLINESS

1	9AP; ALLY LIGHT
1	1WL; 500 SERIES LED RED/CLEAR
1	1WL; 500 SERIES LED RED/CLEAR
2	9IP; VERTEX SINGLE RED

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

07/10/2017 TIRES / 12: BROKEN / REPAIR
BAD TIRES

07/10/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST. IGNITION SWITCH IS BROKEN AND STICKS WHEN YOU START THE VEHICLE.

07/10/2017 SERVICE REQUEST / 46: LOST OR MISSING / REPAIR
PLEASE REMOVE THE PROUDLY SERVING THE GLADES DECALS AND STA 73 DECALS ON THE SIDES AND REAR OF THE TRUCK. THANKS.

07/10/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING. THE EMERGENCY LIGHT BAR ON THE ROOF OF THE VEHICLE HAS SOME LIGHTS NOT WORKING. CAN YOU PLEASE REPLACE THE RED LED'S WHILE IT IS IN THE SHOP FOR PM AND REPAIRS. THANKS.

CSHOP-2017-4101

Date Opened 7-12-2017 Date Finished 7-12-2017 Meter 1 Reading: 155,705

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-5151

Comments: **SHORELINE CHARGER ONLY SHOWING 1 BAR**

Date Opened 9-1-2017 Date Finished 1-3-2018 Meter 1 Reading: 164,973

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

SHORELINE CHRAGER

Service Requests:

09/01/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SERVICE REQUEST. VEHICLE IS NOT CHARGING PROPERLY WHEN PLUGGED INTO SHORELINE.

Asset Work Order History 10175539

CSHOP-2017-521

Comments: **SPARE EMS 6 AT STATION 28 EMERGENCY LIGHTS NOT WORKING. MAKE NEW SHORELINE [LUIS]**

Date Opened 1-24-2017 Date Finished 2-6-2017 Meter 1 Reading: 146,749

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS

1 TDS; PIAA RELAY

Service Requests:

01/23/2017 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING - FOG LIGHTS DO NOT WORK. ALSO HEAD LIGHTS NEED ADJUSTING. DRIVER SIDE POINTS ALMOST DIRECTLY IN FRONT OF THE VEHICLE AT THE GROUND

CSHOP-2017-5617

Comments: **SPARE EMS AT STATION 28**

Date Opened 9-27-2017 Date Finished 11-30-2017 Meter 1 Reading: 163,139

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHT BAR

4 9IP; RED MARKER LIGHT RECTANGULAR

Service Requests:

09/27/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING. ONE OF THE ROOF MARKER LIGHTS IS OUT. ONE OF THE SMALL MARKER LIGHTS UNDER THE TAIL GATE IS MISSING THE LENS COVER. THE TRUCK IS ALSO 800 MILES FROM NEEDING PM DONE.

CSHOP-2017-5873

Date Opened 10-11-2017 Date Finished 10-24-2017 Meter 1 Reading: 160,860

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Service Requests:

10/11/2017 SERVICE REQUEST / 13: CHIPPED / INSPECT
SERVICE REQUEST VEHICLE DUE FOR PM

10/11/2017 TIRES / 44: WORN / INSPECT
BAD TIRES. THERE IS A SCREW IN THE DRIVER SIDE REAR TIRE. THE TIRE IS NOT FLAT YET BUT LOW ON AIR. ALSO ALL 4 REAR TIRES ARE ALMOST AT THE WEAR BARS AND NEED TO BE REPLACED. THE TIRES WERE PUT IN SEVERAL MONTHS AGO AND ONLY THE TWO FRONT TIRES WERE REPLACED AND NOT THE REAR TIRES.

10/11/2017 BRAKES / 44: WORN / INSPECT
BRAKE ISSUES. THE TRUCK WAS JUST PICKED UP BY SHOP PERSONNEL FOR PM AND TIRES. THE BRAKES WERE STARTING TO FEEL SOFT WHEN PUSHING THE BRAKE PEDAL. CAN YOU PLEASE CHECK THE BRAKES WHILE IT IS IN PM

Asset Work Order History 10175539

CSHOP-2017-6019

Date Opened 10-18-2017 Date Finished 10-18-2017 Meter 1 Reading: 160,775

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-6271

Comments: **THROTTLE STICKING**

Date Opened 10-30-2017 Date Finished 11-2-2017 Meter 1 Reading: 161,148

TASKS PERFORMED

NO PARTS USED

THROTTLE CONTROLS

CSHOP-2017-6720

Date Opened 11-21-2017 Date Finished 11-22-2017 Meter 1 Reading: 162,583

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY 65 SEVERE DUTY
1 6KU; AC2000 12V PLC (TEN-8)

Service Requests:

11/21/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
AUTO EJECT IS NOT WORKING AND VEHICLE IS NOT CHARGING WHEN PLUGGED IN.

CSHOP-2018-1156

Date Opened 2-26-2018 Date Finished 2-26-2018 Meter 1 Reading: 168,014

WARNING LIGHT INOP.

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

1 1WL; LIGHT LED RED TIR6

CSHOP-2018-1213

Date Opened 2-28-2018 Date Finished 2-28-2018 Meter 1 Reading: 168,039

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2018-1471

Comments: **ENGINE OVERHEAT**

Date Opened 3-12-2018 Date Finished 3-12-2018 Meter 1 Reading: 169,063

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Asset Work Order History 10175539

CSHOP-2018-1682

Date Opened 3-26-2018 Date Finished 3-28-2018 Meter 1 Reading: 169,064

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM

Service Requests:

03/25/2018 SERVICE REQUEST / 43: WEAK / INSPECT
WHEN SPARE EMS 28 IS PLUGGED INTO SHORE POWER, THE AUTO CHARGER LIGHT BARS DO NOT LIGHT UP.
CHARGING LIGHTS WORKED EARLIER TODAY.

CSHOP-2018-1770

Date Opened 3-29-2018 Date Finished 3-29-2018 Meter 1 Reading: 169,072

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? AL PACKER

CSHOP-2018-269

Comments: **SPARE EMS AT 28**

Date Opened 1-12-2018 Date Finished 1-17-2018 Meter 1 Reading: 165,708

TASKS PERFORMED

NO PARTS USED

TURN SIGNAL LIGHTS

Service Requests:

01/12/2018 LIGHTS / 38: SHORTED / REPAIR
VEHICLE LIGHTS NOT WORKING. LEFT FRONT TURN SIGNAL NOT WORKING.

CSHOP-2018-3072

Date Opened 6-4-2018 Date Finished 6-4-2018 Meter 1 Reading: 171,214

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? AL PACKER

CSHOP-2018-3723

Date Opened 7-2-2018 Date Finished 7-2-2018 Meter 1 Reading: 171,228

TASKS PERFORMED

NO PARTS USED

OIL

VENDOR? AL PACKER

Asset Work Order History 10175539

CSHOP-2018-6150

Date Opened 10-29-2018 Date Finished 12-21-2018 Meter 1 Reading: 171,323

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
BATTERY
HOOD

12 9AP; BRAKE CLEAN
1 GRO; CLAMPS
2 1AD; 65 SERIES BATTERY
2 1FD; HOOD SHOCKS

CSHOP-2018-7148

Date Opened 12-17-2018 Date Finished 12-28-2018 Meter 1 Reading: 171,323

TASKS PERFORMED

NO PARTS USED

OIL PAN-GASKET

VENDOR? AL PACKER

RADIO-2017-519

Comments: **COMPLETED**

Date Opened 8-18-2017 Date Finished 8-18-2017 Meter 1 Reading: 156,940

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

08/04/2017 RADIO / /
RADIO ISSUES, NEED UNIVERSAL MDC BASE INSTALLED TO ACCOMMODATE LARGER GETAC S-EMS-6
