



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V074

In Date: 10/06/2005
Close Date: 10/14/2005

Meter Reading:

Problem?

O2 LEAK R-24

Task performed:

Parts	Quantity
M54-13SPM5413 NIPPLE	1

Workorder: V407

In Date: 11/01/2005
Close Date: 11/02/2005

Meter Reading:

Problem?

door alarm comes on intermittently

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V425

In Date: 11/02/2005
Close Date: 11/07/2005

Meter Reading: 63,027.00

Problem?

front strobe out r24

Task performed:

Parts	Quantity
508RED58EC20RU STROBE-RED SURFACE MOUNT	1

Workorder: V421

In Date: 11/02/2005
Close Date: 11/10/2005

Meter Reading: 63,215.00

Problem?

D/SIDE STROBE LIGHT INOP, R-24

Task performed:

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V749

In Date: 11/29/2005

Meter Reading:

Close Date: 12/02/2005

Problem?

CHECK ENGINE LITE ON,, R-24

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V784

In Date: 12/02/2005

Meter Reading:

Close Date: 12/14/2005

Problem?

A INSPECTION R24 SPARE

Task performed:

Parts

Quantity

194BULB

10

Workorder: V1081

In Date: 12/30/2005

Meter Reading:

Close Date: 01/04/2006

Problem?

A inspection (back from 33)

Task performed:

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB

1

18-20141-000WASHER

3

HLD374211 IN HOLD-OPEN 30LB

1

Workorder: V1309

In Date: 01/26/2006

Meter Reading:

Close Date: 01/31/2006

Problem?

INSTALL TAG, R-24

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1394

In Date: 02/03/2006

Meter Reading:

Close Date: 02/15/2006

Problem?

A INSPECTION SPARE R55

Task performed:

Parts

Quantity

4020362171 GRO LAMP DOME 4 IN

2

91513AMBER LENS

2

Workorder: V1393

In Date: 02/02/2006

Meter Reading:

Close Date: 02/23/2006

Problem?

A INSPECTION R55 SPARE

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1533

In Date: 02/16/2006

Meter Reading:

Close Date: 03/09/2006

Problem?

AIR LEAK, R-14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1796

In Date: 03/09/2006

Meter Reading:

Close Date: 03/10/2006

Problem?

A INSPECTION SPARE R72

Task performed:

Parts

Quantity

52-24WIPER BLADES ANCO 24

2

LTC594211657-16 LATCH L/H MEDIC MASTER

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1857

In Date: 03/15/2006

Meter Reading:

Close Date: 03/15/2006

Problem?

AIR HORN INOP, R-45

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1626

In Date: 02/24/2006

Meter Reading:

Close Date: 03/20/2006

Problem?

A INSPECTION R14 SPARE

Task performed:

Parts

Quantity

3157TAIL LIGHT BULBS

1

PSP5911CIRCUIT BOARD 21

1

Workorder: V1826

In Date: 03/13/2006

Meter Reading:

Close Date: 03/28/2006

Problem?

REAR SIGNAL INDICATOR INOP, E-45

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1981

In Date: 03/27/2006

Meter Reading:

Close Date: 04/07/2006

Problem?

A INSPECTION SR-7

Task performed:

Parts

Quantity

0106837849C8COMP LIGHT WHITE LED 200

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2208

In Date: 04/12/2006
Close Date: 04/28/2006

Meter Reading: 67,300.00

Problem?

B INSPECTION, SR-7

Task performed:

See B Inspection pre-printed form

Parts	Quantity
BOS62221360026222207-001 W AIR SEAT	1
ESX120105112STARTER RELAY ESX-120-105112	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1

Vendor? CENT0002

Workorder: V2624

In Date: 05/15/2006
Close Date: 05/18/2006

Meter Reading: 68,130.00

Problem?

A INSPECTION, SR-7 (BACK FROM STA-33)

Task performed:

Parts	Quantity
4870JBR4870JBR ALTERNATOR 270A	1
6809880678STUD DZ	2
6809940145CLIP	2

Workorder: V2898

In Date: 06/07/2006
Close Date: 06/12/2006

Meter Reading:

Problem?

A INSPECTION, SR-7 (BACK FROM STA-31)

Task performed:

Parts	Quantity
NO PARTS USED	



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3852

In Date: 08/09/2006

Meter Reading:

Close Date: 08/23/2006

Problem?

Right Rear Flashing Light Cover on R35 is missing or broken. Needs to be replaced.

Task performed:

Parts

Quantity

68118313250OBSOLETE REPLACE UNIT LENS RED 97 E S

1

Workorder: V4138

In Date: 08/27/2006

Meter Reading:

Close Date: 08/31/2006

Problem?

the brake fluid is low, marker lights are out, rearlight bar has strobe light out, belts are squeaking when the rescue is running down the road off and on. R35

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4140

In Date: 08/27/2006

Meter Reading:

Close Date: 08/31/2006

Problem?

The side exterior patient compartment door handlebroke in half. The door can only be opened from the inside. R35

Task performed:

Parts

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V4395

In Date: 09/12/2006
Close Date: 09/25/2006

Meter Reading: 69,266.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR7 BACKFROM 35

Task performed:

1. A- INSPECTION.
2. R/R HORNS.
3. R/R LF ROOF MARKER AND R/R ROOF CLEARANCE BULBS.
4. REPLACCE TRAFFIC ARROW BULB.
5. R/R R WINDSHIELD NOZZEL.
6. REPLACED AUTO-EJECT.
7. REPLACED 110V A/C CONDENSER FANS.
8. CHARGE A/C & CHECK FOR LEAKS, NONE FOUND.
9. R/R R REAR OUTSIDE WHEEL & FIXED AIR LEAK AT STEM.
- 10 CHECKED COMPUTER CODES FOR ENGINE AND TRANI, EARSE CODES.

Parts

Quantity

0915520120AUTO EJECT 20 AERO OTL3925	1
29509637USE 29643432 SENSOR SPEED	1
60027FAN A/C COND 12IN 860026-2-W	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
H20SN12H20SN12 BULB	1
SPRGW251WASHER NOZZLE	1

Workorder: V4497

In Date: 09/20/2006
Close Date: 10/10/2006

Meter Reading: 69,266.00

Problem?

REPAIR FLAT AT SHOP CALLAGHAN ENT SR7

Task performed:

1. REPAIR FLAT AT SHOP/ CALL CALLAGHAN ENT SR7

Parts

Quantity

NO PARTS USED

Workorder: V5088

In Date: 10/25/2006
Close Date: 11/06/2006

Meter Reading: 69,698.00

Problem?

AINSPECTION AND REPAIRS AS NEEDED SR7 BACK FROM 32

Task performed:

1. "A" inspection
2. replace wiper blades
3. replace a/c door
4. replace door shocks in pt compartment

Parts

Quantity

52-24WIPER BLADES ANCO 24	2
HLD3999GSS1715UV 30LB STRUT GAS	2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5606

In Date: 11/29/2006
Close Date: 12/04/2006

Meter Reading: 6,623.50

Problem?

small oil leak under front of r33. level is fine. may need to inspect when this spare is returned. thanks, dan sr2 at 33

Task performed:

drive to sta. check r33 for oil leak, blow by only

Parts

NO PARTS USED

Quantity

Workorder: V6218

In Date: 01/11/2007
Close Date: 01/16/2007

Meter Reading: 70,118.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED SR7

Task performed:

1. B Inspection
2. Serviced air dryer
3. Replaced front and rear brakes
4. Replaced rear shocks
5. Replaced batteries and cleaned all conections
6. Replaced light bar strobe and l/f marker

Parts

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT 1
 02038332800REFLECTOR 1
 11-26521487 SWITCH NC O 340 - C 210 HIGH PRESS 1
 112028SWITCH LOW PRESSURE 1
 161657700065489 SHOCK REAR NEW RESCUE 2
 281288HOSE AND FITTINGS 1
 52-24WIPER BLADES ANCO 24 2
 A0631087000CABLE BATT. POS. 1
 A0631088000CABLE BATT. NEG. 1
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF 4
 CA8193AIR FILTER 46744 WIX 1
 HP-31DBATTERY 950CCA HP-31D 4
 L1261F33585XE FUEL FILTER WIX 1
 MK184HDBRAKE PADS 2
 PH8942FILTER OIL 57182 LFP3729 1
 RN60JDRYER KIT 1
 S3225PFUEL FILTER 33630 LFF5849 1
 UMVS056511STRAP 1
 UMVS111611STRAP 2
 UNT7744USE PINK A/C FILTER MEDIC MASTER 1

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6759

In Date: 02/14/2007

Meter Reading: 6,686.20

Close Date: 02/22/2007

Problem?

right strobe light is out in the rear light bar.

Task performed:

1. TRAVELED TO STN 35. REPAIRED BAD CONNECTION IN STROBE WIRE.
2. MARKER LIGHTS INOP. REPAIRED GROUND WIRE, TEST/ OK.
3. REPAIRED BROKEN WIRE ON LEFT REAR ROTATOR.

Parts

Quantity

NO PARTS USED

Workorder: V6777

In Date: 02/15/2007

Meter Reading: 6,691.00

Close Date: 02/26/2007

Problem?

Passenger side running lights sr7 at 35

Task performed:

REPAIR MARKER LIGHTS

Parts

Quantity

NO PARTS USED

Workorder: V6953

In Date: 02/27/2007

Meter Reading: 70,909.00

Close Date: 03/07/2007

Problem?

a inspection and repairs as needed back from 35

Task performed:

1. A Inspection
2. Low coolant added as needed and pressure check
3. L4 door seal missing clean and install new seal
4. Replaced door latches and hold opens
5. Rear lightbar strobe out. R&R bad strobe
6. Filled washer tank
7. Steering wheel tilt will not lock. Removed column and replaced stripped gear assembly. Reassembled and test ok
8. Fuel leak at filter housing drain. Remove housing and replaced drain. Reassemble and test ok

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT

1

3926759-SDRAIN KIT

1

FREIGHTSHIPPING CHARGES

1

HLD3999GSS1715UV 30LB STRUT GAS

1

LTC5993SSM1-63-8 LATCH STAINLESS

2

RGT-475224X1SUPPORT BRACKET

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7214

In Date: 03/15/2007
Close Date: 03/16/2007

Meter Reading: 71,358.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR7 BACK FROM 41

Task performed:

Parts

Quantity

1. A Inspection
2. Repaired patient compartment dome lights

NO PARTS USED

Workorder: V7699

In Date: 04/13/2007
Close Date: 04/16/2007

Meter Reading: 71,551.00

Problem?

A inspection and related repairs (back from sta 23)

Task performed:

Parts

Quantity

1. A Inspection
2. Clean and service patient compt. e-core
3. Replaced high speed fan connector burned replaced
4. Repaired compt. door latch

NO PARTS USED

Workorder: V7635

In Date: 04/11/2007
Close Date: 04/26/2007

Meter Reading: 71,551.00

Problem?

ON CALL DOOR ALARM GOING OFF

Task performed:

Parts

Quantity

Rem door ajar display & repair connections.
All door switches-ok.

NO PARTS USED

Workorder: V8105

In Date: 05/04/2007
Close Date: 05/15/2007

Meter Reading: 6,821.00

Problem?

CAN NOT GET DOOR OPEN WARNING LIGHT AND AUDIBLE ALARM IN CAB OF SPARE R52 TO GO OFF. IT IS ON THE ENTIRE TIME YOUR DRIVING. THERE ARE NO DOORS OPEN.

Task performed:

Parts

Quantity

Found no problem

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8465

In Date: 05/29/2007 Meter Reading: 72,561.00
Close Date: 06/05/2007

Problem?

adjust steering wheel sr7 at 34

Task performed:

Parts

Quantity

1. R&R steering wheel to center, clean hands free button contacts

NO PARTS USED

Workorder: V8195

In Date: 05/10/2007 Meter Reading: 72,069.40
Close Date: 06/06/2007

Problem?

A inspection and related repairs (back from 52)

Task performed:

Parts

Quantity

- 1. A-Inspection, adjust air horns
- 2. Replace L&R side marker/turn assemblies
- 3. Replace belt tensioner
- 4. Remove dash and free up defroster cable

39768315259022 GROOVED TENSIONER OLD#3936213
40202RT/L#40202R RED TAIL LIGHT

1
2

Workorder: V8529

In Date: 06/01/2007 Meter Reading: 72,708.00
Close Date: 06/14/2007

Problem?

A inspection and repairs as needed sr7 back from 34

Task performed:

Parts

Quantity

- 1. Perform "A" service
- 2. Replaced wiper blades, cleaned debris from window & topped off resevoir

52-24WIPER BLADES ANCO 24

2

Workorder: V8064

In Date: 05/03/2007 Meter Reading: 6,821.00
Close Date: 07/05/2007

Problem?

rescue 52 spare door alarm keeps sounding with all doors shut!!! Thanks

Task performed:

Parts

Quantity

Replc MOD display for door

SWT5924DOOR OPEN MAP DISPLAY

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9340

In Date: 07/16/2007 Meter Reading: 972.00
Close Date: 07/19/2007

Problem?

PSI gauge on the main O2 tank is broken. R17

Task performed:

1. DRIVE TO STA. R&R OXYGEN GAUGE. TEST FOR LEAK. NONE FOUND.

Parts

MG-C23SPMGC23 GAUGE

Quantity

1

Workorder: V9388

In Date: 07/17/2007 Meter Reading: 972.00
Close Date: 07/20/2007

Problem?

Rear A/C blows cold air but does not cool the patient compartment effectly. Truck was running for almost 2 hours on a call/transpc & temp did not get below 78.(this is a spare truck)

Task performed:

1. DRIVE TO STA. FILL WITH FREON. CHECK FOR LEAKS. TIGHTEN FITTING AND HOSE CLAMPS. TEST-OK.

Parts

NO PARTS USED

Quantity

Workorder: V9545

In Date: 07/25/2007 Meter Reading: 72,814.00
Close Date: 07/31/2007

Problem?

A inspection and related repairs (back from 17)

Task performed:

1. A INSPECTION.
2. R&R SHARPS LID. R&R SIDE DOOR HANDLE ASSY AND ADJUST.
3. REPLACE ROCKER SWITCHES IN REAR OF TRUCK. R&R REFLECTOR ON REAR DOOR.

Parts

98003RREFLECTOR RED 40132 GROTE

DOOR2LEXAN 14.5 X 8.5

HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING

M54-13SPM5413 NIPPLE

SWT5492744435 ACTUATOR-BLACK

Quantity

1

1

1

1

3

Workorder: V10317

In Date: 09/07/2007 Meter Reading: 73,613.00
Close Date: 09/26/2007

Problem?

A inspection and related repairs (back from 42)

Task performed:

1. PERFORM "A" SERVICE

Parts

NO PARTS USED

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11105

In Date: 10/18/2007
Close Date: 10/23/2007

Meter Reading: 7,023.00

Problem?

Pt. compartment passanger side, front amber clearance light out. Rear traffic adviser light bar, two right rights, not working. sr7 at

Task performed:

Parts

Quantity

1. repaired lights for marker lights
2. traced out problem with traffic control adviser. found control head bad.

NO PARTS USED

Workorder: V11417

In Date: 11/03/2007
Close Date: 11/14/2007

Meter Reading: 7,065.00

Problem?

Check engine light came on at approx. 2200 hrs, 11/3/2007; truck continuing to function normally other than air leak in compressor or air line(s). SR7 AT 35

Task performed:

Parts

Quantity

1. Cleared codes in Comp.
2. Adjusted rear air bags and road tested.
3. Installed 110 cord in station for 110 A/C on recsue.

NO PARTS USED

Workorder: V11450

In Date: 11/05/2007
Close Date: 11/14/2007

Meter Reading: 7,084.10

Problem?

the steering wheel tilt is broken. The steering wheel moves up and down. sr7 at 35

Task performed:

Parts

Quantity

1. Repaired steering colum that was lose.
2. Adjusted rear air bags to make rear of rescue level.

NO PARTS USED

Workorder: V11406

In Date: 11/02/2007
Close Date: 11/15/2007

Meter Reading: 7,065.00

Problem?

the engine has a loose belt. the right front light bar has a strobe out. The rear air dump has an air leak. Everytime the unit is off the rear of the unit dumps and it delays response waiting for the air to fill back up SR7 AT 35

Task performed:

Parts

Quantity

1. Adjusted belts to A/C.
2. Checked for air leaks found none at this time.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11518

In Date: 11/08/2007

Meter Reading: 75,026.00

Close Date: 11/15/2007

Problem?

a inspection and repairs as needed sr7 back from 35

Task performed:

1. Clean shop work area, Pick up rescue from station 35
2. Road test and Inspection
3. Pacent Comp. A/C blowing cool- diagnose problem repair. Cab A/C cool diagnose problem and repair. Units low on coolant, no leak found, A/C cume system, change systems and check pressure.
4. Front light bar strobes, trtraffic, adviser lights, map light Inop. Remove blown strobe light install new strtobe asseembly, traffic adviser had bad ground clean adn secure ground cable, marker light bulb ground corosive build up clean contact points.
5. All 3 belts needed remove and ionstall new belts.
6. Disaplenary meeting with Tim E.O., Mike L
7. A/C snapon vacline freeon tank low on freeon, refill tank.
8. Windshield and window part on molding missing- remove parts and install new part.

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1
1829601000LHINGE PILLAR RESCUE	1
22-43808-000HARDLINE A/C	1
546085303NC SWITCH/BRACKT	1
716907-0610A DRYER	1
9451BELT	1
9485BELT	1
A2245482000 12-0615A VALVE EXPANSION FTRLNR 1606	1
K080733BELT	1
REFINISHPAINT FL PILLAR	1

Workorder: V11814

In Date: 11/29/2007

Meter Reading: 75,026.00

Close Date: 12/04/2007

Problem?

b inspectinon and repairs as needed sr7

Task performed:

1. B INSPECTION
2. REPLACED STEERING STOP
3. SERVICED AIR DRYER
4. TORQUED U-BOLTS
5. TRACED COOLENT LEAK THROUGH R-1 COMPARTMENT TO CONTROL VALVE IN PAT. COMPT. REPAIRED HOSE AND REPLACED HOSE CLAMP
6. REPLACED O-2 WRENCH
7. REPAIRED MARKER AND CLEARENCE LIGHTS

Parts

Quantity

194BULB	10
AS75807OXM1757-01 OXYGEN WRENCH	1
CA8193AIR FILTER 46744 WIX	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
TDA26X1017BOLT STR STOP	1
V122XARESCUES MARKER LIGHT	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6715

In Date: 02/12/2007

Meter Reading: 70,633.00

Close Date: 01/08/2008

Problem?

1 light out in rear light bar (R35)

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V6718

In Date: 02/12/2007

Meter Reading: 6,678.40

Close Date: 01/14/2008

Problem?

Passenger side upper red strobe out on light bar. sr7 at 35

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V7636

In Date: 04/11/2007

Meter Reading: 71,551.00

Close Date: 01/14/2008

Problem?

ON CALL COMP DOOR WONT OPEN E23

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12907

In Date: 01/30/2008

Meter Reading: 75,688.00

Close Date: 02/05/2008

Problem?

REPAIR A/C SR7 AT 41

Task performed:

Parts

Quantity

1. Rear a/c not cold, cleaned condenser fan and retested

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2572

In Date: 05/11/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

We need brackets for the fire extinguishers in the driver side compartment

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V13064

In Date: 02/05/2008

Meter Reading: 75,918.00

Close Date: 02/11/2008

Problem?

a inspection and repairs as needed er7 back from 41

Task performed:

Parts

Quantity

- "A" inspection.
- Test for air leaks, found 3, replace air horn solenoid, repair 3 leaks
- Clean patient compartment
- Get stretcher from reserve stock, put into truck (stretcher missing)
- Replace wiper blades
- Parts room duty (1500-1600hrs)

12105QUICK DRAIN

2

EL360081760611 SOLENOID AIR HORN

1

U-24RWIPER REFILL

1

Workorder: V14394

In Date: 04/10/2008

Meter Reading: 77,014.00

Close Date: 04/15/2008

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR7

Task performed:

Parts

Quantity

- a inspection
- voltage too high on alt-ajust.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V14884

In Date: 05/06/2008

Meter Reading: 77,014.00

Close Date: 05/12/2008

Problem?

A inspection and repairs as needed

Task performed:

- A-Inspection
- 2. Washers inop; nozzle clogged; unclog nozzle.
- 3. Plexi door for cabinet & hazmat tray-broken; installed new plexi glass.
- 4. Hazmat pull out tray inop; slider broken; installed new slide. j

<u>Parts</u>	<u>Quantity</u>
2220-145632-14 DRAWER SLIDE	1
322502BULB PATIENT GH22	5
508RED58EC20RU STROBE-RED SURFACE MOUNT	1
AEVDOOR LOCK BEZEL	1
AS75600MONI-A01 O2 MINDER KIT	1
DOOR2LEXAN 14.5 X 8.5	1
DOOR5LEXAN 9 X 38 1/2 IN	1

Workorder: V14804

In Date: 05/01/2008

Meter Reading: 1,334.90

Close Date: 06/17/2008

Problem?

Emergency lights on front grill inop. R-28

Task performed:

- 1. FOUND BAD GROUND REWORK-TESTED OK

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15635

In Date: 06/09/2008
Close Date: 06/25/2008

Meter Reading: 77,429.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR 7

Task performed:

- C-Inspection
- 2. Svc diff.
- 3. Svc Trans
- 4. Safery meeting/shop meeting.
- 5. Svc battries.
- 6. Painted fuel cap.
- 7. Replc rear A/C filter.
- 8. Replc pat comaprtn side entry door inner door latch handle bezel.
- 9. Replc L/R door weather strips (cab).
- 10. Replc L/R cab step non skid.
- 11. Tightened/lubed all door holdopns, latches, strikers & hinges.
- 12. replc L/R flag stickers on rear of body. (faded0.
- 13. Chkd out 110V A/C inop; fnd main brkr tripped & no freon in sys; vac sys (held vac); chrged sys; leak chkd sys extensively; fnd no leaks; reset brkr; ran sys for extended peiod; did not trip brkr. j

Parts

Quantity

15W40BSYN OIL BULK QTS	16
29526898 29548988 TRANS FILTER ALLISON	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
AEVDOOR LOCK BEZEL	1
CA8193AIR FILTER 46744 WIX	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V18089

In Date: 10/02/2008
Close Date: 10/08/2008

Meter Reading: 77,951.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED

Task performed:

- 1. Perform "A" service.
- 2. replced wiper blades
- 3. Replc broken "T" fitting in window washer hoses. j

Parts

Quantity

52-24WIPER BLADES ANCO 24	2
SPR-W58-1TEE PLASTIC	1

Workorder: V19138

In Date: 11/18/2008
Close Date: 11/26/2008

Meter Reading: 7,851,617.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR BACK FROM 23

Task performed:

- A-Inspection
- 2. Frnt hubs leaking; fill caps bad; installed new fill caps.
- 3. L/S washer inop; clogged; unclogged.
- 4. L/R/F tire low; replaced valve core. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19198

In Date: 11/20/2008

Meter Reading: 7,851,617.00

Close Date: 11/26/2008

Problem?

REPLACE STRECTHER, R-34

Task performed:

Stetcher won't lock properly; fnd track pins & bushings worn; went to shop & swapped stretcher; return home.
j

Parts

NO PARTS USED

Quantity

Workorder: V19456

In Date: 12/02/2008

Meter Reading: 79,485.00

Close Date: 12/17/2008

Problem?

A inspection (back from 34)

Task performed:

A-Inspection.
2. Replaced alt not charging.
3. Topped off all fluids. j

Parts

4870JBALTERNATOR 270 AMP NEEDS EXCITER WIRE

1

Workorder: V19834

In Date: 12/18/2008

Meter Reading: 79,485.00

Close Date: 01/07/2009

Problem?

A inspection

Task performed:

A-Inspection; top off fluids & tires.
2. Replc rotator light in rear light bar.
3. R/R marker light & 02 light. j

Parts

01-0416333-00LIGHT ROTATOR

4020362171 GRO LAMP DOME 4 IN

ICC5RLLED CLEARANCE LIGHT RED

1

1

1

Workorder: V20008

In Date: 12/29/2008

Meter Reading: 1,561.40

Close Date: 01/13/2009

Problem?

rear light bar cracked...E-light does not work..the rest of the of the E-light bar works. ar at 54

Task performed:

1. Rear light bar damaged; straightened out & rep rotato
2. A-Inspection.
3. Rear door panels loose; msng & stripped screws; rep door panels; also svc all doors. j

Parts

68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19846

In Date: 12/18/2008
Close Date: 01/15/2009

Meter Reading: 79,485.00

Problem?
repair flat

Task performed:	Parts	Quantity
Repair flat - Callaghan j	NO PARTS USED	

Vendor? CALLAGHAN

Workorder: V20045

In Date: 12/31/2008
Close Date: 01/15/2009

Meter Reading: 79,803.60

Problem?
door hard to open sr at 53

Task performed:	Parts	Quantity
Readj door linkage & greased. j	NO PARTS USED	

Workorder: V20286

In Date: 01/12/2009
Close Date: 02/05/2009

Meter Reading: 80,637.00

Problem?
A INSPETION AND REPAIRS AS NEEDED SR7

Task performed:	Parts	Quantity
A-Inspection. 2. Ck for air leak; sprayed air fittings, lines & drain valves; fnd (2) drains leaking; R/R drain valves; ran/ck for leaks; ck ok. j	12105QUICK DRAIN	2

Workorder: V20621

In Date: 01/26/2009
Close Date: 02/12/2009

Meter Reading: 1,592.00

Problem?
left headlight not woking on low beam. R20

Task performed:	Parts	Quantity
1- Drive to sta. replaced head lite, test ok.	H6054USE CV TYPE SEALED BEAM	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20959

In Date: 02/09/2009
Close Date: 02/12/2009

Meter Reading: 81,259.70

Problem?

WHEEL SEAL LEAK R-33

Task performed:

Parts

Quantity

1- Call out to sta-33. found leak at rear wheels, swap ou

NO PARTS USED

Workorder: V20820

In Date: 02/03/2009
Close Date: 02/24/2009

Meter Reading: 81,259.70

Problem?

a inspection and repairs as needed sr 7

Task performed:

Parts

Quantity

1. Perform A-Inspection.

NO PARTS USED

2. Rep loose steering column. j

Workorder: V20830

In Date: 02/03/2009
Close Date: 02/28/2009

Meter Reading: 81,259.70

Problem?

replace rear tires at shop sr 7

Task performed:

Parts

Quantity

Replace rear tirest at shop SR7 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V21081

In Date: 02/12/2009
Close Date: 02/28/2009

Meter Reading: 81,259.70

Problem?

UPDATE ECM FOR OIL PRESSURE SWITCH, R-45

Task performed:

Parts

Quantity

Update ECM for oil pressure switch R45 - Cummins j

R134AFREON LB

2

Vendor? CUMMINS



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20831

In Date: 02/03/2009

Meter Reading: 81,259.70

Close Date: 03/03/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED SR 7 LEAK AT REAR WHELNS BRAKES HANGING UP

Task performed:

- B-Inspection
- 2. Replc all (4) btrys, load test & chk charging sys.
- 3. Replc btry tender.
- 4. Install shocks.
- 5. R/R rear wheels, calipers & rotors; replcd L&R rear grease seals; cln/inspect bearings & ____; adj wheel bearings to specs; ttorque bolts to specs; road test & rechk.
- 6. Meeting with Tim, Mike L. & Ed O.
- 7. Chk 110V btry charging sys-ok.
- 8. Crimp 02 cable to wrench.
- 9. Clear computer codes; problem w/laptop; use other laptop. j

Parts

Quantity

032-0116549297 BATTERY INDICATOR	1
1229H4636LOCKRING WITH TABS	1
15W40BSYN OIL BULK QTS	16
161657700065489 SHOCK REAR NEW RESCUE	2
370047ASEAL 34387	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
E-2436R002436 GASKET-REAR AXLE	2
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SA66613SHOCK FRONT RESC	2

Workorder: V21690

In Date: 03/10/2009

Meter Reading: 81,259.70

Close Date: 03/18/2009

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR 7

Task performed:

- Road test & A-Inspection.
- 2. Maplight out; rem bulb; bulb probe brkn in socket; rem probe & install new bulb.
- 3. Fire main radio power knob msng; receive replacmenet knob from radio shop; isntall knob.
- 4. Cln up shop & work on lift;, greasing & replacing torn curtain. j

Parts

Quantity

15W40BSYN OIL BULK QTS	24
8550A250A8550A250A BULB	2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22152

In Date: 03/27/2009

Meter Reading: 81,259.70

Close Date: 03/31/2009

Problem?

A inspection and related repairs (back from S034)

Task performed:

A-Inspection
2. Replc both frnt seat belt asys; rem inner wall panel to rep dowel hole for lower part of seat belt asy on right side; (passenger) of cab. j

Parts

Quantity

IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OLD #

1

IMMF13225BELT SEAT PASS. IMMF11852 OLD #

1

Workorder: V23141

In Date: 05/07/2009

Meter Reading: 7,793.00

Close Date: 05/19/2009

Problem?

the a/c in the back pt compartment is not working in the spare truck at station 23

Task performed:

C/O A/C; fnd bad wire on blower resister; rep wire. j

Parts

Quantity

071704214035 GASKET 1 1/2

1

Workorder: V23494

In Date: 05/22/2009

Meter Reading: 1,903.50

Close Date: 06/01/2009

Problem?

low beam head light on the driver side is out in the spare rescue at station23

Task performed:

Go to Stn23; replcd L/F head lamp H6054. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1

Workorder: V23633

In Date: 05/29/2009

Meter Reading: 85,370.80

Close Date: 06/12/2009

Problem?

on call repair exhaust r23

Task performed:

Drive to Stn 23; R-23B broken exhaust brckt to tail pipe; rep; put back in svc. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V24514

In Date: 07/01/2009

Meter Reading: 86,473.00

Close Date: 07/10/2009

Problem?

A inspection and repairs (from 23)

Task performed:

- A-Inspection
2. Add 1 qt motor oil; add P/S fluid; add coolant; air L/R/I tire; rem screw stuck in RRO tire & chk for leaks - ok.
3. Replcd R/F pat compt bulb. j

Parts

Quantity

322502BULB PATIENT GH22

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25376

In Date: 08/07/2009

Meter Reading: 87,097.00

Close Date: 08/19/2009

Problem?

C inspection and repairs (from 39)

Task performed:

- C-Inspection
- 2. T-shoot no power to 110 A/C sys; rep short in wiring.
- 3. Chk 110 A/C opn.
- 4. replc cab door latches.
- 5. Replc city horns.
- 6. Start replacing fan belts & tensioner.
- 7. Replc rear pat door striker pins; tap out ___ prev nuts & free up; adj pins for door closure.
- 8. Finish installing fan belts.
- 9. Rebuild Air dryer.
- 10. Replc all (4) A/C diverters.
- 11. Evacuate 110 A/C sys.
- 12. R/R hose line compressor.
- 13. Charge R22 sys & chk opn; cooling properly now.
- 14. Cln coil in pat compt.
- 15. Rem steering column bolts; cln threads & reinstall w/locktite.
- 16. Cln evap cords in pat compt A/C.
- 17. Paint fuel cap.
- 18. Replc out of svc decals; replc fire rescue deal on hood.
- 19. Rep fuel leak at pump; tighten loose fuel line.
- 20. Replc front grille; swap over emblem; replc strobe light; polish lense.
- 21. Rep rear light bar; bent on side; replcd (1) light & (2) lenses.
- 22. Replc front/rear brakes.
- 23. Replcd master _____ rocker lower knob.
- 24. Rem & recenter steering wheel; final road test & chk over. j

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
1500900017000USE 9 X 14 FILTER	2
15W40BSYN OIL BULK QTS	24
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
6808880023GRILLE FRTLNR. A17-14766-000	1
68116169650CLENS RED SUPER ADV. PLUS LT. BAR 68-1	1
68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR	1
9007H9007 BULB ASSY	1
9451BELT	1
9485BELT	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
CA8193AIR FILTER 46744 WIX	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
STP594115449 STRIKER PIN	4
SWT54924ACTUATOR-RED	1

Workorder: V25626

In Date: 08/18/2009

Meter Reading: 87,097.00

Close Date: 08/19/2009

Problem?

a inspection and repairs as needed

Task performed:

perform A-Inspection j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25608

In Date: 08/18/2009

Meter Reading: 87,097.00

Close Date: 08/26/2009

Problem?

REPLACE FRONT TIRES AT SHOP TIRE SOLES

Task performed:

Parts

Quantity

Replace frnt tires at shop - Tiresoles j

NO PARTS USED

Vendor? TIRESOLES

Workorder: V25780

In Date: 08/25/2009

Meter Reading: 87,097.00

Close Date: 08/26/2009

Problem?

A INSPECTION AND REPAIRS AS NEEDED, SR-7

Task performed:

Parts

Quantity

Perform "A" Svc

1895BULB

2

2. Replc rear marker light bulb. j

Workorder: V25685

In Date: 08/21/2009

Meter Reading: 87,097.00

Close Date: 08/27/2009

Problem?

rear a/c stinks

Task performed:

Parts

Quantity

Deodorize pat compt. j

NO PARTS USED

Workorder: V26172

In Date: 09/10/2009

Meter Reading: 87,802.50

Close Date: 09/15/2009

Problem?

A inspection and repairs (from 23)

Task performed:

Parts

Quantity

A-Inspection

NO PARTS USED

2. Adj tire pressures.

3. Replc exterior door handles & lube linkage; sec tool holders in L-2.

4. Rep side marker light; added coolant.



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26780

In Date: 10/09/2009

Meter Reading: 88,246.80

Close Date: 10/21/2009

Problem?

A inspection and repairs (from 25)

Task performed:

- Perform A-service
- 2. Replcd wiperblades
- 3. R/R driver's door panel to secure door handle/latch (loose). j

Parts

52-24WIPER BLADES ANCO 24

Quantity

2

Workorder: V27107

In Date: 10/22/2009

Meter Reading: 89,151.30

Close Date: 10/27/2009

Problem?

repair compt. door latch R36

Task performed:

- 1. Travel to Stn36 from C/S.
- 2. Open compt door that won't open; R/R inner door panel; reattach linkage rod to lower latch on compt L-2; secure rod to latch; clip brkn.

Parts

NO PARTS USED

Quantity

Workorder: V27128

In Date: 10/23/2009

Meter Reading: 89,151.30

Close Date: 10/27/2009

Problem?

A inspection (from 47)

Task performed:

- A-Inspection & road test.
- 2. Secure loose cable along frame rail.
- 3. L-2 light inop; dia; fnd wire harness dropped btwn walls; fish out wire harness; bulb blown; install new bulb.

Parts

4020362171 GRO LAMP DOME 4 IN

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V27437

In Date: 11/05/2009

Meter Reading: 89,151.30

Close Date: 12/02/2009

Problem?

A inspection and repairs (from 30)

Task performed:

- A-Service
- 2. Replc radiator - leaking.
- 3. Replc radiator a second time because new radiator leaked; road teste/chkd over.
- 4. Replcd L-4 compt door holdopen.
- 5. Replc T-signal side marker lenses - cracked.
- 6. Replcd wiper blades.
- 7. Replcd outer A/C compressor belt - rubbing fan harness brkt.
- 8. C/O door alarm malfunction; traced problem to faulty magnetic switch on btry box; replc magnet. j

Parts

Quantity

05-17223-002RAD CAP 20 LB	1
52-24WIPER BLADES ANCO 24	2
56415CIG. LIGHTER ACCES.	1
91513AMBER LENS	2
9485BELT	1
BHT/A4570RADIATOR	1
HLD374211 IN HOLD-OPEN 30LB	1
SWT54930SWITCH DOOR	1

Workorder: V28320

In Date: 12/14/2009

Meter Reading: 89,151.30

Close Date: 01/11/2010

Problem?

A inspection and repairs, need keys to patient box (from 54)

Task performed:

- A-Inspection
- 2. Replc bulb in L/S top & R/side cab roof marker.
- 3. Trace wiring problem w/city horn; replc horn button; replc "Y" harness for horns.
- 4. Install Nader pin covers.
- 5. Install SCBA brkts (new ones); redrill holes for seat packing all (3) on vehi.
- 6. Install R/side windshield molding. j

Parts

Quantity

1829601001RHINGE PILLAR RESCUE	1
6814600340A14-15472-000 HORN BUTTON	1
A0620881001PIGTAIL FOR HORN	1

Workorder: V29455

In Date: 01/26/2010

Meter Reading: 89,151.00

Close Date: 01/29/2010

Problem?

Med box slide tracks inop spare recue

Task performed:

- Replc draw slides. j

Parts

Quantity

5632-1010 IN DRAWER SLIDES PR	2
-------------------------------	---



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32333

In Date: 05/20/2010
Close Date: 06/01/2010

Meter Reading: 89,151.00

Problem?

dead batteries

Task performed:

1. Tried to start - NG; tried to jump start - NG; bring charger to veh & plug in for btrys to charge.
2. Move veh into shop; test all btrys-all failed; R/R (4) btrys; cln all cable & connections.
3. Test on-board charger-not working; dia problem & repair.
4. Test veh charging sys; belt seems loose; chk to see if correct belt/tensioner; chk belt alignment/mntng; hand feel tensioner w/rachet-seems ok. j

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V32884

In Date: 06/14/2010
Close Date: 06/24/2010

Meter Reading: 91,530.00

Problem?

A INSPECTION AND REPAIRS ASC NEEDED SR 7

Task performed:

1. A-Svc.
2. Replc marker light.
3. Replc R/scene lite.
4. Recvr, test & recharge A/C sys. j

Parts

Quantity

02028324901USE 90E00ZR ASSY	1
H35SN12BULB	1

Workorder: V32637

In Date: 06/04/2010
Close Date: 06/28/2010

Meter Reading: 90,911.10

Problem?

turn signals 10-7 sr at 35

Task performed:

1. Rep tt-signal switch. j

Parts

Quantity

6805450124SWITCH TURN SIGNAL	1
------------------------------	---



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32661

In Date: 06/04/2010
Close Date: 07/20/2010

Meter Reading: 91,331.00

Problem?

Right rear scene light is out. r35

Task performed:

Rep grnd for light in rear. j

Parts

Quantity

NO PARTS USED

Workorder: V33306

In Date: 07/02/2010
Close Date: 07/29/2010

Meter Reading: 91,642.00

Problem?

A INSPECTION AND REPAIRS (from 72)

Task performed:

A-Inspection; add P/S fluid; adj air in tires. ja

Parts

Quantity

NO PARTS USED

Workorder: V33956

In Date: 08/02/2010
Close Date: 09/09/2010

Meter Reading: 91,390.80

Problem?

COVER FROM SHORELINE OUTLET BROKE OFF R43

Task performed:

1. Air leak-rep fitting on dryer that was leaking.
2. Rear pat lights inop; rep switch for timer. j

Parts

Quantity

NO PARTS USED

Workorder: V34086

In Date: 08/06/2010
Close Date: 09/14/2010

Meter Reading: 92,075.00

Problem?

A inspection and repairs (from 43)

Task performed:

1. A-Service
2. Replc Kusmal cvr.
3. Replc frnt left side strobe fixture. j

Parts

Quantity

02-0383470-CROBSOLETE LENS RED/CLEAR	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37697

In Date: 01/10/2011

Meter Reading: 91,390.80

Close Date: 01/18/2011

Problem?

on call air dump wont raise 37

Task performed:

Opr complnt air dump inop; on route to stn, dispatch called & cancelled; called stn -opr error.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37773

In Date: 01/12/2011

Meter Reading: 92,761.00

Close Date: 01/25/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR7

Task performed:

- (1) 'C' INSPECTION AND NEEDED REPAIRS.
- (2) PAINTED FUEL CAP.
- (3) SECURED AIR HORN TO HOOD. BROKEN/FALLING OFF.
- (4) FABRICATED A NEW CABLE & REMOUNTED O2 WRENCH IN L-1 COMPARTMENT.
- (5) REPLACED WIPER BLADES.
- (6) REPLACED ENTRY LIGHT IN REAR LIGHT BAR THAT WAS BURN'T.
- (7) REPLACED BULB IN LEFT BACKUP LIGHT.
- (8) REPLACED DRIVER DOOR WEATHER STRIPPING
- (9) REPLACED BULB IN RIGHT FRONT TURN SIGNAL LIGHT.
- (10) REPLACED DRIVER DOOR WINDOW WEATHER STRIPPING.
- (11) REPLACED BOTH CAB DOOR TRIMS THAT WAS BROKEN.
- (12) R&R PASSENGER SIDE DOOR PANEL TO TIGHTEN OUTER DOOR LATCH ASSEMBLY THAT WAS LOOSE.
- (13) SERVICED AIR DRYER TO BRAKE SYSTEM.
- (14) REPLACED SQUARD BENCH SHOCKS.
- (15) REPLACED HOLD OPEN SHOCKS ON ALL CABINET DOORS IN PATIENT COMPARTMENT AND ASJUSTED CROOKED CABINET SHELF.
- (16) REPLACED PATIENT COMPARTMENT A/C FILTER.
- (17) REMOVED, CLEANED & REINSTALLED WINDOW GASKET ON LEFT REAR ENTRY DOOR THAT WAS FALLING OFF.
- (18) R&R DASH TO ADJUST A/C VENT CABLE SO DEFROSTER WOULD SHUT ALL THE WAY.
- (19) REPLACED ENGINE AIR FILTER.
- (20) LUBED AND ADJUSTED ALL DOOR LATCHES, BRACKETS AND HOLD OPEN SHOCKS.
- (21) QUALITY CHECK.
- (22) REMOVED DOOR SEAL, PUT GLUE ON IT AND REINSTALLED FOR L-4 COMPARTMENT. IT WAS FALLING OFF THE DOOR. J.W.

Parts

Quantity

Parts	Quantity
1156BULB	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
52-24WIPER BLADES ANCO 24	2
6737200054673-720-00-54 SEAL WINDOW	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
H27SN12BULB	1
H50SN12BULB	1
HLD3999GSS1715UV 30LB STRUT GAS	8
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38125

In Date: 01/28/2011

Meter Reading: 92,860.00

Close Date: 02/02/2011

Problem?

A inspection and repairs (from 81)

Task performed:

A-Inspection
2. Hazard waste drawer brkn - sitting on floor; rem stainless dividers inside drawer; grind down rough edges; grind off slides welded to drawer box; drill new holes & mnt newer style slides to drawer box; install drawer box in cabinet. j

Parts

5632-1010 IN DRAWER SLIDES PR

Quantity

2

Workorder: V37738

In Date: 01/11/2011

Meter Reading: 91,390.80

Close Date: 02/08/2011

Problem?

air leak, gets to zero in a couple of hours. SR AT 37

Task performed:

chkd for air leaks; fnd none. j

Parts

NO PARTS USED

Quantity

Workorder: V38419

In Date: 02/10/2011

Meter Reading: 93,536.50

Close Date: 02/24/2011

Problem?

back up light is out and plug for front radio is loose. r41

Task performed:

Rep radio plug & rep back-up light. j

Parts

NO PARTS USED

Quantity

Workorder: V38551

In Date: 02/16/2011

Meter Reading: 94,017.00

Close Date: 02/25/2011

Problem?

on call wont start sr at 41

Task performed:

Intermittent - no start; starter bad - replaced. j

Parts

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38834

In Date: 02/28/2011

Meter Reading: 95,379.00

Close Date: 03/29/2011

Problem?

A INSPECTION AND REPAIRS AS NEEDED

Task performed:

- 1. A-Inspection
- 2. Tighten/adj all compt door latches/pins.
- 3. Resecure ____ draw slides.
- 4. Resecure L-3 compt door hinge mnts. j 3/29/11
- 5. A-Inspection
- 6. Add trans fluid.
- 7. Lube drivers door hinges.
- 8. Replcd L/headlight.
- 9. Replc maplight.
- 10. Tighten both A/C belts. j3/30/11

Parts

Quantity

H35SN12BULB	2
H6054USE CV TYPE SEALED BEAM	2
LF18TS-LEDMAP LIGHT LED 18 IN	1

Workorder: V39517

In Date: 03/29/2011

Meter Reading: 95,804.00

Close Date: 05/10/2011

Problem?

A inspection (from 54) oil leak, air leak

Task performed:

- 1. A-Inspection
- 2. Started cleaning oil off frnt L/side of eng; fnd belts loose on air compressor; tightene/cln again; test drive/chk for leaks; no leaks.
- 3. Chk bulbs on R/side of traffic advisor; fnd bulbs good; chk connection, it was very dirty - clean; light works.
- 4. Chk truck for air leak; fnd no leak under truk but fnd a small leak on line to gauge in dash; replc fittings/hose; stopped leak; top off air to chk if leaks down over night.
- 5. Chk air sys for leak; fnd no more leaks outside; chkd chk valve; fnd a lot of dirt in chk valve; replc chk valve.
- 6. Chk for air leak in dash; fnd park brake valve leaking under knob; R/R park brake valve; fill sys w/air to see if any more leaks.
- 7. Fnd air leak at gov; R/R gov.
- 8. R/R hood latch on pass side.

Parts

Quantity

17-14781-000PLASTIC HOOD LATCH	1
23-11345-710SCREW DASH	6
276567XVALVE DASH PP1	1
284358GOVERNOR D-2	1
800372CHECK VALVE	1
S693AIR CHUCK	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40903

In Date: 05/27/2011

Meter Reading: 94,828.10

Close Date: 05/31/2011

Problem?

pt compartment a/c inop. Sta 91.

Task performed:

Pat compt A/C inop; blower motor seized; swapped out.
j

Parts

NO PARTS USED

Quantity

Workorder: V40904

In Date: 05/27/2011

Meter Reading: 94,828.10

Close Date: 06/08/2011

Problem?

Blower motor repair, Sta 91.

Task performed:

1. Pat compt A/C fan; diss A/C unit rewire/install new A/C fan blower.
2. Med waste basket slider brkn; reassem; no part available - on order; drill mntng slider holes; install new slider on draws & install on unit.
3. Pat compt mansaver drift pin out; install drift pin in mansaver. j

Parts

5632-1010 IN DRAWER SLIDES PR

2

ACX-84534LUG NUT COVER PK10

10

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 110 A/

1

Workorder: V41811

In Date: 07/05/2011

Meter Reading: 94,828.10

Close Date: 07/13/2011

Problem?

Dead battery.

Task performed:

Put unit on slow charge; start unit; no load 13.9 volts; full load test unit 13.3 volts. j

Parts

NO PARTS USED

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43539

In Date: 09/09/2011

Meter Reading: 97,417.00

Close Date: 09/22/2011

Problem?

A inspection.

Task performed:

- A-Inspection
- 2. Adj air horns.
- 3. Chk/recharge pat A/C.
- 4. Tighten/lube all pat compt latches.
- 5. Adj stretcher lock. j

Parts

Quantity

322502BULB PATIENT GH22

1

921LIGHT BULB

1

Workorder: V44478

In Date: 10/18/2011

Meter Reading: 98,264.00

Close Date: 10/21/2011

Problem?

B INSPECTION AND REPAIRS SR 7

Task performed:

- B-Inspection
- 2. Diff svc.
- 3. Air dryer svc.
- 4. Trans svc.
- 5. Oil on air compressor - cln compressor & surrounding area.
- 6. Rear brake svc.
- 7. Frame fail slider crack; drill end of crack as per M. Lehan.
- 8. Coolant low; press test cap & sys; no leak fnd; top off coolant reservoir.
- 9. Pat compt forward side padding loose; sec w/glue padding to mntng board.
- 10. Action area drop down latch inop; latch weak; prop up/isntall support brkt.
- 11. Pat compt hi-light inop; fnd blown bulb; rem/install new bulb.
- 12. L-2 tool holder brkn; rem brkn support/install new tool holder.
- 13. Right rear scene light 10-7; fnd bulb blown; rem/install new bulb.
- 14. L/R compt door panel screws loose; sec loose screws.
- 15. L-3 hold open loose; sec loose holdopen.
- 16. L-3 has wter in compt; cln compt & adj door hinge screws to securely close & seal compts.
- 17. quality check. j

Parts

Quantity

29526898 29548988 TRANS FILTER ALLISON

1

322502BULB PATIENT GH22

1

CL200CL200 TOOL CLIP

1

H35SN12BULB

1

L1261F33585XE FUEL FILTER WIX

1

MK184HDBRAKE PADS

1

PH8942FILTER OIL 57182 LFP3729

1

RN60JDRYER KIT

1

S3225PFUEL FILTER 33630 LFF5849

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45280

In Date: 11/18/2011
Close Date: 11/21/2011

Meter Reading: 98,915.00

Problem?

A-Inspection

Task performed:

a inspection

Parts

Quantity

15W40BSYN OIL BULK QTS

2

Workorder: V45952

In Date: 12/19/2011
Close Date: 12/27/2011

Meter Reading: 98,890.00

Problem?

A inspection.

Task performed:

A-INSPECTION.

Parts

Quantity

NO PARTS USED

REPAIR R/S INSIDE CAB LIGHT.

Workorder: V46710

In Date: 01/19/2012
Close Date: 01/20/2012

Meter Reading: 98,890.00

Problem?

A inspection.

Task performed:

1. A-INSPECTION
2. ADJUST ALL TIRE PRESSURES.
3. BATTERY CHARGER INDICATOR LIGHT DOESN'T COME ON WHEN PLUGGED IN. CHECKED VOLTS AT BATTERIES - CHARGER NOT WORKING - DIAGNOSE WHY. R&R PROTECTIVE CAGE AT BATTERY CHARGER CHECK FOR 110 VOLT - NO-CHECK BRKR - LOAD TEST BREAKER WITH A/C ON - OK.

Parts

Quantity

NO PARTS USED

Workorder: V47031

In Date: 02/02/2012
Close Date: 02/02/2012

Meter Reading: 99,156.50

Problem?

A inspection.

Task performed:

A INSPECTION

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48338

In Date: 04/02/2012

Meter Reading: 99,234.00

Close Date: 04/04/2012

Problem?

A inspection

Task performed:

1. A-INSPECTION.
2. REPLACE MISSING ROCKER SWITCH FOR PATIENT AREA L/SIDE OVERHEAD LIGHTING.

Parts

Quantity

SWT5492744435 ACTUATOR-BLACK

1

Workorder: V49209

In Date: 05/09/2012

Meter Reading:

Close Date: 05/09/2012

Problem?

Spair rescue for station 47, the pt compartment AC is not working, very hott

Task performed:

1. check for warm pat. compt. a/c, check freon, cond. fans, all ok, found when you wiggle compressor wire the clutch comes on and off, cut connector out of system and test ok, now blows cold..

Parts

Quantity

NO PARTS USED

Workorder: V49050

In Date: 05/02/2012

Meter Reading: 99,476.00

Close Date: 05/11/2012

Problem?

would like to have stryker stretcher piece installed or moved from regular r47 to acomadate stryker stretcher

Task performed:

INSTALLED STRETCHER.

Parts

Quantity

6092036018J HOOK STRYKER

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49545

In Date: 05/22/2012

Meter Reading: 100,718.00

Close Date: 06/01/2012

Problem?

A inspection from 47

Task performed:

1. A-SERVICE.
2. CHECK REAR A/C, BLOW OUT A/C CONDENSER UNDER TRUCK. CHECK BOTH FAN, WORKING, TOP OF UNIT WITH R-134. RECHECK SYSTEM.
3. REPLACE OVER HEAD LIGHTS, AND REPLACE S/A LIGHT NOT WORKING.
4. BUFF ALL LENSE ON TRUCK , LIGHT BAR ETC. REPAIR LIGHT ON REAR LIGHT BAR, CLEAR BACK UP OUT.

Parts

Quantity

02-0383470-CROBSOLETE LENS RED/CLEAR

1

Workorder: V50895

In Date: 07/16/2012

Meter Reading: 100,718.00

Close Date: 09/18/2012

Problem?

C INSPECTION SR 7

Task performed:

1. C INSP
2. R&R 2 A/C CONDENSOR FANS FOR REAR A/C.
3. L-2 COMPT HOLD OPEN.
4. SHOWED STEVE CRACKS IN REAR CROSSMEMBER AND LFT SIDE CHASSIS RAIL. HIS DECISION IS TO LEAVE VEH IN SERVICE.
- 5.REPAIR DRAWER TRUCK ON MED SUPPY DRAWER.
6. SQUAD BENCHS STRICKER FOR LATCH MISSING-NO PART IN STOCK MAKE STRIKER FRM FOOT MAN LOOP.
7. DIAGNOSE STROBE SYST PS OK ALL LENSES FROZEN TO LIGHT BAR. CUT OUT AND REMOVE ENOUGH LENSES TO RENCH CENTER.
8. R&R LENS R&R BULBS IN ACTION AREA LT.
9. 110V A/C SYST R&R INTERIOR PANELS TO CHK DRYER, CONNECT TRANS AND LOOK FOR LEAKS. HOOK UP R22 GAUGES RAN SYST TO DIAGNOSE PROB.
10. 110V A/C SYST CONT. REFILL FREON AND RETEST SYST-OK.

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

52-24WIPER BLADES ANCO 24

2

60027FAN A/C COND 12IN 860026-2-W

2

CA8193AIR FILTER 46744 WIX

1

L1261F33585XE FUEL FILTER WIX

1

PH8942FILTER OIL 57182 LFP3729

1

S3225PFUEL FILTER 33630 LFF5849

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52131

In Date: 09/04/2012
Close Date: 09/20/2012

Meter Reading: 100,718.00

Problem?

A INSPECTION SR 7

Task performed:

A INSPECTION.

Parts

NO PARTS USED

Quantity

Workorder: V52760

In Date: 10/01/2012
Close Date: 10/03/2012

Meter Reading: 101,363.80

Problem?

A INSPECTION SR 11

Task performed:

1. A-INSPECTION.
2. REPLACED L TURN BULB. CLEAN AND LUBRICATE SOCKET.
3. DIAGNOSE RF STROBE IN/OP - FOUND BAD STROBE LAMP. REPLACED STROBE LAMP. TEST OK.
4. REPLACED PATIENT COMPT LOW BEAM LAMP.
5. REAR PATIENT COMPT DOOR HARD TO OPEN - FOUND NADER PIN COVER OBSTRUCTING DOOR. STRAIGHTENED OUT COVER.
6. TIGHTEN A/C BELTS. INSTALL NOT MISSING FROM LOWER A/C COMPRESSOR BELT.
7. COOLANT STAIN FROM HEAD GASKET R FRONT - RADIATOR CAP WRONG PRESSURE 20 PSI REPLACED CAP WITH 10 LB. AND PRESSURE CHECKED COOLING SYSTEM OK AT THIS TIME. HEAD GASKET TO BE MONITORED PER ED AND STEVE.
8. L FRONT TIRE WORN ON INSIDE AND REAR TIRES WORN OUT. ALL NEW TIRES TO BE INSTALLED BY VENDOR.

Parts

05-17223-000CAP RADIATOR 10 LB
 58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E
 906LIGHT BULB 12CP

Quantity

1
1
1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53248

In Date: 10/22/2012
Close Date: 10/23/2012

Meter Reading: 103,297.00

Problem?

A Inspection

Task performed:

1. A INSP
2. R&R LENS R&R BULB IN PATIENT CEILING LT.
3. DIAGNOSE AND REPAIR ROOF SPOT LIGHT. R&R CONTROL ASSY.

Parts	Quantity
21481SEARCHLIGHT CONTROL	1
322502BULB PATIENT GH22	1

Workorder: V53612

In Date: 11/07/2012
Close Date: 11/08/2012

Meter Reading: 103,297.00

Problem?

install placards missing r 93

Task performed:

MARK UP PLACARDS FOR RESCUE AT SHOP GO TO STATION REMOVE OLD BRACKET FROM TRUCK REMOVE GLUE CLEAN AND INSTALLED NEW BRACKETS AND PLACARDS.

Parts	Quantity
L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CARD	1

Workorder: V54158

In Date: 12/03/2012
Close Date: 12/03/2012

Meter Reading: 104,100.00

Problem?

A INSPECTION

Task performed:

1. A INSPECTION.
2. REPLACE BROKEN ROTATOR IN REAR LT/BAR- ALSO WHILE INSIDE REPAIR 3 REFLECTORS THAT WERE LOOSE- (FLOPPING AROUND).

Parts	Quantity
01-0416333-00LIGHT ROTATOR	1

Workorder: V54783

In Date: 01/03/2013
Close Date: 01/04/2013

Meter Reading: 104,100.00

Problem?

make number plates se1

Task performed:

MADE AND STICKER NUMBER PLATES.

Parts	Quantity
L PLACARD INSERTLARGE PLACARD INSERT CARD	2



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55141

In Date: 01/18/2013
Close Date: 02/12/2013

Meter Reading: 104,100.00

Problem?

PARKING BRAKE HANDLE BROKEN S-Events RESCUE

Task performed:

INSTALLED NEW HANDLE ON BRAKE VALVE.

Parts

103899KNOB PARKING BRAKE

Quantity

1

Workorder: V51759

In Date: 08/21/2012
Close Date: 04/04/2013

Meter Reading: 100,718.00

Problem?

CAB AC NOT BLOWING COLD

Task performed:

1. DIAGNOIS A/C PROB. CHK FOR LEAK REMOVE COMPRESSOR AND LOW PRESSURE HOSE.
2. INSTALL A/C COMPRESSOR DRIER BOLTS AND LOW PRESSURE HOSE RECHARGE SYST.
3. A/C FOR LEAKS AT FILL PORT SYST REMOVE FILL VALVE INSTALL NEW VLAVE STILL LEAKING.

Parts

16-31438915 VALVE CORE A/C 3544706C1
 416019HOSE & FITTING ASSY
 532703-0602 COMPRESSOR U4735 4471
 716907-0610A DRYER
 9451BELT
 9485BELT

Quantity

2
1
1
1
1
1

Workorder: V52861

In Date: 10/04/2012
Close Date: 04/09/2013

Meter Reading: 101,363.80

Problem?

replace tires

Task performed:

Parts

NO PARTS USED

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58098

In Date: 05/31/2013

Meter Reading: 104,561.50

Close Date: 06/17/2013

Problem?

B inspection SER1

Task performed:

1. B INSPECTION.
2. BATTERY WEEK - REMOVE AND INSTALL 4 NEW 3ID.
3. POWER STEERING SERVICE FILTER AND FLUID.
4. COOLANT SERVICE.
5. PRIMARY FUEL FILTER HOUSING LEAKING - REMOVE INSTALL NEW ASSEMBLY, PRIME FUEL SYSTEM AND OPERATE UNIT, CHECK FOR LEAKS.
6. ENGINE CODES ENGINE POWER SUPPLY 128-251-2 AND ABS CODE 136-001-2 IN ACTIVE CLARE AND ROAD TEST RECHECK NO CODES REAPPEAR.
7. REAR LIGHT BAR OUT STROBE INOP - REMOVE LEASE FOUND STROBE TUBE BURNT, REPLACE STROBE ASSEMBLY AND REASSEMBLE.
8. Q & A.

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
FS1269FUEL FILTER COMPLETE	1
HP-31DBATTERY 950CCA HP-31D	4
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1

Workorder: V64132

In Date: 02/11/2014

Meter Reading: 105,823.00

Close Date: 02/11/2014

Problem?

Cig lighter smoking

Task performed:

TRAVEL TO THE POLO JUMPING DRIVER COMPLAINT CIG LIGHTER SPARKING R LIGHTER.

Parts

Quantity

56415CIG. LIGHTER ACCES.	1
--------------------------	---

Workorder: V63313

In Date: 01/11/2014

Meter Reading: 105,171.30

Close Date: 03/03/2014

Problem?

Smell of smoke when turning on patient a/c

Task performed:

1. DRIVER COMPLAINT, BURNING SMELL IN PATIENT COMPARTMENT RAN UNIT FOR 20 TO 30 MINUTES, BLOWER WORKING FINE, A/C BLOWING WARM, FOUND A/C CONDENSER FANS INOP CIRCUIT BOARD FOR FANS MELTED REWIRED NEW RELAY IN SYSTEM SO FANS WORK.

Parts

Quantity

SY21-6REVECIRCUIT BOARD MEDIC MASTER	1
--------------------------------------	---



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63648

In Date: 01/23/2014

Meter Reading:

Close Date: 03/03/2014

Problem?

rear door handle broken, will not open from outside

Task performed:

Parts

Quantity

REAR DOOR INOP LINKAGE OFF REPAIRED DOOR LINKAGE.

HND5948TM22676-02 HANDLE DOOR ENTRY

1

Workorder: V63880

In Date: 01/31/2014

Meter Reading:

Close Date: 03/03/2014

Problem?

rear door latch is broken. door wont open from outside. Special events rescue

Task performed:

Parts

Quantity

REPAIRED ON V63648.

NO PARTS USED

Workorder: V63919

In Date: 02/02/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

Door handle on exterior door is broken and inoperable. Door can only be opened from the interior. Truck is at Station 25 for special events.

Task performed:

Parts

Quantity

REAR DOOR WONT OPEN FROM OUTSIDE LINKAGE COME OFF, REPLACED DOOR LINKAGE.

NO PARTS USED

Workorder: V60006

In Date: 08/23/2013

Meter Reading:

Close Date: 04/10/2014

Problem?

will not start...seems like batt are dead

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136354

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67810

In Date: 07/10/2014

Meter Reading:

Close Date: 07/15/2014

Problem?

will not start, batt dead...left plugged in for 1 week and still dead.

Task performed:

Parts

Quantity

Travel to 25, driver complaint will not start . Jump started truck. Turned brakes on for on road charger.

NO PARTS USED

Workorder: V68707

In Date: 08/15/2014

Meter Reading: 106,194.00

Close Date: 08/18/2014

Problem?

rear a/c inop

Task performed:

Parts

Quantity

1. Replaced blown relay for condensor fans and recharged A/C.

87401RY-30T RELAY 5 PIN 12V

2

Workorder: V70122

In Date: 10/14/2014

Meter Reading: 106,732.90

Close Date: 10/30/2014

Problem?

C inspection SER 1

Task performed:

Parts

Quantity

1. C Inspection.

16-15762-00016-19471-000 AIR BAG

2

2. a & b - C Inspection and repairs. Tire valve stem leaking. Air bags replaced.

52-24WIPER BLADES ANCO 24

2

CA8193AIR FILTER 46744 WIX

1

L1261F33585XE FUEL FILTER WIX

1

PH8942FILTER OIL 57182 LFP3729

1

S3225PFUEL FILTER 33630 LFF5849

1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10136354) 2001 - FREIGHTLINER FL60 Advanced Life Support Vehicle

10136354

CSHOP-2015-2929

Comments: REPLACE LATCH

Date Opened 9-16-2015 Date Finished 9-17-2015 Meter 1 Reading: 107,185

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR LATCH

2 BOLT ASSY

CSHOP-2015-3009

Comments: 10122968 WONT START AT CRUZAN

Date Opened 9-21-2015 Date Finished 9-21-2015 Meter 1 Reading: 107,185

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

CSHOP-2015-3142

Comments: REPAIR BATTERY BOX ON MULE FROM CRUZAN MIG ARE NOT ON GATOR SMALL VEHICLE. AND HR ARE NOT ON UNIT.

Date Opened 9-29-2015 Date Finished 10-6-2015 Meter 1 Reading: 107,185

TASKS PERFORMED

NO PARTS USED

BATTERY HOLD DOWN
BATTERY TRAY
CONNECTOR
WIRING
FUSE

CSHOP-2015-3603

Comments: MULE @ CRUZAN

Date Opened 10-26-2015 Date Finished 10-26-2015 Meter 1 Reading: 107,185

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

1 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
1 BATTERY; BATTERY

Asset Work Order History 10136354

CSHOP-2015-4295

Comments: **SET UP NEW EMS CART FOR SPECIAL EVENTS REMOVE THE 71.57 HR AND MAKE IT 8.0 HRS**
Date Opened 12-3-2015 Date Finished 1-20-2016 Meter 1 Reading: 107,964

TASKS PERFORMED

Q PARTS

STRETCHER	1	NEWPART; STRIKER ANTLER ASSY
EQUIPMENT MOUNTING BRACKETS	1	HORTON; J HOOK STRYKER
SAFTEY-EMERGENCY EQUIPMENT	1	NEWPART; STRIKER BAR/RAIL ASSY
	1	HORTON; ANTLER BAR

CSHOP-2015-833

Comments: **CHECK BRAKE PEDAL ON BOBCAT CART 10172700 AT AMPHITHEATER**
Date Opened 5-27-2015 Date Finished 5-28-2015 Meter 1 Reading: 107,185

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PEDAL

CSHOP-2016-221

Comments: **SPECIAL EVENTS RESCUE AT STADIUM JUMPING**
Date Opened 1-19-2016 Date Finished 3-17-2016 Meter 1 Reading: 107,965

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	LIGHT; HEADLIGHT EXTRA BRIGHT
HEADLIGHTS LOW BEAM	1	LENS; LENS-RED 68-1181349-5
STROBE LIGHTS	1	HANDLE; HANDLE DOOR
DOOR HANDLES INSIDE-OUTSIDE	2	HANDLE; TM22676-02 HANDLE DOOR ENTRY

Service Requests:

01/18/2016	DOOR / 12: BROKEN / EXCHANGE - NEW INSIDE HANDLE ON RIGHT SIDE IS BROKE, HAVE TO ROLL DOWN WINDOW AND OPEN DOOR FROM OUTSIDE
01/18/2016	BODY / 12: BROKEN / EXCHANGE - USED REAR EMERGENCY LIGHT COVER BROKEN

CSHOP-2016-3249

Comments: **SPECIAL EVENTS RESCUE WITH AIR LEAK**
Date Opened 7-6-2016 Date Finished 7-12-2016 Meter 1 Reading: 108,210

TASKS PERFORMED

Q PARTS

REAR DOOR LATCH ASSEMBLY	1	HANDLE; TM22676-02 HANDLE DOOR ENTRY
AIR SYSTEM	1	SWITCH; 76072-15-DC SWITCH SW76072
AIR CONDITIONING	1	A/C; FREON LB

Service Requests:

07/05/2016	AIR RIDE / 18: LEAKING / REPAIR AIR LEAK UNDER THE DRIVER DASH. GOOD AIR PRESSURE WHEN DRIVING. AIR BRAKE SIGNAL GOES OFF BUT AIR BRAKE DOES COME OFF. TRUCK WILL BE AT 25 THE REST OF JULY 5TH. WILL BE AT INTERNATIONAL POLO CLUB THE REST OF THE WEEK. CALL TIM IF NEED TO HEAD OUT TO EVENT TO FIX. 5614364726
------------	---

Asset Work Order History 10136354

CSHOP-2016-4090

Comments: **C INSPECTION**

Date Opened 8-18-2016

Date Finished

9-15-2016

Meter 1 Reading:

108,652

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FILTER OIL 57182 LFP3729
1 FILTER; FUEL FILTER 33630 LFF5849
24 FLUID; SYN OIL BULK QTS
1 FILTER; 33585XE FUEL FILTER WIX
1 SWITCH; SWITCH DOOR

CSHOP-2016-4207

Date Opened 8-26-2016

Date Finished

8-26-2016

Meter 1 Reading:

95,480

TASKS PERFORMED

NO PARTS USED

CAB

VENDOR? TUFF COAT PAINT & BODY SHOP

CSHOP-2016-4253

Comments: **REPAIRS FROM PM**

Date Opened 8-29-2016

Date Finished

9-15-2016

Meter 1 Reading:

108,652

TASKS PERFORMED

Q PARTS

PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
CHARGING SYSTEM
FILTER
TRANSMISSION
REAR SHOCK
RESERVOIR
AIR DRIER
AIR HORN
SEAT FRONT
A/C BELT REAR A/C

1 LIGHT; 9186-1500-10 MARKER LT. RED LED
1 REFLECTOR; STROBE LINEAR REFLECTOR 6ELTUBE
1 BATTERY; 549297 BATTERY INDICATOR
5 FLUID; ALLISON TRANS FLUID GAL
1 NEWPART; HOSE
1 FILTER; 29548988 TRANS FILTER ALLISON
1 NEWPART; DRAIN PLUG
1 FILTER; FILTER P/S
1 WASHER; WASHER P/S
1 GASKET; GASKET P/S COVER
1 DRYER; DRYER KIT
2 DRAIN; DRAIN COCK
1 SWITCH; 64-0023 SWITCH FOOT SIREN
1 COMPRESSOR; COMPRESSOR A/C 115V R22

CSHOP-2016-4548

Date Opened 9-19-2016

Date Finished

9-19-2016

Meter 1 Reading:

95,480

TASKS PERFORMED

NO PARTS USED

SEAT FRONT

VENDOR? CENTRAL AUTO TRIM CO.

Asset Work Order History 10136354

CSHOP-2016-5723

Date Opened 12-8-2016 Date Finished 12-8-2016 Meter 1 Reading: 109,106

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2016-5800

Date Opened 12-12-2016 Date Finished 12-13-2016 Meter 1 Reading: 109,147

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

1 COMPRESSOR; 03-0602 COMPRESSOR U4735 4471
1 BELT; BELT

CSHOP-2016-989

Comments: **CARTS DEAD AT CRUZAN**

Date Opened 3-1-2016 Date Finished 3-9-2016 Meter 1 Reading: 107,965

TASKS PERFORMED

Q PARTS

BATTERY

1 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
1 BATTERY; BATTERY

CSHOP-2017-1394

Comments: **TIRES FOR SPECIAL EVENTS CART: 26-12X12 2 FRONTS 10169636 25-11X12 2 FRONTS 10182241**

Date Opened 3-6-2017 Date Finished 7-1-2017 Meter 1 Reading: 109,106

TASKS PERFORMED

Q PARTS

TIRE

2 TIR; TIR
2 TIR; TIR

CSHOP-2017-2029

Date Opened 4-6-2017 Date Finished 4-10-2017 Meter 1 Reading: 109,106

TASKS PERFORMED

Q PARTS

BATTERY
DOOR

4 1AD; BATTERY 31 SERIES

Service Requests:

04/06/2017 SERVICE REQUEST / 12: BROKEN / REPAIR

CSHOP-2017-4058

Date Opened 7-10-2017 Date Finished 7-10-2017 Meter 1 Reading: 109,106

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10136354

CSHOP-2017-4840

Comments: **USE A INSPECTION FORM**

Date Opened 8-18-2017 Date Finished 8-29-2017 Meter 1 Reading: 109,525

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2017-4848

Comments: **REPAIRS FROM PM**

Date Opened 8-18-2017 Date Finished 8-23-2017 Meter 1 Reading: 109,525

TASKS PERFORMED

Q PARTS

SIDE DOOR
WIPER BLADES
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
REPAIR FROM PM - 110 A/C
REPAIR FROM PM - A/C
VENT
LIGHT BAR
SIREN
INTERIOR TRIM-MOLDINGS-UPHOLS

2 1AN; WIPER BLADE 24 IN
1 2FL; LAMP ASSY W/STUDS
1 BOARD; CIRCUT BOARD MEDIC MASTER
1 2FL; AC
1 GRO; SOCKET
5 9XX; AC FREON 10174676
1 2FL; AC
1 5SC; RELAY 40A/30A 5PIN
1 2FL; AC
1 9IP; STROBE LINEAR REFLECTOR 6ELTUBE
1 9IP; MOLD L/H

CSHOP-2017-5098

Comments: **REPAIR TOP ON SPECIAL EVENTS CART**

Date Opened 8-30-2017 Date Finished 8-31-2017 Meter 1 Reading: 109,525

TASKS PERFORMED

Q PARTS

STRETCHER

1 9IP; STRECHER BAR NEW

CSHOP-2018-1301

Comments: **ON-CALL SPECIAL EVENTS CARTS**

Date Opened 3-5-2018 Date Finished 3-16-2018 Meter 1 Reading: 109,731

TASKS PERFORMED

Q PARTS

TRAILER

1 9AP; TRAILER JACK

Asset Work Order History 10136354

CSHOP-2018-157

Date Opened 1-8-2018 Date Finished 1-23-2018 Meter 1 Reading: 109,728

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	LMP; HALOGEN LAMP
HEADLIGHTS LOW BEAM	1	NONSTOCK; FREIGHT CHARGE
SHORELINE CHRAGER	1	9AP; BATTERY TENDER 20A
WINDOW REGULATOR	1	2FL; SCREW
	1	2FL; REGULATOR
	1	HANDLE; HANDLE-WINDOW

CSHOP-2018-1893

Date Opened 4-4-2018 Date Finished 4-4-2018 Meter 1 Reading: 109,731

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BUMPER FRONT

CSHOP-2018-3597

Comments: **INSPECT ONLY NO OIL / FILTERS USE "A" INSPECTION FORM AT ST25**

Date Opened 6-26-2018 Date Finished 8-9-2018 Meter 1 Reading: 110,207

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

CSHOP-2018-3729

Date Opened 7-3-2018 Date Finished 7-3-2018 Meter 1 Reading: 110,007

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	LMP; LAMP
HEADLIGHTS LOW BEAM		

Service Requests:

07/01/2018 LIGHTS / 38: SHORTED / EXCHANGE - NEW
HEAD LITE OUT. NO EVENTS THIS WEEK FOR THE RESCUES SO NO RUSH

CSHOP-2018-4390

Comments: **TIRES FOR SPECIAL EVENTS CARTS**

Date Opened 8-6-2018 Date Finished 8-14-2018 Meter 1 Reading: 110,207

TASKS PERFORMED

Q PARTS

TIRE	1	9AP; CARLISLE TIRE
	2	9AP; CARLISLE25X10124TIRES