10139601 2002 FORD TAURUS Car, Standard, 4 Door, Station Wagon

Workorder: 242044 Meter: In Date: 06/11/2002 Closed: 06/13/2002 Problem: CUT AND PROGRAMMED 2 KEYS **Parts List** - Cut And Programmed 2 Keys Qty - Shop Supplies 164-r0475 Ign Key 2010-earlier (don't Reorder) 2.00 Shop Supplies 1.00 Labor: 50.00 Hours 1.00 Parts: 44.90 Total: 94.90 06/12/2002 Workorder: 242140 Meter: In Date: 06/12/2002 Closed: 0 Problem: WASH VEHICLE - Wash Vehicle - Pre-delivery Inspection - Make Duplicate Keys For New Vehicle Hours 3.30 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 243151 Meter: 06/12/2002 Closed: In Date: 06/28/2002 Problem: 001 WASH TICKET ISSUED OUT 06/12/02 - 001 Wash Ticket Issued Out 06/12/02 Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 247347 Meter: In Date: 09/05/2002 Closed: 09/05/2002 Problem: VEHICLE TAG CHARGE **Parts List** - New Vehicle Tag Qty New Vehicle Tag 1.00 Hours 0.00 Labor: 0.00 Parts: 51.85 Total: 51.85 Workorder: 333306 Closed: Meter: 3199 In Date: 01/23/2003 01/27/2003 Problem: P.M.SERVICE - Pm Service **Parts List** Qty - Shop Supplies **Shop Supplies** 1.00 L/f Ph400 Frm Ph3600 Wix 51516 Oil Filter 1.00 10w30 Motor Oil 5.00 Hours 2.00 Labor: 100.00 Parts: 10.73 Total: 110.73 Workorder: 345611 Meter: 6569 In Date: 08/07/2003 Closed: 08/11/2003 Problem: P.M.SERVICE - P.m. Service. **Parts List** Qty - Shop Supplies **Shop Supplies** 1.00 L/f Ph400 Frm Ph3600 Wix 51516 Oil Filter 1.00 5w20 Engine Oil 5.00 61a P/steering Fluid 1.00 Hours 2.00 Labor: 100.00 Parts: 22.89 Total: 122.89

:

Workorder: Problem:	347439 WATER	LEAKII	Meter: NG ON F	6611 LOOR P	ASSENGER	SIDE	In Date:	09/05/2003	Closed:	09/08/20	003
- Transport & Floor P.side)	Pickup V	ehicle A	At Dealer	.(leaking \	Water On	Parts L Shop S					Qty 1.00
- Shop Suppli	es					•					
		Hours :	1.00		Labor:	50.00	Parts:	2.00	Total:	52.00	
Workorder:	353595		Meter:	8424			In Date:	12/19/2003	Closed:	12/23/20	003
Problem:	R/R TIRI	E FLAT	-USED F	FIX-A-FLA	T/NO LUG V	VRENCH	I				
- Repaired Ho	ole In Tire					Parts L	ist				Qty
- Cleaned Fix	A Flat Fro	om Insi	de Of Tir	e		Shop S	upplies				1.00
- Shop Suppli	es										
		Hours	1.50		Labor:	75.00	Parts:	2.00	Total:	77.00	
Workorder: Problem:	435616 P.M.SEF	RVICE.	Meter:	9174			In Date:	02/20/2004	Closed:	02/25/20	004
- Pm Service						Parts L	ist				Qty
- R&r Rear W	/blade,ins	tall Lug	g Wrench	In Truck.		Shop S	upplies				1.00
- Shop Suppli	es					G3802a	Fuel Filter l	Lbf G800 Wix	33097		1.00
						Ca8997	Air Filter Lb	of Af1683 Wix	52385		1.00
						L/f Ph40	00 Frm Ph36	600 Wix 5151	6 Oil Filter		1.00
						5w20 E	ngine Oil				5.00
						31-20 V	Viper Blades	20" Blade			1.00
						31-24 \	Wiper Blades	s 24" Blade			1.00
						Nb-18 '	Wiper Blade	s 18" Anco 3	1-18		1.00
		Hours :	2.25		Labor:	112.50	Parts:	44.74	Total:	157.24	
Workorder: Problem:	455484 P.M.SEF	RVICE	Meter:	11739			In Date:	08/27/2004	Closed:	08/31/20	004
- Pm Service						Parts L	ist				Qty
- Shop Suppli	es					Shop S	upplies				1.00
						Ca8997	Air Filter Lb	of Af1683 Wix	52385		1.00
						1516 C	il Filterfrm F	h3600 Wix 5	1516		1.00
						G3802a	Fuel Filter I	Lbf G800 Wix	33097		1.00
						5w20 E	ngine Oil				5.00
						31-20 V	Viper Blades	20" Blade			1.00
							Wiper Blades				1.00
		Hours :	2.00		Labor:	100.00	Parts:	44.19	Total:	144.19	
Workorder: Problem:	539324 P.M.SEF	RVICE	Meter:	13584			In Date:	03/17/2005	Closed:	03/18/20	005
- Pm Service						Parts L	ist				Qty
- Shop Suppli	es					Shop S	upplies				1.00
						1516 C	il Filterfrm F	h3600 Wix 5	1516		1.00
						5w20 E	ngine Oil				5.00
		Hours	2.00		Labor:	100.00	Parts:	17.84	Total:	117.84	

Workorder: Problem:	555055 P.M.SEI	RVICE	Meter:	16466			In Date:	09/15/2005	Closed:	09/19/20	005
- Pm Service	1					Parts Lis	st				Qty
- Shop Suppl						Shop Su					1.00
								of Af1683 Wix	52385		1.00
						1516 Oil	Filterfrm F	Ph3600 Wix 51	1516		1.00
						G3802a	Fuel Filter	Lbf G800 Wix	33097		1.00
						5w20 En	gine Oil				5.00
							-	s 20" Blade			1.00
						31-24 W	iper Blade	s 24" Blade			1.00
		Hours :	2.00		Labor:	100.00	Parts:	40.81	Total:	140.81	
Workorder: Problem:	637567 P.M. SE	RVICE.	Meter:	19599			In Date:	04/17/2006	Closed:	04/19/20	006
- Pm Service)					Parts Lis	st				Qty
- Replace Pc	v Valve.					Shop Su	pplies				1.00
- Shop Suppl	lies					1516 Oil	Filterfrm F	Ph3600 Wix 51	1516		1.00
						5w20 En	gine Oil				5.00
						Nb-18 W	/iper Blade	es 18" Anco 3	1-18		1.00
						31-20 Wi	iper Blades	s 20" Blade			1.00
						31-24 W	iper Blade	s 24" Blade			1.00
						D6tz6730	Da Drain P	lug			1.00
						1f1z6c32	24aa Pcv V	alve With Elbo)W		1.00
		Hours :	2.50		Labor:	125.00	Parts:	65.58	Total:	190.58	
Workorder: Problem:	648604 P.M. SE	RVICE.	Meter:	22911			In Date:	11/13/2006	Closed:	11/20/20	006
-		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	648827 P.M SEI	RVICE,	Meter: CHECK	22911 TIRES			In Date:	11/17/2006	Closed:	11/20/20	006
- Pm Service						Parts Lis	st				Qty
- Transmission	on Flush					Shop Su	pplies				1.00
- Fill Tires W/	/nitrogen					Ca8997	Air Filter Ll	of Af1683 Wix	52385		1.00
- Road Test						1516 Oil	Filterfrm F	Ph3600 Wix 51	1516		1.00
- Shop Suppl	ies							ner Don't Reo	rder		1.00
						10w30 M					5.00
								O 41 41-			16.00
						Syn/att T	rans Fluid	Synthetic			10.00
						Nb-18 W	/iper Blade	es 18" Anco 3	1-18		1.00
						Nb-18 W 31-20 Wi	/iper Blade iper Blades	es 18" Anco 3 s 20" Blade			1.00
		Hours				Nb-18 W 31-20 Wi	/iper Blade iper Blades iper Blades	es 18" Anco 3	ade	371.31	1.00

Workorder: 738196 In Date: 05/04/2007 Closed: 05/04/2007 Meter: 0 Problem: SISTERS TOWING & TRANSPORTATION TOW FROM 3650 SUMMI - Sisters Towing & Transportation Tow From 3650 Summit Blvd /far West Parking Lot - Tow To Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 738201 Meter: 24498 In Date: 05/04/2007 Closed: 05/07/2007 Problem: TOWED IN, NO START - Test Starting And Charging Sys. Charge And Test **Parts List** Qty Battery.r&r Load Battery. **Shop Supplies** 1.00 - Shop Supplies Group 58r Battery (mtc Bxt-58r) 1.00 Hours 1.00 Labor: 55.00 Parts: 95.40 Total: 150.40 Workorder: 740476 Meter: 25012 In Date: 06/22/2007 Closed: 06/28/2007 Problem: P.M SERVICE - Pm Service Complete Repl Fuel Filter. Parts List Qty - Serpentine Belt Cracks Dryrotted Repl To Correct Problem. Shop Supplies 1.00 - Index The L/frt Tire 180deg Away Fr Valve, hispeed Bal Jk6856aa Fan Belt 1.00 4tiresto Correct Vibration In Front & Rear Of Vehicle Over 50 1516 Oil Filterfrm Ph3600 Wix 51516 1.00 Mph G3802a Fuel Filter Lbf G800 Wix 33097 1.00 - R/r Tire Flat-nail Throught Tire-remv Tire Fr Wheel,repair 5w20 Engine Oil 6.00 Same From Inside To Correct Problem. 31-20 Wiper Blades 20" Blade 1.00 - Wheel Alignment Complete To Correct L/pulling Condition And Center The Steering Wheel On A Level Roadway. 31-24 Wiper Blades 24" Blade 1.00 - Shop Supplies Total: 475.56 Hours 7.30 Labor: 401.50 Parts: 74.06 Workorder: 834225 Meter: 27788 In Date: 02/14/2008 Closed: 02/22/2008 Problem: P.M SERVICE - Pm Service **Parts List** Qty - Mirror Inoper. Remove Door And Replace Mirror Switch Shop Supplies 1.00 - Pressure Test And Inspect Cooling System. Flush And Ca8997 Air Filter Lbf Af1683 Wix 52385 1.00 Refill System 1516 Oil Filterfrm Ph3600 Wix 51516 1.00 - Rotate, High Speed Balance And Nitro Fill All 4 Tires G3802a Fuel Filter Lbf G800 Wix 33097 1.00 - Shop Supplies 5w20 Engine Oil 5.00 Nb-18 Wiper Blades 18" Anco 31-18 1.00 31-20 Wiper Blades 20" Blade 1.00 31-24 Wiper Blades 24" Blade 1.00 Power Mirror Switch 1.00

Labor: 360.00

Hours 6.00

Antifreeze Ext/life All Makes (peak 407)

Parts: 82.06

1.00

Total: 442.06

Workorder: Problem:	844550 P.M. SER\	Meter: /ICE.TOWED	30292 IN,STALLED			In Date:	09/22/2008	Closed:	09/30/20	800
- Pm Service					Parts Lis	st				Qty
		e System,repla			Shop Sup	oplies				1.00
Cylinder,leaki Drive.	ng Fluid.flus	h & Bleed Bra	ke System &	Test	1516 Oil	Filterfrm F	Ph3600 Wix 5	1516		1.00
	ear Gate Wir	ndow;glass W	ould Not Stav		G3802a I	Fuel Filter	Lbf G800 Wix	33097		1.00
Open.replace			odia Not Otay		Master C	ylinder				1.00
			ace Faulty Fue		1401 Bra	ake Fluid E	Brake Fluid			1.00
Relay & Ignition Intermittent.	on Relay Wit	th New. Relay	s Are Corrode	ed &	5w20 Eng			5.00		
	Speed Bala	nce 4 Tires.ni	tro Fill Tires		Nb-18 W	1-18		1.00		
- Shop Suppl	•	1100 4 11100.111	uo i ili ilioo.			•	s 20" Blade			1.00
Onop Ouppi	100						s 24" Blade			1.00
						ss Suppor	τ			2.00
	ш	ours 7.40		Lobor	Relay 444.00	Dorto:	259.22	Total	703.22	2.00
	:	ouis 7.40		Labor.	444.00	raits.	209.22	TOlai.	103.22	
Workorder:	844551	Meter:	0			In Date:	09/22/2008	Closed:	09/22/20	008
(library In Mil-	•	· Tow To Lv S ours 0.00	Shop	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	937057 P.M SERV	Meter: ICE,BRAKES	32472 MAKE NOISE			In Date:	04/27/2009	Closed:	04/30/20	009
- Pm Service					Parts Lis	st				Qty
			surface Rotors		Shop Sup	oplies				1.00
Calipers.flush	•				1516 Oil	Filterfrm F	Ph3600 Wix 5	1516		1.00
		Tires. Nitro F	·III.		Qc610 Bi	rake Pads	Ray Pgd610r			1.00
- Shop Suppl	ies					Front Pads	s Taurus			1.00
					5w20 Eng	-				5.00
							s 20" Blade			1.00
						•	s 24" Blade			1.00
					Tire Disp			(T 04)		4.00
		44.00)r16 Assur Coi		4 407 45	4.00
	H-	ours 11.00		Labor:	660.00	Parts:	507.15	l otal:	1,167.15)
Workorder: Problem:	943390 Nail in L/R	Meter:	34496			In Date:	09/17/2009	Closed:	09/21/20	009
D = = = i = 1 /= +i		tire.								
 Repair L/r ti 	re.	tire.			Parts Lis	st				Qty
- Repair L/r ti		tire.			Parts Lis					Qty

Problem:	1001200 P.M service.	Meter:	36168	In Date:	02/02/2010	Closed:	02/10/20	010
- P.m service				Parts List				Qty
- Rotate & ba	lance all four ti	ires.		Shop Supplies				1.00
- Shop Suppli	ies			1516 Oil Filterfrm F	Ph3600 Wix 5	1516		1.00
				G3802a Fuel Filter	Lbf G800 Wix	33097		1.00
				5w20 Engine Oil				5.00
	Hou	rs 3.00	Labor:	<u> </u>	18.04	Total:	198.04	
Workorder: Problem:	1008651 Pm service.A	Meter: also see not	38371 es on brake noises.	In Date:	08/11/2010	Closed:	08/20/20	010
- Perform pm	service.			Parts List				Qty
- Clean and b	ouff debri from		pads.clean and lube	Shop Supplies				1.00
	and bleed syst			1516 Oil Filterfrm F	Ph3600 Wix 5	1516		1.00
	balance all fou	r tires.		5w20 Engine Oil				5.00
- Shop Suppli	ies			31-20 Wiper Blades	s 20" Blade			1.00
				31-24 Wiper Blade	s 24" Blade			1.00
				Nb-18 Wiper Blade	es 18" Anco 3	1-18		1.00
	Hou	rs 5.00	Labor:	300.00 Parts:	28.55	Total:	328.55	
Vorkorder: Problem:	1102420 Pm service a	Meter: Iso see not	40650 es on washer fluid and	In Date: I tire pressure warnin	03/03/2011 ig light.	Closed:	03/10/20	011
- Perform pm	service.			Parts List				Qt
- Inspect and	replace failed	windshield	washer hose	Shop Supplies				1.00
•			and adjust spray jets.	W/w Hose Jets-stru	ıt Tower			1.00
	balance all fou	r tires.		1516 Oil Filterfrm F	Ph3600 Wix 5	1516		1.00
- Shop Suppli	ies			G3802a Fuel Filter	Lbf G800 Wix	33097		
								1.00
				5w20 Engine Oil				
					es 18" Anco 3	1-18		5.00
				5w20 Engine Oil		1-18		5.00 1.00
				5w20 Engine Oil Nb-18 Wiper Blade	s 20" Blade	1-18		1.00 5.00 1.00 1.00
				5w20 Engine Oil Nb-18 Wiper Blade 31-20 Wiper Blades	s 20" Blade	1-18		5.00 1.00 1.00 1.00
	Hou :	rs 3.75	Labor:	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blade Fuel Line Clip	s 20" Blade		280.05	5.00 1.00 1.00 1.00
	Hou : 1109645 P.M. service	Meter:	42812	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blade Fuel Line Clip	s 20" Blade s 24" Blade		280.05	5.00 1.00 1.00 1.00 1.00
Problem:	: 1109645 P.M. service	Meter:	42812	5w20 Engine Oil Nb-18 Wiper Blade 31-20 Wiper Blade 31-24 Wiper Blade Fuel Line Clip 225.00 Parts:	s 20" Blade s 24" Blade 55.05	Total:		5.00 1.00 1.00 1.00 1.00
Problem: - Perform pm	: 1109645 P.M. service service.	Meter: and idles ro	42812	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blade Fuel Line Clip 225.00 Parts:	5 20" Blade es 24" Blade 55.05 09/08/2011	Total:	09/15/20	5.00 1.00 1.00 1.00 1.00
Problem: - Perform pm - Computer di	: 1109645 P.M. service service.	Meter: and idles ro	42812 bugh at times.	5w20 Engine Oil Nb-18 Wiper Blade 31-20 Wiper Blade 31-24 Wiper Blade Fuel Line Clip 225.00 Parts: In Date: Parts List	5 20" Blade s 24" Blade 55.05 09/08/2011	Total:	09/15/20	5.00 1.00 1.00 1.00 1.00
Problem: Perform pm Computer dialled cam syr Perform indi	: 1109645 P.M. service service. iagnose for rouncronizer and couction service.	Meter: and idles ro ugh idle cor cam sensor and clean t	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction Contents In Date:	5 20" Blade s 24" Blade 55.05 09/08/2011	Total:	09/15/20	5.00 1.00 1.00 1.00 1.00 011 Qty 1.00
Problem: Perform pm Computer diailed cam syr Perform indiush all fuel in	: 1109645 P.M. service service. iagnose for rouncronizer and couction service shipectors and clean	Meter: and idles rough idle cor cam sensor and clean tear codes w	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction Clause C	5 20" Blade s 24" Blade 55.05 09/08/2011 Cleaner Soft Cleaner	Total: Closed: (use Bg Ka8	09/15/20	5.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: Perform pm Computer dialled cam syr Perform indiush all fuel in Rotate and I	: 1109645 P.M. service service. iagnose for rouncronizer and couction service sijectors and cleabalance all fou	Meter: and idles rough idle cor cam sensor and clean tear codes w	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction County 408 Fuel Injection County Shop Supplies	5 20" Blade s 24" Blade 55.05 09/08/2011 Cleaner Soft Cleaner	Total: Closed: (use Bg Ka8	09/15/20	5.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0
Problem: - Perform pm - Computer diailed cam syr - Perform indush all fuel in - Rotate and I	: 1109645 P.M. service service. iagnose for rouncronizer and couction service sijectors and cleabalance all fou	Meter: and idles rough idle cor cam sensor and clean tear codes w	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction C 408 Fuel Injection C Shop Supplies 1516 Oil Filterfrm F	5 20" Blade s 24" Blade 55.05 09/08/2011 Cleaner Soft Cleaner	Total: Closed: (use Bg Ka8	09/15/20	5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - Perform pm - Computer diailed cam syr - Perform indulush all fuel in - Rotate and I	: 1109645 P.M. service service. iagnose for rouncronizer and couction service sijectors and cleabalance all fou	Meter: and idles rough idle cor cam sensor and clean tear codes w	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction Classes 408 Fuel Injection Classes 516 Oil Filterfrm Filter List Ca8997 Air Filter List	5 20" Blade s 24" Blade 55.05 09/08/2011 Cleaner Soft Cleaner	Total: Closed: (use Bg Ka8	09/15/20	5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
 Perform pm Computer dialled cam syr Perform indiallesh all fuel in 	: 1109645 P.M. service service. iagnose for rouncronizer and couction service sijectors and cleabalance all fou	Meter: and idles rough idle cor cam sensor and clean tear codes w	42812 bugh at times. ncern.test and replace with new. rottle body.power	5w20 Engine Oil Nb-18 Wiper Blades 31-20 Wiper Blades 31-24 Wiper Blades Fuel Line Clip 225.00 Parts: In Date: Parts List L17025 Induction Co 408 Fuel Injection Co Shop Supplies 1516 Oil Filterfrm F Ca8997 Air Filter List 5w20 Engine Oil	5 20" Blade s 24" Blade 55.05 09/08/2011 Cleaner Soft Cleaner	Total: Closed: (use Bg Ka8	09/15/20	5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

:

Workorder: Problem:	1204174 P.M. service a	Meter: and creakir	45862 ng noise over	bumps in	front of	In Date: car and roug	05/02/2012 gh idle at times	Closed:	05/16/2012	2
- P.m. Service	е.				Parts L	ist			(Qty
- Test battery	and charging	system.rep	lace bad batte	ery.	Shop St	upplies			1	.00
	e under vehicle		abilizer bar		1516 O	il Filterfrm P	h3600 Wix 51	516	1	.00
•	subframe bolts				G3802a	Fuel Filter I	Lbf G800 Wix	33097	1	.00
 Perform pov drive. 	ver balance tes	st.replace s	park plugs an	nd test	09997 I	Brake Clean	1		1	.00
	st cooling syste	m renlace	leaking coola	nt	Wd40 S	Spray Lube S	Stock# 405540	0002	1	.00
reservoir,top o		лплеріасс	icaning coola		5w20 E	ngine Oil			5	00.
- Rotate and I	balance all tires	S.			Spark P	lugs			6	00.
- Shop Suppli	ies				Group 5	58r Battery (ı	mtc Bxt-58r)		1	.00
					Sway B	ar Link			1	.00
					Sway B	ar Link			1	.00
					Coolant	Bottle			1	.00
	Hour :	rs 8.50		Labor:	510.00	Parts:	314.85	Total:	824.85	
Workorder: Problem:	1211621 Pm service.	Meter:	48592			In Date:	12/03/2012	Closed:	12/14/2012	2
- Perform pm	service.				Parts L	ist			(Qty
-	d replace dama	age asset r	numbers to fro	ont	5w20 Eı	ngine Oil			5	.00
windshield.	•				Ph3600	Oil Filter Lb	of		1	.00
- Rotate and I	balance all foui	r tires.			31-24 V	Niper Blades	s 2		1	.00
- Shop Suppli	ies				31-20 W	Viper Blades	20		1	.00
					31-18 W	Viper Blades	18		1	.00
					G3802a	Fuel Filter I	Lb		1	.00
					Mac Wit	te Lithium G	res		1	.00
					Shop St	upplies			1	.00
	Hour :	rs 4.00		Labor:	240.00	Parts:	58.09	Total:	298.09	
Workorder: Problem:	1212063 1 - Detail Veh	Meter: icle Wash	48517 Ticket(s) Issu	ed		In Date:	12/13/2012	Closed:	12/13/2012	2
- 1 - Detail Ve	ehicle Wash Tid	cket(s) Issu	ıed							
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1301628 Right rear tire	Meter: going flat.	49055			In Date:	02/14/2013	Closed:	02/21/2013	3
- Replace and	d balanceright i	rear tire.			Parts L	ist			(Qty
- Shop Suppli	ies				738571	571 P215-60	Or16		1	.00
• • •					Shop St	upplies			1	.00
					-	posal Fee			1	.00
	Hour :	rs 1.00		Labor:		•	145.54	Total:	205.54	

1301654 Workorder: Meter: 49002 In Date: 02/14/2013 Closed: 02/15/2013 Problem: Service - Tire Service 4730 Maine st., Lake Worth - Service Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1307158 Meter: 50819 In Date: 07/17/2013 Closed: 07/31/2013 **Problem:** P.M. service and strong odor of gas after driving and lfet rear window inop. - P.m. Service. **Parts List** Qty - R&r fuel tank and replace leaking fuel pump. 5w20 Engine Oil 5.00 - Replace failed left rear window motor. Napagold Oil Filter 1.00 - Test battery and charging system.replace bad battery. 31-20 Wiper Blades 20 1.00 - Rotate and balance all four tires. 31-24 Wiper Blades 2 1.00 - Shop Supplies Wiper Blade 1.00 Napagold Fuel Filter 1.00 **Brake Cleaner** 1.00 Fuel Pum 1.00 Group 58r Battery Mtc 1.00 Window Lift Motor 1.00 **Shop Supplies** 1.00 Hours 8.00 Labor: 480.00 Parts: 723.11 Total: 1,203.11 Workorder: 1404950 Meter: 53762 In Date: 05/21/2014 Closed: 06/04/2014 **Problem:** Pm service. Check for overheating and check tires. - P.m. Service. **Parts List** Qty - Pressure test and inspect cooling system.replace defective 5w20 Engine Oil 5.00 thermopstat and gasket.flush and refill system. Napagold Oil Filter 1.00 - Replace rear glass lift supports. 31-24 Wiper Blades 2 1.00 - Rotate and balance all tires. Wiper Blade 1.00 - Shop Supplies Wiper Blade 1.00 1.00 Napagold Fuel Filter Engine Seal 12oz 1.00 Peak Global 2.00 Thermostat 1.00 Support 2.00 1.00 Thermostat Seal Fuel Line Clip 1.00 **Thermostat** 1.00 Gasket 1.00 **Shop Supplies** 1.00

Labor: 360.00

Parts: 177.53

Total: 537.53

Hours 6.00

Workorder: 1504711 Meter: 58479 Problem: Pm service.		In Date:	05/08/2015	Closed:	05/14/2015
- Pm service.		Parts List			Qty
- Perform transmission service.replace filter.flush and r	efill	5w20 Engine Oil			5.00
transmission fluid.		Napagold Oil Filter			1.00
- Replace and balance all four tires.		Napagold Fuel Filte	er		1.00
- Perform complete wheel alignment.test drive.		Wiper Blade			1.00
- Shop Supplies		Wiper Blade			1.00
		31-24 Wiper Blade	s 2		1.00
		Syn-atf Trans Fluid	S		16.00
		Trans Filter Kit			1.00
		738571571 P215-6	0r16		4.00
		Shop Supplies			1.00
		Tire Disposal Fee			4.00
Hours 9.00 I	_abor:	540.00 Parts:	731.10	Total:	1,271.10
Workorder: 1511686 Meter: 61037 Problem: P.M. Service.		In Date:	11/16/2015	Closed:	11/24/2015
- Pm service.		Parts List			Qty
- Check electrical and starting system.battery failed		Group 58 Battery M	ltc		1.00
loadtest.replace defective battery and burnt maxi fuse.		5w20 Engine Oil			5.00
- Rotate and balance all four wheels.		Napagold Oil Filter			1.00
- Shop Supplies		Wiper Blade			1.00
		Wiper Blade			1.00
		Wiper Blade			1.00
		Napagold Air Filter			1.00
		Datter			1.00
		Battery			1.00
		Maxi Fuse			1.00
		•			

Workorder: 1605444 Meter: 63441		In Date:	05/26/2016	Closed:	06/09/201	16
Problem: P.M. service and rear wiper missing.						
- P.m. Service.		Parts List				Qty
- A/c performance test.replace leaking /noisy		5w20 Engine Oil			į	5.00
compressor, accumulator and orifice tube. vaccum and	t	Napagold Oil Filte	er		•	1.00
recharge system to specs.		Napagold Fuel Fil	ter			1.00
- Clean and polish headlamp lenses.		Wiper Blades 24"				1.00
- Rotate and balance all tires.		18" wiper blades				1.00
- Shop Supplies		Wiper			•	1.00
		Wheel Center Ca	p			1.00
		Orifice Tube				1.00
		R134a Lv Shop 2			2	2.00
		E8 A/c Oil Univ W	Dye		•	1.00
		V-ribbed Belt	•			1.00
		New Comprssr W	Clutch			1.00
		Accumulator W H				1.00
		Shop Supplies				1.00
Hours 8.50	Labor:		s: 379.85	Total:	889.85	
:			10/01/0010	<u> </u>	44/04/004	
Workorder: 1611241 Meter: 65276 Problem: P.M. service and check engine light or	n .antenn	In Date: a sticks.ants	10/31/2016	Closed:	11/21/201	16
- P.m. Service.	,	Parts List				O41
	n.t					Qty
 Diagnose check engine light.p1507.perform pin poir test.replace defective lac valve.clear codes. 	H	5w20 Engine Oil				5.00 1.00
- Replace power attennea mast.		Napagold Oil Filte	;I			1.00 1.00
- Rotate and balance all tires.		Wiper Blades 24"				
- Shop Supplies		18" wiper blades				1.00
5 37 5311 53		Wiper				1.00
		Valve Asy				1.00
		Antenna Mast				1.00
		Shop Supplies	0.10.1.1	-		1.00
Hours 6.50 :	Labor:	390.00 Part	s: 219.14	l otal:	609.14	
Workorder: 1703656 Meter: 67391 Problem: P.M. Service.		In Date:	04/11/2017	Closed:	04/20/201	17
- P.m. Service.		Parts List				Qty
- F.III. OCIVICE.						5.00
		5w20 Engine Oil			Į.	
- Repair left front tire.rotate and balance all four.		5w20 Engine Oil Napagold Oil Filte	er			
		Napagold Oil Filte			•	1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil				1.00 1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24"				1.00 1.00 1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24" 18" wiper blades				1.00 1.00 1.00 1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24" 18" wiper blades Wiper				1.00 1.00 1.00 1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24" 18" wiper blades Wiper Wd40 Spr				1.00 1.00 1.00 1.00 1.00
- Repair left front tire.rotate and balance all four.		Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24" 18" wiper blades Wiper Wd40 Spr Wheel Cap				1.00 1.00 1.00 1.00 1.00 1.00
- Repair left front tire.rotate and balance all four.	l obor:	Napagold Oil Filte Napagold Fuel Fil Wiper Blades 24" 18" wiper blades Wiper Wd40 Spr Wheel Cap Shop Supplies		Takali		1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1706885 Rear liftgate v	Meter: vill not stay	68549 up and right f	ront wind		In Date:	07/13/2017	Closed:	07/31/2017
- Diagnoise rig	ght front windo	w inop.r&r	defective wind	low	Parts Lis	t			Qty 2.00
- Test and rep	lace rear liftga	te struts.			Window L	ift Motor			1.00
- Shop Suppli	es				Lift-suppo				2.00
					Lift-suppo				2.00
					Shop Sup				1.00
	Houi	rs 1.80		Labor:	108.00	•	246.89	Total:	354.89
Workorder: Problem:	1710743 P.M. service.	Meter:	69513			In Date:	10/31/2017	Closed:	11/16/2017
- P.m. service	ı.				Parts Lis	t			Qty
 Front and rear ball joints failed .remove front lower balljoint and rear upper ball joints, replace with new.left front inner tie 					5w20 Eng	gine Oil			5.00
and rear uppe rod end failed.	r ball joints, rep r&r with new	place with	new.left front ir	nner tie	Napagold	Oil Filter			1.00
	ig light inop .r8	r with new	,		Wiper Bla	ides 24"			1.00
•	nigh speed bal				18" wipe	r blades			1.00
	ur wheeel aligi		ui tiics.		Wiper				1.00
- Shop Suppli	J	iiiioiii.			Bulb				1.00
опор очррп	C 3				Ball Joint				4.00
						Inner Tie Rod End			1.00
					Shop Sup	plies			1.00
	Houi :	s 12.00		Labor:	720.00	Parts:	371.57	Total:	1,091.57
Workorder: Problem:	1801188 A/C not coolir	Meter:	70262 traps for roden	t inside		In Date:	01/31/2018	Closed:	02/08/2018
- Perform hva	c performance	test.cools	to 50 degrees.		Parts Lis	t			Qty
			spec.retest coo	ling to	Freon Lv	Shop 1			3.00
- Remove glo	d .set traps ,no	ebris from	heater box and	d under	Shop Sup	pplies			1.00
111		s 2.50		Labor:	150.00	Parts:	20.63	Total:	170.63

	305734 .M. service	Meter: and towed i	70915 in for no start.			In Date:	06/05/2018	Closed:	06/21/2018
- P.m. Service.					Parts Li	st			Q
- Test battery an	d charging	svstem.rep	lace bad batte	rv.	Napago	ld Oil Filter			1.0
- Resurface from				.,.	. •	ngine Oil			5.0
pads.replace rea	r brake roto			rs.flush		ld Fuel Filte	er		1.0
and bleed systen	n.				Wiper		•		1.0
- Rotate and bala					•	lades 24"			1.0
- Shop Supplies					•	er blades			1.0
						Oot 3-32oz			1.0
						Oil Stop Lea	ak		1.0
					battery	o 0.0p 20.	A		4.0
					Real Bra	ake Pad			4.0
						ake Rotor			8.0
					Brake C				4.0
					Brake C	•			5.0
					Pad	alipei			5.0
					Shop Su	ınnlies			1.0
	Hou	rs 10.00		Labor:	600.00		1,926.83	Total:	2,526.83
Problem: Si Co - Tow From: 428	ontact: Tod 39 Cherry R	d 662-6542		Labor:	0.00	Parts:	0.00	Total:	0.00
	:								
Workorder: 19 Problem: Pl	900747 M Service	Meter:	72053			In Date:	01/18/2019	Closed:	02/07/2019
- P.m. service.									
					Parts Li	st			Q
- Test and replace	ce washer h	ose . Fill w	asher fuild . Re	∍test .		st ngine Oil			Q : 5.0
- R&r defective b					5w20 Er	-			
- R&r defective bengine . Retest .	ooth valve g	askets . Cle	ean excess oil	off	5w20 Er	ngine Oil			5.0
- R&r defective bengine . Retest Rotate and bala	ooth valve g	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper	ngine Oil			5.0 1.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B	ngine Oil ld Oil Filter			5.0 1.0 1.0
- R&r defective bengine . Retest Rotate and bala	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B 18" wip	ngine Oil ld Oil Filter lades 24"			5.0 1.0 1.0 1.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B 18" wipe Wheel C	ngine Oil ld Oil Filter lades 24" er blades	ng		5.0 1.0 1.0 1.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va	ngine Oil Id Oil Filter lades 24" er blades Center Cap	•		5.0 1.0 1.0 1.0 1.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B 18" wipe Wheel C W W Va Valve C	ngine Oil ld Oil Filter lades 24" er blades Center Cap cuum Tubir	net		5.0 1.0 1.0 1.0 1.0 2.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va Valve C Upperp	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir	net ket		5.0 1.0 1.0 1.0 1.0 2.0 16.0
- R&r defective bengine . Retest Rotate and bala Tpms.	ooth valve g ance all fou	askets . Cle	ean excess oil	off	5w20 Er Napagol Wiper Wiper B 18" wipe Wheel C W W Valve C Upperp Valve C	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl	net ket		5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0
- R&r defective bengine . Retest . - Rotate and bala - Poms.	ooth valve g	askets . Cle	ean excess oil	off et	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va Valve C Upperp	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl over Gaske	net ket	Total:	5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0
- R&r defective bengine . Retest Rotate and bala Tpms Shop Supplies	ooth valve g ance all fou Hou : 902469	r tires . Nitro	ean excess oil	off et	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va Valve C Upperp Valve C Shop Su	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl over Gaske	net ket t	Total:	5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0 2.0
- R&r defective bengine . Retest Rotate and balations Shop Supplies Workorder: 19 Problem: Tr	Hou : 902469 ransition Pro	r tires . Nitro	ean excess oil ofill all and res	off et	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va Valve C Upperp Valve C Shop Su	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl over Gaske upplies Parts:	net ket t 199.23		5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0 2.0 1.0
- R&r defective bengine . Retest Rotate and balations Shop Supplies Workorder: 19	Hou : 902469 ransition Pro	r tires . Nitro rs 6.10 Meter: ep Charge	ean excess oil ofill all and res	off et Labor:	5w20 Er Napagol Wiper Wiper B 18" wipe Wheel C W W Va Valve Co Upperp Valve Co Shop Su 408.70	ngine Oil Id Oil Filter Iades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl over Gaske upplies Parts: In Date:	net ket t 199.23 03/05/2019	Closed:	5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0 2.0 1.0 607.93
- R&r defective bengine . Retest Rotate and baland Tpms Shop Supplies Workorder: 19 Problem: Tr	Hou : 902469 ransition Pro	r tires . Nitro	ean excess oil ofill all and res	off et Labor:	5w20 Er Napago Wiper Wiper B 18" wip Wheel C W W Va Valve C Upperp Valve C Shop Su	ngine Oil Id Oil Filter lades 24" er blades Center Cap cuum Tubir over Gronr Intake Gasl over Gaske upplies Parts:	net ket t 199.23 03/05/2019	Closed:	5.0 1.0 1.0 1.0 1.0 2.0 16.0 3.0 2.0 1.0