

**Palm Beach County Fleet Management
Asset Maintenance History**

10174389 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 838184 **Meter:** 0 **In Date:** 05/07/2008 **Closed:** 05/07/2008
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 846340 **Meter:** 3136 **In Date:** 10/30/2008 **Closed:** 11/06/2008
Problem: P.M.SERVICE

- Pm Service

Parts List **Qty**

- Test Drive

Shop Supplies 1.00

- Shop Supplies

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

Hours 3.25 Labor: 195.00 Parts: 38.68 Total: 233.68
:

Workorder: 934471 **Meter:** 5095 **In Date:** 02/26/2009 **Closed:** 03/09/2009
Problem: CHECK ENGINE LIGHT STAYS ON

- C/s Ck Engine Light Stays On; Verify Concern; Ids Test
Code P2135 - Defective Tp Sensor

Parts List **Qty**

Shop Supplies 1.00

- Transport & Pick Up Vehicle At Dealer For Warranty -
Defective Tp Sensor

- Shop Supplies

Hours 2.45 Labor: 147.00 Parts: 2.00 Total: 149.00
:

Workorder: 939219 **Meter:** 7347 **In Date:** 06/18/2009 **Closed:** 06/22/2009
Problem: P.M.SERVICE

- Pm Service

Parts List **Qty**

- Install New Decal

Shop Supplies 1.00

- Shop Supplies

Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 8.00

Used Firex Refurbed Fire Extingshers 1.00

Hours 3.00 Labor: 180.00 Parts: 91.52 Total: 271.52
:

Workorder: 946897 **Meter:** 10123 **In Date:** 12/10/2009 **Closed:** 12/15/2009
Problem: P.M.SERVICE,LOW TIRE PRESSURE

- P.m.

Parts List **Qty**

- C/c: low tire pressure. Verify. Nail in front right tire. Remove
nail, dismount tire,patch, mount, balance, add 75 Spi fo N2,
rotate to right rear.

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

- Shop Supplies

5w20 Engine Oil 8.00

Hours 3.75 Labor: 225.00 Parts: 60.63 Total: 285.63
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1005996 **Meter:** 13923 **In Date:** 06/08/2010 **Closed:** 06/22/2010
Problem: P. M.

- P. M. Service.	Parts List	Qty
- Removed visor & Led light assy. Disassembled light, repaired connector, reassembled & reinstalled light & visor.	Shop Supplies	1.00
- Installed driving sticker.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Transport & pick up vehicle at dealer. L/rear signal, cargo light & L/front head light inop.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Dealer warranty repair only. L/side head light, cargo light & L/rear signal light inop.	5w20 Engine Oil	8.00
- Shop Supplies	Nb-19 Wiper Blades 19" Anco 31-19	2.00
	Used Firex Refurbed Fire Extingshers	1.00

Hours 6.50 Labor: 390.00 Parts: 73.79 Total: 463.79
:

Workorder: 1007470 **Meter:** 14374 **In Date:** 07/15/2010 **Closed:** 07/19/2010
Problem: Passenger side brake light out.

- Replace right rear brake light bulb.	Parts List	Qty
	3157 Tail Light Bulbs	1.00

Hours 0.50 Labor: 30.00 Parts: 1.11 Total: 31.11
:

Workorder: 1012153 **Meter:** 16042 **In Date:** 10/29/2010 **Closed:** 10/29/2010
Problem: Nail in front passenger side tire.

- Repair right front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1013803 **Meter:** 16655 **In Date:** 12/15/2010 **Closed:** 12/22/2010
Problem: P.M.SERVICE

- P. M. Service.	Parts List	Qty
- Replace 4 tires & reprogram Tpm.	Shop Supplies	1.00
- 3rd brake light bulb.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	1066 White Lithium (crc 05037)	1.00
	5w20 Engine Oil	8.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00

Hours 5.75 Labor: 345.00 Parts: 799.71 Total: 1,144.71
:

Workorder: 1100167 **Meter:** 16792 **In Date:** 01/05/2011 **Closed:** 01/11/2011
Problem: flash canceiver

- reflash canceiver and reprogram	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1102097	Meter: 17476	In Date: 02/23/2011	Closed: 03/14/2011
Problem: C/C: STARTER NOT WORKING			
- Jump start. Recharge battery. Test battery systems. Found defective battery.	Parts List		Qty
	Shop Supplies		1.00
- Transport & pick up vehicle at dealer for battery warranty.			
- Dealer To Replace Defective Battery.			
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1102636	Meter: 17562	In Date: 03/09/2011	Closed: 03/22/2011
Problem: DEFECTIVE FLOOR MAT			
- Transport & pick up vehicle at dealer (defective floor mat).	Parts List		Qty
- Dealer to replace defective floor mat.	Shop Supplies		1.00
- Shop Supplies			
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			
Workorder: 1106063	Meter: 19725	In Date: 06/08/2011	Closed: 06/17/2011
Problem: P. M. SERVICE			
- P. M. Service.	Parts List		Qty
- Verify, nail in front right tire. Dismount, patch, mount, balance, & add N2.	Shop Supplies		1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00
	1372 Oil Filter Frm Ph2 Wix 51372		1.00
	5w20 Engine Oil		8.00
	Nb-19 Wiper Blades 19" Anco 31-19		2.00
Hours 3.75	Labor: 225.00	Parts: 59.88	Total: 284.88
:			
Workorder: 1200981	Meter: 23329	In Date: 01/31/2012	Closed: 01/31/2012
Problem: P. M. SERVICE			
- P. M. Service.	Parts List		Qty
- Verify, nail in f/r tire. Dismount, patch, mount, balance, rotate to r/r.	Shop Supplies		1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372		1.00
	5w20 Engine Oil		8.00
	Nb-19 Wiper Blades 19" Anco 31-19		2.00
Hours 3.75	Labor: 225.00	Parts: 43.25	Total: 268.25
:			
Workorder: 1208792	Meter: 28352	In Date: 09/14/2012	Closed: 09/27/2012
Problem: P.M.SERVICE,CHECK ENGINE LIGHT STAYS ON,STALLS,CARGO LIGHT INOP.			
- pm	Parts List		Qty
- replace cargo light bulb	Shop Supplies		1.00
- ck ok engine light is on stalls scan and found code # p2135	1372 Oil Filter Frm Ph2 Wix 51372		1.00
ck found tsb for code p2135 send to dealer for warranty	G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00
- transport and pick up vehicle at dealer defective throttle position sensor	Ca10262 Air Filter Mtc Fa1883 Wix 49883		1.00
- Shop Supplies	5w20 Engine Oil		8.00
	Nb-19 Wiper Blades 19" Anco 31-19		2.00
	Used Firex Refurbed Fire Extingshers		1.00
Hours 6.75	Labor: 405.00	Parts: 69.48	Total: 474.48
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1209988 **Meter:** 28792 **In Date:** 10/18/2012 **Closed:** 10/22/2012
Problem: passenger brake light out

- repair wire harness for right rear brake light **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1210468 **Meter:** 29138 **In Date:** 10/30/2012 **Closed:** 11/08/2012
Problem: A/C ONLY WORKS ON #4/ CHECK DOME LIGHT

- ck ac only works on # 4 verify concern perform pinpont test and found bad ac blower resister replace blower resistor **Parts List** **Qty**
Yh1715 A-c Blower Res 1.00
- replace dome light bulb Shop Supplies 1.00
- Shop Supplies

Hours 3.25 Labor: 195.00 Parts: 34.21 Total: 229.21
:

Workorder: 1304726 **Meter:** 33597 **In Date:** 05/10/2013 **Closed:** 05/29/2013
Problem: P.M.SERVICE,W/WIPERS WOULD COME ON PERIODICALLY ON THEIR OWN.

- pm **Parts List** **Qty**
- replace 4 tires Napa Quart 5w20 8.00
- ck wiper would coime on intermittently perform pinpoint and found bad multifunction switch replace multifunction switch Napagold Oil Filter 1.00
Napagold Fuel Filter 1.00
- fill all tires wioth nitrogen 31-19 Wiper Blades 19 2.00
- Shop Supplies 179636492 Lt245-75r17 4.00
Switch 1.00
Shop Supplies 1.00
Tire Disposal Fee 4.00

Hours 9.50 Labor: 570.00 Parts: 1,137.13 Total: 1,707.13
:

Workorder: 1305723 **Meter:** 33852 **In Date:** 06/10/2013 **Closed:** 06/14/2013
Problem: W/WIPERS & WASHER MOTOR COME ON INTERMITTENTLY.

- C/s: Windshield wipers comes on intermittently. Perform pinpoint test & found short circuit in wiper module. Replace wiper motor assembly. **Parts List** **Qty**
Wiper Motor Assembly 1.00
Shop Supplies 1.00
- Shop Supplies

Hours 3.50 Labor: 210.00 Parts: 151.48 Total: 361.48
:

Workorder: 1309334 **Meter:** 37249 **In Date:** 09/13/2013 **Closed:** 09/18/2013
Problem: battery/had to jump2x today

- recharge battery test charging sys rr battery **Parts List** **Qty**
- Shop Supplies Battery 1.00
05023 Battery Cleaner 1.00
Bat Term Protector 1.00
Shop Supplies 1.00

Hours 0.75 Labor: 45.00 Parts: 132.50 Total: 177.50
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1400218	Meter: 41608	In Date: 01/08/2014	Closed: 01/09/2014
Problem: air in tire			
- ck low air light on inspect all tires and valve stems correct all n2 levels clear tpms light	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1400625	Meter: 42926	In Date: 01/17/2014	Closed: 02/12/2014
Problem: P.M.SERVICE/SEE NOTE			
- pm	Parts List		Qty
- replace tool box lid support	Napa Quart 5w20		8.00
- replace strobe light bulb inside visor	Napagold Oil Filter		1.00
- replace utilidty light bulb in back of truck	Wiper Blade		2.00
- repair both rear tires	Used Fire X Refurbished		1.00
- Shop Supplies	Napagold Air Filter		1.00
	Support		2.00
	20mr8 12 v fl23		2.00
	Napagold Fuel Filter		1.00
	Shop Supplies		1.00
Hours 8.25	Labor: 495.00	Parts: 160.01	Total: 655.01
:			
Workorder: 1411023	Meter: 49033	In Date: 11/04/2014	Closed: 11/10/2014
Problem: P.M.SERVICE			
- pm	Parts List		Qty
- verify moisture in headlight asm replace headlight asm front passanger	Napagold Oil Filter		1.00
- Shop Supplies	Napa Quart 5w20		8.00
	Halogen Lamp		1.00
	Shop Supplies		1.00
Hours 3.25	Labor: 195.00	Parts: 48.70	Total: 243.70
:			
Workorder: 1505349	Meter: 51821	In Date: 05/28/2015	Closed: 06/04/2015
Problem: pm			
- pm	Parts List		Qty
- repair right rear brake light 3rd brake light and both utility bed light	Napagold Oil Filter		1.00
- install hows my driving decal	Napa Quart 5w20		8.00
- Shop Supplies	Wiper Blade		2.00
	Used Fire X Refurbished		1.00
	Napagold Air Filter		1.00
	Napagold Fuel Filter		1.00
	Bulb		1.00
	Bulb		3.00
	Shop Supplies		1.00
Hours 4.50	Labor: 270.00	Parts: 82.04	Total: 352.04
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1512408 **Meter:** 55240 **In Date:** 12/09/2015 **Closed:** 12/17/2015

Problem: pm, battery keeps dying, install cooler reack

- pm	Parts List	Qty
- ck and replace battery ck charging sys	Napagold Oil Filter	1.00
- replace body mounts	Napa Quart 5w20	8.00
- test drive after repair	Washer Fluid Concentr	1.00
- install water cooler bracket	Battery	1.00
- Shop Supplies	Body Mount Kit	2.00
	Body Mount Kit	4.00
	12"x14/18tpi Blade	2.00
	saw blade, pkg of 5 dw4811	1.00
	Shop Supplies	1.00
Hours 11.25	Labor: 675.00	Parts: 696.32
:		Total: 1,371.32

Workorder: 1604818 **Meter:** 58981 **In Date:** 05/06/2016 **Closed:** 05/17/2016

Problem: Right tail lamp inop.

- Test and replace defective right tail lamp bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.78
:		Total: 30.78

Workorder: 1605830 **Meter:** 59595 **In Date:** 06/07/2016 **Closed:**

Problem: Pm service.

-		
Hours 0.00	Labor: 0.00	Parts: 0.00
:		Total: 0.00

Workorder: 1605831 **Meter:** 59595 **In Date:** 06/07/2016 **Closed:**

Problem: Pm service.

-		
Hours 0.00	Labor: 0.00	Parts: 0.00
:		Total: 0.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605835 **Meter:** 59893 **In Date:** 06/07/2016 **Closed:** 06/14/2016
Problem: P m service

- Pm service.
- Replace damage trailer socket ,wire harness,socket and repair bracket.replace pintle pin.
- Replace and balance four tires.
- Fill all tires with nitrogen.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Washer Fluid Concentr	1.00
Wiper Blade Anco	2.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Pintle Pin W/chain	1.00
trailer plug	1.00
Vinyl Electrical Tape	1.00
Wire Term 16-14 Blt	10.00
Term 24-22 Conn	10.00
179636492 Lt245-75r17	4.00
Def Fluid 2.5	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours 9.25 Labor: 555.00 Parts: 1,130.16 Total: 1,685.16
:

Workorder: 1702227 **Meter:** 63865 **In Date:** 03/03/2017 **Closed:** 03/13/2017
Problem: PM Service.Power outlet broken.

- Pm Service.
- Install steering wheel cover.
- Repair front right tire.rotate and balance all.correct N2.relearn Tpms
- C/c power plug inop.test plug.verify complain.replace cig. lighter plug.
- Replace two tag light lenses
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade Anco	2.00
Used Fire X Refurbished	1.00
Drain Plug	1.00
Stg Wheel Cov - Ford	1.00
Soket Pauer Outlet	1.00
Ring	1.00
Lamp Asy	2.00
Shop Supplies	1.00

Hours 6.75 Labor: 405.00 Parts: 131.84 Total: 536.84
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1708308 **Meter:** 64562 **In Date:** 08/23/2017 **Closed:** 08/28/2017
Problem: PM Service.Dead battery,Radio inop.

- Pm Service.	Parts List	Qty
- Replace left headlamp.	Napagold Oil Filter	1.00
- Jump start vehicle.test battery and charging systemreplace battery and service cables.	Napa Quart 5w20	8.00
- Performfront and rear brake job.cut rotors.lube and service slides and calipers.repack front wheel bearings and replace grease seals.	Wiper Blade Anco	2.00
- Trace radio power circuits and replace 2 blown fuses to radio.	Washer Fluid Concentr	1.00
- Rotate and balance four tires.	Napagold Fuel Filter	1.00
- Clean corroded wires to trailer connector and repack with dielectric grease.	Halogen Lamp	1.00
- Repair oil cooler (fins damage) with a fin comb back to specs.	Battery	1.00
- Shop Supplies	Pads	1.00
	Rear Pads	1.00
	Non-chlor Brake Clnr	1.00
	Wheel Seal - Front Wheel	2.00
	Shop Supplies	1.00
Hours 19.00	Labor: 1,140.0	Parts: 345.22
:	0	Total: 1,485.22

Workorder: 1709213 **Meter:** 65895 **In Date:** 09/22/2017 **Closed:** 09/25/2017
Problem: wont fuel

- Test and remove canceiver issue fuel card	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1800530 **Meter:** 68278 **In Date:** 01/17/2018 **Closed:** 01/29/2018
Problem: Dead battery.Radio inop.Right side tail lamp.

- Repair right side brake lamp.	Parts List	Qty
- Repair radio.replace fuse.	Bulb	1.00
- Recharge battery.check charging system and found no problem at this time.battery tested ok.	Atm-20 Fuse	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.50	Labor: 150.00	Parts: 6.38
:		Total: 156.38

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802672 **Meter:** 69456 **In Date:** 03/12/2018 **Closed:** 03/29/2018
Problem: PM Service Strobe lights inop.

- Pm Service.	Parts List	Qty
- Diagnose strobe lights inop.found and replace bad toggle switch.	Reflex Truck Shock	2.00
- Rplace missing brake pedal pad.	Napagold Air Filter	1.00
- Rotate and balance four tires.	Napagold Oil Filter	1.00
- Replace both rear shocks.	Napa Quart 5w20	8.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Wiper Blade Anco	2.00
	Washer Fluid Concentr	1.00
	Toggle Switch	1.00
	Pedal Pad	1.00
	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 202.12
:		Total: 637.12

Workorder: 1805183 **Meter:** 70915 **In Date:** 05/18/2018 **Closed:** 05/30/2018
Problem: Left rear tire flat.

- Repair and balance left rear tire.nitrogen fill all.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1806867 **Meter:** 71726 **In Date:** 07/05/2018 **Closed:** 07/30/2018
Problem: ABS problem and TPMS light on.

- C/s Abs light onscan and found code #c1155 Pinpointtest and found bad Abs wheel speed sensor.replace both front Abs sensors and clear codes	Parts List	Qty
- Repair left fronr tire.	Sensor Asy	2.00
- Test drive before and after repairs	Shop Supplies	1.00
- Shop Supplies		
Hours 5.00	Labor: 300.00	Parts: 155.09
:		Total: 455.09

Workorder: 1809236 **Meter:** 72609 **In Date:** 09/07/2018 **Closed:** 09/18/2018
Problem: PM Service..Noisy suspension.

- Pm Service.	Parts List	Qty
- C/s Noises in front end .check and found bad shocks.replace both front shocks.	Napa Quart 5w20	8.00
- Rotate and balance all tires	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Gas Grande Fleet Shoc	2.00
	Gas Grande Shock	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 4.50	Labor: 270.00	Parts: 291.28
:		Total: 561.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810196 **Meter:** 73270 **In Date:** 10/01/2018 **Closed:** 11/30/2018
Problem: AC Problem.

- Ac performance and leak test.vacume and recharge to specs.replace bad ac compressor clutch,had to reseal system **Parts List** **Qty**
- Shop Supplies Freon Sr Shop 2.00
Red Angel Ac Stop Lk 1.00
disc mag 1.00
Shop Supplies 1.00

Hours 4.50 Labor: 301.50 Parts: 116.16 Total: 417.66
:

Workorder: 1900268 **Meter:** 73291 **In Date:** 01/07/2019 **Closed:** 02/11/2019
Problem: Belt noise when turning.

- Diagnose for belt noise.adjust power steering pump pulley to correct depth on shaft to align with belt. **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 2.00 Labor: 134.00 Parts: 3.00 Total: 137.00
:

Workorder: 1902123 **Meter:** 73291 **In Date:** 02/25/2019 **Closed:** 02/26/2019
Problem: not fixing it, new asset on order, put in transition

- Tow From: Sr shop To: Vista-transition

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1902544 **Meter:** 73291 **In Date:** 03/07/2019 **Closed:** 03/07/2019
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 134.00 Parts: 0.00 Total: 134.00
: