

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 646735

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 10/05/2006	Hours	Description
Close Date: 10/05/2006	Quantity	
- Pre-Delivery Inspection	2.30	
- Make Duplicate Keys For New Vehicle		
Parts Charge: 0.00	Labor Charge: 16.50	

Workorder: 646935

Problem: INSTALL VISE, LADDER RACK AND FLOOR MATS

Meter Reading: 81	Labor	Parts
In Date: 10/10/2006	Hours	Description
Close Date: 12/14/2006	Quantity	
- Install Vise,Ladder Rack Floor Mats And Move Keg Holder.	8.00	WTG1425-3 RACK LADDER,ALUM. RBW10044903 SHELF 34 1/8X16"
- Shop Supplies		6C3Z2513086C FLOOR MATS SHOP SUPPLIES RBW10044863 SHELF 23X16"
Parts Charge: 955.48	Labor Charge: 440.00	

Workorder: 648780

Problem: INSTALL SPOT MIRRORS.

Meter Reading: 98	Labor	Parts
In Date: 11/16/2006	Hours	Description
Close Date: 11/20/2006	Quantity	
- Install Two Spot Mirrors.	0.25	7039D SPOT MIRROR VELVAC 723060
Parts Charge: 2.72	Labor Charge: 13.75	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 736476

Problem: P.M. SERVICE.DETAIL.CHECK ENGINE LIGHT ON.

Meter Reading: 3200 In Date: 04/02/2007	Close Date: 04/10/2007	Labor Hours	Description	Parts	Quantity
- Pm Service		6.70	15/40 OIL		15.00
- Nitro Service 6 Tires			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Ck Eng Lgt On Scan Codes-P0460 Found.Fuel Level Input			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
Sensorsensor Malfunction.Fuel Gauge Reads Full.Ck			SHOP SUPPLIES		1.00
Fleet Fuel Sys Records.Send T/Deal			10003 INJECTOR CLEANER DON'T REORDER		1.00
- Transport Vehicle To Dealer For Check Engine					
Light(Reprogrampcm)					
- Shop Supplies					
Parts Charge:		93.68	Labor Charge:		33.00

Workorder: 745256

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 7968 In Date: 10/05/2007	Close Date: 10/26/2007	Labor Hours	Description	Parts	Quantity
- Pm Service,Repl Airfilter,Fuel Filter,Wiper Blades,Fire		6.80	CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
Extinguisher,Fuel Additive Rotated Tires			31-20 WIPER BLADES 20" BLADE		2.00
- Hi Speed Balance On 6 Tires			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Water Was Not Draining Out Of Truck Bed.Drilled 2 Holes			10003 INJECTOR CLEANER DON'T REORDER		1.00
Toward Front Of Bed To Let Water Drain			15/40 OIL		15.00
- Coordinate Cable Step Installation.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Shop Supplies			CA9516 AIR FILTER LBF LAF1646 WIX 42731		1.00
			39-58051 CABLE STEP		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		396.51	Labor Charge:		30.00

Workorder: 746103

Problem: WELD ON REAR STEP

Meter Reading: 7968 In Date: 10/23/2007	Close Date: 10/30/2007	Labor Hours	Description	Parts	Quantity
- Weld Step On Rear Bumper		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		60.00

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 837003

Problem: P.M SERVICE.DETAIL

Meter Reading: 12329	Labor	Parts		
In Date: 04/15/2008	Hours	Description	Quantity	
- Pm Service	7.00	15/40 OIL	15.00	
- Rotate And Balance All 6 Tires.		CA9516 AIR FILTER LBF LAF1646 WIX 42731	1.00	
- Transmission Service Flush With New Fluid.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00	
		SYN/ATF TRANS FLUID SYNTHETIC	17.00	
		SHOP SUPPLIES	1.00	
		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00	
Parts Charge:	204.90	Labor Charge:	90.00	

Workorder: 837711

Problem: TUFF-COAT PAINT & BODY

Meter Reading: 0	Labor	Parts		
In Date: 04/21/2008	Hours	Description	Quantity	
- Tuff-Coat Paint & Body				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 276.00

Workorder: 845140

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 16093	Labor	Parts		
In Date: 10/03/2008	Hours	Description	Quantity	
- Pm Service	10.00	PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00	
- Remove Headache Bar And Ladder Rack To Reseal Bolt Holes, Leaking Water Into Bins.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
- Check Batteries & Charging Sys.R&R Both Defective Batteries.		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00	
- Rotate And High Speed Balance All 6 Tires.Nitro Fill Tires.		31-20 WIPER BLADES 20" BLADE	2.00	
- Shop Supplies		15/40 OIL	15.00	
		GROUP 65 BATTERY (MTC BXT-65-850)	2.00	
		SHOP SUPPLIES	1.00	
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
		66BR CLEAR SILICONE	3.00	
Parts Charge:	384.90	Labor Charge:	90.00	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 945096

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 23805	Labor	Parts	
In Date: 10/27/2009	Hours	Description	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 96.00	

Workorder: 1000900

Problem: Check engine light on.

Meter Reading: 25522	Labor	Parts	
In Date: 01/25/2010	Hours	Description	Quantity
- Perform Computer Diagnostics, Run Egr Flow Test, Remove Egr Valve & Decoke Egr System, Reprogram Pcm With Updated Calibration. Test Drive.	3.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 180.00		

Workorder: 1004506

Problem: P.M service, check ladder rack, Detail.

Meter Reading: 27963	Labor	Parts	
In Date: 05/03/2010	Hours	Description	Quantity
- P.M Service.	6.75	19006R MARKER LIGHT 4" RECTANGULAR RED LED	1.00
- Inspect & Reseal Ladder Rack Mounting Plates.		FUEL FILTER HOUSING / 6C3Z9B249A	1.00
- Test & Replace R/R Led Brake/Turn Lamp, Test & Replace Two Body Marker Lamps & Bases.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Replace Water Seperator Housing Due To Excessive Corrosion.		66BR CLEAR SILICONE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		15/40 OIL	15.00
		44202R TAIL LIGHT 4" RED 42 LED	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
		19006Y MARKER LIGHT 4" RECT YELLOW LED	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Parts Charge: 297.23	Labor Charge: 405.00		

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1004665 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 27963	Labor	Parts
In Date: 05/05/2010	Hours	Description
Close Date: 05/05/2010	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 96.00

Workorder: 1011262 **Problem:** Pm service,also see notes on detail.

Meter Reading: 31615	Labor	Parts
In Date: 10/13/2010	Hours	Description
Close Date: 10/20/2010	Quantity	
- Perform Pm Service.	13.00	GROUP 65 BATTERY (MTC BXT-65-850)
- Install Six New Tires.Nitrogen Fill And Balance All Six.		TIRE DISPOSAL FEE
- Test Starting And Charging System.Batteries Failed Load		7312 OIL FILTERFRM CH9549 WIX 57312
Test After Recharge.Replace Both Failed Batteries With		CS9667A FUEL FILTER LBF L4604F WIX 33899
New.		15/40 OIL
- Perform Wheel Alignment Complete.		CA9516 AIR FILTER LBF LAF1646 WIX 42731
- Inspect Loose Front Wheel Bearings.Repack And Adjust		09997 BRAKE CLEAN
Both Front Wheel Bearings.		31-20 WIPER BLADES 20" BLADE
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E
		SHOP SUPPLIES
Parts Charge: 1,506.05	Labor Charge: 780.00	

Workorder: 1011758 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 31615	Labor	Parts
In Date: 10/20/2010	Hours	Description
Close Date: 10/20/2010	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 97.92

Workorder: 1013364 **Problem:** Heater inop.

Meter Reading: 32462	Labor	Parts
In Date: 12/03/2010	Hours	Description
Close Date: 12/08/2010	Quantity	
- Diagnose Heater Control System.R&R Glove Box And	2.50	SHOP SUPPLIES
Replace Defective Blend Door Actuator.		BLEND DOOR ACTUATOR
- Shop Supplies		
Parts Charge: 51.71	Labor Charge: 150.00	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1104618

Problem: Pm service also detail vehicle.

Meter Reading: 35941		Labor		Parts	
In Date: 04/29/2011	Close Date: 05/10/2011	Hours	Description	Quantity	
-	Perform Pm Service.	5.50	15/40 OIL		15.00
-	Rotate And Balance All Four Tires.		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	Shop Supplies		CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		122.96	Labor Charge:	330.00	

Workorder: 1107738

Problem: Check engine light on.

Meter Reading: 37666		Labor		Parts	
In Date: 07/22/2011	Close Date: 08/15/2011	Hours	Description	Quantity	
-	Computer Diagnose For Check Engine Light On.Test And Replace Failed Egr Valve With New.Clean And Flush Egr Port With Bg Flush Kit .Clear Codes With Scan Tool And Road Test.	5.00	SHOP SUPPLIES		1.00
-	Shop Supplies		DPKQ7 EGR SERVICE KIT (BG PRODUCTS)		1.00
			EGR VALVE		1.00
Parts Charge:		421.40	Labor Charge:	300.00	

Workorder: 1112644

Problem: P.M. service and replace wiper blades.

Meter Reading: 40409		Labor		Parts	
In Date: 11/30/2011	Close Date: 12/12/2011	Hours	Description	Quantity	
-	Perform Pm Service.	6.00	SHOP SUPPLIES		1.00
-	Inspect And Replace Failed Right Rear Led Brake Lamp With New.		1401 BRAKE FLUID BRAKE FLUID		1.00
-	Rotate,Nitrogen Fill And Balance All Six Tires.		D3TZ2457B BRAKE PEDAL PAD		1.00
-	Shop Supplies		CA9516 AIR FILTER LBF LAF1646 WIX 42731		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			44202R TAIL LIGHT 4" RED 42 LED		1.00
			15/40 OIL		15.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Parts Charge:		213.78	Labor Charge:	360.00	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1202896

Problem: Left rear outer tire flat.

Meter Reading: 42891	Labor	Parts	
In Date: 03/26/2012	Hours	Description	Quantity
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1205252

Problem: P.M. service and detail.

Meter Reading: 44540	Labor	Parts	
In Date: 06/05/2012	Hours	Description	Quantity
- P.M. Service.	6.00	SHOP SUPPLIES	1.00
- Replace Left Front Marker Light On Utility Box.		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
- Rotate And Balance Six Tires.		19006Y MARKER LIGHT 4" RECT YELLOW LED	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00
		15/40 OIL	15.00
Parts Charge:	131.35	Labor Charge:	360.00

Workorder: 1205631

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 44514	Labor	Parts	
In Date: 06/13/2012	Hours	Description	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	97.92

Workorder: 1207972

Problem: Missing fuel cap.

Meter Reading: 46473	Labor	Parts	
In Date: 08/22/2012	Hours	Description	Quantity
- Replace Missing Fuel Cap.	0.25	FUEL CAP	1.00
Parts Charge:	33.17	Labor Charge:	15.00

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1211304

Problem: Towed in for no crank no start.

Meter Reading: 48818	Labor	Parts
In Date: 11/21/2012	Hours	Quantity
Close Date: 11/28/2012	Description	
- Test Starting And Charging System.Both Batteries Failed	2.00	1.00
Load Test After Recharge.Replace Both Failed Batteries		2.00
With New.		
- Shop Supplies		
Parts Charge:	289.22	
Labor Charge:	120.00	

Workorder: 1211351

Problem: NO START

Meter Reading: 48501	Labor	Parts
In Date: 11/21/2012	Hours	Quantity
Close Date: 11/26/2012	Description	
- Tow From: Airport Hilton (Australian And Belvedere) To: Lv Shop		
Parts Charge:	0.00	
Labor Charge:	0.00	
Commercial Charge:		134.77

Workorder: 1211497

Problem: Pm service and Check charging system intermittent.

Meter Reading: 48843	Labor	Parts
In Date: 11/29/2012	Hours	Quantity
Close Date: 12/14/2012	Description	
- Perform Pm Service.	9.00	1.00
- Test Starting And Charging System.Test And Replace		2.00
Failed Alternator Assembly And Corroded Central Junction		1.00
Block With New.		1.00
- Rotate Annd Balance All Six Tires.		1.00
- Shop Supplies		15.00
		1.00
		1.00
Parts Charge:	817.95	
Labor Charge:	540.00	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1306121

Problem: Pm service.Wiper blades.Reseal water leak under ladder rack.

Meter Reading: 52957 In Date: 06/19/2013	Close Date: 06/27/2013	Labor Hours	Description	Parts	Quantity
- P.M. Service.		8.50	31-20 WIPER BLADES 20		2.00
- Remove Ladder Rack And Seal Water Leak Under Rack.Reinstall.			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
- Diagnose And Repair Wiring For Right Side Body Marker Light.			NAPAGOLD OIL FILTER		1.00
			15-40 OIL		15.00
- Rotate And Balance All Tires.			CLR RTV SILCN SEALANT		2.00
- Shop Supplies					
Parts Charge:		117.60	Labor Charge:		510.00

Workorder: 1312766

Problem: Pm service.Fuel smells in cab while driving.

Meter Reading: 57256 In Date: 12/23/2013	Close Date: 01/28/2014	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		10.00	SHOP SUPPLIES		1.00
- Computer Diagnose For Misfire And Fuel Smells.Test And Replace Failed Leaking #6 Injector And Fuel Rail Seals With New.Clear Codes With Scan Tool And Road Test.			15-40 OIL		15.00
			NAPAGOLD FUEL FILTER		1.00
			USED FIRE X REFURBISHED		1.00
- Rotate And Balance All Six Tires.			GASKET		2.00
			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			INJECTOR NOZZLE		1.00
			VALVE COVER GASKET		1.00
			NAPAGOLD FUEL FILTER		1.00
			WIPER BLADE		2.00
			3C3Z6766CA OIL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			DIESEL FUEL FIL CAP		1.00
			WIPER BLADE		2.00
			PM-22-A ADDITIVE DIES		1.00
Parts Charge:		559.91	Labor Charge:		600.00

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1405109

Problem: Check engine light on.

Meter Reading: 60228	Labor	Parts	
In Date: 05/27/2014	Hours	Description	Quantity
- Diagnose Check Engine	3.00	SHOP SUPPLIES	1.00
Light.P0611,P0261,P0279.Perform Pin-Point Test		REMAN MODU	1.00
.Replace And Reprogram Ficm Module.Clear Codes And Test Drive.			
- Shop Supplies			
Parts Charge: 1,001.85		Labor Charge: 180.00	

Workorder: 1407194

Problem: P.M. Service.

Meter Reading: 61252	Labor	Parts	
In Date: 07/22/2014	Hours	Description	Quantity
- Perform Pm Service.	9.25	TIRE DISPOSAL FEE	2.00
- Replace Two Tires,Rotate And Balance All Six.		NAPAGOLD OIL FILTER	1.00
- Inspect And Test Electrical Circuit For Right Brake Light		SHOP SUPPLIES	1.00
Ok.Replace Failed Right Brake Lamp .		FUEL FILTER	1.00
- Perform Wheel Alignment Complete.		LT245/75R17 HANKOOK TIRE	2.00
- Shop Supplies		SIGNAL STOP LAMP	1.00
		WASHER FLUID CONCENTR	1.00
		44202R TAIL LIGHT 4IN	1.00
		WIPER BLADE	2.00
		CASTER-CAMBER BUSHING	1.00
		15-40 OIL	15.00
Parts Charge: 767.91		Labor Charge: 555.00	

Workorder: 1408018

Problem: Core charge for FICM Module (w/o #1405109)

Meter Reading: 61252	Labor	Parts	
In Date: 08/13/2014	Hours	Description	Quantity
-			
Parts Charge: 0.00		Labor Charge: 0.00	

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1410634

Problem: ladder rack

Meter Reading: 63050	Labor	Parts	
In Date: 10/23/2014	Hours	Description	
Close Date: 10/28/2014		Quantity	
- Weld Broken Ladder Rack. Reseal All Accessories Mounted To Top Of Bins/R&R Head Ache Bar And Empty All Bins To Access	6.00	SHOP SUPPLIES PTEX ULTRA BLACK 30Z	1.00 1.00
- Shop Supplies			
Parts Charge:	9.68	Labor Charge:	360.00

Workorder: 1412690

Problem: P.M. service.

Meter Reading: 64387	Labor	Parts	
In Date: 12/19/2014	Hours	Description	
Close Date: 01/06/2015		Quantity	
- Pm Service.	7.00	TIRE DISPOSAL FEE	4.00
- Replace Four Tires And Balance All Six.		SHOP SUPPLIES	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		WIPER BLADE	2.00
		LT245/75R17 HANKOOK TIRE	4.00
		3C3Z9A343A SEAL KIT	1.00
		USED FIRE X REFURBISHED	1.00
		15-40 OIL	15.00
		FUEL FILTER	1.00
Parts Charge:	1,236.26	Labor Charge:	420.00

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1506794

Problem: Pm service.

Meter Reading: 68897 In Date: 07/08/2015	Close Date: 07/28/2015	Labor Hours	Description	Parts	Quantity
- P.M. Service.		17.50	NAPAGOLD AIR FILTER		1.00
- Test Batteries And Charging System.Replace Both Bad Batteries.			WASHER FLUID CONCENTR		1.00
			PEAK GLOBAL		3.00
- Pressure Test And Inspect Cooling System.Flush And Refill System.			SHOP SUPPLIES		1.00
			FUEL FILTER		1.00
- Resurface Rear Brake Rotors,Replace Brake Pads.Service And Lube Calipers.Flush And Bleed System.Replace Leaking Left And Right Rear Hub Seals.			NAPA OIL SEAL		1.00
			BRAKE PADS REAR DUEL R		1.00
- Rotate And Abalnce All Six Tires.			BRAKE CLEANER		2.00
			15-40 OIL		15.00
- Shop Supplies			BATTERY		2.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
			NAPA OIL SEAL		1.00
	Parts Charge: 578.72	Labor Charge: 1,050.00			

Workorder: 1600857

Problem: P.M. Service.

Meter Reading: 73285 In Date: 01/26/2016	Close Date: 02/04/2016	Labor Hours	Description	Parts	Quantity
- Pm Service.		6.50	USED FIRE X REFURBISHED		1.00
- Replace Broken Tag Lamp Assembly On Utility Box.Fabricate Mounting And Wiring As Needed.			WASHER FLUID CONCENTR		1.00
			FUEL FILTER		1.00
- Rotate And Balance All Six Tires.			SHOP SUPPLIES		1.00
			22" WIPER BLADE		2.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			15-40 OIL		15.00
			LICENSE BRACKET W/LIGHT		1.00
	Parts Charge: 173.27	Labor Charge: 390.00			

1/3/2017
12:30:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164687 2006 FORD F350 Utility Body, 1 Ton

Workorder: 1608341

Problem: P.M. service and water leak right side .

Meter Reading: 77454	Labor	Parts	
In Date: 08/12/2016	Hours	Description	Quantity
- P.M. Service.	7.50	22" WIPER BLADE	2.00
- Check Water Leak In Right Front Of Utility Bed.R&R		WASHER FLUID CONCENTR	1.00
- Ladder Rack And Reseal Bin.Retest.		FUEL FILTER	1.00
- Rotate And Balance All Six Tires.		PTEX ULTRA BLACK 30Z	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		15-40 OIL	15.00
		NAPAGOLD OIL FILTER	1.00
		USED FIRE X REFURBISHED	1.00
Parts Charge:	171.80	Labor Charge:	450.00

Workorder: 1610833

Problem: Transition Prep Charge

Meter Reading: 78513	Labor	Parts	
In Date: 10/20/2016	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	10,736.84	Total Labor Charges:	9,626.25	Total Comm. Charges:	1,002.61
----------------------	------------------	----------------------	-----------------	----------------------	-----------------