

**Palm Beach County Fleet Management
Asset Maintenance History**

10169516 2008 FORD F350 Utility Body, 1 Ton, W/Winch

Workorder: 747300 **Meter:** 0 **In Date:** 11/13/2007 **Closed:** 11/13/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 838029 **Meter:** 5197 **In Date:** 05/05/2008 **Closed:** 05/13/2008
Problem: P.M SERVICE,CHECK HOLE IN SEAT

- Pm Service	Parts List	Qty
- Nitro Service,vacuum All 6 Tires And Nitro Fill	Shop Supplies	1.00
- Transport Vehicle To And Fr Dealer For Warranty Repair For Seat Leather.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00

Hours 6.90 Labor: 414.00 Parts: 114.60 Total: 528.60
:

Workorder: 839824 **Meter:** 6121 **In Date:** 06/10/2008 **Closed:** 06/16/2008
Problem: SEAT BELT WORN HOLE IN D/S SEAT

- To/fr Dealer For Warranty Repair To D/s Side Of Seat.(seat Belt Worn Hole In Side)	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

Workorder: 847391 **Meter:** 10201 **In Date:** 11/21/2008 **Closed:** 12/24/2008
Problem: P.M. SERVICE.SEE NOTE.

- Pm Service	Parts List	Qty
- Service Winch	Shop Supplies	1.00
- Rotate And Hi Speed Balance 6 Tires.nitrofill Tires.	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- To/fr Dealer For Recall #08b06.broken Door Ck Floor Mat And D/s Side Seat Hole Worn In It.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00

Hours 8.50 Labor: 510.00 Parts: 213.04 Total: 723.04
:

Workorder: 933757 **Meter:** 11420 **In Date:** 02/09/2009 **Closed:** 02/12/2009
Problem: RECALL 08B07 & 08B06

- To/fr Dealer For Recall 08b07	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 940276 **Meter:** 14633 **In Date:** 07/06/2009 **Closed:** 07/13/2009
Problem: P.M. Service.

- P.m service	Parts List	Qty
- Mount two new tires, rotate & balance all six tires	Shop Supplies	1.00
- Test tag lamp circuit. fabricate & repair ground circuit.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	Wd40 Spray Lube Stock# 405540002	1.00
	15/40 Oil	15.00
	Fuel Filter Housing Seal Kit	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
Hours 7.00	Labor: 420.00	Parts: 492.91
:		Total: 912.91

Workorder: 947441 **Meter:** 18791 **In Date:** 12/31/2009 **Closed:** 01/07/2010
Problem: PM SERVICE

- P.m service.	Parts List	Qty
- Mount four new tires, rotate & balance all six tires.	Shop Supplies	1.00
- Inspect & service winch.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Alignment.	Cs10263 Fuel Filter (use Cs10263a)	1.00
- Shop Supplies	15/40 Oil	15.00
	Floor Mats	1.00
	31-20 Wiper Blades 20" Blade	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tr416 Valve Stem	4.00
	Tire Disposal Fee	4.00
Hours 10.00	Labor: 600.00	Parts: 908.34
:		Total: 1,508.34

Workorder: 1002674 **Meter:** 19956 **In Date:** 03/10/2010 **Closed:** 03/16/2010
Problem: lft. r outside tire flat

- jp maintenance compound			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1007136 **Meter:** 22626 **In Date:** 07/07/2010 **Closed:** 07/16/2010
Problem: P.M. Service.Dome light inop.

- P.m. Service.	Parts List	Qty
- Replace dome lamp bulb.repair rear clearance light ground.	Shop Supplies	1.00
- Rotate and balance all six tires.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Inspect and service winch.	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	Used Firex Refurbed Fire Extingshers	1.00
	D3tz2457b Brake Pedal Pad	1.00
Hours 7.50	Labor: 450.00	Parts: 144.40
:		Total: 594.40

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1009075	Meter: 23557	In Date: 08/23/2010	Closed: 08/30/2010
Problem: Dead battery.			
- Test starting and charging system.batteries failed load test after recharge.replace both failed batteries with new.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	Group 65 Battery (mtc Bxt-65-850)		2.00
Hours 2.00	Labor: 120.00	Parts: 259.49	Total: 379.49
:			
Workorder: 1009100	Meter: 23381	In Date: 08/23/2010	Closed: 08/23/2010
Problem: No start			
- From: Lake Lytal Park To: Lv Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1100139	Meter: 26173	In Date: 01/04/2011	Closed: 01/13/2011
Problem: Pm service also see notes on blower speeds.			
- Perform pm service.	Parts List		Qty
- Fabricate and replace missing hitch pindel pin with new and secure.	Shop Supplies		1.00
	7312 Oil Filterfrm Ch9549 Wix 57312		1.00
- Diagnose and repair over heated blower motor wiring harness.test and replace failed blower switch and blower resistor with new.	Cs10263 Fuel Filter (use Cs10263a)		1.00
	15/40 Oil		15.00
- Rotate and balance all six tires.	31-20 Wiper Blades 20" Blade		2.00
- Inspect and service power winch.	A/c Blower Switch		1.00
- Shop Supplies	Yh1715 A/c Blower Resistor (motorcraft)		1.00
	18410 Pintle Pin		1.00
Hours 8.50	Labor: 510.00	Parts: 144.60	Total: 654.60
:			
Workorder: 1107547	Meter: 30785	In Date: 07/19/2011	Closed: 08/18/2011
Problem: Pm service and right center door on utility body damage.			
- P.m. Service.	Parts List		Qty
- Flush and refill transmission.	Pm-22-a Additive Diesel Fuel (m/craft)		1.00
- Replace left stop lamp assemble.	Shop Supplies		1.00
- Replace two tires,rotate and balance all six.	Ca10270 Air Filter Mtc Fa1886 Wix 49886		1.00
- Replace damaged right side bin door.transfer part and adjust stiker.	3963 Fuel Filter Frm Cs10263a Wix 33963		1.00
	7312 Oil Filterfrm Ch9549 Wix 57312		1.00
- Inspect and service winch.	8c3z9a343a Seal Kit Fuel Filter (ford)		1.00
- Shop Supplies	15/40 Oil		15.00
	Syn/atf Trans Fluid Synthetic		18.00
	31-20 Wiper Blades 20" Blade		2.00
	Used Firex Refurbed Fire Extingshers		1.00
	44202r Tail Light 4" Red 42 Led		1.00
	179636492 Lt245/75r17 Wrangler Sr-a E		2.00
	Tire Disposal Fee		2.00
	Right Center Utility Door (white With Hardwear)		1.00
Hours 11.50	Labor: 690.00	Parts: 1,680.14	Total: 2,370.14
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1201094 **Meter:** 34674 **In Date:** 02/01/2012 **Closed:** 02/22/2012
Problem: P.M. Service.Screw in left front tire.

<ul style="list-style-type: none"> - P.m. Service. - Replace four tires,rotate and and balance all six. - Test batteries and charging system.recharge and retest batteries,fail load test.replace defective batteries. - Replace leaking hydro-booster.flush and refill power steering system. - Pressure test and inspect cooling system.replace leaking upper radiator hose.flush and refill cooling system. - Inspect and service winch. - Complete wheel alignment.test drive. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> <tr><td>Upper Radiator Hose</td><td align="right">1.00</td></tr> <tr><td>7312 Oil Filterfrm Ch9549 Wix 57312</td><td align="right">1.00</td></tr> <tr><td>3963 Fuel Filter Frm Cs10263a Wix 33963</td><td align="right">1.00</td></tr> <tr><td>Brake Hydrobooster</td><td align="right">1.00</td></tr> <tr><td>15/40 Oil</td><td align="right">15.00</td></tr> <tr><td>Syn/atf Trans Fluid Synthetic</td><td align="right">2.00</td></tr> <tr><td>31-20 Wiper Blades 20" Blade</td><td align="right">2.00</td></tr> <tr><td>Group 65 Battery (mtc Bxt-65-850)</td><td align="right">2.00</td></tr> <tr><td>P/steering Seals</td><td align="right">4.00</td></tr> <tr><td>P/steering Hose</td><td align="right">4.00</td></tr> <tr><td>Antifreeze Ext/life All Makes (peak 407)</td><td align="right">2.00</td></tr> <tr><td>179636492 Lt245/75r17 Wrangler Sr-a E</td><td align="right">2.00</td></tr> <tr><td>Tire Disposal Fee</td><td align="right">2.00</td></tr> <tr><td>179636492 Lt245/75r17 Wrangler Sr-a E</td><td align="right">2.00</td></tr> <tr><td>Tire Disposal Fee</td><td align="right">2.00</td></tr> </tbody> </table>	Parts List	Qty	Shop Supplies	1.00	Upper Radiator Hose	1.00	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00	Brake Hydrobooster	1.00	15/40 Oil	15.00	Syn/atf Trans Fluid Synthetic	2.00	31-20 Wiper Blades 20" Blade	2.00	Group 65 Battery (mtc Bxt-65-850)	2.00	P/steering Seals	4.00	P/steering Hose	4.00	Antifreeze Ext/life All Makes (peak 407)	2.00	179636492 Lt245/75r17 Wrangler Sr-a E	2.00	Tire Disposal Fee	2.00	179636492 Lt245/75r17 Wrangler Sr-a E	2.00	Tire Disposal Fee	2.00
Parts List	Qty																																		
Shop Supplies	1.00																																		
Upper Radiator Hose	1.00																																		
7312 Oil Filterfrm Ch9549 Wix 57312	1.00																																		
3963 Fuel Filter Frm Cs10263a Wix 33963	1.00																																		
Brake Hydrobooster	1.00																																		
15/40 Oil	15.00																																		
Syn/atf Trans Fluid Synthetic	2.00																																		
31-20 Wiper Blades 20" Blade	2.00																																		
Group 65 Battery (mtc Bxt-65-850)	2.00																																		
P/steering Seals	4.00																																		
P/steering Hose	4.00																																		
Antifreeze Ext/life All Makes (peak 407)	2.00																																		
179636492 Lt245/75r17 Wrangler Sr-a E	2.00																																		
Tire Disposal Fee	2.00																																		
179636492 Lt245/75r17 Wrangler Sr-a E	2.00																																		
Tire Disposal Fee	2.00																																		
Hours 18.50 :	<table border="0"> <tr> <td>Labor: 1,110.0</td> <td>Parts: 1,584.19</td> <td>Total: 2,694.19</td> </tr> <tr> <td>0</td> <td></td> <td></td> </tr> </table>	Labor: 1,110.0	Parts: 1,584.19	Total: 2,694.19	0																														
Labor: 1,110.0	Parts: 1,584.19	Total: 2,694.19																																	
0																																			

Workorder: 1207267 **Meter:** 39120 **In Date:** 08/02/2012 **Closed:** 08/23/2012
Problem: P.M. service and check engine light on and cup holder broken.

<ul style="list-style-type: none"> - P.m. Service. - Replace broken cup holder. - Diagnose check engine light.perform pin point test.replace defective exhaust temp sensor.test and replace failed brake spressure switch.clear codes and test drive. - Rotate and balance six tires. - Inspect and service winch. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> <tr><td>7312 Oil Filterfrm Ch9549 Wix 57312</td><td align="right">1.00</td></tr> <tr><td>3963 Fuel Filter Frm Cs10263a Wix 33963</td><td align="right">1.00</td></tr> <tr><td>15/40 Oil</td><td align="right">15.00</td></tr> <tr><td>Cup Holder</td><td align="right">1.00</td></tr> <tr><td>Used Firex Refurbed Fire Extingshers</td><td align="right">1.00</td></tr> <tr><td>31-20 Wiper Blades 20" Blade</td><td align="right">2.00</td></tr> <tr><td>Brake Pressure Switch</td><td align="right">1.00</td></tr> <tr><td>Exhaust Temp Sensor</td><td align="right">1.00</td></tr> </tbody> </table>	Parts List	Qty	Shop Supplies	1.00	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00	15/40 Oil	15.00	Cup Holder	1.00	Used Firex Refurbed Fire Extingshers	1.00	31-20 Wiper Blades 20" Blade	2.00	Brake Pressure Switch	1.00	Exhaust Temp Sensor	1.00
Parts List	Qty																				
Shop Supplies	1.00																				
7312 Oil Filterfrm Ch9549 Wix 57312	1.00																				
3963 Fuel Filter Frm Cs10263a Wix 33963	1.00																				
15/40 Oil	15.00																				
Cup Holder	1.00																				
Used Firex Refurbed Fire Extingshers	1.00																				
31-20 Wiper Blades 20" Blade	2.00																				
Brake Pressure Switch	1.00																				
Exhaust Temp Sensor	1.00																				
Hours 12.00 :	<table border="0"> <tr> <td>Labor: 720.00</td> <td>Parts: 298.78</td> <td>Total: 1,018.78</td> </tr> </table>	Labor: 720.00	Parts: 298.78	Total: 1,018.78																	
Labor: 720.00	Parts: 298.78	Total: 1,018.78																			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1301516 **Meter:** 43920 **In Date:** 02/12/2013 **Closed:** 03/11/2013
Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Replace broken tag lamp and bracket.repair wiring.	15-40 Oil	15.00
- Replace leaking left rear axle seal.	Oil Filter	1.00
- Diagnose check engine light.replace defective #5 glow plug.clear codes and retest.	Napagold Fuel Filter	1.00
- Inspect and service winch.	31-20 Wiper Blades 20	2.00
- Rotate and balance six tires.	05023 Battery Cleaner	1.00
- Shop Supplies	L0135-063 Lubriplate	1.00
	License Plate Brkt	1.00
	26330 Tag Light Tkr L	1.00
	Brake Cleaner	2.00
	12345841 Gear Oil Syn	1.00
	Seal	1.00
	Glow Plug	1.00
	Shop Supplies	1.00
Hours 11.50	Labor: 690.00	Parts: 199.10
:		Total: 889.10

Workorder: 1308806 **Meter:** 47312 **In Date:** 08/30/2013 **Closed:** 09/20/2013
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Test batteries and charging system.replace both bad batteries.	Radiator	1.00
- Pressure test and inspect cooling system.replace leaking radiator and lower hose.flush and refill cooling system.	lower hose	1.00
- Inspect and service winch.	Radiator Hose	1.00
- Rotate and balance all six tires.	Washer Nozzle	2.00
- Shop Supplies	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	31-20 Wiper Blades 20	2.00
	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
	Battery 65	2.00
	Peak Global	3.00
	Shop Supplies	1.00
Hours 14.50	Labor: 870.00	Parts: 1,482.37
:		Total: 2,352.37

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402617 **Meter:** 50923 **In Date:** 03/18/2014 **Closed:** 04/01/2014
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Replace and balance six new tires.	15-40 Oil	15.00
- Replace left tail lamp.	Napagold Oil Filter	1.00
- R&r front seat and send to upholstery shop for repairs.	Fuel Filter Ford Only	1.00
- Inspect and service winch.	Wiper Blade	2.00
- Complete wheel alignment.test drive.	Brake Cleaner	1.00
- Shop Supplies	179636492 Lt245-75r17	6.00
	Tr416 Valve Stem	6.00
	Led Sup Mdl 44 42 Dio	1.00
	Caster-camber Bushing	2.00
	Seat R And R	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	6.00
Hours 12.00	Labor: 720.00	Parts: 2,003.35
:		Total: 2,723.35

Workorder: 1409928 **Meter:** 53153 **In Date:** 10/02/2014 **Closed:** 10/17/2014
Problem: P.M. service.

- Pm service.	Parts List	Qty
- Test and replace defective amber side marker lamp assembly and licence plate lamp bulb.	15-40 Oil	15.00
- Inspect and service winch	Napagold Oil Filter	1.00
- Rotate and balance all six tires.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Fuel Filter Ford Only	1.00
	Led M C Lamp	1.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 176.00
:		Total: 611.00

Workorder: 1503404 **Meter:** 55916 **In Date:** 04/01/2015 **Closed:** 04/14/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Test and replace defective left reverse lamp and right rear turn signal lamp.	15-40 Oil	15.00
- Inspect for noise and replace defective serpentine belt and belt tensioner.	Napagold Oil Filter	1.00
- Inspect and service power winch.	Fuel Filter Ford Only	1.00
- Rotate and balance all six tires.	Wiper Blade	2.00
- Shop Supplies	Wd40 16oz	1.00
	Led Sup Mdl 44 42 Dio	1.00
	Led Back-up Lamp Sys	1.00
	Serpentine Belt	1.00
	Tensioner-heavy Duty	1.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours 10.75	Labor: 645.00	Parts: 538.33
:		Total: 1,183.33

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1510316 **Meter:** 59279 **In Date:** 10/13/2015 **Closed:** 10/28/2015

Problem: P.M. service and A/C not cold and water leak at back glass.

	Parts List	Qty
- Pm service.		
- Ac performance and leak test.replace defective evaporator,accumulator and expansion tube.replace high side schrader valve.vacuum and recharge system to specs.	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
- Replace both left and right defective upper and lower ball joints.	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
- Inspect and service winch.	Mac Wite Lithium Gres	1.00
- Rotate and balance all six tires.	Evapotator Core	1.00
- Complete front end alignment.	Accumulator	1.00
- Shop Supplies	A/c Valve Core	1.00
	Tube Filter	1.00
	E8 A/c Oil Univ W Dye	1.00
	Rapid Seal Kit	1.00
	Ball Joint	2.00
	Ball Joint	2.00
	Ac Valve Core High	1.00
	R134a Lv Shop 1	2.00
	Shop Supplies	1.00

Hours 27.20
:

Labor: 1,632.0 Parts: 768.41
0

Total: 2,400.41

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604843 **Meter:** 64463 **In Date:** 05/09/2016 **Closed:** 05/27/2016
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Test batteries and charging system.replace both batteries.	15-40 Oil	15.00
- Resurface front and rear brake rotors,replace brake pads.service and lube calipers.flush and bleed system.	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
- Replace two worn out body mounts.	20" Wiper Blade	2.00
- Perform engine decarb,injector cleaning.clean intercooler.r&r particulate filter and pressure wash element.clear codes and test drive vehicle.	Battery	2.00
	Led Sup Mdl 44 42 Dio	1.00
- Rotate and balance all six tires.	Reman Brake Caliper	1.00
- Shop Supplies	Reman Brake Caliper	1.00
	Reman Brake Caliper	2.00
	Reman Brake Caliper	1.00
	B Fluid Dot 3-32oz	2.00
	Brake Cleaner	1.00
	Body Mount Kit	2.00
	Brake Pads	1.00
	Brake Pad	1.00
	Kq22932df Diesel Inje	1.00
	Dpkq7 Egr Service Kit	1.00
	Fuel Cap Diesel	2.00
	Washer Nozzle	1.00
	Exha	1.00
	Shop Supplies	1.00
Hours 27.50	Labor: 1,650.0	Parts: 1,609.31
:	0	Total: 3,259.31

Workorder: 1610868 **Meter:** 68162 **In Date:** 10/21/2016 **Closed:** 11/02/2016
Problem: P.M. service and Check engine light on.

	Parts List	Qty
- P.m. Service.		
- Replace and balance six new tires.	15-40 Oil	15.00
- Diagnose check engine light.p0676.perform pin point test.replace defective #6 glow plug.	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
- Replace rear axle bump stoppers.	20" Wiper Blade	2.00
- Complete wheel alignment.test drive.	Used Fire X Refurbished	1.00
- Inspect and service winch.	179636492 Lt245-75r17	6.00
- Shop Supplies	Glow Plug	1.00
	Real Suspension Bumpstops	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	6.00
Hours 13.50	Labor: 810.00	Parts: 1,774.06
:		Total: 2,584.06

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701999 **Meter:** 70804 **In Date:** 02/27/2017 **Closed:** 03/13/2017

Problem: Rear window leaking .

- Leak test rear window.r&r high mount brake light and reseal.	Parts List	Qty
	Cover Brake Light	1.00
- Shop Supplies	Air Freshener	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 23.08
:		Total: 83.08

Workorder: 1704241 **Meter:** 72042 **In Date:** 04/27/2017 **Closed:** 05/15/2017

Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace two burnt out tail lamps.	Napagold Air Filter	1.00
- Replace four worn out rear body mounts.	15-40 Oil	15.00
- Replace front suspension bump stoppers.	Napagold Oil Filter	1.00
- Service transmission.flush and refill system.	Fuel Filter Ford Only	1.00
- Inspect and service winch.	Used Fire X Refurbished	1.00
- Rotate and balance all six tires.	4 Led S T T Lamp	2.00
- Shop Supplies	bumper	2.00
	Body Mount Kit	4.00
	Syn-atf Trans Fluid S	19.00
	Screen Asy	1.00
	Screen Asy	1.00
	20" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 14.50	Labor: 870.00	Parts: 771.13
:		Total: 1,641.13

Workorder: 1705719 **Meter:** 72750 **In Date:** 06/08/2017 **Closed:** 06/15/2017

Problem: Check play in steering.

- Check ,performed steering performance test.rteplace defective steering gear box assembly .filled with fluid and bleed system.test drive.	Parts List	Qty
	Steering Gear Box	1.00
- Complete front end alignment and road test.	Shop Supplies	1.00
- Shop Supplies		
Hours 5.50	Labor: 330.00	Parts: 681.92
:		Total: 1,011.92

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711014 **Meter:** 76369 **In Date:** 11/06/2017 **Closed:** 11/29/2017
Problem: P.M. service and battery light on.

- P.m. service.	Parts List	Qty
- Test batteries and charging system.alternator failed .remove and replace with new.retest	15-40 Oil	15.00
- Vice broken.remove and fabricate and install new vice .replace broken pintle pin.	Napagold Oil Filter	1.00
- Inspect and service winch.replace failed hook with new.	Fuel Filter Ford Only	1.00
- Rotate and high speed balance all six tires .repair right rear inner tire.	20" Wiper Blade	2.00
- Shop Supplies	Pedal Pad	1.00
	Hd Workshop Vise	1.00
	Clevis Slip Hook-bulk	1.00
	alternator	1.00
	Pintle Pin W/clip	1.00
	Shop Supplies	1.00
Hours 12.05	Labor: 723.00	Parts: 549.47
:		Total: 1,272.47

Workorder: 1800924 **Meter:** 77971 **In Date:** 01/25/2018 **Closed:** 01/30/2018
Problem: Oil leak

- Oil leak at filter cover .replace oil filter with cover and top off oil .clean engine compartment.	Parts List	Qty
- Shop Supplies	Napagold Oil Filter	1.00
	15-40 Oil	4.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 27.01
:		Total: 87.01

Workorder: 1805331 **Meter:** 81327 **In Date:** 05/24/2018 **Closed:** 06/12/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace both failed headlight bulbs.	15-40 Oil	15.00
- Inspect and service winch.	Napagold Oil Filter	1.00
- Rotate and high speed balance all six tires.	Fuel Filter Ford Only	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Halogen Sealed Beams	2.00
	15w40 Oil	15.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 235.31
:		Total: 685.31

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808168 **Meter:** 82809 **In Date:** 08/08/2018 **Closed:** 08/16/2018
Problem: Trailer lights inop on right side and transmission slipping in higher gears.

<ul style="list-style-type: none"> - Computer diagnose check engine light and trans slipping. P117b, P1335 ,p20e4. Perform pinpoint test . Replace all three exhuaast gas temp sensors and tap out back sensor mount ,stripped. Performm Tsb 12-12-10 Pcm reprogram .test drive. - Test and replace trailer plug connector and rewire as needed. - Diagnose rattle over bumps . Replace both front defective shocks . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Blaster Penetrant</td><td></td><td align="right">1.00</td></tr> <tr><td>trailer plug</td><td></td><td align="right">1.00</td></tr> <tr><td>Gas Grande Fleet Shoc</td><td></td><td align="right">2.00</td></tr> <tr><td>exhaust sensor</td><td></td><td align="right">3.00</td></tr> <tr><td>Clr Rtv Silcn Sealant</td><td></td><td align="right">1.00</td></tr> <tr><td>Exha</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Blaster Penetrant		1.00	trailer plug		1.00	Gas Grande Fleet Shoc		2.00	exhaust sensor		3.00	Clr Rtv Silcn Sealant		1.00	Exha		1.00	Shop Supplies		1.00
Parts List		Qty																							
Blaster Penetrant		1.00																							
trailer plug		1.00																							
Gas Grande Fleet Shoc		2.00																							
exhaust sensor		3.00																							
Clr Rtv Silcn Sealant		1.00																							
Exha		1.00																							
Shop Supplies		1.00																							
Hours 7.00 :	Labor: 420.00	Parts: 566.81	Total: 986.81																						

Workorder: 1808633 **Meter:** 82929 **In Date:** 08/22/2018 **Closed:** 08/23/2018
Problem: Towed in for no start.

<ul style="list-style-type: none"> - Diagnose no start. Perform starting and charging test . Batteries failed load test . R&r both defective batteries . Retest all system passed. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Battery</td><td></td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Battery		2.00	Shop Supplies		1.00
Parts List		Qty								
Battery		2.00								
Shop Supplies		1.00								
Hours 2.00 :	Labor: 120.00	Parts: 259.28	Total: 379.28							

Workorder: 1808681 **Meter:** 82912 **In Date:** 08/21/2018 **Closed:** 08/22/2018
Problem: NO Start

<ul style="list-style-type: none"> - Tow From: Jpp Campground 	Hours 0.00 :	Labor: 0.00	Parts: 0.00	Total: 0.00
--	-----------------	-------------	-------------	-------------

Workorder: 1809471 **Meter:** 83211 **In Date:** 09/14/2018 **Closed:** 09/19/2018
Problem: Starter issues, powers up but wont start.

<ul style="list-style-type: none"> - Circuit test starter circuits . R&r defective starter motor .retest. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Starter Motor</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Starter Motor		1.00	Shop Supplies		1.00
Parts List		Qty								
Starter Motor		1.00								
Shop Supplies		1.00								
Hours 2.00 :	Labor: 120.00	Parts: 662.00	Total: 782.00							

Workorder: 1809508 **Meter:** 83085 **In Date:** 09/13/2018 **Closed:** 09/14/2018
Problem: Starting issues?? Starter (it powers up but want turn over)
 Contact: Chris Franks @ 561 963-6726

<ul style="list-style-type: none"> - Tow From: Jpp To: Lv shop 	Hours 0.00 :	Labor: 0.00	Parts: 0.00	Total: 0.00
---	-----------------	-------------	-------------	-------------

Workorder: 1811061 **Meter:** 84526 **In Date:** 10/26/2018 **Closed:** 11/06/2018
Problem: Check engine light.

<ul style="list-style-type: none"> - Computer diagnose check engine light , code P0675. Perform pinpoint test . Replace number five glow plug . Clear code and retest. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Glow Plug</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Glow Plug		1.00	Shop Supplies		1.00
Parts List		Qty								
Glow Plug		1.00								
Shop Supplies		1.00								
Hours 2.50 :	Labor: 167.50	Parts: 18.50	Total: 186.00							

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1813076 **Meter:** 86049 **In Date:** 12/28/2018 **Closed:** 01/07/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Inspect all brakes . Resurface rear rotors . Replace rear calipers and brake pads . Flush and bleed brake system . Road test.	Napagold Oil Filter	1.00
	15-40 Oil	15.00
- Test and replace right side marker light and retest.	Fuel Filter Ford Only	1.00
- Rotate and high speed balance all six tires . Nitrofill all.	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	Brake Pad	1.00
	Non-chlor Brake Clnr	1.00
	B Fluid Dot 3-32oz	1.00
	M C Base Mount Kit	1.00
	Shop Supplies	1.00
Hours 11.00	Labor: 737.00	Parts: 392.87
:		Total: 1,129.87

Workorder: 1906811 **Meter:** 90835 **In Date:** 06/28/2019 **Closed:** 07/16/2019
Problem: PM Service

- P.m. service.	Parts List	Qty
- Replace and high speed balance all six tires . Nitrofill all tires .	Napagold Oil Filter	1.00
	15-40 Oil	15.00
- Peeform complete front end alignment and road test .	Washer Fluid Concentr	1.00
- Shop Supplies	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Fuel Filter Ford Only	1.00
	179636492 Lt245-75r17	6.00
	Shop Supplies	1.00
	Tire Disposal Fee	6.00
Hours 9.50	Labor: 636.50	Parts: 1,711.76
:		Total: 2,348.26

Workorder: 1910148 **Meter:** 92392 **In Date:** 10/01/2019 **Closed:** 10/01/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00