10198084 2014 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Workorder: Problem:	1500219 1061 - Pre Del	Meter: livery Insp	0 ection			In Date:	01/07/2015	Closed:	01/07/2015
- Pre Delivery		, ,							
- 1 Te Delivery	•	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	1602342 pm	Meter:	339			In Date:	03/04/2016	Closed:	03/14/2016
- pm					Parts Li	st			Qty
- svc hyd sys	inspect lines an	nd hoses r	r hyd filter co	rrect fluid	Air Filter				1.00
level					Air Filter				1.00
- wash eq					Fuel Filte	er			1.00
- Shop Suppli	es				Fuel Filte	er			1.00
					Oil Filter	•			1.00
					15w40 B	Bulk South F	Reg		8.00
					Hydrauli	c Filter			1.00
					Shop Su	ıpplies			1.00
	Hours	s 6.00		Labor:	360.00	Parts:	268.70	Total:	628.70
Workorder: Problem:	1604128 Four new tires	Meter:	415			In Date:	04/20/2016	Closed:	04/27/2016
0/ / /:		_							
- C/c four tire	s.replace all fou	ur tires.mo	unt.add N2.		Parts Li	st			Qty
- C/c four tire - Shop Suppli	-	ır tires.mo	unt.add N2.			st 0-15 6 ply l	nector		Qty 2.00
	-	ur tires.mo	unt.add N2.		29x14.00				-
	-	ur tires.mo	unt.add N2.		29x14.00	0-15 6 ply l 0 4 ply hec			2.00
	-	ur tires.mo	unt.add N2.		29x14.00 20x10-10 Shop Su	0-15 6 ply l 0 4 ply hec			2.00 2.00
	es	ur tires.mo	unt.add N2.	Labor:	29x14.00 20x10-10 Shop Su	0-15 6 ply h 0 4 ply hec opplies posal Fee		Total:	2.00 2.00 1.00
	es		unt.add N2.	Labor:	29x14.00 20x10-10 Shop Su Tire Disp	0-15 6 ply h 0 4 ply hec opplies posal Fee	tor	Total:	2.00 2.00 1.00 4.00
- Shop Suppli	es Hours :	s 2.00 Meter:	419		29x14.00 20x10-10 Shop Su Tire Disp 120.00	0-15 6 ply h 0 4 ply hec upplies posal Fee Parts:	961.06		2.00 2.00 1.00 4.00 1,081.06
- Shop Suppli Workorder: Problem:	Hours: 1604753 Low coolant was	s 2.00 Meter: arning me	419 ssage on.Sta	alls intermi	29x14.00 20x10-10 Shop Su Tire Disp 120.00	0-15 6 ply hecopolics posal Fee Parts:	961.06		2.00 2.00 1.00 4.00 1,081.06
- Shop Suppli Workorder: Problem: - C/c stalling.t relay under was operating prop	Hours: 1604753 Low coolant warranty.test drovely at this time	Meter: arning me trouble co	419 ssage on.Sta	alls intermi	29x14.00 20x10-10 Shop Su Tire Disp 120.00	0-15 6 ply h 0 4 ply heco posal Fee Parts: In Date:	961.06		2.00 2.00 1.00 4.00 1,081.06
- Shop Suppli Workorder: Problem: - C/c stalling.trelay under wa	Hours: : 1604753 Low coolant water drive found arranty test droverly at this time es	Meter: arning me trouble cove after rep	419 ssage on.Sta	alls intermi eplace uipment	29x14.00 20x10-10 Shop Su Tire Disp 120.00 ittently. Parts Lis Shop Su	0-15 6 ply hecopolics posal Fee Parts: In Date: st	961.06 05/05/2016	Closed:	2.00 2.00 1.00 4.00 1,081.06 05/18/2016 Qty 1.00
- Shop Suppli Workorder: Problem: - C/c stalling.t relay under was operating prop	Hours: : 1604753 Low coolant water drive found arranty test droverly at this time es	Meter: arning me trouble co	419 ssage on.Sta	alls intermi	29x14.00 20x10-10 Shop Su Tire Disp 120.00 ittently. Parts Lis Shop Su	0-15 6 ply h 0 4 ply heco posal Fee Parts: In Date:	961.06 05/05/2016		2.00 2.00 1.00 4.00 1,081.06 05/18/2016 Qty 1.00
- Shop Suppli Workorder: Problem: - C/c stalling.t relay under was operating prop	Hours: 1604753 Low coolant water drive found arranty test droverly at this time es Hours: 1605060	Meter: arning me trouble cove after rep	419 ssage on.Sta	alls intermi eplace uipment	29x14.00 20x10-10 Shop Su Tire Disp 120.00 ittently. Parts Lis Shop Su	0-15 6 ply hecopolics posal Fee Parts: In Date: st	961.06 05/05/2016	Closed:	2.00 2.00 1.00 4.00 1,081.06 05/18/2016 Qty 1.00
- Shop Suppli Workorder: Problem: - C/c stalling.t relay under wa operating prop - Shop Suppli Workorder: Problem: - Prep equipm	Hours: 1604753 Low coolant water drive found arranty test droverly at this time es Hours: 1605060	Meter: arning me trouble co ye after rep arring Meter:	419 ssage on.Standes.hector repair verify eq 429	alls intermi eplace uipment Labor:	29x14.00 20x10-10 Shop Su Tire Disp 120.00 ittently. Parts Lis Shop Su	0-15 6 ply h 0 4 ply heco posal Fee Parts: In Date: st upplies	961.06 05/05/2016 2.00	Closed:	2.00 2.00 1.00 4.00 1,081.06 05/18/2016 Qty 1.00

Workorder: Problem:	1605244 Intermittent	Meter: no crank.Ca	429 nnot read hour me	eter.		In Date:	05/20/2016	Closed:	05/26/2016
- C/c will not	crank.not disi	plav hours.ve	erify intermittent		Parts Li	st			Qty
	splay not ope		erly.arrange warra		Shop Su				1.00
- Shop Suppli									
	Ho :	ours 1.00	La	abor:	60.00	Parts:	2.00	Total:	62.00
Workorder:	1606208	Meter:	429			In Date:	06/16/2016	Closed:	07/19/2016
Problem:	Rollers don	t roll well.En	gine buggs down v	while	mowing				
			while mowing.verit		Parts Li	st			Qty
past due for re picked up for v			gen fron unit.deal	er	Shop Su	ıpplies			1.00
- C/c rollers w		cate rollers.							
- Shop Suppli									
	Ho :	ours 1.50	La	abor:	90.00	Parts:	2.00	Total:	92.00
Workorder:	1609904	Meter:	429			In Date:	09/22/2016	Closed:	09/22/2016
Problem:	Broken Hos	e							
- Tow From: 13026 South			Boca Raton To:						
	•	ours 0.00	La	abor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1609984	Meter:	429			In Date:	09/23/2016	Closed:	09/29/2016
Problem:	Broken hyd	raulic hose.							
		e.replace hy	draulic hose.add	10	Parts Li	st			Qty
quarts of hydr			,		Hose H	vd Acev			
- Test run fou equipment ver			n perform regen o			yu Assy			1.00
- Wash equip				'11	Aw68 Bu	•			1.00 10.00
		emp. iamp oi red.no codes		711	Aw68 Bu Shop Su	ulk Sr			
	ment.			111		ulk Sr			10.00
- Shop Suppli	ment.		or faults.			ulk Sr ipplies	143.57	Total:	10.00
- Shop Suppli	ment.	red.no codes	or faults.		Shop Su	ulk Sr ipplies	143.57 01/17/2017	Total:	10.00 1.00
- Shop Suppli Workorder:	ment. les Ho	red.no codes ours 4.00	or faults.		Shop Su	ulk Sr upplies Parts:			10.00 1.00 383.57
- Shop Suppli Workorder:	ment. es Ho : 1700487 wont start	ours 4.00 Meter:	or faults. La		Shop Su	ulk Sr upplies Parts:			10.00 1.00 383.57
- Shop Suppli Workorder: Problem:	ment. les Ho : 1700487 wont start	ours 4.00 Meter:	La 429		Shop Su 240.00	ulk Sr upplies Parts:	01/17/2017		10.00 1.00 383.57 01/17/2017
- Shop Suppli Workorder: Problem: - Tow From:	ment. les Ho : 1700487 wont start 11101 south Ho : 1700601	Meter: reginal pk boours 0.00 Meter:	La 429	abor:	Shop Su 240.00	ulk Sr ipplies Parts: In Date:	01/17/2017	Closed:	10.00 1.00 383.57 01/17/2017
- Shop Suppli Workorder: Problem: - Tow From:	ment. les Ho : 1700487 wont start 11101 south	Meter: reginal pk boours 0.00 Meter:	dor faults. La 429 boca La	abor:	Shop Su 240.00	Parts: Parts:	01/17/2017	Closed:	10.00 1.00 383.57 01/17/2017
- Shop Suppli Workorder: Problem: - Tow From: Workorder: Problem: - diagnose no	ment. les Ho : 1700487 wont start 11101 south Ho : 1700601 towed in for	Meter: reginal pk boours 0.00 Meter:	dor faults. La 429 boca La	abor:	240.00 0.00	Parts: Parts: In Date: In Date:	01/17/2017	Closed:	10.00 1.00 383.57 01/17/2017
- Shop Suppli Workorder: Problem: - Tow From: Workorder: Problem: - diagnose no harness conei	ment. les Ho : 1700487 wont start 11101 south Ho : 1700601 towed in for	Meter: reginal pk boours 0.00 Meter:	La 429 oca La 429	abor: abor:	240.00 0.00	Parts: Parts: In Date: In Date:	01/17/2017	Closed:	10.00 1.00 383.57 01/17/2017 0.00 01/31/2017
- Shop Suppli Workorder: Problem: - Tow From: Workorder: Problem: - diagnose not harness coner - R/r frt tires	ment. les Ho : 1700487 wont start 11101 south Ho : 1700601 towed in for	Meter: reginal pk boours 0.00 Meter:	La 429 oca La 429	abor: abor:	240.00 0.00 Parts Li Relay	Parts: Parts: In Date: In Date:	01/17/2017 0.00 01/19/2017	Closed:	10.00 1.00 383.57 01/17/2017 0.00 01/31/2017
- Shop Suppli Workorder: Problem: - Tow From: Workorder: Problem: - diagnose no harness coner	ment. les Ho : 1700487 wont start 11101 south Ho : 1700601 towed in for	Meter: reginal pk boours 0.00 Meter:	429 oca La 429 ug solenoid and c	abor: abor:	240.00 0.00 Parts Li Relay	Parts: Parts: In Date: st 4-15 Nhs 6	01/17/2017 0.00 01/19/2017	Closed:	10.00 1.00 383.57 01/17/2017 0.00 01/31/2017 Qty 2.00

Workorder:	1701835	Meter: 92	20		In Date:	02/21/2017	Closed:	03/13/20)17
Problem:	PM Service.Ha	ard start.Ser	vice light comes of	n.Paddle	e and switch r	ot align interm	ittently.		
- Pm Service.				Parts	s List				Qty
- Service hyd	. system.inspec	t lines,hoses	fittings etcrepla	ce Air Fi	ilter				1.00
both filters.correct fluid level.					ilter				1.00
	not align.verify tr			Fuel	Filter				1.00
neutral.remove sensor assm.adjust and reinstall C/c service soon light on.verify complain.perform regen and					a Fuel Filter				1.00
clear service l		my complair	.perioriti regeri e	Oil Fi	ilter				1.00
- Wash equipment.					10 Bulk South	Reg			8.00
- Shop Suppli	ies			Hydra	aulic Filter				1.00
					a Hydraulic Fil	tr			1.00
				Aw68	Bulk Sr				3.00
					Supplies				1.00
	Hours	s 10.25	Lab	or: 615.0	00 Parts	: 223.52	Total:	838.52	
Workorder: Problem:	1702576 Check rear tire		35 oil leak.		In Date:	03/13/2017	Closed:	03/20/20)17
- C/c check re	ear tires.replace	rear tires.mo	ount,add N2	Parts	s List				Qty
	eak.replace hyd			Hose	Made				1.00
- Shop Suppli		J		20x1	0-10 4 ply he		2.00		
				Shop	Supplies		1.00		
				Tire [Disposal Fee				2.00
	Hours	s 4.50	Lab	or: 270.0	00 Parts	: 437.16	Total:	707.16	
Workorder:	1705946	Meter: 1	136		In Date:	06/15/2017	Closed:	06/30/20	
Problem:	Right front dec				III Date.	00/13/2017	0.0000.)17
		ck pin/Right s	ide wing drift/Rig	ht side ro		00/13/2017	Olocou.)17
- C/c right win	· ·		side wing drift/Rig extract broken bo			00/13/2017	Olocou.)1 / Qty
	· ·	y complaint.e	,	lt Parts	oller bent.		Globbal		
	ng pin bent.verif ce pin,lubricate	y complaint.e	,	lt Parts	oller bent. s List		o.ooou.		Qty
from pin.repla - Run regen c	ng pin bent.verif ce pin,lubricate on Dpf. nd raise exhaus	y complaint.e and test,	extract broken bo	lt Parts Pivot Pin	oller bent. s List		o.ooou.		Qty 1.00
from pin.repla - Run regen c - Test mow a	ng pin bent.verif ce pin,lubricate on Dpf. nd raise exhaus ies	y complaint.e and test,	extract broken bo	lt Parts Pivot Pin	oller bent. S List Carrier Shaft Supplies			319.63	Qty 1.00
from pin.replar - Run regen c - Test mow ar - Shop Suppli Workorder:	ng pin bent.verif ce pin,lubricate on Dpf. nd raise exhaus ies	y complaint.e and test, st temp. for rest 4.25	extract broken bo	lt Parts Pivot Pin Shop	oller bent. S List Carrier Shaft Supplies			319.63	Qty 1.00 1.00 1.00
from pin.replar - Run regen c - Test mow ar - Shop Suppli Workorder: Problem:	ng pin bent.verifice pin,lubricate on Dpf. nd raise exhausies Hours: 1709252 Engine loosing	y complaint.e and test, st temp. for rest temp. for rest 4.25 Meter: 14 g power.Check	extract broken bo	Pivot Pin Shop or: 255.0	oller bent. S List Carrier Shaft Supplies O Parts	: 64.63	Total:		Qty 1.00 1.00 1.00
from pin.replar - Run regen co - Test mow and - Shop Supplin Workorder: Problem: - C/c looses pound to not perform	ng pin bent.verifice pin,lubricate on Dpf. nd raise exhausies Hours: 1709252 Engine loosing	y complaint.e and test, st temp. for rest temp. for rest 4.25 Meter: 14 g power.Check	extract broken bo egen. Lab 416 ck brakes.	Pivot Pin Shop or: 255.0	oller bent. S List Carrier Shaft Supplies OParts In Date:	64.63 09/25/2017	Total:		Qty 1.00 1.00 1.00
from pin.repla - Run regen c - Test mow a - Shop Suppli Workorder: Problem: - C/c looses p to not perform regen.	ng pin bent.verify ce pin,lubricate on Dpf. nd raise exhaus ies Hours : 1709252 Engine loosing power.verify magning Dpf regen o	y complaint.e and test, st temp. for rest temp. for rest 4.25 Meter: 14 g power.Check	extract broken bo egen. Lab 416 ck brakes.	Pivot Pin Shop or: 255.0	oller bent. S List Carrier Shaft Supplies OParts In Date:	64.63 09/25/2017	Total:		Qty 1.00 1.00 1.00
from pin.replar Run regen c Test mow at Shop Supplit Workorder: Problem: C/c looses p	ng pin bent.verifice pin,lubricate on Dpf. nd raise exhausies Hours: 1709252 Engine loosing ower.verify magning Dpf regen of the pin bent process.	y complaint.e and test, st temp. for rest temp. for rest 4.25 Meter: 14 g power.Check	extract broken bo egen. Lab 416 ck brakes. ato limp mode dured Pcm/re/dpf	Pivot Pin Shop or: 255.0	In Date: S List O Parts In Date: S List O Supplies	64.63 09/25/2017	Total:		Qty 1.00 1.00 1.00 017 Qty 1.00

Workorder: Problem:	1802761 PM Service	Meter: .New grease	1785 fittings.		lı	n Date:	03/13/2018	Closed:	03/29/20	018
- Pm Service					Parts List					Qty
- Service hyd	- Service hydraulic system.inspect lines,hoses and						Asm			4.00
fittings.correct		Air Filter					1.00			
- Replace mu		Air Filter		1.00						
found Spn.522 return.	Fuel Filter		1.00							
- Test run to	Napa Fuel	l Filter				1.00				
service hours.			J		Oil Filter					1.00
- Wash equip					15w40 Bu	lk South F	Reg			8.00
- Shop Suppl	ies				Shop Supp	plies				1.00
	Ho :	ours 8.50		Labor:	510.00	Parts:	177.65	Total:	687.65	
Workorder:	1805880	Meter:	1910		lı	n Date:	06/08/2018	Closed:	06/26/20	018
Problem:	Replace mi	ssing deck bo	olts and spac	ers.Repla	ce tires.					
- C/c 4 tires.re	eplace four ti	res.mount ar	ıd add N2.		Parts List					Qty
- Adjust all de	eck heights.re	eplace deck h	nardware.		20x10-10	4 ply hec	tor			2.00
- Shop Suppl	ies				Tire29x14-15 Nhs 6 Ply					2.00
					Shim Hoc		3.00			
					Spcer Hoo			3.00		
					Plate Asm		3.00			
					Roll Pin		3.00			
					Shop Supp	plies				1.00
					Tire Dispo	sal Fee				2.00
	Ho	ours 4.00		Labor:	240.00	Parts:	1,207.41	Total:	1,447.41	1
Workorder: Problem:	1809237 Right front l	Meter: olade slow.Li	2185 mp mode.Le	ft wing hy	==	n Date:	09/07/2018	Closed:		
-	Ho :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
		Meter:	2130	/ 1 . 6		n Date:	09/12/2018	Closed:	09/26/20	018
Workorder: Problem:	1809382 RF blades t	urns slow/ lin	np mode no į	power/ left	wing nya i	can				
	RF blades t	urns slow/ lin	np mode no ¡	power/ left	Parts List					Qty
Problem:	RF blades t t front hydrau	urns slow/ linulic motor	np mode no	power/ left						Qty 1.00
Problem: - replace righ	RF blades t t front hydrau and parking	urns slow/ lin ulic motor brake switch			Parts List	Motor				_
Problem: - replace righ - replace pto	RF blades to the front hydrau and parking 3/ p1424, fer	urns slow/ lin ulic motor brake switch			Parts List	Motor Switch				1.00
Problem: - replace righ - replace pto - codes p146	RF blades to the front hydrau and parking 3/ p1424, fer	urns slow/ lin ulic motor brake switch			Parts List Hydraulic Proximity	Motor Switch				1.00 1.00

Problem:	1811216 service/ code	Meter: es/ see attac	2214 ched list			In Date:	10/31/2018	Closed:	11/13/20	018
- service mow		56, 566 ana			Parts Lis	st				Qty
- diagnose codes, adjust traction pedal, recalibrate. clean					Oil Filter			1.00		
fuse panel						il				8.00
- repair hydrau		Napa Fu	el Filter			1.00				
- Shop Supplie	es				Fuel Filte					1.00
					Air Filter					1.00
					Air Filter					1.00
					Shop Su	pplies				1.00
	Hou	ırs 7.00		Labor:	469.00	Parts:	157.61	Total:	626.61	
Workorder:	1812786	Meter:	2316			In Date:	12/17/2018	Closed:	12/26/20	018
Problem:	no power/ re	gen light/ m	ultiple codes							
- update toro i	nfo center. pe	erform reger	n and test run	l	Parts Lis	st				Qty
- Shop Supplie	es				Shop Su	pplies				1.00
	Hou	ırs 3.00		Labor:	201.00	Parts:	3.00	Total:	204.00	
Workorder: Problem: - install newes found	1813005 multiple code st computer up		2219 n test run. no	problem			12/26/2018	Closed:	01/25/20	Qty 1.00
- Shop Supplie	es				Chop Cu	ppiloo				1.00
	Hor	ırs 1.50		Lobor	100 F0	Dorto:	3.00	Total:	103.50	
	:	115 1.50		Labor.	100.50	raits.	0.00			
Workorder: Problem:	1904779	Meter:	2693			In Date:	05/01/2019	Closed:	05/30/20	019
Problem:	:	Meter:			ear.	In Date:		Closed:	05/30/20	
Problem: - Pm Service	: 1904779 PM Service,0	Meter: Grease fittin			ear. Parts Lis	In Date:		Closed:	05/30/20	019 Qty 1.00
Problem: - Pm Service - Service Hyd.	: 1904779 PM Service,0	Meter: Grease fittin	gs,front right	and left re	ear. Parts Lis Napagolo	In Date: st d Air Filter		Closed:	05/30/20	Qty
Problem: - Pm Service	: 1904779 PM Service,0	Meter: Grease fittin	gs,front right	and left re	ear. Parts Lis Napagolo	In Date: st d Air Filter d Air Filter		Closed:	05/30/20	Qty 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	ear. Parts Lis Napagolo Napagolo	In Date: st d Air Filter d Air Filter el Filter		Closed:	05/30/20	Qty 1.00 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all.	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	ear. Parts Lis Napagolo Napagolo Napa Fuel Fuel Filte	In Date: st d Air Filter d Air Filter el Filter	05/01/2019	Closed:	05/30/20	Qty 1.00 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	ear. Parts Lis Napagolo Napagolo Napa Fuel Fuel Filte	In Date: st d Air Filter d Air Filter el Filter	05/01/2019	Closed:	05/30/20	Qty 1.00 1.00 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	Parts Lis Napagolo Napagolo Napa Fuo Fuel Filte 15w40 B	In Date: In Date: Air Filter Air Filter In Filter	05/01/2019	Closed:	05/30/20	Qty 1.00 1.00 1.00 1.00 6.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	Parts Lis Napagolo Napagolo Napa Fuel Fuel Filte 15w40 B Oil Filter	In Date: St d Air Filter d Air Filter el Filter er ulk South F	05/01/2019	Closed:	05/30/20	Qty 1.00 1.00 1.00 1.00 6.00 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	Parts List Napagold Napa Fud Fuel Filte 15w40 B Oil Filter Hyd Filte	In Date: St d Air Filter d Air Filter el Filter er ulk South F	05/01/2019	Closed:	05/30/20	Qty 1.00 1.00 1.00 1.00 6.00 1.00
Problem: - Pm Service - Service Hyd C/c Replace grease all Vacume gras	: 1904779 PM Service,0 system.insper grease fitting ss and wash eas	Meter: Grease fittin ect all. ss.replace m	gs,front right	and left re	Parts List Napagold Napa Fud Fuel Filte 15w40 B Oil Filter Hyd Filte	In Date: In Dat	05/01/2019		05/30/20 749.52	Qty 1.00 1.00 1.00 1.00 6.00 1.00 1.00

Workorder: Problem:	1907607 Front left and	Meter: d right deck	2693 pin.front righ	nt hyd. hos	e.Codes o	In Date: displayed	07/23/2019	Closed:	08/19/20	019	
 Problem: Front left and right deck pin.front right hyd. hos C/c Bent pins.replace two front outer deck pins.lube all test mow. Replace Hyd. hose on front right deck Regen code flashing.mow for 30 minuites code did not return. Shop Supplies 					Parts List thrust washer Pin Pivot Carrier Shaft Screw Hose Asm Shop Supplies Freight Charge					Qty 2.00 2.00 2.00 2.00 1.00 1.00	
	Hou	urs 3.75		Labor:	251.25	·	276.81	Total:	528.06		
Workorder: Problem:	1909612 Wont start.B	Meter: ad battery.h	2693 lad to drive t	o Parks Do	epartment	In Date: t to install b	09/18/2019 pattery.	Closed:	09/23/20	019	
 C/c Wont start.test battery bad.replace battery bad.check charging system. Travel to loggers run to test and install new battery. Shop Supplies 					Parts List Battery Shop Su					Qty 1.00 1.00	
		urs 2.50		Labor:	167.50	Parts:	128.04	Total:	295.54		

Workorder:	1909805	Meter: 2693			In Date:	09/24/2019	Closed:	10/29/2019		
	Trouble starting					00/2 1/2010	0.000	. 0, _0, _0		
C/a traubla s	starting intermitt	antly varify traction nade	ol.	Parts Lis	~ 4			Otv		
	 C/c trouble starting.intermittently.verify traction pedal components.worn.replace all of pedal and switch assm.adjust 							Qty 1.00		
and test mow.fault#12.522619fmi:9										
- Shop Suppli	es			Roll Pin	VVIICEI			1.00 1.00		
				Flange				1.00		
				Roll Pin				1.00		
				Nut I				1.00		
				Washer				1.00		
				Capscre	w			1.00		
				Pedal Pa				1.00		
				Pad				1.00		
				Pin				1.00		
					ver Sensor			1.00		
				Shaft Piv	ot Traction			1.00		
				Hub Trad	ction Pedal	Pivot		1.00		
				Pin				1.00		
				Sensor F	Position			1.00		
				Hub Asm	า			1.00		
				Washer				1.00		
				Spring				1.00		
				Retainer	Spring			1.00		
				Braket S	pring			1.00		
				Spring S	haft			1.00		
				Bearing	Rod End			1.00		
				Pedal Ad	celerator			1.00		
				Pedal				1.00		
				Shop Su				1.00		
				Freight C	J			1.00		
				Freight C	J			1.00		
				Freight C	•			1.00		
	Hours	3.00	Labor:	219.00	Parts:	961.50	Total:	1,180.50		
Workorder:	1911402	Meter: 2694			In Date:	11/01/2019	Closed:	11/12/2019		
	Broken.belt.Ru	inning hot.Fix hood crac	k.							
- Replace bro	ken engine v- b	elt.		Parts Lis	st			Qty		
- C/c Repair c	-			V-belt				1.00		
•		ated from belt coming o	ff.	Jb Weld				1.00		
-		nt.correct all N2.			Antifreeze			1.00		
- Shop Suppli				•	0-10/4 Turf	Master		2.00		
				Shop Su				1.00		
				-	osal Fee			2.00		
	Hours	6.00	Labor:	438.00		271.60	Total:	709.60		
	:									

Workorder: 1912007 **Meter:** 2694 **In Date:** 11/20/2019 **Closed:** 11/20/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00

: