10175088 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

		10175088	2009 FOF	RD F350 Utilit	y Body,	1 Ton, W/M	ed. Duty Cra	ne		
Workorder: Problem:	937875 PRE-DE	Meter: LIVERY INSPE	0 ECTION			In Date:	05/18/2009	Closed:	05/18/2	2009
- Pre-delivery	Inspection	n								
		Hours 4.00 :		Labor:	240.00	Parts:	0.00	Total:	240.00	
Workorder: Problem:	937944 MAKE 2	Meter: SPARE KEYS	58			In Date:	05/19/2009	Closed:	05/26/2	2009
- Make 2 Spar	re Keys				Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
		Hours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	942505 display v	Meter: wiring fault in tra	3581 ailer harn	ess		In Date:	08/25/2009	Closed:	09/03/2	2009
- Test trailer p	lug circui	t, Replace corr	oded plug	g socket.	Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
					153194	77 Fuse 30	Amp Gmc			1.00
					5404 Fe	emale Conne	ector			1.00
		Hours 1.00		Labor:	60.00	Parts:	13.88	Total:	73.88	
Workorder: Problem:	945082 P.M serv	Meter:	5644			In Date:	10/27/2009	Closed:	11/13/2	2009
- P.m. Service	Э.				Parts L	ist				Qty
- Service cran	e and rep	olace hydaulic f	ilter.		Shop St	upplies				1.00
- Rotate and b	oalance a	II six tires.nitro	fill		7312 O	il Filterfrm C	Ch9549 Wix 5	7312		1.00
- Shop Suppli	es				Cs1026	3 Fuel Filter	(use Cs1026	3a)		1.00
						Hydraulic Fil	ter			1.00
					15/40 C					15.00
							d Fire Extings		400.0=	1.00
		Hours 6.50		Labor:	390.00	Parts:	106.27	Total:	496.27	
Workorder: Problem:	1002910 P.M serv	Meter: vice, pulls right.	10863			In Date:	03/22/2010	Closed:	03/29/2	2010
- P.m service.					Parts L	ist				Qty
- Mount, balar	nce & nitr	o fill two new ti	res, repai	r L/r inner tire.	Shop St	upplies				1.00
- Inspect & se	rvice cra	ne.			7312 O	il Filterfrm C	Ch9549 Wix 5	57312		1.00
- Alignment.							(use Cs1026	3a)		1.00
- Shop Suppli	es				15/40 C					15.00
						/iper Blades				2.00
							5r17 Wrangle	r Sr-a E		2.00
						posal Fee				2.00
		Harris 0.50				alve Stem	470.50	.	4 0 40 =	2.00
		Hours 9.50		Labor:	570.00	Parts:	472.53	ı otal:	1,042.5	3

Workorder: Problem:	1006330 Truck stalls and	Meter: d sputters	13017 in regen. n	node.		In Date:	06/15/2010	Closed:	06/24/20	010
	hicle to dealer f	•	•		Parts Li					Qty 1.00
спор сарри	Hours	2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1008317 R/S headlight i	Meter:	14239			In Date:	08/04/2010	Closed:	08/04/20	010
	it side headlam I beam lamp wi		ly,test and ı	replace	Parts Li	ıpplies	_			Qty 1.00
2sp 2.spp	Hours	0.75		Labor:		Sealed Bear Parts:		Total:	54.49	1.00
Workorder: Problem:	1009368 P.M. service.	Meter:	15465			In Date:	08/30/2010	Closed:	09/13/20	010
- P.m. Service - Inspect and s - Replace four - Shop Supplie	service crane. tires./rotate an	÷ 7.50	all six.	Labor:	7312 O Cs1026 Ca1027 51551 H 15/40 C 61a P/st Used Fir 1796364 Tire Dis	upplies 343a Seal K 343a Seal K 3 Fuel Filter O Air Filter I Uydraulic Filt Dil Dil Dieering Fluic Tex Refurbe 192 Lt245/75 Dosal Fee alve Stem		57312 3a) /ix 49886 shers r Sr-a E	1,384.40	
	flash canceiver			Labor:	Parts Li Shop St 60.00	st			62.00	Qty 1.00
Workorder: Problem:	1011686 Check noise al	Meter: ong drive	16737 train see n	otes.		In Date:	10/19/2010	Closed:	10/21/20	010
- Test drive ve normal normal - Shop Supplie		mes.no pi	oblem four	nd.tire/road	Parts Li Shop Su					Qty 1.00
	Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: 1013830 Meter: 17877 In Date: 12/16/2010 Closed: 12/16/2010 Problem: 4 - Wash ticket(s) issued - 4 - Wash ticket(s) issued Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1101912 Meter: 19610 In Date: 02/17/2011 Closed: 02/28/2011 **Problem:** Pm service also see notes on bed liner. - P.m. Service. Parts List Qty - Replace right side marker light assemble. **Shop Supplies** 1.00 - Replace missing hitch pintle pin. Cs10263 Fuel Filter (use Cs10263a) 1.00 - Replace leaking Pto gasket.inspect and service crane and 7312 Oil Filterfrm Ch9549 Wix 57312 1.00 top off fluid. 51551 Hydraulic Filter 1.00 - Repair and balance left rear tire.rotate and balance all tires. Aw68 Hydro Fluid Hydraulic Oil 68 3.00 - Shop Supplies Wd40 Spray Lube Stock# 405540002 1.00 L0135-063 Lubriplate Chain&cable 1.00 Lube,03050crc 15/40 Oil 15.00 31-20 Wiper Blades 20" Blade 2.00 19006y Marker Light 4" Rect Yellow Led 1.00 18410 Pintle Pin 1.00 Gasket 1.00 Hours 10.25 Labor: 615.00 Parts: 150.15 Total: 765.15 Workorder: 1104808 Meter: 21156 In Date: 05/05/2011 Closed: 05/05/2011 Problem: 2 - Key(s) issued **Parts List** - 2 - Key(s) issued Qty **Duplicate Vehicle Keys** 2.00 Labor: 24.00 Hours 0.40 Parts: 6.00 Total: 30.00 Workorder: 1107736 22982 Meter: In Date: 07/22/2011 Closed: 08/18/2011 **Problem:** Pm service also noise in rear end when turning see notes. - P.m. Service. **Parts List** Qty - Inspect and service crane. Shop Supplies 1.00 - Replace center brake light bulb, repair wiring for tag lamp 51551 Hydraulic Filter 1.00 ground circuit. 7312 Oil Filterfrm Ch9549 Wix 57312 1.00 - Rotate and balance all six tires. 3963 Fuel Filter Frm Cs10263a Wix 33963 1.00 - Transport vehicle to dealer for rear end noise(pinion Aw68 Hydro Fluid Hydraulic Oil 68 1.00 bearing), coolant leak(rad. hose) and recall #11b23 15/40 Oil 15.00 - Shop Supplies Used Firex Refurbed Fire Extingshers 1.00 31-20 Wiper Blades 20" Blade 2.00 Labor: 570.00 Parts: 132.04 Hours 9.50 Total: 702.04

Problem:	1108805 Had to jump st	Meter: art this m	23034 orning.			In Date:	08/19/2011	Closed:	08/22/20	011
	nd test both batt	teries,fail	load test.re	place	Parts Lis	st				Qty
deffective batte					Shop Su	pplies				1.00
- Shop Supplie	es				Group 65	5 Battery (n	ntc Bxt-65-850	O)		2.00
	Hours :	3 2.00		Labor:	120.00	Parts:	259.49	Total:	379.49	
Workorder: Problem:	1110539 Right front tire	Meter: going flat	24413			In Date:	10/03/2011	Closed:	10/06/20	011
- Repair flat rig	ght front tire.nit	rogen fill a	and balance	e same.	Parts Lis	st				Qty
- Shop Supplie	es				Shop Su	pplies				1.00
	Hours :	3 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1201602 Pm service.	Meter:	26870			In Date:	02/17/2012	Closed:	03/29/20	012
- P.m. Service	9.				Parts Lis	st				Qty
- Replace two	tires, rotate an	d balance	all six.		Shop Su	pplies				1.00
- Inspect and	service crane.					ydraulic Fil				1.00
•	take down light	-	ar.				Ch9549 Wix 5			1.00
•	hee alignment.t						m Cs10263a			1.00
•	hicle dealer for	engine o	l leak.		-		lydraulic Oil 6	8		2.00
- Shop Supplie	es				15/40 O		0011 DI 1			15.00
						•	20" Blade			2.00
						wn Light As	•	. C		1.00
							5r17 Wrangle	r Sr-a E		2.00
	Hours	12.50		Labor:	750.00	osal Fee Parts:	557.88	Total:	1,307.88	2.00 8
Workorder: Problem:	: 1208765 P.M. service.	Meter:	28221			In Date:	09/14/2012	Closed:	09/26/20	012
- P.m. Service) .				Parts Lis	st				Qty
- Inspect and	service crane.				Shop Su	pplies				1.00
- Rotate and b	palance six tires	3.			51551 H	ydraulic Fil [.]	ter			1.00
- Shop Supplie	es				7312 Oi	I Filterfrm C	Ch9549 Wix 5	7312		1.00
					3963 Fu	el Filter Fr	m Cs10263a	Wix 33963		1.00
					15/40 O	il				15.00
					31-20 W	iper Blades	20" Blade			2.00
					Used Fir	ex Refurbe	d Fire Extings	hers		1.00
	Hours :	s 6.50		Labor:	390.00	Parts:	129.06	Total:	519.06	
	Hours : 1209446 Floor mats.	6.50	28223	Labor:	390.00	Parts:	129.06	Total:	10/11/20	012
Problem:	: 1209446 Floor mats.	Meter:			390.00 Parts Lis	In Date:				
Problem: - Fabricate an	: 1209446 Floor mats. ad install new flo	Meter:			Parts Lis	In Date:	10/02/2012			012 Qty 1.00
	: 1209446 Floor mats. ad install new flo	Meter:			Parts Lis	In Date: st Frt Floor M	10/02/2012			Qty

Problem:	1302130 Pm service.Lo	Meter: eft front tire	28843 e flat.Has to j	jump start i		n Date:	03/01/2013	Closed:	03/12/20	013
- P.m. Service	e.				Parts List					Qty
- Replace bot	th alley lamps o	on light bar			15-40 Oil					15.00
•	service crane.	•			Napagold (Oil Filter				1.00
- Repair left f	ront tire,rotate	and baland	e all six.		Fuel Filter					1.00
- Test batterie	es and charging	g system,c	k.unable to	duplicate	31-20 Wipe	er Blades	20			2.00
operators com	•				Brake Clea	aner				1.00
- Shop Suppli	ies				Fxalf1 Alle	y Light Le	Э			2.00
					Napa Hydr	aulic Filtı	•			1.00
					Cx05-0145	Hook La	atch			1.00
					Shop Supp	olies				1.00
	Hou	rs 9.00		Labor:	540.00	Parts:	258.82	Total:	798.82	
Workorder: Problem:	1306214 No power on	Meter: acceleration	30454 on.		lr	n Date:	06/20/2013	Closed:	07/11/20	013
high pump pre	ehicle to dealer essure).re-flash		ver complain	ıt.(p0088	Parts List Shop Supp	olies				Qty 1.00
- Shop Suppli		rs 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
	1307470 1 - Key(s) iss	Meter: ued	30454			n Date:	07/25/2013	Closed:	07/25/20	
- 1 - Key(s) is	ssued				Parts List	/ . l. ! . l l .				Qty
	Have	0.00		Laban	Duplicate \		-	Tatal	45.00	1.00
	Hou :	rs 0.20		Labor:	12.00	Parts:	3.00	ı otai:	15.00	
Workorder:	1308582	Meter:	32783			n Date:	08/26/2013	Closed:	09/25/20	113
Problem:	P.M. service.				Ir			Ciosea:	00/20/20	313
- P.m. Service					Parts List			Closed:	03/23/20	Qty
- P.m. Service								Ciosea:	03/23/20	
- P.m. Service - Inspect and	e.		all six.		Parts List	Air Filter		Ciosea:	00/20/20	Qty
- P.m. Service - Inspect and - Replace two - Test batterie	e. service crane. o tires,rotate ar es and chargin	nd balance g system.re	echarge and		Parts List	Air Filter		Closea:		Qty 1.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both	e. service crane. tires,rotate ar as and charging failed load tes	nd balance g system.re t.replace b	echarge and oth defective	batteries.	Parts List Napagold A	Air Filter re Switch		Closed:		Qty 1.00
- P.m. Service - Inspect and - Replace two - Test batteries,both - Diagnose w	e. service crane. tires,rotate ar and charging failed load tes	nd balance g system.re t.replace b ne oil light	echarge and oth defective flashing at id	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil	Air Filter re Switch Oil Filter	1	Closed:		Qty 1.00 1.00 15.00
- P.m. Service - Inspect and - Replace two - Test batteries,both - Diagnose w speeds.perfor	e. service crane. tires,rotate ar as and charging failed load tes	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil Napagold	Air Filter re Switch Oil Filter Fuel Filte	r	Closed:		Qty 1.00 1.00 15.00 1.00
- P.m. Service - Inspect and - Replace two - Test batteries,both - Diagnose w speeds.perfor	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil Napagold Napagold	Air Filter re Switch Oil Filter Fuel Filte er Blades	r ; 20	Closed:		Qty 1.00 1.00 15.00 1.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil Napagold A Napagold A 31-20 Wipe Used Fire Napa Hydr	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb	r s 20 ished	Closed:		Qty 1.00 1.00 15.00 1.00 2.00 1.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil Napagold A Napagold B 31-20 Wipe Used Fire A Napa Hydr 179636492	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filti 2 Lt245-7	r s 20 ished	Closed:		Qty 1.00 1.00 15.00 1.00 2.00 1.00 2.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold A Oil Pressu 15-40 Oil Napagold A Napagold A 31-20 Wipe Used Fire Napa Hydr 179636492 Tr416 Valv	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filti 2 Lt245-7	r s 20 ished	Closed:		Qty 1.00 1.00 15.00 1.00 2.00 1.00 2.00 2.00 2.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold of Discourse Vision 15-40 Oil Napagold of Napagold of S1-20 Wipe Used Fire Napa Hydrom 179636492 Tr416 Valve Battery 65	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filti 2 Lt245-7 re Stem	r s 20 ished	Closed:		Qty 1.00 1.00 15.00 1.00 2.00 1.00 2.00 2.00 2.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold Oil Pressu 15-40 Oil Napagold Napagold 31-20 Wipe Used Fire Napa Hydr 179636492 Tr416 Valv Battery 65 Brake Clea	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filti 2 Lt245-7 re Stem	r s 20 ished	Closed:		Qty 1.00 1.00 15.00 1.00 1.00 2.00 1.00 2.00 2.00 2.00 1.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. tires,rotate ar es and charging failed load tes ith Ids for engir m oil pressure ch with new an	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile	Parts List Napagold of Discourse Vision Napagold of Napagold of Napagold of Napagold of Napa Hydron 179636492 Tr416 Valve Battery 65 Brake Clear Shop Supp	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filti 2 Lt245-7 re Stem aner olies	r s 20 ished	Closed:		Qty 1.00 1.00 1.00 1.00 2.00 1.00 2.00 2.00
- P.m. Service - Inspect and - Replace two - Test batteries batteries,both - Diagnose w speeds.perfor pressure swite	e. service crane. o tires,rotate ar es and charging failed load tes ith Ids for engin m oil pressure ch with new and ies	nd balance g system.ro t.replace b ne oil light test and re	echarge and oth defective flashing at id eplace failed	e batteries. Ile engine oil	Parts List Napagold Oil Pressu 15-40 Oil Napagold Napagold 31-20 Wipe Used Fire Napa Hydr 179636492 Tr416 Valv Battery 65 Brake Clea	Air Filter re Switch Oil Filter Fuel Filte er Blades X Refurb raulic Filte 2 Lt245-7 re Stem aner olies sal Fee	r s 20 ished			Qty 1.00 1.00 1.00 1.00 1.00 2.00 1.00 2.00 2

Workorder:	1312584	Meter:	35690			In Date:	12/17/2013	Closed:	01/09/20	014
Problem:	Pm service	e.Request to i	nstall new vic	e.Check b	oin doors	and crane p	pendant cable	plug.		
- Perform pm	service.				Parts Lis	st				Qty
- Inspect and	service hyd	Iraulic crane a	nd secure wi	ring.	15-40 O	il				15.00
- Install two n	ew tires to t	he front whee	ls.nitrogen fill	l and	Napagolo	d Oil Filter				1.00
balance all six	ζ.				Fuel Filte	er Ford Only	y			1.00
- Test and rep		•			Napa Hy	draulic Filtr	•			1.00
		oads and resu			Aw68 Hy	dro Fluid H	lydr			4.00
rotors.service hydraulic systematics				ea bleea	Angle Pe	ndulum De	ecal			2.00
- Shop Suppli					1796364	92 Lt245-7	5r17			2.00
					Bulb					1.00
					Pads					1.00
					2232 Bra	ke Fluid Q	uar			1.00
					Brake Cl	eaner				1.00
					Shop Su	pplies				1.00
					Tire Disp	osal Fee				2.00
	⊢	lours 12.80		Labor:	768.00	Parts:	749.58	Total:	1,517.58	8
Workorder:	1400082	Meter:	35694			In Date:	01/03/2014	Closed:	01/10/20	014
	Mount Vic						0 17 007 20 1 1	0.000	0 1, 10, 2	
- drill holes fo	r vise and p	aint area			Parts Lis	st				Qty
- fab/ weld vis	se mount				66997 C	ombo Vise	Rigid			1.00
- Shop Suppli	ies				GI Whit					1.00
					Gray Sea	a				1.00
					Shop Su	pplies				1.00
					4" X 24 S	Square Tub	ing			3.00
					2"x21 Bla	ack Pipe				10.00
	⊢	lours 7.00		Labor:	420.00	Parts:	662.86	Total:	1,082.86	6
Workorder:	1401760	Meter:	37255			In Date:	02/24/2014	Closed:	03/06/20	014
Problem:	P.T.O. ino	p and bad cor	nection at cr	ane contro	oler.					
- Test and rep	pair ground	pin on crane	control		Parts Lis	st				Qty
pendant.diagn				sure	Switch					1.00
switch.					Shop Su	oplies				1.00
- Shop Suppli										
	⊢ :	lours 3.00		Labor:	180.00	Parts:	42.68	Total:	222.68	
Workorder:	1402281	Meter:	37255			In Date:	03/07/2014	Closed:	03/07/20	014
Problem:	1 - Key(s)	issueu								
- 1 - Key(s) is	sued				Parts Lis	st				Qty
					Duplicate	e Vehicle K	eys			1.00
	⊢ :	lours 0.20		Labor:	12.00	Parts:	3.00	Total:	15.00	

Workorder: 1403248 Meter: 40732 Problem: Light Tower	In Date : 04/02/2014	Closed:	07/15/2014
- install go light. fabricate mounting brackets and wire unit	Parts List		Qty
- mount air compressor, mount hose reel, plumb air to hose	Trailer Wire		21.00
reel	Cable Tie		1.00
- test run	Nylon Tubing		1.00
- Shop Supplies	Rubber Mount		2.00
	Power Supply Cord		1.00
	U-bolt		2.00
	Permanent Mount W Wir		1.00
	Hitch Mount Light Pole		1.00
	Fuse Holder		1.00
	Shop Supplies		1.00
Hours 14.00 Labor	: 840.00 Parts: 867.28	Total:	1,707.28
Workorder: 1404814 Meter: 40119	In Date: 05/16/2014	Closed:	06/11/2014
Problem: Pm service, Check over pulley noise and blow	er speeds.		
- P.m. Service.	Parts List		Qty
- inspect and service crane.	15-40 Oil		15.00
- Check light bar.dis-assemble light bar and replace four ino	o Napagold Oil Filter		1.00
amber light modules.	Fuel Filter Ford Only		1.00
 Resurface rear brakes rotors, replace rear brake pads.service and lube calipers. flush and bleed system. 	Napagold Air Filter		1.00
- Replace serpentine belt and a/c belts.	Wiper Blade		2.00
- Check a/c blower.replace defective blower resistor.	Macs Chain Cable Lube		1.00
- Rotate and balance all six tires.	Mac Wite Lithium Gres		1.00
- Shop Supplies	Napa Hydraulic Filtr		1.00
- опор оцррнез	44202r Tail Light 4in		2.00
	Brake Pad		1.00
	Serpentine Belt		1.00
	Serpentine Belt		1.00
	Blower Motor Resistor		1.00
	Shop Supplies		1.00
Hours 18.00 Labor :	: 1,080.0 Parts: 495.19 0	Total:	1,575.19
Workorder: 1407247 Meter: 40946	In Date: 07/23/2014	Closed:	07/30/2014
Problem: Belt squeakes in A/M.			
- Inspect and replace failed serpentine belt tensioner and	Parts List		Qty
three idler pulleys with new.	Belt Tensioner		1.00
- Shop Supplies	Belt Tensioner		1.00
	Idler Pulley		1.00
	Idler Pulley Smooth		1.00
	Shop Supplies		1.00
Hours 3.50 Labor	: 210.00 Parts: 349.99	Total:	559.99

Workorder: Problem:	1408422 Both outrigger	Meter: cylinders	41643 dropping dow	n		In Date:	08/22/2014	Closed:	09/08/2014
				and top	Parts Li Cylinder Cylinder Shop St	r Repair r Repair			Qty 1.00 1.00 1.00
	Hours :	3 2.50		Labor:	150.00	Parts:	939.20	Total:	1,089.20
	1411691 Driver Rear fla					In Date:	11/18/2014	Closed:	11/18/2014
	1105 Royal Pa t tire (dept has		i bivu (iit oi si	ubway) -					
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1411716 Left rear outer	Meter: tire flat.	43351			In Date:	11/19/2014	Closed:	11/25/2014
- Replace and	balance one ti	re.			Parts L	ist			Qty
- Shop Suppli	es				Shop St	upplies			1.00
						5r17 Tire			1.00
	Hours :	0.50		Labor:	30.00	Parts:	150.50	Total:	180.50
Workorder: Problem:	1500093 Pm service	Meter:	44286			In Date:	01/05/2015	Closed:	01/23/2015
- Pm service.					Parts L	ist			Qty
- Inspect and	service crane.				Used Fi	re X Refurbi	shed		1.00
	ken driver side		oard and both	front	15-40				15.00
	rm bump stops palance all six ti				. •	ld Oil Filter			1.00
- Shop Suppli		163.				er Ford Only	•		1.00
опор оцррп						ydraulic Filtr			1.00
					Wiper B	nade Ining Board	Λem		2.00 1.00
					bumper	•	W2111		2.00
					Shop St				1.00
	Hours	8.00		Labor:	480.00		628.76	Total:	1,108.76
Workorder: Problem:	1501932 Right front tire	Meter: flat.	45945			In Date:	02/24/2015	Closed:	04/30/2015
- Repair and h	alance right fro	nt tire.			Parts L	ist			Qty
- Diagnose ind	op trailer brakes		place six pin			Conn Socket	:		1.00
	power/check e er for high pres				Electrica Shop Su	•			1.00 1.00
- Shop Suppli	• .	cano pan	.p ropidocinicii	•••					
2.70p 3 4ppii		4.50		Labor:	270.00	Parts:	15.92	Total:	285.92

Workorder: Problem:	1505474 Check engine	Meter:	46982 as no power.l	Fumes in	cab.	In Date:	06/01/2015	Closed:	06/04/2015
- Computer di pinpoint test.r& assembly.clea low pressure to repairs.	&r defective ex r code and ret	haust back est.retorqu	pressure ser e exhaust cla	nsor mp at	Parts Lis Sensor A Shop Su	Assembly			Qty 1.00 1.00
- Shop Suppli	es								
	Hou	rs 4.50		Labor:	270.00	Parts:	103.03	Total:	373.03
Workorder: Problem:	1507214 Pm service.	Meter:	48286			In Date:	07/20/2015	Closed:	08/06/2015
- P.m. Service) .				Parts Lis	st			Qty
- Inspect and	service crane.	replace hyd	draulic tank fil	ller cap.	Caster-c	amber Bus	hing		1.00
- Replace two	tires,rotate ar	nd balance	all six.		Hydrauli	c Cap W S	creen		1.00
- Pressure tes	st and inspect	cooling sys	tem.flush and	d refill	15-40 O	il			15.00
system.					Napagol	d Oil Filter			1.00
 Replace right alignment and 		er bushing.	complete who	eel	Fuel Filte	er Ford Onl	У		1.00
- Shop Suppli					Wiper BI	ade			2.00
- Shop Suppli	C S				Napa Hy	draulic Filt	r		1.00
					1796364	92 Lt245-7	′5r17		2.00
					Coolant	Ford Gold			3.00
					Used Fir	e X Refurb	ished		1.00
					Aw68 Hy	dro Fluid H	Hydr		4.00
					Shop Su	pplies			1.00
					Tire Disp	osal Fee			2.00
	Hou :	rs 12.50		Labor:	750.00	Parts:	898.97	Total:	1,648.97

Workorder: 1600713 Meter: 52792	In Date: 01/21/2016 Close	ed: 02/04/2016
Problem: P.M. Seevice.Leak on crane.		
- Pm service.	Parts List	Qty
- Check battery and charging system.both batteries failed	5w20 Engine Oil	7.00
loadtest after recharge.replace both defective	Napagold Oil Filter	1.00
batteries.replace one amber cab lamp and one tail lamp Inspect and service crane.r&r leaking hydraulic hose and	Used Fire X Refurbished	1.00
send out for repair.	22" Wiper Blade	2.00
- Replace four tires.rotate and balance all six.	Washer Fluid Concentr	1.00
- Perform transmission flush.replace filter,gasket and fluid.	Coolant Ford Gold	2.00
- Shop Supplies	Syn-atf Trans Fluid S	14.00
	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
	Battery	2.00
	Led M C Lamp	1.00
	M C Base Mount Kit	1.00
	Napa Hydraulic Filtr	1.00
	Aw68 Hydro Fluid Hydr	5.00
	179636492 Lt245-75r17	4.00
	Syn-atf Trans Fluid S	20.00
	H Y D Hose	1.00
	Trans Pan Gasket	1.00
	Trans Filter	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 14.00 Labo	:: 840.00 Parts: 1,828.77 To	otal: 2,668.77
Workorder: 1601971 Meter: 53577	In Date: 02/25/2016 Close	ed: 03/07/2016
Problem: Always in regen. Exhaust fumes in cab. Ac into	ermittent.	
- Computer diagnose.no codes.test drive.repair oil leaking	Parts List	Qty
into engine.clean oil from engine.change engine oil,oil filter	Napagold Oil Filter	1.00
and air filter.test drive .no odor in cab.	15-40 Oil	15.00
- Shop Supplies	Napagold Air Filter	1.00
	Pm-22-a Additive Dies	1.00
	Shop Supplies	1.00
Hours 3.50 Labo	: 210.00 Parts: 111.80 Te	otal: 321.80

Workorder: 1606717 Meter: 57081 Problem: P.M. Service.Exhaust fumes in cab,	In Date: 07/01/2016 Closed: 07/25/2016
- P.m. Service.	Parts List Qty
- Service and clean air induction system .flush imjectors and	15-40 Oil 15.00
fuel supply.r&r Dpf and pressure clean.clear codes.	Napagold Oil Filter 1.00
- Replace both headlights,one tag light and left turn signal bulb.	Fuel Filter Ford Only 1.00
- Inspect and service rear differential.	20" Wiper Blade 2.00
- Replace both leaking front shocks and both worn out	Used Fire X Refurbished 1.00
bounce stops.	Dpkq7 Egr Service Kit 1.00
- Inspect and service crane.	Kq22932df Diesel Inje 1.00
- Replace and rewire corroded trailer connector.	Exha 1.00
- Rotate and balance all six tires.	Halogen Lamp 2.00
- Shop Supplies	Led M C Lamp 2.00
	Bulb 1.00
	Led Sup Mdl 44 42 Dio 1.00
	75w140 Ford Axle Lube 4.00
	Friction Modifier 2.00
	Reflex Truck Shock 2.00
	Real Suspension Bumpstops 2.00
	Napa Hydraulic Filtr 1.00
	trailer plug 1.00
	Bezel 1.00
	Shop Supplies 1.00
Hours 19.75 Labor:	1,185.0 Parts: 1,141.28 Total: 2,326.28 0
Workorder: 1609858 Meter: 58302 Problem: Fumes in cab.Crossover pipe broken.	In Date: 09/21/2016 Closed: 09/30/2016
- Diagnose and transport vehicle to dealer for exhaust cross	Parts List Qty
over pipe replacement.	Shop Supplies 1.00
- Shop Supplies	
Hours 2.00 Labor:	120.00 Parts: 2.00 Total: 122.00

Workorder: Problem:	1700024 P.M. service	Meter: e and nail in	61388 left rear inn	er tire and r		In Date: e handle.	01/03/2017	Closed:	01/23/2	017
- P.m. Service	9 .				Parts Lis	t				Qty
- Inspect and			aking pressi	ıre hose	ridgid vise	e handle				1.00
and return hos	•				Hose					1.00
 Replace don inbterior bulb. 	ne light bulb	center brake	amp bulbs	s and	Aw68 Hy		Hydr			4.00
- Replace two	tires,rotate	and balance	all six.		Napagold					1.00
- Replace mis	ing vise han	dle.			15-40 Oi	-	L.			15.00
- Complete wh	heel alignme	nt.test drive.	ı		Fuel Filte		ıy			1.00
- Shop Suppli	es				20" Wiper Napa Hyd		r			2.00 1.00
					Bulb	araunc i iii	I			2.00
					Rpl Bulb					1.00
					Map Lam	n				1.00
					•	- 92 Lt245-7	'5r17			2.00
					Shop Sup	plies				1.00
					Tire Dispo	-				2.00
	Ho	ours 14.50		Labor:	870.00	Parts:	904.59	Total:	1,774.5	9
Workorder: Problem:	1700323 Weld Vice	Meter:	61210			In Date:	01/11/2017	Closed:	01/12/2	017
- Weld vice ha	andle				Parts Lis	t				Qty
- Shop Suppli	es				Shop Sup	plies				1.00
	Ho	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1705802 Check engi	Meter: ne light on.	65105			In Date:	06/12/2017	Closed:	06/15/2	017
- Diagnoise ch					Parts Lis	t				Qty
and P20e3 ext		mp out of rar			exhaust s	ensor				3.00
				ensors.test	Blaster Po	enetrant				1.00
sensor Bank o	n self test .pe	'I ISD IZ-IZ:								
	-	: ISD 12-12.			Shop Sup	plies				1.00

Workorder: 17 Problem: P.	707658 .M. service a	Meter: and power	66650 outlet inop.		ln l	Date:	08/04/2017	Closed:	08/16/2017
- P.m. service.					Parts List				Q
- Inspect and ser	rvice crane.				15-40 Oil				16.0
- Check starting	and chargin	g system.b	oth batteries	failed	Napagold Oi	il Filter			1.0
oad test .replace	both batteri	es with ne	w batteries.		Fuel Filter Fo	ord Onl	у		1.0
 Test electrical of 	circuit and re	eplace faile	d power outle	et.	20" Wiper Bl	lade			2.0
 Rotate and high 	h speed bala	ance all six	tires.		Used Fire X	Refurb	ished		1.0
- Shop Supplies					Napa Hydra	ulic Filtr	r		1.0
					Battery				2.0
					Mac Wite Lit	hium G	res		1.0
					Macs Chain	Cable I	Lube		1.0
					Soket Pawer	r Outlet			1.0
					Ring				1.0
					Cover				1.0
					Aw68 Hydro	Fluid H	łydr		8.0
					Shop Suppli	es			1.0
	Hour	s 9.30		Labor:	558.00	Parts:	490.61	Total:	1,048.61
Norkorder: 18	801246	Meter:	70755		In I	Date:	02/01/2018	Closed:	02/05/2018
Problem: Ri									
Problem: Ri	ight rear tire	going flat.		l tires.	Parts List				Q
Problem: Ri - Repair right rea	ight rear tire ar outer tire a	going flat.		l tires.	Parts List Shop Supplie	es			Q 1.0
Problem: Ri - Repair right rea	ight rear tire	going flat.		I tires. Labor:	Shop Suppli	es Parts:	2.00	Total:	
Problem: Ri - Repair right rea - Shop Supplies	ight rear tire ar outer tire a Hour : 802054	going flat.			Shop Suppli		2.00 02/23/2018	Total:	1.0
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pf	ight rear tire ar outer tire a Hour : 802054	going flat. and balanc s 1.00	e .nitrogen fill		Shop Suppli	Parts:			62.00
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl	ight rear tire ar outer tire a Hour : 802054 M Service	going flat. and balanc s 1.00	e .nitrogen fill		Shop Suppli 60.00	Parts:			1.0 62.00 02/27/2018
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl - P.m. service Inspect and ser	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane.	going flat. and balanc s 1.00 Meter:	e .nitrogen fill	Labor:	Shop Supplie 60.00 In I Parts List 15-40 Oil	Parts:			1.0 62.00 02/27/2018
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires.	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires wit	going flat. and balances 1.00 Meter:	e .nitrogen fill 71243 ate and balan	Labor:	Shop Supplie 60.00 In I Parts List 15-40 Oil	Parts: Date: il Filter	02/23/2018		1.0 62.00 02/27/2018 Q 16.0
Problem: Ri - Repair right rea - Shop Supplies Vorkorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four waires Remove both fr	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires wit	going flat. and balances 1.00 Meter: th new .rotand repack weeters	e .nitrogen fill 71243 ate and balan	Labor:	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi	Parts: Date: il Filter ord Onl	02/23/2018 y		1.0 62.00 02/27/2018 Q 16.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four waires Remove both freplace seals.res	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with	going flat. and balances 1.00 Meter: th new .rotand repack we front rotors	e .nitrogen fill 71243 ate and balan wheel bearing	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oil Fuel Filter Fo	Parts: Date: il Filter ord Onlid Conce	02/23/2018 y		1.0 62.00 02/27/2018 Q 16.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Norkorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with the same and	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as	e .nitrogen fill 71243 ate and balan wheel bearing	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo	Parts: Date: il Filter ord Onlid Concellade	02/23/2018 y		1.0 62.00 02/27/2018 Q 16.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.res calipers .flush and	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed braket t asset number	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fe Washer Fluid 20" Wiper Bl	Parts: Date: il Filter ord Onle d Concellade r Filter	02/23/2018 y entr		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0
Problem: Ri - Repair right rea - Shop Supplies - Vorkorder: 18 - Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded fronto-	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo Washer Fluid 20" Wiper Bl Napagold Ai	Parts: Date: il Filter ord Onlid Concellade r Filter ulic Filtr	02/23/2018 y entr		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0
Problem: Ri - Repair right rea - Shop Supplies - Vorkorder: 18 - Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded frontocomplete fronto	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fe Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrae	Parts: Date: il Filter ord Onle d Concel lade r Filter ulic Filtr Lt245-7	02/23/2018 y entr 5r17		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0 1.1
Problem: Ri - Repair right rea - Shop Supplies - Vorkorder: 18 - Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded frontocomplete fronto	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrad 179636492 I	Parts: Date: il Filter ord Onlid Concellade r Filter ulic Filtr Lt245-7	02/23/2018 y entr 5r17 Wheel		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0 1.0 4.0
Problem: Ri - Repair right rea - Shop Supplies Norkorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded front - Complete front	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fe Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrad 179636492 I Wheel Seal	Parts: Date: Il Filter ord Onle d Conce lade r Filter ulic Filtr Lt245-7 - Front ise Calip	02/23/2018 y entr 5r17 Wheel er		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0 1.0 4.0 2.0
Problem: Ri - Repair right rea - Shop Supplies Norkorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded front - Complete front	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrad 179636492 I Wheel Seal Reman Brak	Parts: Date: Il Filter ord Onle d Conce lade r Filter ulic Filtr Lt245-7 - Front ise Calip	02/23/2018 y entr 5r17 Wheel er		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 1.0 4.0 2.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Norkorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.resealipers .flush and R&r faded front	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fe Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrad 179636492 I Wheel Seal Reman Brak Reman Brak	Parts: Date: Il Filter ord Onle d Conce lade r Filter ulic Filtr Lt245-7 - Front ise Calip	02/23/2018 y entr 5r17 Wheel er		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 2.0 1.0 4.0 2.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pt - P.m. service.	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo Washer Fluid 20" Wiper Bl Napagold Ai Napa Hydrad 179636492 I Wheel Seal Reman Brak Reman Brak Pads	Parts: Date: il Filter ord Onle d Conce lade r Filter ulic Filtr Lt245-7 - Front ice Calip ice Calip ice Calip	02/23/2018 y entr 5r17 Wheel er		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 4.0 2.0 1.0 1.0 1.0
Problem: Ri - Repair right rea - Shop Supplies Workorder: 18 Problem: Pl - P.m. service Inspect and ser - Replace four wires Remove both freplace seals.res calipers .flush and - R&r faded front - Complete front	ight rear tire ar outer tire a Hour : 802054 M Service rvice crane. worn tires with ront hubs and surface both ad bleed brake t asset number end alignment	going flat. and balances 1.00 Meter: th new .rotated repack we front rotors are system as overs .	e .nitrogen fill 71243 ate and balan wheel bearing s.replace pade	Labor: ace all six s and s and	Shop Supplie 60.00 In I Parts List 15-40 Oil Napagold Oi Fuel Filter Fo Washer Fluic 20" Wiper Bl Napagold Ai Napa Hydrae 179636492 I Wheel Seal Reman Brak Reman Brak Pads B Fluid Dot 3	Parts: Date: il Filter ord Onl d Conce lade r Filter ulic Filtr Lt245-7 - Front ae Calip ae Calip 3-32oz es	02/23/2018 y entr 5r17 Wheel er		1.0 62.00 02/27/2018 Q 16.0 1.0 1.0 1.0 4.0 2.0 1.0 1.0 1.0

Workorder: 1806190 Meter: 74088 Problem: Hydraulic oil leakin g under truck.			In Date:	06/18/2018	Closed:	06/25/2018	
- R&r leaking hydraulic hose,reservior to pressure valve.refill hydraulic fluid Shop Supplies			Aw68 Hydro Fluid Hydr Hose Assy				
Hours 5.00	Labor:	Shop Sup 300.00	•	255.98	Total:	1.00 555.98	
Workorder: 1807946 Meter: 75101 Problem: 1 - Key(s) issued			In Date:	08/02/2018	Closed:	08/02/2018	
- 1 - Key(s) issued		Parts Lis	st			Qty	
		Duplicate	1.00				
Hours 0.30	Labor:	18.00	Parts:	3.00	Total:	21.00	
Workorder: 1811777 Meter: 77427 Problem: PM Service, Check engine light, Detail			In Date:	11/16/2018	Closed:	12/05/2018	
- P.m. service.		Parts Lis	st			Qty	
- Replace broken crane hook safety latch and rusted	Napagolo	1.00					
mounting bolts . Inspect and service crane.		15-40 O	15.00				
 Test and replace left led stop lamp. Remove and re ground circuit for three lamp parking light bar. 	pair	Fuel Filter Ford Only				1.00	
- Computer diagnose Abs light . code C1155 . Perform	Used Fire X Refurbished				1.00		
pinpoint test . R&r defective left front wheel speed sensor .			Ford Triton Pvc Swc				
Clear code and retest.	20" Wiper Blade Napa Hydraulic Filtr Led Sup Mdl 44 42 Dio Non-chlor Brake Clnr B Fluid Dot 3-32oz				2.00		
 Resurface both rear brake rotors. Replace both rea calipers and pads. Flush and bleed brake system. Ro 					1.00		
test.					1.00		
- Replace both front upper and lower ball joints .					1.00		
- Rotate and balance all six tires. Nitrofill all.		1.00 1.00					
- Complete front end alignment and road test.	Reman Brake Caliper Reman Brake Caliper				1.00		
- Shop Supplies		Sensor Asy				1.00	
	Brake Pad Latch Hook Kit				1.00		
					1.00		
	Lower Ball Joint				2.00		
	Upper Ball Joint				2.00		
	Washer Fluid Concentr				1.00		
		Shop Supplies				1.00	
Hours 23.20 :	Labor:	1,554.4 0	-	754.25	Total:	2,308.65	
Workorder: 1812232 Meter: 77194 Problem: 1 - Wash ticket(s) issued			In Date:	11/30/2018	Closed:	11/30/2018	
- 1 - Wash ticket(s) issued							
Hours 0.00 :	Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1902519 Crane inop	Meter: and light bar	79044 inop.			In Date:	03/06/2019	Closed:	03/13/20)19
- Diagnose crane inop. Test circuits to crane . Repair bad connection at crane power switch . Retest operation of crane					Parts Lis				Qty	
- Diagnose lig . Repair powe - Shop Suppli	r cable melte									
	Ho :	urs 1.80		Labor:	120.60	Parts:	3.00	Total:	123.60	
Workorder: Problem:	1904951 P.M. service	Meter: and towed	79057 in for no sta	art.		In Date:	05/07/2019	Closed:	05/16/20)19
- P.m. service) .				Parts Lis	st				Qty
- Charge both			ries and ch	arging	Napagol	d Oil Filter				1.00
system . R&r both defective batteries .					15-40 O	il		15.0	15.00	
- Inspect and	service crane	e and outrigo	gers .		20" Wipe	r Blade				2.00
- Rotate and	high speed ba	alance all six	ctires . Nitro	ofill all.	Washer	Fluid Conce	entr			1.00
- Shop Supplies				Fuel Filte	er Ford Onl			1.00		
			Battery				2.00			
				Napa Hy	draulic Filtr				1.00	
					Shop Su	pplies				1.00
	Ho	urs 9.50		Labor:	636.50	Parts:	404.96	Total:	1,041.46	6
Workorder: Problem:	1905000 No start	Meter:	79044			In Date:	05/07/2019	Closed:	05/08/20)19
- Tow From: 'shop	12500 40th st	reet, Royal	Palm Beach	To: Lv						
	Ho :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1905394 Runs rough	Meter:	79062			In Date:	05/17/2019	Closed:	05/23/20)19
- Perform eng power balance from injector a	e test . numbe and test drive	er four cylind			Parts Lis Shop Su					Qty 1.00
- Shop Suppli		urs 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00	
	:									

Labor: 0.00

Hours 0.00

Parts: 0.00

Total: 0.00

Workorder: 1907355 81122 07/16/2019 07/25/2019 Meter: In Date: Closed: Problem: Towed in for stalled and crank no start. - Replace left headlight assembly thats full of water. **Parts List** Qty - Computer diagnose no start. Test fuel pressure . no Halogen Sealed Beams 1.00 presure. Front tank empty. full with five gallon of fuel. Bleed Fuel Pump 1.00 system and test leak down . R&r defective frame rail fuel **Shop Supplies** 1.00 pump assembly . Bleed system and retest . Road test . - Shop Supplies Hours 3.00 Labor: 201.00 Parts: 390.86 Total: 591.86 Workorder: 1912359 Meter: 81122 In Date: 12/02/2019 Closed: 12/03/2019 Problem: remove compressor for customer **Parts List** - remove air compressor for customer Qty - Shop Supplies **Shop Supplies** 1.00 Labor: 182.50 Hours 2.50 Parts: 4.00 Total: 186.50 Workorder: 1912394 Meter: 81122 In Date: 12/03/2019 Closed: 12/03/2019 Problem: Transition Prep Charge - Transition Prep Charge Labor: 146.00 Hours 2.00 Parts: 0.00 Total: 146.00