10192551 2013 FORD F150 Pickup, 1/2 Ton

Workorder: 1306739 Meter: 343 In Date: 07/08/2013 Closed: 07/08/2013 Problem: 1061 - Pre Delivery Inspection - Pre Delivery Inspection - Wash Vehicle Hours 3.00 Labor: 180.00 Total: 180.00 Parts: 0.00 Workorder: 1307242 Meter: 343 In Date: 07/19/2013 Closed: 08/08/2013 Problem: Install toolbox. - Fabricate and install new tool box in bed of truck install new Parts List Qty floor mats to protect carpet. Tool Box 1.00 - Shop Supplies Floor Mat-2pc Rub Bk 1.00 Shop Supplies 1.00 Hours 1.50 Labor: 90.00 Parts: 656.69 Total: 746.69 1310114 Workorder: Meter: 5642 Closed: 10/31/2013 In Date: 10/07/2013 **Problem:** Pm service and major damage to front bumper. **Parts List** - Perform pm service. Qty - Remove front bumper Fabricate with torch and realign front 5w20 Engine Oil 6.00 brackets and bumper cover. Napagold Oil Filter 1.00 - Rotate and balance all four tires. Shop Supplies 1.00 - Shop Supplies Hours 5.00 Labor: 300.00 Parts: 22.00 Total: 322.00 1400594 Workorder: Meter: 12592 In Date: 01/14/2014 Closed: 01/17/2014 Problem: Flat tire: right rear - Tire Service 8100 Forest Hill Blvd East end of warehouse bldg - Flat tire: right rear Labor: 0.00 Total: 0.00 Hours 0.00 Parts: 0.00 Workorder: 1401405 Meter: 13810 In Date: 02/11/2014 Closed: 02/28/2014 Problem: Pm service. Check tires. Deodorize. Request to detail vehicle - Perform pm service. **Parts List** Qty - Rotate and balance all four tires. 5w20 Engine Oil 6.00 - Perform wheel alignment complete. Napagold Oil Filter 1.00 - Shop Supplies Washer Fluid Concentr 1.00 Used Fire X Refurbished 1.00 Wiper Blade 1.00 Wiper Blade 1.00 235 75r17 Adventure 4.00 Shop Supplies 1.00 Tire Disposal Fee 4.00 Hours 6.50 Labor: 390.00 Parts: 988.54 Total: 1,378.54

Workorder: Problem:	1401582 1 - Detail V	Meter: 'ehicle Wash	13680 Ticket(s) Is	ssued		In Date:	02/19/2014	Closed:	02/19/20	014
- 1 - Detail Ve	ehicle Wash	Ticket(s) Issu	ıed							
	H(ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1406306 pm	Meter:	19624			In Date:	06/26/2014	Closed:	07/07/2	014
- pm					Parts L	_ist				Qty
- Shop Suppl	ies				Napago	old Oil Filter				1.00
					Napa C	Quart 5w20				6.00
					Washe	r Fl				1.00
						Supplies				1.00
	H(ours 2.00		Labor:	120.00	Parts:	30.79	Total:	150.79	
Workorder: Problem:	1410493 pm cs	Meter:	24240			In Date:	10/21/2014	Closed:	10/30/20	014
- pm					Parts L	_ist				Qty
- Shop Suppl	ies				Napago	old Oil Filter				1.00
					Napa C	Quart 5w20				6.00
					Washe	r Fl				1.00
					Wiper E	Blade				1.00
					Wiper E	Blade				1.00
					Mac W	ite Lithium G	res			1.00
					Shop S	Supplies				1.00
	H(ours 2.00		Labor:	120.00	Parts:	45.05	Total:	165.05	
Workorder: Problem:	1503934 pm, ritght r	Meter: ear tire has a	29777 screw but	maintain pro	oper pre	In Date:	04/16/2015	Closed:	04/23/20	015
- pm					Parts L	_ist				Qty
- nail right rea	ar tire verify	complaint rep	air tire add	d n2	Napa C	Quart 5w20				6.00
- Shop Suppl	ies				Napago	old Oil Filter				1.00
					Shop S	Supplies				1.00
	H(ours 3.00		Labor:	180.00	Parts:	27.67	Total:	207.67	
Workorder: Problem:	1508018 pm	Meter:	35581			In Date:	08/11/2015	Closed:	08/27/2	015
- pm					Parts L	_ist				Qty
- replace two		tate to front r	nount blan	ace add n2						
- Shop Suppl	ies					Quart 5w20				7.00
					Wiper E					2.00
					Washe	r Fl				1.00
						ok P235 75r1	7 Dp At			2.00
					-	Supplies				1.00
						sposal Fee				2.00
	H(ours 3.50		Labor:	210.00	Parts:	478.82	Total:	688.82	

Workorder: 1 Problem: P	512016 ² .M. Service	Meter: e.Right rear	40807 tire flat.		In Da	ate:	11/30/2015	Closed:	12/09/2015
- Pm service.					Parts List				Qty
- Replace front	and rear bra	ake pads.re	surface all fo	ur brake	5w20 Engine (7.00			
rotors.lube calipe					Napagold Oil I	1.00			
- Replace two ti	res.rotate a	ind balance	all four.		Napagold Air				1.00
- Perform transr	mission flus	h service.			22" Wiper Blad	2.00			
- Replace broke	en left side s	seat trim par	nels.		Used Fire X R	efurb	ished		1.00
- Shop Supplies	3				Stg Wheel Co	v - Fo	ord		1.00
					kit brak				1.00
					Pad Brak				1.00
					B Fluid Dot 3-	32oz			2.00
					Brake Cleaner	r			1.00
					235 75r17 Adv	ventu	re		2.00
					Syn-atf Trans	Fluid	S		12.00
					Housing				1.00
					seatpanel shie	eld as	у		1.00
					Shop Supplies	3		1.00	
					Tire Disposal I	Fee		2.00	
	Hou	urs 13.00		Labor:	780.00 F	Parts:	832.67	Total:	1,612.67
Problem: rr	512020 · flat tire/ pn	Meter: n	40730		In Da	ate:	11/30/2015	Closed:	11/30/2015
	flat tire/ pn	n	40730	Labor:			11/30/2015 0.00	Closed:	
Problem: rr	flat tire/ pn oc bldg 2 To Hou : 603542	n o: Iv shop urs 0.00	40730 46161	Labor:		Parts:			
Problem: rr - Tow From: cro Workorder: 1	flat tire/ pn oc bldg 2 To Hou : 603542	n o: Iv shop urs 0.00		Labor:	0.00 F	Parts:	0.00	Total:	0.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service.	r flat tire/ pn oc bldg 2 To Hou : 603542 P.M. Service	n o: Iv shop urs 0.00 Meter:	46161	Labor:	0.00 F In Da	oarts:	0.00	Total:	0.00 04/19/2016 Qty
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.eva	r flat tire/ pn oc bldg 2 To Hou : 603542 P.M. Service necksytem,l acuate syst	n o: Iv shop urs 0.00 Meter: ow freon,leadem and rep	46161 aking lace		0.00 F	Parts: ate: Oil	0.00	Total:	0.00 04/19/2016 Qty 7.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci	r flat tire/ pn oc bldg 2 To Hou : 603542 P.M. Service necksytem,l acuate syst	n o: Iv shop urs 0.00 Meter: ow freon,leadem and rep	46161 aking lace		0.00 F In Da Parts List 5w20 Engine 0	Parts: ate: Oil Filter	0.00	Total:	0.00 04/19/2016 Qty 7.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,l acuate syst umulator ar .leak test.	o: Iv shop urs 0.00 Meter: e. ow freon,leader and replaced orifice.vac	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I	Parts: ate: Oil Filter de	0.00	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressor.ev compressor,acc system to specs - R&r driveshaft	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,l acuate syst umulator ar .leak test.	o: Iv shop urs 0.00 Meter: e. ow freon,leader and replaced orifice.vac	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I 22" Wiper Blace	Parts: ate: Oil Filter de Conc	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressor.acc compressor,acc system to specs - R&r driveshaft	r flat tire/ pn oc bldg 2 To Hou : 603542 P.M. Service necksytem,l acuate syst umulator ar leak test. and replac	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid	Parts: ate: Oil Filter de Conc	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressor,acci system to specs - R&r driveshaft seal.	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi	Parts: ate: Oil Filter de Conc	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi Compressor	Parts: ate: Oil Filter de Conc	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I 22" Wiper Black Washer Fluid Mac Wite Lithi Compressor Accumulator	Parts: ate: Oil Filter de Conc	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi Compressor Accumulator Seal Kits	Parts: Oil Filter de Concium G	0.00 04/04/2016 entr	Total:	0.00 04/19/2016 Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I 22" Wiper Black Washer Fluid Mac Wite Lithi Compressor Accumulator Seal Kits Seal	Parts: ate: Oil Filter de Concium G	0.00 04/04/2016 entr ires	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00 1.00 2.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine O Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi Compressor Accumulator Seal Kits Seal Syn-atf Trans	Parts: Oil Filter de Concium G	0.00 04/04/2016 entr cres S Seal	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00 1.00 2.00 1.00 1
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I 22" Wiper Black Washer Fluid (Mac Wite Lithic Compressor Accumulator Seal Kits Seal Syn-atf Trans Transmission	Parts: Oil Filter de Concium G	0.00 04/04/2016 entr cres S Seal	Total:	0.00 04/19/2016 Qty 7.00 1.00 2.00 1.00 1.00 1.00 2.00 1.00 1
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi Compressor Accumulator Seal Kits Seal Syn-atf Trans Transmission Transmission	Parts: Oil Filter de Concium G	0.00 04/04/2016 entr cres S Seal	Total:	0.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressdor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine (Napagold Oil I 22" Wiper Black Washer Fluid (Mac Wite Lithic Compressor Accumulator Seal Kits Seal Syn-atf Trans Transmission Transmission Nut Tram	Parts: Tate: Oil Filter de Concium G Fluid Real Real	0.00 04/04/2016 entr cres S Seal	Total:	0.00 04/19/2016 Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: rr - Tow From: cro Workorder: 1 Problem: P - P.m. Service A/c not cold.ch compressor.ev compressor,acci system to specs - R&r driveshaft seal Rotate and ba	r flat tire/ pn c bldg 2 To Hou : 603542 P.M. Service necksytem,lacuate syst umulator ar leak test. and replace	Meter: ow freon, leader and replaced orifice. value leaking trains	46161 aking lace cuum and rec	charge	0.00 F In Da Parts List 5w20 Engine 0 Napagold Oil I 22" Wiper Blac Washer Fluid Mac Wite Lithi Compressor Accumulator Seal Kits Seal Syn-atf Trans Transmission Transmission Nut Tram V Belt	Parts: Oil Filter de Concium G Fluid Real Real	0.00 04/04/2016 entr cres S Seal	Total:	0.00 04/19/2016 Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

:

In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	tre de de de de de de de de de de de de de	Total:	1,159.34	2.00 1.00 2.00 1.00 2.00 1.00 2.00
Used Fire X Refurb Bulb 235 75r17 Adventu Blower Resistor Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	tre de de de de de de de de de de de de de			6.00 1.00 2.00 1.00 2.00 1.00 2.00 2.00 1.00 2.00
Used Fire X Refurb Bulb 235 75r17 Adventu Blower Resistor Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	tre de de de de de de de de de de de de de			1.00 1.00 2.00 1.00 2.00 1.00 2.00 2.00
Bulb 235 75r17 Adventu Blower Resistor Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	tre de de de de de de de de de de de de de			1.00 2.00 1.00 2.00 1.00 2.00 2.00 16 Qty 1.00
235 75r17 Adventus Blower Resistor Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	te: 559.34 11/16/2016			2.00 1.00 2.00 1.00 2.00 1.00 2.00
Blower Resistor Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	te: 559.34 11/16/2016			1.00 2.00 1.00 2.00 1.00 2.00
Ford Red Antifreez Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			2.00 1.00 2.00 1.00 2.00 16 Qty 1.00
Napagold Oil Filter 22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts: In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			1.00 2.00 1.00 2.00 116 Qty 1.00
22" Wiper Blade Shop Supplies Tire Disposal Fee 600.00 Parts In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			2.00 1.00 2.00 116 Qty 1.00
Shop Supplies Tire Disposal Fee 600.00 Parts In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			1.00 2.00 116 Qty 1.00
Tire Disposal Fee 600.00 Parts In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			2.00 116 Qty
In Date: Parts List Napagold Oil Filter 5w20 Engine Oil	11/16/2016			116 Qty 1.00
Parts List Napagold Oil Filter 5w20 Engine Oil		Closed:	11/30/20	Qty 1.00
Parts List Napagold Oil Filter 5w20 Engine Oil		Closed:	11/30/20	Qty 1.00
Napagold Oil Filter 5w20 Engine Oil				1.00
5w20 Engine Oil				1.00 6.00
•	r			6.00
Napagold Air Filte	r			
			1.00	
22" Wiper Blade				2.00
Washer Fluid Cond	centr			1.00
235 75r17 Adventu	ire			2.00
Repair Kit				1.00
Shop Supplies				1.00
Tire Disposal Fee				2.00
315.00 Parts	483.29	Total:	798.29	
In Date:	01/12/2017	Closed:	01/23/20	17
Parts List				Qty
Battery				1.00
Bat Term Protector	r			1.00
Shop Supplies				1.00
	132.28	Total:	192.28	
In Date:	04/10/2017	Closed:	04/18/20	17
Parts List				Qty
5w20 Engine Oil				6.00
Oil Filter				1.00
22" Wiper Blade				2.00
Bulb				1.00
Shop Supplies				1.00
	: 25.15	Total:	235.15	
	22" Wiper Blade Washer Fluid Cond 235 75r17 Adventu Repair Kit Shop Supplies Tire Disposal Fee 315.00 Parts In Date: Parts List Battery Bat Term Protector Shop Supplies 60.00 Parts In Date: Parts List 5w20 Engine Oil Oil Filter 22" Wiper Blade Bulb Shop Supplies	Washer Fluid Concentr 235 75r17 Adventure Repair Kit Shop Supplies Tire Disposal Fee : 315.00 Parts: 483.29 In Date: 01/12/2017 Parts List Battery Bat Term Protector Shop Supplies : 60.00 Parts: 132.28 In Date: 04/10/2017 Parts List 5w20 Engine Oil Oil Filter 22" Wiper Blade Bulb Shop Supplies	22" Wiper Blade Washer Fluid Concentr 235 75r17 Adventure Repair Kit Shop Supplies Tire Disposal Fee : 315.00 Parts: 483.29 Total: In Date: 01/12/2017 Closed: Parts List Battery Bat Term Protector Shop Supplies : 60.00 Parts: 132.28 Total: In Date: 04/10/2017 Closed: Parts List 5w20 Engine Oil Oil Filter 22" Wiper Blade Bulb Shop Supplies	Napagold Air Filter 22" Wiper Blade Washer Fluid Concentr 235 75r17 Adventure Repair Kit Shop Supplies Tire Disposal Fee : 315.00 Parts: 483.29 Total: 798.29 In Date: 01/12/2017 Closed: 01/23/20 Parts List Battery Bat Term Protector Shop Supplies : 60.00 Parts: 132.28 Total: 192.28 In Date: 04/10/2017 Closed: 04/18/20 Parts List 5w20 Engine Oil Oil Filter 22" Wiper Blade Bulb Shop Supplies

Workorder: 1708083 Meter: 71114	In Date: 08/16/2017 Closed:	08/31/2017
Problem: PM Service, Shaky ride.		
- P.m. service.	Parts List	Qty
- Test drive to diagnoise shake condition.measure tire road	5w20 Engine Oil	6.00
force.limits exceeded all tires.mount and balance four new	Napagold Oil Filter	1.00
tires.nitrofill.	22" Wiper Blade	2.00
- Perform rear differential service.	Used Fire X Refurbished	1.00
- Replace worn left door check strap.replace broken left seat trim panels.	Stg Wheel Cov - Ford	1.00
- Perform complete wheel alignment.test drive.	Bulb	1.00
- Shop Supplies	Hankook P235 75r17 Dp At	4.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	1.00
	Check Asy	1.00
	Housing	1.00
	seatpanel shield asy	1.00
	Non-chlor Brake Clnr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50 Labor:	510.00 Parts: 1,184.07 Tota	ll: 1,694.07
: Workorder: 1802327 Meter: 76349	In Date: 03/01/2018 Closed:	
<u> </u>		
: Workorder: 1802327 Meter: 76349		
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper	In Date: 03/01/2018 Closed:	: 03/08/2018
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs.	In Date: 03/01/2018 Closed: Parts List	03/08/2018 Qty
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil	Qty 6.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter	Qty 6.00 1.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter	Qty 6.00 1.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr	Qty 6.00 1.00 1.00 1.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr 22" Wiper Blade	Qty 6.00 1.00 1.00 2.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr 22" Wiper Blade Spark Plugs	Qty 6.00 1.00 1.00 2.00 6.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr 22" Wiper Blade Spark Plugs Injector Cleaner	Qty 6.00 1.00 1.00 2.00 6.00 1.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr 22" Wiper Blade Spark Plugs Injector Cleaner Intake Cleaner Kit	Qty 6.00 1.00 1.00 2.00 6.00 1.00 1.00
: Workorder: 1802327 Meter: 76349 Problem: P.M. service. - P.m. service. - Perform tune-up.replace all six spark plugs .r&r upper intake to access plugs. - Induction system cleaning.flush injector .clean trottle body .clear all codes with scan tool. - Rotate and high speed balance all four tires.	In Date: 03/01/2018 Closed: Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter Washer Fluid Concentr 22" Wiper Blade Spark Plugs Injector Cleaner Intake Cleaner Kit Throttle Body Cleaner	Qty 6.00 1.00 1.00 2.00 6.00 1.00 1.00

Workorder: Problem:	1806554 P.M. service.	Meter:	82252			In Date:	06/27/2018	Closed:	07/12/20)18
- P.m. service					Parts Li	st				Qty
- Replace two	tires .rotate a	nd high sp	eed balance all	four	Napago		1.00			
tires. Nitrogen					5w20 Er			6.00		
			king water pum		22" Wip	er Blade				2.00
and water pun		stem and	retest .replace /	A/C Delt	Hankool			2.00		
•	nplete front end	d alignmen	t. Road test.		Anti Fre			1.00		
- Shop Suppli	•	a ag			Gasket					1.00
олор опрри					Gasket					1.00
					Thermo	stat				1.00
					V Belt					1.00
					V Belt					1.00
					Water P	ump				1.00
					Thermo	stat Gasket				1.00
					Gasket					1.00
					Shop Su	ıpplies				1.00
					Tire Dis	oosal Fee				2.00
	Houi	rs 10.90		Labor:	654.00	Parts:	705.57	Total:	1,359.57	7
Workorder: Problem:	1807041 replace winds	Meter: sheild	82269			In Date:	07/11/2018	Closed:	07/18/20)18
- set up frepa	irs & reasett				Parts Li	st				Qty
- Shop Suppli					Shop Su	ıpplies				1.00
		rs 1.00		Labor:	-	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1808718 Stalls.	Meter:	83971			In Date:	08/23/2018	Closed:	08/28/20)18
- Computer di	agnose stalling	g ,no code	es present. Test	t drive .	Parts Li	st				Qty
Perform evap	test. R&r stuck	open pur	ge valve .retest		Purge V					1.00
	gram Pcm with	updated c	alibration.		Shop Su	ıpplies				1.00
- Shop Suppli		rs 3.00		Labor:	180.00	Parts:	46.73	Total:	226.73	
Workorder:	: 1809774 Wont start, Ju	Meter:	85160			In Date:	09/21/2018	Closed:	09/26/20)18
		-								
			t. Code P0230		Parts Li					Qty
Perform fuel pressure test . Pinpoint test . R&r defective fuel pump driver module . Clear codes and test drive.				Fuel Pump Module					1.00	
- Shop Suppli					Shop Su	ıpplies				1.00
Chief Cappii		rs 2.00		Labor:	120.00	Parts:	33.65	Total:	153.65	
Workorder:	1809775 wont start, jur	Meter:	84993			In Date:	09/21/2018	Closed:	09/21/20)18
	•		up.							
- IOW From: (Croc O&m build	•	up	1 -1	0.00	D	0.00	T	0.00	
	Houi	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1810681 Left rear tire	Meter: going flat.	86053			In Date:	10/17/2018	Closed:	10/18/2	018
- Repair left r	ear tire and ba	lance . Nitr	ogen fill all tire	es.	Parts L	ist				Qty
- Shop Suppl	ies				Shop St	upplies				1.00
	Hou	rs 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00	
Workorder: Problem:	1811605 P.M. service.	Meter:	87408			In Date:	11/13/2018	Closed:	11/26/2	018
- P.m. service) .				Parts L	ist				Qty
- Resurface rear brake rotors and replace front rotors .					Napago	ld Oil Filter				1.00
Replace all four calipers and brake pads . Flush and bleed brake system . Test drive.					Napa Q	uart 5w20				6.00
-		and haland	e all four tires	.	Used Fi	re X Refurb	ished			1.00
- Replace two tires . Rotate and balance all four tires. Nitrogen fill all tires.					Washer	Fluid Conc	entr			1.00
- Shop Suppl	ies				•	er Blade				2.00
					Brake R					2.00
					Brake P					1.00
					Brake P					1.00
					Brake C	•				1.00 1.00
					Reman/	•				1.00
					Reman/					1.00
						Dot 3-32oz				1.00
					Non-chl	or Brake Cli	nr			3.00
					Hankoo	k P235 75r1	17 Dp At			2.00
					Caliper	Washer				4.00
					Shop St	upplies				1.00
					Tire Dis	posal Fee				2.00
	Hou :	rs 11.00		Labor:	737.00	Parts:	1,095.64	Total:	1,832.6	4
Workorder: Problem:	1901945 Right rear tire	Meter: going flat.	92129			In Date:	02/20/2019	Closed:	02/22/2	019
- Repair right	rear tire and b	alance . Ni	trofill all.		Parts L	ist				Qty
- Shop Suppl	ies				Shop St	upplies				1.00
	Hou	rs 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00	
Workorder: Problem:	1902898 PM Service	Meter:	93519			In Date:	03/15/2019	Closed:	03/22/2	019
- P.m. Service	е.				Parts L	ist				Qty
- Replace tag						ld Oil Filter				1.00
- Rotate and	•				. •	ngine Oil				6.00
- Shop Suppl	ies					ld Air Filter				1.00
					22" Wip	er Blade				2.00
					Boxed N	Miniatures				1.00
					Ford Tri	ton Pvc Sw	С			1.00
					Shop St	upplies				1.00
	Hou	rs 3.50		Labor:	234.50	Parts:	56.42	Total:	290.92	

Workorder: Problem:	1903235 1 - Detail Ve	Meter: hicle Wash	93519 Ticket(s) Issu	ued		In Date:	03/25/2019	Closed:	03/25/2019
- 1 - Detail Ve	hicle Wash T	icket(s) Issu	ed						
	Hor :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1909757 P.M. service	Meter: and detail.	97671			In Date:	09/23/2019	Closed:	10/07/2019
- P.m. service					Parts L	ist			Qty
- Replace two	tires . Rotate	e and baland	e all four tire	s. Nitrofill	5w20 E	ngine Oil			7.00
all.					Napago	ld Oil Filter			1.00
- Pressure tes heater hose fro					Used Fi	re X Refurb	ished		1.00
retest.	JIII LAIIK LO LIII	emiosiai io	leater core.	ixeiiii aiiu	22" Wiper Blade				2.00
- Shop Suppli	es				Hankook P235 75r17 Dp At				2.00
					Anti Freeze Motorcraft				1.00
					Heater I	Hose			1.00
					Shop St	upplies			1.00
					Tire Dis	posal Fee			2.00
	Hor :	urs 5.50		Labor:	401.50	Parts:	642.74	Total:	1,044.24
Workorder: Problem:	1910219 1 - Detail Ve	Meter: hicle Wash	97658 Ticket(s) Issu	ued		In Date:	10/02/2019	Closed:	10/02/2019
- 1 - Detail Ve	hicle Wash T	icket(s) Issu	ed						
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	2000597	Meter:	101313			In Date:	01/16/2020	Closed:	01/16/2020
Problem:	Transition P	rep Charge							
- Transition P	rep Charge								
	Hoi	urs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00