10194179 2013 MENZI MUCK M540 Excavator, Walking, All Terrain

 Workorder:
 1401684
 Meter:
 13
 In Date:
 02/20/2014
 Closed:
 02/28/2014

 Problem:
 check in

Check In and tint windows
 Shop Supplies
 Window Tint
 1.00

Shop Supplies 1.00

1.00

Hours 5.00 Labor: 300.00 Parts: 827.00 Total: 1,127.00

**Workorder:** 1401759 **Meter:** 13 **In Date:** 02/24/2014 **Closed:** 02/24/2014

**Problem:** 1062 - Make & Apply Decals. Check Fluids, Belts and Operation

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours 1.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Workorder: 1402397 Meter: 13 In Date: 03/12/2014 Closed: 03/17/2014

Problem: Road Call

- check overheat Parts List Qty
- to sabal palm ditch Bandenmarkt Bmt-09 600/65r23 1.00

- tire damaged Shop Supplies 1.00- Shop Supplies Tire Disposal Fee 1.00

Hours 3.00 Labor: 180.00 Parts: 3,469.00 Total: 3,649.00

:

Workorder: 1402425 Meter: 13 In Date: 03/12/2014 Closed: 03/14/2014

**Problem:** Repair Flat

- flat repair

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Workorder: 1402904 Meter: 13 In Date: 03/26/2014 Closed: 03/28/2014

Problem: Greese

- Greese Parts List Qty

- Shop Supplies 5% Moly Req'd 20.00

Shop Supplies

Hours 0.00 Labor: 0.00 Parts: 91.40 Total: 91.40

:

Workorder: Problem:	1403208 grease	Meter:	100			In Date:	04/02/2014	Closed:	04/29/2014
- grease	3				Parts L	ist			Qty
- to acme dair	y rd				5% Moly	y Req'd			20.00
to lantanna rd	2 times				15-40 C	Dil			24.00
- check startin	g system				Aw68 H	ydro Fluid H	Hydr		1013.00
- pm					85-140	Gear Oil G	ear		16.00
- service final	drives				5% Moly	y Req'd			20.00
- weld assets	to attachmen	ts			Oil Filter				1.00
<ul> <li>check hyd le engine bay</li> </ul>	ak. fill tank. r	epair leak a	nd R&r panels	. wash		ydro Fluid F	lydr		60.00
- Shop Suppli	es				Shop Su				1.00
	Цал	ro 27.00		Lobori	Freight	•	2.066.40	Totalı	1.00
	: :	ırs 27.00		Labor.	1,620.0 0	Paris.	2,966.10	Total.	4,586.10
Workorder: Problem:	1403839 pm by menz	Meter:	13			In Date:	04/21/2014	Closed:	04/22/2014
- P.m. By Mer	nzi								
	Ηοι :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1404342 hyd leak	Meter:	200			In Date:	05/02/2014	Closed:	07/08/2014
- replace pow	er tilt hoses. f	ill hyd tank			Parts L	ist			Qty
- to lantanna a	and fearnly 3	times			5% Moly	y Req'd			20.00
to mako					5% Moly	y Req'd			40.00
- Pm	ord and blood	dayatam			Aw68 H	ydro Fluid H	lydr		78.00
replace fuel filt - grease	eru ariu bieet	a system			Hyd Hos	se Assy			1.00
- Shop Suppli	<b>0</b> 0				Washer	FI			2.00
- Onop Suppli	<del></del>				M5 Filte	r Kit			1.00
					Napa G	al 15w40			6.00
					Fuel Inje	ection Hose			15.00
					Shop St	upplies			1.00
	Ηοι :	urs 15.50		Labor:	930.00	Parts:	2,817.85	Total:	3,747.85
Workorder: Problem:	1406716 overheat	Meter:	200			In Date:	07/08/2014	Closed:	07/29/2014
- check overh	eat				Parts L	ist			Qty
- to blanchette	and yearling	I			5% Moly	y Req'd			20.00
- grease					Shop St	upplies			1.00
- Shop Suppli	es				-				
		urs 2.50		Labor:	150.00	Parts:	91.40	Total:	241.40

Workorder: 1407507 Meter: 200 Problem: Greese	In Date:	07/31/2014	Closed:	08/04/2014
- grease	Parts List			Qty
- Shop Supplies	5% Moly Req'd			20.00
	Shop Supplies			1.00
Hours 0.50 Labor :	30.00 Parts:	91.40	Total:	121.40
Workorder: 1408194 Meter: 417 Problem: Greese	In Date:	08/19/2014	Closed:	01/12/2015
- grease	Parts List			Qty
- R&r bucket	5% Moly Req'd			120.00
- remove pin to change push rod	Hose Make Up			1.00
- to jpp. to lake blvd. to lyons many times	Push Rod			1.00
- repair hyd leak at leg. repair hyd leak at pump. add hyd	Pin			1.00
fluid	Spacer			2.00
- R&r power tilt. repair power tilt. weld eye on power tilt	Snap Ring			2.00
- to lyons rd. to industrial dr. to german town rd	Peak Global			1.00
- replace power tilt lines 2 times. fill hyd fluid	Aw68 Hydro Fluid H	Hydr		18.00
- to lyons rd. to clintmoore	Hose Make Up			1.00
- check and add coolant. check overheating. clean debris from radiator	Hose Make Up			1.00
- replace power tilt hoses	Aw68 Hydro Fluid H	Hydr		68.00
- to mako	Aw68 Hydro Fluid H	-		40.00
- to acme dairy rd	Low Coolant Senso	or		1.00
- Shop Supplies	Shop Supplies			1.00
2 31 2311 23	Freight Charge			1.00
	Freight Charge			1.00
Hours 64.50 Labor :	3,870.0 Parts: 0	5,893.17	Total:	9,763.17
Workorder: 1500414 Meter: 417 Problem: Greese	In Date:	01/13/2015	Closed:	02/18/2015
- Greese	Parts List			Qty
- Acme Dairy Rd	5% Moly Req'd			50.00
- Ck for codes and repair	5% Moly Req'd			40.00
- Shop Supplies	Shop Supplies			1.00
Hours 3.00 Labor :	180.00 Parts:	418.10	Total:	598.10
Workorder: 1502217 Meter: 417 Problem: Greese	In Date:	03/03/2015	Closed:	03/13/2015
- Greese	Parts List			Qty
- To Lyons & Lantana	5% Moly Req'd			20.00
- Worked on removing steer cylinder	Shop Supplies			1.00
- Removed inspection covers and sent to shop - Shop Supplies				
Chief Cappino				458.30

Workorder: Problem:	1502701 steam clean	Meter:	417			In Date:	03/16/2015	Closed:	03/18/2015
- add oil					Parts Li	st			Qty
- wash machi	ne				15-40 C				12.00
- Shop Suppli	es				Aw68 H	ydro Fluid H	lvdr		43.00
					Bigg De	-	,		1.00
					Shop Su				1.00
	Hou :	ırs 5.00		Labor:	300.00	Parts:	149.21	Total:	449.21
Workorder: Problem:	1503006 pm service b	<b>Meter:</b> y Menzi US	417 A			In Date:	03/24/2015	Closed:	03/27/2015
- Pm by Menz	zi								
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1503332 Power Tilt	Meter:	889			In Date:	03/31/2015	Closed:	05/07/2015
- top off hyd o	il				Parts Li	st			Qty
- to arrowhead					Serpent	ine Belt			1.00
to pinion Rd 2	XS				5% Moly	/ Req'd			20.00
- replace belt					Washer	FI			2.00
- grease					Shop Su	upplies			1.00
- change pow		r fluid							
- Shop Suppli		0.00		l ab an	F40.00	Danta	4.44.05	Tatal	004.05
	H0U :	ırs 9.00		Labor:	540.00	Parts:	141.25	ı otal:	681.25
Workorder: Problem:	1504671 cab door bro	<b>Meter:</b> ken	1066			In Date:	05/07/2015	Closed:	07/21/2015
- temp fix doo	r. R&r door a	nd cut plexi	glass		Parts Li	st			Qty
- to roberts ar		to owasso r	d. to cong	ress and	Bigg De	greaser			1.00
6th. to lakewoo					60"x90"	Clear Acryl	ic		1.00
- replace wipe	er				Ptex Ult	ra Black 30	Z		7.00
- grease					Severe	Duty			1.00
- flip lines to n					5% Moly	/ Req'd			40.00
- install new g		م ما ادارات			Door As	-			1.00
- to lakewood		na kirk				Front Lowe	er		1.00
- Shop Suppli	es es				Windshi				1.00
					24v 886				3.00
					Shop Su				1.00
					Freight	_			1.00
					Freight (	•			1.00
	Hou :	ırs 26.50		Labor:	1,590.0 0	Parts:	13,167.66	Total:	14,757.66

Workorder: Problem:	1507547 PM		Meter:	1066			In Date:	07/29/2015	Closed:	09/03/2015
- pm						Parts L	ist			Qty
- service hyd	system					5% Mol	v Rea'd			20.00
- washer fluid	•	ease				Brake C		1.00		
- test run	J					M5 Filte		1.00		
- Shop Suppli	es					Bigg De	greaser			2.00
							Ford Axle I	Lube		16.00
						Severe	Duty			1.00
							serv truck			24.00
							ydro Fluid H	Hydr		152.00
							Fluid Tank	-		1.00
						Shop S	upplies			1.00
						Freight				1.00
		Hours	12.00		Labor:	720.00	_	3,207.44	Total:	3,927.44
Workorder: Problem:	1509008 Hyd. Lea	k	Meter:	1281			In Date:	09/08/2015	Closed:	09/15/2015
- replace hyd	hose in R	r leg				Parts L	ist			Qty
- to atlantic av	to atlantic ave and lake 2xs					Hose M	1.00			
- to mako						Aw68 H	ydro Fluid H	Hydr		40.00
- Shop Suppli	- Shop Supplies					Shop S	upplies			1.00
		Hours :	16.50		Labor:	990.00	Parts:	267.14	Total:	1,257.14
Workorder: Problem:	1509057 LF tire		Meter:	1066			In Date:	09/09/2015	Closed:	09/14/2015
- Lf Tire										
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1509299 Greese		Meter:	1281			In Date:	09/16/2015	Closed:	09/22/2015
- Greese						Parts L	ist			Qty
- Shop Suppli	es					5% Mol				20.00
5ap 5.app						Shop S	•			1.00
		Hours	0.00		Labor:	•		98.60	Total:	98.60
Workorder: Problem:	1510469 grease	•	Meter:	1281			In Date:	10/16/2015	Closed:	11/03/2015
- Greese	_					Parts L	ist			Qty
- Tire						5% Mol				20.00
- Shop Suppli	es							09 600/65r23		1.00
,,						Shop S				1.00
						-	posal Fee			1.00
		Hours	0.00		Labor:			3,813.10	Total·	3,813.10
		 :	5.55		_0001.	5.55	i dito.	3,010.10	i otal.	5,5 .50

Workorder: Problem:	1511286 Coolent sen	Meter: cer	1445			In Date:	11/03/2015	Closed:	11/12/2015
- check overh	eating. clean	radiator. ir	nstall coolar	nt level	Parts Li				Qty
switch					Peak Glo		3.00		
- to lyons and		XS			Low Coc		1.00		
- Shop Suppli	es				Shop Su	pplies		1.00	
	Hou :	urs 8.50		Labor:	510.00	Parts:	351.86	Total:	861.86
Workorder: Problem:	1511747 PM	Meter:	1525			In Date:	11/17/2015	Closed:	12/31/2015
- Pm					Parts Li	st			Qty
- Service final	l drives				M5 Filter	1.00			
R&r door sh	ed greese	15-40 O	12.00						
line			Aw68 Hy	10.00					
- Clean glass					5% Moly		2.00		
- Wash Ac filt					85-140	Gear Oil G		12.00	
- Repair gree					Wiper BI	ade		1.00	
- Repair retur				<b>D</b> I	Clr Rtv S		2.00		
<ul> <li>To Ives Dair ditch 3xs</li> </ul>	y Rd, To Lan	tana & Jog 2	2xs, and To	Plantation	Gas Sho	ck		1.00	
- Check engir	ne codes 231	& 142			Pressure	Switch	1.0		
- Greese	10 00000 201	ω 1 1 <u>2</u>			5% Moly	Req'd			20.00
- Shop Suppli	es				Shop Su	pplies			1.00
опор сарри					Freight C	Charge			1.00
					Freight C	Charge			1.00
	Ho:	urs 31.00		Labor:	1,860.0 0	Parts:	3,380.49	Total:	5,240.49
Workorder: Problem:	1600062 hyd switch	Meter:	1559			In Date:	01/04/2016	Closed:	01/08/2016
- replace hyd	return switch	. check fluid	d level		Parts Li	st			Qty
- repair greas	e lines under	cab and on	leg. replac	e blades	Mower B		3.00		
- to lantanna	and Jog. to h	nagan ranch	and lantar	ina	Blade Ro	oll Pin			3.00
- Shop Suppli	es				Blade Bo	olt			3.00
					Blade No	ut			3.00
					Blade W	asher			3.00
					Shop Su	pplies			1.00

Hours 8.00

Labor: 480.00 Parts: 405.79

Total: 885.79

Workorder: 160030 Problem: Blades	1 Meter	: 1525			In Date:	01/08/2016	Closed:	02/10/2016
- Replace blades				Parts Lis	t			Qty
- Replace boom hoses	s and joy stick	control butto	ns. Fill with	Mower Bl	ade			3.00
oil				Blade Bo	lt			3.00
- To Lantana				Blade Nu	t			3.00
- Repair coolent leak a	and presure tes	st .		Blade Wa		3.00		
- To Mako 2xs				Aw68 Hy		16.00		
- Replace boom exste	nsion cyl,			5% Moly		20.00		
- Shop Supplies				Napa Ant	ifreeze Ga	al		2.00
					at Cable T			1.00
				Hose Mad	de Mako 1	0194179		1.00
				Reman E	xt Cyl			1.00
				Shop Sup	-			1.00
				Freight Charge				1.00
	Hours 50.50		Labor:	3,030.0	•	8,799.00	Total:	11,829.00
_	:			0				02/29/2016
Problem: Transpo 2/4/201 - Tow From: Fleet He Fairbanks St., Lakeland	6 at 6:30a Shop To: Men			anks St, La	akeland Fl	(Menzi Muck	USA)-Sched	duled for
	Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 160294 Problem: pin and		: 1559			In Date:	03/21/2016	Closed:	03/30/2016
- Replace Pins and Bu	ıshinas							
	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 160320 Problem: hyd leal		: 1559			In Date:	03/28/2016	Closed:	02/20/2016
i iobieiii. Tiyu leal							Oloscu.	03/30/2016
- repair hyd leak. R&r		assembly a	and test run.	Parts Lis			Oloscu.	Qty
- repair hyd leak. R&r replace hyd filter	solenoid valve	·		Hyd Filter	•		Gloscu.	
- repair hyd leak. R&r replace hyd filter - check grease lines. r	solenoid valve	·		Hyd Filter		00ct	Gloscu.	Qty
- repair hyd leak. R&r replace hyd filter	solenoid valve	·		Hyd Filter Hw Pigma	•		oloseu.	<b>Qty</b> 1.00
- repair hyd leak. R&r replace hyd filter - check grease lines. r	solenoid valve	·		Hyd Filter Hw Pigma hyd strap	at 15x20 1	nt	oloseu.	<b>Qty</b> 1.00 1.00
- repair hyd leak. R&r replace hyd filter - check grease lines. r	solenoid valve	·		Hyd Filter Hw Pigma hyd strap	at 15x20 1 assortme dro Fluid H	nt	oloseu.	<b>Qty</b> 1.00 1.00 1.00
- repair hyd leak. R&r replace hyd filter - check grease lines. r	solenoid valve	·	test pump	Hyd Filter Hw Pigma hyd strap Aw68 Hyd	at 15x20 1 assortme dro Fluid F oplies	nt		<b>Qty</b> 1.00 1.00 1.00 8.00
- repair hyd leak. R&r replace hyd filter - check grease lines. r - Shop Supplies	repair 2 broken  Hours 13.50  .  Meter	fittings and	test pump	Hyd Filter Hw Pigma hyd strap Aw68 Hyd Shop Sup 810.00	at 15x20 1 assortme dro Fluid F oplies	nt Hydr		Qty 1.00 1.00 1.00 8.00 1.00
- repair hyd leak. R&r replace hyd filter - check grease lines. r - Shop Supplies  Workorder: 160339 Problem: Oil Leak	repair 2 broken  Hours 13.50 :  Meter	fittings and	test pump	Hyd Filter Hw Pigma hyd strap Aw68 Hyd Shop Sup 810.00	at 15x20 1 assortme dro Fluid F oplies Parts:	nt Hydr 1,008.83	Total:	Qty 1.00 1.00 1.00 8.00 1.00 1,818.83
- repair hyd leak. R&r replace hyd filter - check grease lines. r - Shop Supplies  Workorder: 160339 Problem: Oil Leak	repair 2 broken  Hours 13.50 :  Meter	fittings and	test pump	Hyd Filter Hw Pigma hyd strap Aw68 Hyd Shop Sup 810.00	at 15x20 1 assortme dro Fluid F oplies Parts: In Date:	nt Hydr 1,008.83 03/31/2016	Total:	Qty 1.00 1.00 1.00 8.00 1.00 1,818.83
- repair hyd leak. R&r replace hyd filter - check grease lines. r - Shop Supplies  Workorder: 160339 Problem: Oil Leak	repair 2 broken  Hours 13.50 :  Meter	fittings and	test pump	Hyd Filter Hw Pigma hyd strap Aw68 Hyd Shop Sup 810.00	at 15x20 1 assortme dro Fluid F oplies Parts: In Date:  tt cope Cylin	nt Hydr 1,008.83 03/31/2016	Total:	Qty 1.00 1.00 1.00 8.00 1.00 1,818.83

Workorder: Problem:	1603803 repair by <b>I</b>	<b>Meter:</b> Menzi	1559		ln	Date:	04/11/2016	Closed:	06/16/2016
- Repair by M	lenzi				Parts List				Qty
- To Cambrid	ge & Millita	ry			reducing pre	esure va	lve		1.00
- Remove stu	ck wheel fo	or replacemen	t		hyd hose		2.00		
- Adjust side	door	·			Wiper Blade	1.00			
- Test Run					wiper arm		1.00		
- Shop Suppli	ies				Aw68 Hydro	Fluid H	lydr		52.00
					5% Moly Re				80.00
					hose made	•			1.00
					Shop Suppl	ies			1.00
	ŀ	Hours 5.50		Labor:	330.00		1,818.52	Total:	2,148.52
- Tow From: <sup>-</sup> St, La	·	r: Menzi Muck Hours 0.00	: Usa-1850	Fairbanks Labor:	0.00	Parts:	0.00	Total:	0.00
St, La		Hours 0.00							
	H : 1604937		1559			Parts:	0.00	Total:	0.00
St, La Workorder:	H : 1604937	Hours 0.00							
St, La  Workorder: Problem:	1604937 Tire	Hours 0.00			ln		05/12/2016		05/17/2016
St, La  Workorder: Problem:	1604937 Tire	Meter:		Labor:	<b>In</b> 0.00	Date:	05/12/2016	Closed:	05/17/2016
St, La  Workorder: Problem: - Tire  Workorder:	1604937 Tire	Meter:	1559	Labor:	<b>In</b> 0.00	Date: Parts:	05/12/2016	Closed:	05/17/2016
Workorder: Problem: - Tire  Workorder: Problem:	1604937 Tire H:: 1605148 Tire	Meter:	1559	Labor:	0.00 In	Date: Parts: Date:	05/12/2016 0.00 05/17/2016	Closed:	05/17/2016 0.00 05/20/2016
St, La  Workorder: Problem: - Tire  Workorder: Problem: - Tire	1604937 Tire H:: 1605148 Tire	Meter:	1559	Labor:	0.00 In Parts List	Date: Parts: Date:	05/12/2016 0.00 05/17/2016	Closed:	05/17/2016 0.00 05/20/2016 <b>Qty</b>
St, La  Workorder: Problem: - Tire  Workorder: Problem: - Tire	1604937 Tire H:: 1605148 Tire	Meter:	1559	Labor:	0.00 In Parts List 198562 Tire	Date: Parts: Date:	05/12/2016 0.00 05/17/2016	Closed:	05/17/2016  0.00  05/20/2016  Qty 1.00

Workorder: Problem:	1605355 Greeser	Meter:	1803			In Date:	05/24/2016	Closed:	06/21/201	16
- Repair broke	n greese line	)			Parts Li	st				Qty
- Ck mowing d	•		iper assembly	y	mower s	pindle				1.00
- To Carver St	. 2 xs To Me	mory Garde	ns Ditch		Mower E	Blade				3.00
- Change out		•			Blade R			3.00		
- R&r Hyd mot	or assembly	for mower			Blade N	ut				3.00
- Crushed gree	ese lines at b	oom pivot. ı	epaired 5 line	es. Pulled	Blade B		3.00			
panels and hos fittings at knucl	ses to repair				Blade W		3.00			
- To 10th Ave.	and to Moso	quito Control			hyd rota		1.00			
- To Mako fror	n 10th ave				•	ydro Fluid F	iyar			6.00
- Shop Supplie	es				hose ma					1.00
					Shop Su					1.00
					Freight (	•				1.00
	Hoi :	urs 31.00		Labor:	1,860.0 0	Parts:	6,300.53	Total:	8,160.53	
Workorder: Problem:	1606137 Blades	Meter:	1840			In Date:	06/15/2016	Closed:	06/29/201	16
- replace blade	es				Parts Li	st				Qty
- to lake blvd					Mower E	Blade				3.00
- replace spind	dle assembly	. replace hy	draulic motor	r and	Blade R	oll Pin				3.00
install blades					Blade N	ut				3.00
- Shop Supplie	es				Blade B	olt				3.00
					Blade W	asher				3.00
					Shop Su	ıpplies				1.00
					Freight (	Charge				1.00
	Hou :	urs 24.50		Labor:	1,470.0 0	Parts:	461.86	Total:	1,931.86	
Workorder: Problem:	1606844 Greese	Meter:	1840			In Date:	07/07/2016	Closed:	07/13/20	16
- grease					Parts Li	st				Qty
- Shop Supplie	es				Ultra Su	preme 238	Moly Grease		2	0.00
					Shop Su	ıpplies				1.00
	Hor :	urs 0.00		Labor:	0.00	Parts:	143.00	Total:	143.00	
Workorder: Problem:	1607248 Blow out cod	Meter: olers	1840			In Date:	07/15/2016	Closed:	07/18/201	16
- blow out air f	ilter and coo	lers			Parts Li	st				Qty
<ul><li>to lyons and</li><li>Shop Supplie</li></ul>					Shop Su	ıpplies				1.00
		urs 3.00		Labor:	180.00	Parts:	2.00	Total:	182.00	

Workorder: 1607590 Meter: 1840 Problem: grease	In Date: 07/26/2016 Closed: 07/28/2016
- grease	Parts List Qt
- Shop Supplies	Ultra Supreme 238 Moly Grease 20.00
	Shop Supplies 1.0
Hours 0.00 Labor:	0.00 Parts: 143.00 Total: 143.00
Workorder: 1607771 Meter: 1840 Problem: pins	<b>In Date</b> : 07/29/2016 <b>Closed</b> : 08/31/2016
- Order Pins	Parts List Qt
- Repair broken greese lines	Thermostat 1.00
- To Acmie Dairy, Coliny Ditch, and to Plantation Ditch	Thermostat Gasket 1.00
- Greese	Gasket 3.0
- Pm	15-40 Oil 12.00
- Service Planitaries	M5 Filter Kit 1.00
- Service Ac	Brake Cleaner 6.00
- R&r wiper arm	85-140 Gear Oil Gear 10.00
- Drill out broken bolts for pins	Air Freshener 2.00
- Repair bad o-rings for hyd. leak	Ultra Supreme 238 Moly Grease 50.00
- Repair frozen pins	Aw68 Hydro Fluid Hydr 10.00
- Repair greese lines and clean out under cab	a/c compressor 1.00
- Presure wash	E8 A/c Oil Univ W Dye 1.00
- Test Run	R134a Freon 7.00
- Replace broken radiator hose	H Duty Anti-freeze 1.00
- Replace Joy Stick	Peak Global Antifrz 3.00
- Shop Supplies	joystick 1.00
	Bucket Pin 3.00
	Shop Supplies 1.00
	Freight Charge 1.00
	Freight Charge 1.00
Hours 49.00 Labor:	2,940.0 Parts: 11,041.83 Total: 13,981.83
Workorder: 1609353 Meter: 2042 Problem: Alarm	In Date: 09/08/2016 Closed: 10/13/2016
- hyd filter replace	Parts List Qt
- to Plantation ditch	Pressure Switch 1.00
- hyd switch install. solder wires. R&r covers. install couplers	
- clean radiator and fill with coolant	holes made 1.00
- install coupler on mower deck	Shop Supplies 1.00
- Shop Supplies	Freight Charge 1.00
·	1,020.0 Parts: 2,305.99 Total: 3,325.99

Workorder: 161070 Problem: radio	6 Meter:	2042			In Date:	10/18/2016	Closed:	11/18/2016
- Greese				Parts Lis	st			Qty
- Install speakers				15-40 O	il			12.00
- Replace cooling hose	es to radiator/ en	gine. Add cool	ent,	M5 Filter	Kit			1.00
test, and cleen				Cable Ti	е			1.00
- Pm				hose ma	1.00			
- Replace lines to stee	ring cyl. Replace	ed pump fittings	and	Big G De	2.00			
sencer ck for leaks	arooo linaa and	upplyand fittin	ao Ck	Rotell El	2.00			
- Replaced all broken automatic greeser	greese lines and	unpiugea iittin	gs. Ck	Cable Ti	1.00			
- Add hyd. oil				Hose Me	ender 2in			4.00
- To Mako 2xs				Hose Ma	ide			1.00
- Shop Supplies				Silicone	Hose 2in			24.00
				Ultra Sup	oreme 238	Moly Grease		20.00
				4" speak	ers			1.00
				Wiper BI	ade			1.00
				sensor				2.00
				Hose Ma	de 101941	79		1.00
				Fitting 10	0194179			1.00
				hose ma	de			1.00
				Aw68 Hy	dro Fluid H	Hydr		28.00
				Shop Su	pplies			1.00
				Freight C	Charge			1.00
	Hours 91.50 :		Labor:	5,490.0 0	Parts:	5,790.23	Total:	11,280.23
Workorder: 161190 Problem: repair jo		2150			In Date:	11/17/2016	Closed:	11/18/2016
- Repair Joy Stick				Parts Lis	st			Qty
- To Wiggins ditch - Shop Supplies				Shop Su	pplies			1.00
- 1 - 11	Hours 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00
Workorder: 161209 Problem: hyd leal		2163			In Date:	11/28/2016	Closed:	12/08/2016
- R&r power tilt hoses,	and top off oil			Parts Lis	st			Qty
- To Haverhill & Melali	•			hose ma				1.00
- To Mako					dro Fluid H	lydr		50.00
- Shop Supplies				Shop Supplies			1.00	
1 11	Hours 4.00		Labor:	240.00		245.53	Total:	485.53

Workorder: 1 Problem: A	612762 AC	Meter:	2163		ı	n Date:	12/13/2016	Closed:	12/19/2016
- Repair Ac wiri	ng				Parts List	t			Qty
- To Floral Park	_				White Mp	Grs Cart			4.00
- Refill Mower C	Greeser				Shop Sup				1.00
- Shop Supplies	6					•			
		ours 6.00		Labor:	360.00	Parts:	23.30	Total:	383.30
Workorder: 1 Problem: A	613010 AC	Meter:	2165		I	n Date:	12/21/2016	Closed:	01/12/2017
- Replace Ac co	ompressor	& dryer. Red	harge		Parts List	t			Qty
- Repair Ac wirr	ing				Ultra Supi	reme 238	Moly Grease		20.00
- Greese					Drier				1.00
- Shop Supplies	6				A/c Comp	7h15 Em	24v Menzi		1.00
					Cable Tie				1.00
					Freon He	Shop			3.00
					Shop Sup	plies			1.00
	Ho	ours 6.50		Labor:	390.00	Parts:	717.35	Total:	1,107.35
Workorder: 1	701100	Meter:	2267		ı	n Date:	02/02/2017	Closed:	02/14/2017
Problem: (	Greese								
- Greese					Parts List				Qty
- Replace hydro	olic switch	and filter, R8	r covers		Ultra Supi	20.00			
- To Lake Ave.	Delray, To	2nd Ave 2xs	3		hose mad	1.00			
- Add Coolent					Hyd Filter				1.00
- Shop Supplies	6				Pressure				1.00
					Shop Sup	-			1.00
					Freight Ch	narge			1.00
	H( :	ours 12.00		Labor:	720.00	Parts:	1,232.51	Total:	1,952.51
Workorder: 1 Problem: J	701657 loy Stick	Meter:	2281		I	n Date:	02/15/2017	Closed:	03/16/2017
Problem: J	loy Stick				Parts List		02/15/2017	Closed:	
<b>Problem:</b> J	loy Stick stick, repa	ir door latch	cable	lintmoore,		t	02/15/2017	Closed:	03/16/2017 <b>Qty</b> 1.00
Problem: J - Retighten joy : - To Old Germa	loy Stick stick, repa antown Rd	ir door latch	cable	lintmoore,	Parts List	<b>t</b> ener	02/15/2017	Closed:	Qty
Problem: J - Retighten joy : - To Old Germa	loy Stick stick, repa antown Rd	ir door latch	cable	lintmoore,	Parts List	<b>t</b> ener	02/15/2017	Closed:	<b>Qty</b> 1.00
Problem: J - Retighten joy : - To Old Germa to Lyons & Clint	loy Stick stick, repa antown Rd	ir door latch	cable	lintmoore,	Parts List Air Freshe door cable door lock	<b>t</b> ener e	02/15/2017 Moly Grease	Closed:	<b>Qty</b> 1.00 1.00
Problem: J - Retighten joy : - To Old Germa to Lyons & Clint - Greese	loy Stick stick, repa antown Rd moore	ir door latch o , to Hagen Ra	cable anch Rd & C		Parts List Air Freshe door cable door lock	t ener e reme 238	Moly Grease	Closed:	<b>Qty</b> 1.00 1.00 1.00
Problem: J - Retighten joy : - To Old Germa to Lyons & Clint - Greese - Hyd. Cap	loy Stick stick, repa antown Rd moore se block, r	ir door latch o , to Hagen Ra	cable anch Rd & C		Parts List Air Freshe door cable door lock Ultra Supi	t ener e reme 238 eather cap	Moly Grease	Closed:	<b>Qty</b> 1.00 1.00 1.00 20.00
Problem: J - Retighten joy: - To Old Germa to Lyons & Clint - Greese - Hyd. Cap - Manualy grees	loy Stick stick, repa antown Rd moore se block, r	ir door latch o , to Hagen Ra	cable anch Rd & C		Parts List Air Freshe door cable door lock Ultra Supi hyd oil bre	t ener e reme 238 eather cap Grs Cart	Moly Grease	Closed:	Qty 1.00 1.00 1.00 20.00 1.00
Problem: J - Retighten joy: - To Old Germa to Lyons & Clint - Greese - Hyd. Cap - Manualy grees	loy Stick stick, repa antown Rd moore se block, r	ir door latch o , to Hagen Ra	cable anch Rd & C		Parts List Air Freshe door cable door lock Ultra Supi hyd oil bre White Mp	t ener e reme 238 eather cap Grs Cart plies	Moly Grease	Closed:	Qty 1.00 1.00 1.00 20.00 1.00
Problem: J - Retighten joy: - To Old Germa to Lyons & Clint - Greese - Hyd. Cap - Manualy grees	loy Stick stick, repa antown Rd moore se block, r	ir door latch o , to Hagen Ra	cable anch Rd & C		Parts List Air Freshe door cable door lock Ultra Supi hyd oil bre White Mp Shop Sup	t ener e reme 238 eather cap Grs Cart plies narge	Moly Grease	Closed:	Qty 1.00 1.00 20.00 1.00 10.00

Workorder: Problem:	1702330 Tire repair	Meter:	2267			In Date:	03/08/2017	Closed:	03/14/2017
- Flat repair	Цол	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	: :	115 0.00		Labor.	0.00	rails.	0.00	TOlai.	0.00
Workorder: Problem:	1702858 PM	Meter:	2368			In Date:	03/21/2017	Closed:	05/05/2017
- Pm					Parts L	ist			Qty
	nister greese p		repaired all	broken	15-40	Oil			12.00
greese lines.					M5 Filte	er Kit			1.00
•	oolt clamps on	coolent sy	stem ck for	leaks	Wiper E	Blade			1.00
- To Mako					Couple	r			2.00
•	ess for hyd. hi	gh presure	switch		Clr Rtv	Silcn Sealar	nt		2.00
- Shop Suppli	es				zerk fitt	ing			20.00
					elemen	t			4.00
					t bolt cla	amps			8.00
					Ultra Su	ıpreme 238	Moly Grease		10.00
					hose m				1.00
					Shop S				1.00
					Freight	-			1.00
	Ηου :	ırs 49.00		Labor:	2,940.0 0	Parts:	4,852.32	Total:	7,792.32
Workorder: Problem:	1703926 hose	Meter:	2400			In Date:	04/19/2017	Closed:	04/25/2017
	er tilt hoses a	nd top off fl	uid. repair l	ower boom	Parts L	ist			Qty
grease lines	Pr. L				hose m	ade			1.00
- to plantation						lydro Fluid H	•		20.00
- to mako .5 v						•	Moly Grease		22.00
- Shop Suppli					Shop S				1.00
	Ηου :	ırs 8.00		Labor:	480.00	Parts:	369.65	Total:	849.65
Workorder: Problem:	1704706 recalls	Meter:	2464			In Date:	05/11/2017	Closed:	06/01/2017
- Work on Me	nzi recalls/ Re	eplace powe	er tilt		Parts L	ist			Qty
- To Plantatio	n Ditch 2xs	-			30 175	Nat Cable T	ie		2.00
- Top off hyd.	oil				power t	ilt assy			1.00
- Test run					Glos Bl	k			1.00
- Quik discon	nects				Ultra Su	preme 238	Moly Grease		20.00
- Shop Suppli	es				Shop S	upplies			1.00
					Freight	Charge			1.00
	Hou	ırs 12.50		Labor:	750.00	Parts:	12,883.89	Total:	13,633.89

Workorder: Problem:	1705451 Greese	N	leter:	2400			In Date:	06/01/2017	Closed:	06/06/2017
- Greese - Shop Suppli	ies					<b>Parts Li</b> Ultra Su		Moly Grease		<b>Qty</b> 20.00
						Shop Su	1.00			
		Hours 0	.00		Labor:			143.00	Total:	143.00
Workorder: Problem:	1705618 AC	N	leter:	2469			In Date:	06/06/2017	Closed:	06/20/2017
- Ac blows warm. repair open at compressor coil						Parts Li	<b>Qty</b> 1.00			
<ul><li>to palloming</li><li>Shop Supplies</li></ul>						Shop Su	ipplies			1.00
- опор оцры		Hours 3	.00		Labor:	180.00	Parts:	2.00	Total:	182.00
Workorder: Problem:	1706303 grease	. IV	leter:	2560			In Date:	06/27/2017	Closed:	07/25/2017
- replace hyd	_	ıpling an	d beari	ng assembly o	on	Parts Li	st			Qty
mower deck						service a	1.00			
- check engin						sprocke	t			1.00
- to palomino	aitcn					roller ch	ain			1.00
<ul><li>keys</li><li>R&amp;r blades</li></ul>						mower s	•			1.00
- tighten hose	s refill cod	olant and	l clean	coolers		50 inch				1.00
- to wiggin rd		Jianit and	Clean	COOLETS		cap scre				6.00
- Shop Suppli							Rotary Moto	or		1.00
Oriop Guppi	.00					Plug	L			8.00
						losk was	sner			6.00
						Key	obal Antifrz			3.00 2.00
							egreaser 1 (	Cal		1.00
								Moly Grease		20.00
						Shop Su	•	ivioly Grease		1.00
						Freight (	• •			1.00
						Freight (	•			1.00
						Freight (	_			1.00
						Freight (	_			2.00
		Hours 2	9.50		Labor:	1,770.0 0	Parts:	12,543.44	Total:	14,313.44
Workorder: Problem:	1707305 overheat		leter:	2570			In Date:	07/25/2017	Closed:	08/07/2017
- R&r thermostats and flush cooling system					Parts List C					
- repair grease lines and fittings						m5 therr	1.00			
- Shop Suppli	ies					thermos	tat gasket			1.00
						Ptex Ult	ra Black 30z	Z		1.00
						disf rote	lla			6.00
						Shop Su	ıpplies			1.00
		Hours 1	3.50		Labor:	810.00	Parts:	691.88	Total:	1,501.88

:

Workorder: Problem:	1708069 hyd leak		2570			In Date:	08/16/2017	Closed:	08/23/2017	
- Replace Fou	ır Hyd Ho	ese From Boo	om		Parts Li	st			Qty	
- Grease						/dro Fluid H	Hydr		80.08	
- Service Call At Melaluca And Haverhill 2x						nat 15x20 1	00ct		1.00	
- To Mako Plus Wait Time						Nat Cable T	ie		1.00	
- Add Hyd Oil						int pen			1.00	
- Test System Operation Inspec For Leaks						Ultra Supreme 238 Moly Grease				
- Shop Supplies						hose made mako				
					Shop Su	pplies			1.00	
		Hours 15.00 :		Labor:	900.00	Parts:	2,207.87	Total:	3,107.87	
Workorder:	1708553		2661			In Date:	08/30/2017	Closed:	09/21/2017	
Problem:	attatcnm	ent								
- reconnect ho					Parts Li				Qty	
- to hibiscus ir					Shop Su	pplies			1.00	
- repair grease		•								
- to laurence r		ux								
- Shop Supplie	es									
		Hours 12.50 :		Labor:	750.00	Parts:	2.00	Total:	752.00	
Workorder: Problem:	1709378 hyd. leak	Meter: at fittings for				In Date:	09/27/2017	Closed:	10/31/2017	
- repair oil leal	k at coup	lers. repair gr	ease lines. ı	replace hyd	Parts Li	st			Qty	
hoses in legs					Wiper Bl	ade			1.00	
- to floral park	-				M5 Filter	· Kit			1.00	
- replace joy s	tick butto	ns			15-40 C	il			12.00	
- add hyd oil					hose ma	de mako			1.00	
- pm	P				Joystick	Buttons - (	red)		25.00	
- repair many	-	_	easer		Ultra Su	preme 238		10.00		
- replace oil in final drives						obal Antifrz		1.00		
- repair bolts and holes for rear cover								2.00		
- wash rear leg and grease block						egreaser 1		1.00		
- Shop Supplie	es				Aw68 Hy	/dro Fluid H	Hydr		72.00	
					Shop Su	pplies			1.00	
					Freight (	Charge			1.00 1.00	
							Freight Charge			
					Freight (	Charge			1.00	
		Hours 57.00 :		Labor:	3,420.0 0	Parts:	3,485.40	Total:	6,905.40	
Workorder: Problem:	1709977 tires	Meter	2661			In Date:	10/12/2017	Closed:	10/13/2017	
- tires mount o	dismount									
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00	

· <del></del>									
Workorder: 17	I1189 eese	Meter:	2661		lı	n Date:	11/14/2017	Closed:	11/22/2017
- grease					Parts List				Qty
- Shop Supplies		Ultra Supr	eme 238	Moly Grease		20.00			
				Washer Fl		•		2.00	
					Air Freshe	ner			2.00
					Shop Supplies				1.00
	Ho	urs 0.00		Labor:			153.38	Total:	153.38
Workorder: 177 Problem: Bro	11535 oken gree	Meter: ese fitting	2740		I	n Date:	11/22/2017	Closed:	12/19/2017
- Repair greese li	nes				Parts List				Qty
- To Sandsberry [		Seminole Co	olony 2xs		Ultra Supr	eme 238	Moly Grease		2.00
- Repair hood loc			,		hose made		•		1.00
- To Mako		,			Aw68 Hyd	ro Fluid H	Hydr		10.00
- R&r bad boom h	oses				Shop Sup			1.00	
- Shop Supplies									
	Ho :	urs 13.00		Labor:	780.00	Parts:	552.25	Total:	1,332.25
Workorder: 17	12750 pair Gree	Meter: ese lines	2740		I	n Date:	12/28/2017	Closed:	12/28/2017
- Repair greese li	nes				Parts List				Qty
- Shop Supplies					Shop Sup	1.00			
	Ho :	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: 180 Problem: Gre	00159 eese	Meter:	2740		I	n Date:	01/04/2018	Closed:	01/16/2018
- Greese Unit					Parts List				Qty
- Shop Supplies					Ultra Supr	20.00			
спор сарриос					Shop Sup			1.00	
	Ho	urs 0.50		Labor:			143.00	Total:	173.00
Workorder: 180 Problem: Re	00490 pair lines	Meter:	2808		I	n Date:	01/16/2018	Closed:	02/16/2018
- Replace Hyd. ho	se to Lh	steering Cyl	. Repair bro	ken	Parts List				Qty
greese lines	hose from	1.00							
- To Westgate dit	Aw68 Hyd	57.00							
- Replace wiper a	wiper arm	1.00							
- Tighten several	Wiper Blad	2.00							
- Wash out engine	Aw68 Hyd	10.00							
- Shop Supplies					Shop Sup				1.00
					Freight Ch				1.00
	Ho :	urs 17.50		Labor:	1,050.0 0	•	1,064.32	Total:	2,114.32

**Workorder:** 1804107 **Meter:** 2808 **In Date:** 04/19/2018 **Closed:** 04/19/2018

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

: