Workorder: Problem:	736942 PRE-DELIVE	Meter: RY INSPE	0 CTION			In Date:	04/09/2007	Closed:	04/09/20	007
- Pre-delivery	Inspection									
	Hour:	s 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	741323 002 WASH TI	Meter: CKETS IS	0 SUED OUT	07/11/07		In Date:	07/11/2007	Closed:	07/11/20	007
- 002 Wash T	ickets Issued C	Out 07/11/	07							
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	747655 P.M SERVICE	Meter:	388			In Date:	11/21/2007	Closed:	11/27/20	007
- Pm Service					Parts Li	st				Qty
	Balance All 4 T			on In	Shop Su	upplies				1.00
- Shop Suppli	le When Drivin	g Over 50	mpn.				ord/motorcraf	t Only		1.00
		0.0.75		Lobor	5w20 Er 225.00	ngine Oil	20 50	Totalı	245 50	5.00
	Hours	s 3.75		Labor	225.00	Parts:	20.59	Total:	245.59	
Problem:	003 WASH TI	CKETS IS	SUED OUT	06/02/08						
	ickets Issued C			06/02/08 Labor:	0.00	Parts:	0.00	Total:	0.00	
- 003 Wash T Workorder:	ickets Issued C	00/02/			0.00	Parts: In Date:	0.00 07/07/2008	Total: Closed:	0.00	008
- 003 Wash T Workorder:	ickets Issued C Hour : 840946	0ut 06/02/ s 0.00	08		0.00 Parts Li	In Date:				
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su	In Date:	07/07/2008	Closed:		<b>Qty</b> 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4 Stemhigh Spe</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su Fl-2017t	In Date: st upplies o Oil Filter F	07/07/2008	Closed:		<b>Qty</b> 1.00 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su Fl-2017f 3296 Fu	In Date: st upplies o Oil Filter Fr el Filter Frr	07/07/2008	Closed:		<b>Qty</b> 1.00 1.00 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4 Stemhigh Spe</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su FI-2017k 3296 Fu 5w20 Er	In Date: st upplies o Oil Filter F rel Filter Frr ngine Oil	07/07/2008 Ford/motorcraft n G3850	Closed:		<b>Qty</b> 1.00 1.00 1.00 5.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4 Stemhigh Spe</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su Fl-2017t 3296 Fu 5w20 Er Wd40 S	In Date: st o Oil Filter F el Filter Frr ngine Oil pray Lube S	07/07/2008 Ford/motorcraf n G3850 Stock# 405540	Closed:		<b>Qty</b> 1.00 1.00 5.00 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4 Stemhigh Spe</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl I ed Balance All es	Out 06/02/ s 0.00 Meter:	08 1240 Split, Cracked	Labor:	Parts Li Shop Su Fl-2017t 3296 Fu 5w20 Er Wd40 S	In Date: st upplies o Oil Filter F el Filter Frr ngine Oil pray Lube S 6 Wiper Bla	07/07/2008 Ford/motorcraft n G3850	Closed: it Only 0002 it)		<b>Qty</b> 1.00 1.00 5.00 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> <li>Stemhigh Spe</li> <li>- Shop Suppli</li> <li>Workorder:</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl I ed Balance All es	Out 06/02/ s 0.00 Meter: Defective S 4 Tires.nit s 4.75 Meter:	08 1240 Split, Cracked	Labor:	<b>Parts Li</b> Shop Su FI-2017k 3296 Fu 5w20 Er Wd40 S Ww-204	In Date: st upplies o Oil Filter F el Filter Frr ngine Oil pray Lube S 6 Wiper Bla	07/07/2008 Ford/motorcraf n G3850 Stock# 405540 ide (motorcraf	Closed: it Only 0002 it)	07/10/20	<b>Qty</b> 1.00 1.00 5.00 1.00 2.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4 Stemhigh Spe</li> <li>- Shop Suppli</li> <li>Workorder:</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All es Hour : 935091	Out 06/02/ s 0.00 Meter: Defective S 4 Tires.nit s 4.75 Meter:	08 1240 Split, Cracked ro Fill Tires.	Labor:	<b>Parts Li</b> Shop Su FI-2017k 3296 Fu 5w20 Er Wd40 S Ww-204	In Date: st upplies o Oil Filter Fr el Filter Frr ngine Oil pray Lube S 6 Wiper Bla Parts: In Date:	07/07/2008 Ford/motorcraft n G3850 Stock# 405540 de (motorcraft 66.70	Closed: it Only 0002 it) Total:	07/10/20	<b>Qty</b> 1.00 1.00 5.00 1.00 2.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> <li>Stemhigh Spe</li> <li>- Shop Suppli</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl E ed Balance All es Hour : 935091	Out 06/02/ s 0.00 Meter: Defective S 4 Tires.nit s 4.75 Meter:	08 1240 Split, Cracked tro Fill Tires.	Labor:	<b>Parts Li</b> Shop Su FI-2017k 3296 Fu 5w20 Er Wd40 S Ww-204 285.00	In Date: st upplies o Oil Filter Fr ngine Oil pray Lube S 6 Wiper Bla Parts: In Date: st	07/07/2008 Ford/motorcraft n G3850 Stock# 405540 de (motorcraft 66.70	Closed: it Only 0002 it) Total:	07/10/20	Qty 1.00 1.00 5.00 1.00 2.00 009 Qty
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> <li>Stemhigh Spe</li> <li>- Shop Suppli</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl I ed Balance All es Hour : 935091 P.M SERVICE e,missaligned F	Out 06/02/ s 0.00 Meter: Defective S 4 Tires.nit s 4.75 Meter:	08 1240 Split, Cracked tro Fill Tires.	Labor:	Parts Li Shop Su FI-2017k 3296 Fu 5w20 Er Wd40 S Ww-204 285.00 Parts Li Shop Su	In Date: st upplies o Oil Filter Fr el Filter Frr ngine Oil pray Lube S 6 Wiper Bla Parts: In Date: st upplies	07/07/2008 Ford/motorcraft n G3850 Stock# 405540 de (motorcraft 66.70	Closed: it Only 0002 it) Total: Closed:	07/10/20	<b>Qty</b> 1.00 1.00 5.00 1.00 2.00 009 <b>Qty</b> 1.00
<ul> <li>- 003 Wash T</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Dismount 4</li> <li>Stemhigh Spe</li> <li>- Shop Suppli</li> <li>Workorder: Problem:</li> <li>- Pm Service</li> <li>- Repair Loos</li> </ul>	ickets Issued C Hour : 840946 PM SERVICE Tires To Repl I ed Balance All es Hour : 935091 P.M SERVICE e,missaligned F	Out 06/02/ s 0.00 Meter: Defective S 4 Tires.nit s 4.75 Meter:	08 1240 Split, Cracked tro Fill Tires.	Labor:	Parts Li Shop Su FI-2017k 3296 Fu 5w20 Er Wd40 S Ww-204 285.00 Parts Li Shop Su FI-2017k	In Date: st upplies o Oil Filter Fr el Filter Frr ngine Oil pray Lube S 6 Wiper Bla Parts: In Date: st upplies	07/07/2008 Ford/motorcraft n G3850 Stock# 405540 de (motorcraft 66.70 03/12/2009	Closed: it Only 0002 it) Total: Closed:	07/10/20	<b>Qty</b> 1.00 1.00 5.00 1.00 2.00

Workorder: Problem:	935190 001 DET	<b>Met</b> TAIL VEHIC		0 03/12/09			In Date:	03/12/2009	Closed:	03/16/20	009
- 001 Detail V	ehicle	03/12/09	9								
		Hours 0.00 :	)		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	943537 P.M. Se	Mete rvice.	er:	3620			In Date:	09/22/2009	Closed:	09/29/20	)09
- P.m. Service	).					Parts L	.ist				Qty
- Rotate and b	alance a	Il four tires.				Shop S	upplies				1.00
- Shop Suppli	es					FI-2017	b Oil Filter F	ord/motorcrat	ft Only		1.00
						3296 Fu	uel Filter Fri	m G3850			1.00
						Ca1017	70 Air Filter L	_bf Af3601 Wi	x 49187		1.00
						5w20 E	ngine Oil				5.00
						Ww-204	46 Wiper Bla	ade (motorcrai	ft)		2.00
		Hours 3.75	)		Labor:	225.00	Parts:	63.65	Total:	288.65	
Workorder: Problem:	1003500 P.M serv		er:	4373			In Date:	04/05/2010	Closed:	04/14/20	)10
- P.m service.						Parts L	ist				Qty
- Shop Suppli	es					Shop S	upplies				1.00
						FI-2017	'b Oil Filter F	ord/motorcrat	ft Only		1.00
						5w20 E	ngine Oil				5.00
						Ww-120	02 Wiper Bla	ade (motorcrai	ft)		1.00
							46 Wiper Bla	ade (motorcrat	ft)		2.00
		Hours 2.75	•		Labor:	165.00	Parts:	67.66	Total:	232.66	
Workorder: Problem:	1011375 Pm serv		er:	5169			In Date:	10/14/2010	Closed:	10/25/20	)10
- Perform pm	service.					Parts L	ist				Qty
- Rotate and b	alance a	II four tires.				Shop S	upplies				1.00
- Shop Suppli	es					FI-2017	'b Oil Filter F	ord/motorcrat	ft Only		1.00
						3296 Fi	uel Filter Fri	m G3850			1.00
						5w20 E	ngine Oil				5.00
		Hours 3.75			Labor:	225.00	Parts:	23.25	Total:	248.25	
Workorder: Problem:	1013160 1 - Wasi	) Meten n ticket(s) is:		5169 I			In Date:	11/30/2010	Closed:	11/30/20	)10
- 1 - Wash tick	ket(s) iss	ued									
		Hours 0.00 :	)		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1106165 Pm service	Meter:	7478		l	n Date:	06/10/2011	Closed:	06/22/20	011
- P.m. Service	Э.				Parts List					Qty
- Rotate and I	balance all tires	3.			Shop Sup	plies				1.00
- Shop Suppli	es						ord/motorcraf	t Only		1.00
					5w20 Eng					5.00
					-		ade (motorcraf	t)		1.00
							ade (motorcraf			2.00
	Hour	s 3.75		Labor:	225.00	•	78.52	,	303.52	
Workorder: Problem:	1110664 Check engine	Meter: light on.	7792		l	n Date:	10/05/2011	Closed:	10/24/20	011
	agnose for che				Parts List					Qty
	replace failed			valve and	Shop Sup	plies				1.00
• •	ew.clear codes	s and road	test.		Fuel Cap					1.00
- Shop Suppli	es				Canister V	ent Sole	niod			1.00
	Hour	s 3.25		Labor:	195.00	Parts:	99.35	Total:	294.35	
Workorder: Problem:	1112244 Left front blow	Meter:	8004		l	n Date:	11/16/2011	Closed:	11/17/20	D11
- Replace and	balance two ti	ires.			Parts List					Qty
- Shop Suppli	es				Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
					18340741	8 P235/7	0r16 Wrangler	Sr-a 104s		2.00
	Hour :	s 1.00		Labor:	60.00	Parts:	286.36	Total:	346.36	
Workorder: Problem:	1113475 P.M. service.	Meter:	8207		l	n Date:	12/27/2011	Closed:	01/09/20	012
- P.m. Service	9.				Parts List					Qty
	balance all tires	S.			Shop Sup					1.00
- Shop Suppli							- ord/motorcraf	t Only		1.00
					3296 Fuel			,		1.00
							Stock# 405540	002		1.00
					5w20 Eng	-				5.00
	Hour	s 3.75		Labor:	225.00		32.90	Total:	257.90	
Workorder: Problem:	1207139 P.M. service.	Meter:	13349		l	n Date:	07/31/2012	Closed:	08/09/20	012
- Perform pm	service.				Parts List					Qty
-	balance all four	tires.			Shop Sup					1.00
- Shop Suppli							- ord/motorcraf	t Only		1.00
1	-						Lbf Af3601 Wiz	•		1.00
					5w20 Eng					5.00
	Hour	s 3.75		Labor.	225.00		25.29	Total	250.29	2.00
				Laboi.		7 0110.	-00	i otal.	200.20	

Workorder:1300729Meter:16645Problem:Pm service and right rear tire flat.		In	Date:	01/22/2013	Closed:	01/31/20	13
- P.m. Service.		Parts List					Qty
- Test battery and charging system.recharge an	d retest	Sensa-trac	Trk Sho	ck			2.00
battery, fail load test.replace defective battery.		5w20 Engir	ne Oil				5.00
- Replace leaking rear shocks.		Filter					1.00
- Repair right rear tire, rotate and balance all fou	ır.	G3850 Fue	I Filter L	of			1.00
- Shop Supplies		Ww-2046 V	Viper Bla	ide M			2.00
		Wd40 Spra	y Lube S	Stock			1.00
		Brake Clea	ner				1.00
		Bxt96r 59					1.00
		Shop Supp					1.00
Hours 6.75 :	Labor:	405.00	Parts:	317.23	Total:	722.23	
Workorder:1307045Meter:19513Problem:Pm service.Check engine light or	۱.	In	Date:	07/15/2013	Closed:	07/25/20	13
- P.m. Service.		Parts List					Qty
- Diagnose check engine light,p0442.perform ev	vap system	5w20 Engir	ne Oil				5.00
test.replace failed fuel cap.clear code.		Filter					1.00
- Repair right rear tire, rotate and balance all fou	r.	Cap Asy					1.00
- Shop Supplies		Shop Supp	lies				1.00
Hours 6.25 :	Labor:	375.00	Parts:	51.40	Total:	426.40	
Workorder: 1401758 Meter: 23944 Problem: P.M. service.		In	Date:	02/24/2014	Closed:	02/28/20	14
- Perform pm service.		Parts List					Qty
- Rotate and balance all four tires.		5w20 Engir	ne Oil				5.00
- Shop Supplies		Filter					1.00
		Napagold F	Fuel Filte	r			1.00
		Wiper Blad	е				2.00
		Ww-1202 V	Viper Bla	ide M			1.00
		Wd40 16oz					1.00
		Wu+0 1002	_				
		Wiper Blad					2.00
		Wiper Blad Shop Supp	е				2.00 1.00
Hours 3.75 :	Labor:	Wiper Blad	e lies	89.20	Total:	314.20	
:	Labor:	Wiper Blad Shop Supp 225.00	e lies	89.20 06/25/2014	Total: Closed:	314.20 07/08/20	1.00
: Workorder: 1406213 Meter: 25578	Labor:	Wiper Blad Shop Supp 225.00	e lies Parts:				1.00
: Workorder: 1406213 Meter: 25578 Problem: Pm service.	Labor:	Wiper Blad Shop Supp 225.00 In Parts List	e lies Parts: <b>Date:</b>				1.00
: Workorder: 1406213 Meter: 25578 Problem: Pm service. - Perform pm service. - Rotate and balance all four tires.	Labor:	Wiper Blad Shop Supp 225.00 In	e lies Parts: <b>Date:</b>				1.00 14 Qty
: Workorder: 1406213 Meter: 25578 Problem: Pm service. - Perform pm service.	Labor:	Wiper Blad Shop Supp 225.00 In Parts List 5w20 Engin	e lies Parts: <b>Date:</b> ne Oil				1.00 14 <b>Qty</b> 5.00

Workorder: Problem:	1408520 Check engine	Meter: e light on.Sa	26422 afety recall 1	4S05 and		n Date:	08/26/2014	Closed:	09/08/2014
P0442.perform	Computer diagnose for check engine light on.code 0442.perform evap.test.replace defective vent valve olenoid.clear code and retest evap system.								<b>G</b> 1.
- Transport vehicle to and from dealer for safety recalls 14s05 and 14s19.reprogram power steering control module and inspect Mecp.					Shop Sup	plies			1.
- Shop Suppli		ırs 5.00		Labor:	300.00	Parts:	131.41	Total:	431.41
Workorder: Problem:	: 1505410 Pm service.S	Meter: Safety recall	30107 #14S19		I	n Date:	05/29/2015	Closed:	06/11/2015
- Pm service.					Parts List	:			C
- Rotate and I	balance all fou	ır tires.			5w20 Eng	ine Oil			5.
	ehicle to and fr	rom dealer f	for safety rec	all	Napagold	Air Filter			1.
#14s19	-				Wiper Bla	de			2.
- Shop Suppli	ies				Ww-1202	Wiper Bla	ade M		1.
					Filter				1.
					Mac Wite	Lithium G	res		1.
					Washer Fluid Concentr				1.
					Shop Sup	plies		1.	
	Hou	ırs 5.75		Labor:	345.00	Parts:	89.90	Total:	434.90
	1512257 Pm service.	Meter:	33092		I	n Date:	12/03/2015	Closed:	12/21/2015
	Pm service.	Meter:	33092		I Parts List		12/03/2015	Closed:	12/21/2015 C
Problem: - Pm service.	Pm service.					1	12/03/2015	Closed:	
Problem: - Pm service. - Replace def	Pm service.	ar strobe la	mp bulb.	h glass.	Parts List	rt Glass	12/03/2015	Closed:	C
Problem: - Pm service. - Replace def - Replace bot - Load test ba	Pm service. fective right reat th defective lift attery and chec	ar strobe lar support for	mp bulb. tailgate hato	•	Parts List Lift Suppo	rt Glass	12/03/2015	Closed:	<b>C</b> 2.
Problem: - Pm service. - Replace def - Replace bot - Load test bat defective batte	Pm service. fective right rea th defective lift attery and chea ery.	ar strobe lar support for ck charging	mp bulb. tailgate hato system.repla	•	Parts List Lift Suppo 5w20 Eng	rt Glass ine Oil	12/03/2015	Closed:	<b>G</b> 2. 5.
Problem: - Pm service. - Replace def - Replace bot - Load test batted defective batted - Replace two	Pm service. fective right reat th defective lift attery and cheat ery. tries.rotate an	ar strobe lan support for ck charging nd balance	mp bulb. tailgate hato system.repla all four.	•	<b>Parts List</b> Lift Suppo 5w20 Eng Filter	rt Glass ine Oil de		Closed:	<b>C</b> 2. 5. 1.
Problem: - Pm service. - Replace def - Replace bot - Load test batted defective batted - Replace two - Resurface b	Pm service. fective right reat th defective lift attery and cheat ery. tires.rotate an poth rear brake	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	<b>Parts List</b> Lift Suppo 5w20 Eng Filter Wiper Blac	rt Glass ine Oil de Wiper Bla	ade M	Closed:	<b>G</b> 2. 5. 1. 2.
Problem: - Pm service. - Replace def - Replace bot - Load test batte defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an poth rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202	rt Glass ine Oil de Wiper Bla uid Conce	ade M entr	Closed:	<b>C</b> 2. 5. 1. 2. 1.
Problem: - Pm service. - Replace def - Replace bot - Load test batted defective batted - Replace two - Resurface b	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an poth rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl	rt Glass ine Oil de Wiper Bla uid Conce Fuel Filte	ade M entr	Closed:	<b>G</b> 2. 5. 1. 2. 1.
Problem: - Pm service. - Replace def - Replace bot - Load test batte defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an poth rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold	rt Glass ine Oil de Wiper Bla uid Conce Fuel Filte	ade M entr	Closed:	C 2. 5. 1. 2. 1. 1. 1.
Problem: - Pm service. - Replace def - Replace bot - Load test batte defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an poth rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold Hide Away Battery 18340741	rt Glass ine Oil de Wiper Bla uid Conce Fuel Filte / Strob 8 P235-70	ade M entr r	Closed:	C 2. 5. 1. 2. 1. 1. 1. 1. 2.
Problem: - Pm service. - Replace def - Replace bot - Load test bat defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an poth rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold Hide Away Battery 18340741 B Fluid Do	rt Glass ine Oil de Wiper Bla uid Conce Fuel Filte / Strob 8 P235-70	ade M entr r	Closed:	C 2. 5. 1. 2. 1. 1. 1. 1. 2. 6.
- Pm service. - Replace def - Replace bot - Load test ba defective batte - Replace two - Resurface b pads.service o	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an both rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold Hide Away Battery 18340741	rt Glass ine Oil de Wiper Bla uid Conce Fuel Filte / Strob 8 P235-70	ade M entr r	Closed:	C 2. 5. 1. 2. 1. 1. 1. 1. 2.
Problem: - Pm service. - Replace def - Replace bot - Load test bat defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an both rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold Hide Away Battery 18340741 B Fluid Do Real Pad Shop Sup	rt Glass ine Oil de Wiper Bla uid Conco Fuel Filte / Strob 8 P235-70 ot 3-32oz plies	ade M entr r	Closed:	C 2. 5. 1. 2. 1. 1. 1. 1. 2. 6. 1.
Problem: - Pm service. - Replace def - Replace bot - Load test bat defective batte - Replace two - Resurface b pads.service of	Pm service. fective right rea th defective lift attery and chea ery. tres.rotate an both rear brake calipers.flush a	ar strobe lan support for ck charging nd balance e rotors.repl	mp bulb. tailgate hato system.repla all four. ace brake	ace	Parts List Lift Suppo 5w20 Eng Filter Wiper Blac Ww-1202 Washer Fl Napagold Hide Away Battery 18340741 B Fluid Do Real Pad	rt Glass ine Oil de Wiper Bla uid Conco Fuel Filte / Strob 8 P235-70 ot 3-32oz plies	ade M entr r	Closed:	<b>G</b> 2. 5. 1. 2. 1. 1. 1. 1. 2. 6.

Workorder:	1608892	Meter:	36735			In Date:	08/25/2016	Closed:	09/29/2016
Problem:	P.M. service	e and ABS liq	jht on and t	orakes went	to the flo	oor.			
- P.m. Service	Э.				Parts Li	ist			Qty
- Diagnose At	os system.re	place defecti	ve Hcu.flus	h and	Filter				1.00
bleed system.					5w20 Er	ngine Oil			5.00
- Recover free		nd recharge	system to s	pecs.	Wiper B	lade			2.00
- Shop Suppli	es				Ww-120	2 Wiper Bla	ide M		1.00
					Mac Wit	te Lithium G	res		1.00
					НСИС	Control Asy			1.00
						Dot 3-32oz			6.00
					Non-chl	or Brake Clr	٦r		2.00
					Shop Su				1.00
	Ho :	ours 9.25		Labor:	555.00	Parts:	4,183.50	Total:	4,738.50
Workorder: Problem:	1608935 Brakes/PM	Meter:	36700			In Date:	08/25/2016	Closed:	08/26/2016
- Tow From: 3	3550 Mil.trl S	of Indiantow	n Rd Fire F	Rescue#16					
	Ho :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1704027 P.M. service	Meter: e.	39653			In Date:	04/21/2017	Closed:	04/28/2017
- P.m. service	).				Parts Li	ist			Qty
- Drain and flu	ush transmis	sion.			5w20 Er	ngine Oil			5.00
- Rotate and h	nigh speed b	alance all fou	ur wheels.ni	itro fill all.	Filter				1.00
- Shop Suppli	es				Wiper B	lade			2.00
					Accufit F	Rear			1.00
					Washer	Fluid Conce	entr		1.00
					Napago	ld Fuel Filte	r		1.00
					Syn-atf	Trans Fluid	S		7.00
					Shop Su	upplies			1.00
	Hc	ours 5.25		Labor:	315.00	Parts:	90.22	Total:	405.22
	1704280 1 - Wash tio	Meter: cket(s) issued	39653 1			In Date:	04/27/2017	Closed:	04/27/2017
Workorder: Problem: - 1 - Wash ticl	1 - Wash tio	cket(s) issued				In Date:	04/27/2017	Closed:	04/27/2017

Workorder: Problem:	1712118 P.M. service.	Meter:	43376			In Date:	12/11/2017	Closed:	12/18/201	17
- P.m. service	).				Parts Li	st				Qty
- Remove and	d resurface both	n front roto	ors.replace bra	ke pads	5w20 Er	igine Oil				5.00
and service ca	alipers and blee	d brake sy	stem.road tes	t.	Oil Filter					1.00
- Rotate and I	palance four tire	es.			Napagol	d Fuel Filte	r			1.00
<ul> <li>Shop Suppli</li> </ul>	es				Washer	Fluid Conce	entr			1.0
					Pads					1.00
					brake flu	iid				1.00
					Shop Su	pplies				1.00
	Hours :	s 7.25		Labor:	435.00	Parts:	98.78	Total:	533.78	
Workorder:	1800230	Meter:	43471			In Date:	01/05/2018	Closed:	01/19/201	18
Problem:	Towed in for n	o start.								
	iagnoise no stai				Parts Li	st				Qty
	b1239,b12a7.p ymode door act				motor as	sm				1.00
	front A/c ,b12a				Motor As	sy				1.00
clear codes ar		•			Shop Su	pplies				1.00
<ul> <li>Shop Suppli</li> </ul>	es									
	Hours :	s 3.50		Labor:	210.00	Parts:	91.18	Total:	301.18	
Norkorder: Problem:	1800418 No start	Meter:	43376			In Date:	01/05/2018	Closed:	01/11/201	18
- Tow From: 3	301 n Olve ave									
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1806011 PM Service	Meter:	45588			In Date:	06/12/2018	Closed:	06/20/201	18
										•
- P.m. Service					Parts Li	st				Qty
- Rotate and I					Filter					1.00
- Shop Suppli	es				5w20 Er	-				5.00
						ctfit-rear				1.00
						ctfit-beam				2.00
						Fluid Conce	entr			1.00
					Shop Su	• •				1.00
	Hours :	s 3.75		Labor:	225.00	Parts:	58.04	Total:	283.04	
Workorder: Problem:	1806532 Transition Pre	Meter: p Charge	45588			In Date:	06/26/2018	Closed:	06/26/201	18
- Transition P	rep Charge									
	Hours	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
	:									