10172353 2009 CHEVROLET MALIBU Car, Intermediate, Hybrid

		10172353	2009 CF	HEVROLET M	IALIBU (	Car, Interme	ediate, Hybrid		
Workorder: Problem:	844954 PRE-DE	<b>Mete</b> ELIVERY INS				In Date:	10/01/2008	Closed:	10/01/2008
- Pre-delivery	Inspection	on							
		Hours 2.00 :		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	845695 001 WA	Mete SH TICKET I	-	T 10/01/08		In Date:	10/01/2008	Closed:	10/15/2008
- 001 Wash T	icket Issu	ued Out 10/0	1/08						
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	847341 001 DE	<b>Mete</b> TAIL VEHICL	-	18/08		In Date:	11/18/2008	Closed:	11/20/2008
- 001 Detail V	ehicle	11/18/08							
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	848058 001 WA	Mete SH TICKET I	-	T 12/05/08		In Date:	12/05/2008	Closed:	12/10/2008
- 001 Wash T	icket Issu	ued Out 12/0	5/08						
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	932834 001 WA	Mete SH TICKET I	-	T 01/13/09		In Date:	01/13/2009	Closed:	01/15/2009
- 001 Wash T	icket Issu	ued Out 01/1	3/09						
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	933684 001 WA	Mete SH TICKET I		T 01/30/09		In Date:	01/30/2009	Closed:	02/06/2009
- 001 Wash T	icket Issu	ued Out 01/3	0/09						
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	936410 PM SEF	<b>Mete</b> RVICE	r: 7572			In Date:	04/13/2009	Closed:	04/15/2009
- Pm Service					Parts L	ist			Qty
							cd Pf457g Wix	57082	1.00
		Hours 2.00		Labor:	10w30 l	Motor Oil Parts:	19.16	Total:	5.00 139.16
Workorder:	936523 001 WA	: Mete	-			In Date:	04/10/2009	Closed:	04/15/2009
- 001 Wash T				2 ., 10,00					
oo i wasii i	101101 1001	Hours 0.00	0,00	Labor:	0.00	Parts:	0.00	Total:	0.00

938670 Workorder: Meter: 0 In Date: 06/12/2009 Closed: 06/05/2009 Problem: 001 WASH TICKET ISSUED OUT 06/12/09 - 001 Wash Ticket Issued Out 06/12/09 Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 940181 Meter: 9876 In Date: 07/02/2009 Closed: 07/09/2009 Problem: Recall - To/from Dealer for safety Recall #09041, trans shifter cable. Hours 2.00 Total: 120.00 Labor: 120.00 Parts: 0.00 Workorder: 943827 Meter: 09/28/2009 Closed: 11511 In Date: 10/05/2009 Problem: PM Service - Pm Service **Parts List** Qty Ch9018 Oil Filter Acd Pf457g Wix 57082 1.00 5w30 Oil 5.00 Labor: 120.00 Hours 2.00 Parts: 17.72 Total: 137.72 Workorder: 946764 Meter: 12308 In Date: 12/07/2009 Closed: 12/07/2009 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued - 1 - Detail Vehicle Wash Ticket(s) Issued Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 1000896 Workorder: Meter: 13107 In Date: 01/25/2010 Closed: 02/03/2010 Problem: Replace windshield wipers - Wiper Blades **Parts List** Qty 19187382 Wiper Blade R/hand (acd 8-992115) 1.00 1.00 L Wiper Blade Labor: 30.00 Total: 71.25 Hours 0.50 Parts: 41.25 Workorder: 1003696 Meter: 14277 In Date: 04/09/2010 **Closed:** 04/19/2010 Problem: PM - Pm Service **Parts List** Qty Ch9018 Oil Filter Acd Pf457g Wix 57082 1.00 5w30 Oil 5.00 Hours 2.00 Labor: 120.00 Parts: 17.72 Total: 137.72 Workorder: 1003774 Meter: 14277 04/12/2010 Closed: In Date: 04/12/2010 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued - 1 - Detail Vehicle Wash Ticket(s) Issued Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 1005906 Meter: 15426 In Date: 06/04/2010 Closed: 06/18/2010 Workorder: Problem: service hybrid light on - Transport to dealer

Labor: 60.00

Hours 1.00

Parts: 0.00

Total: 60.00

Workorder: Problem:	1010677 pm servic		ter: ancei	16526 ver			In Date:	09/28/2010	Closed:	09/30/2010
- Pm Service						Parts Li	st			Qt
- Flash Cance	eiver							d Pf457g Wix	¢ 57082	1.0
						5w30 Oi				5.0
								ade R/hand (a	acd 8-99211	
							•	ade L/hand (a		•
	H	Hours 3.0	00		Labor:	180.00	Parts:	•		237.41
Workorder:	1010798	_	ter:	16526	au ad		In Date:	09/30/2010	Closed:	09/30/2010
				Ticket(s) Iss	sueu					
- 1 - Detail Ve		•	•	ed			_			
		Hours 0.0	00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1011053 key fob in		eter:	16664			In Date:	10/06/2010	Closed:	10/08/2010
- Set up with	dealer to w	arranty k	ey Fol	b						
	H :	Hours 0.5	50		Labor:	30.00	Parts:	0.00	Total:	30.00
Workorder: Problem:	1011190 Dead batt		ter:	16696			In Date:	10/12/2010	Closed:	10/12/2010
- Transport ve varranty.		aler for b		replaceme		120.00	Parts:	0.00	Total:	120.00
	:	10013 2.0			Labor.	120.00	i aits.	0.00	Total.	120.00
Workorder: Problem:	1103628 P.M. Serv	_	ter:	18569			In Date:	04/04/2011	Closed:	04/14/2011
- Perform pm	service.					Parts Li	st			Qt
- Rotate and I	balance all	four tires				Shop Su	upplies			1.00
- Shop Suppli	ies					Ch9018	Oil Filter Ac	d Pf457g Wix	c 57082	1.00
						5w30 Oi		· ·		5.00
	H :	Hours 3.0	00		Labor:	180.00	Parts:	19.66	Total:	199.66
Workorder: Problem:	1107886 no start	Ме	eter:	18569			In Date:	07/27/2011	Closed:	07/27/2011
- From: 8100	forest hill b	olvd To	: lv sh	ор						
	H :	Hours 0.0	00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1107898 Towed in		eter: no cra	18585 nk.			In Date:	07/28/2011	Closed:	07/29/2011
- Test starting						Parts Li	st			Qt
est for draw.s - Shop Suppli		shop to rp	oair ca	anceiver dra	aw.	Shop Su	upplies			1.00
опор оцруп		Hours 1.0	00		Labor:	60.00	Parts:	2.00	Total:	62.00

Workorder: Problem:	1107938 remove cancei	Meter: ver	18586			In Date:	07/28/2011	Closed:	07/29/2	011
issues	ceiver and issue	fuel card	d for battery dr	ain	Parts L Shop S					<b>Qty</b> 1.00
- Shop Suppli		s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1108009 1 - Detail Vehic	Meter: cle Wash	18586 Ticket(s) Issue	ed		In Date:	08/01/2011	Closed:	08/01/2	011
- 1 - Detail Ve	hicle Wash Tick	ket(s) Issu	ued							
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1201869 1 - Wash ticket	Meter:	21605 d			In Date:	02/24/2012	Closed:	02/24/2	012
- 1 - Wash tic	ket(s) issued									
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1203995 low air in tires	Meter:	22819			In Date:	04/27/2012	Closed:	04/30/2	012
- ck low tire liq	ght on ck all tire: es	s fill all 35	5 psi of nitroge	n	Parts L Shop S					<b>Qty</b> 1.00
	Hours :	1.00		Labor:	•	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1204169 P.M. service.	Meter:	22842			In Date:	05/02/2012	Closed:	05/10/2	012
- P.m. Service	Э.				Parts L	.ist				Qty
- Rotate and I	palance all tires.				Shop S	upplies				1.00
- Shop Suppli	es				Ch9018	3 Oil Filter Ad	cd Pf457g Wix	57082		1.00
					Ca9492	2 Air Filter Ad	cd A1627c Wi	x 46092		1.00
					5w30 C					5.00
						•	ade L/hand (a		,	1.00
						•	ade R/hand (a		•	1.00
	Hours :	3.00		Labor:	180.00	Parts:	57.19	Total:	237.19	
Workorder: Problem:	1206570 1 - Detail Vehic	Meter: cle Wash	30324 Ticket(s) Issue	ed		In Date:	07/13/2012	Closed:	07/13/2	012
- 1 - Detail Ve	hicle Wash Tick	ket(s) Issu	ued							
	Hours :			Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: 13001 Problem: Pm se		25707	In Date	e: 01/04/2013	Closed:	01/24/2013
- Perform pm service			Parts List			Qty
•		o remove parcel shelf	Napa Quart 5w3	30		5.00
to acess and replace	failed third brake I	amp assembly with	Oil Filter			1.00
new.	to the front whee	le nitrogen fill and	215 55r17 94v A	ssur Tour		2.00
<ul> <li>Install two new tires balance all four.</li> </ul>	to the nont whee	is.fiitiogen iiii and	Ligth Asy			1.00
- Perform wheel align	ment complete.		Shop Supplies			1.00
- Shop Supplies	·		Tire Disposal Fe	ee		2.00
	Hours 7.75	Labor:	465.00 Par	rts: 566.52	Total:	1,031.52
Workorder: 130069 Problem: 1 - Det		25412 Ticket(s) Issued	In Date	e: 01/18/2013	Closed:	01/18/2013
- 1 - Detail Vehicle W	ash Ticket(s) Issu	ied				
	Hours 0.00	Labor:	0.00 Par	rts: 0.00	Total:	0.00
Workorder: 130399 Problem: Towed		27334 nage beyond repairs.	In Date	e: 04/23/2013	Closed:	04/24/2013
- Install new tire to the	e right front wheel	l.nitrogen fill and	Parts List			Qty
balance same.			215 55r17 94v A	ssur Tour		1.00
- Shop Supplies			Shop Supplies			1.00
			Tire Disposal Fe			1.00
	Hours 1.00 :	Labor:	60.00 Pai	rts: 205.14	Total:	265.14
Workorder: 13040 Problem: Flat tire		27275	In Date	e: 04/23/2013	Closed:	04/23/2013
- Tow From: 800 Cler	natis St (health D	ept) To: Lv Shop				
	Hours 0.00	Labor:	0.00 Pa	rts: 0.00	Total:	0.00
Workorder: 130409 Problem: Flat tire	: 53 <b>Meter:</b>	27334	0.00 Par			0.00
	: 53 <b>Meter:</b> e on F/P	27334				
<b>Problem:</b> Flat tire	: 53 <b>Meter:</b> e on F/P	27334	In Date			04/24/2013
<b>Problem:</b> Flat tire	:  53 Meter: e on F/P  ematis st - Flat tire Hours 0.00 :  Meter:	27334 e on F/p Labor:	In Date	e: 04/23/2013	Closed:	04/24/2013
Problem: Flat tire - Tire Service 800 Cle Workorder: 130449	:  53 Meter: e on F/P ematis st - Flat tire Hours 0.00 :  92 Meter: sh ticket(s) issued	27334 e on F/p Labor:	In Date	e: 04/23/2013	Closed:	04/24/2013

Workorder: 1312107 Meter: 31857 Problem: Pm service and wiper blades.			In Date:	12/04/2013	Closed:	12/17/20	13
- P.m. Service.		Parts Lis	<b>~4</b>				Qty
- Rotate and balance all tires.			iart 5w30				5.00
		•					1.00
- Shop Supplies		Accufit B	d Oil Filter				
				iit Daaaanaa	ula Ciala		1.00
		-		it - Passenge	rs Side		1.00
H 0.00	1 -1	Shop Su		50.44	<b>T</b> . ( - 1	000.44	1.00
Hours 3.00 :	Labor:	180.00	Parts:	50.14	ı otai:	230.14	
Workorder: 1411643 Meter: 38238 Problem: Pm service.Safety recall#13036			In Date:	11/18/2014	Closed:	12/12/20	14
- Pm service.		Parts Lis	st				Qty
- Check starting and charging system.battery failed I		Napa Qu	ıart 5w30				5.00
after recharge.replace defective battery and negative cable.	battery	Napagol	d Oil Filter				1.00
- Replace two tires. rotate and balance all four.		Accufit B	eam				1.00
Replace two tires. Totale and balance all four.     Replace broken turnsignal multifunction switch.		Wiper Bl	ade - Accuf	it - Passenge	r's Side		1.00
Transport vehicle to and from dealer for safety reca	all	Bat Term	Protector				1.00
#13036 Perform repair for brake lamp malfunction.	all	Battery					1.00
- Shop Supplies		Headligh	t Switch				1.00
		215 55r1	7 94v Assu	ır Tour			2.00
		Cable					1.00
		Shop Su	pplies				1.00
			osal Fee				2.00
Hours 9.00	Labor:	540.00		734.75	Total:	1,274.75	
Workorder: 1512878 Meter: 39098 Problem: Pm service.			In Date:	12/21/2015	Closed:	01/19/20	16
- Pm service.		Parts Lis	st				Qty
- Pressure test and inspect cooling system.flush and	d renew	Napa Qu	art 5w30				5.00
coolant.		•	d Oil Filter				1.00
- Fabricate and replace faded front and rear asset no	umbers.	Accufit B					1.00
- Rotate and balance all four tires.		Wiper Bl	ade - Accut	it - Passenge	r's Side		1.00
- Shop Supplies		•	Fluid Conce	_			1.00
		Peak Glo					1.00
		Shop Su					1.00
Hours 6.00	I ahor	360.00	Parts:	75.59	Total:	435.59	
:	Labor.						
Workorder: 1600289 Meter: 38906 Problem: 1 - Wash ticket(s) issued	Labor.		In Date:	01/08/2016	Closed:	01/08/20	16
: Workorder: 1600289 Meter: 38906	Labor.		In Date:	01/08/2016	Closed:	01/08/20	16

Workorder: Problem:	1606937 P.M. servic	Meter: e and left rea	40699 r tire going fla	t.		In Date:	07/11/2016	Closed:	07/25/20	016
- P.m. Service	e.				Parts L	ist				Qty
- Service tran	smission.flus	sh and refill sy	/stem.		Napa Q	uart 5w30				5.00
- Rotate and I	oalance tires	i.			Napago	ld Oil Filter				1.00
- Shop Suppli	es				Wiper B	Blade				1.00
					Wiper B	Blade				1.00
					tram filte	er				1.00
					Syn-atf	Trans Fluid	S			8.00
					Shop S					1.00
	Ho :	ours 5.50		Labor:	330.00	Parts:	134.59	Total:	464.59	
Workorder: Problem:	1607086 1 - Wash tid	Meter: cket(s) issued	40563			In Date:	07/13/2016	Closed:	07/13/20	016
- 1 - Wash tic	ket(s) issued	ł								
	Ho :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1608779 Flat Tire on	Meter:	40788			In Date:	08/19/2016	Closed:	08/24/20	016
- Tire Service R/f	8100 Fores	t Hil Blvd Wat	er Plant - Flat	Tire on						
	Ho :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1610830 Check engi	Meter: ne light on.	41217			In Date:	10/20/2016	Closed:	10/31/20	016
- Diagnose ch			ear code and	reset	Parts L					Qty
transmission s - Shop Suppli	•	est unve.			Shop S	upplies				1.00
		ours 1.50		Labor:	90.00	Parts:	2.00	Total:	92.00	
Workorder: Problem:	1700145 P.M. servic	Meter:	41299			In Date:	01/05/2017	Closed:	01/23/20	017
- P.m. Service	Э.				Parts L	ist				Qty
- Replace one	Tpms.rotate	e and balance	all four		Napago	ld Oil Filter				1.00
tires.reprograr	n Tpms.				Napa S	Syn 5w30 Qt				5.00
- Pressure tes	st and inspec	ct cooling syst	em.flush and	refill	Air Filte	r				1.00
system. - Shop Suppli	<b>A</b> S				Washer	Fluid Conce	entr			1.00
- Shop Suppli	C3				Accufit I	Beam				1.00
					Wiper B	Blade - Accuf	fit - Passenge	er's Side		1.00
					Tire Ser	nsor				1.00
					Dex Co	olant Engine	)			2.00
					Shop S	upplies				1.00
						• •				

- P.m. service Found passenger side low beam headlamp inop.found filliment burned and ground terminal on connector burned.replaced harness and bulb.normal operation High speed balance all four tires.nitro filled Shop Supplies  - Shop Supplies  - Shop Supplies  - Hours 3.60 - Labor: - Problem: P.M. service P.m. service P.m. service Check starting and charging system.battery failed load test replace with new battery Rotate and high speed balance all four tires Shop Supplies - Parts List - Napagold Oil Filter - 5w20 Synthetic Motor - Wiper Blade - Accufit - Passenger's Side - Accufit Beam - Washer Fluid Concentr - Halogen Bulb - Lamp Harness - Napa Syn 5w30 Qt - Wiper Blade - Niper Blade - Wiper Blade - Shop Supplies - T. La 45 50 Accufit - Passenger's Side - Accufit Beam - Washer Fluid Concentr - Halogen Bulb - Lamp Harness - Napa Syn 5w30 Qt - Napagold Oil Filter - Sw20 Synthetic Motor - Wiper Blade - Napa Syn 5w30 Qt - Napagold Oil Filter - 21 in Exactfit-beam - 24 in Exactfit-beam - 24 in Exactfit-beam - 24 in Exactfit-beam - 24 in Exactfit-beam - 25 in Exactfit-beam - 26 in Exactfit-beam - 27 in Exactfit-beam - 28 in Exactfit-beam - 28 in Exactfit-beam - 29 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 25 in Exactfit-beam - 26 in Exactfit-beam - 27 in Exactfit-beam - 28 in Exactfit-beam - 27 in Exactfit-beam - 28 in Exactfit-beam - 28 in Exactfit-beam - 29 in Exactfit-beam - 20 in Exactfit-beam - 21 in Exactfit-beam - 22 in Exactfit-beam - 23 in Exactfit-beam - 24 in Exactfit-beam - 25 in Exactfit-beam - 26 in Exactfit-beam - 27 in Exactfit-beam - 28 in Exactfit-beam - 29 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 20 in Exactfit-beam - 21 in Exactfit-	
filiment burned and ground terminal on connector burned.replaced harness and bulb.normal operation.  - High speed balance all four tires.nitro filled Shop Supplies  - Shop Supplies  - Shop Supplies  - Hours 3.60 - Labor:  - P.m. service Check starting and charging system.battery failed load test .replace with new battery Rotate and high speed balance all four tires Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Check starting and charging system.battery failed load test .replace with new battery Rotate and high speed balance all four tires Shop Supplies - Shop Supplies	1.00 5.00 1.00 1.00 1.00 1.00 1.00 1.00
filliment burned and ground terminal on connector burned.replaced harness and bulb.normal operation.  - High speed balance all four tires.nitro filled Shop Supplies  - Hours 3.60 - Labor: - P.m. service P.m. service Check starting and charging system.battery failed load test. replace with new battery Rotate and high speed balance all four tires Shop Supplies - Parts List - Napa Syn 5w30 Qt - Napagold Oil Filter - 21 in Exactfit-beam - Battery - Wiper Blade - Wiper Blade - Wiper Blade - Wiper Blade - Shop Supplies	1.00 1.00 1.00 1.00 5.00 1.00 1.00 1.00
- High speed balance all four tires.nitro filled Shop Supplies  Accufit Beam  Washer Fluid Concentr  Halogen Bulb  Lamp Harness  Napa Syn 5w30 Qt  Wiper Blade A/c Delco  Wiper Blade A/c Delco  Harness  Shop Supplies  Hours 3.60  Labor: 216.00  Parts: 213.01  Total: 429.0  Workorder: 1800587  Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test.replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Wiper Blade  Wiper Blade  Shop Supplies	1.00 1.00 1.00 5.00 1.00 1.00 1.00
- Shop Supplies  Acculit Beam Washer Fluid Concentr Halogen Bulb Lamp Harness Napa Syn 5w30 Qt Wiper Blade A/c Delco Wiper Blade A/c Delco Harness Shop Supplies  Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Problem: P.M. service.  - P.m. service Check starting and charging system.battery failed load test .replace with new battery Rotate and high speed balance all four tires Shop Supplies  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Shop Supplies	1.00 1.00 5.00 1.00 1.00 1.00 1.00
Washer Fluid Concentr Halogen Bulb Lamp Harness Napa Syn 5w30 Qt Wiper Blade A/c Delco Wiper Blade A/c Delco Harness Shop Supplies  Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Meter: 45250 In Date: 01/18/2018 Closed: 01/29  Problem: P.M. service P.m. service Check starting and charging system.battery failed load test replace with new battery Rotate and high speed balance all four tires Shop Supplies  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Wiper Blade Shop Supplies	1.00 1.00 5.00 1.00 1.00 1.00 1
Lamp Harness Napa Syn 5w30 Qt Wiper Blade A/c Delco Wiper Blade A/c Delco Wiper Blade A/c Delco Harness Shop Supplies Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Meter: 45250 In Date: 01/18/2018 Closed: 01/29 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  - Shop Supplies  Labor: 216.00 Parts: 213.01 Total: 429.0  In Date: 01/18/2018 Closed: 01/29  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Wiper Blade Shop Supplies	1.00 5.00 1.00 1.00 1.00 1.00 1
Napa Syn 5w30 Qt Wiper Blade A/c Delco Wiper Blade A/c Delco Harness Shop Supplies  Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test Ireplace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Shop Supplies	5.00 1.00 1.00 1.00 1.00 1
Wiper Blade A/c Delco Wiper Blade A/c Delco Harness Shop Supplies  Hours 3.60 Eabor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Wiper Blade Wiper Blade Shop Supplies	1.00 1.00 1.00 1.00 1 2018
Wiper Blade A/c Delco Harness Shop Supplies  Hours 3.60 Eabor: 216.00 Parts: 213.01 Total: 429.0  Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - P.m. service Check starting and charging system.battery failed load test replace with new battery Rotate and high speed balance all four tires Shop Supplies  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Shop Supplies	1.00 1.00 1.00 1 2018
Harness Shop Supplies  Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.00  Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Harness Shop Supplies  In Date: 01/18/2018 Closed: 01/29  Parts List Napa Syn 5w30 Qt Napagold Oil Filter 21 in Exactfit-beam Battery Wiper Blade Wiper Blade Wiper Blade Shop Supplies	1.00 1.00 1 2018
Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.00  Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Shop Supplies  In Date: 01/18/2018 Closed: 01/29  Parts List  Napa Syn 5w30 Qt  Napagold Oil Filter  21in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Wiper Blade  Shop Supplies	1.00 1 /2018 <b>Qty</b>
Workorder: 1800587 Meter: 45250 Problem: P.M. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Hours 3.60 Labor: 216.00 Parts: 213.01 Total: 429.0  In Date: 01/18/2018 Closed: 01/29  Parts List  Napa Syn 5w30 Qt  Napagold Oil Filter  21in Exactfit-beam  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	1 '2018 <b>Qty</b>
Workorder: 1800587 Meter: 45250 In Date: 01/18/2018 Closed: 01/29 Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  - Shop Supplies  - Rotate and high speed balance all four tires.  - Shop Supplies  - Shop Supplies  - Shop Supplies  - Shop Supplies	(2018 <b>Qty</b>
Problem: P.M. service.  - P.m. service.  - Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Parts List  Napa Syn 5w30 Qt  Napagold Oil Filter  21in Exactfit-beam  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	Qty
- Check starting and charging system.battery failed load test replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  Shop Supplies  Napa Syn 5w30 Qt Napagold Oil Filter  21in Exactfit-beam  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	-
.replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	-
replace with new battery.  - Rotate and high speed balance all four tires.  - Shop Supplies  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	
- Rotate and high speed balance all four tires Shop Supplies  24in Exactfit-beam  Battery  Wiper Blade  Wiper Blade  Shop Supplies	1.00
Battery Wiper Blade Wiper Blade Shop Supplies	1.00
Wiper Blade Wiper Blade Shop Supplies	1.00
Wiper Blade Shop Supplies	1.00
Shop Supplies	1.00
	1.00
He = 4.00 Feb. 040.00 Pests 047.40 Total 457.4	1.00
Hours 4.00 Labor: 240.00 Parts: 217.48 Total: 457.4	3
Workorder: 1803873 Meter: 45996 In Date: 04/13/2018 Closed: 04/13  Problem: 1 - Wash ticket(s) issued	2018
- 1 - Wash ticket(s) issued	
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00	
Workorder:         1804376         Meter:         46600         In Date:         04/26/2018         Closed:         05/09           Problem:         Check for fuel smell.	2018
- Diagnoise fuel smell .pressure test evap system . Remove	Qty
fuel tank and smoke test fuel tank .replace leaking fuel pump Fuel Module	1.00
assembly and evap and filler tube.return fuel to tank and retest.  Line Hose Gas	
Hara Olas	1.00
- Shop Supplies Hose Cim  F- S Hose	1.00 2.00
Shop Supplies	2.00
Hours 4.50 Labor: 270.00 Parts: 811.46 Total: 1,081	

**Workorder:** 1807507 **Meter:** 47757 **In Date:** 07/24/2018 **Closed:** 09/10/2018

Problem: PM Service

- Oil change only(vehicle replace with new) Parts List Qty

- Shop Supplies Napa Syn 5w30 Qt 5.00

Oil Filter 1.00

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 33.13 Total: 93.13

**Workorder:** 1808420 **Meter:** 47757 **In Date:** 08/16/2018 **Closed:** 08/16/2018

**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

: