		10174394	200010	RD F250	Ріскир,	3/4 ION, W	/Tow Pkg			
Workorder: 83 Problem: PF	89190 RE-DELIVER	Meter: 0 Y INSPECT				In Date:	05/30/2008	Closed:	05/30/20	800
- Pre-delivery Ins	spection									
	Hours :	2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: 84 Problem: P.I	6765 M SERVICE	Meter: 4	056			In Date:	11/05/2008	Closed:	11/10/20	008
- Pm Service					Parts Li	st				Qty
- Rotate & High S	Speed Baland	ce All 4 Tire	s.nitro Fill 1	Fires.	Shop Su	pplies				1.00
- Shop Supplies					1372 Oi	il Filter Frm	n Ph2 Wix 51	372		1.00
					G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Er	ngine Oil				7.00
	Hours :	3.75		Labor:	225.00	Parts:	38.50	Total:	263.50	
Workorder: 94 Problem: P.I	0891 M service, in		091 stand			In Date:	07/17/2009	Closed:	07/27/20	009
- P.m service					Parts Li	st				Qty
- Fabricate & inst	tall customer	s computer	stand & po	wer	Shop Su	pplies				1.00
harness.					1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
- Rotate & balance	ce all four tire	es.			Ca10262	2 Air Filter I	Mtc Fa1883 W	/ix 49883		1.00
- Shop Supplies					5w20 Er	ngine Oil				7.00
					31-20 W	iper Blades	20" Blade			2.00
					Used Fir	ex Refurbe	d Fire Extings	shers		1.00
	Hours :	7.75		Labor:	465.00	Parts:	47.33	Total:	512.33	
Workorder: 10 Problem: P.I)10743 M.SERVICE,		7881 DEAD			In Date:	09/30/2010	Closed:	10/13/20	010
- P. M.					Parts Li	st				Qty
- Transport & pic	k up vehicle	at dealer (d	efective bat	ttery).	Shop Su	pplies				1.00
- Dealer To Repla	ace Battery (warranty).			1372 Oi	il Filter Frm	n Ph2 Wix 51	372		1.00
- Shop Supplies					G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Er	ngine Oil				7.00
						iper Blades				2.00
	Hours :	4.75		Labor:	285.00	Parts:	57.04	Total:	342.04	
Workorder: 12 Problem: P.	200093 M. SERVICE		2452 tes			In Date:	01/04/2012	Closed:	01/12/20)12
D. M. Samilaa					Parts Li	st				Qty
- P. M. Service.		ng bracket			Shop Su	pplies				1.00
- Repair trailer lig	ghts connecti	ng brachen								
	ghts connecti				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
- Repair trailer lig	ghts connecti				1372 Oi 5w20 Er		n Ph2 Wix 51:	372		1.00 7.00
- Repair trailer lig	ghts connecti				5w20 Er			372		
- Repair trailer lig	ghts connecti				5w20 Er 31-20 W	ngine Oil ⁄iper Blades				7.00

Workorder: Problem:	1202082 DEAD BATTI	Meter: ERY	22832			In Date:	02/29/2012	Closed:	03/09/2	012
- replace bad	battery ok cha	rging sys			Parts L	ist				Qty
- Shop Suppli	-				Shop S	upplies				1.00
					Group 6	65 Battery (n	ntc Bxt-65-850))		1.00
	Hou :	rs 0.75		Labor:	45.00	Parts:	130.75	Total:	175.75	
Workorder: Problem:	1209518 dead battery	Meter:	24806			In Date:	10/04/2012	Closed:	10/04/2	012
- jump start ve battery battery	ehicle from wu is ok st this ti		ot recharge a	nd ck						
	Hou :	rs 0.75		Labor:	45.00	Parts:	0.00	Total:	45.00	
Workorder: Problem:	1401972 3 - Key(s) iss	Meter: ued	24806			In Date:	02/28/2014	Closed:	02/28/2	014
- 3 - Key(s) is	sued				Parts L	ist				Qty
					Duplica	te Vehicle K	eys			3.00
	Hou :	rs 0.60		Labor:	36.00	Parts:	9.00	Total:	45.00	
Workorder: Problem:	1402036 pm, wont star	Meter: t	24870			In Date:	03/03/2014	Closed:	03/18/2	014
- pm					Parts L	ist				Qty
- wont start te	st battery bad	ck chargin	g sys replace	battery	Napago	old Fuel Filte	r			1.00
- verify needs	4 tires dismou	unt mount b	alance add n	2	Napago	old Oil Filter				1.00
	tail light out re	place 1 tai	l light bulb cle	ean		uart 5w20				7.00
sockets ck all	from wiper an	d vonte ele	an under ber	d and	Washer					1.00
inside wheels	nom wper an				Wiper E	Blade				2.00
- Shop Suppli	es				Battery	400 1 40 45 7	F 4 7			1.00
						492 Lt245-7	5117			4.00
					Shop S	opplies posal Fee				1.00 4.00
	Hou	rs 7.25		Labor:	435.00	•	1,158.06	Total:	1,593.0	
Workorder: Problem:	1402664 check engine	Meter: light is on	24935			In Date:	03/19/2014	Closed:	03/27/2	014
- ck engine lig b1318 b1676 reprogram pcr	•			2011	Parts L Shop S					Qty 1.00
 test drive ve Shop Suppli 	hicle before ar es	nd after rep	air 51 miles							
		rs 4.00		Labor:	240.00	Parts:	2.00	Total:	242.00	

1404980 ck engine light	Meter:	27453 missions leak)	not the		n Date:	05/22/2014	Closed:	05/30/20	014
ck engine ligni	(gross ei	nissions leak)	not the g	gas cap cha	anged out	l last time			
				Parts List	t				Qty
				Ch Cannis	ster Filter				1.00
				Valve					1.0
<i>,</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					plies				1.00
es									
Hours	s 6.00		Labor:	360.00	Parts:	171.71	Total:	531.71	
1406533	Meter:	28603		l	n Date:	07/02/2014	Closed:	07/17/20	014
pm, suspensio	on shocks	, rattling while	e driving						
				Parts List		Qty			
e pin				Napagold		1.00			
- ck suspension noise perform pinpoint test and found all									7.00
		upervisor to ta	ake	Washer F	I				1.00
- Shop Supplies						ished			1.00
65				Napagold	Air Filter				1.00
				Pintle Pin	W/chain				1.00
				Shop Sup	plies				1.00
Hours	s 4.00		Labor:	240.00	Parts:	61.43	Total:	301.43	
1410509 ABS light on.C	Meter: Check traile	31358 er plug wiring.		I	n Date:	10/21/2014	Closed:	10/31/20	014
bs light.c1145 8	k c1234.re	place defectiv	e right	Parts List	t				Qty
			U	Abs Sense	or				1.00
	ace corrod	ed connector	and	Female C	onn Sock	et			1.00
				Stg Whee	l Cov - Fo	ord			1.00
es				•					1.00
				Shop Sup	•				1.00
	0 4 50		Labor:	270.00		114.13	Total:	384.13	
Hours	5 4.50								
:		31358			n Date:	09/23/2014	Closed:	10/27/20	014
Hours : 1410693 damage to rea	Meter:	31358 tail gate & hit	ch, also ı		n Date: ts replace	09/23/2014 ed	Closed:	10/27/20	014
: 1410693	Meter: ar bumper,	tail gate & hit					Closed:	10/27/20	014
	ight is on sczn a int test trace rei canister and fo mbly purge valv ies Hour: 1406533 pm, suspension le pin on noise perform to frame is worr body shop for r ies Hour: 1410509 ABS light on Co bs light.c1145 &	aght is on sczn and found of int test trace remove and canister and foiund dama mbly purge valve clear coor ies Hours 6.00 : 1406533 Meter: pm, suspension shocks, le pin on noise perform pinpoint to frame is worn out told s body shop for repair ies Hours 4.00 : 1410509 Meter: ABS light on.Check trailer bis light.c1145 & c1234.rep ensor.clear codes and test trailer plug.replace corrod harness.	aght is on sczn and found code p0442 p int test trace remove and inspect all eva canister and foiund damage canister re- mbly purge valve clear code retest evap ies Hours 6.00 : 1406533 Meter: 28603 pm, suspension shocks, rattling while le pin on noise perform pinpoint test and foun to frame is worn out told supervisor to ta body shop for repair ies Hours 4.00 : 1410509 Meter: 31358 ABS light on.Check trailer plug wiring. bs light.c1145 & c1234.replace defective ensor.clear codes and test drive. trailer plug.replace corroded connector harness.	aght is on sczn and found code p0442 p055 int test trace remove and inspect all evap hose canister and found damage canister replace mbly purge valve clear code retest evap sys and ies Hours 6.00 Labor: 1406533 Meter: 28603 pm, suspension shocks, rattling while driving le pin on noise perform pinpoint test and found all to frame is worn out told supervisor to take body shop for repair ies Hours 4.00 Labor: 1410509 Meter: 31358 ABS light on.Check trailer plug wiring. bs light.c1145 & c1234.replace defective right ensor.clear codes and test drive. trailer plug.replace corroded connector and harness.	int test trace remove and inspect all evap hose canister and found damage canister replace mbly purge valve clear code retest evap sys and valve shop Sup lies Parts List Ch Cannis Valve Shop Sup Sup Shop Sup Sup Shop Shop Shop Shop Shop Shop Shop Sho	int test trace remove and inspect all evap hose canister and found damage canister replace mbly purge valve clear code retest evap sys and bly purge valve clear code retest evap sys and so the second system of	In test trace remove and inspect all evap hose canister and found damage canister replace mbly purge valve clear code retest evap sys and more supervised retest evap sys and the supervise of the s	ght is on scan and found code p0442 p055 int test trace remove and inspect all evap hose canister and found damage canister replace mbly purge valve clear code retest evap sys and ies Parts List Ch Cannister Filter Valve Shop Supplies ies Hours 6.00 Labor: 360.00 Parts: 171.71 Total: 1406533 Meter: 28603 In Date: 07/02/2014 Closed: pm, suspension shocks, rattling while driving Parts List Napagold Oil Filter Napa Quart 5w20 Washer FI Used Fire X Refurbished Napagold Air Filter Pintle Pin W/chain Shop Supplies ies Hours 4.00 Labor: 240.00 Parts: 61.43 Total: 1410509 Meter: 31358 In Date: 10/21/2014 Closed: ABS light on.Check trailer plug wiring. Parts List ABS light on.Check trailer plug wiring. Parts List Abs Sensor Female Conn Socket Stg Wheel Cov - Ford Electrical Tape Parts List	ght is on sczn and found code p0442 p055 int test trace remove and inspect all evap hose canister and foiund damage canister replace holy purge valve clear code retest evap sys and Parts List Ch Cannister Filter Valve Shop Supplies Hours 6.00 Labor: 360.00 Parts: 171.71 Total: 531.71 1406533 Meter: 28603 In Date: 07/02/2014 Closed: 07/17/20 1406533 Meter: 28603 In Date: 10/21/2014 Closed: 10/11/20 Ise Hours 4.00 Labor: 240.00 Parts: 61.43 Total: 301.43 1410509 Meter: 31358 In Date: 10/21/2014 Closed: 10/31/20 ABS light on.Check trailer plug wiring. bs Sensor Female C

1411086	Meter:	31590			In Date:	11/05/2014	Closed:	12/04/20	014
remove stro	be bars fron	t and back							
el tank with	tool box and	wire aux fuel	tank	Parts Lis	t				Qty
nationate II at an	ha liakta fra	الماجا والمشيد م	م بم جا	Napa Tra	ns Filter				1.00
		n wind shield :	and	Shop Sup	plies				1.00
nt test remo	ve dash pane ule and fouin	els trace wire l	harness						
es									
Ho :	ours 19.50		Labor:	1,170.0 0	Parts:	6.79	Total:	1,176.79	9
1500054 plug in l/rea	Meter: ar tire	33903			In Date:	01/05/2015	Closed:	01/09/20	015
n hole in Ir tir	re mount bala	ance add n2		Parts Lis	t				Qty
- Shop Supplies				Shop Sup	plies				1.00
Ho	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
1500325 pm, straigh	Meter: ten bumper	33988			In Date:	01/09/2015	Closed:	01/22/20	015
				Parts Lis	t				Qty
filter				Napagold Oil Filter					
oumper				Napa Qua	art 5w20				7.00
es				Washer F	1				1.00
				Napagold	Fuel Filte	r			1.00
				20" Wiper	Blade				2.00
				Shop Sup	plies				1.00
Hc :	ours 5.25		Labor:	315.00	Parts:	53.53	Total:	368.53	
		36439			In Date:	03/16/2015	Closed:	03/20/20	015
1502703 left rear turr	Meter: n signal out	00100							
				Parts Lis	t				Qty
left rear turr				Parts Lis Bulb	t				Qty 1.00
	remove stro el tank with reinstall stro window tinti king ck and nt test remo ox gem modu wire harnes es <u>Ho</u> 1500054 plug in l/rea hole in lr tir es <u>Ho</u> 1500325 pm, straight filter oumper es	remove strobe bars from el tank with tool box and reinstall strobe lights from window tinting king ck and found ac cor nt test remove dash pane ox gem module and found wire harness es Hours 19.50 : 1500054 Meter: plug in l/rear tire hole in Ir tire mount bala es Hours 1.00 : 1500325 Meter: pm, straighten bumper	remove strobe bars front and back el tank with tool box and wire aux fuel a reinstall strobe lights from wind shield window tinting king ck and found ac controller not wor nt test remove dash panels trace wire for ox gem module and fouind broken wire wire harness es Hours 19.50 : 1500054 Meter: 33903 plug in l/rear tire hole in Ir tire mount balance add n2 es Hours 1.00 : 1500325 Meter: 33988 pm, straighten bumper filter bumper es	remove strobe bars front and back el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting thing ck and found ac controller not working nt test remove dash panels trace wire harness ox gem module and fouind broken wire in wire harness es Hours 19.50 Labor: 1500054 Meter: 33903 plug in l/rear tire hole in Ir tire mount balance add n2 es Hours 1.00 Labor: 1500325 Meter: 33988 pm, straighten bumper filter pumper es	remove strobe bars front and back el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting king ck and found ac controller not working nt test remove dash panels trace wire harness res Hours 19.50 Labor: 1,170.0 0 1500054 Meter: 33903 plug in l/rear tire Hours 1.00 Labor: 60.00 Hours 1.00 Labor: 60.00 Hours 1.00 Charler: 33988 pm, straighten bumper Parts Lis filter Napagold 20" Wiper Shop Sup	remove strobe bars front and back el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting fiting ck and found ac controller not working nt test remove dash panels trace wire harness wx gem module and fouind broken wire in wire harness es Hours 19.50 Labor: 1,170.0 Parts: 0 In Date: Parts List Napa Trans Filter Shop Supplies In Date: Parts List Shop Supplies In Date: In Date: Parts List Shop Supplies In Date: Parts List Napagold Oil Filter Napagold Fuel Filte 20" Wiper Blade Shop Supplies	remove strobe bars front and back el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting tking ck and found ac controller not working nt test remove dash panels trace wire harness ax gem module and fouind broken wire in wire harness es Hours 19.50 Hours 19.50 Hours 1.00 Hours 1.	remove strobe bars front and back el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting king ck and found ac controller not working nt test remove dash panels trace wire harness wire move dash panels trace wire harness wire harness wire move dash panels trace wire harness wire harness wire move dash panels trace wire harness wire harness wire harness wire move dash panels trace wire harness wire harness wire harness wire harness wire move dash panels trace wire harness	remove strobe bars front and back el tank with tool box and wire aux fuel tank el tank with tool box and wire aux fuel tank reinstall strobe lights from wind shield and window tinting tking ck and found ac controller not working nt test remove dash panels trace wire harness ws gem module and fouind broken wire in wire harness es Hours 19.50 Hours 19.50 Hours 19.50 Hours 19.50 Hours 10.0 Hours 10.0 Hours 1.00 Hours Hours Hours

Workorder: Problem:	1505396 P.M.SERICE,	Meter: HITCH PII	39243 N			In Date:	05/29/2015	Closed:	06/04/2015
- pm					Parts Lis	st			Qt
- pintle pin re	place					d Oil Filter			1.0
- repair 3rd bi					5w20 En				8.0
- svc aux fuel	-					e X Refurb	ished		1.0
- Shop Suppli	ies				Napagolo	d Air Filter			1.0
						n W/chain			1.0
					Bulb				1.0
					Napa Tra	ans Filter			1.0
						art 5w20			8.0
					Shop Su				1.0
	Houi :	rs 4.50		Labor:	270.00		92.87	Total:	362.87
Workorder: Problem:	1507811 wont starT	Meter:	41715			In Date:	08/05/2015	Closed:	08/11/2015
- ck and repla	ace bad battery	battery pr	ovided by na	pa nc					
	Hour	rs 0.75		Labor:	45.00	Parts:	0.00	Total:	45.00
Workorder: Problem:	1509536 P.M.SERVICI	Meter: E,INSTALI	44258 POWER IN	VERTER,I	_/BRAKE	In Date: LIGHT/TUI	09/22/2015 RN SIGNAL C	Closed: DUT.	09/30/2015
- pm					Parts Lis	st			Qt
- svc aux fuel	tank				Napagolo	d Oil Filter			1.0
- repair left re	ar brake lights				Napa Qu	art 5w20			8.0
- install invert	er				Napagolo	d Fuel Filte	r		1.0
- install hows	my driving dec	al			Washer I	Fluid Conc	entr		1.0
- Shop Suppli	ies				Wiper Bla	ade			2.0
					Mac Wite	e Lithium G	ires		1.0
					Used Fire	e X Refurb	ished		1.0
					Napa Tra	ans Filter			1.0
					Bulb				1.0
					Bulk Batt	tery Cable			40.0
					Cabl/lug				20.0
					Cb185-1	00 Cir Brkr			2.0
					Shop Su	pplies			1.0
	Houi :	rs 7.50		Labor:	450.00	Parts:	309.97	Total:	759.97
Workorder: Problem:	1512033 steering whee	Meter: el cover	47761			In Date:	11/30/2015	Closed:	12/03/2015
- steering whe	eel cover instal	l new stee	ring wheel co	ver	Parts Lis	st el Cov - Fc	ard		Qt 1.0
	11-	0.05		ا ماه ما				Tatal	
	Houi :	rs 0.25		Labor:	15.00	Parts:	16.74	i otal:	31.74

	1600317 pm, left rear t	Meter:	49655			In Date:	01/11/2016	Closed:	01/22/20	16
- pm	F,				Parts Lis	t				Qty
-	lat verify needs	s 4 tires rr 4	4 tires mount l	balance	Napagold	Oil Filter				1.00
add n2	···· · · · · · · · · · · · · · · · · ·				Napa Qua					8.00
- svc aux fuel	system				•)2 Lt245-7	5r17			4.00
- Shop Suppli	ies				Napa Tra					1.00
					Shop Sup					1.00
					Tire Dispo	•				4.00
	Hou	rs 5.75		Labor:	345.00		1,052.16	Total:	1,397.16	
	:		54054				00/05/0040	<u> </u>		4.0
Workorder: Problem:	1603172 tail light drive	Meter: r side	51854			In Date:	03/25/2016	Closed:	03/29/20	16
- repair left br	ake light				Parts Lis	t				Qty
					Bulb					1.00
	Hou	rs 0.50		Labor:	30.00	Parts:	0.78	Total:	30.78	
Workorder: Problem:	1606171 Pm service.	Meter:	55105			In Date:	06/15/2016	Closed:	06/29/20	16
- Pm service.					Parts Lis	t				Qty
- Service aux	iliary fuel tank.	replace filte	er.		Air Filter					1.00
- Replace thir		Napagold	I Fuel Filte	r			1.00			
- Rotate and	balance all fou	r tires.			Napagold	Oil Filter				1.00
- C/c Install s	econd tool box	install tool	box provided	by Wud.	Napa Qua	art 5w20				8.00
- Shop Suppl					Washer F	luid Conce	entr			1.00
					20" Wipeı	r Blade				2.00
					Napa Tra					1.00
					Bulb					1.00
							Front Susp			
					Ball Joint	- Upper - I	TUIL Susp			
					Ball Joint Ball Jnt	- Upper - I	Tont Susp			2.00 2.00
					Ball Jnt		Tont Susp			2.00 2.00
					Ball Jnt Wd40 160	DZ	Tont Susp			2.00
	Hou	rs 7.00		Labor:	Ball Jnt	oz oplies	299.15	Total:	719.15	2.00 2.00 1.00
	Hou : 1607967 I/rear tail light	Meter:	56188	Labor:	Ball Jnt Wd40 160 Shop Sup 420.00	oz oplies		Total: Closed:	719.15 08/04/20	2.00 2.00 1.00 1.00
Problem:	: 1607967 I/rear tail light	Meter: t bulb	56188	Labor:	Ball Jnt Wd40 160 Shop Sup 420.00	oz oplies Parts: In Date:	299.15			2.00 2.00 1.00 1.00
	: 1607967	Meter: t bulb	56188	Labor:	Ball Jnt Wd40 160 Shop Sup 420.00 Parts Lis	oz oplies Parts: In Date:	299.15			2.00 2.00 1.00 1.00
Problem:	: 1607967 I/rear tail light ear Tail Light B	Meter: t bulb	56188	Labor: Labor:	Ball Jnt Wd40 166 Shop Sup 420.00 Parts Lis Bulb	oz oplies Parts: In Date:	299.15 08/03/2016	Closed:		2.00 2.00 1.00 1.00
Problem: - Replace L/re Workorder:	: 1607967 I/rear tail light ear Tail Light B	Meter: t bulb Bulb. rs 0.25 Meter:	58967		Ball Jnt Wd40 166 Shop Sup 420.00 Parts Lis Bulb 15.00	oz oplies Parts: In Date: t	299.15 08/03/2016	Closed:	08/04/20	2.00 2.00 1.00 1.00
Problem: - Replace L/re Workorder: Problem:	: 1607967 I/rear tail light ear Tail Light B Hou : 1610789 Ac blower 1st	Meter: t bulb Bulb. rs 0.25 Meter: t speed ino	58967 p.	Labor:	Ball Jnt Wd40 166 Shop Sup 420.00 Parts Lis Bulb 15.00	oz oplies Parts: In Date: t Parts: In Date:	299.15 08/03/2016 0.78	Closed: Total:	08/04/20	2.00 2.00 1.00 1.00 16 Qty 1.00
Problem: - Replace L/re Workorder: Problem: - Test And Re	: 1607967 I/rear tail light ear Tail Light B Hou : 1610789 Ac blower 1st	Meter: t bulb Bulb. rs 0.25 Meter: t speed ino	58967 p.	Labor:	Ball Jnt Wd40 166 Shop Sup 420.00 Parts Lis Bulb 15.00 Parts Lis	oz oplies Parts: In Date: t Parts: In Date: t	299.15 08/03/2016 0.78	Closed: Total:	08/04/20	2.00 2.00 1.00 1.00 16 Qty 16 Qty
Problem: - Replace L/re Workorder: Problem:	: 1607967 I/rear tail light ear Tail Light B Hou : 1610789 Ac blower 1st	Meter: t bulb Bulb. rs 0.25 Meter: t speed ino	58967 p.	Labor:	Ball Jnt Wd40 166 Shop Sup 420.00 Parts Lis Bulb 15.00	oz oplies Parts: In Date: t Parts: In Date: t esistor	299.15 08/03/2016 0.78	Closed: Total:	08/04/20	2.00 2.00 1.00 1.00 16 Qty 1.00

	adlight asse ht bulb. y fuel tank.r rear brake pads.	embly. replace filte	er and test.		Parts Lis Napagolo Napa Qua 20" Wipe Washer F Halogen	d Oil Filter art 5w20 r Blade				Qty 1.00 8.00
 Replace cab light Service auxiliary Verify needs for calipers.r/r brake p Shop Supplies 	ht bulb. y fuel tank.r rear brake pads.	eplace filte			Napa Qua 20" Wipe Washer F	art 5w20 r Blade				1.00
 Replace cab light Service auxiliary Verify needs for calipers.r/r brake p Shop Supplies 	ht bulb. y fuel tank.r rear brake pads.	eplace filte			Napa Qua 20" Wipe Washer F	art 5w20 r Blade				
- Service auxiliary - Verify needs for calipers.r/r brake p - Shop Supplies Workorder: 170	y fuel tank.r · rear brake pads.	•			20" Wipe Washer F	r Blade				
- Verify needs for calipers.r/r brake p - Shop Supplies Workorder: 170	rear brake pads.	•			Washer F					2.00
calipers.r/r brake p - Shop Supplies Workorder: 170	pads.	P					entr			1.00
Workorder: 17	Hour									1.00
	Hour				Napa Tra					1.00
	Hour				Disc Brak					1.00
	Hour				Shop Sup					1.00
		s 9.50		Labor:	570.00	•	123.97	Total:	693.97	
Problem: De	01383 ead battery.	Meter:	59503			In Date:	02/09/2017	Closed:	02/21/20	017
- Test starting and provided by Napa		system.rep	place bad batte	əry						
		s 0.75		Labor:	45.00	Parts:	0.00	Total:	45.00	
Workorder: 17 Problem: rer	01423 move cance	Meter: eiver	59503			In Date:	02/10/2017	Closed:	02/14/20	017
- Remove Cancei	iver				Parts Lis	st				Qty
- Shop Supplies					Shop Sup	oplies				1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: 17 Problem: PM	09796 /I Service	Meter:	62954			In Date:	10/05/2017	Closed:	10/18/20	017
- Pm Service					Parts Lis	st				Qty
- Service auxiliary	y fuel tank.				Napagolo		1.00			
- Repair both hea	adlights				Napa Qu		8.00			
- Repair utility be	•				20" Wipe			2.00		
- Install how is my	-	cker.			Washer F	-luid Conce	entr			1.00
- Shop Supplies	, 0				Used Fire			1.00		
					Napa Tra	ns Filter				1.00
					Halogen					2.00
					Bulb					3.00
					Shop Sup	oplies				1.00
	Hour	s 7.00		Labor:	420.00	•	91.97	Total:	511.97	
Workorder: 17 Problem: DE	11790 EAD BATTE	Meter:	63066			In Date:	12/01/2017	Closed:	12/11/20	017
- Replace bad ba			jing system.		Parts Lis	st				Qty
- Repair and bala	-	-			Battery					1.00
- Shop Supplies					Shop Sup	oplies				1.00
ench eabbling	Hour	s 1.75		l abor:	105.00	•	130.64	Total	235.64	
	:	0 1110			100.00			i otal.	200.04	

Workorder:1803851Meter:64934Problem:PM Service.Dead battery in WUD Parking lot.	In Date: 04/13/2018 Closed:	04/23/2018
- Pm Service and replace brake pedal pad.	Parts List	Qty
- Replace missing pintle pin with chain and tighten hitch ball.	Napagold Air Filter	1.00
- Replace left brake lamp assembly and both brake lamp	Used Fire X Refurbished	1.00
bulbs.	Napagold Oil Filter	1.00
- Service auxilliary fuel tank and replace filter	Napa Quart 5w20	8.00
- Replace both front brake calipers, pads, seals and cut two	Drain Plug	1.00
rotors.repack wheel bearings.flush and bleed system.	Pedal Pad	1.00
- Jump start vehicle in Wud parking lot.fully recharge and load test battery.tested Ok at this time.	20" Wiper Blade	2.00
- Rotate and balance four tires.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Pintle Pin W/clip	1.00
	Boxed Miniatures	2.00
	Napa Trans Filter	1.00
	Pads	1.00
	Wheel Seal - Front Wheel	2.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Non-chlor Brake Clnr	1.00
	Lamp Asy	1.00
	Shop Supplies	1.00
Hours 12.50 Labor:	750.00 Parts: 402.83 Total:	1,152.83
Workorder: 1809164 Meter: 66622 Problem: PM Service.Check rear suspension.	In Date: 09/06/2018 Closed:	09/18/2018
- Pm Service	Parts List	Qty
- Service auxiliary fuel tank.	Napa Quart 5w20	8.00
- Check rear for noise.bad shock bushings.replace both rear	Napagold Oil Filter	1.00
shocks.	Washer Fluid Concentr	1.00
- Repair right headlamp.	22" Wiper Blade	2.00
- Shop Supplies	Napa Trans Filter	1.00
	Gas Grande Shock	2.00
	Halogen Sealed Beams	1.00
	Shop Supplies	1.00
Hours 5.75 Labor:	345.00 Parts: 175.36 Total:	520.36
Workorder: 1809633 Meter: 66685 Problem: REMOVE INVERTER, SADDLE TANK, TOOL	In Date: 09/18/2018 Closed: BOX.	
- Hours 0.00 Labor:	0.00 Parts: 0.00 Total:	0.00

Workorder: Problem:	1809674 REMOVE IN	Meter: IVERTER, S	66685 SADDLE	TANK,TOOL	BOX.	In Date:	09/19/2018	Closed:	09/28/2018
 Remove auxiliary fuel tank.tool box.inverter and computer stand.reseal computer stand mounting hole Clean debris from vehicle to access bolts Shop Supplies 						ist ra Black 302 upplies	Qty 1.00 1.00		
		urs 5.00		Labor:	300.00	Parts:	10.12	Total:	310.12
Workorder: Problem:	1809875 Transition P	Meter: rep Charge	66622			In Date:	09/25/2018	Closed:	09/25/2018
- Transition P		0.00			100.00			-	100.00
	Hou :	urs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00