10166700 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid, Silver

Workorder:	737659	Meter:	•			In Date:	04/25/2007	Closed:	04/25/20	07
Problem:	PRE-DE	LIVERY INSPE	CTION							
- Pre-delivery	<sup>'</sup> Inspectio	n								
		Hours 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	743548 P.M. SE	Meter: RVICE.	5355			In Date:	09/04/2007	Closed:	09/10/20	07
- Pm Service					Parts Lis	st				Qty
- Nitro Servic	е				Shop Su	pplies				1.00
- Service Rea			Ph4967	Oil Filter Lb	f Ph2840 Wix	51394		1.00		
- Shop Suppl	ies				10020 In	jector Clea	ner Don't Red	order		1.00
					5w20 En	gine Oil				4.00
		Hours 4.00		Labor:	220.00	Parts:	22.12	Total:	242.12	
Workorder: Problem:	832540 FRONT	Meter: BRAKES GRIN	6291 DING.			In Date:	01/09/2008	Closed:	01/14/20	08
Frt Rotors Cle	an Pads.9	akes.remv Frt C 90% Of Brake P			Parts Lis Shop Su					<b>Qty</b> 1.00
Brakes And Ir - Shop Suppl	-	usı								
- Onop Ouppi	163	Hours 2.50		Labor:	150.00	Parts:	2.00	Total:	152.00	
Workorder:		:								
workorder.	836760	Meter:	9420			In Date:	04/09/2008	Closed:	04/11/20	80
Problem:			9420			In Date:	04/09/2008	Closed:	04/11/20	80
			9420		Parts Lis		04/09/2008	Closed:	04/11/20	08 <b>Qty</b>
Problem: - Pm Service	P.M SEF			Brakes.	Parts Lis	st	04/09/2008	Closed:	04/11/20	
Problem: - Pm Service - Service Rea	P.M SEF ar Brakes.i	RVICE	Adjust Rear		Shop Su	<b>st</b> pplies	04/09/2008 of Ph2840 Wix		04/11/20	Qty
Problem: - Pm Service - Service Rea	P.M SEF ar Brakes.i gh Speed	RVICE inspect,clean &	Adjust Rear		Shop Su	<b>st</b> pplies Oil Filter Lb			04/11/20	<b>Qty</b> 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed	RVICE inspect,clean &	Adjust Rear		Shop Su Ph4967 5w30 Oil	<b>st</b> pplies Oil Filter Lb		: 51394	04/11/20	<b>Qty</b> 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed	RVICE inspect,clean &	Adjust Rear		Shop Su Ph4967 5w30 Oil Nb-18 V	<b>st</b> pplies Oil Filter Lb l Viper Blade	of Ph2840 Wix	: 51394	04/11/20	<b>Qty</b> 1.00 1.00 4.00
Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed	RVICE inspect,clean &	Adjust Rear	Tires.	Shop Su Ph4967 5w30 Oil Nb-18 V	<b>st</b> pplies Oil Filter Lb l Viper Blade	of Ph2840 Wix s 18" Anco 3 s 24" Blade	: 51394 1-18	04/11/20 266.76	<b>Qty</b> 1.00 1.00 4.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed ies	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter:	Adjust Rear	Tires.	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W	<b>st</b> pplies Oil Filter Lb Viper Blade /iper Blades	of Ph2840 Wix s 18" Anco 3 s 24" Blade	: 51394 1-18		<b>Qty</b> 1.00 1.00 4.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl	P.M SEF ar Brakes.i gh Speed ies	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter:	Adjust Rear ïres.nitro Fill	Tires.	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W	st pplies Oil Filter Lb Viper Blade Viper Blades Parts:	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76	: 51394 1-18 Total:	266.76	<b>Qty</b> 1.00 1.00 4.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem:	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter:	Adjust Rear ïres.nitro Fill	Tires.	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W 240.00	st pplies Oil Filter Lb Viper Blade /iper Blades Parts: In Date:	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76	: 51394 1-18 Total:	266.76	Qty 1.00 1.00 4.00 1.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes.	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter:	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 5w30 Oil Nb-18 W 31-24 W 240.00 Parts Lis Shop Su	st pplies Oil Filter Lb Viper Blade Viper Blades Parts: In Date: st pplies	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76	1-18 Total:	266.76	Qty 1.00 1.00 4.00 1.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes. Speed Ba	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter: RVICE	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W 240.00 Parts Lis Shop Su Ca9501	pplies Oil Filter Lb Viper Blade Viper Blade Parts: In Date: st pplies Air Filter W	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76 09/05/2008	51394 1-18 Total: Closed:	266.76	Qty 1.00 1.00 4.00 1.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes. Speed Ba	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter: RVICE	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W 240.00 Parts Lis Shop Su Ca9501	st pplies Oil Filter Lb Viper Blade Viper Blades Parts: In Date: st pplies Air Filter W Oil Filter Lb	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76 09/05/2008	51394 1-18 Total: Closed:	266.76	Qty 1.00 1.00 4.00 1.00 1.00 08 Qty 1.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes. Speed Ba	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter: RVICE	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W 240.00 Parts Lis Shop Su Ca9501 Ph4967 5w30 Oil	pplies Oil Filter Lb Viper Blade Viper Blade Parts: In Date: st pplies Air Filter W Oil Filter Lb	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76 09/05/2008	Total:  Closed:  \$ 01-03 \$ 51394	266.76	Qty 1.00 1.00 1.00 1.00 08 Qty 1.00 1.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes. Speed Ba	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter: RVICE	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 9 5w30 Oil Nb-18 W 31-24 W 240.00 Parts Lis Shop Su Ca9501 9 Ph4967 9 5w30 Oil Nb-18 W	st pplies Oil Filter Lb Viper Blade Viper Blades Parts: In Date: st pplies Air Filter W Oil Filter Lb	of Ph2840 Wixes 18" Anco 3 as 24" Blade 26.76  09/05/2008  ix 42306 Prius of Ph2840 Wixes 18" Anco 3	Total:  Closed:  \$ 01-03 \$ 51394	266.76	Qty 1.00 1.00 1.00 1.00 1.00 08 Qty 1.00 1.00 1.00 4.00
Problem: - Pm Service - Service Rea - Rotate & Hi - Shop Suppl  Workorder: Problem: - Pm Service - Service Rea - Rotate & Hi	P.M SEF ar Brakes.i gh Speed ies 843828 P.M SEF ar Brakes. Speed Ba	RVICE inspect,clean & Balance All 4 T  Hours 4.00 : Meter: RVICE	Adjust Rear ires.nitro Fill 15236	Tires.  Labor:	Shop Su Ph4967 5w30 Oil Nb-18 V 31-24 W 240.00 Parts Lis Shop Su Ca9501 Ph4967 5w30 Oil Nb-18 V 31-24 W	pplies Oil Filter Lb Viper Blade Viper Blade: Parts: In Date: st pplies Air Filter W Oil Filter Lb Viper Blade	of Ph2840 Wix s 18" Anco 3 s 24" Blade 26.76 09/05/2008 ix 42306 Prius of Ph2840 Wix	Total:  Closed:  \$ 01-03 \$ 51394  1-18	266.76	Qty 1.00 1.00 1.00 1.00 1.00 08  Qty 1.00 1.00 1.00 1.00 1.00

:

Workorder: Problem:	844431 003 WASH TI	Meter: CKETS IS	0 SUED OUT (	09/12/08		In Date:	09/12/2008	Closed:	09/19/200	)8
- 003 Wash T	ickets Issued (	Out 09/12/	08							
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	934305 PM SERVICE	Meter:	19540			In Date:	02/23/2009	Closed:	03/03/200	)9
- Pm Service					Parts L	ist				Qty
- Service Rear Brakes.						upplies				1.00
- Shop Suppli	es						of Ph2840 Wix	51394		1.00
					5w30 O	il				4.00
	Hour :	s 3.00		Labor:	180.00	Parts:	16.27	Total:	196.27	
Workorder: Problem:	942881 P.M service.	Meter:	20774			In Date:	09/02/2009	Closed:	09/10/200	)9
- P.m service.					Parts L	ist				Qty
- Mount two n	ew tires, rotate	& balance	e all four tires.		Shop S		1.00			
- Service rear	drum brakes.				Ph4967		1.00			
- Alignment.					5w30 O	il				4.00
- Shop Suppli	es				5441 Clear Gel Lube Gel Guard (mantek)					1.00
					Nb-18 '	Wiper Blade	s 18" Anco 3	1-18		1.00
					31-24 \	Niper Blades	s 24" Blade			1.00
					852424	7010 Blade	Rear Wiper (t	oyota)		1.00
					402032	477 185/65	r15 Integrity I	Don't Reorde	er :	2.00
					Tire Dis	posal Fee				2.00
	Hour	s 7.50		Labor:	450.00	Parts:	185.89	Total:	635.89	
Workorder: Problem:	943862 Transition Pre	Meter: ep Charge	20774			In Date:	09/29/2009	Closed:	09/29/200	)9
- Transition P	rep Charge									
	Hour	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	945492 get ready for	<b>Meter:</b> reasignme	20774 nt to Utilities			In Date:	10/30/2009	Closed:	11/04/200	)9
- Repalce ded	cals, fuel, clear	and get re	eady for reass	ignment	Parts L	ist				Qty
- Shop Suppli	es				Shop S	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1002652 (silver) PM s	Meter: service, chec	24122 ck recalls			In Date:	03/15/2010	Closed:	03/30/20	010
- Pm Service					Parts Lis	t				Qty
- Replace Fro	nt Tires.				Shop Sup	plies				1.00
- Trouble Sho		System .			Ca9501 A	Air Filter W	/ix 42306 Priu	s 01-03		1.00
- Shop Suppli					Ph4967 C		1.00			
- Test run					10w30 M	otor Oil				4.00
					Nb-18 W	iper Blade	s 18" Anco 3	1-18		1.00
					31-24 W	iper Blade	s 24" Blade			1.00
					Tire Dispo	osal Fee				2.00
					40203247	77 185/65	r15 Integrity	Don't Reorde	er	2.00
	Hou :	urs 5.50		Labor:	330.00	Parts:	216.47	Total:	546.47	
Workorder: Problem:	1013304 P.M. SERVI	Meter: CE	27849			In Date:	12/02/2010	Closed:	12/14/20	010
- P. M.					Parts Lis	t				Qty
- Clean & adju	ust rear brake	s.			Shop Sup	plies				1.00
- Shop Suppli	es				Ph4967 Oil Filter Lbf Ph2840 Wix 51394					1.00
					09997 Bi	rake Clear	1			1.00
					5w30 Oil					4.00
					1066 Wh	ite Lithium	n (crc 05037)			1.00
	Hou :	urs 3.00		Labor:	180.00	Parts:	22.80	Total:	202.80	
Workorder: Problem:	1107014 2 - Wash ticl	Meter: ket(s) issued	31311 d			In Date:	07/01/2011	Closed:	07/01/20	011
- 2 - Wash tic	ket(s) issued									
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1107017	Meter:	31326			In Date:	07/01/2011	Closed:	07/14/20	011
Problem:	P. M., & Red	call (Electric	Hybrid Wate	r Pump Re	eplacemer	nt).				
- P. M. Servic	e.				Parts Lis	t				Qty
- Clean & adju	ust rear brake	s.			Shop Sup	plies				1.00
- Replace bac	ck door opene	er switch.			Ph4967 C	Dil Filter Lb	of Ph2840 Wix	c 51394		1.00
- Transport & Hybrid Water		le at dealer	for recall (ele	ectric		Air Filter W rake Clear	/ix 42306 Priu	s 01-03		1.00 1.00
- Shop Suppli	• /				5w30 Oil	iane Oledi	1			4.00
						ite Lithium	n (crc 05037)			1.00
							es 18" Anco 3	1-18		1.00
							s 16 Anco 3 s 24" Blade	1110		1.00
						r Opener				1.00
	Ног	urs 6.00		Labor:	360.00		108.21	Total:	468.21	1.00
		3.00				. 3.13.		. 0.01.		

Workorder: 1 Problem: P	200503 P. M. SERVIC	Meter: E & low ti	33867 re pressure li	ght on inte	ermittently	In Date:	01/17/2012	Closed:	01/27/20	012
- P. M. Service.					Parts Li	st				Qty
- Service rear b	rakes.				Shop Su			1.00		
- C/c: Tpms ligh	t on intermitt	ently. Veri	fy, all tires ar	eound 5	Ph4967	c 51394		1.00		
Psi low. Correct		, reset Tpn	ns light.		5w30 Oi	I				4.00
- Shop Supplies										
	Hour :	s 3.50		Labor:	210.00	Parts:	18.94	Total:	228.94	
Workorder: 1 Problem: p	207199 m, maint ligh	Meter: It on, low ti	36570 re pressure l	ight on		In Date:	08/01/2012	Closed:	08/17/20	012
- pm					Parts Li	st				Qty
- ck tpms light o	n repair 4r ti	re dismour	nt patch mou	nt	Shop Su	upplies				1.00
balance add n2	_				Ph4967		1.00			
- svc rear brake					5w30 Oi	I				4.00
- Shop Supplies		s 4.00		l ahor:	240.00	Parts:	18 02	Total:	258.92	
	:	J 4.00		Labor.	240.00	i aito.	10.02	rotai.	200.02	
Workorder: 1 Problem: re	300474 ecall	Meter:	38068			In Date:	01/14/2013	Closed:	01/18/20	013
- transport and p	pick up vehic	le at deale	r for recall st	eering	Parts Li	st				Qty
extension shaft - Shop Supplies	3				Shop Su	ıpplies				1.00
	Hour :	s 1.50		Labor:	90.00	Parts:	2.00	Total:	92.00	
Workorder: 1 Problem: p	306068 m	Meter:	39629			In Date:	06/18/2013	Closed:	06/27/20	013
- pm					Parts Li	st				Qty
- svc rear drum	brakes				Ph4967	Oil Filter Lb	f			1.00
- verify tpms ligh	ht on remove	tire patch	mount balan	ice add	Napa Qı	uart 5w30				5.00
n2					Shop Su	upplies				1.00
- Shop Supplies										
	Hour :	s 4.00		Labor:	240.00	Parts:	25.90	Total:	265.90	
Workorder: 1 Problem: 1	306577 - Detail Veh	Meter: icle Wash	39629 Ticket(s) Issi	ued		In Date:	07/01/2013	Closed:	07/01/20	013
- 1 - Detail Vehi	cle Wash Tid	ket(s) Issu	ied							
	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Problem:	1312295 pm, vehicle v	Meter: will not start	40753 t , ck engine iç	ght is on	lı	n Date:	12/10/2013	Closed:	12/17/20	)13
- pm					Parts List					Qty
- clean and ad	j rear brakes				Napa Qua	rt 5w30				5.00
- replace batte	ry				Napagold	Oil Filter				1.00
- ck engine ligh	ht is on scan	and found	no codes ck ε	engine	31-24 Wip	er Blade	s 2			1.00
light was not or		ehicle 50 m	iles and was	unable to	Wiper Blad	de				1.00
verify ck at this					Brake Clea	aner				1.00
- Shop Supplie	<del>,</del> 5				Agm Batte	ry				1.00
					Shop Supp	olies				1.00
	Ηοι :	urs 5.75		Labor:	345.00	Parts:	257.03	Total:	602.03	
	1312722 no start, nee	Meter: eds pm	40753		lı	n Date:	12/10/2013	Closed:	12/20/20	)13
- Tow From: 90	045 jog rd bo	ynton To:	sr delray							
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1408072 pm	Meter:	42393		lı	n Date:	08/14/2014	Closed:	08/19/20	)14
- pm					Parts List					Qty
- svc and adj d	drum brakes				Napagold	Oil Filter				1.00
- Shop Supplie	es				Napa Qua	rt 5w30				5.00
					Shop Supp	olies				1.00
	Hou	urs 3.00		Labor:	180.00	Parts:	24.59	Total:	204.59	
	1501614 TOWED IN V	<b>Meter:</b> WITH FLAT	43284 TIRE, PM S\	VΕ	lı	n Date:	02/12/2015	Closed:	02/26/20	)15
- nm					Parts List					O41
PIII										Qty
- svc rear brak	e drums				Napagold					1.00
-	e drums				Napagold Napagold	Air Filter				-
- repair fr tire						Air Filter Oil Filter				1.00
<ul><li>svc rear brak</li><li>repair fr tire</li></ul>					Napagold	Air Filter Oil Filter rt 5w30				1.00
<ul><li>svc rear brak</li><li>repair fr tire</li></ul>					Napagold Napa Qua	Air Filter Oil Filter rt 5w30 per Blade				1.00 1.00 4.00
<ul><li>svc rear brak</li><li>repair fr tire</li></ul>					Napagold Napa Qua 31-24 Wip	Air Filter Oil Filter rt 5w30 oer Blade de				1.00 1.00 4.00 1.00
- svc rear brak					Napagold Napa Qua 31-24 Wip Wiper Blad	Air Filter Oil Filter rt 5w30 oer Blade de ar				1.00 1.00 4.00 1.00
<ul><li>svc rear brak</li><li>repair fr tire</li></ul>					Napagold Napa Qua 31-24 Wip Wiper Blad Accufit Re	Air Filter Oil Filter rt 5w30 per Blade: de ar				1.00 1.00 4.00 1.00 1.00
<ul><li>svc rear brak</li><li>repair fr tire</li></ul>	es	urs 4.00		Labor:	Napagold Napa Qua 31-24 Wip Wiper Blac Accufit Re Washer Fl	Air Filter Oil Filter rt 5w30 per Blades de ar		Total:	285.77	1.00 4.00 1.00 1.00 1.00 1.00
- svc rear brak - repair fr tire - Shop Supplie	es	Meter:	43045	Labor:	Napagold Napa Qua 31-24 Wip Wiper Blac Accufit Re Washer Fl Shop Supp 240.00	Air Filter Oil Filter rt 5w30 per Blades de ar	s 2	Total:	285.77	1.00 1.00 4.00 1.00 1.00 1.00 1.00
- svc rear brak - repair fr tire - Shop Supplie	Hou : 1501645 flat tire and p	Meter: om svc		Labor:	Napagold Napa Qua 31-24 Wip Wiper Blac Accufit Re Washer Fl Shop Supp 240.00	Air Filter Oil Filter rt 5w30 per Blades de ar plies Parts:	s 2 45.77			1.00 1.00 4.00 1.00 1.00 1.00 1.00

Workorder:	1508761 PM, TIRE LIG	Meter:	43785			In Date:	09/01/2015	Closed:	09/08/20	)15
- pm	T WI, TINE LIO	111 10 011			Parts Li	ist				Qty
-	tires replace 4	tires mou	nt hlanace add	d n2	Napagold Oil Filter					1.00
- rear brake d	•	tires mou	it biariace au	u IIZ	Napa Q		4.00			
- Shop Suppli					7385235			4.00		
- Shop Suppli	<b>C</b> 3						5115			1.00
					Shop Su					
	Hours	s 5.00		Labor:	300.00	posal Fee Parts:	506.05	Total:	806.05	4.00
Workorder:	1602076	Meter:	44464			In Date:	02/29/2016	Closed:	03/14/20	16
	P.M. Service.			etail.		iii Date.	02/20/2010	Olosca.	00/14/20	, 10
- Pm service.					Parts Li	ist				Qty
	agnose for che				Napa Q	uart 5w30				4.00
	and P0302.four injector wires a			e by	Napago	ld Oil Filter				1.00
•	st and inspect c			lofoctivo	Wiper Blades 24"					1.00
					18" wip		1.00			
engine water pump and thermostat due to coolant leak.relace drive belt.flush and replace coolant.					Accufit F	Rear			1.00	
- Inspect and	service rear bra	akes.			Napa Ca	abin Air Filte	er			1.00
- Rotate and b	oalance all four	tires.			Washer	Fluid Conce	entr			1.00
- Shop Suppli	es				Vinyl Electrical Tape					1.00
					Water P	•				1.00
					Thermos	•				1.00
					Toyota (	Coolant				2.00
					V-ribbed					1.00
					Gasket					1.00
					Shop Su	ınnlies				1.00
	Hour	s 13.00		Labor.	780.00	• •	257.53	Total·	1,037.53	
	:			Labor.	700.00	- arto.		Total.		
Workorder: Problem:	1602506 1 - Detail Vehi	<b>Meter:</b> cle Wash	44431 Ticket(s) Issu	ed		In Date:	03/09/2016	Closed:	03/09/20	)16
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	ed							
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1610394 P.M. Service.	Meter:	45696			In Date:	10/04/2016	Closed:	10/20/20	)16
- P.m. Service	э.				Parts Li	ist				Qty
- Rotate and I	palance all tires				Napa Q	uart 5w30				4.00
- Service and	adjust rear bra	kes.			Napago	ld Oil Filter				1.00
- Straighten b shield.	racket and sec	ure uder s	de engine spl	lash		lades 24"				1.00
- Shop Suppli	es					er blades				1.00
op - oappii		- 5.00		1 -1	Shop Su		00.44	<del>-</del>	000 11	1.00
	Hours	s 5.00		Labor:	300.00	Parts:	26.41	I otal:	326.41	

Workorder: 161060 Problem: 1 - Deta		45541 Ficket(s) Issue	ed		In Date:	10/13/2016	Closed:	10/13/2016	
- 1 - Detail Vehicle Wa	ash Ticket(s) Issu	ed							
	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: 170508 Problem: P.M. se		47094 andle broken	and disp		In Date: nd detail.	05/23/2017	Closed:	06/13/2017	
- P.m. service				Parts Lis	t			Qty	
- Remove liftgate trim				Napa Qua	art 5w30		4.00		
liftgate .display is sun l this time.	baked ,not cost ef	fective to replant	ace at	Napagold	Oil Filter			1.00	
- Rotate and balance	all four tires nitroc		Washer F	luid Conce	entr		1.00		
- Shop Supplies		,011 IIII ti100.		Wiper Bla			1.00		
				18" wipe				1.00	
				Accufit Re				1.00	
				Garnish S				1.00	
				Switch R			1.00		
	Hours 3.50		Labor:	Shop Sup 210.00	•	491.17	Total:	1.00 701.17	
Problem: 1 - Detail Vehicle Wa		` '	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: 171045 Problem: P.M. se		47598 ge center unre	adable a		In Date:	10/24/2017	Closed:	11/02/2017	
- P.m. service.				Parts Lis	t			Qty	
- Water leak check rea	ar trunk due to wa	ter inside.rem	ove	Napa Qua	art 5w30			4.00	
trunk panels and seal		s of roof chanr	nels due	Napagold	Oil Filter			1.00	
to cracks in seams.rete				Wiper Bla	ides 24"			1.00	
<ul> <li>Inspect and service</li> <li>Rotate and balance</li> </ul>				18" wipe	r blades			1.00	
		new		Accufit Re	ear			1.00	
- Shop Supplies	- Replace faded rear asset number with new.					Washer Fluid Concentr			
- σπορ σαρριίσο						J. 14.		1.00	
				Shop Sup				1.00	
	Hours 6.40 :		Labor:		plies	37.90	Total:		
Workorder: 171092 Problem: 1 - Deta	: 9 <b>Meter:</b>	47598 Ficket(s) Issue		Shop Sup 384.00	plies		Total:	1.00	
	: 9 <b>Meter:</b> ail Vehicle Wash	Ficket(s) Issue		Shop Sup 384.00	oplies Parts:	37.90		1.00 421.90 11/03/2017	

<b>Workorder:</b> 1803129 <b>Meter:</b> 4955	54	In Date:	03/26/2018	Closed:	05/21/2018
Problem: Intermittent dash board wont t	urn on and could	I not turn car off, TPI	MS light on.P.N	1. service.	
- Transport to and from dealer for cluster rep	lacement.	Parts List	Qty		
- P.m. service		Program		1.00	
- Clean and adjuste and inspect rear brakes	•	Washer Fluid Cond		1.00	
- Rotate and balance four tires and reset Tpr	ns light.	Wiper Blades 24"		1.00	
- Shop Supplies		18" wiper blades	1.00		
		14in Exactfit-rear	1.00		
		Napa Quart 5w30	4.00		
		Napagold Oil Filter	1.00		
		Shop Supplies			1.00
Hours 5.00	Labor:	300.00 Parts:	1,408.70	Total:	1,708.70
Workorder: 1812142 Meter: 5155 Problem: Transition Prep Charge	58	In Date:	11/28/2018	Closed:	11/28/2018
- Transition Prep Charge					
Hours 2.00	Labor:	134.00 Parts:	0.00	Total:	134.00