10169601 2008 FORD E350 Van, Cargo, 1 Ton W/R. Step Bumper

Workorder: Problem:	745405 PRE-DELIVE	Meter: RY INSPE	0 CTION			In Date:	10/10/2007	Closed:	10/10/20	07
- Pre-delivery	Inspection									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	838157 P.M SERVICE	<b>Meter:</b> E,MISSFIR	4263 E @ 50MPH			In Date:	05/07/2008	Closed:	05/09/20	08
	Service Comp				Parts Li	st				Qty
	rify Customer C	•	Missfire @ 50	mph	Shop Su	upplies				1.00
• .	Balance All Tire	es.			Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
- Shop Suppli	es				1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					G8018 F	Fuel Filter Ll	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
	Hour	s 5.00		Labor:	300.00	Parts:	31.12	Total:	331.12	
Workorder: Problem:	844670 AIR BAG & TI	Meter: IRE LIGHT	6823 ON			In Date:	09/24/2008	Closed:	09/29/20	08
Sys.	•	n Airbag Sy	/s.b1342 Inte	rnal	Parts Li Shop Su					<b>Qty</b> 1.00
		s 3.50		Labor:	210.00	Parts:	2.00	Total:	212.00	
Workorder: Problem:	847982 P.M. SERVIC	<b>Meter:</b> E.INSTALI	8033 L STROBE LI	GHTS.		In Date:	12/09/2008	Closed:	12/18/20	08
- Pm Service					Parts Li	st				Qty
- Fabricate Ar	nd Install 4 Hea	ad Strobe L	amp Sys.		Shop Su	upplies				1.00
- Rotate & Hi	Speed Balance	e 4 Tires.fil	I W/nitrogen.		1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- Shop Suppli	es				G8018 F	Fuel Filter Ll	of G6593 Wix	33595		1.00
					5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
					Ds-167	Toggle Swit	ch (standard	)		1.00
					80865 F	useholder l	mperial 80865	5		1.00
					S660cc	cc Strobe Ki	t 4 Head Kit			1.00
	Hour	rs 13.00		Labor:	780.00	Parts:	335.54	Total:	1,115.54	

Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  G8018 Fuel Filter Lbf G6593 Wix 33595  Ca8039 Air Filter Lbf Af1615 Wix 46418  5w20 Engine Oil  31-20 Wiper Blades 20" Blade  R134a Refrigerant  Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	Qty 1.00 1.00 7.00 1.00 632.77  03/09/2010  Qty 1.00 1.00 1.00 7.00 2.00
harness.  - A/c inspection, scan for codes. 48deg out of vents.  - Rotate & balance all four tires.  - Shop Supplies  Hours 10.00  Hours 10.00  Problem: P.M service, check A/C.  - Perform A/c inspection & service.  - Perform A/c inspection & service.  - Shop Supplies  Perform A/c inspection & service.  - Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  Sw20 Engine Oil  Used Firex Refurbed Fire Extingshers  In Date: 03/03/2010 Closed: 03  Parts List  Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  G8018 Fuel Filter Lbf G6593 Wix 33595  Ca8039 Air Filter Lbf Af1615 Wix 46418  5w20 Engine Oil  31-20 Wiper Blades 20" Blade  R134a Refrigerant  Hours 6.00  Labor: 360.00 Parts: 45.28 Total: 40	1.00 7.00 1.00 632.77 03/09/2010 <b>Qty</b> 1.00 1.00 1.00 7.00
- A/c inspection, scan for codes. 48deg out of vents Rotate & balance all four tires Shop Supplies  Hours 10.00 Elabor: 600.00 Parts: 32.77 Total: 63  Workorder: 1002212 Meter: 16660 Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  Parts List Shop Supplies  Parts List Shop Supplies  1372 Oil Filter Filter Extingshers  Farts List Shop Supplies  1372 Oil Filter Filter Lbf G6593 Wix 33595 Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	7.00 1.00 632.77 03/09/2010 Qty 1.00 1.00 1.00 7.00
- Rotate & balance all four tires Shop Supplies  Hours 10.00 Labor: 600.00 Parts: 32.77 Total: 63  Workorder: 1002212 Meter: 16660 Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  Parts List Shop Supplies  Parts List Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372 G8018 Fuel Filter Lbf G6593 Wix 33595 Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	1.00 632.77 03/09/2010 Qty 1.00 1.00 1.00 7.00
- Rotate & balance all four tires Shop Supplies  Hours 10.00 :  Workorder: 1002212 Meter: 16660 Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  Phous 10.00 Supplies  Parts List Shop Supplies  Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372 G8018 Fuel Filter Lbf G6593 Wix 33595 Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Hours 6.00 Labor: 360.00 Parts: 45.28  Total: 46	03/09/2010 Qty 1.00 1.00 1.00 7.00
- Shop Supplies  Hours 10.00 :  Workorder: 1002212 Meter: 16660 Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372 G8018 Fuel Filter Lbf G6593 Wix 33595 Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 46	03/09/2010 Qty 1.00 1.00 1.00 7.00
:  Workorder: 1002212	03/09/2010 Qty 1.00 1.00 1.00 7.00
Problem: P.M service, check A/C.  - P.m service Perform A/c inspection & service Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  G8018 Fuel Filter Lbf G6593 Wix 33595  Ca8039 Air Filter Lbf Af1615 Wix 46418  5w20 Engine Oil  31-20 Wiper Blades 20" Blade  R134a Refrigerant  Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	Qty 1.00 1.00 1.00 1.00 7.00
- Perform A/c inspection & service.  - Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  G8018 Fuel Filter Lbf G6593 Wix 33595  Ca8039 Air Filter Lbf Af1615 Wix 46418  5w20 Engine Oil  31-20 Wiper Blades 20" Blade  R134a Refrigerant  Hours 6.00  Labor: 360.00 Parts: 45.28 Total: 40	1.00 1.00 1.00 1.00 7.00
- Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372  G8018 Fuel Filter Lbf G6593 Wix 33595  Ca8039 Air Filter Lbf Af1615 Wix 46418  5w20 Engine Oil  31-20 Wiper Blades 20" Blade  R134a Refrigerant  Hours 6.00  Labor: 360.00 Parts: 45.28 Total: 40	1.00 1.00 1.00 7.00
G8018 Fuel Filter Lbf G6593 Wix 33595 Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	1.00 1.00 7.00
Ca8039 Air Filter Lbf Af1615 Wix 46418 5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	1.00 7.00
5w20 Engine Oil 31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	7.00
31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40 :	
31-20 Wiper Blades 20" Blade R134a Refrigerant Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40 :	2.00
R134a Refrigerant  Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	
Hours 6.00 Labor: 360.00 Parts: 45.28 Total: 40	2.00
Workorder: 1006622 Meter: 18972 In Date: 06/10/2010 Closed: 06	405.28
Problem: P/R flat tire	06/23/2010
- 6910 Lake Worth Rd-w of Jog left side	
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.	0.00
Workorder:         1006623         Meter:         18972         In Date:         06/10/2010         Closed:         06/10/2010           Problem:         TIRES	06/23/2010
- From: Repair Site	
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.	0.00
Workorder: 1008792 Meter: 20269 In Date: 08/16/2010 Closed: 08/16/2010 Problem: Problems starting clicking noise only	08/18/2010
- Test starting and charging system.battery failed load test	Qty
after recharge replace failed battery with new.  Shop Supplies	1.00
- Shop Supplies Group 65 Battery (mtc Bxt-65-850)	
Hours 1.00 Labor: 60.00 Parts: 136.01 Total: 19	1.00

Problem: P.M. Se	35 ervicean	Meter: d strobes	21211 inop at times			In Date:	09/30/2010	Closed:	10/06/20	010
- P.m. Service.					Parts Lis	t				Qty
- Test strobe lamps.re	place fa	ailed strot	e lamp switch.		Shop Sup	plies				1.00
- Repair left front tire.	rotate ai	nd balanc	e all.		1372 Oil	Filter Frm	Ph2 Wix 513	372		1.00
- Shop Supplies					5w20 Eng	gine Oil				7.00
					Used Fire	x Refurbe	d Fire Extings	hers		1.00
					31-20 Wi	per Blades	20" Blade			2.00
					Ds-167 T	oggle Swit	ch (standard	)		1.00
	Hours :	7.00		Labor:	420.00	Parts:	49.74	Total:	469.74	
Workorder: 110372 Problem: Pm ser		Meter:	25603			In Date:	04/05/2011	Closed:	04/14/20	011
- Perform pm service.					Parts Lis	t				Qty
- Install two new tires.	nitroger	n fill and b	alance all four	•	Shop Sup	plies				1.00
- Perform wheel align	ment co	mplete.			G8018 F	uel Filter L	of G6593 Wix	33595		1.00
- Shop Supplies					1372 Oil	Filter Frm	Ph2 Wix 513	372		1.00
					Ca8039 A	Air Filter Lb	of Af1615 Wix	46418		1.00
					5w20 Eng	gine Oil				7.00
					D3tz2457	b Brake P	edal Pad			1.00
							5r16 Wrangle	r Sr-a E		2.00
					Tire Disp					2.00
					Tr416 Va					2.00
	Hours :	8.50		Labor:	510.00	Parts:	368.94	Total:	878.94	
Workorder: 110914 Problem: Passer		<b>Meter:</b> ar Flat tire	29165			In Date:	08/15/2011	Closed:	08/29/20	011
- 8100 Forest Hil Blvd	1									
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	2	Meter:	30346			In Date:	10/17/2011	Closed:	10/27/20	011
Workorder: 111101 Problem: P.M. se				due to p	aint overs	pray.				
				due to p	eaint overs  Parts Lis					Qty
<b>Problem:</b> P.M. se	ervice ar	nd replace		due to p		t				<b>Qty</b> 1.00
<b>Problem:</b> P.M. se - P.m. Service.	ervice ar	nd replace		due to p	Parts Lis	t oplies	Ph2 Wix 513	372		-
Problem: P.M. service Rotate and balance	ervice ar	nd replace		due to p	Parts Lis	i <b>t</b> oplies Filter Frm	Ph2 Wix 513	372		1.00
Problem: P.M. service Rotate and balance	ervice ar	nd replace		due to p	Parts Lis Shop Sup 1372 Oil 5w20 Eng	t oplies Filter Frm gine Oil	Ph2 Wix 513	372		1.00 1.00
Problem: P.M. service Rotate and balance	ervice ar	nd replace		due to p	Parts Lis Shop Sup 1372 Oil 5w20 Eng 31-20 Wi	oplies Filter Frm gine Oil per Blades				1.00 1.00 7.00

Workorder: Problem:	1205385 P.M. sei		Meter: ad abs lig	35861 nt on and wind	Isheild cı	racked ar	In Date: ad body dam	06/07/2012 nage.	Closed:	07/06/2	012
- P.m. Service	€.					Parts Li	st				Qty
		1096.pe	erform pin	point test.rep	lace	Shop Su	pplies				1.00
defective Abs	control u					-		Ph2 Wix 51	372		1.00
and test drive.		II Cara				G8018 F	uel Filter L	of G6593 Wix	33595		1.00
- Rotate and I		III tires.				Abs Bra	ke Module				1.00
- Shop Suppli	es					Hydrauli	c Control U	nit Abs			1.00
						5w20 Er	ngine Oil				7.00
						31-20 W	iper Blades	20" Blade			2.00
						Used Fir	ex Refurbe	d Fire Extings	hers		1.00
		Hours :	9.00		Labor:	540.00	Parts:	1,071.87	Total:	1,611.8	7
Workorder: Problem:	1206234 replace		<b>Meter:</b> d windshe	35865 eild			In Date:	07/02/2012	Closed:	07/11/2	012
- Set up repai	rs for win	dshield	reasset	and check		Parts Li	st				Qty
- Shop Suppli						Shop Su	ipplies				1.00
		Hours	1.00		Labor:	-	Parts:	2.00	Total:	62.00	
Problem: - damage to It	_		oody	r of body	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	130010°		Meter:	41082			In Date:	01/02/2013	Closed:	01/28/2	013
- Perform pm	service.					Parts Li	st				Qty
- Test starting	and cha	rging sy	stem.tes	t and replace	failed	5w20 Er	ngine Oil				7.00
alternator asse	embly wit	h new.				1372 Oil	Filter				1.00
- Install two not balance all four		o the fro	ont whee	ls.nitrogen fill a	and	Ca8039	Air Filter Lb	of			1.00
		o pode	and recu	rface front bra	ko	Alternate	or				1.00
rotors.service						1797474	192 Lt245-7	5r16			2.00
hydraulic syste						Tr416 V	alve Stem				2.00
- Shop Suppli	es					Disc Bra	ke Pads				1.00
						Shop Su	ıpplies				1.00
						-	osal Fee				2.00
		Hours :	12.00		Labor:	720.00	Parts:	809.52	Total:	1,529.5	2
Workorder: Problem:	1307285 P.M.	5	Meter:	45880			In Date:	07/22/2013	Closed:		
-		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1307863 Pm servic	eLeft	Meter:	46538 flat and ac in	termittent.		In Date:	08/06/2013	Closed:	08/21/2013
- Perform pm		0_0				Parts Li	ist			Qı
- Test starting		iina sv	/stem.ba	tterv failed lo	adtest		Resevoir			1.0
after recharge						A/c Valv	⁄e			1.0
- Diagnose ad					replace	Battery				1.0
failed vacume						•	cuum Tubir	ng		5.0
- Repair flat ri	-	e.nitro	gen fill a	nd balance a	ll four.	5w20 Er	ngine Oil			7.0
- Shop Suppli	es					Napago	ld Oil Filter			1.0
						31-20 W	/iper Blades	s 20		2.0
						Napago	ld Fuel Filte	r		1.0
						Used Fi	re X Refurb	ished		1.0
						Shop Su	upplies			1.0
	F ·	Hours	10.00		Labor:	600.00	Parts:	229.16	Total:	829.16
Workorder:	1402592		Meter:	50678			In Date:	03/18/2014	Closed:	03/26/2014
Problem:	Pm servic	e and	I low tire	pressure war	ning light	on.				
- Perform pm	service.					Parts Li	ist			Qt
- Pressure tes		ect co	oling sys	tem.reverse	flush and	5w20 Er	ngine Oil			7.0
renew engine				fa a a la uala		Napago	ld Oil Filter			1.0
<ul> <li>Install new retors.service</li> </ul>					ic system		ld Fuel Filte			1.0
with scan tool.				,	, ,		ld Air Filter			1.0
- Rotate and b	palance all	four t	ires.			Wiper B				2.0
- Shop Suppli	es					Peak GI				2.0
							Brake Pads	5		1.0
						Shop Su				1.0
	<b>⊢</b> :	Hours	11.00		Labor:	660.00	Parts:	148.27	Total:	808.27
Workorder: Problem:	1406536 Tires		Meter:	53092			In Date:	07/01/2014	Closed:	07/02/2014
- Tire Service	8100 Fore	st Hill	Blvd (wa	ater plant) - T	ïres					
	H :	Hours	0.00	•	Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1406537 Service		Meter:	53092			In Date:	07/01/2014	Closed:	07/02/2014
- Tire Service	8100 Fore	st Hill	Blvd (wa	ater plant) - S	ervice					
	H	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: 14114 Problem: Pm se			55163 es.		ln	Date:	11/17/2014	Closed:	12/04/2	014
- Pm service.					Parts List					Qty
- Replace two tires.ro	tate and bala	nce a	all four tires.		5w20 Engin	ne Oil				7.00
- Inspect and replace	defective righ	t he	adlamp seal	l beam.	Napagold C	Dil Filter				1.00
- Service transmissio	n.replace filte	.flus	sh and refill		Wiper Blade	е				2.00
transmission oil.					Stg Wheel	Cov - Fo	ord			1.00
- Complete front end	alignment and	tes!	t drive.		Lt245 75r16	6				2.00
- Shop Supplies					Tr416 Valve	e Stem				2.00
					Halogen La	mp				1.00
					Ft1167 Tran	ns Filter	L			1.00
					Syn-atf Trai	ns Fluid	S			16.00
					Shop Suppl	lies				1.00
					Tire Dispos	al Fee				2.00
	Hours 11.5	0		Labor:	690.00	Parts:	625.70	Total:	1,315.7	0
	•									
Workorder: 150460 Problem: Left rea			57693		ln	Date:	05/07/2015	Closed:	05/12/2	015
	ar tire going fl	at.	57693		In Parts List	Date:	05/07/2015	Closed:	05/12/2	
Problem: Left rea	ar tire going fl	at.	57693				05/07/2015	Closed:	05/12/2	Qty
Problem: Left rear t	ar tire going fl	at.	57693	Labor:	Parts List Shop Suppl				05/12/2 62.00	Qty
Problem: Left rear t	ar tire going fl ire and baland Hours 1.00 :	at.	57693 59041	Labor:	Parts List Shop Suppl 60.00	lies				<b>Qty</b> 1.00
Problem: Left rear to - Shop Supplies  Workorder: 15071	ar tire going fl ire and baland Hours 1.00 :	at.		Labor:	Parts List Shop Suppl 60.00	lies Parts:	2.00	Total:	62.00	<b>Qty</b> 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service.	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00 In Parts List	lies Parts: <b>Date:</b>	2.00	Total:	62.00	<b>Qty</b> 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm se	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin	lies Parts:  Date:	2.00	Total:	62.00	Qty 1.00 015 Qty 7.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00 In Parts List	lies Parts:  Date:  ne Oil Dil Filter	2.00	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List 60.00  In  Parts List 5w20 Engin Napagold C Wiper Blade	Date: ne Oil Dil Filter	2.00 07/16/2015	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00 2.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin Napagold C	Date:  Date:  ne Oil Dil Filter e	2.00 07/16/2015	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00 2.00 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin Napagold C Wiper Blade Napagold F	Date:  Date:  Description of the content of the con	2.00 07/16/2015 r res	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00 2.00 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin Napagold C Wiper Blade Napagold F Mac Wite Li	Date:  Date:  Description of the content of the con	2.00 07/16/2015 r res	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00 2.00 1.00 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin Napagold C Wiper Blade Napagold F Mac Wite Li Lt245/75r16 Tr416 Valve	Date: Date:  Description of the content of the cont	2.00 07/16/2015 r res	Total:	62.00	Qty 1.00 015 Qty 7.00 1.00 1.00 1.00 1.00
Problem: Left rear to - Repair flat left rear to - Shop Supplies  Workorder: 15071 Problem: Pm set - P.m. Service Replace one tire,rote	ar tire going flire and baland Hours 1.00 : 11 Metervice.	at. ce.	59041	Labor:	Parts List Shop Suppl 60.00  In  Parts List 5w20 Engin Napagold C Wiper Blade Napagold F Mac Wite Li Lt245/75r16	Date: Date:  Description of the control of the cont	2.00 07/16/2015 r res	Total:	62.00	<b>Qty</b> 1.00

Workorder: 1602866 Meter: 63105 Problem: Pm service.Has to jump start.Has to add engin	In Date: 03/17/2016 Closed: e oil.	03/31/2016
- Pm service.	Parts List	Qty
- Inspect circuits and bulb to third brake inop.replace third	5w20 Engine Oil	7.00
brake lamp, bulbs and harness due to water intrusion.	Napagold Oil Filter	1.00
- Perform engine major tune up.	20" Wiper Blade	2.00
- Perform injectors cleaning,trottle body cleaning and engine decarb.	Washer Fluid Concentr	1.00
- Test electrical starting and charging system battery failed	Lamp Assembly	1.00
after recharge.replace defective battery.	Spark Plug	8.00
- Starting oil consumption test.at this mileage,full.	Throttle Body Cleaner	1.00
- Rotate and balance all four wheels.	Injector Cleaner	1.00
- Shop Supplies	Intake Cleaner Kit	1.00
	Bulb	2.00
	Battery	1.00
	Shop Supplies	1.00
Hours 13.80 Labor:	828.00 Parts: 356.48 Total:	1,184.48
Workorder: 1611200 Meter: 68877 Problem: P.M. service.	In Date: 10/28/2016 Closed:	11/14/2016
	In Date: 10/28/2016 Closed: Parts List	11/14/2016 <b>Qty</b>
Problem: P.M. service.		
Problem: P.M. service P.m. Service.	Parts List	Qty
Problem: P.M. service P.m. Service Replace leaking front shocks.	Parts List Napagold Oil Filter	<b>Qty</b> 1.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.	Parts List Napagold Oil Filter 5w20 Engine Oil	<b>Qty</b> 1.00 7.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade	<b>Qty</b> 1.00 7.00 2.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter	Qty 1.00 7.00 2.00 1.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished	Qty 1.00 7.00 2.00 1.00 1.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished Shock - Gas Grande Fleet - Front	Qty 1.00 7.00 2.00 1.00 1.00 2.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished Shock - Gas Grande Fleet - Front 75w140 Ford Axle Lube	Qty 1.00 7.00 2.00 1.00 1.00 2.00 3.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished Shock - Gas Grande Fleet - Front 75w140 Ford Axle Lube Friction Modifier	Qty 1.00 7.00 2.00 1.00 2.00 3.00 2.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished Shock - Gas Grande Fleet - Front 75w140 Ford Axle Lube Friction Modifier Non-chlor Brake Clnr	Qty 1.00 7.00 2.00 1.00 1.00 2.00 3.00 2.00 1.00
Problem: P.M. service.  - P.m. Service.  - Replace leaking front shocks.  - Inspect and service rear differential.  - Replace extinguisher bracket.secure loose arm rest.  - Rotate and balance tires.  - Shop Supplies	Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Napagold Fuel Filter Used Fire X Refurbished Shock - Gas Grande Fleet - Front 75w140 Ford Axle Lube Friction Modifier Non-chlor Brake Clnr Custom Bracket Fire Ex Shop Supplies	Qty 1.00 7.00 2.00 1.00 2.00 3.00 2.00 1.00 1.00

Workorder: Problem:	1705574 P.M. Ser		Meter: witch for s	72138 strobe lights	broke.Ligh		n Date:	06/05/2017	Closed:	06/15/2017
- P.m. service				<b>3</b>	<b>J</b>	Parts List	t			Qt
- Cigarette ligi	r failed	.remove	and install ne	ew.strobe	Socket	1.00				
light inop.switch failed R&r dash and install new switch.						luminous	1.00			
- Steering colu					d.r&r	5w20 Eng	jine Oil			7.00
steering colum			•			Napagold	Oil Filter			1.00
- Rotate and h	•	d balan	ice all fou	ır.		20" Wiper	Blade			2.00
- Shop Suppli	es					Bat Term	Protector			1.00
						Used Fire	X Refurb	ished		1.00
						Toggle Sv	vitch			1.00
						Cover				1.00
						Damper A	sy			1.00
						F3tz7l278	a Bushing	<b>S</b> h		2.00
						Shop Sup	plies			1.00
		Hours :	9.00		Labor:	540.00	Parts:	146.99	Total:	686.99
Workorder: Problem:	1706783 repair rus		Meter:	72138		I	n Date:	06/15/2017	Closed:	07/11/2017
- repair rust or	n roof									
		Hours			Labor:	0.00	Parts:	0.00	Total:	0.00
- repair rust o	1712082	:	0.00 <b>Meter:</b>	75467 rear doors o		ı	n Date:	0.00	Total:	0.00
- repair rust o	1712082 PM Serv	:	0.00 <b>Meter:</b>			ı	n Date: er rack.			
- repair rust or  Workorder: Problem: - P.m. service - Inspect and	1712082 PM Serv e. replace b	: Price, Bo	0.00 Meter: th side &	rear doors o	dont open,	I Need ladd Parts Lis	n Date: er rack.			12/19/2017
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asse	1712082 PM Serv e. replace b embly with	: Price, Bo roken b h new.	0.00  Meter: th side &	rear doors of	dont open,	I Need ladd Parts Lis	In Date: ler rack. t			12/19/2017 <b>Qt</b>
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservicate a	1712082 PM Serve. replace bembly with	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng	In Date: er rack. t jine Oil Oil Filter	12/08/2017		12/19/2017 <b>Qt</b> y 7.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold	In Date: ler rack. t line Oil Oil Filter luid Conce	12/08/2017		12/19/2017 Qty 7.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservicate a	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F	In Date: er rack.  t gine Oil Oil Filter luid Conce	12/08/2017 entr		12/19/2017  Qty 7.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte	12/08/2017 entr		12/19/2017 Qty 7.00 1.00 2.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte	12/08/2017 entr		12/19/2017  Qty 7.00 1.00 2.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte	12/08/2017 entr		12/19/2017  Qty 7.00 1.00 2.00 1.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte h W/cable	12/08/2017 entr		12/19/2017  Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc latch	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte h W/cable	12/08/2017 entr r		12/19/2017  Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc latch latch door latch	In Date: er rack.  t gine Oil Oil Filter luid Conce Blade Fuel Filte h W/cable	12/08/2017 entr r		12/19/2017  Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc latch latch door latch	In Date: ler rack.  t line Oil Oil Filter luid Conce Blade Fuel Filte h W/cable remote ce dle W/cab	12/08/2017 entr r		12/19/2017  Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- repair rust or  Workorder: Problem: - P.m. service - Inspect and and cable asservable asservable asservable and the restricts are restricted as a restrict and the restricts are restricted.	1712082 PM Serve. replace bembly with and mount balance for	: rice, Bo roken b h new. t ladder	0.00  Meter: th side &	rear doors of	dont open,	Need ladd Parts List 5w20 Eng Napagold Washer F 20" Wiper Napagold Door Latc latch latch door latch Door Hand	In Date: er rack.  t gine Oil Oil Filter luid Conce Blade Fuel Filte h W/cable remote co dle W/cab	12/08/2017 entr r		12/19/2017  Qty 7.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: 1806467 Meter: 79900 Problem: P.M. service and Battery goes dead.	In Date: 06/25/2018	<b>Closed:</b> 07/03/2018
- P.m. service.	Parts List	Qty
- check and charge battery . battery failed load test .r&r	Napagold Oil Filter	1.00
defective battery.	5w20 Engine Oil	7.00
- Test and replace thrid brake light bulb.	Napagold Air Filter	1.00
<ul> <li>Replace right front tire .repair right rear tire . Rotate and high speed balance all four tires.</li> </ul>	20" Wiper Blade	2.00
	Wd40 Spr	1.00
- Complete front end alignment. Road test.	Mac Wite Lithium Gres	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Battery	1.00
	Boxed Miniatures	1.00
	Shop Supplies	1.00
	Lt245/75r16 Tire	1.00
	Tire Disposal Fee	1.00
Hours 10.00 Labor:	600.00 Parts: 316.39	Total: 916.39
Workorder: 1900779 Meter: 83769 Problem: Transition Prep Charge	<b>In Date:</b> 01/18/2019	<b>Closed:</b> 01/18/2019
- Transition Prep Charge		
Hours 2.00 Labor:	134.00 Parts: 0.00	Total: 134.00