10185033 2011 FORD F150 Pickup, 1/2 Ton

Workorder: Problem:	1105250 Pre Delivery Ir	Meter: spection	0			In Date:	05/17/2011	Closed:	05/17/20	011
- Pre Delivery	Inspection									
	Hours :	3 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1109573 P.M. service.	Meter:	5858			In Date:	09/07/2011	Closed:	09/13/20	)11
- P.m. Service	Э.				Parts Li	ist				Qty
- Rotate and b	palance all tires				Shop Su	upplies				1.00
- Shop Suppli	es				Ph1057	5 Oil Filter N	Atc FI500s Wix	x 57502		1.00
					5w20 Er	ngine Oil				6.00
	Hours :	3.00		Labor:	180.00	Parts:	19.35	Total:	199.35	
Workorder: Problem:	1200570 Pm service	Meter:	11292			In Date:	01/18/2012	Closed:	01/25/20	)12
- P.m. Service	Э.				Parts Li	ist				Qty
- Rotate and b	palance all tires				Shop Supplies					1.00
- Shop Suppli	es				Ph1057	5 Oil Filter N	Atc FI500s Wix	x 57502		1.00
					5w20 Er	ngine Oil				6.00
					1066 W	hite Lithium/	(crc 05037)			1.00
					7090blk	Frt Floor M	ats (rubber Qı	ueen)		1.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
	Hours :	3.00		Labor:	180.00	Parts:	77.43	Total:	257.43	
Workorder: Problem:	1202839 Hessitates who	<b>Meter:</b> en drivind	14273 over 50mph a	ınd wren	ch light c	In Date: omes on.	03/23/2012	Closed:	04/16/20	)12
	ehicle to dealer vrench light on.(			ting	Parts Li					<b>Qty</b> 1.00
отор обрат		s 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1203607 Truck still shift	Meter: s hard and	14373 d misfire.			In Date:	04/17/2012	Closed:	05/07/20	)12
transmission I	ehicle to and fro harness with ne				Parts Li					<b>Qty</b> 1.00
- Shop Suppli		s 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	

Workorder: Problem:	1206305 P.M., Service.	Meter:	17122		İ	n Date:	07/05/2012	Closed:	07/19/20	012
- Perform pm	service.				Parts List					Qty
-	palance all four	tires.			Shop Supp	olies				1.00
- Shop Suppli	es				Ph10575 (	Dil Filter N	Mtc Fl500s Wix	k 57502		1.00
					5w20 Engi	ine Oil				6.00
					31-22 Wip	er Blades	s 22" Wiper Bla	ade		2.00
	Hours	3.00		Labor:	180.00	Parts:	29.85	Total:	209.85	
Workorder: Problem:	1208393 Right front rire	Meter: s has scre	19418 ew		lı	n Date:	09/05/2012	Closed:	09/10/20	012
- Repair and b	palance right fro	ont tire.			Parts List					Qty
- Shop Suppli	_				Shop Supp	olies				1.00
		s 1.00		Labor:		Parts:	2.00	Total:	62.00	
Workorder: Problem:	1300603 P.M. service.	Meter:	24326		l	n Date:	01/16/2013	Closed:	01/29/20	013
- Perform pm	service.				Parts List					Qty
•	palance all four	tires.			5w20 Engi	ine Oil				6.00
- Shop Suppli	es				Napagold					1.00
					Ca10262		Мt			1.00
					31-22 Wip	er Blades	s 22			2.00
					Used Fire	k Refurbe	ed F			1.00
					Shop Supp	olies				1.00
	Hours :	3.00		Labor:	180.00	Parts:	56.93	Total:	236.93	
Workorder: Problem:	1303643 3 - Wash ticke	Meter: t(s) issued	24341 d		lı	n Date:	04/12/2013	Closed:	04/12/20	013
- 3 - Wash ticl	ket(s) issued									
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1307058 Pm service.Clu	Meter: unk when	26916 coming to a	stop.Instal		n Date: supplied	07/15/2013 safety net.	Closed:	07/25/20	013
- P.m. Service	<b>)</b> .				Parts List					Qty
	/.recharge batte				5w20 Eng	ine Oil				6.00
	m.battery fail lo	ad test.re	place defect	tive	Napagold	Oil Filter				1.00
battery.	oft accomble an	d alcan a	nd luba anlia	00 pc*	Wiper Blad	de				2.00
	aft assemble an clunking noise		na iubė spiir	ies per	Battery 65					1.00
	d install coston	•	ed cargo net		Repair Kit					1.00
	palance all tires		3.5.70		Adhesive					1.00
- Shop Suppli					Shop Supp	olies				1.00
1 1	Hours	6.00		Lobori	360.00	Dorto	186.55	Totalı	546.55	

Workorder: Problem:	1401481 Pm service.	Meter:	31837		In Date:	02/13/2014	Closed:	02/27/20	014
- P.m. Service	Э.				Parts List				Qty
	balance all tire	s.			5w20 Engine Oil				6.00
- Shop Suppli	es				Napagold Oil Filter				1.00
					Mac Wite Lithium (				1.00
					Wiper Blade				2.00
					Used Fire X Refurb	oished			1.00
					Shop Supplies				1.00
	Hou :	rs 3.00		Labor:	180.00 Parts	: 50.18	Total:	230.18	
Workorder: Problem:	1408423 Pm service.	Meter:	36122		In Date:	08/22/2014	Closed:	09/08/20	014
- Pm service.					Parts List				Qty
	ont and rear b				5w20 Engine Oil				6.00
-	ice all four cali	-	rive.		Napagold Oil Filter				1.00
	balance all fou	r tires.			Wiper Blade				2.00
- Shop Suppli	es				Shop Supplies				1.00
	Hou :	rs 6.00		Labor:	360.00 Parts	: 29.68	Total:	389.68	
Workorder: Problem:	1500087 Right front tire	<b>Meter:</b> e damage.	39475		In Date:	01/05/2015	Closed:	01/06/20	J15
- Replace two	tires and hala	ance both re	enlace one d	amage	Parts I ist				Otv
•	tires and bala sensor.	ance both.re	eplace one d	amage	Parts List Hankook P235 75r	17 Dp At			•
•	sensor.	ance both.re	eplace one d	amage	Parts List Hankook P235 75r Tpms12 Sensor Ti	•			2.00
tire pressure s	sensor.	ance both.re	eplace one d	amage	Hankook P235 75r	•			2.00
tire pressure s	sensor.	ance both.re	eplace one d	amage	Hankook P235 75r Tpms12 Sensor Ti	•			1.00
tire pressure s	ensor. ies	ance both.re	eplace one d	amage Labor:	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee	•	Total:	607.80	2.00 1.00 1.00
tire pressure s - Shop Suppli Workorder:	ensor. jes Hou : 1500132	rs 1.25 <b>Meter:</b>	39374	-	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee	re Pr	Total:	607.80	2.00 1.00 1.00 2.00
tire pressure s - Shop Suppli Workorder: Problem:	ensor. es Hou :	rs 1.25  Meter: ront Passer	39374 nger	Labor:	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:	re Pr : 532.80			2.00 1.00 1.00 2.00
vertire pressure s - Shop Suppli  Workorder: Problem:	Hou : 1500132 Flat tire on Fr	rs 1.25  Meter: ront Passer	39374 nger	Labor:	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:	re Pr : 532.80		01/06/20	2.00 1.00 1.00 2.00
Workorder: Problem: - Tow From: 2 shop  Workorder:	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902	rs 1.25  Meter: ront Passer g rd Vista G	39374 nger	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:	re Pr : 532.80 01/05/2015	Closed:	01/06/20	2.00 1.00 1.00 2.00
Workorder: Problem: - Tow From: 2 shop  Workorder: Problem:	Hou: 1500132 Flat tire on Fr 2300 North Jog	rs 1.25  Meter: ront Passer g rd Vista G	39374 nger Sarage 3rd flo	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:  0.00 Parts	re Pr : 532.80	Closed: Total:	01/06/20	2.00 1.00 1.00 2.00
Workorder: Problem: Tow From: 2 shop  Workorder: Problem: - Tom From: 2 - Problem: - Problem:	Hou: 1500132 Flat tire on Fr 2300 North Jog Hou: 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:  O.00 Parts  In Date:	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015
Workorder: Problem: - Tow From: 2 shop  Workorder: Problem: - Replace two	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts In Date:  O.00 Parts  In Date:  Parts List 5w20 Engine Oil	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015 Qty 6.00
Workorder: Problem: Tow From: 2 shop  Workorder: Problem: Problem: Problem: Problem: Problem:	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts  In Date:  O.00 Parts  In Date:  Parts List 5w20 Engine Oil Napagold Oil Filter	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015 Qty 6.00 1.00
Workorder: Problem: - Tow From: 2 shop  Workorder: Problem: - Replace two	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts  In Date:  O.00 Parts  In Date:  Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015 015 Qty 6.00 1.00 2.00
Workorder: Problem: Tow From: 2 shop  Workorder: Problem: Problem: Problem: Problem: Problem:	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts  In Date:  O.00 Parts  Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Washer Fluid Cond	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015 015 Qty 6.00 1.00 2.00 1.00
Workorder: Problem: Tow From: 2 shop  Workorder: Problem: Problem: Problem: Problem: Problem:	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts  In Date:  O.00 Parts  In Date:  Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Washer Fluid Cond 235 75r17 Advente	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 1.00 2.00 015 015 Qty 6.00 1.00 2.00 1.00 2.00
Workorder: Problem: Tow From: 2 shop  Workorder: Problem: Problem: Problem: Problem: Problem:	Hou : 1500132 Flat tire on Fr 2300 North Jog Hou : 1501902 Pm service.	Meter: ront Passer g rd Vista G rs 0.00  Meter:	39374 nger Sarage 3rd flo 41099 all four.	Labor: por To: Lv	Hankook P235 75r Tpms12 Sensor Ti Shop Supplies Tire Disposal Fee 75.00 Parts  In Date:  O.00 Parts  Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Washer Fluid Cond	re Pr : 532.80	Closed:	01/06/20	2.00 1.00 2.00 015 015 Qty 6.00 1.00 2.00

Workorder: Problem:	1502933 Right rear tir	Meter: e flat.	41640			In Date:	03/20/2015	Closed:	03/26/2	015
- Repair and	balance flat riç	ght rear tire	,		Parts L	.ist				Qty
- Shop Suppl	ies				Shop S	upplies				1.00
	Hou :	ırs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1503965 Towed in.Let	Meter: ft front tire f				In Date:	04/17/2015	Closed:	04/28/2	015
- Replace and	d balance left	front tire.			Parts L	.ist				Qty
- Shop Suppl					235 75	17 Adventur	е			1.00
					Shop S	upplies				1.00
					-	sposal Fee				1.00
	Hou	urs 0.50		Labor:	30.00	Parts:	241.96	Total:	271.96	
Workorder: Problem:	1503990 Flat tire	Meter:	42227			In Date:	04/17/2015	Closed:	04/17/2	015
- Tow From:	7099 Parker A	ve (golf Co	urse) To: Lv	/ shop						
	Ηοι :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1506375 Right front til	Meter: re flat.	45070			In Date:	06/25/2015	Closed:	06/29/2	015
- Repair and	balance right f	ront tire.			Parts L	.ist				Qty
- Shop Suppl	•				Shop S	upplies				1.00
	Hou :	ırs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1507965 P.M. Service	Meter:	46551			In Date:	08/10/2015	Closed:	08/25/2	015
- Pm service.					Parts L	.ist				Qty
- Battry failed	loadtest after	recharge.re	eplace defe	ctive	5w20 E	ngine Oil				6.00
battery.					Napago	old Oil Filter				1.00
	nsmission flus				Used F	ire X Refurbi	ished			1.00
<ul> <li>Diagnose cl disassemble t</li> </ul>	unking noise o				Washe	r Fluid Conce	entr			1.00
	wo piece drive balance all fou		oo alib yoke	•	Battery					1.00
- Shop Suppl		ai 11163.			Syn-atf	Trans Fluid	S			12.00
опор оцррг	100				Shop S	upplies				1.00
	Hou	ırs 6.75		Labor:	405.00	Parts:	214.94	Total:	619.94	

Workorder: Problem:	1601974 Pm service.	Meter:	52165			In Date:	02/25/2016	Closed:	03/07/20	)16
- Pm service.					Parts Lis	st				Qty
- Pressure tes	t and inspect	cooling sys	stem.flush an	d replace	5w20 En	gine Oil				6.00
coolant.					Napagolo	d Oil Filter				1.00
- Rotate and b	alance all fou	ır tires.			22" Wipe	r Blade				2.00
- Shop Supplie	es				Ford Red	l Antifreeze	)			1.00
					Shop Su	oplies				1.00
	Hou :	urs 5.00		Labor:	300.00	Parts:	52.31	Total:	352.31	
Workorder:	1608608	Meter:	56839			In Date:	08/18/2016	Closed:	08/31/20	)16
Problem:	P.M. service	and clicking	g in dash.							
- P.m. Service	) <b>.</b>				Parts Lis	st				Qty
- Inspect and	service rear d	lifferential.			Napagol	d Oil Filter				1.00
- Diagnose no			ea.replace ar	nd	5w20 En	gine Oil				7.00
recalibrate ble					Used Fire	e X Refurbi	shed			1.00
- Rotate and b		<b>.</b>			22" Wipe					2.00
- Shop Suppli	es				75w140	Ford Axle L	.ube			3.00
					Ptex Ultr	a Grey 3oz				1.00
					A/c Mode	Actuator I	Motor			1.00
					Shop Su	oplies				1.00
	Hou :	ırs 6.00		Labor:	360.00	Parts:	163.21	Total:	523.21	
Workorder:	1701944	Meter:	61133			In Date:	02/24/2017	Closed:	03/28/20	)17
Problem:	P.M. service	and vibration	on and transi	nission ciu	icks and s	ecure gps	wires.			
- P.m. Service	) <b>.</b>				Parts Lis	st				Qty
- Chack rear o			odifior		5w20 En	gine Oil				6.00
- Officer real c	lifferential.add	d friction mo	Juliei.							
- Scan transm	ission system	n for codes,	none presen			d Oil Filter				1.00
- Scan transm drive vehicle fo	ission system or slipping cor	n for codes,	none presen							1.00 2.00
- Scan transm	ission system or slipping cor	n for codes,	none presen		Napagolo 20" Wipe		entr			
- Scan transm drive vehicle fo	ission system or slipping cor	n for codes,	none presen		Napagolo 20" Wipe	r Blade Fluid Conce	entr			2.00
- Scan transm drive vehicle fo	ission system or slipping cor	n for codes,	none presen		Napagolo 20" Wipe Washer I	r Blade Fluid Conce Modifier	entr			2.00 1.00
- Scan transm drive vehicle fo	ission system or slipping cor es	n for codes,	none presen	this time.	Napagolo 20" Wipe Washer I Friction M	r Blade Fluid Conce Modifier		Total:	243.70	2.00 1.00 1.00
- Scan transm drive vehicle for - Shop Supplied Workorder:	ission system or slipping cor es	n for codes, ncern.unabl urs 3.50	none presen e to varify at 61823	this time.	Napagold 20" Wipe Washer I Friction N Shop Su	r Blade Fluid Conce Modifier oplies		Total:	243.70	2.00 1.00 1.00 1.00
- Scan transm drive vehicle for - Shop Supplied Workorder:	ission system or slipping cor es Hou : 1703415 Left rear turn	n for codes, ncern.unabl urs 3.50  Meter: n signal inop	none presen e to varify at 61823	this time.	Napagold 20" Wipe Washer I Friction N Shop Su	r Blade Fluid Conce Modifier oplies Parts:	33.70			2.00 1.00 1.00 1.00
- Scan transm drive vehicle for - Shop Supplied Workorder: Problem:	ission system or slipping cor es Hou : 1703415 Left rear turn	n for codes, ncern.unabl urs 3.50  Meter: n signal inop	none presen e to varify at 61823	this time.	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00	r Blade Fluid Conce Modifier oplies Parts:	33.70			2.00 1.00 1.00 1.00
- Scan transm drive vehicle for - Shop Supplied Workorder: Problem:	ission system or slipping cor es Hou : 1703415 Left rear turn rear signal lig	n for codes, ncern.unabl urs 3.50  Meter: n signal inop	none presen e to varify at 61823	this time.	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00	r Blade Fluid Conce Modifier oplies Parts:	33.70 04/05/2017	Closed:		2.00 1.00 1.00 1.00
- Scan transm drive vehicle for - Shop Supplied Workorder: Problem:	ission system or slipping cor es Hou : 1703415 Left rear turn rear signal lig	n for codes, neern.unablurs 3.50  Meter: n signal inoposition	none presen e to varify at 61823	this time.	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00	r Blade Fluid Conce Modifier oplies Parts: In Date:	33.70 04/05/2017	Closed:	04/18/20	2.00 1.00 1.00 1.00 1.00 017 Qty 1.00
- Scan transmodrive vehicle for a shop Supplied - Shop Supplied - Shop Supplied - Problem: - Replace left - Workorder:	ission system or slipping cor es  Hou :  1703415 Left rear turn rear signal lig Hou :	n for codes, neern.unablurs 3.50  Meter: n signal inoposition bulb. urs 0.50  Meter:	none presen e to varify at 61823 b.	Labor:	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00 Parts Lis Bulb 30.00	r Blade Fluid Conce Modifier oplies Parts: In Date: St Parts:	33.70 04/05/2017 0.78	Closed:	04/18/20	2.00 1.00 1.00 1.00 1.00 017 Qty 1.00
- Scan transmodrive vehicle for a shop Supplied - Shop Supplied - Shop Supplied - Problem: - Replace left - Workorder:	House	m for codes, neern.unable urs 3.50  Meter: a signal inoper urs 0.50  Meter: eft door, left	61823 o. 63085 t side of cab a	Labor:	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00 Parts Lis Bulb 30.00	r Blade Fluid Conce Modifier oplies Parts: In Date: St Parts:	33.70 04/05/2017 0.78	Closed:	04/18/20	2.00 1.00 1.00 1.00 1.00 017 Qty 1.00
- Scan transmodrive vehicle for a shop Supplied - Shop Supplied - Shop Supplied - Problem: - Replace left - Workorder: Problem:	House	m for codes, neern.unable urs 3.50  Meter: a signal inoper urs 0.50  Meter: eft door, left	61823 o. 63085 t side of cab a	Labor:	Napagolo 20" Wipe Washer I Friction I Shop Su 210.00  Parts Lis Bulb 30.00  of bed	r Blade Fluid Conce Modifier oplies Parts: In Date: St Parts:	33.70 04/05/2017 0.78 06/07/2017	Closed:	30.78	2.00 1.00 1.00 1.00 1.00 017 Qty 1.00

Workorder: 1708896 Meter: 64926 Problem: PM Service	In Date: 09/15/2017 Closed: 0	09/28/2017
- P.m. service.	Parts List	Qty
- Replace two tires also nitrogen fill.rotate and high speed	5w20 Engine Oil	7.00
balance all four tires.	Napagold Oil Filter	1.00
- Resurface both rear brake rotors and service parking	22" Wiper Blade	2.00
brakes.replace calipers and new pads.flush and bleed brak system.	Used Fire X Refurbished	1.00
- Perform front end alignment.	Stg Wheel Cov - Ford	1.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Disc Pad	1.00
	Caliper w/ Hardware - Left Rear (eclipse	1.00
	Caliper w/ Hardware - Right Rear (eclips	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.00 Lab	or: 600.00 Parts: 655.08 Total: 1	1,255.08
Workorder: 1801320 Meter: 69945 Problem: PM Service	In Date: 02/02/2018 Closed: 0	02/12/2018
- P.m. service.	Parts List	Qty
- Remove and resurface front rotors, replace front brake	Napagold Oil Filter	1.00
pads.service calipers and flush and bleed brake system .te drive.	<sup>st</sup> 5w20 Engine Oil	7.00
- Diagnoise washer pump inop at times.test and replace	Bulb	1.00
washer pump and wiper switch Test operation.	Brake Pad	1.00
- Balance and rotate all four wheels .nitrofill.	Non-chlor Brake Clnr	1.00
- Shop Supplies	Washer Pump	1.00
	22" Wiper Blade	2.00
	Switch	1.00
	B Fluid Dot 3-32oz	1.00
	Shop Supplies	1.00
Hours 7.90 Lab	or: 474.00 Parts: 167.17 Total: 6	641.17
Workorder: 1801803 Meter: 69945 Problem: 1 - Wash ticket(s) issued	In Date: 02/15/2018 Closed: 0	02/15/2018
- 1 - Wash ticket(s) issued		
Hours 0.00 Lab	or: 0.00 Parts: 0.00 Total: 0	0.00

- Replace two tires, rotate and balance all four Shop Supplies - Hours 4.00 - Labor: - Check brakes, low brake pedal and fluid Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest Shop Supplies - Shop Supplie	Problem:	1806052 PM Service	Meter:	75075		In	Date:	06/13/2018	Closed:	06/28/2018
- Shop Supplies   5w20 Engine Oil   7.7	- P.m. Service	Э.				Parts List				Qt
Washer Fluid Concentr   Used Fire X Refurbished   1.   Hankook P235 75r17 Dp At   2.   22" Wiper Blade   2.   Shop Supplies   1.   Tire Disposal Fee   2.   240.00   Parts: 415.68   Total: 655.68   Morkorder: 1806716   Meter: 75079   In Date: 06/29/2018   Closed: 07/05/2018   Problem: Check brakes, low brake pedal and fluid.   Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest.   Briud Dot 3-320z   2.   Brake Master Cylinder   B Fluid Dot 3-320z   2.   Brake Pedal Pin   1.   Brake Switch   1.	- Replace two	tires,rotate an	nd balance	all four.		Napagold C	Oil Filter			1.0
Used Fire X Refurbished	- Shop Suppli	es				5w20 Engir	ne Oil			7.0
Hankook P235 75r17 Dp At   22   22" Wiper Blade   32   32   340						Washer Flu	uid Conce	entr		2.0
22" Wiper Blade   22   Shop Supplies   1.   1.   1.   1.   1.   1.   1.   1						Used Fire >	X Refurb	ished		1.0
Hours 4.00   Labor:   240.00   Parts:   415.68   Total:   655.68						Hankook P.	235 75r1	7 Dp At		2.0
Tire Disposal Fee 2. Hours 4.00 Labor: 240.00 Parts: 415.68 Total: 655.68  Workorder: 1806716 Meter: 75079 In Date: 06/29/2018 Closed: 07/05/2018 Problem: Check brakes, low brake pedal and fluid.  - Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest.  - Shop Supplies Brake Master Cylinder Bruid Dot 3-320z Brake Pedal Pin Brake Switch Shop Supplies 1.  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018 Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018 Problem: Brake lights inop on light braking.						22" Wiper E	Blade			2.0
Hours 4.00 Labor: 240.00 Parts: 415.68 Total: 655.68  Workorder: 1806716 Problem: Check brakes, low brake pedal and fluid.  Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest. Shop Supplies  Briuid Dot 3-32oz Brake Pedal Pin Brake Switch Shop Supplies  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 655.68  Closed: 07/05/2018  Closed: 06/29/2018  Closed: 06/29/2018  Closed: 06/29/2018  Closed: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Hours 0.00 Labor: 0.00 Parts: 0.00  Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018						Shop Supp	olies			1.0
Workorder: 1806716 Meter: 75079 In Date: 06/29/2018 Closed: 07/05/2018  Problem: Check brakes, low brake pedal and fluid.  - Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest.  - Shop Supplies  - Shop Supplies  B Fluid Dot 3-320z  Brake Pedal Pin  Brake Switch  Shop Supplies  - Hours 4.10  Labor: 246.00  Parts: 289.04  Total: 535.04  Workorder: 1806722 Meter: 75075  In Date: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop  Hours 0.00  Labor: 0.00  Parts: 0.00  Parts: 0.00  Total: 0.00  Workorder: 1808132 Meter: 77843  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.						Tire Dispos	sal Fee			2.0
Problem: Check brakes, low brake pedal and fluid.  - Diagnoise and inspect brakes .r&r defective master cylinder and brake booster and brake light switch and bushing. Bleed brakes and retest.  - Shop Supplies  Brake Master Cylinder Briuid Dot 3-320z Brake Pedal Pin Brake Switch Shop Supplies  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Broblem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Hours 0.00 Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.		Hour :	rs 4.00		Labor:	240.00	Parts:	415.68	Total:	655.68
Booster Assy 1.  Brake Master Cylinder 1.  Brake Master Cylinder 1.  Brake Pedal Pin 1.  Brake Switch 5.  Shop Supplies 1.  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018 Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018 Problem: Brake lights inop on light braking.  Diagnose brake lights . Adjust brake light switch and bracket and retest.					fluid.	In	Date:	06/29/2018	Closed:	07/05/2018
brakes and retest Shop Supplies  Brake Master Cylinder  B Fluid Dot 3-32oz  Brake Pedal Pin  Brake Switch  Shop Supplies  Hours 4.10  Labor: 246.00  Parts: 289.04  Total: 535.04  Workorder: 1806722  Meter: 75075  In Date: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop  Hours 0.00  Labor: 0.00  Parts: 0.00  Parts: 0.00  Total: 0.00  Workorder: 1808132  Meter: 77843  In Date: 08/08/2018  Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Diagnoise a	nd inspect brak	kes .r&r de	fective mast	er cylinder	Parts List				Qt
Brake Master Cylinder B Fluid Dot 3-32oz Brake Pedal Pin Brake Switch Shop Supplies  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018 Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018 Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.			light switch	h and bushi	ng. Bleed	Booster As	sy			1.0
B Fluid Dot 3-32oz Brake Pedal Pin Brake Switch Shop Supplies 1.  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Hours 0.00 Brake Fluid Dot 3-32oz Brake Pedal Pin 1.  In Date: 06/29/2018 Closed: 06/29/2018  Closed: 06/29/2018  Total: 0.00  Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	orakes and re	iest.								
Brake Switch Shop Supplies 1.  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	Chan Cunnli					Brake Mast	ter Cylind	der		1.0
Shop Supplies 1.  Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop  Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Shop Suppli						•	der		1.0 2.0
Hours 4.10 Labor: 246.00 Parts: 289.04 Total: 535.04  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Shop Suppli					B Fluid Dot	t 3-32oz	der		
:  Workorder: 1806722 Meter: 75075 In Date: 06/29/2018 Closed: 06/29/2018  Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop  Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Shop Suppli					B Fluid Dot Brake Peda	t 3-32oz al Pin	der		2.0
Problem: Low Brake Fluid and Brakes are not stopping like they should Per Driver.  - Tow From: Vista Garage 2nd Floor To: Lv shop  Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Shop Suppli					B Fluid Dot Brake Peda Brake Swite	t 3-32oz al Pin ch	der		2.0
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00  Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018  Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	- Shop Suppli	es	rs 4.10		Labor:	B Fluid Dot Brake Peda Brake Swite Shop Supp	t 3-32oz al Pin ch olies		Total:	2.0 1.0 1.0 1.0
: Workorder: 1808132 Meter: 77843 In Date: 08/08/2018 Closed: 08/09/2018 Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	Workorder:	Hour : 1806722	Meter:			B Fluid Dot Brake Peda Brake Swite Shop Supp 246.00	t 3-32oz al Pin ch blies Parts:	289.04 06/29/2018		2.0 1.0 1.0 1.0
Problem: Brake lights inop on light braking.  - Diagnose brake lights . Adjust brake light switch and bracket and retest.	Workorder: Problem:	Hour : 1806722 Low Brake Flu	Meter: uid and Bra	akes are not		B Fluid Dot Brake Peda Brake Swite Shop Supp 246.00	t 3-32oz al Pin ch blies Parts:	289.04 06/29/2018		2.0 1.0 1.0 1.0 535.04
bracket and retest.	Workorder: Problem:	Hour : 1806722 Low Brake Flu /ista Garage 2	Meter: uid and Bra nd Floor T	akes are not	stopping li	B Fluid Dot Brake Peda Brake Swite Shop Supp 246.00 In ke they show	t 3-32oz al Pin ch blies Parts: n Date: uld Per D	289.04 06/29/2018 Oriver.	Closed:	2.0 1.0 1.0 1.0 535.04
Hours 0.30 Labor: 18.00 Parts: 0.00 Total: 18.00	Workorder: Problem: - Tow From: \	Hour : 1806722 Low Brake Flu /ista Garage 2 Hour : 1808132	Meter: uid and Bra nd Floor T rs 0.00  Meter:	akes are not o: Lv shop 77843	stopping li	B Fluid Dot Brake Peda Brake Swite Shop Supp 246.00  In ke they show	t 3-32oz al Pin ch blies Parts: a Date: uld Per D	289.04 06/29/2018 Oriver. 0.00	Closed: Total:	2.0 1.0 1.0 1.0 535.04
	Workorder: Problem: - Tow From: \ Workorder: Problem: - Diagnose br	Hour : 1806722 Low Brake Flu /ista Garage 2 Hour : 1808132 Brake lights ir	Meter: uid and Bra nd Floor T rs 0.00  Meter: nop on ligh	akes are not o: Lv shop 77843 t braking.	stopping li Labor:	B Fluid Dot Brake Peda Brake Swite Shop Supp 246.00  In ke they show	t 3-32oz al Pin ch blies Parts: a Date: uld Per D	289.04 06/29/2018 Oriver. 0.00	Closed: Total:	2.0 1.0 1.0 1.0 535.04 06/29/2018

Workorder: Problem:	1809339 P.M. service.	Meter:	80293			In Date:	09/11/2018	Closed:	09/24/2018
- P.m. service	<b>).</b>				Parts L	ist			Qty
	st and inspect o				Napago		1.00		
	thermostat anf				5w20 Eı		6.00		
	elt . Flush and r				22" Wip		2.00		
	unk when stopp lip yoke. Retes		ing oii . Remov	ve arive	Washer		1.00		
- Rotate and l		V Belt				1.00			
- Shop Suppli					V Belt				1.00
omer cappe					Gasket				1.00
					Thermo	stat			1.00
					Water P	ump			1.00
					Anti Fre	eze Motorci	raft		2.00
					Repair l	<b>Kit</b>			1.00
					Shop St	upplies			1.00
	Hour	s 10.25		Labor:	615.00	Parts:	317.15	Total:	932.15
	winch out, loca overlook and ric Hour		_			of road. Parts:	0.00	Total:	0.00
	:								
Workorder: Problem:	1810584 1 - Wash ticke	Meter: et(s) issued	81392 J			In Date:	10/15/2018	Closed:	10/15/2018
- 1 - Wash tic	ket(s) issued								
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1812837 2 - Wash ticke	Meter: et(s) issued	84597 d			In Date:	12/18/2018	Closed:	12/18/2018
- 2 - Wash tic	ket(s) issued								
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1900105 Transition Pre	<b>Meter:</b> p Charge	84597			In Date:	01/02/2019	Closed:	01/02/2019
- Transition P	rep Charge								
2. 22.,		s 2.00		Labor:	134.00	Parts:	0.00	Total:	134.00