10185038 2011 FORD F150 Pickup, 1/2 Ton Workorder: 1104976 Meter: 0 In Date: 05/11/2011 Closed: 05/11/2011 Problem: Pre Delivery Inspection - Pre Delivery Inspection - Wash Vehicle Hours 3.00 Labor: 180.00 Total: 180.00 Parts: 0.00 : Workorder: 1105069 299 Meter: In Date: 05/12/2011 Closed: 05/12/2011 Problem: 1 - Wash ticket(s) issued - 1 - Wash ticket(s) issued Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1111307 Meter: 5136 In Date: 10/25/2011 Closed: 10/31/2011 Problem: P.M. service. Parts List - Perform pm service. Qty - Rotate and balance all four tires. Shop Supplies 1.00 Ph10575 Oil Filter Mtc Fl500s Wix 57502 - Shop Supplies 1.00 5w20 Engine Oil 6.00 Used Firex Refurbed Fire Extingshers 1.00 7090blk Frt Floor Mats (rubber Queen) 1.00 Labor: 180.00 Parts: 74.33 Total: 254.33 Hours 3.00 9775 Workorder: 1202383 Meter: In Date: 03/08/2012 Closed: 03/19/2012 **Problem:** Pm service and front end noise when climbing curbs. - P.m. Service. Parts List Qty - Check front suspension for noise.lube steering stops. Shop Supplies 1.00 - Rotate and balance all four tires. Ph10575 Oil Filter Mtc Fl500s Wix 57502 1.00 - Shop Supplies 5w20 Engine Oil 6.00 Wd40 Spray Lube Stock# 405540002 1.00 31-22 Wiper Blades 22" Wiper Blade 2.00 Hours 3.50 Labor: 210.00 Parts: 36.14 Total: 246.14 Workorder: 1203416 Meter: 10394 In Date: 04/10/2012 Closed: 04/26/2012 Problem: Steering sticking on long left turns. - Transport vehicle to dealer for defective rack & pinnion Parts List Qty assemble. Shop Supplies 1.00 - Shop Supplies Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Workorder: Problem:	1208695 Pm service.	Meter:	14913			In Date:	09/12/2012	Closed:	09/20/20)12
- P.m. Service	9.				Parts Li	st				Qty
	balance all tires	S.			Shop St					1.00
- Shop Suppli						• •	Atc FI500s Wiz	x 57502		1.00
						2 Air Filter M	Atc Fa1883 W	ix 49883		1.00
					5w20 Ei	ngine Oil				6.00
						-	d Fire Extings	hers		1.00
	Hour :	s 3.00		Labor:	180.00	Parts:	38.23	Total:	218.23	
Workorder: Problem:	1300747 Pm service.Ri	Meter: ght rear tir	19267 e flat.			In Date:	01/23/2013	Closed:	01/31/20)13
- P.m. Service	Э.				Parts Li	st				Qty
- Repair right	rear tire.rotate	and balan	ce all four.		5w20 Ei	ngine Oil				6.00
- Shop Suppli	es				Napago	ld Oil Filter				1.00
					31-22 W	/iper Blades	22			2.00
					Shop Su	upplies				1.00
	Hour	s 4.00		Labor:	240.00	Parts:	36.46	Total:	276.46	
	1301117 1 - Detail Veh hicle Wash Tic			ed		In Date:	01/31/2013	Closed:	01/31/20)13
- I - Detail ve		s 0.00	ieu	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1302160 Towed in will	Meter: not come o	21251 out of gear.			In Date:	03/04/2013	Closed:	03/11/20)13
- Recharge de	ead battery.che	ck shift lo	ck system.rep	lace	Parts Li	st				Qty
broken brake	ight switch.rete	est battery	and charging		Switch					1.00
system,good.(switch.)	went dead bec	ause of br	oken brake lig	int	Shop Su	upplies				1.00
,	nd repair hinge	system ac	n rear topper	lift gate.						
- Shop Suppli		-,		Jeres and a second s						
		s 3.00		Labor:	180.00	Parts:	31.19	Total:	211.19	
Workorder: Problem:	1302242 No start, wire	Meter: off under of	20948 Jash			In Date:	03/04/2013	Closed:	03/05/20)13
- Tow From: 3 shop	Brd floor parking	g garage 2	300 jog road	To: Lv						
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Problem:	1304994 P.M. service.	Meter:	24643		I	n Date:	05/20/2013	Closed:	05/29/20	013
- P.m. Service	e.				Parts List					Qty
	balance all tires	S.			5w20 Eng	ine Oil				6.00
- Shop Suppl	lies				Napagold					1.00
					. c 31-22 Wip		3 22			2.00
					Shop Sup					1.00
	Hour	s 3.00		Labor:	180.00	•	34.81	Total:	214.81	
Workorder: Problem:	1309628 Left rear tire g	Meter: oing flat.	27677		I	n Date:	09/24/2013	Closed:	09/30/20	013
- Repair and	balance left rea	r tires.			Parts List	:				Qty
- Shop Supplies					Shop Sup	plies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1311428 P.M. service a	Meter:	29926 essure light o	n.	I	n Date:	11/12/2013	Closed:	11/25/20	013
- P.m. Service					Parts List					Qty
	- P.m. Service. - Test and replace right rear strobe lamp Rewire as needed.									6.00
	rear tire,rotate		-	neeueu.	5w20 Eng Napagold					1.00
- Shop Suppl			ce all lour.		Washer Fl					1.00
- Shop Suppl	1105				Vtx609c L					1.00
					Shop Sup	niies				1 00
	Hour	s 5.00		Labor:	Shop Sup 300.00	-	146.74	Total:	446.74	1.00
Workorder: Problem:	: 1403035	Meter:	34784 n slips and sl		300.00	Parts: n Date:	146.74 03/28/2014	Total: Closed:	446.74 04/07/20	
Problem:	: 1403035 Pm service.Tr	Meter:			300.00	Parts: n Date: ly.				014
Problem: - Perform pm	: 1403035 Pm service.Tr service.	Meter: ansmissio	n slips and sl	hifts hard i	300.00	Parts: n Date: ly.				014 Qty
Problem: - Perform pm - Diagnose tra	: 1403035 Pm service.Tr	Meter: ansmissio	n slips and sl des found.ren	hifts hard i	300.00 Intermittent Parts List 5w20 Eng	Parts: n Date: ly. ine Oil				014 Qty 6.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb	: 1403035 Pm service.Tr service. ansmission for s smantle,clean an	Meter: ansmissio slip.no coo nd lube sli	n slips and sl des found.ren p joint splines	hifts hard i nove s asper	300.00 Intermittent Parts List 5w20 Eng Napagold	Parts: n Date: ly. ine Oil Oil Filter	03/28/2014			014 Qty 6.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting	: 1403035 Pm service.Tr service. ansmission for s smantle,clean and g and charging s	Meter: cansmissio slip.no coo nd lube sli system.ba	n slips and sl des found.rem p joint splines ttery failed lo	hifts hard i nove s asper	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold	Parts: n Date: ly. ine Oil Oil Filter Air Filter	03/28/2014			014 Qty 6.00 1.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean and g and charging a e.replace failed	Meter: cansmissio slip.no coo nd lube sli system.ba battery wit	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac	Parts: n Date: ly. ine Oil Oil Filter Air Filter de	03/28/2014			014 Qty 6.00 1.00 1.00 2.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean and g and charging a s.replace failed new tires.nitroge	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb	03/28/2014			014 Qty 6.00 1.00 1.00 2.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 1.00 2.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 1.00 2.00 1.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea Washer Fl	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 2.00 1.00 1.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea Washer Fl 235 75r17	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 2.00 1.00 1.00 1.00 4.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea Washer Fl 235 75r17 Battery 65	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 2.00 1.00 1.00 1.00 4.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea Washer Fl 235 75r17 Battery 65 Repair Kit	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner	03/28/2014			014 Qty 6.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - Perform pm - Diagnose tra drive shaft,dis Tsb - Test starting after recharge - Install four r - Perform who	: 1403035 Pm service.Tr a service. ansmission for a smantle,clean an g and charging a c.replace failed new tires.nitroge eel alignment c	Meter: ansmissio slip.no coo nd lube sli system.ba battery wit en fill and	n slips and sl des found.rem p joint splines ttery failed loo h new.	hifts hard i nove s asper ad test	300.00 Intermittent Parts List 5w20 Eng Napagold Napagold Wiper Blac Used Fire Brake Clea Washer Fl 235 75r17 Battery 65 Repair Kit Adhesive	Parts: n Date: ly. ine Oil Oil Filter Air Filter de X Refurb aner Adventur	03/28/2014			014 Qty 6.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1

Workorder: Problem:	1404581 damage to lft	Meter: rear fende	35301 r, tail lgt & ta	il gate		In Date:	04/30/2014	Closed:	05/12/20)14
- damage to If	t rear fender, t	ail lgt & tai	l gate							
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1409482 Pm service	Meter:	39819			In Date:	09/22/2014	Closed:	10/03/20)14
- Pm service.					Parts L	ist				Qty
- Rotate and balance all four tires.					5w20 E	ngine Oil				6.00
- Shop Suppli	es				Napago	old Oil Filter				1.00
					Bigg De	egreaser				1.00
					Wiper E	Blade				2.00
					Stg Wh	eel Cov - Fo	rd			1.00
					Shop S	upplies				1.00
	Hour	s 3.00		Labor:	180.00	Parts:	56.00	Total:	236.00	
Workorder: Problem:	1412323 Key switch ma	Meter: alfunction,	42390 wont start ev	ery time.le	ft turnsig	In Date: Inal inop.	12/09/2014	Closed:	01/15/20)15
	agnose for inte				Parts L	ist				Qty
control module		m all Pats			Module Bulb					1.00 2.00
•	lace both left r		inal lamp bul	bs.	Shop S	upplies				1.00
	hicle to and fro	om dealer	•							
- Shop Suppli	es									
	Hour :	s 5.50		Labor:	330.00	Parts:	216.74	Total:	546.74	
Workorder: Problem:	1501536 Difficult to mo	Meter: ve gear sh	43848 ifter out of pa	ark intermi	ttently.	In Date:	02/11/2015	Closed:	02/19/20)15
- Computer di	agnose difficu	It to move	gear shifter		Parts L	ist				Qty
intermittently.c	odes C116a,p	0504 and I	-0572.pinpoi		Switch					1.00
and replace de with scan tool.		ight switch	and clear al	l codes	Shop S	upplies				1.00
- Shop Suppli	es									
	Hour	s 2.50		Labor:	150.00	Parts:	33.26	Total:	183.26	

Workorder: Problem:	1502622 Pm service.	Meter:	45007		Ir	Date:	03/12/2015	Closed:	03/20/201	5
- Pm service.					Parts List				(Qty
- Rotate and b	balance all fou	r tires.			5w20 Engi	ne Oil			6	6.00
- Shop Suppli	ies				Napagold (Oil Filter			1	00.1
					Napagold /	Air Filter			1	00.1
						uid Conc	entr		1	00.1
					Used Fire 2	X Refurb	ished		1	00.1
					Wiper Blad	le			2	2.00
					Shop Supp	olies			1	00.1
	Hou :	rs 3.00		Labor:	180.00	Parts:	57.64	Total:	237.64	
Workorder: Problem:	1506397 Over heating	Meter:	48605		Ir	Date:	06/25/2015	Closed:	07/06/201	5
- Diagnose ov	verheating test	fan poerat	ion.ok.pressure	e test	Parts List					Qty
cooling system.replace leaking water pump and thermostat.flush cooling system and refill.test drive.					Thermosta	t Gasket			1	00. I
		tem and rei	ill.test drive.		Hose Clam	р			2	2.00
- Shop Suppli	les				Water Purr	пр			1	00.1
					Thermosta	t			1	00.1
					Gasket				1	.00
					Gasket Ford Red A	Antifreeze	Э			
							e		1	00.1
	Hou	rs 5.00		Labor:	Ford Red A	olies	e 197.81	Total:	1	1.00 1.00 1.00
	Hou : 1510329 Pm service.	rs 5.00 Meter:	50117	Labor:	Ford Red A Shop Supp 300.00	olies		Total: Closed:	1 1	00.1 1.00
	: 1510329 Pm service.		50117	Labor:	Ford Red A Shop Supp 300.00	olies Parts:	197.81		1 497.81 10/27/2013	00.1 1.00
Problem: - Pm service.	: 1510329 Pm service.	Meter:	50117 and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List	Parts:	197.81		1 497.81 10/27/2013	1.00 1.00 5
Problem: - Pm service. - Replace def	: 1510329 Pm service.	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List	Parts: Parts: Date: ne Oil	197.81		1 497.81 10/27/2013 6	1.00 1.00 5 Qty
Problem: - Pm service. - Replace def - Replace def	: 1510329 Pm service. fective left rear	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List 5w20 Engin	Parts: Parts: Date: ne Oil Oil Filter	197.81		1 497.81 10/27/2013 6 1	1.00 1.00 5 Qty 6.00
Problem: - Pm service. - Replace def - Replace def - Rotate and b	: 1510329 Pm service. fective left rear fective driver so balance all fou	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List 5w20 Engin Napagold (Parts: Parts: Date: ne Oil Oil Filter	197.81		1 497.81 10/27/2013 6 1 2	1.00 1.00 5 Qty 5.00
Problem: - Pm service. - Replace def - Replace def - Rotate and b	: 1510329 Pm service. fective left rear fective driver so balance all fou	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List 5w20 Engin Napagold (Wiper Blad	olies Parts: Date: ne Oil Dil Filter le	197.81		1 497.81 10/27/2013 6 1 2 2	1.00 1.00 5 Qty 1.00 2.00
Problem: - Pm service. - Replace def - Replace def - Rotate and b	: 1510329 Pm service. fective left rear fective driver so balance all fou	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List 5w20 Engin Napagold 0 Wiper Blad Bulb	olies Parts: Date: ne Oil Dil Filter le	197.81		1 497.81 10/27/2013 6 1 2 2 2 1	1.00 1.00 5 Qty 3.00 1.00 2.00
- Pm service. - Replace def - Replace def	: 1510329 Pm service. fective left rear fective driver so balance all fou	Meter:	and brake lam		Ford Red A Shop Supp 300.00 Ir Parts List 5w20 Engin Napagold 0 Wiper Blad Bulb Stg Wheel	olies Parts: Date: ne Oil Dil Filter le Cov - Fo	197.81		1 497.81 10/27/2013 6 1 2 2 1 1	1.00 1.00 5 Qty 1.00 2.00 1.00

Workorder: Problem:	1601987 Pm service.Lo	Meter: eft turnsign	55099 al.Topper do	or hinge ri	vets.	In Date:	02/25/2016	Closed:	03/07/20	16
- Pm service.		- 0.1	,,	0	Parts Li	st				Qty
	ective left turns	signal and	brake lamp b	ulb	5w20 Er		6.00			
•	pair and secur	•	•			d Oil Filter				1.00
	balance all fou		0.1			d Air Filter				1.00
	oth front brake			n front	22" Wipe		2.0			
-	replace front b	orake pads			Floor Ma	at-2pc Rub I	Bk			1.00
- Shop Suppli	es				Bulb					1.00
					kit brak					1.00
					Shop Su					1.00
	Hou :	rs 7.50		Labor:	450.00	Parts:	144.83	Total:	594.83	
Workorder: Problem:	1609455 P.M. service.	Meter:	60670			In Date:	09/12/2016	Closed:	09/27/20	16
- P.m. Service	э.				Parts Li	st				Qty
- Test battery	ery.	5w20 Er	ngine Oil				6.00			
- Flush and re	efill transmissio	on.			Napagol		1.00			
- Replace tew	vo tires,rotate a	and balance	e all four.		Used Fir	e X Refurbi	ished			1.00
- Ddiagnose a	and replace de	fective bler	nd door asser	nble.	20" Wipe	er Blade				2.00
	haft and clean a	and lube sl	ip joint to corr	rect	Battery					1.00
clunling at stop	p and take-on. heel alignment	tost drivo				Trans Fluid			1	14.00
- Shop Suppli	•				235 75r1		2.00			
Click Output					Repair K					1.00
					motor As	•				1.00 1.00
					Shop Su Tire Disr	pplies posal Fee				2.00
	Ноч	rs 11.75		l abor	705.00		704.60	Total	1,409.60	
	:				, 00.00	1 0113.	, 0-1.00	i otal.	1,400.00	,
Workorder: Problem:	1609960 2 - Wash tick	Meter: et(s) issued	60670 d			In Date:	09/23/2016	Closed:	09/23/20	16
- 2 - Wash ticl	ket(s) issued									
	Hour	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1612613 Will not come	Meter:	63653 k at times.			In Date:	12/08/2016	Closed:	01/02/20)17
Problem:		ne out of pa	ark sometime	.replace	Parts Li	st				Qty
- Diagnose sh	nifter won't com				Outlinele					
- Diagnose sh defective shiof	ft lock solenoid				Switch					1.00
- Diagnose sh	ft lock solenoid				Switch Shift Kit	Tram				1.00 1.00
- Diagnose sh defective shiof	ft lock solenoid									

Workorder:	1700969	Meter:	65061			In Date:	01/31/2017	Closed:	02/14/2017	
Problem:	Right rear tire	e flat ,spare	e on truck.							
- Repair and b	balance right r	ear tire.			Parts Li	st			Q	
- Shop Suppli	es				Shop Su	pplies			1.0	
	Hou :	rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1702273 P.M. service.	Meter:	66238			In Date:	03/06/2017	Closed:	03/16/2017	
- P.m. Service	Э.				Parts Li	st			Q	
- Replace two	- Replace two tires, rotate and balance all four.								6.0	
- Inspect and		Napagol	d Oil Filter			1.0				
- Replace worn out oil fller cap.						er Blade			2.0	
- Shop Suppli	es				Washer	Fluid Conc	entr		1.0	
					235 75r1	7 Adventu	re		2.0	
					75w140	Ford Axle I	_ube		3.0	
					Friction I	Modifier			1.(
						a Grey 3oz	<u></u>		1.0	
					Oil Cap /	-			1.0	
						or Brake Cli	nr		1.0	
					Shop Su				1.0	
						osal Fee			2.0	
	Hou :	rs 5.25		Labor:	315.00	Parts:	561.27	Total:	876.27	
Workorder: Problem:	1704920 1 - Wash tick	Meter: et(s) issue	66729 d			In Date:	05/17/2017	Closed:	05/17/2017	
- 1 - Wash ticl	ket(s) issued									
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1708591 P.M. service.	Meter:	69329			In Date:	08/30/2017	Closed:	09/07/2017	
- P.m. service					Parts List G					
- Balance and	I rotate all four	r tires.			5w20 Engine Oil					
- Shop Suppli	es					d Oil Filter			1.0	
					Used Fir	e X Refurb	ished		1.0	
					Mac Wite	e Lithium G	ires		1.0	
					Wd40 Sp	or			1.0	
					22" Wipe Shop Su				2.0 1.0	

Labor: 180.00

Parts: 52.54

Total: 232.54

Hours 3.00

:

Workorder:1710780Meter:74701Problem:P.M. service.		In	Date:	10/31/2017	Closed:	11/16/2	017
- P.m. service.		Parts List					Qty
- Rotate and high speed balance all four tires.		5w20 Engi	ne Oil				6.00
- Shop Supplies		Napagold (1.00
		22" Wiper I					2.00
		Napagold A					1.00
		Shop Supp					1.00
Hours 3.00	Labor:	180.00		34.40	Total:	214.40	
Workorder: 1802275 Meter: 79787 Problem: P.M. service and water leak right doo	or and real		Date:	02/28/2018	Closed:	03/15/2	018
- P.m. service.		Parts List					Qty
- Remove and replace left rear tail light lens aasemb	oly	5w20 Engi	ne Oil				6.00
.fabricate and installed strobe light in new lens.		Napagold (Dil Filter				1.00
- Rotated and balanced all four tires .nitrogen filled a		22" Wiper I	Blade				2.00
- Leak test cab .remove and reinstall bed topper to access for rear glass reseal.	allow	Lamp Assembly					1.00
- Shop Supplies		Clr Rtv Silcn Sealant 1.					
		Shop Supp	lies				1.00
Hours 5.50 :	Labor:	330.00	Parts:	190.75	Total:	520.75	
Workorder: 1802551 Meter: 79471 Problem: reseal rear window		In	Date:	03/08/2018	Closed:	03/13/2	018
- set up repairs and get Do		Parts List					Qty
- Shop Supplies		Shop Supp	lies				1.00
Hours 1.00	Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:1808844Meter:84017Problem:P.M. service and washers inop.		In	Date:	08/27/2018	Closed:	09/04/2	018
- P.m. service.		Parts List					Qty
- Computer diagnose wipers inop . monitor pids . R8	٦r	Napagold (Dil Filtor				1.00
defective multifunction switch and washer jets.		5w20 Engi					6.00
- Rotate and high speed balance all four tires.		22" Wiper I					2.00
- Shop Supplies		Washer No					2.00
		Switch	2210				1.00
		Shop Supp	lies				1.00
Hours 5.00	Labor:	300.00		93.37	Total:	393.37	1.00
Workorder: 1812517 Meter: 87435 Problem: Blower inop on speed one and cracke	ad windsh		Date:	12/10/2018	Closed:	12/13/2	018
							. .
- Test and replace blower resistor . Retest.		Parts List	• .				Qty
- Shop Supplies		Blower Res					1.00
		Shop Supp					1.00
Hours 0.60	Labor:	10.20	Dorte	37.59	Total	77.79	

:

Workorder: Problem:	1812565 repair chippe	Meter: ed windsheil	87435 Id			In Date:	12/11/2018	Closed:	12/13/2018
- set up repair	rs & inspect			Parts L	ist			Qty	
- Shop Suppli	es				Shop S	upplies			1.00
	Hou :	ırs 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00
Workorder: Problem:	1900223 2 - Wash tick	Meter: (s) issued	87952 d			In Date:	01/04/2019	Closed:	01/04/2019
- 2 - Wash ticl	ket(s) issued								
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1900954 Transition Pr	Meter: ep Charge	88925			In Date:	01/25/2019	Closed:	01/25/2019
- Transition P	rep Charge								
	Hou :	ırs 2.00		Labor:	134.00	Parts:	0.00	Total:	134.00