Workorder: 745568	Problem	: PRE-DE	LIVERY INSPECTIO	N		
Meter Reading: 0			Labor		Parts	
In Date: 10/15/2007	Close Date: 10/15	6/2007	Hours	Description		Quantity
- Pre-Delivery Inspection			2.00			
	Parts Charge:	0.00	Labor Charge:	120.00		
Workorder: 746444	Problem	: 001 KEY	ISSUED OUT	10/30/07		
Meter Reading: 0			Labor		Parts	
In Date: 10/30/2007	Close Date: 10/30	/2007	Hours	Description		Quantity
- 001 Key Issued Out	10/30/07		0.20	UPLICATE VEHICLE KEYS		1.00
	Parts Charge:	3.00	Labor Charge:	0.00		
Workorder: 746504	Problem	TRAILE	R WIRING FAULT			
Meter Reading: 333		-	Labor		Parts	
In Date: 10/31/2007	Close Date: 11/07	/2007	Hours	Description		Quantity
- Replace Blown Fuse To	Marker Lights And Repair	r Wires	1.00 1	5319477 FUSE 30 AMP GMC		1.00
In Tailer Plug. - Shop Supplies	<u> </u>		-	HOP SUPPLIES		1.00
	Parts Charge:	3.72	Labor Charge:	60.00		
Workorder: 746833	Problem	: INSTALI	_ TOOL BOX			
Meter Reading: 357			Labor		Parts	
In Date: 11/06/2007	Close Date: 11/07	/2007	Hours	Description		Quantity
- Install Toolbox In Back 0	Df Bed		1.00 T	BSD72LP TOOL BOX (UNITED W	ELDING)	1.00
				```	,	
- Shop Supplies			S	HOP SUPPLIES		1.00

Vorkorder: 835542	Proble	m: INSTALL	LADDER RACK		
Meter Reading: 4377			Labor	Parts	
In Date: 03/14/2008	Close Date: 03/	25/2008	Hours	Description	Quantity
- Fabricate & Install Ladder R	lack.		6.25	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Pm Service				CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
<ul> <li>Shop Supplies</li> </ul>				USED FIREX REFURBED FIRE EXTINGSHERS	1.00
				SHOP SUPPLIES	1.00
				CA10270 AIR FILTER MTC FA1886 WIX 49886	-1.00
				1372 OIL FILTER FRM PH2 WIX 51372	1.00
				31-20 WIPER BLADES 20" BLADE	2.00
				5W20 ENGINE OIL	7.00
				CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
				LADDER RACK	1.00
I	Parts Charge:	399.09	Labor Charge	e: 165.00	

Vorkorder: 841247	Probl	em: A/C INSF	PECTION,STROBE	ES INOP		
Meter Reading: 8726			Labor		Parts	
In Date: 07/11/2008	Close Date: 07	7/23/2008	Hours	Description		Quantity
- Strobe Beacon Inop.Diag (	Circuit,R&R Strobe E	Beacon	4.50	66BR CLEAR SILICONE		1.00
Assy, Had Rewire & Fabric	ae For New Beacor	n To Fit		SHOP SUPPLIES		1.00
Retest,Ok				684-51081 STROBE (ALTEC)		1.00
- Ac Sys Blowing Warm Air.I	nspect, Test And Dia	ag Sys.Ac				
Sys Leaking, Send To De	ale To Repair.					
- To/From Dealer For Ac Re	pairs.					
- Shop Supplies						
	Parts Charge:	195.39	Labor Charge	: 60.00		

Meter Reading: 1032	2		Labor		Parts	
In Date: 09/09/2008	Close Date: 09/12	/2008	Hours	Description		Quantity
- Pm Service			<b>5.25</b> C/	10262 AIR FILTER	MTC FA1883 WIX 49883	1.00
- Check Brake Message.	Replace Trailer Brake Lig	ht	5V	V20 ENGINE OIL		7.00
Socket & Regired. Had			SH	IOP SUPPLIES		1.00
- Rotate, Balance, Nitro F	•		G	0166 FUEL FILTER	MTC FG1083 WIX 33243	1.00
- Shop Supplies			US	SED FIREX REFURB	BED FIRE EXTINGSHERS	1.00
			31	-20 WIPER BLADES	20" BLADE	2.00
			13	72 OIL FILTER FR	M PH2 WIX 51372	1.00
			54	04 FEMALE CONNE	CTOR	1.00
	Parts Charge:	85.95	Labor Charge:	60.00		
Workorder: 847188 Meter Reading: 1281 In Date: 11/18/2008	Problem: 9 Close Date: 11/18		IN L/F TIRE Labor Hours	Description	Parts	Quantity
- Repair R/F Tire.Nitro Fil	ll Tire.Train Tps System.		1.00 TF	416 VALVE STEM		1.00
<ul> <li>Shop Supplies</li> </ul>			SH	IOP SUPPLIES		1.00
	Parts Charge:	3.89	Labor Charge:	60.00		
	Problem:	SISTER	S TOWING & TRANS	PORTATON TOW FF	ROM SR FLEET -	
Workorder: 932249			Labor		Parts	
Workorder: 932249 Meter Reading: 0						
	Close Date: 01/05	/2009	Hours	Description		Quantity
Meter Reading: 0 In Date: 12/31/2008	Close Date: 01/05 portaton Tow From Sr Flee		Hours	Description		Quantity
Meter Reading: 0 In Date: 12/31/2008			Hours	Description		Quantity

Workorder: 933691	Proble	em: P.M SEF	RVICE			
Meter Reading: 15441			Labor		Parts	
In Date: 02/06/2009	Close Date: 02	/13/2009	Hours	Description		Quantity
- Pm Service			3.75	SHOP SUPPLIES		1.00
<ul> <li>Rotate &amp; High Speed Balar</li> </ul>	nce All 4 Tires. Nitro	Fill Tires.		5W20 ENGINE OIL		7.00
<ul> <li>Shop Supplies</li> </ul>				31-20 WIPER BLADES 20" BLADE		2.00
				1372 OIL FILTER FRM PH2 WIX	51372	1.00
	Parts Charge:	33.15	Labor Charg	<b>e:</b> 225.00		

Meter Reading: 20972			Labor		Parts	
In Date: 07/02/2009	Close Date: 07	7/07/2009	Hours	Description		Quantity
- P.M Service			9.25	5W20 ENGINE OIL		7.00
- Mount Two New Tires, Rot	ate & Balance All F	our Tires		1372 OIL FILTER FRM PH2 WIX 5	1372	1.00
- Replace Blown R/R Tail Lig	ght Bulb			CA10262 AIR FILTER MTC FA1883	WIX 49883	1.00
- Alignment				USED FIREX REFURBED FIRE EXT	TINGSHERS	1.00
- Flush & Clean A/C Evapor	ator Core, Deoderiz	e A/C Vents		TIRE DISPOSAL FEE		2.00
- Shop Supplies	,			3157 TAIL LIGHT BULBS		1.00
				G10166 FUEL FILTER MTC FG1083	3 WIX 33243	1.00
				SHOP SUPPLIES		1.00
				TR416 VALVE STEM		2.00
				179636492 LT245/75R17 WRANGLE	ER SR-A E	2.00
	Parts Charge:	419.63	Labor Charge	: 555.00		

Workorder: 946635	Problem: Check	brake lights.			
Meter Reading: 26049		Labor		Parts	
In Date: 12/03/2009	Close Date: 12/04/2009	Hours	Description		Quantity
- Check All Lights & Replace	e L/R Brake Light Bulbs.	0.50	3157 TAIL LIGHT BULBS		2.00
	Parts Charge: 1.59	Labor Charg	<b>e:</b> 60.00		

Workorder: 1008961

## Palm Beach County Fleet Management Asset Maintenance History

### Asset: 10170993 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Norkorder: 1000636	Problem: pm servi	ce ,also has to ji	ump start all the time	
Meter Reading: 27015		Labor	Parts	
In Date: 01/15/2010	Close Date: 01/29/2010	Hours	Description	Quantity
- P.M Service.		7.75	TIRE DISPOSAL FEE	2.00
- Mount Two New Tires, Rota	ate & Balance All Four Tires.		SHOP SUPPLIES	1.00
- Test Starting & Charging S	ystem, Charge & Test Battery,		FLOOR MATS	1.00
Replace Failed Battery.			GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- To/From Dealer For Warren	ntv Floor Mat.		TR416 VALVE STEM	2.00
- Shop Supplies	-,		179636492 LT245/75R17 WRANGLER SR-A E	2.00
			31-20 WIPER BLADES 20" BLADE	2.00
			5W20 ENGINE OIL	7.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00
	Parts Charge: 594.70	Labor Char	ge: 405.00	

**Problem:** Pm service. Also check engine light on, Stalls and see notes on tail gate.

Meter Reading: 33930			Labor	Parts	
In Date: 08/19/2010	Close Date: 09	/08/2010	Hours	Description	Quantity
P.M. Service.			6.50	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Replace Center Brake Larr	ıp Bulb.			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Replace Missing Tailgate N	loulding.			SHOP SUPPLIES	1.00
Rotate And Balance All Tir	es.			NB-19 WIPER BLADES 19" ANCO 31-19	2.00
Transport Vehicle To Deale	er For Defective Fue	l Pump.		TAILGATE MOLDING	1.00
Shop Supplies				1372 OIL FILTER FRM PH2 WIX 51372	1.00
chick cabburg				5W20 ENGINE OIL	7.00
				CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
	Parts Charge:	91.44	Labor Charg	<b>je:</b> 330.00	

			ice also see notes on a	c inop.		
Meter Reading: 40308			Labor		Parts	
In Date: 03/09/2011	Close Date: 03/	15/2011	Hours	Description		Quantity
- Perform Pm Service.			5.75 CY	CLING SWITCH		1.00
- Ac Performance Test.Tes	st And Replace Failed	Ac		20 ENGINE OIL		7.00
Compressor Cycling Swit			137	2 OIL FILTER FRM PH2 V	NIX 51372	1.00
- Rotate And Balance All F			SH	OP SUPPLIES		1.00
- Test And Replace Failed	Dome Lamp Bulb With	New.	NB-	19 WIPER BLADES 19" AN	NCO 31-19	2.00
- Shop Supplies						
	Parts Charge:	46.59	Labor Charge:	345.00		
Vorkorder: 1103521	Proble	m: Screw rig	ght rear tire.			
Meter Reading: 40740			Labor		Parts	
In Date: 04/01/2011	Close Date: 04/	07/2011	Hours	Description		Quantity
- Repair Flat Right Rear Ti	re.Nitrogen Fill And Ba	lance	1.00 SH	OP SUPPLIES		1.00
Same.	Ū					
- Shop Supplies						
	Parts Charge:	44.00	Labor Charge:	60.00		
	-		-			
<b>Vorkorder</b> : 1108239	Proble	m: P.M. ser	vice and cup holder bro	ken.		
Vorkorder: 1108239 Meter Reading: 45139		m: P.M. ser	vice and cup holder bro Labor	ken.	Parts	
			•	ken. Description	Parts	Quantity
Meter Reading: 45139			Labor Hours	Description		
Meter Reading: 45139 In Date: 08/05/2011	Close Date: 08/	18/2011	Labor Hours 8.25 137	Description 2 OIL FILTER FRM PH2 V	NIX 51372	1.00
Meter Reading: 45139           In Date: 08/05/2011           -         P.M. Service.	Close Date: 08/	18/2011 r.	Labor Hours 8.25 137 31-2	Description	WIX 51372 ADE	1.00 2.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI	<b>Description</b> 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA	WIX 51372 ADE E EXTINGSHERS	1.00 2.00 1.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10	<b>Description</b> 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243	1.00 2.00 1.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10 CA	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FG	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883	1.00 2.00 1.00 1.00 1.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31-3 USI G10 CA 179	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FG 10262 AIR FILTER MTC FA	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883	1.00 2.00 1.00 1.00 1.00 2.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10 CA 179 5W	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FG 10262 AIR FILTER MTC FA 636492 LT245/75R17 WRA	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883 NGLER SR-A E	1.00 2.00 1.00 1.00 1.00 2.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10 CA 179 5W WD	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FG 10262 AIR FILTER MTC FA 636492 LT245/75R17 WRA 20 ENGINE OIL	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883 NGLER SR-A E	1.00 2.00 1.00 1.00 1.00 2.00 7.00 1.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10 CA 179 5W WD SH0	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FO 10262 AIR FILTER MTC FA 636492 LT245/75R17 WRA 20 ENGINE OIL 40 SPRAY LUBE STOCK#	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883 NGLER SR-A E	1.00 2.00 1.00 1.00 2.00 7.00 1.00 1.00
Meter Reading: 45139 In Date: 08/05/2011 - P.M. Service. - Replace Two Tires,Rotate - Remove Dash Panel And - Complete Wheel Alignme	Close Date: 08/ e And Balance All Fou d Replace Broken Cup	18/2011 r.	Labor Hours 8.25 137 31- USI G10 CA 179 5W WD SH0 CU	Description 2 OIL FILTER FRM PH2 V 20 WIPER BLADES 20" BLA ED FIREX REFURBED FIRE 0166 FUEL FILTER MTC FA 10262 AIR FILTER MTC FA 636492 LT245/75R17 WRA 20 ENGINE OIL 40 SPRAY LUBE STOCK# 5 OP SUPPLIES	WIX 51372 ADE E EXTINGSHERS G1083 WIX 33243 1883 WIX 49883 NGLER SR-A E	1.00 2.00 1.00 1.00 1.00 2.00 7.00

Workorder: 1205154

# Palm Beach County Fleet Management Asset Maintenance History

### Asset: 10170993 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1200497	Problem:	Pm service				
Meter Reading: 50583			Labor		Parts	
In Date: 01/17/2012	Close Date: 01/25/2	012	Hours	Description		Quantity
- P.M. Service.			6.25	SHOP SUPPLIES		1.00
- Service Transmission.Flush	n And Refill System.			NB-19 WIPER BLADES 19" ANCO 3	31-19	2.00
- Rotate And Balance All Tire	es.			SYN/ATF TRANS FLUID SYNTHETI	С	16.00
- Shop Supplies				5W20 ENGINE OIL		7.00
				1372 OIL FILTER FRM PH2 WIX 5	1372	1.00
				FT-180 TRANS FILTER (MTC)		1.00
	Parts Charge: 1	177.57 <b>I</b>	Labor Charg	<b>je:</b> 375.00		

#### **Problem:** P.M. service and right side running board cracked.

Meter Reading: 55397		Labor	Parts	
In Date: 06/01/2012	Close Date: 06/19/2012	Hours	Description	Quantity
- P.M. Service.		5.75	RH RUNNING BOARD	1.00
- Replace Two Tires,Rotate	And Balance All Four.		5W20 ENGINE OIL	7.00
- Replace Broken Right Side	e Step.		TR416 VALVE STEM	2.00
- Shop Supplies			SHOP SUPPLIES	1.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00
			TIRE DISPOSAL FEE	2.00
			179636492 LT245/75R17 WRANGLER SR-A E	2.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			31-20 WIPER BLADES 20" BLADE	2.00
	Parts Charge: 762.65	Labor Char	rge: 345.00	

Workorder: 1206294	Problem: Left re	ar signal light out.			
Meter Reading: 55787		Labor		Parts	
In Date: 07/05/2012	Close Date: 07/11/2012	Hours	Description		Quantity
- Replace Rear Signal Light	Bulbs.	0.50	3157 TAIL LIGHT BULBS		1.00
	Parts Charge: 0.60	Labor Charg	ge: 30.00		

Workorder: 1211153	Problem:	Pm servic	e and head light	inop.		
Meter Reading: 61008			Labor		Parts	
In Date: 11/16/2012	Close Date: 11/30/	2012	Hours	Description		Quantity
- Perform Pm Service.			4.50	SHOP SUPPLIES		1.00
- Replace Failed Right Side I	Headlamp Sealbeam As	ssembly		5W20 ENGINE OIL		7.00
With New.		-		31-20 WIPER BLADES 20		2.00
- Rotate And Balance All Fou	ır Tires.			USED FIREX REFURBED F		1.00
- Shop Supplies				H6054 SEALED BEAM		1.00
				PH2 OIL FILTER LBF PH		1.00
				FORD FUEL FILTER		1.00
	Parts Charge:	87.52	Labor Charg	e: 270.00		

Workorder: 1303196	Problem:	Had to jump start in A/	m and misses under load.		
Meter Reading: 64859 In Date: 04/02/2013	Close Date: 04/05	/2013 Hours	Description	Parts	atitu
<ul> <li>Test Starting And Charging S Loadtest After Recharge.Reg New.</li> <li>Perform Air Induction Servic Body.Power Flush Injectors S With Scan Tool And Road To</li> <li>Computer Diagnose For Mis Failed Spark Plugs With New Coils With New.Clear Codes Test.Install New Steering Wit</li> <li>Shop Supplies</li> </ul>	System.Battery Failed blace Failed Battery W e And Clean Trottle And Fuel Lines.Clear ( est. fire.Test And Replace v.Replace #8 And #6 I With Scan Tool And F	8.00 /ith Codes Eight Ignition	Description 408 FUEL INJECTION CL COIL STG WHEEL COV - FORD KA8A THROTTLE BODY- U SPARK PLUG BATTERY 65 SHOP SUPPLIES 5068 PENETRANT LUBE P	Qua	1.00 2.00 1.00 1.00 8.00 1.00 1.00 1.00
P	arts Charge:	540.19 Labor Ch	arge: 480.00		

Workorder: 1311377

## Palm Beach County Fleet Management Asset Maintenance History

### Asset: 10170993 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1304903	Problem:	Pm service				
Meter Reading: 66099			Labor		Parts	
In Date: 05/16/2013	Close Date: 05/29/	2013	Hours	Description		Quantity
- P.M. Service.			5.75	31-20 WIPER BLADES 20		2.00
- A/C Blower Low Speed Inor	o.Replace Defective Blo	ower		PEDAL PAD		1.00
Resistor.				BLOWER RESISTOR		1.00
- Inspect And Service Rear D	)ifferential.			NAPAGOLD AIR FILTER		1.00
- Rotate And Balance All Tire				ULTRA GREY RTV SILICONE		1.00
- Shop Supplies				5W20 ENGINE OIL		7.00
				NAPAGOLD OIL FILTER		1.00
				SHOP SUPPLIES		1.00
				C8AZ19B546A ADDITIVE		2.00
				75W140 GEAR LUBE SYNT		3.00
I	Parts Charge:	165.57	Labor Char	rge: 345.00		

#### Problem: Pm service.Right brake lamp inop and tail gate cap fell off.

Meter Reading: 71136	Labor		Parts
In Date: 11/08/2013 Close Date: 11/25/20	013 Hours	Description	Quantity
- P.M. Service.	14.00	NAPAGOLD FUEL FILTER	1.00
- Replace Center Brake Light And Right Brake Light B	ulb.	5W20 ENGINE OIL	7.00
- Resurface Front And Rear Brake Rotors, Replace Fro	ont	REAR PADS	1.00
And Rear Brake Pads.Service And Lube All Four		PADS	1.00
Calipers, Flush And Bleed System.		179636492 LT245-75R17	2.00
- Replace Two Tires, Rotate And Balance All Four.		BULB	1.00
- Replace Tail Gate Cap.		WIPER BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		USED FIRE X REFURBISHED	1.00
		NAPAGOLD OIL FILTER	1.00
		MOULDING	1.00
		TR416 VALVE STEM	2.00
		TIRE DISPOSAL FEE	2.00
		BRAKE CLEANER	2.00
		2232 BRAKE FLUID QUAR	2.00
Parts Charge: 8	04.83 Labor Chai	rge: 840.00	

Norkorder: 1312300	Problem:	Left brake	e lamp inop.			
Meter Reading: 71457			Labor		Parts	
In Date: 12/10/2013	Close Date: 12/13/2	2013	Hours	Description		Quantity
- Test And Replace Failed I	Left Brake Lamp Bulb Wit	h New.	0.50	BULB		1.00
	Parts Charge:	0.99	Labor Charge	e: 30.00		
<b>Vorkorder:</b> 1404979	Problem:	Pm servi	ce.			
Meter Reading: 76643			Labor		Parts	
In Date: 05/22/2014	Close Date: 06/05/2	2014	Hours	Description		Quantity
- P.M. Service.			10.25	5W20 ENGINE OIL		7.00
- Replace Two Tires, Rotate	And Balance All Four.			NAPAGOLD OIL FILTER		1.00
- R&R Driveshaft And Repla	ace Leaking Pinion Seal.			NAPAGOLD AIR FILTER		1.00
- Complete Wheel Alignmei	nt.Test Drive.			WIPER BLADE		2.00
- Shop Supplies				75W140 FORD AXLE LUBE		4.00
				PTEX ULTRA GREY 30Z		1.00
				SHOP SUPPLIES		1.00
				FRICTION MODIFIER		2.00
				SEAL		1.00
				TIRE DISPOSAL FEE		2.00
				179636492 LT245-75R17		2.00
	Parts Charge:	684.65	Labor Charge	e: 615.00		

Workorder: 1410818	Problem	: Pm servic	e.Power outlet	and trailer plug inop.		
Meter Reading: 81718			Labor		Parts	
In Date: 10/29/2014	Close Date: 11/12	2/2014	Hours	Description		Quantity
<ul> <li>Pm Service.</li> <li>Inspect Front End For Loos Upper And Lower Ball Joint Wheel Bearings.</li> <li>Test And Replace Defective Repair Wiring As Needed.A</li> <li>Rotate And Balance All Fou Perform Complete Wheel A</li> <li>Shop Supplies</li> </ul>	eness.Replace Left Ar s.Clean And Repack F e Trailer Plug Socket A Ilso Replace Lighter Fu ır Tires.	nd Right Front and use.	12.30	SHOP SUPPLIES NAPAGOLD OIL FILTER NAPAGOLD FUEL FILTER BULB WASHER NOZZLE UPPER BALL JOINT LOWER BALL JOINT USED FIRE X REFURBISHED 5W20 ENGINE OIL WIPER BLADE bumper		1.00 1.00 1.00 2.00 2.00 2.00 1.00 7.00 2.00 1.00 1.00
				Wheel Seal - Front Wheel		2.00
				FUSE		1.00
				TRAILER CONN SOCKET		1.00
I	Parts Charge:	251.60	Labor Char	r <b>ge:</b> 738.00		

Workorder: 1500255	Proble	m: No powe	r from trailer plug.			
Meter Reading: 84185			Labor		Parts	
In Date: 01/08/2015	Close Date: 01/	13/2015	Hours	Description		Quantity
- Test Trailer Plug Circiuts F	or No PowerReplac	e Open 30	1.00	SHOP SUPPLIES		1.00
Amps Fuse.Short In Trailer	Send Trailer To Se	Shop.		FMX-30 FUSE		1.00
<ul> <li>Shop Supplies</li> </ul>						
	Parts Charge:	6.65	Labor Charge	60.00		

Workorder: 1501811	Proble	em: Right rea	ar tire flat.			
Meter Reading: 85656			Labor		Parts	
In Date: 02/19/2015	Close Date: 02	/26/2015	Hours	Description		Quantity
- Replace And Balance One	Damage Tire.		0.50	179636492 LT245-75R17		1.00
<ul> <li>Shop Supplies</li> </ul>				TIRE DISPOSAL FEE		1.00
				SHOP SUPPLIES		1.00
	Parts Charge:	265.51	Labor Charge	e: 30.00		

### Asset: 10170993 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

#### Problem: Pm service.Cup holder broken.Trailer harness message on dash.

Workorder: 1503474	Problem:	Pm service.Cup holder b	roken.Trailer harness message on das	sh.	
Meter Reading: 87790 In Date: 04/03/2015	Close Date: 04/28/20	Labor 015 Hours	Description	Parts Quanti	ty
<ul> <li>Pm Service.</li> <li>Inspect And Replace Defectiv Arm Bump Stop.</li> <li>Remove Dash Panel And Rep</li> <li>Perform Coolant Service.Flusi</li> <li>Inspect And Replace Two Def Mounts/Insulators.</li> <li>Rotate And Balance All Four 1</li> <li>Shop Supplies</li> </ul>	olace Defective Cupholo h And Refill Engine Coo rective Front Frame To	der olant.	MACS BATTERY CLEANER SHOP SUPPLIES NAPAGOLD AIR FILTER TRAILER CONN SOCKET BODY MOUNT KIT PEAK GLOBAL BIGG DEGREASER 5W20 ENGINE OIL bumper NAPAGOLD OIL FILTER WIPER BLADE HOLDER		1.00 1.00 1.00 2.00 2.00 1.00 7.00 1.00 1.00 2.00 1.00
Pa	rts Charge: 35	51.83 Labor Chai			1.00

Workorder: 1600267	Problem:	Pm service.				
Meter Reading: 98222			Labor		Parts	
In Date: 01/08/2016	Close Date: 01/26/	2016	Hours	Description	Quant	ity
- P.M. Service.			<b>8.25</b> 5	W20 ENGINE OIL		7.00
- Test Battery And Charging S	ystem.Replace Bad Ba	attery.	Ν	APAGOLD FUEL FILTER		1.00
- Replace Two Tires, Roatae A	nd Balance All Four.		2	0" WIPER BLADE		2.00
- Complete Wheel Alignment.T	Fest Drive.		Ν	APAGOLD OIL FILTER		1.00
- Shop Supplies			Т	R416 VALVE STEM		2.00
			Т	IRE DISPOSAL FEE		2.00
			В	ATTERY		1.00
			U	SED FIRE X REFURBISHED		1.00
			Ν	APAGOLD AIR FILTER		1.00
			S	TG WHEEL COV - FORD		1.00
			S	HOP SUPPLIES		1.00
			1	79636492 LT245-75R17		2.00
Pa	arts Charge:	711.27	Labor Charge:	495.00		

Workorder: 1602377	Problem:	Flat tire rep	bair				
Meter Reading: 99256			Labor		Parts		
In Date: 03/02/2016	Close Date: 03/04/2	2016	Hours	Description			Quantity
- Tire Service 454 West Co	ourt - Flat Tire Repair						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	161.59	
Workorder: 1602380	Problem:	Emergency	/ Tire Servie				
Meter Reading: 99256			Labor		Parts		
In Date: 03/03/2016	Close Date: 03/04/2	2016	Hours	Description			Quantity
- Tire Service 154 West Ct	- Emergency Tire Servie						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	51.56	
Workorder: 1605408	Problem:	Left side m	irror knocked off.				
Meter Reading: 102369	9		Labor		Parts		
In Date: 05/25/2016	Close Date: 05/31/2	2016	Hours	Description			Quantity
- R&R Driver Door Panel A	nd Replace Broken Door	Mirror	1.00 SI	HOP SUPPLIES			1.00
Assemble.			Μ	IRROR ASY			1.00
- Shop Supplies	Parts Charge:	203.53	Labor Charge:	60.00			
Workorder: 1606822	Problem:	P.M. servic	e and check engine	e light on runs rough.			
Meter Reading: 102840			Labor	5 5	Parts		
In Date: 07/06/2016	Close Date: 07/19/	2016	Hours	Description			Quantity
- P.M. Service.			11.25 N	APAGOLD OIL FILTEF	र		1.00
- Service And Clean Thrott	le Body And Induction		C	OIL			3.00
System.Flush Injectors.				" WIPER BLADE			2.00
- Diagnose Check Engine L	Light, Multiple Misfire			PARK PLUG			8.00
Codes Replace Spark Di	0 / 1		וח				1.00
	ugs And Three Coils.						
- Replace Right Back Up La	ugs And Three Coils. amp.		SI	HOP SUPPLIES			1.00
<ul> <li>Replace Right Back Up Li</li> <li>Rotate And Balance All Ti</li> </ul>	ugs And Three Coils. amp.		SI 5V	HOP SUPPLIES W20 ENGINE OIL			1.00 7.00
- Replace Right Back Up La	ugs And Three Coils. amp.		SI 5V SC	HOP SUPPLIES V20 ENGINE OIL OCKEY ASSY			1.00 7.00 1.00
<ul> <li>Replace Right Back Up Li</li> <li>Rotate And Balance All Ti</li> </ul>	ugs And Three Coils. amp.		SI 5V S( IN	HOP SUPPLIES W20 ENGINE OIL			1.00 7.00

Workorder: 1607931	Problem:	Check e	ngine light on and tailgate	e protector fell off.		
Meter Reading: 103772			Labor		Parts	
In Date: 08/02/2016	Close Date: 08/30/	2016	Hours	Description		Quantity
- Replace Missing Tailgate Edge Moulding.			2.50 SHO	P SUPPLIES		1.00
- Transport Vehicle To Deal Converters.	ler For Defective Catalyti	C	MOU	LDING		1.00
- Shop Supplies	Parts Charge:	86.54	Labor Charge:	150.00		
<b>Workorder:</b> 1609191	Problem:	Left brak	e light inop.			
Meter Reading: 104232			Labor		Parts	
In Date: 09/02/2016	Close Date: 09/21/	2016	Hours	Description		Quantity
- Replace Left Brake Lamp Bulb.			0.50 BULE	3		2.00
	Parts Charge:	1.56	Labor Charge:	30.00		
Workorder: 1610832	Problem:	Transitic	n Prep Charge			
Meter Reading: 104844			Labor		Parts	
In Date: 10/20/2016	Close Date: 10/20/	2016	Hours	Description		Quantity
- Transition Prep Charge			2.00			
	Parts Charge:	0.00	Labor Charge:	0.00		
Total Parts C	Charges: 8,413.7	'8	Total Labor Charg	es: 9,168.00	Total Comm. Charges:	291.15