10169460 2007 CHEVROLET UPLANDER Mini Van, 7 Passenger

	101	69460	2007 CHEVR	OLEIU	PLANDE	R Mini van	, / Passenge	r		
Workorder: Problem:	736301 PRE-DELIVE	Meter: RY INSPE	0 ECTION			In Date:	03/28/2007	Closed:	03/28/20	007
- Pre-delivery	Inspection									
	Houi :	rs 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	745803 P.M SERVICI	Meter:	1930			In Date:	10/17/2007	Closed:	10/23/20	007
- Perform Pm	Service Comp	lete			Parts Li	st				Qty
	Body Of Vehic				Shop Su	ıpplies				1.00
	High Spedd Ba cern When Driv		4 Tires To Cori	rect ine		Oil Filter W	ix 51522			1.00
Around Turns	ront Tire Wear perform Whee As Per Print C	l Alignmei			10w30 N	Motor Oil				5.00
- Shop Suppl										
	Houi :	rs 6.25		Labor:	375.00	Parts:	16.40	l otal:	391.40	
Workorder: Problem:	838173 P.M SERVICI	Meter:	3513			In Date:	05/07/2008	Closed:	05/09/20	800
- Pm Service					Parts Li	st				Qty
- Rotate Ck A	and High Speed	d Balance	All 4 Tires.		Shop Su	ıpplies				1.00
- Shop Suppli	es				Ca7597	Air Filter Lb	f Af7872 Wix	46302		1.00
					Ph9837	Oil Filter W	ix 51522			1.00
					10w30 N	Notor Oil				5.00
					31-22 W	iper Blades/	22" Wiper Bl	ade		1.00
						Viper Blades				1.00
	Hour :	rs 3.75		Labor:	225.00	Parts:	32.55	Total:	257.55	
Workorder: Problem:	847250 P.M SERVICI	Meter:	5039			In Date:	11/19/2008	Closed:	11/22/20	800
- Pm Service					Parts Li	st				Qty
- Rotate And	Hi Speed Bala	nce 4 Tire	s.nitrofill Tires.		Shop Su	ıpplies				1.00
- Shop Suppli	es				Ph9837	Oil Filter W	ix 51522			1.00
					10w30 N	Notor Oil				5.00
					1066 W	hite Lithium	(crc 05037)			1.00
					31-16 W	/iper Blades	16" Wiper Bl	ade		1.00
					31-22 W	/iper Blades	22" Wiper Bl	ade		1.00
					31-24 V	Viper Blades	s 24" Blade			1.00
	Hour :	rs 3.75		Labor:	225.00	Parts:	37.52	Total:	262.52	
	848489 SISTERS TO				W FROM	In Date: BLDG 508	12/22/2008 O	Closed:	12/22/20	800
	ing & Transpor of Belvedere - 1		From Bldg 50	8 Off Of						

Labor: 0.00

Hours 0.00

Parts: 0.00

Total: 0.00

Workorder: Problem:	848492 TOWED	IN,NO	Meter: START	5345			In Date:	12/22/2008	Closed:	12/24/20	800
- Test Starting Andtest Batter - Shop Suppli	y.battery			· Sys Draw C	k.charge	Parts Li Shop St					Qty 1.00
		Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	938585 P.M. SEF	RVICE	Meter:	6493			In Date:	06/03/2009	Closed:	06/09/20	009
- Pm Service						Parts L	ist				Qty
- Balance 4 T	ires. Nitro	Fill.				Shop St	upplies				1.00
- Shop Suppli	es					Ph9837	Oil Filter W	ix 51522			1.00
						10w30 N	Motor Oil				5.00
		Hours :	3.75		Labor:	225.00	Parts:	19.67	Total:	244.67	
Workorder: Problem:	941616 Bolt in L/	F tire	Meter:	6968			In Date:	08/04/2009	Closed:	08/04/20	009
- Repair L/f tir	e					Parts L	ist				Qty
- Shop Suppli	es					Shop St	upplies				1.00
		Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	942914 Key fob i	nop	Meter:	7180			In Date:	09/03/2009	Closed:	09/10/20	009
- Replace & re	eprogram	new k	ey fob.			Parts L	ist				Qty
- Shop Suppli	es					Shop St	upplies				1.00
						Key Fob)				1.00
		Hours :	1.00		Labor:	60.00	Parts:	59.75	Total:	119.75	
Workorder: Problem:	946636 P.M serv	ice.	Meter:	7883			In Date:	12/03/2009	Closed:	12/14/20	009
- P.m service.	ı					Parts L	ist				Qty
- Rotate & bal	ance all fo	our tire	es.			Shop St					1.00
- Shop Suppli	es						Oil Filter W	ix 51522			1.00
							Motor Oil		_		5.00
							•	22" Wiper Bl	ade		1.00
			0.75				Niper Blades		.	050 50	1.00
		Hours :	3.75		Labor:	225.00	Parts:	28.50	l otal:	253.50	
Workorder: Problem:	1004817 no start		Meter:	8798			In Date:	05/10/2010	Closed:	05/10/20	010
- From: 508 b	elverdere	To:	lv shop								
		Hours	•		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1004820 Towed in, dea	Meter: ad battery.	8876			In Date:	05/10/2010	Closed:	05/11/20	010
- Test starting	& charging sy	stem, rech	arge & test	battery, all	Parts Li	st				Qty
systems ok at	this time.			-	Shop Su	ıpplies				1.00
- Shop Suppli	es									
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1006456 Pm service.	Meter:	9218			In Date:	06/18/2010	Closed:	06/24/20	010
- Perform pm	service.				Parts Li	st				Qty
- Repair right	rear tire and ba	alance san	ne.		Shop Su	ıpplies				1.00
- Shop Suppli	es				Ph9837	Oil Filter W	ix 51522			1.00
					Ca7597	Air Filter Lb	of Af7872 Wix	46302		1.00
					09997 E	Brake Clear)			1.00
					10w30 N	Notor Oil				5.00
					31-22 W	iper Blades	22" Wiper Bla	ade		1.00
					31-24 V	Viper Blade:	s 24" Blade			1.00
					31-16 W	iper Blades	16" Wiper Bla	ade		1.00
	Hour	s 3.75		Labor:	225.00	Parts:	41.03	Total:	266.03	
Workorder: Problem:	1100937 P.M. service.	Meter:	10567			In Date:	01/25/2011	Closed:	02/09/20	011
- Perform pm	service.				Parts Li	st				Qty
- Test starting	and charging	system.ba	ttery failed l	oad test	Shop Su	ıpplies				1.00
•	replace failed.	-	h new.		Ph9837	Oil Filter W	ix 51522			1.00
- Rotate and I	palance all four	r tires.			10w30 N	/lotor Oil				5.00
- Shop Suppli	es				31-22 W	iper Blades	22" Wiper Bla	ade		1.00
					31-24 V	Viper Blade	s 24" Blade			1.00
					31-16 W	iper Blades	16" Wiper Bla	ade		1.00
					Group 3	4 Battery (a	icd 34ps)			1.00
	Hour	s 4.75		Labor:	285.00	Parts:	136.99	Total:	421.99	
Workorder: Problem:	1108812 Pm service.	Meter:	11970			In Date:	08/19/2011	Closed:	08/25/20	011
- Perform pm	service.				Parts Li	st				Qty
-	palance all four	r tires.			Shop Su					1.00
- Shop Suppli						Oil Filter W	ix 51522			1.00
11- F.					10w30 N		-			5.00
							s 24" Blade			1.00
							22" Wiper Bla	ade		1.00
						•	16" Wiper Bla			1.00
	Hou	s 3.75		Labor:	225.00	•	31.93		256.93	
	:									

Workorder: Problem:	1113462 no start	. Mete	er: 21554			In Date:	12/27/2011	Closed:	12/27/2	011
- Tow From: k	oldg 508	To: lv shop)							
	Ü	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1113468 Towed in	Meten for start/no				In Date:	12/27/2011	Closed:	12/30/2	011
left on.		ttery and ch	arging syste	em.dome light		_ist Supplies				Qty 1.00
- Shop Suppli	es	Hours 0.75		Labor:	45.00	Parts:	2.00	Total:	47.00	
Workorder: Problem:	1202447 P.M. ser	Mete				In Date:	03/12/2012	Closed:	03/27/2	012
- Perform pm	service.				Parts L	_ist				Qty
		d remote for	door entry	with new and	Shop S	Supplies				1.00
reprogram with			!		Ph9837	7 Oil Filter W	ix 51522			1.00
- Remove driv bezel/trim with		acess and	repiace fail	ed seat		Motor Oil				5.00
- Rotate and I	palance a	Il four tires.				Wiper Blade				1.00
- Shop Suppli	es					•	22" Wiper Bl			1.00
						•	16" Wiper Bl	ade		1.00
						Cover Seat Pa				1.00
		Hours 5.50		Labor	330.00	e Keyless En	126.84	Totalı	456.84	1.00
		: :		Labor.	330.00	rails.	120.04	i Olai.	430.04	
Workorder: Problem:	1208606 Pm serv		er: 13911			In Date:	09/11/2012	Closed:	09/26/2	012
- P.m. Service	Э.				Parts L	_ist				Qty
- Rotae and b	alance al	l tires.			Shop S	Supplies				1.00
- Shop Suppli	es				Ph9837	7 Oil Filter W	ix 51522			1.00
					Cabin A	Air Filter				1.00
					10w30	Motor Oil				5.00
		Hours 3.75 :		Labor:	225.00	Parts:	28.11	Total:	253.11	
Workorder: Problem:	1302789 Pm serv		er: 14876			In Date:	03/21/2013	Closed:	03/28/2	013
- Perform pm	service.				Parts L	_ist				Qty
- Rotate and I	oalance a	ll four tires.			10w30	Motor Oil				5.00
- Shop Suppli	es				Napago	old Oil Filter				1.00
					Washe	r Fl				1.00
					31-24	Wiper Blade	s 2			1.00
						Niper Blades				1.00
						Niper Blades	: 16			1.00
					•	Supplies		_		1.00
		Hours 3.00		Labor:	180.00	Parts:	37.58	Total:	217.58	

Workorder: Problem:	1309373 Pm service.	Meter:	15961		ı	n Date:	09/16/2013	Closed:	09/30/2013	3
- P.m. Service	Э.				Parts List	t				Qty
- Rotate and	balance all tires	S.			10w30 Motor Oil					5.00
- Shop Suppli					Napagold			.00		
					31-24 Wij		s 2			.00
					Wiper Blad				1	.00
					31-16 Wip		s 16		1	.00
					Shop Sup				1	.00
	Hour :	rs 3.75		Labor:	225.00		33.76	Total:	258.76	
Workorder:	1402918	Meter:	17028		I	n Date:	03/26/2014	Closed:	04/03/201	4
Problem:	P.M. service.									
- Perform pm	service.				Parts List	:				Qty
- Replace bro	ken tailgate sil	plate cap	with new.		10w30 Mc	tor Oil			5	5.00
	ew tires to the	front whee	ls.nitrogen fi	ll and	Napagold	Oil Filter		1	.00	
balance all for	ır.				Napagold Air Filter					.00
- Perform who	eel alignment complete. 738168571 225-60r17							2	2.00	
- Shop Suppli	ies				Plate				1	.00
					Shop Sup	plies			1	.00
					Tire Dispo	sal Fee			2	2.00
	Hour :	s 7.55		Labor:	453.00	Parts:	445.19	Total:	898.19	
Workorder: Problem:	1409650 Pm service	Meter:	18170		I	n Date:	09/25/2014	Closed:	10/08/2014	4
- Pm service.					Parts List	:				Qty
- Check batte	ry and charging	g Battery fa	ailed loadtes	t.replace	10w30 Mc	tor Oil			5	5.00
defective batte	ery.				Napagold	Oil Filter			1	.00
•	tires.rotate an	d balance	all four.		31-24 Wij	per Blade	s 2		1	.00
- Shop Suppli	ies				Wiper Blad	de			1	.00
					Wiper Blad	de			1	.00
					Group 34	Battery			1	.00
					73816857	1 225-60)r17		2	2.00
					Shop Sup	plies			1	.00
					Tire Dispo	sal Fee			2	2.00
	Hour	s 5.75		Labor:	345.00	Parts:	500.34	Total:	845.34	
Workorder:	1500564	Meter:	18268		I	n Date:	11/18/2014	Closed:	01/15/201	5
Problem:	damage to lft	rear fende	r & hub cap,	repaint rea	ar bumper					
- damage to l	ft rear fender &	hub cap,	repaint rear l	oumper						
	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Problem: Left brake and tail lights inop.	2/26/2015
- Diagnose for left brake and tail lights inop.pin point test and repair damage connector pin for tail lights circuit.also replace one back up lamp bulb. Shop Supplies	Qty 1.00 1.00
- Shop Supplies	1.00
Hours 1.00 Labor: 60.00 Parts: 2.75 Total: 6	2.75
Workorder: 1503264 Meter: 18939 In Date: 03/30/2015 Closed: 0 Problem: Pm service.	4/07/2015
- Pm service. Parts List	Qty
- Rotate and balance all four tires. 10w30 Motor Oil	5.00
- Shop Supplies Napagold Oil Filter	1.00
Wiper Blade	1.00
31-24 Wiper Blades 2	1.00
Brake Cleaner	1.00
Shop Supplies	1.00
Hours 3.75 Labor: 225.00 Parts: 32.24 Total: 2	57.24
Workorder: 1508516 Meter: 19789 In Date: 08/25/2015 Closed: 0 Problem: Ac Blows warm from left side vents.	8/31/2015
- Ac performance and leak test.evacuate,vacuum and Parts List	Qty
recharge system to specs.use scan tool to recalibrate Hvac system doors.replace cabin air filter.test drive.	2.00
- Shop Supplies	1.00
E8 A/c Oil Univ W Dye	1.00
Shop Supplies	1.00
Hours 3.00 Labor: 180.00 Parts: 32.99 Total: 2	12.99
Workorder: 1509786 Meter: 19944 In Date: 09/28/2015 Closed: 1 Problem: Pm service.	0/13/2015
- Pm service. Parts List	Qty
- Rotate and balance all four tires. 10w30 Motor Oil	5.00
- Shop Supplies Napagold Oil Filter	1.00
Wiper Blade	1.00
·	
Shop Supplies Hours 3.75 Labor: 225.00 Parts: 33.46 Total: 2	58.46
Shop Supplies Hours 3.75 Labor: 225.00 Parts: 33.46 Total: 2	1/19/2016
Shop Supplies Hours 3.75 Labor: 225.00 Parts: 33.46 Total: 2	1/19/2016
Shop Supplies Hours 3.75 Labor: 225.00 Parts: 33.46 Total: 2	1/19/2016 Qty
Shop Supplies Hours 3.75 Labor: 225.00 Parts: 33.46 Total: 2 Workorder: 1512920 Meter: 20537 Problem: Remote inop. Replace one defective remote and program all with scan Parts List	1/19/2016

Workorder: Problem:	1603206 P.M. service.	Meter:	20959		lr	n Date:	03/28/2016	Closed:	04/06/20)16
- Pm service.					Parts List					Qty
	ng and chargin			oadtest	10w30 Mo	tor Oil				5.00
after recharge	•	•	'.		Napagold (Oil Filter				1.00
	palance all four	r tires.			Wiper Blac		1.00			
- Shop Suppli	es				22" Wiper	Blade				1.00
					Wiper					1.00
					Group 78 E	Battery				1.00
					Shop Supp	olies				1.00
	Houi	rs 4.75		Labor:	285.00	Parts:	127.10	Total:	412.10	
Workorder: Problem:	1609497 P.M. Service.	Meter:	21928		İr	n Date:	09/13/2016	Closed:	09/29/20)16
										01
- P.m. Service	€.				Parts List					Qtv
	e. palance all tires	S.			Parts List Napagold	Oil Filter				-
- Rotate and b	palance all tires		g assemble.				:			1.00
- Rotate and b	oalance all tires		g assemble.		Napagold (5w30 Qt				1.00
- Rotate and brace right	oalance all tires		g assemble.		Napagold (5w30 Qt Air Filter				1.00 6.00
- Rotate and brace right	oalance all tires		g assemble.		Napagold (Napa Syn Napagold /	5w30 Qt Air Filter les 24"				1.00 6.00 1.00
- Rotate and brace right	oalance all tires		g assemble.		Napagold (Napa Syn Napagold (Wiper Blace	5w30 Qt Air Filter les 24"				1.00 6.00 1.00 1.00 1.00
- Rotate and brace right	oalance all tires		g assemble.		Napagold (Napa Syn Napagold (Wiper Blac 22" Wiper	5w30 Qt Air Filter des 24" Blade				1.00 6.00 1.00 1.00 1.00
Rotate and bReplace right	oalance all tires		g assemble.		Napagold (Napa Syn Napagold (Wiper Blac 22" Wiper Wiper	5w30 Qt Air Filter des 24" Blade uid Conc				1.00 6.00 1.00 1.00 1.00
Rotate and bReplace right	oalance all tires		g assemble.		Napagold (Napa Syn Napagold (Wiper Blac 22" Wiper Wiper Washer Flu	5w30 Qt Air Filter des 24" Blade uid Conc sy				1.00 1.00 1.00 1.00
Rotate and bReplace right	oalance all tire: nt front hub/wh		g assemble.	Labor:	Napagold (Napa Syn Napagold (Wiper Black 22" Wiper Wiper Wiper Washer Fluck L/f Hub As	5w30 Qt Air Filter des 24" Blade uid Conc sy blies		Total:	514.75	1.00 6.00 1.00 1.00 1.00 1.00 1.00
- Rotate and burners - Shop Suppli	oalance all tire: nt front hub/wh	rs 4.25 Meter:	g assemble.	Labor:	Napagold (Napa Syn Napagold (Wiper Black 22" Wiper Wiper Wiper Washer Fluck L/f Hub As Shop Supp 255.00	5w30 Qt Air Filter des 24" Blade uid Conc sy blies	entr	Total:	514.75	1.00 6.00 1.00 1.00 1.00 1.00 1.00
- Rotate and burners - Replace right - Shop Supplication - Shop Su	Hour :	rs 4.25 Meter: al inop.		Labor:	Napagold (Napa Syn Napagold (Wiper Black 22" Wiper Wiper Wiper Washer Fluck L/f Hub As Shop Supp 255.00	5w30 Qt Air Filter des 24" Blade uid Conc sy blies Parts:	entr 259.75			1.00 6.00 1.00 1.00 1.00 1.00 1.00
- Rotate and burners - Replace right - Shop Supplication - Shop Su	Hour : 1701282 Left turn signs	rs 4.25 Meter: al inop.		Labor:	Napagold (Napa Syn Napagold (Wiper Black 22" Wiper Wiper Washer Flo L/f Hub As Shop Supp 255.00	5w30 Qt Air Filter des 24" Blade uid Conc sy blies Parts:	entr 259.75			1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: 1702588 Meter: 22873 Problem: P.M. service.		In	Date:	03/14/2017	Closed:	03/29/2017
- P.m. Service.		Parts List				Qty
- Replace two tires,rotate and balance all four.		10w30 Mot	or Oil			5.00
- Pressure test and inspect cooling system.flush and refi	Ш	Napagold (Oil Filter			1.00
system.		Mac Wite L	ithium G	res		1.00
- Replace worn out bump stoppers.		Wiper Blad	es 24"			1.00
- Replace broken center brake lamp.		22" Wiper E		1.00		
- Complete wheel alignment.test drive.		Wiper				1.00
- Shop Supplies		738168571	225-60	r17		2.00
		Dex Coolar	nt Engine	;		2.00
		Stop Bump	er			2.00
		Lamp				1.00
		Shop Supp	lies			1.00
		Tire Dispos	sal Fee			2.00
Hours 9.50 La	abor:	570.00	Parts:	596.84	Total:	1,166.84
Workorder: 1706713 Meter: 23369 Problem: Rear liftgate falls down.		In	Date:	07/10/2017	Closed:	07/17/2017
- Test and replace both liftgate gas struts.retest.		Parts List				Qty
- Shop Supplies		Lift Gate				2.00
		Shop Supp	lies			1.00
Hours 0.50 La	abor:	30.00	Parts:	61.46	Total:	91.46
Workorder: 1707534 Meter: 23446 Problem: Left front seat back panel fell off.		In	Date:	08/01/2017	Closed:	08/03/2017
- Repair seat back panel .obsolete part .no longer availib	ole.					
	abor:	36.00	Parts:	0.00	Total:	36.00
Workorder: 1708143 Meter: 23494 Problem: Towed in for gear shifter broken.		In	Date:	08/17/2017	Closed:	08/22/2017
- Diagnoise shifter.r&r broken shifter cable.adjust cable		Parts List				Qty
.retest.		Cable				1.00
- Shop Supplies		Shop Supp	lies			1.00
Hours 1.50 La	abor:		Parts:	88.00	Total:	178.00
Workorder: 1708153 Meter: 23466 Problem: Gear Shifter broke on Van		In	Date:	08/17/2017	Closed:	08/18/2017
- Tow From: Banyan and Quadrill Loading Dock To: Lv	shop					
	abor:	0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	1709048 P.M. service	Meter:	23604		ı	In Date:	09/20/2017	Closed:	09/27/20	017
- P.m. service	2 .				Parts Lis	t				Qty
	high speed ba	lance all fo	ur tires.		5w20 Eng	ine Oil				5.00
- Shop Suppl	•				Napagold					1.00
					Wiper Bla	des 24"				1.00
					22" Wiper	Blade				1.00
					Wiper					1.00
					Shop Sup	plies				1.00
	Ηοι :	urs 3.75		Labor:	225.00	Parts:	26.45	Total:	251.45	
Workorder: Problem:	1802723 P.M. service	Meter:	24093		l	In Date:	03/13/2018	Closed:	03/22/20	018
- P.m. service	Э.				Parts Lis	t				Qty
	orakes.r&i worı				Napagold	Oil Filter				1.00
rotors and ser .road test.	vice calipers .	flush and b	eed brake s	ystem	Washer F	luid Conc	entr			1.00
	replace glove	box door la	tch Replac	e tailnate	Wiper					1.00
pull strap with		box door id	ion i repiae	o tangato	Wiper Bla	des 24"				2.00
- Shop Suppl	ies				22" Wiper					1.00
					Non-chlor		nr			1.00
					brake fluid					1.00
					Real Brak	e Pad				1.00
					Latch					1.00
					Strao	0.1				1.00
					10w30 Mo					5.00
	I I a	7.05		l ab an	Shop Sup	•	000.50	Tatal	000.50	1.00
	HOU :	urs 7.05		Labor:	423.00	Parts:	260.59	ı otai:	683.59	
	Right front se	eat back fel			I	In Date:	07/24/2018	Closed:	07/25/20	018
 Reinstall rig screws. 	ht front seat b	ack panel a	ind secure w	vith						
	Ηοι :	urs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	
Workorder:	1809404 P.M. service	Meter:	24546		l	n Date:	09/12/2018	Closed:	09/28/20	018
	1 301 1100									01
Problem:					Parts Lis	τ				Qty
Problem: - P.m. service - Diagnose de	e. ome lamp inop			or panel	Napagold					1.00
Problem: - P.m. service - Diagnose de and window m	e. ome lamp inop nodule to repla	ace door lat	ch . Retest.	•		Oil Filter				-
Problem: - P.m. service - Diagnose de and window m - Rotate and	e. ome lamp inop nodule to repla high speed ba	ace door lat	ch . Retest.	•	Napagold	Oil Filter jine Oil				1.00
Problem: - P.m. service - Diagnose de and window m - Rotate and	e. ome lamp inop nodule to repla high speed ba	ace door lat	ch . Retest.	•	Napagold 5w20 Eng	Oil Filter gine Oil Blade				1.00 5.00
Problem: - P.m. service - Diagnose de and window m - Rotate and	e. ome lamp inop nodule to repla high speed ba	ace door lat	ch . Retest.	•	Napagold 5w20 Eng 22" Wiper	Oil Filter gine Oil Blade				1.00 5.00 1.00
Problem: - P.m. service - Diagnose de and window m	e. ome lamp inop nodule to repla high speed ba	ace door lat	ch . Retest.	•	Napagold 5w20 Eng 22" Wiper Wiper Bla	Oil Filter gine Oil Blade des 24"	entr			1.00 5.00 1.00 1.00
Problem: - P.m. service - Diagnose de and window m - Rotate and	e. ome lamp inop nodule to repla high speed ba	ace door lat	ch . Retest.	•	Napagold 5w20 Eng 22" Wiper Wiper Bla Wiper	Oil Filter gine Oil Blade des 24"	entr			1.00 5.00 1.00 1.00 1.00
Problem: - P.m. service - Diagnose de and window m - Rotate and	e. ome lamp inop nodule to repla high speed ba ies	ace door lat	ch . Retest.	Nitrofill all.	Napagold 5w20 Eng 22" Wiper Wiper Bla Wiper Washer F	Oil Filter gine Oil Blade des 24" luid Conce	entr 187.16		514.16	1.00 5.00 1.00 1.00 1.00

:

Workorder: 1902665 Meter: 24775 Problem: P.M. service .	In Date: 03/11/2019	Closed: 03/22/2019
 P.m. service. Charge battery fully . Load test battery . Battery failed load test . R&r defective battery . Replace two tires . Rotate and balance all four tires . Nitrofill all . Perform four wheelalignment and test drive . Remove and replace faded front asset number. 	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Wiper Blades 24" 22" Wiper Blade Mac Wite Lithium Gres	Qty 5.00 1.00 1.00 1.00 1.00
- Shop Supplies	Battery 738168571 225-60r17 Shop Supplies Tire Disposal Fee	1.00 2.00 1.00 2.00
Hours 8.75 Labor:	586.25 Parts: 492.57	Total: 1,078.82
Workorder: 1904259 Meter: 24775 Problem: Transition Prep Charge	In Date: 04/18/2019	Closed: 04/18/2019
- Transition Prep Charge Hours 2.00 Labor:	134.00 Parts: 0.00	Total: 134.00