10175095 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: Problem:	937370 PRE-DE	LIVER	Meter:				In Date:	05/04/2009	Closed:	05/04/2009
- Pre-delivery	Inspectio	n								
		Hours	4.00		Labor:	240.00	Parts:	0.00	Total:	240.00
Workorder: Problem:	942426 Hyd. leal	k	Meter:	2013			In Date:	08/24/2009	Closed:	08/28/2009
- replace hyd.	. line from	tank t	o crane			Parts Li	ist			Qty
- shop to fl. m	ango					Shop Su	upplies			1.00
- Shop Suppli	es					Aw68 H	ydro Fluid H	lydraulic Oil 6	8	20.00
		Hours :	6.00		Labor:	360.00	Parts:	49.51	Total:	409.51
Workorder: Problem:	947112 P.M serv	vice.	Meter:	4823			In Date:	12/16/2009	Closed:	01/06/2010
- P.m service						Parts Li	ist			Qty
- Mount two n	ew tires 8	k balar	nce, perfo	rm nitro ser	vice on all	Big G D	egreaser St	ock# 4851800	002	1.00
six tires.						Shop St	upplies			1.00
- Inspect & se compartment,							lydraulic Fil			1.00
- Alignment.				3-				Ch9549 Wix 5		1.00
- Shop Suppli	es							(use Cs1026	3a )	1.00
						15/40 C				15.00
							/iper Blades		_	2.00
								d Fire Extings	shers	1.00
							alve Stem			2.00
							posal Fee	5.47 W	. 0	2.00
			40.50		Laban			5r17 Wrangle		2.00
		Hours :	10.50		Labor:	630.00	Parts:	503.03	i otai:	1,133.03
Workorder: Problem:	1011196 P.M. Ser		Meter:	11789			In Date:	10/12/2010	Closed:	10/25/2010
- P.m. Service	Э.					Parts Li	ist			Qty
- Replace mis	sing pintle	e pin.				Shop St	upplies			1.00
- Replace fou	r tires,rota	ate and	d balance	all six.		7312 O	il Filterfrm (	Ch9549 Wix 5	7312	1.00
- Inspect and	service cı	rane.				Cs1026	3 Fuel Filter	(use Cs1026	3a )	1.00
- Shop Suppli	es					8c3z9a3	343a Seal k	Kit Fuel Filter	(ford)	1.00
						15/40 C	Dil			15.00
								d Fire Extings	shers	1.00
							liper Blades			2.00
								5r17 Wrangle	r Sr-a E	4.00
							posal Fee			4.00
							alve Stem			4.00
							Pintle Pin		_	1.00
		Hours :	8.25		Labor:	495.00	Parts:	903.38	Total:	1,398.38

Workorder: Problem:	1011875 reflash canceiv	Meter: /er	11801			In Date:	10/25/2010	Closed:	10/26/2010
- Flash Cance	eiver				Parts Li	ist			Qty
- Shop Suppli	ies				Shop Su	upplies			1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	1101223 Dead battery,h	Meter: ave to jur	14223 mp start.			In Date:	02/01/2011	Closed:	02/07/2011
- Recharge be test, replace be	oth batteries and oth batteries.	d retest.bo	oth failed load	d	Parts Li				<b>Qt</b> y
<ul> <li>Repair ground wire to power switch for crane.retorque hydraulic fittings inside bin and clean oil.</li> <li>Shop Supplies</li> </ul>					•	• •	ntc Bxt-65-850	0)	2.00
Chop Guppii		3.50		Labor:	210.00	Parts:	259.49	Total:	469.49
Workorder: Problem:	1105300 Pm service.	Meter:	16424			In Date:	05/18/2011	Closed:	06/06/2011
- Perform pm	service.				Parts Li	ist			Qty
- Test and rep	olace failed rock	er switch	for light bar w	vith new.	Shop Su	upplies			1.00
	ew tires to the fi	ront whee	ls.nitrogen fill	and	51551 H	lydraulic Filt	ter		1.00
balance all six					7312 O	il Filterfrm C	Ch9549 Wix 5	7312	1.00
	service crane.re new,reposition a			lter	Cs1026	3 Fuel Filter	(use Cs1026	3a )	1.00
_	d install new as:			nd rear	Ca1027	0 Air Filter N	∕Itc Fa1886 W	/ix 49886	1.00
	placing damage			ia roai	15/40 C	Dil			15.00
- Perform who	eel alignment co	mplete.			Aw68 H	ydro Fluid H	lydraulic Oil 6	8	2.00
- Shop Suppli	ies					ilter Adapte	,		1.00
							ats (rubber Q	ueen)	1.00
						/iper Blades	20" Blade		2.00
						cker Switch			1.00
							5r17 Wrangle	r Sr-a E	2.00
						posal Fee			2.00
						alve Stem			2.00
	Hours	12.50		Labor:	750.00	Pintle Pin Parts:	595.35	Total:	1.00 1,345.35
Workorder: Problem:	: 1112420 no start and f/o	Meter:	20022			In Date:	11/22/2011	Closed:	11/22/2011
- From: 8100	forest hill blvd	To: lv sł	пор						
		0.00	•	Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder:	1112436	:	Meter:	20239			In Date:	11/22/2011	Closed:	12/12/2011
					art and left f	ront tire l		11/44/4011	Gioseu.	12/12/2011
- Perform pm	service					Parts Li	ist			Qty
- Inspect and		vdraulio	crane t	est and ren	lace failed	Shop Su				1.00
right side out r	igger high	n press				•	lydraulic Filt	tor		1.00
hose and top	off fluid le	vel.					•	Ch9549 Wix 5	57312	1.00
- Install two n		o the fro	ont whee	els.nitrogen	fill and			m Cs10263a		1.00
balance all six						15/40 C		III 05 10203a	VVIX 33903	15.00
- Fabricate ar	•	e failed	tag lamp	assembly	with new.					
- Shop Suppli	es					-		# 450240010	- h - u -	2.00
								d Fire Extings	sners	1.00
							ag Light (tk	,	0 5	1.00
								5r17 Wrangle	er Sr-a E	2.00
						_	alve Stem			2.00
							posal Fee			2.00
							-	en Hyd Tank		
							-	se 1/4" Msha		10.00
		Hours	9.50		Labor:	570.00	Parts:	609.44	Total:	1,179.44
Workorder: Problem:	1200830 L/R FLA		Meter:	20575			In Date:	01/20/2012	Closed:	01/26/2012
- Tire Service Flat Tire	Marginal	Rd. an	d 7th Pla	ace off of Pi	ioneer - L/r					
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1200832 tires	2	Meter:	20575			In Date:	01/20/2012	Closed:	01/26/2012
- Tire Service	Marginal	rd and	7th plac	e south - tir	es					
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1206841 P.M serv			25726 A/C.			In Date:	07/23/2012	Closed:	08/08/2012
- Perform pm	service.					Parts Li	ist			Qty
- Inspect and		vdraulio	crane.			Shop Su	upplies			1.00
- Install four n		•		en fill and b	alance all	•		Ch9549 Wix 5	57312	1.00
six.			3					m Cs10263a		1.00
- Fabricate ar	nd replace	missin	g hitch p	oindel pin w	ith new and		lydraulic Filt			1.00
secure.						15/40 C	•			16.00
- Ac performa	ince test a	and rep	lace faile	ed blower re	esistor with			lydraulic Oil 6	88	4.00
new.							/iper Blades		,0	2.00
- Perform whe	_	ient cor	npiete.			Blower I	•	, 20 Diado		1.00
- Shop Suppli	es							5r17 Wrangle	r Sr-a E	4.00
								5r17 Wrangle	51 31-a E	4.00
							posal Fee Pintle Pin			1.00
		المدينة	11 FO		l abar			000 50	Total	
		Hours :	11.50		Labor:	690.00	Parts:	900.59	i otal:	1,590.59

Workorder: 1208873 Meter: 25774  Problem: No crank after sitting for a long time.	In Date: 09/18/2012 Closed: 09/20/2012
<ul> <li>Test starting and charging system.both batteries failed loadtest after recharge.replace both batteries with new.</li> <li>Shop Supplies</li> </ul>	Parts List Qty Shop Supplies 1.00
	Group 65 Battery (mtc Bxt-65-850) 2.00 120.00 Parts: 262.10 Total: 382.10
Workorder: 1301921 Meter: 29179 Problem: Pm service.	In Date: 02/25/2013 Closed: 03/12/2013
- P.m. Service.	Parts List Qty
- Inspect and service crane.drain contaminated fluid.flush	15-40 Oil 15.00
system and refill.	Oil Filter 1.00
- Resurface front and rear brake rotors,replace brake	Fuel Filter 1.00
pads.service and lube calipers.flush and bleed system Rotate and balance all six tires.	31-20 Wiper Blades 20 2.00
	Used Firex Refurbed F 1.00
- Shop Supplies	Mac Wite Lithium Gres 1.00
	Napa Hydraulic Filtr 1.00
	Brake Pads 1.00
	Brake Cleaner 1.00
	Brake Pads 1.00
	Napagold Air Filter 1.00
	Aw68 Hydro Fluid Hydr 45.00
	Shop Supplies 1.00
Hours 17.00 Labo	: 1,020.0 Parts: 410.75 Total: 1,430.75

Workorder: Problem:	1307315 P.M. service	Meter: and check	33642 engine light or	n.		In Date:	07/22/2013	Closed:	08/15/20	)13
- P.m. Service	<del>)</del> .				Parts Li	st				Qty
- Fabricate an	d replace righ	nt alley lamp	with harness	<b>;</b>	15-40 C	Dil				15.00
connector.					Napagol	d Oil Filter				1.00
- Remove righ		trim and rep	place outside	door	Napagol	d Fuel Filte	r			1.00
<ul><li>handle and lock cylinder.</li><li>Replace two tires,rotate and balance all six.</li><li>Pressure test and inspect cooling systemreplace upper and</li></ul>						el Cov - Fo			1.00	
						Bulb Mr11	-12v			1.00
				pper and	46-0763	846-13 Soc	cket			1.00
lower radiator hoses.flush and refill cooling system - Inspect and service crane.						Asy		1.0	1.00	
- Diagnose ch	eck engine lig	ht.p2080,p	2081,p2082.p	erform	Lock Cy	linder				1.00
pin point test.r		exhaust tem	np sensorscle	ear	1796364	92 Lt245-7	5r17			2.00
codes and rete		( l <i>l</i>			Top Rad	liator Hose				1.00
<ul> <li>Replace both alignment and</li> </ul>		t camber/ca	aster busnings	s.perrorm	lower ho	se				1.00
- Shop Suppli					Radiator	Hose				1.00
оор оарр					Peak Gl	obal				2.00
					Napa Hy	draulic Filtı	r			1.00
					Aw68 Hy	/dro Fluid H	lydr			3.00
					exhaust	sensor				3.00
						amber Bus	hing			2.00
					Shop Su	pplies				1.00
					•	osal Fee				2.00
	Hou :	irs 20.75		Labor:	1,245.0 0	Parts:	1,300.31	Total:	2,545.31	
Workorder: Problem:	1308915 Right front ar	Meter: nd right rea	33914 r outter tire go	ing flat.		In Date:	09/04/2013	Closed:		
-	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1311117	Meter:	35602			In Date:	11/01/2013	Closed:	11/19/20	)13
Problem:	Engine misfir	es.Had to t	urn off and res	start.						
- Diagnose en updated calibra		0088.repro	gram Pcm Wit	th	Parts Li Shop Su					<b>Qty</b> 1.00
- Shop Suppli	es				Shop Su	ippii00				1.00
		ırs 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	

Workorder: 1400104 M	<b>/leter:</b> 3	36860	In	Date:	01/06/2014	Closed:	01/29/2014
Problem: Check brake nois	se and red	quest detail.					
- Replace front brake rotors and	d resurfac	e rear rotors.replace	Parts List				Qty
front calipers, service and lube re		ce brake pads.flush	Brake Pads	6			1.00
and bleed system and test drive	•		Brake Pad				1.00
- Shop Supplies			Wheel Sea	I - Front	Wheel		2.00
			Front Rotor				2.00
			Reman Bra	ke Calip	er		1.00
			Reman Bra	ke Calip	er		1.00
			2232 Brake	Fluid Q	uar		2.00
			Brake Clea	ner			2.00
			Ceramic Br	ake Lube	Э		1.00
			Shop Supp	lies			1.00
Hours 9	9.00	Labor:	540.00	Parts:	713.57	Total:	1,253.57
Workorder: 1400675 M Problem: 1 - Detail Vehicle		36697 cket(s) Issued	In	Date:	01/21/2014	Closed:	01/21/2014
- 1 - Detail Vehicle Wash Ticket	t(s) Issued	d					
Hours 0	0.00	Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: 1402296 Meter: 38197 Problem: Pm service.Request to detail vehicle.	In Date:	03/07/2014	Closed:	04/03/2014
- P.m. Service.	Parts List			Qty
- Replace left alley lamp in lightbar.replace both brake lamps.	15-40 Oil			15.00
- Replace foun tires,rotate and balance all six.	Napagold Oil Filter	1.00		
- Inspect and service crane.replace missing angle indicator	Fuel Filter Ford Onl		1.00	
charts.replace leaking out-rigger hydraulic hose.	17189e Bulb Mr11	2.00		
- Replace right front bump stop.	46-0763846-13 Soc		1.00	
- Pressure test and inspect cooling system replace leaking	179636492 Lt245-7	′5r17		4.00
radiator.flush and refill system.	Tr416 Valve Stem		4.00	
- Shop Supplies	Napa Hydraulic Filt		1.00	
	Used Fire X Refurb	ished		1.00
	Wiper Blade			2.00
	Coolant Ford Gold			2.00
	Green Diesel Fuel	Сар		2.00
	Fuel Cap Diesel			2.00
	bumper			1.00
	Sand Pad			1.00
	Complete Radiator			1.00
	Angle Pendulum De	ecal		2.00
	Hex Bolt & amp; Nu	t		1.00
	Radiator			1.00
	Led Sup Mdl 44 42	Dio		2.00
	Hydraulic Hose			1.00
	Shop Supplies			1.00
	Tire Disposal Fee			4.00
Hours 16.25 Labor:	975.00 Parts:	3,347.50	Total:	4,322.50
Workorder: 1402711 Meter: 38057 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued	In Date:	03/20/2014	Closed:	03/20/2014
- 1 - Detail Vehicle Wash Ticket(s) Issued				
Hours 0.00 Labor:	0.00 Parts:	0.00	Total:	0.00
Workorder: 1409216 Meter: 42258 Problem: 1 - Key(s) issued	In Date:	09/12/2014	Closed:	09/12/2014
- 1 - Key(s) issued	Parts List			Qty
	Duplicate Vehicle K	(eys		1.00
Hours 0.20 Labor:	•	•	Total·	15.00

Problem: P.M	9540 I. Service.A	Meter: VC not co	42688 ld.			In Date:	09/23/2014	Closed:	10/14/2014
- Pm service.					Parts Lis	st			Qty
- Inspect service h	ydraulic cra	ane also r	eplace two r	nissing	15-40 O	il			15.00
outrigger foot pads					Napagol	d Oil Filter			1.00
- Ac performance a				over	Fuel Filte	1.00			
freon.replace leakir valve.vacuum and					Wiper Bl	ade			2.00
- Test and replace	•	•	•	ıke down	Napa Hy	draulic Filtr	•		1.00
lamp.		Ü	Ü		Accumul	ator			1.00
- Replace broken r	ight front d	loor key c	ylinder and r	ecode to	R134a L	v Shop 1			2.00
orignal key.					Orifice T	ube			1.00
<ul> <li>Fabricate and instrear of vehicle.</li> </ul>	itali missino	g asset nu	inders for fro	ont and	E8 A/c O	il Univ W D	)ye		1.00
- Rotate and balan	ice all six ti	res.			Blb Assy				1.00
- Shop Supplies					Sand Pa	d Hardware	9		1.00
					Lock Cyl				1.00
					Sand Pa				2.00
					Shop Su	• •			1.00
					Freight C	Charge			1.00
	Hours :	s 15.00		Labor:	900.00	Parts:	641.28	Total:	1,541.28
Manlandan 4.44	0004								
Problem: outr	0881 igger cylind	<b>Meter:</b> ders falling	42874 g,will not sta	y up.		In Date:	10/30/2014	Closed:	11/12/2014
<b>Problem:</b> outr	igger cylind	ders falling	g,will not sta		Parts Lis		10/30/2014	Closed:	11/12/2014 <b>Qty</b>
Problem: outr - Remove both lea repairs and reinstal	igger cylind	ders falling	g,will not sta		Parts Lis	st	10/30/2014	Closed:	
<b>Problem:</b> outr	igger cylind	ders falling	g,will not sta			<b>st</b> Repair	10/30/2014	Closed:	Qty
Problem: outr - Remove both lea repairs and reinstal	igger cylind Iking outrige Il after over	ders falling	g,will not sta	out for	Cylinder	<b>st</b> Repair pplies	10/30/2014 988.25		<b>Qty</b> 2.00
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies	igger cylind Iking outrig Il after over Hours : 2802	ger cylind rhaul.  s 3.00  Meter:	g,will not star ers to send of 43770	out for	Cylinder Shop Su	<b>st</b> Repair pplies			<b>Qty</b> 2.00 1.00
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141	igger cylind Iking outrig Il after over Hours : 2802 ved in for tr	ger cylind rhaul.  s 3.00  Meter: cansmissic	ers to send of the start of the	out for Labor:	Cylinder Shop Su 180.00	st Repair pplies Parts:	988.25	Total:	<b>Qty</b> 2.00 1.00 1,168.25
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141: Problem: Tow - Diagnose vehicle dealer for high pres	igger cylind king outrig Il after over Hours : 2802 ved in for tra	ger cylind rhaul.  s 3.00  Meter: ransmissic	ers to send of the standard sers to send of the sers to sers the sers to ser the sers to sers the sers to serve the sers to serve the sers to serve the sers to serve the s	out for Labor:	Cylinder Shop Su 180.00	st Repair pplies Parts: In Date:	988.25	Total:	Qty 2.00 1.00 1,168.25 01/29/2015
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141 Problem: Tow - Diagnose vehicle	igger cylind king outrig Il after over Hours : 2802 ved in for tra e,towed in fossure pump	ger cylind rhaul.  s 3.00  Meter: cansmissic for no power replacen	ers to send of the standard sers to send of the sers to sers the sers to ser the sers to sers the sers to serve the sers to serve the sers to serve the sers to serve the s	Labor:	Cylinder Shop Su 180.00 Parts Lis Shop Su	Repair pplies Parts: In Date: st pplies	988.25	Total:	Qty 2.00 1.00 1,168.25  01/29/2015  Qty 1.00
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141: Problem: Tow - Diagnose vehicle dealer for high pres	igger cylind king outrig Il after over Hours : 2802 ved in for tra e,towed in fossure pump	ger cylind rhaul.  s 3.00  Meter: ransmissic	ers to send of the standard sers to send of the sers to sers the sers to ser the sers to sers the sers to serve the sers to serve the sers to serve the sers to serve the s	Labor:	Cylinder Shop Su 180.00	st Repair pplies Parts: In Date:	988.25	Total:	Qty 2.00 1.00 1,168.25 01/29/2015 Qty
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141: Problem: Tow - Diagnose vehicle dealer for high pres - Shop Supplies	igger cylind lking outrige ll after over  Hours : 2802 ved in for tra e,towed in for ssure pump  Hours : 2826	ger cylind rhaul.  s 3.00  Meter: ransmissic for no power replacents 2.00  Meter:	ers to send of the standard sers to send of the sers to sers the sers to ser the sers to sers the sers to serve the sers to serve the sers to serve the sers to serve the s	Labor:	Cylinder Shop Su 180.00 Parts Lis Shop Su	Repair pplies Parts: In Date: st pplies	988.25	Total:	Qty 2.00 1.00 1,168.25  01/29/2015  Qty 1.00
Problem: outr - Remove both lea repairs and reinstal - Shop Supplies  Workorder: 141: Problem: Tow - Diagnose vehicle dealer for high pres - Shop Supplies  Workorder: 141:	igger cylind lking outrige ll after over  Hours : 2802 ved in for tra e,towed in for ssure pump  Hours : 2826 nsmission for	ger cylind rhaul.  s 3.00  Meter: ransmissic for no power replacents 2.00  Meter: Problem	ers to send of 43770 on problem. ver.transport nent.	Labor:	Cylinder Shop Su 180.00 Parts Lis Shop Su	Repair pplies Parts: In Date: st pplies Parts:	988.25 12/24/2014 2.00	Total: Closed: Total:	Qty 2.00 1.00 1,168.25 01/29/2015 Qty 1.00

Problem: Pm	2755 <b>Meter:</b> service and noise f		gine.Deta	ail.	In Date:	03/17/2015	Closed:	03/31/2015
- Pm service.			-	Parts Li	st			Qty
- Inspect and serv	ice crane.			15-40 C	il			15.00
	ace defective one si			Napagol	d Oil Filter			1.00
•	ce defective left wir			Fuel Filte		1.00		
•	e defective lower co		Wiper BI	ade			2.00	
	oling system for coo		Used Fir	e X Refurbi	ished		1.00	
coolant.	ve hose clamps an	a reiiii system v	vitri	Napa Hy	draulic Filtr	•		1.00
- Rotate and balar	nce all six tires.			Mount				1.00
- Shop Supplies				Washer	Nozzle			1.00
5p 5.0pp5				bumper				1.00
				Shop Su	pplies			1.00
	Hours 9.00		Labor:	540.00	Parts:	187.97	Total:	727.97
	3153 <b>Meter:</b> Detail Vehicle Wash	–	ed		In Date:	03/26/2015	Closed:	03/26/2015
- 1 - Detail Vehicle	Wash Ticket(s) Iss	sued						
- 1 - Detail Vehicle	e Wash Ticket(s) Iss Hours 0.00	sued	Labor:	0.00	Parts:	0.00	Total:	0.00
	Hours 0.00 : 7644 <b>Meter:</b>		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 150 Problem: Has - Recharge both b	Hours 0.00 : 7644 <b>Meter:</b>	46890		0.00	In Date:			
Workorder: 150 Problem: Has - Recharge both b both bad batteries.	Hours 0.00 : 7644 Meter: s to jump start atteries and test ch	46890 arging system.i	replace	Parts Li	In Date:			08/06/2015
Workorder: 150 Problem: Has - Recharge both b both bad batteries.	Hours 0.00 : 7644 <b>Meter:</b> s to jump start	46890 arging system.i	replace	Parts Li	In Date: st d Oil Filter			08/06/2015 <b>Qty</b>
Workorder: 150 Problem: Has - Recharge both b both bad batteries.	Hours 0.00 : 7644 Meter: s to jump start atteries and test ch	46890 arging system.i	replace	Parts Li	In Date: st d Oil Filter			08/06/2015 <b>Qty</b> 1.00
Workorder: 150 Problem: Has - Recharge both b both bad batteries Replace broken	Hours 0.00 : 7644 Meter: s to jump start atteries and test ch	46890 arging system.i	replace	Parts Li Napagol Battery 6	In Date: st d Oil Filter 65 Nozzle			08/06/2015 Qty 1.00 2.00

Workorder: Problem:	1508985 Pm service.	Meter: Towed in.Be	47545 elt failed.PS leak.	.Head	light and	In Date: door lock in	09/08/2015 op.	Closed:	09/29/20	15
- Pm service.					Parts Li		•			Qty
- Inspect and	service hydra	aulic crane.			15-40 C				1	5.00
•	-		elt,tensioner and	two	Napago	ld Oil Filter				1.00
idler pulleys.re	eplace defect	ive/ leaking	power steering			er Ford Onl	у			1.00
pump.flush an	•		h 1 l - 6		Washer	Fluid Conc		1.00		
<ul> <li>Replace defective left headlamp seal beam and left rear rec</li> <li>Led marker lamp.</li> <li>Replace four tires.rotate and balance all six.</li> <li>Replace damage right front door lock cylinder and recode</li> </ul>						lade				2.00
						ydraulic Filtı	r			1.00
						ine Belt				1.00
to original key			,		Serpent	ine Belt				1.00
- Replace mis	sing hitch pir	ntle pin.			Tension	er-heavy D	uty			1.00
- Shop Suppli	es				Driveali	gn Pulley				1.00
					B S Pull	еу				1.00
					Haloger	n Lamp				1.00
					1796364	492 Lt245-7	5r17			2.00
					Pawer S	Steering Pur	mp			1.00
					Lock Cy	linder				1.00
					Psf Qt					2.00
					Tran Flu	u Qt Dexron	3i			2.00
					Pintle P	in W/chain				1.00
					M C Bas	se Mount Ki	t			1.00
					Shop Su	upplies				1.00
					Tire Dis	posal Fee				2.00
	Ho :	urs 19.00	L	_abor:	1,140.0 0	Parts:	1,242.69	Total:	2,382.69	
Workorder: Problem:	1509033 Power Stee	Meter: ring Issues	47403 .check belts			In Date:	09/08/2015	Closed:	09/09/20	15
- Tow From: 8	3100 Foreest	Hill Blvd To	o: Lv shop							
	Ho :	urs 0.00	L	_abor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1509683 2 - Key(s) is	Meter: sued	47403			In Date:	09/24/2015	Closed:	09/24/20	15
- 2 - Key(s) is	sued				Parts Li	ist				Qty
, ,						te Vehicle K	eys			2.00
	Но	urs 0.60	L	_abor:	36.00	Parts:	-	Total:	42.00	

Workorder: 1602026 Meter: 52451		In Date:	02/26/2016	Closed:	03/14/2016
Problem: Pm service.Outrigger cylinder leaking.Ste	ering	wheel cover.			
- Pm service.		Parts List		Qty	
- Replace four tires.rotate and balance all six.		Cylinder Out Rigger		1.00	
- Inspect and replace both defective front shocks, leakin	ng.	15-40 Oil			15.00
- Inspect hydraulic oil leak at right side outrigger.r&i cylir	nder	Napagold Oil Filter			1.00
for repairs.inspect and perform crane service.		Fuel Filter Ford Onl	у		1.00
- Inspect and replace missing hitch pintle pin.		20" Wiper Blade			2.00
- Inspect emergency lighting bar.left side alley light	المارة: ا	Washer Fluid Conce	entr		1.00
inop.check circuit ok.replace burnt bulb.had to dismantle bar.	ııgnı	Used Fire X Refurbi	ished		1.00
- Inspect and replace defective rear service vise.rusty ar	nd	179636492 Lt245-7	5r17		4.00
siezed.		Gas Grande Fleet S	Shoc		2.00
- Perform complete front end alignment.		Napa Hydraulic Filtr			1.00
- Shop Supplies		Pintle Pin W/chain			1.00
		Bulb ( Mr11-12v )			1.00
		Vise			1.00
		Stg Wheel Cov - Fo	rd		1.00
		Aw68 Hydro Fluid H	lydr		15.00
		Shop Supplies			1.00
		Tire Disposal Fee		4.00	
Hours 16.25 La	abor:	975.00 Parts:	1,842.52	Total:	2,817.52

Workorder: 1607668 Meter: 56664 Problem: P.M. service and A/C warm and light bar inop.	In Date: 07/27/2016	<b>Closed:</b> 08/17/2016
- P.m. Service.	Parts List	Qty
- Replace left rear signal lamp/marker light assemble.replace	Ptex Ultra Grey 3oz	1.00
high mount market light bulb.	Napagold Oil Filter	1.00
- Replace rear brake rotors,calipers and brake pads.install	15-40 Oil	15.00
new seals.service bearings, clean and adjust parking brake shoes. flush and bleed system and test drive.	Napagold Air Filter	1.00
- Inspect and service rear differential.	20" Wiper Blade	2.00
- Service transmission.flush and refill system.	4 Led S T T Lamp	1.00
- Inspect and service crane.	Rpl Bulb	1.00
- Replace two tires,rotate and balance all six.	Reman Brake Caliper	1.00
- A/c performance check.recover freon,add dye and leak	Reman Brake Caliper	1.00
check.vacuum system and recharge to specs.	Napa Oil Seal	2.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Brake Pad	1.00
	1qt Syngear Oil 75-90	5.00
	Brake Cleaner	2.00
	Syn-atf Trans Fluid S	20.00
	Fuel Filter Ford Only	1.00
	Napa Hydraulic Filtr	1.00
	Rear Rotor	2.00
	Atp Filter	1.00
	Aw68 Hydro Fluid Hydr	4.00
	179636492 Lt245-75r17	2.00
	Rocker Switch	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 21.00 Labor:	1,260.0 Parts: 1,458.59	Total: 2,718.59
Workorder: 1612107 Meter: 58814	In Date: 11/28/2016	<b>Closed:</b> 12/15/2016
Problem: Noise in front end on turns and cargo light inop	and has to jump start.	
- Replace center mount brake lamp bulb.	Parts List	Qty
- Test batteries and charging system.replace bad batteries.	Lamp Assy	1.00
- Diagnose noise in front end.retorque shock mountings.	Rpl Bulb	3.00
- Shop Supplies	Battery	2.00
	Shop Supplies	1.00
Hours 3.00 Labor:	180.00 Parts: 359.68	Total: 539.68

Workorder: 1700348 Meter: 59014 Problem: P.M. service.	In Date: 01/11/2017 Closed:	01/23/2017
- P.m. Service.	Parts List	Qty
- Inspect and service crane.	15-40 Oil	15.00
- Resurface front brake rotors,replace pads and	Napagold Oil Filter	1.00
calipers.flush and bleed system.	Fuel Filter Ford Only	1.00
- Replace rear axle bump stops.	20" Wiper Blade	2.00
- Rotate and balance all six tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Napa Hydraulic Filtr	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	2.00
	Brake Pads	1.00
	Real Suspension Bumpstops	2.00
	Shop Supplies	1.00
Hours 12.00 Labor:	720.00 Parts: 507.52 Total:	1,227.52
Workorder: 1702261 Meter: 59023	In Date: 03/06/2017 Closed:	03/28/2017
Problem: A/C inop.Brakes pulsating.	111 Date: 00/00/2017 010364.	03/20/2011
<ul><li>Problem: A/C inop.Brakes pulsating.</li><li>Check front brakes.replace front rotors,repack wheel</li></ul>	Parts List	Qty
<ul><li>Problem: A/C inop.Brakes pulsating.</li><li>Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.</li></ul>	Parts List Hub Asy	
<ul> <li>Problem: A/C inop.Brakes pulsating.</li> <li>Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.</li> <li>A/c performance test.leak check system.r&amp;r dash to replace</li> </ul>	Parts List Hub Asy	Qty
<ul> <li>Problem: A/C inop.Brakes pulsating.</li> <li>Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.</li> <li>A/c performance test.leak check system.r&amp;r dash to replace leaking evaporator,accumulator and orifice.replace leaking</li> </ul>	Parts List Hub Asy	<b>Qty</b> 2.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal	<b>Qty</b> 2.00 2.00
<ul> <li>Problem: A/C inop.Brakes pulsating.</li> <li>Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.</li> <li>A/c performance test.leak check system.r&amp;r dash to replace leaking evaporator,accumulator and orifice.replace leaking</li> </ul>	Parts List Hub Asy Seal Evapotator Core	<b>Qty</b> 2.00 2.00 1.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser	Qty 2.00 2.00 1.00 1.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter	Qty 2.00 2.00 1.00 1.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter Accumulator	Qty 2.00 2.00 1.00 1.00 1.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter Accumulator Seal	Qty 2.00 2.00 1.00 1.00 1.00 4.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter Accumulator Seal Freon Lv Shop 2	Qty 2.00 2.00 1.00 1.00 1.00 4.00 2.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter Accumulator Seal Freon Lv Shop 2 E8 A/c Oil Univ W Dye	Qty 2.00 2.00 1.00 1.00 1.00 4.00 2.00 1.00
Problem: A/C inop.Brakes pulsating.  - Check front brakes.replace front rotors,repack wheel bearings.service and lube calipers.  - A/c performance test.leak check system.r&r dash to replace leaking evaporator,accumulator and orifice.replace leaking condensor.vacuum system and recharge to specs.	Parts List Hub Asy Seal Evapotator Core A/c Condenser Tube Filter Accumulator Seal Freon Lv Shop 2 E8 A/c Oil Univ W Dye Seal Kits	Qty 2.00 2.00 1.00 1.00 1.00 4.00 2.00 1.00 2.00

Workorder: Problem:	1705766 A/C blows wa	Meter: arm and cra	60379 ane missing s	safety pin a		n Date: lder broke	06/09/2017 en.	Closed:	07/07/2017	
- A/c performa	Parts List		Qty							
and orifice.vac	A C Cut-o	ff Switch			1.00					
- Replace righ	Cap And \	Valve Kit			1.00					
- Replace broken glove box.						New Compress W Clutch				
- Replace safety pin on crane boom.					Orifice Tu	1.00				
- Shop Supplies				Freon Lv S		2.00				
					E8 A/c Oil	1.00				
					Flush Solv	vent			1.00	
					Halogen L	_amp			1.00	
					Boxassy				1.00	
					Safey Pin				1.00	
					Shop Sup	plies			1.00	
					Freight Ch	narge			1.00	
	Hou	ırs 8.50		Labor:	510.00	Parts:	676.56	Total:	1,186.56	
Workorder: Problem:	1707208 P.M. service	Meter: and crane	60525 inop.		I	n Date:	07/24/2017	Closed:	08/31/2017	
- P.m. service					Parts List	t			Qty	
- Replace two	front tires.bal	lance and r	otate all six.		15-40 Oil	15.00				
- Check crane					Napagold	1.00				
valve.replace of switch .service				na Atb	Fuel Filter	1.00				
- Shop Suppli		opiaco iiaia			20" Wiper	2.00				
опор оцррп	- Shop Supplies				Seal Kit		1.00			
				17963649	2 Lt245-7		2.00			
				Hyd Hose		1.00				
					Napa Hyd	lraulic Filt	r		1.00	
					Limit Swite				1.00	
				Flow Cont		1.00				
				Aw68 Hydro Fluid Hydr				42.00		
				Flow Control Valve				1.00		
					Shop Supplies				1.00	
				Tire Disposal Fee				2.00		
					Freight Charge				1.00	
				Freight Charge				1.00		
Hours 11.00 Labor:					660.00	2,133.72				

Workorder: Problem:	170913 Install in		<b>eter:</b> er left	60850 rear tire flat.Hi	tch miss	ina.	In Date:	09/21/2017	Closed:	10/04/2017
						Parts Li	st			Qty
<ul> <li>Remove and replace damaged left rear inner tire on sidewall with new .mount and balance tire.</li> <li>Mount new inverter onto center floor board.fabericate wiring and install circuit breaker.relocate fire extinguisher .test inverter.</li> <li>Install new missing hitch with pindle lock and locking hitch</li> </ul>							192 Lt245-7	5r17		1.00
						Cpi 157	1.00			
						Bulk Ba	5.00 9.00			
						Bulk Ba				
pin.	moonig m	itori witii p	indic i		grintori	Cb185-	1.00			
- Shop Suppl	ies					Fab/loor	n			14.00
						Clr Rtv S	Silcn Sealar	nt		1.00
						Termina	I			2.00
						Cabl/lug			4.00	
							n Lock		1.00	
							Ball For			1.00
						Pintle H	ook With Ba		1.00	
						Pintle Pin W/clip				1.00
						Pintle Hook Mount				1.00
						Shop St	upplies		1.00	
						Tire Dis	oosal Fee		1.00	
		Hours 6.	00		Labor:	360.00	Parts:	708.46	Total:	1,068.46
Workorder: Problem:	171114 Towed i		eter: art.	61516			In Date:	11/13/2017	Closed:	11/16/2017
- Replace bro	ken heat	er hoses.fi	ill cool	ing system.pre	essure	Parts Li	st			Qty
test.scan com	•	ear codes.t	est dr	ive.		Heater I	1.00			
- Shop Suppl	ies					Heater I	Hose		1.00	
						Peak GI	obal Antifrz		2.00	
					Heater I	Hose		1.00		
					Shop St	ıpplies		1.00		
		Hours 3.	00		Labor:	180.00	Parts:	149.51	Total:	329.51
Workorder: Problem:	171126 no start		eter:	61292			In Date:	11/09/2017	Closed:	11/15/2017
- Tow From: 8	3100 For	est Hill Blv	d To:	Lv shop						
		Hours 0.	00	-	Labor:	0.00	Parts:	0.00	Total:	0.00
		_								

Workorder: Problem:	1801824 P.M. service.	Meter:	63486			In Date:	02/15/2018	Closed:	02/27/2018
- P.m. service	<b>)</b> .				Parts L	ist			Qty
<ul> <li>Inspect and service crane.</li> <li>Check charging and starting systems .batteries failed load test .replace both batteries with new.</li> <li>Pressure test cooling system .replace radiator and upper and lower hoses.flush and refill cooling system.</li> <li>Rotate and high speed balance all six tires.</li> </ul>						Dil			15.00
						ld Oil Filter			1.00
						ter Ford Onl		1.00	
						er Blade		2.00	
						re X Refurb		3.00	
						ydraulic Filt		1.00	
- Shop Suppli	ies				Battery				2.00
					Coolant	Ford Gold			4.00
					Radiato	r			1.00
					Curved	Radiator Ho	ose		1.00
					Curved	Radiator Ho	ose		1.00
					Shop St	upplies			1.00
	Hour	s 13.60		Labor:	816.00	Parts:	1,372.66	Total:	2,188.66
Workorder: Problem:	1803370 Crane inop, W	Meter: Vindshield	64228 wipers broken	ı.		In Date:	03/30/2018	Closed:	04/23/2018
- Cancel P.m	. service.				Parts L	ist			Qty
- Replace from	nt wiper blades				22" Wip	2.00			
	rane inop.perfo			ed crane	Liftmoor	re Control		1.00	
	orm complete o	perational	test of crane.		Shop St	upplies			1.00
- Shop Suppli		s 1.30		Labor:	78 00	Parts:	909.44	Total:	987.44
	:			Luboi.	70.00				
Workorder: Problem:	1808433 P.M. service a	Meter: and detail.	67189			In Date:	08/16/2018	Closed:	08/28/2018
- P.m. service	<b>)</b> .				Parts L	ist			Qty
- Inspect and	service crane.				Napago	ld Oil Filter			1.00
•	eft side marker	light inop.r	eplace missin	g piece	15-40 C	Dil			15.00
on wire and re					Fuel Filt	ter Ford Onl	У		1.00
<ul> <li>Replace two fill all tires.</li> </ul>	tires . Rotate	and baland	e all six tires.	Nitrogen	20" Wip	er Blade			2.00
- Shop Suppli	ies				Napa H	ydraulic Filt		1.00	
- опор оцррп	163				Aw68 H	ydro Fluid H	Hydr		12.00
					Primary	Wire			3.00
					179636	492 Lt245-7	′5r17		2.00
					Shop St	upplies		1.00	
					Tire Dis	posal Fee			2.00
	Hour :	s 8.30		Labor:	498.00	Parts:	619.19	Total:	1,117.19
Workorder: Problem:	1808832 1 - Detail Veh	Meter: icle Wash	66990 Ticket(s) Issue	ed		In Date:	08/27/2018	Closed:	08/27/2018
- 1 - Detail Ve	ehicle Wash Tic	cket(s) Issu	ıed						
. 2000		s 0.00	- <del></del>	Labor:	0.00	Parts:	0.00	Total:	0.00
	:	<del>-</del>			<del>.</del>				

Workorder: 1810919 Meter: 68382 Problem: Left rear inner tire going flat.	In Date:	10/23/2018	Closed:	10/25/2018		
- Replace left rear inner tire and balance . Due to sidewall	Parts List			Qty		
damage .	179636492 Lt245-75	5r17		1.00		
- Shop Supplies	Shop Supplies			1.00		
	Tire Disposal Fee		1.00			
Hours 0.50 Labor:	33.50 Parts:	224.45	Total:	257.95		
Workorder: 1901205 Meter: 70590 Problem: P.M. service andcheck tires and detail.	In Date:	01/31/2019	Closed:	02/13/2019		
- P.m. service.	Parts List			Qty		
- Test and replace light bar take down lights and alley lights .	Napagold Oil Filter			1.00		
Replace bulbs and retest . Test and replace rear running light bar .	15-40 Oil			15.00		
- Inspect and service crane and outriggers .	22" Wiper Blade		2.00			
- Replace two tires on front . Rotate and high speed balance	Pedal Pad	Pedal Pad				
all six tires . Nitrofill all.	Napagold Air Filter		1.00			
- Replace broken pintle pin .	Fuel Filter Ford Only		1.00			
- Complete front end alignment and road test.	Used Fire X Refurbis		1.00			
- Shop Supplies	Blb Assy		1.00			
	Led Id Bar 6 Ctrs		1.00			
	Napa Hydraulic Filtr	1.00				
	Lt245/75r17 Mich De	efend Ltx		2.00		
	Bulbs			1.00		
	Mac Wite Lithium Gr	es		1.00		
	Pintle Pin W/clip			1.00		
	Shop Supplies			1.00		
	Tire Disposal Fee			2.00		
Hours 12.80 Labor:	857.60 Parts:	858.06	Total:	1,715.66		
Workorder: 1901694 Meter: 70367 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued	In Date:	02/13/2019	Closed:	02/13/2019		
- 1 - Detail Vehicle Wash Ticket(s) Issued						
Hours 0.00 Labor:	0.00 Parts:	0.00	Total:	0.00		
Workorder: 1905511 Meter: 72376 Problem: Transition Prep Charge	In Date:	05/23/2019	Closed:	05/23/2019		
- Transition Prep Charge						
Hours 2.00 Labor:	134.00 Parts:	0.00	Total:	134.00		