Palm Beach County Fleet Management Asset Maintenance History

10193019 2013 JACOBSON GROOM MASTER II Ballfield Groomer, Diesel

| | | | | | _ | | , | | | |
|--|-----------------------------|-----------------------|----------------|--------|-----------------------------|--|------------|---------|--------------|--|
| Workorder: Problem: | 1308558 1061 - Pre De | Meter: livery Insp | 1 pection | | | In Date: | 08/26/2013 | Closed: | 08/26/2013 | |
| - Pre Delivery | Inspection | | | | | | | | | |
| | Hours : | s 2.00 | | Labor: | 120.00 | Parts: | 0.00 | Total: | 120.00 | |
| Workorder: Problem: | 1409538 Pm service,wo | Meter: on't start. | 42 | | | In Date: | 09/23/2014 | Closed: | 10/17/2014 | |
| - Pm service. | | | | | Parts Li | Qty | | | | |
| - Won't start/stay running. Check start and run circuit. Fuel | | | | | Controll | 1.00 | | | | |
| pump not working. No signal from module. Replace faulty module Hyd. service. | | | | | | Aw68 Hyd Fluid Tank Pahokee | | | | |
| | | | | | | Group 22nf Delco | | | | |
| - Battery failed load test. Replace battery and rusted battery | | | | | | Bat Cabl | | | | |
| hold down bolts. | | | | | 15w40 E | 3.00 | | | | |
| - Fuel pump not pumping. Fuel pump inlet clogged. Remove | | | | | Napago | 1.00 | | | | |
| and clean fuel pump. Reroute fuel lines to filter fuel before fuel pump. | | | | | Napago | 1.00 1.00 | | | | |
| - Shop Supplies | | | | | | Napagold Air Filter Napa Trans Filter | | | | |
| | | | | | Shop St | | | | 1.00 1.00 | |
| | Hours : | s 10.00 | | Labor: | 600.00 | | 1,128.53 | Total: | 1,728.53 | |
| Workorder: Problem: | 1409586 Won't run. | Meter: | 42 | | | In Date: | 09/24/2014 | Closed: | 09/24/2014 | |
| - Tow From: F | Pioneer Park To | o: Pa sho | р | | | | | | | |
| | Hours : | s 0.00 | | Labor: | 0.00 | Parts: | 0.00 | Total: | 0.00 | |
| Workorder: Problem: | 1410871 fuel shut off so | Meter: olenoid/ w | 121 arranty | | | In Date: | 10/30/2014 | Closed: | 10/31/2014 | |
| - Horizon war | ranty fuel shut o | off soenoi | d | | | | | | | |
| | Hours : | s 0.00 | | Labor: | 0.00 | Parts: | 0.00 | Total: | 0.00 | |
| Workorder: Problem: | 1600574 Pm service | Meter: | 191 | | | In Date: | 01/19/2016 | Closed: | 01/22/2016 | |
| - Pm service. | | | | | Parts Li | ist | | | Qty | |
| - Test run. | | | | | 15w40 Bulk Tank Pahokee 3.0 | | | | | |
| - Shop Supplies | | | | | Napago | ld Oil Filter | | | 1.00 | |
| | | | | | Napago | ld Air Filter | | | 1.00 | |
| | | | | | | ld Fuel Filte | | | 1.00 | |
| | | | | | | ydraulic Filtr | • | | 1.00 | |
| | | | | | Shop Su | • • | | | 1.00 | |
| | Hours : | s 4.50 | | Labor: | 270.00 | Parts: | 33.65 | Total: | 303.65 | |

Palm Beach County Fleet Management Asset Maintenance History

| Workorder: 1702307 Meter: 257 Problem: Pm service, won't start. | | I | n Date: | 03/07/2017 | Closed: | 03/23/20 |)17 |
|---|--------------------------|---|--------------------------------------|----------------------------|--------------|----------|---------------------------|
| - Pm service. | | Parts List | | | | | Qty |
| - Battery failed load test. Replace battery. | 15w40 Bulk Tank Pahokee | | | | | 3.00 | |
| - Brake switch shorted. Replace brake switch. | Napagold Oil Filter | | | | 1.00 1.00 | | |
| - Test run to check all functions. | Napagold | | | | | | |
| - Shop Supplies | Napagold | | 1.00 | | | | |
| | | Napa Hyd | raulic Filtr | | | | 1.00 |
| | | Acd 22nf | | | | | 1.00 |
| | Switch, Pr | | 1.00 | | | | |
| | | Shop Sup | plies | | | | 1.00 |
| Hours 6.50 : | Labor: | 390.00 | Parts: | 223.30 | Total: | 613.30 | |
| Workorder: 1801040 Meter: 319 | | ļ | n Date: | 01/29/2018 | Closed: | 02/07/20 |)18 |
| Problem: Replace missing rake pins and washers | ; . | | | | | | |
| - Install new clevis pins and washers for rake attachme | Parts List | | | | | Qty | |
| - Shop Supplies | Clevis Pin 5/16x3/4 10pk | | | | | 2.00 | |
| | | Shop Sup | plies | | | | 1.00 |
| Hours 1.00 : | Labor: | 60.00 | Parts: | 21.86 | Total: | 81.86 | |
| Workorder: 1802546 Meter: 335 Problem: Pm service | | I | n Date: | 03/07/2018 | Closed: | 03/15/20 |)18 |
| - Pm service. | | Parts List | | | | | Qty |
| - Replace broken headlight switch. | | 15w40 Bulk Tank Pahokee | | | | | 3.00 |
| - Shop Supplies | | Napagold | | 1.00 | | | |
| | | Napagold | Air Filter | | | | 1.00 |
| | | Napagold | Fuel Filte | r | | | 1.00 |
| | | Headlight Switch | | | | | 1.00 |
| | | Shop Sup | plies | | | | 1.00 |
| | | Freight Ch | arge | | | | 1.00 |
| | | 070.00 | D(- | FF 70 | Total | 325.76 | |
| Hours 4.50 | Labor: | 270.00 | Parts: | 55.76 | TOtal. | | |
| Hours 4.50 : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes. | Labor: | | n Date: | 04/24/2018 | Closed: | 05/10/20 |)18 |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes. | Labor: | | n Date: | | | | |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes Replaced leaking o-rings on steering motor. | Labor: | l Parts List | n Date: | | | | 018 Qty 4.00 |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes. - Replaced leaking o-rings on steering motor Replace rakes and mounting hardware. | Labor: | Parts List 19237000 | n Date: | 04/24/2018 Tine Gmaster | | | Qty |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes Replaced leaking o-rings on steering motor. | Labor: | Parts List 19237000 Aw68 Hyd | n Date: Rake 24 Fluid Tar | 04/24/2018 Tine Gmaster | | | Qty 4.00 |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes. - Replaced leaking o-rings on steering motor Replace rakes and mounting hardware. | Labor: | Parts List 19237000 Aw68 Hyd Locking C | n Date: Rake 24 Fluid Tar | 04/24/2018 Tine Gmaster | | | Qty 4.00 1.00 4.00 |
| : Workorder: 1804227 Meter: 339 Problem: Oil leak. Check brakes. - Replaced leaking o-rings on steering motor Replace rakes and mounting hardware. | Labor: | Parts List 19237000 Aw68 Hyd | n Date: Rake 24 Fluid Tarollar Staff | 04/24/2018 Tine Gmaster | | | Qty 4.00 |

Palm Beach County Fleet Management Asset Maintenance History

Workorder: 1811250 379 10/31/2018 Meter: In Date: Closed: 11/06/2018 Problem: Won't start. - Checked starting circuit. Found poor connections at battery. Parts List Qty Cleand battery connections. **Shop Supplies** 1.00 - Parking brake not holding. Adjust parking brake. - Shop Supplies Labor: 167.50 Total: 170.50 Hours 2.50 Parts: 3.00 Workorder: 1901655 In Date: 02/12/2019 Closed: Meter: 417 02/21/2019 Problem: Replace tires as needed. - Replace all worn tires. **Parts List** Qty - Shop Supplies 20x11.00-10 4ply Carl Turf Tamer 3.00 **Shop Supplies** 1.00 Tire Disposal Fee 3.00 Labor: 100.50 Hours 1.50 Parts: 494.10 Total: 594.60 Workorder: 1903135 433 Closed: Meter: In Date: 03/21/2019 04/10/2019 Problem: Pm service, check scarifier teeth. - Pm service. **Parts List** Qty - Adjusted scarifier teeth. Napagold Oil Filter 1.00 - Shop Supplies 15w40 Bulk Tank Pahokee 3.00 Napagold Air Filter 1.00 Napagold Fuel Filter 1.00 **Shop Supplies** 1.00 Hours 5.50 Labor: 368.50 Parts: 30.21 Total: 398.71 **Closed:** 06/10/2019 Workorder: 1906083 Meter: 451 In Date: 06/10/2019 **Problem:** Transition Prep Charge - Transition Prep Charge Labor: 134.00 Parts: 0.00 Total: 134.00 Hours 2.00