

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 36016

Problem: MODIFY TRAILER

Meter Reading: 0	Labor	Parts	
In Date: 03/09/2000	Hours	Description	Quantity
- Weld On Asse #. Install Tool Box. Madify Trailer For Pipe.	34.00	T-235 GRAY PRIMER	3.00
- Welding Supplies		4" WELD ON BINDER 3630	2.00
		3/16X3X20 STEEL FLAT BAR	3.00
		1/2X3X20 STEEL FLAT BAR	8.00
		3"X24' SQ. TUBE 3/16"WALL STEEL	24.00
			1.00
		4" STRAP W/FLAT HOOK 3638	2.00
		TOOL BOX	1.00
		T-29 YELLOW PAINT SCHOOL BUS	4.00
Parts Charge:	766.54	Labor Charge:	1,530.00

Workorder: 36058

Problem: PRE-DELIVERY

Meter Reading: 0	Labor	Parts	
In Date: 03/10/2000	Hours	Description	Quantity
- Pre-Delivery Inspection (Heavy Equipment)	2.00		
Parts Charge:	0.00	Labor Charge:	90.00

Workorder: 36495

Problem: TRAILER LIGHTS NOT COMING ON.

Meter Reading: 0	Labor	Parts	
In Date: 03/20/2000	Hours	Description	Quantity
- Diagnose	1.60	SHOP SUPPLIES	1.00
- Corrected Open Circuit In Wiring			
- Test All Lites			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	72.00

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 49731

Problem: PM

Meter Reading: 0	Labor	Parts	
In Date: 12/05/2000	Hours	Description	Quantity
- P.M. Trailer.	5.10	58856 SEAL	4.00
- Repair Tire.		SHOP SUPPLIES	1.00
- Repair Wiring.			
- Shop Supplies			
Parts Charge:	5.60	Labor Charge:	229.50

Workorder: 138003

Problem: FLAT TIRE

Meter Reading: 0	Labor	Parts	
In Date: 04/18/2001	Hours	Description	Quantity
- Repair Valve Stem	0.50		
Parts Charge:	0.00	Labor Charge:	22.50

Workorder: 142022

Problem: CHECK TRAILER PLUG

Meter Reading: 0	Labor	Parts	
In Date: 06/25/2001	Hours	Description	Quantity
- Diagnose	2.50	SHOP SUPPLIES	1.00
- Wire Travel Property			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	112.50

Workorder: 237776

Problem: PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 04/03/2002	Hours	Description	Quantity
- Pm 2 Axle Trailer	5.70	SHOP SUPPLIES	1.00
- Charge Brake Away Battery Test And Replace		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00
- Repair Trailer Wiring (Ground)			
- Shop Supplies			
Parts Charge:	26.55	Labor Charge:	285.00

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 332636

Problem: P.M.

Meter Reading: 0	Labor	Parts	
In Date: 01/10/2003	Hours	Description	Quantity
- Trailer Pm Service (Dual Axle)	6.50	SHOP SUPPLIES	1.00
- Repair Wiring			
- Repair Tire			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	325.00

Workorder: 348393

Problem: 2 LOW TIRES IN YARD

Meter Reading: 0	Labor	Parts	
In Date: 09/22/2003	Hours	Description	Quantity
- Air Up Tires, No Leaks Found-Trailer Sites	2.00	SHOP SUPPLIES	1.00
- Check Lights Because Trailer Is Emergency Trailer That Sits.O.K.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	100.00

Workorder: 350363

Problem: BRAKE-AWAY BARRERY

Meter Reading: 0	Labor	Parts	
In Date: 10/22/2003	Hours	Description	Quantity
- Test And Charge Emergency Brake Away Battery, Replace	2.50	SHOP SUPPLIES PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00 1.00
- Repair Tail Lamp Wiring			
- Shop Supplies			
Parts Charge:	26.55	Labor Charge:	125.00

Workorder: 351758

Problem: L/R TIRE LOW

Meter Reading: 0	Labor	Parts	
In Date: 11/17/2003	Hours	Description	Quantity
- Tire Repair	2.50	SHOP SUPPLIES	1.00
- Repair Trailer Plug Cord			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	125.00

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 433255 **Problem:** P.M.

Meter Reading: 0	Labor	Parts	
In Date: 01/16/2004	Hours	Description	Quantity
- Pm Service	4.00	58856 SEAL	4.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	5.60	Labor Charge:	200.00

Workorder: 648554 **Problem:** P.M./CHECK LIGHTS/MAKE SURE HITCH IS O.K. & LUBED

Meter Reading: 0	Labor	Parts	
In Date: 11/09/2006	Hours	Description	Quantity
- Pm Tandem Axle Trailer	6.50	58856 SEAL	4.00
- Repair Trailer Lights And Replace Male Plug		755-5046 MALE CONNECTOR	1.00
- Replace Breaker Battery And Repair Wire Harness		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	29.62	Labor Charge:	55.00

Workorder: 648991 **Problem:** REPL CE COUPLER

Meter Reading: 0	Labor	Parts	
In Date: 11/21/2006	Hours	Description	Quantity
- Replace Coupler	2.50	SHOP SUPPLIES	1.00
- Shop Supplies		44305 COUPLER	1.00
Parts Charge:	28.25	Labor Charge:	137.50

Workorder: 835574 **Problem:** P.M.

Meter Reading: 0	Labor	Parts	
In Date: 03/14/2008	Hours	Description	Quantity
- Pm Service	6.50	004098 BREAKAWAY SWITCH	1.00
- Replaced Breakaway Switch		58856 SEAL	4.00
- Nitro Tires		PB-16 PBBLASTER	1.00
- Test Drive		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	16.94	Labor Charge:	30.00

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 935138

Problem: P.M.

Meter Reading: 0	Labor	Parts	
In Date: 03/13/2009	Hours	Description	Quantity
- Pm Service	7.50	58856 SEAL	2.00
- Travel Time Pick Up Trailer @ Roads Lot		MARINE 24 BATTERY DEEP CYCLE (ACD M24MF)	1.00
- Replace Battery (Aps) Repair Wiring Install New Hold Down		SHOP SUPPLIES	1.00
- Replace Electrical Switch Aps Water Pump		DS-167 TOGGLE SWITCH (STANDARD)	1.00
- Replace Trailer Plug		755-5046 MALE CONNECTOR	1.00
- Shop Supplies		84-9480 BATTERY HOLD DOWN (GROTE)	1.00
Parts Charge: 106.42		Labor Charge: 450.00	

Workorder: 946391

Problem: pm service and cut up right post level with rail

Meter Reading: 0	Labor	Parts	
In Date: 11/25/2009	Hours	Description	Quantity
- Pm Service	12.00	58856 SEAL	4.00
- Replace Right Rear Tail Light		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00
- Replace Battery		2808 TAIL LIGHT LED LEFT HAND (EXPEDITER)	1.00
- Add Nitrogen To All Tires		T-29 YELLOW PAINT SCHOOL BUS	1.00
- Cut Of Vertical Posts And Weld Cap To Top		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 60.52		Labor Charge: 1,440.00	

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1101121

Problem: pm service

Meter Reading: 0		Labor		Parts	
In Date: 01/31/2011	Close Date: 02/07/2011	Hours	Description		Quantity
-	Pm Tandem Axle Trailer	9.00	TIRE DISPOSAL FEE		4.00
-	Replace 4 Dry Rotted Tires		762173406 225/75R15 MARATHON D		4.00
-	Resecure Various Deck Planks		1066 WHITE LITHIUM (CRC 05037)		1.00
-	Replace Left Tail Light Assy		58856 SEAL		4.00
-	Replace 2 Outer Bearing/Race Assy On Left 2 Hubs(Rusted & Damaged)		SET 4 BEARING SET TIMKEN L44649/L44610		2.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			5/16-18X3 DECK SCREWS T/C TORX M/S BLK		12.00
			2808 TAIL LIGHT LED LEFT HAND (EXPEDITER)		1.00
			TR416 VALVE STEM		4.00
Parts Charge:		479.77	Labor Charge:	540.00	

Workorder: 1101437

Problem: replace lost license plate

Meter Reading: 0		Labor		Parts	
In Date: 02/07/2011	Close Date: 02/11/2011	Hours	Description		Quantity
-	Reassign And Replace Lost License Plate And Install Registration Holder	1.00	97960 DOCUMENT HOLDER (TRUCK LITE)		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		8.09	Labor Charge:	60.00	

Workorder: 1200660

Problem: pm service

Meter Reading: 0		Labor		Parts	
In Date: 01/20/2012	Close Date: 02/08/2012	Hours	Description		Quantity
-	Pm Service	6.50	58856 SEAL		4.00
-	Replace Breakaway Battery		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
-	Replace Trailer Plug		47853-5 MARKER LIGHT YELLOW LED SUB (GROTE)		1.00
-	Replace Side Marker Light		755-5046 MALE CONNECTOR		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		45.43	Labor Charge:	390.00	

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1302102

Problem: PM

Meter Reading: 0	Labor	Parts	
In Date: 03/01/2013	Hours	Description	Quantity
- Pm Service	8.50	TRAILER CONN PLUG	1.00
- Replace Male Trailer Plug Make New Ground Wire		MAC WITE LITHIUM GRES	1.00
- Repair Ramp Mesh		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	12.67	Labor Charge:	510.00

Workorder: 1403551

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 04/11/2014	Hours	Description	Quantity
- Pm	8.00	TRAILER CONN PLUG	1.00
- Replace Trailer Plug		SHOP SUPPLIES	1.00
- Replace L & R Rear Brake Assemblies		RH ELEC BRAKE ASSY 10 X 2 1/4	1.00
- Replace Brakeaway Battery		SEAL 1.719 2.561 .500	4.00
- Shop Supplies		12V5AMP/HOUR BATTERY	1.00
		LH ELEC BRAKE ASSY 10 X 2 1/4	1.00
Parts Charge:	161.76	Labor Charge:	480.00

Workorder: 1505609

Problem: Pm Service

Meter Reading: 0	Labor	Parts	
In Date: 06/03/2015	Hours	Description	Quantity
- Pm	7.00	58856 SEAL	4.00
- Replace Trailer Plug		TRAILER CONN PLUG	1.00
- Fabricate Breakaway Cable For Switch		SHOP SUPPLIES	1.00
- Replace L/Rear Asset			
- Shop Supplies			
Parts Charge:	56.62	Labor Charge:	420.00

1/3/2017
3:43:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10129495 2000 CROSLEY CR81X22TC Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1608725

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/23/2016	Hours	Description	
- Transition Prep Charge	2.00		
Parts Charge: 0.00	Labor Charge: 0.00		

Total Parts Charges: **1,846.93** Total Labor Charges: **7,729.00** Total Comm. Charges: **0.00**