10192574 2013 FORD F150 Pickup, 1/2 Ton

						• *				
Workorder: Problem:	1307595 1061 - Pr	Meter: e Delivery Insp	353 ection			In Date:	07/31/2013	Closed:	07/31/20)13
- Pre Delivery	Inspection	n								
		Hours 2.00 :		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1311608 pm	Meter:	6669			In Date:	11/18/2013	Closed:	11/22/20)13
- P.m.service					Parts Li	st				Qty
- Shop Suppli	es				Washer	Fluid Conc	entr			1.00
					Napago	ld Oil Filter				1.00
					Napa Q	uart 5w20				6.00
					Shop Su	upplies				1.00
		Hours 2.00		Labor:	120.00	Parts:	30.20	Total:	150.20	
Workorder: Problem:	1402604 pm	Meter:	13026			In Date:	03/18/2014	Closed:	03/24/20)14
- pm					Parts Li	st				Qty
- Shop Suppli	es				Napago	ld Oil Filter				1.00
					Napa Q	uart 5w20				6.00
					Shop Su	upplies				1.00
		Hours 2.00		Labor:	120.00	Parts:	28.57	Total:	148.57	
Workorder: Problem:	1403562 rr tire nai	Meter:	15003			In Date:	04/11/2014	Closed:	04/21/20)14
- replace right	t rear tire	with spare tire	and mount	new tire on	Parts Li	ist				Qty
spare rim		-			235 75r	17 Adventui	re			1.00
- Shop Suppli	es				Shop Su	upplies				1.00
					Tire Dis	posal Fee				1.00
		Hours 1.50		Labor:	90.00	Parts:	237.18	Total:	327.18	
Workorder: Problem:	1406158 pm,	Meter:	18739			In Date:	06/23/2014	Closed:	06/30/20)14
- pm					Parts Li	st				Qty
- Shop Suppli	es				Napago	ld Oil Filter				1.00
					Napa Q	uart 5w20				6.00
					Shop Su	upplies				1.00
		Hours 2.00 :		Labor:	120.00	Parts:	28.57	Total:	148.57	

Frobleig:	1407673 I front tire	Meter	: 20820		In	Date:	08/04/2014	Closed:	08/12/20)14
- ck flat tire ve	erify unable	to repair rer	olace two fron	t tires	Parts List					Qty
mount add n2	•				235 75r17 A	dventur	e			2.00
- Shop Suppli	es				Shop Suppl	ies				1.00
					Tire Disposa					2.00
	ŀ	Hours 1.50		Labor:	•		472.35	Total:	562.35	
Workorder: Problem:	1410008 P.M.SER\	Meter: VICE	: 24002		In	Date:	10/03/2014	Closed:	10/09/20)14
- Pm					Parts List					Qty
- Shop Suppli	es				Napagold O	il Filter				1.00
					Napa Quart					7.00
					Shop Suppl					1.00
	F ·	Hours 2.00		Labor:	120.00		32.47	Total:	152.47	
Workorder: Problem:	1500902 pm	Meter	29999		In	Date:	01/26/2015	Closed:	01/30/20)15
- pm					Parts List					Qty
- Shop Suppli	es				Napagold A	ir Filter				1.00
					Napagold O	il Filter				1.00
					Napa Quart	5w20				7.00
					Wiper Blade)				2.00
					Washer FI					1.00
					Shop Suppl	ies				1.00
	H :	Hours 2.00		Labor:	120.00	Parts:	51.74	Total:	171.74	
Workorder:	1504383 ROAD CA	Meter:	: 33958 ATTERY AT	451 S CON		Date:	04/29/2015	Closed:	04/30/20)15
Problem:		tery at 345 s	outh congress	S	Parts List					Qty
Problem: - road call jum	np start bat	•	•		Parts List Shop Suppl	ies				-
Problem: - road call jum - recharge bat	np start bat ttery and te	est charging :	sys fofund def			ies				-
Problem: - road call jum - recharge bat battery sys and - dealer tdo re	np start bat ttery and te d found de eplace batte	est charging stective batter ery warrnty	sys fofund del 'y			ies				Qty 1.00
Problem: - road call jum - recharge bat battery sys and	np start bat ttery and te d found de eplace batte	est charging stective batter ery warrnty	sys fofund del 'y			ies				-
Problem: - road call jum - recharge bat battery sys and - dealer tdo re	np start bat ttery and te d found de eplace batte d pick up v	est charging stective batter ery warrnty	sys fofund del 'y	fective	Shop Suppl	ies				-
Problem: - road call jum - recharge bat battery sys and - dealer tdo re - transport and	np start bat ttery and te d found de eplace batte d pick up v es	est charging stective batter ery warrnty	sys fofund del 'y	fective		ies Parts:	2.00	Total:	197.00	-
Problem: - road call jum - recharge bat battery sys and dealer tdo reduced transport and Shop Supplied	np start bat ttery and te d found de eplace batte d pick up v es F 1505356	est charging steetive batter ery warrnty vehicle at dea	sys fofund def y ıler 2 times	fective	Shop Suppl		2.00 05/28/2015	Total:	197.00	1.00
Problem: - road call jum - recharge bat battery sys and - dealer tdo re - transport and - Shop Supplie	np start bat ttery and te d found de eplace batte d pick up v es F 1505356	est charging sefective batter ery warrnty yehicle at dear Hours 3.25	sys fofund def y ller 2 times	fective	Shop Suppl	Parts:				1.00
Problem: - road call jum - recharge bat battery sys and - dealer tdo re - transport and - Shop Supplie Workorder: Problem:	np start bat ttery and te d found de eplace batte d pick up v es .: 1505356 pm	est charging sefective batter ery warrnty rehicle at dear Hours 3.25	sys fofund def y aler 2 times : 35320	fective	Shop Suppl	Parts:				1.00 015 Qty
Problem: - road call jum - recharge bat battery sys and - dealer tdo re - transport and - Shop Supplie Workorder: Problem: - pm	np start bat ttery and te d found dei eplace batte d pick up v es h: 1505356 pm	est charging sefective batter ery warrnty rehicle at dear Hours 3.25	sys fofund def y aler 2 times : 35320	fective	Shop Suppl 195.00 In Parts List	Parts: Date: iii Filter				1.00 015 Qty 1.00
Problem: - road call jum - recharge bat battery sys and - dealer tdo re - transport and - Shop Supplie Workorder: Problem: - pm - verify bumpe	np start bat ttery and te d found dei eplace batte d pick up v es h: 1505356 pm	est charging sefective batter ery warrnty rehicle at dear Hours 3.25	sys fofund def y aler 2 times : 35320	fective	195.00 In Parts List Napagold C	Parts: Date: iil Filter 5w20				1.00

Workorder: Problem:	1507444 If tire screw	Meter:	38684			In Date:	07/27/2015	Closed:	07/30/20	015
- ck nail fl tire	repair fl tire a	add n2			Parts L	ist				Qty
- Shop Suppli	-				Shop S	upplies				1.00
		urs 1.00		Labor:	•	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1509579 pm	Meter:	42211			In Date:	09/22/2015	Closed:	09/30/20	015
- pm					Parts L	ist				Qty
- replace both	rear tires an	d rotate to the	ne front		Napago	ld Oil Filter				1.00
- Shop Suppli	es				Napa Q	uart 5w20				7.00
					Wiper B					2.00
					•	Fluid Conce	entr			1.00
						17 Adventur				2.00
					Shop S					1.00
					-	posal Fee				2.00
	Но	urs 3.50		Labor:	210.00	•	470.76	Total:	680.76	
	:						0.1.1.0.10.0.1.0			
Workorder: Problem:	1600409 pm	Meter:	47711			In Date:	01/12/2016	Closed:	01/27/20	016
- pm					Parts L	ist				Qty
- Shop Suppli	es				5w20 S	yn Blend				7.00
						ld Oil Filter				1.00
						uart 5w20				14.00
					•	Fluid Conce	entr			1.00
					Shop S	upplies				1.00
	Ho :	urs 2.00		Labor:	120.00		88.36	Total:	208.36	
Workorder: Problem:	1603400 NAIL IN R/F	Meter: REAR TIRE	51810			In Date:	03/31/2016	Closed:	03/31/20	016
- Repair Nail	In R/rear Tire	:			Parts L	ist				Qty
- Shop Suppli					Shop S					1.00
		urs 1.00		Labor:	•	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1604502 Pm service.	Meter:	53857			In Date:	04/28/2016	Closed:	05/06/20	016
- Pm service.					Parts L	ist				Qty
- Replace two	tires.balance	e and rotate	all four add N	12.reset		ld Air Filter				1.00
Tpms.	5515414110					ld Oil Filter				1.00
- Verify needs		pads.turn rot	ors.service		. •	uart 5w20				7.00
calipers.r&r br						Fluid Conce	entr			1.00
- Shop Suppli	es					17 Adventur				2.00
							Ultra Premiur	n - Oe C		1.00
					Shop S		Jida i icililul	500		1.00
					-	posal Fee				2.00
	LJA	urs 7.00		Lobori	420.00	•	545.69	Total	965.69	∠.00
	II()	ui		. (100)	サノい いし	Faus	. 14. 1 ()27	10141	-nu: 1 (1)	

Workorder: Problem:	1608545 Pm Serv	Meter:	60580	e lights asp	er Bob Ni	In Date:	08/17/2016	Closed:	09/16/20)16
	1 111 0017	ioo.iiiotaii ioai		o ligitio dop	Parts Li					O41
- P.m.service	o Liabt Cv	otom				d Oil Filter				Qty 1.00
- Install Strobe					Butt Cor		4.			
- Repair Both		Lights.				ineci Butt Connec	ntor		100.0	
- Repair R/rea									1.00	
- Shop Suppli	es				•	uart 5w30				7.00
						Fluid Conce				1.00
						Led Strobe	: CI			4.00
					Fuse Ho					1.00
					Universa					1.00
						Silcn Sealar	nt			1.00
					Bulb				2.0	
					22" Wipe					2.00
					Used Fir Wire Ter			1.00		
							10.00 00.00			
						Butt Connector				
						12-10 Conn			10.00	
						-22 Conn				10.00
					Primary	Wire			10	00.00
					Vinyl Ele	ectrical Tap	е			1.00
					Fab Loo	m-split Poly	′		ţ	50.00
					Distribut	or Nipple			ţ	50.00
					Shop Su	ıpplies				1.00
		Hours 12.00 :		Labor:	720.00	Parts:	856.34	Total:	1,576.34	ŀ
Workorder: Problem:	1609641 bad batte		61167			In Date:	09/15/2016	Closed:	09/26/20)16
- C/c bad batt	ery.test a	nd replace bad	battery.che	ck charging	Parts Li	st				Qty
system.	•	•	•	0 0	Battery					1.00
- Shop Suppli	es				Shop Su	ipplies				1.00
		Hours 0.75		Labor:	•		126.43	Total:	171.43	
Workorder:	1610720	Meter:	62279			In Date:	10/18/2016	Closed:	10/28/20)16
		n, Found Code# vap. System &			Parts Li Shop Su					Qty 1.00
	· Bfd To E	m W/latest Cali 13a-12a650-sb 476-cb.								
- Test Drive B										
- Shop Suppli		z								
Chop Guppii		Hours 5.00		l ahor	300.00	Parts:	2.00	Total	302.00	
				Labul.	300.00	rans.	2.00	i Ulal.	302.00	

Workorder: 1612495 Meter: 64629 Problem: Check engine light on.	In Date: 12/06/2016 Closed: 12/19/2016
 Computer diagnose for check engine light on.code P0455.test and replace defective fuel filler neck and purge valve. Shop Supplies 	Parts List Qty Fuel Fill Pipe 1.00 Valva Asy 1.00
Hours 3.00 Labor	Shop Supplies 1.00 180.00 Parts: 124.99 Total: 304.99
Workorder: 1701092 Meter: 67094 Problem: PM service	In Date: 02/01/2017 Closed: 02/21/2017
- Pm Service Service rear differential.	Parts ListQtyNapagold Oil Filter1.00
Rotate and balance all tires.correct N2.relearn Tpms.Shop Supplies	5w20 Engine Oil 7.00 Napa 20w50 Qt 3.00
	Friction Modifier 1.00 Ptex Ultra Grey 3oz 1.00 Shop Supplies 1.00
Hours 4.00 Labor	240.00 Parts: 45.79 Total: 285.79
Workorder: 1705073 Meter: 72475 Problem: PM Service	In Date: 05/22/2017 Closed: 06/12/2017
- Pm service.	Parts List Qty
- Replace transmission pan gasket and filter.clean off pan	Drain Plug 1.00
and residue on transmission with big G and pressure	Napagold Oil Filter 1.00
cleaner use scan tool to read temp.and fill procedure. - Mount two tires and balance four.	Napa Quart 5w20 7.00
- Replace and installed steering wheel cover.	Napagold Air Filter 1.00
- R&r drive shaft to clean and lube slip joint.	Washer Fluid Concentr 1.00
- Shop Supplies	22" Wiper Blade 2.00
- Onop Supplies	Used Fire X Refurbished 1.00
	Stg Wheel Cov - Ford 1.00
	Tram Oil Gasket 1.00
	Screen Asy 1.00
	Syn Atf Bulk South 12.00
	235 75r17 Adventure 2.00
	Shop Supplies 1.00
	Tire Disposal Fee 2.00
Hours 9.75 Labor	585.00 Parts: 654.26 Total: 1,239.26
Workorder: 1706419 Meter: 73991 Problem: NAIL IN R/REAR TIRE	In Date: 06/28/2017 Closed: 06/30/2017
- Repair and balance right rear tire.	Parts List Qty
- Shop Supplies	Shop Supplies 1.00
Hours 1.00 Labor	60.00 Parts: 2.00 Total: 62.00

Workorder: Problem:	1708488 PM Service	Meter:	77930		In Date:	08/28/2017	Closed:	09/21/2017
- Pm Service				Pa	arts List			Qty
	ter pump,theri	mostat and	gasket and coolant	Na	apa Quart 5w20			7.00
			d gasket.fill and ble	- a	apagold Oil Filter	1.00		
system.				Wa	asher Fluid Cond		1.00	
			o rear rotors.replac ers,lube slides.flush		2" Wiper Blade	2.00		
and bleed sys		si vice calipe	is,iube sildes.ildsil		ater Pump		1.00	
-	balance four ti	ires.			nermostat		1.00	
- Shop Suppl	ies				eak Global Antifrz	<u>.</u>		2.00
				Bra	ake Pads - Front	, Ultra Premiur	n - Oe C	1.00
					otor	,		2.00
					sc Pad			1.00
					Fluid Dot 3-32oz			1.00
					on-chlor Brake Cl		1.00	
					nermostat Gasket			1.00
					asket			1.00
					nermostat			1.00
					ake Rotor			2.00
					nop Supplies			1.00
	Ηοι :	urs 16.75	Lab	oor: 1,0 0		668.36	Total:	1,673.36
Workorder: Problem:	1712374 P.M. service	Meter: and remove	82755 e rust stain and det		In Date:	12/15/2017	Closed:	12/21/2017
- P.m. Service					arts List			Qty
- Replace two	tires,rotate a	nd balance	all four.	Sp	beaker			1.00
- Replace lea		on seal.insp	ect and and service		v20 Engine Oil			7.00
		01/loft roots	oint oirquit		apagold Oil Filter			1.00
	rbag light.b00 replace left do		replace blown left	22	2" Wiper Blade	2.00		
door speaker.	.,		.,		asher Fluid Cond	1.00		
- Complete w	hool alianmon							
- Complete wheel alignment.test drive.				23	35 75r17 Adventu	re		2.00
- Shop Suppl	•	it.test drive.		_	35 75r17 Adventu iction Modifier	re		
- Shop Suppl	•	nt.test drive.		Fri Pte	iction Modifier ex Ultra Grey 3o	Z		2.00 1.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte	iction Modifier	Z		2.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte 75 Tir	iction Modifier ex Ultra Grey 30: 5w140 Ford Axle re Pressure Moni	z Lube	Sensor (2.00 1.00 1.00 3.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte 75 Tir Se	iction Modifier ex Ultra Grey 3o: iw140 Ford Axle re Pressure Moni eal Asy	z Lube	Sensor (2.00 1.00 1.00 3.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte 75 Tir Se Wi	iction Modifier ex Ultra Grey 3o: 5w140 Ford Axle re Pressure Moni eal Asy ire Asy	z Lube toring System	Sensor (2.00 1.00 1.00 3.00 1.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte 75 Tir Se Wi No	iction Modifier ex Ultra Grey 3oz iw140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl	z Lube toring System	Sensor (2.00 1.00 1.00 3.00 1.00 1.00 1.00
- Shop Suppl	•	nt.test drive.		Fri Pte 75 Tir Se Wi No Sh	iction Modifier ex Ultra Grey 3o: 5w140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl	z Lube toring System	Sensor (2.00 1.00 1.00 3.00 1.00 1.00 1.00
- Shop Suppl	ies			Fri Pte 75 Tir Se Wi No Sh	iction Modifier ex Ultra Grey 3oz iw140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl nop Supplies re Disposal Fee	z Lube toring System		2.00 1.00 1.00 3.00 1.00 1.00 1.00 2.00
- Shop Suppl	ies	urs 12.50	Lab	Fri Pte 75 Tir Se Wi No Sh	iction Modifier ex Ultra Grey 3oz iw140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl nop Supplies re Disposal Fee	z Lube toring System		2.00 1.00 1.00 3.00 1.00 1.00 1.00
Workorder:	Hou : 1800841	urs 12.50 Meter:	Lab 83069 ear fender & rear bu	Fri Pte 75 Tir Se Wi No Sh Tir por: 75	iction Modifier ex Ultra Grey 3oz iw140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl nop Supplies re Disposal Fee	z Lube toring System nr		2.00 1.00 1.00 3.00 1.00 1.00 1.00 2.00
Workorder: Problem:	Hou : 1800841 Damage to le	urs 12.50 Meter: eft & right re	83069 ear fender & rear bu	Fri Pte 75 Tir Se Wi No Sh Tir por: 75	iction Modifier ex Ultra Grey 302 5w140 Ford Axle re Pressure Moni eal Asy ire Asy on-chlor Brake Cl nop Supplies re Disposal Fee 50.00 Parts:	z Lube toring System nr 644.51	Total:	2.00 1.00 3.00 1.00 1.00 1.00 1.00 2.00 1,394.51

:

Workorder: Problem:	1801974 NAIL IN R/REA	Meter: AR TIRE	85166			In Date:	02/21/2018	Closed:	02/26/20	018
- Repair right	rear tire.				Parts L	ist				Qty
- Shop Suppl	ies				Shop Si	upplies				1.00
	Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1804393 PM Service	Meter:	89336			In Date:	04/26/2018	Closed:	05/16/20)18
- Pm Service.					Parts L	ist				Qty
- Rotate and	balance tires.				Napa Q	uart 5w20				7.00
- Shop Suppli	ies				Napago	ld Oil Filter				1.00
					Washer	Fluid Conce	entr			1.00
					22" Wip	er Blade				2.00
					Napago	ld Oil Filter				1.00
					Shop Si	upplies				1.00
	Hours	2.75		Labor:	165.00	Parts:	44.75	Total:	209.75	
Workorder: Problem:	1808172 P.M.SERVICE	Meter:	95268			In Date:	08/08/2018	Closed:	08/27/20)18
- Pm Service.					Parts L	ist				Qty
- Rotate and	balance tires				Napago	ld Oil Filter				1.00
- Repair right	rear tire.				Napa Q	uart 5w20				7.00
- Shop Suppl	ies				22" Wip	er Blade				2.00
					Washer	Fluid Conce	entr			1.00
					Napago	ld Air Filter				1.00
					Shop St	upplies				1.00
	Hours :	3.75		Labor:	225.00	Parts:	51.55	Total:	276.55	
Workorder:	1812642	Meter:	101213			In Date:	12/12/2018	Closed:	01/14/20)19
Problem:	PM Service									
- Pm service.					Parts L	ist				Qty
- Rotate and	balance four tire	S.			Napa Q	uart 5w20				7.00
- Vacume del	oris from air cow	l and eng	jine compartm	ent.	•	ld Oil Filter				1.00
- Shop Suppli	ies		-		Washer	Fluid Conce	entr			1.00
					22" Wip	er Blade				2.00
					Shop Si					1.00
	Hours	3.50		Labor:	234.50		44.01	Total:	278.51	

Workorder:	1904332	Meter:	107648			In Date:	04/22/2019	Closed:	05/06/2019
Problem:	PM Service.\	Viper moto	stay on.Ched	ck noise v	while drivi	ng.			
- Pm Service					Parts Li	st			Q
- Replace fou	ır tires.				Napagol	d Oil Filter			1.0
	otor stays on.			l no	Napa Qı	uart 5w20			7.0
	n pin point test lace wiper mot				22" Wipe	er Blade			2.0
	hile driving.tes			had	Washer	Fluid Conc	entr		1.0
	ngs.replace pir				Napagol	d Air Filter			1.0
differential.					Wd40 S	pr			1.0
- Test drive b	efore and afte	r repairs.			Hankool	k P235 75r1	7 Dp At		4.0
•	- Replace how is my driving sticker.				Wiper M	otor			1.0
- Shop Suppl	ies				75w140	Ford Axle L	₋ube		2.0
					Non-chlo	or Brake Cli	nr		1.0
					Ptex Ulti	ra Grey 3oz	•		1.0
					Bearing				1.0
					Seal Asy	/			2.0
					Spacer				1.0
					Bearing				1.0
					Kit Spac				1.0
					Shop Su				1.0
		4= 0=			-	osal Fee	4 0 40 00		4.0
	Hou :	rs 15.25		Labor:	1,021.7 5	Parts:	1,349.89	Total:	2,371.64
Workorder:	1908221	Meter:	113393			In Date:	08/07/2019	Closed:	08/19/2019
Problem:	PM Service .	Wiper switc	h intermittent.						
- Pm Service					Parts Li	st			Q
	witch intermitte				Napa Qı	uart 5w20			7.0
test and found wheel and rep		tion switch	remove steer	ing	Napagol	d Oil Filter			1.0
	balance tires.					Fluid Conc	entr		1.0
- Shop Suppl					22" Wipe				2.0
						e X Refurb	ished		1.0
					Switch				1.0
					Shop Su	• •			1.0
	Hou :	rs 5.25		Labor:	351.75	Parts:	109.26	Total:	461.01
Workorder:	1911821	Meter:	117538			In Date:	11/14/2019	Closed:	11/14/2019
Problem:	remove GPS	& extra de	cals						
- remove Gps	s & extra deca	S			Parts Li	st			Q
- Shop Suppl					Shop Su				1.0
		rs 1.50		Labor:	109.50	Parts:	4.00	Total:	113.50

Workorder: 1911833 **Meter:** 117538 **In Date:** 11/14/2019 **Closed:** 11/14/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00

: