

**Palm Beach County Fleet Management
Asset Maintenance History**

10195197 2014 FORD F150 Pickup, 1/2 Ton

Workorder: 1404038 **Meter:** 351 **In Date:** 04/25/2014 **Closed:** 04/25/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1407534 **Meter:** 5696 **In Date:** 07/31/2014 **Closed:** 08/07/2014
Problem: P.M. Service.

- Perform pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 21.19 Total: 201.19
 :

Workorder: 1411777 **Meter:** 11812 **In Date:** 11/20/2014 **Closed:** 12/04/2014
Problem: Pm service.Wiper blades and right rear tire flat,

- Pm service.

- Repair flat right rear tire.rotate and balance all four.

- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Washer Fl	1.00
Wiper Blade	2.00
Stg Wheel Cov - Ford	1.00
Floor Mat-2pc Rub Bk	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours 4.00 Labor: 240.00 Parts: 104.17 Total: 344.17
 :

Workorder: 1505305 **Meter:** 16168 **In Date:** 05/27/2015 **Closed:** 05/29/2015
Problem: to vista garage

- Jump start vehicle drop to Lv shop

- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505312 **Meter:** 16177 **In Date:** 05/27/2015 **Closed:** 06/04/2015
Problem: Pm service.Dead battery.

- Pm service.	Parts List	Qty
- Check starting and charging system.battery failed loadtest after recharge.replace defective battery.	5w20 Engine Oil	6.00
- Replace broken right side mirror glass.	Napagold Oil Filter	1.00
- Diagnose high pitch noise coming from ac blower motor assembly.replace defective blower motor assembly.	Wiper Blade	2.00
- Rotate and balance all four tires.	Mac Wite Lithium Gres	1.00
- Shop Supplies	Battery	1.00
	side mirror glass asy	1.00
	Blower Motor	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 326.41
:		Total: 656.41

Workorder: 1508677 **Meter:** 22427 **In Date:** 08/31/2015 **Closed:** 09/28/2015
Problem: P.M. Service.

- Pm service.	Parts List	Qty
- Replace and balance all four tires.	Napagold Oil Filter	1.00
- Complete alignment.test drive.	5w20 Engine Oil	7.00
- Transport vehicle to and from dealer for right front strut replacement.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Napagold Air Filter	1.00
	Hankook P235 75r17 Dp At	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 510.00	Parts: 915.84
:		Total: 1,425.84

Workorder: 1509436 **Meter:** 22119 **In Date:** 09/18/2015 **Closed:** 09/18/2015
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1511517 **Meter:** 25760 **In Date:** 11/10/2015 **Closed:** 11/12/2015
Problem: Right rear tire going flat.

- Replace and balance one tire due to side wall damage.	Parts List	Qty
- Shop Supplies	Hankook P235 75r17 Dp At	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 0.50	Labor: 30.00	Parts: 215.61
:		Total: 245.61

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1513012 **Meter:** 28915 **In Date:** 12/29/2015 **Closed:** 01/19/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Rotate and balance all four tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 43.09
:		Total: 223.09

Workorder: 1603780 **Meter:** 35271 **In Date:** 04/11/2016 **Closed:** 04/19/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 24.77
:		Total: 204.77

Workorder: 1608979 **Meter:** 41539 **In Date:** 08/29/2016 **Closed:** 09/12/2016
Problem: P.M. Service.Install strobe lights.

- P.m. Service.	Parts List	Qty
- Replace front brake rotors,replace brakes.service and lube calipers.flush and bleed system.test drive.	5w20 Engine Oil	6.00
- Install four corner strobe lights.fabricate and install wiring and switch.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	22" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Front Rotor	2.00
	Front Brake Pad	1.00
	Vtx609a Led Strobe Am	2.00
	Vtx609c Led Strobe Cl	2.00
	Fuse Holder	1.00
	Rocker Led Blk Ambe	1.00
	Clr Rtv Silcn Sealant	1.00
	Fab Loom-split Poly	35.00
	Shop Supplies	1.00
Hours 14.50	Labor: 870.00	Parts: 840.38
:		Total: 1,710.38

Workorder: 1610347 **Meter:** 42700 **In Date:** 10/03/2016 **Closed:** 10/14/2016
Problem: Right front tire going flat.

- Repair and balance right front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700447 **Meter:** 47203 **In Date:** 01/13/2017 **Closed:** 01/31/2017
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace and balance four new tires.	5w20 Engine Oil	6.00
- Pressure test and inspect cooling system.flush and refill system.	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
- Complete wheel alignment.test drive.	235 75r17 Adventure	4.00
- Shop Supplies	Anti Freeze Motorcraft	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 510.00	Parts: 937.74
:		Total: 1,447.74

Workorder: 1705075 **Meter:** 52814 **In Date:** 05/22/2017 **Closed:** 05/31/2017
Problem: P.M. service and left speaker cuts out ,feels like engine going to stall at times,bumper damage.

- P.m. service.	Parts List	Qty
- Diagnose engine stalling with scan tool.no codes detectedand check purge valve test.purge valve not holding vacuum.replace faulty purge valve with new and retest, passed.	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
- Load test battery and recharge.replace failed battery with new.not holding charge.	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
- Inspect drivers door speaker and circuit turning off sound.replace faulty speaker harness assembly with new.	Valva Asy	1.00
	Battery	1.00
- Roatate and balance four tires.	Wire Asy	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 241.00
:		Total: 691.00

Workorder: 1705987 **Meter:** 52814 **In Date:** 05/30/2017 **Closed:** 06/16/2017
Problem: Damage to rear bumper & right side of bed

- Damage to rear bumper & right side of bed			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1710820 **Meter:** 58962 **In Date:** 11/01/2017 **Closed:** 11/16/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Rotate and balance four tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 27.01
:		Total: 207.01

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801712 **Meter:** 62234 **In Date:** 02/13/2018 **Closed:** 02/14/2018
Problem: Screw in drivers rear tire.

- Repair left rear tire and balance .	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00 Parts: 2.00	Total: 62.00
:		

Workorder: 1804077 **Meter:** 65305 **In Date:** 04/19/2018 **Closed:** 04/27/2018
Problem: P.M. service and inverter inop.

- P.m. service.	Parts List	Qty
- Resurface all four brake rotors and replace rear brake pads and calipers .service front calipers .flush and bleed brake system .test drive.	Housing	1.00
- Replace two worn tire .balance and rotate all four tires.	Drain Plug	1.00
- Test and diagnose inverter .r&r defective inverter and circuit breaker and fabricate wiring harness .retest.	5w20 Engine Oil	6.00
- Complete front end alignment.road test.	Napagold Oil Filter	1.00
- Shop Supplies	Drain Plug	1.00
	Used Fire X Refurbished	1.00
	22" Wiper Blade	2.00
	Fron Brake Pad	1.00
	Brk Fluid Dot 4-12oz	2.00
	235 75r17 Adventure	2.00
	400 Watt Pwr Inverter	1.00
	Housing	1.00
	Caliper Washer	4.00
	Cpi 1575 Inverter 1500 W	1.00
	Cabl/lug	4.00
	Inverter Cable End 4ga	2.00
	Fab Loom-split Poly	8.00
	Cb185-100 Cir Brkr	1.00
	Bulk Trailer Wire	8.00
	Bulk Battery Cable	3.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 15.00	Labor: 900.00 Parts: 1,007.88	Total: 1,907.88
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810324 **Meter:** 71934 **In Date:** 10/04/2018 **Closed:** 10/24/2018
Problem: P.M. Service.Check speedometer calibration for accuracy.

- P.m. Service. Test drive vehicle and compared speedometer reading with Waze App. Speed was within 1 (one mile) +/-, which is acceptable per manufacturers specification.
- Replace two tires,rotate and balance all four.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
White Shepherd Stp Lk	1.00
Hankook P235 75r17 Dp At	2.00
22" Wiper Blade	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 4.00 Labor: 268.00 Parts: 524.79 Total: 792.79

:

Workorder: 1903264 **Meter:** 78396 **In Date:** 03/26/2019 **Closed:** 04/03/2019
Problem: PM Service

- P.m. service.
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Ford Triton Pvc Swc	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 201.00 Parts: 59.84 Total: 260.84

:

Workorder: 1903613 **Meter:** 78355 **In Date:** 04/02/2019 **Closed:** 04/02/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

:

Workorder: 1908989 **Meter:** 83020 **In Date:** 08/28/2019 **Closed:** 08/29/2019
Problem: Spare on right rear . Flat tire .

- Repair right rear tire and balance . Remount spare and nitrofill all.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 67.00 Parts: 3.00 Total: 70.00

:

Workorder: 1909000 **Meter:** 83020 **In Date:** 08/27/2019 **Closed:** 08/28/2019
Problem: Passenger rear tire is flat. Put spare on. Driver will remain with the vehicle

- Tow From: 15429 Temple Blvd, Loxahatchee

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1911827 **Meter:** 86533 **In Date:** 11/14/2019 **Closed:** 11/15/2019
Problem: remove GPS & extra decals

- remove Gps & extra decals					
- Shop Supplies					
	Hours 1.50	Labor: 109.50	Parts: 4.00	Total: 113.50	
	:				

Workorder: 1911849 **Meter:** 86533 **In Date:** 11/15/2019 **Closed:** 11/15/2019
Problem: Transition Prep Charge

- Transition Prep Charge					
	Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00	
	:				