

**Palm Beach County Fleet Management
Asset Maintenance History**

10195199 2014 FORD F150 Pickup, 1/2 Ton

Workorder: 1404095 **Meter:** 323 **In Date:** 04/29/2014 **Closed:** 04/29/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1408372 **Meter:** 5769 **In Date:** 08/22/2014 **Closed:** 08/29/2014
Problem: Pm service.

- Perform pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List Qty

Napagold Oil Filter 1.00

5w20 Engine Oil 7.00

Washer Fluid Concentr 1.00

Shop Supplies 1.00

Hours 3.00 Labor: 180.00 Parts: 25.51 Total: 205.51
:

Workorder: 1411978 **Meter:** 10804 **In Date:** 12/01/2014 **Closed:** 12/10/2014
Problem: Pm service.Flat tire in bed of truck.

- Pm service.

- Replace one tire.rotate and balance all four.

- Shop Supplies

Parts List Qty

Hankook P235 75r17 Dp At 1.00

5w20 Engine Oil 6.00

Napa Oil Filter 1.00

Napagold Air Filter 1.00

Floor Mat-2pc Rub Bk 1.00

Stg Wheel Cov - Ford 1.00

Washer Fluid Concentr 1.00

Used Fire X Refurbished 1.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours 3.25 Labor: 195.00 Parts: 330.69 Total: 525.69
:

Workorder: 1503254 **Meter:** 16590 **In Date:** 03/30/2015 **Closed:** 04/08/2015
Problem: Pm service.

- Pm service.

- Replace one tire.rotate and balance all four.

- Shop Supplies

Parts List Qty

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

Wiper Blade 2.00

Wd40 16oz 1.00

Hankook P235 75r17 Dp At 1.00

Cover 1.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours 3.25 Labor: 195.00 Parts: 279.90 Total: 474.90
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1507440 **Meter:** 21958 **In Date:** 07/27/2015 **Closed:** 08/06/2015
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 41.35
:		Total: 221.35

Workorder: 1510902 **Meter:** 26564 **In Date:** 10/28/2015 **Closed:** 11/04/2015
Problem: P.M. Service.

- Pm service.	Parts List	Qty
- Replace cracked left tail light lens..remove center console to reinstall cup holders.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Air Filter	1.00
	22" Wiper Blade	2.00
	Floor Mat-2pc Rub Bk	1.00
	Stg Wheel Cov - Ford	1.00
	Wd40 16oz	1.00
	Lamp Assembly	1.00
	Shop Supplies	1.00
Hours 4.25	Labor: 255.00	Parts: 199.10
:		Total: 454.10

Workorder: 1602313 **Meter:** 32552 **In Date:** 03/04/2016 **Closed:** 03/17/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace two front tires.rotate and balance all four.	5w20 Engine Oil	6.00
- Transport vehicle to and from dealer for repairing air bag light on.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 360.00	Parts: 459.38
:		Total: 819.38

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1606264 **Meter:** 37910 **In Date:** 06/20/2016 **Closed:** 06/29/2016
Problem: P.M. Service..Install strobe lights.

- P.m. Service.	Parts List	Qty
- Install four cornedr strobe lights.fabricate and install wiring and switch.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	5w20 Engine Oil	7.00
- Shop Supplies	Air Filter	1.00
	22" Wiper Blade	2.00
	Mac Wite Lithium Gres	1.00
	Vtx609c Led Strobe Cl	2.00
	Vtx609a Led Strobe Am	2.00
	Fuse Holder	1.00
	Rocker Led Blk Ambe	1.00
	Fab Loom-split Poly	15.00
	Shop Supplies	1.00
Hours 11.00	Labor: 660.00	Parts: 523.40
:		Total: 1,183.40

Workorder: 1608877 **Meter:** 41120 **In Date:** 08/25/2016 **Closed:** 09/08/2016
Problem: Check engine light on and runs rough and right front tire going flat.

- Diagnose check engine light.p2195.perform pin point test.replace defective bank 1,sensor 1 oxygen sensor.clear codes.	Parts List	Qty
- Replace broken left side vent.	Sensor	1.00
- Reoair and balance right front tire.	Louvre	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 218.08
:		Total: 443.08

Workorder: 1610726 **Meter:** 43234 **In Date:** 10/18/2016 **Closed:** 10/31/2016
Problem: P.M. Service.Check tires for slow leak.

- P.m. Service.	Parts List	Qty
- Replace two tires,repair one.rotate and balance all four.	Napagold Oil Filter	1.00
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	5w20 Engine Oil	7.00
- Pressure test and inspect cooling system.flush and refill system.	22" Wiper Blade	2.00
- Complete wheel alignment.test drive.	Washer Fluid Concentr	1.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Battery 65	1.00
	Ford Red Antifreeze	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.50	Labor: 570.00	Parts: 639.51
:		Total: 1,209.51

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701686 **Meter:** 49262 **In Date:** 02/16/2017 **Closed:** 03/06/2017
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. Service. - Resurface front brake rotors,replace front pads and calipers.flush and bleed system. - Rotate and balance tires. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Brake Pad Front Caliper Motorcraft Front Caliper Motorcraft B Fluid Dot 3-32oz Non-chlor Brake Clnr Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 6.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 	
Hours 6.50 :	Labor: 390.00	Parts: 321.37	Total: 711.37

Workorder: 1704501 **Meter:** 53108 **In Date:** 05/04/2017 **Closed:** 05/18/2017
Problem: P.M. service and check engine light on.

<ul style="list-style-type: none"> - P.m. service. - Computer diagnose .codes p2196 and p2198.performed evap test found defective evap purge valve control.replace valve .clear codes .test drive to verify normal operation. - Balance and rotate all four tires . - Check ,pinpoint test and replace two defective 20amp fuses ,one for cigar lighter and one for power outlet. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Bp Fmx-lp F Mx Fuse Valva Asy Used Fire X Refurbished Bp Fmx-lp F Mx Fuse Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 6.00 1.00 2.00 2.00 1.00 1.00 1.00 1.00 	
Hours 6.00 :	Labor: 360.00	Parts: 95.98	Total: 455.98

Workorder: 1708267 **Meter:** 58460 **In Date:** 08/22/2017 **Closed:** 08/31/2017
Problem: P.M. service and left rear tire going flat.

<ul style="list-style-type: none"> - P.m. service. - Check and replace defective trailer plug socket. - Inspect and perform transmission fluid flush and refill. - Check and perform coolant perssure test.found leaking water pump.remove and replace fefective water pump and thermostat housing, drive belt,o-rings.flush coolant Retest. - Repair left rear tire .balance and rotate all four. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade trailer plug Syn-atf Trans Fluid S Water Pump Anti Freeze Motorcraft V Belt Tmermostat Housing Gasket Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 6.00 1.00 2.00 1.00 12.00 1.00 2.00 1.00 1.00 1.00 1.00 	
Hours 10.00 :	Labor: 600.00	Parts: 382.79	Total: 982.79

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709547 **Meter:** 58985 **In Date:** 09/29/2017 **Closed:** 09/29/2017
Problem: BROKEN WIPER BLADE PASSENGER SIDE

- Repair R/side W/blade

Hours 0.25 Labor: 15.00 Parts: 0.00 Total: 15.00
:

Workorder: 1709649 **Meter:** 58985 **In Date:** 09/01/2017 **Closed:** 10/03/2017
Problem: Damage to right side lower bed, right side of cab & right side door

- Damage to right side lower bed, right side of cab & right side door

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1712659 **Meter:** 62736 **In Date:** 12/22/2017 **Closed:** 12/28/2017
Problem: Left rear tire flat.

- Replace both rear tires and balance .nitrogen fill tires.
- Shop Supplies

Parts List	Qty
Hankook P235 75r17 Dp At	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 1.00 Labor: 60.00 Parts: 373.05 Total: 433.05
:

Workorder: 1801028 **Meter:** 64233 **In Date:** 01/29/2018 **Closed:** 02/05/2018
Problem: P.M. service and left rear tire going flat.

- P.m. service.
- Resurface rear brake rotors and service parking brakes and calipers.replace pads .flush and bleed brake system .road test.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Tire Crayon	1.00
B Fluid Dot 3-32oz	1.00
Non-chlor Brake Clnr	1.00
lube	1.00
Fron Brake Pad	1.00
Shop Supplies	1.00

Hours 6.50 Labor: 390.00 Parts: 119.80 Total: 509.80
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804978 **Meter:** 69837 **In Date:** 05/14/2018 **Closed:** 05/24/2018
Problem: P.M. service and left outside mirror broken .

- P.m. service.	Parts List	Qty
- R&r broken mirror glass.	5w20 Engine Oil	6.00
- Inspect and service rear differential.	Napagold Oil Filter	1.00
- Rotate and balance all four tires. Nitrogen fill all tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Ford Triton Pvc Swc	1.00
	22" Wiper Blade	2.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	1.00
	Mirror Asy	1.00
	Mirror	1.00
	Shop Supplies	1.00
Hours 4.80	Labor: 288.00	Parts: 596.12
:		Total: 884.12

Workorder: 1809118 **Meter:** 74870 **In Date:** 09/05/2018 **Closed:** 09/19/2018
Problem: P.M. Service.Driver mirror cover blew off.

- P.m. service.	Parts List	Qty
- Replace two worn tires . High speed balance all four and nitrogen fill tires.	Napagold Oil Filter	1.00
- Remove left front door panel to replace outside mirror assembly.	5w20 Engine Oil	6.00
- Complete front end alignment. Road test.	22" Wiper Blade	2.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Mirror Asy	1.00
	Mirror Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 7.50	Labor: 450.00	Parts: 1,105.01
:		Total: 1,555.01

Workorder: 1812381 **Meter:** 78286 **In Date:** 12/05/2018 **Closed:** 12/10/2018
Problem: Dome light stays on,message on dash.

- Computer diagnose dome light stays on .monitor pids .	Parts List	Qty
Remove left front door panel to replace door harness .	Wire Asy	1.00
Retest.	Shop Supplies	1.00
- Shop Supplies		
Hours 1.50	Labor: 100.50	Parts: 30.72
:		Total: 131.22

Workorder: 1900828 **Meter:** 80020 **In Date:** 01/23/2019 **Closed:** 01/31/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Rotate and high speed balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	6.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
Hours 3.00	Labor: 201.00	Parts: 27.72
:		Total: 228.72

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906340 **Meter:** 86811 **In Date:** 06/17/2019 **Closed:** 06/24/2019
Problem: P.M. service and both inverters are inop .

- P.m. service.	Parts List	Qty
- Diagnose both inverters inop . Test and replace both . retest .	Napagold Oil Filter	1.00
- Rotate and balance all four tires . Nitrofill all.	5w20 Engine Oil	6.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Ford Triton Pvc Swc	1.00
	400w Inverter Cobra	2.00
	Shop Supplies	1.00
Hours 4.50	Labor: 301.50	Parts: 139.97
:		Total: 441.47

Workorder: 1909785 **Meter:** 91216 **In Date:** 09/23/2019 **Closed:** 10/07/2019
Problem: P.M. Service

- P.m. service.	Parts List	Qty
- Test and replace inop strobe light switch .	5w20 Engine Oil	7.00
- Perform complete air intake decarb and cleaning . Flush injectors .	Napagold Oil Filter	1.00
- Perform tune up . Replace all six spark plugs and upper intake gasket .	22" Wiper Blade	2.00
- Replace two tires and rotate and balance all four tires . Nitrofill all and reset Tpms .	Rocker Led Blk Ambe	1.00
- Shop Supplies	Intake Cleaner Kit	1.00
	Motor Tune-up 16oz	1.00
	Gasket	1.00
	Spark Plugs	6.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.10	Labor: 664.30	Parts: 593.63
:		Total: 1,257.93

Workorder: 1911808 **Meter:** 92832 **In Date:** 11/14/2019 **Closed:** 11/14/2019
Problem: remove GPS

- remove Gps & extra decals	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 109.50	Parts: 4.00
:		Total: 113.50

Workorder: 1911824 **Meter:** 92832 **In Date:** 11/14/2019 **Closed:** 11/14/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00