

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10170975    2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg**

<b>Workorder:</b> 746328	<b>Meter:</b> 320	<b>In Date:</b> 10/26/2007	<b>Closed:</b> 10/29/2007
<b>Problem:</b> REPAIR TRAILER PLUG WIRING			
- Rewire Trailer Plug		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			
<b>Workorder:</b> 746395	<b>Meter:</b> 0	<b>In Date:</b> 10/29/2007	<b>Closed:</b> 10/29/2007
<b>Problem:</b> PRE-DELIVERY INSPECTION			
- Pre-delivery Inspection			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			
<b>Workorder:</b> 746443	<b>Meter:</b> 0	<b>In Date:</b> 10/30/2007	<b>Closed:</b> 10/30/2007
<b>Problem:</b> 001 KEY ISSUED OUT	10/30/07		
- 001 Key Issued Out	10/30/07	<b>Parts List</b>	<b>Qty</b>
		Duplicate Vehicle Keys	1.00
Hours 0.20	Labor: 0.00	Parts: 3.00	Total: 3.00
:			
<b>Workorder:</b> 746845	<b>Meter:</b> 339	<b>In Date:</b> 11/06/2007	<b>Closed:</b> 11/07/2007
<b>Problem:</b> INSTALL TOOL BOX			
- Install Tool Box In Back Of Bed		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Tbsd72lp Tool Box (united Welding)	1.00
Hours 1.00	Labor: 60.00	Parts: 429.20	Total: 489.20
:			
<b>Workorder:</b> 746969	<b>Meter:</b> 384	<b>In Date:</b> 11/08/2007	<b>Closed:</b> 11/09/2007
<b>Problem:</b> INSTALL COMPUTER STAND.			
- Custum Install Computer Stand And Wiring Harness For Laptop		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 2.00	Total: 182.00
:			
<b>Workorder:</b> 834056	<b>Meter:</b> 2270	<b>In Date:</b> 02/12/2008	<b>Closed:</b> 02/20/2008
<b>Problem:</b> BATTERY KEEP GOING DEAD.			
- Test Battery & Charging System.ok.test For Draw. .07amp Draw From Laptop Computer Charger.left Plugged In.reset System.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 837488	<b>Meter:</b> 3792	<b>In Date:</b> 04/24/2008	<b>Closed:</b> 04/28/2008
<b>Problem:</b> P.M SERVICE,SERVICE LIGHT ON			
- Pm Service,no Service Lights On At This Time.		<b>Parts List</b>	<b>Qty</b>
- High Speed Balance 4 Tires,nitro Filled.		Shop Supplies	1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil	7.00
Hours 3.75	Labor: 225.00	Parts: 35.99	Total: 260.99
:			
<b>Workorder:</b> 838396	<b>Meter:</b> 0	<b>In Date:</b> 04/25/2008	<b>Closed:</b> 05/13/2008
<b>Problem:</b> ALVIN MATTHEWS PAINT & BODY			
- Alvin Matthews Paint & Body			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 838433	<b>Meter:</b> 3981	<b>In Date:</b> 05/13/2008	<b>Closed:</b> 05/15/2008
<b>Problem:</b> CHECK ENGINE LIGHT ON			
- Perform Computer Diagnostics,pz135 Tps Out Of Range,refer To Dealer For Warranty		<b>Parts List</b>	<b>Qty</b>
- Transport Vehicle To And Fr Dealer For Warranty Repairs To Trottle Sensors/trottle Body.		Shop Supplies	1.00
- Shop Supplies			
Hours 2.40	Labor: 144.00	Parts: 2.00	Total: 146.00
:			
<b>Workorder:</b> 842849	<b>Meter:</b> 6011	<b>In Date:</b> 08/14/2008	<b>Closed:</b> 08/18/2008
<b>Problem:</b> TRAILER FAULT LIGHT COMES ON			
- Test & Replace Corroded Trailer Plug Socket.also Repair Wiring Harness To Plug.		<b>Parts List</b>	<b>Qty</b>
- Replace Broken Trailer Hitch Pintle Pin.		Shop Supplies	1.00
- Shop Supplies		5404 Female Connector	1.00
		18410 Pintle Pin	1.00
Hours 1.50	Labor: 90.00	Parts: 14.11	Total: 104.11
:			
<b>Workorder:</b> 845685	<b>Meter:</b> 0	<b>In Date:</b> 10/10/2008	<b>Closed:</b> 10/15/2008
<b>Problem:</b> 001 WASH TICKET ISSUED OUT 10/10/08			
- 001 Wash Ticket Issued Out 10/10/08			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 845974	<b>Meter:</b> 7590	<b>In Date:</b> 10/21/2008	<b>Closed:</b> 10/27/2008
<b>Problem:</b> P.M SERVICE			
- Pm Service		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil	7.00
		31-20 Wiper Blades 20" Blade	2.00
Hours 2.75	Labor: 165.00	Parts: 49.75	Total: 214.75
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 848483      **Meter:** 8931      **In Date:** 12/22/2008      **Closed:** 12/24/2008  
**Problem:** REPAIR TRAILER WIRING

- Install New Truck Plug, Fasten Mount And Wire	<b>Parts List</b>	<b>Qty</b>
- Test Drive	Shop Supplies	1.00
- Shop Supplies	5404 Female Connector	1.00
Hours 2.00	Labor: 120.00      Parts: 12.10	Total: 132.10
:		

**Workorder:** 932478      **Meter:** 8967      **In Date:** 01/08/2009      **Closed:** 01/13/2009  
**Problem:** INSTALL FUEL TANK

- Install Fuel Tank In Truck And Pump Electrical.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	30055-20 Ckt Breaker 20 Amp	1.00
Hours 10.00	Labor: 600.00      Parts: 6.95	Total: 606.95
:		

**Workorder:** 934649      **Meter:** 0      **In Date:** 03/02/2009      **Closed:** 03/02/2009  
**Problem:** 002 KEYS ISSUED OUT      03/02/09

- 002 Keys Issued Out      03/02/09	<b>Parts List</b>	<b>Qty</b>
	Duplicate Vehicle Keys	2.00
Hours 0.40	Labor: 24.00      Parts: 6.00	Total: 30.00
:		

**Workorder:** 936274      **Meter:** 10773      **In Date:** 04/09/2009      **Closed:** 04/14/2009  
**Problem:** P.M SERVICE,NOISE IN FRONTEND

- Pm Service	<b>Parts List</b>	<b>Qty</b>
- Mount And Balance And Nitro Fill 4 New Tires.	Shop Supplies	1.00
- Replace Missing Pindle Safety Pin.	70236 Fuel Filter 10 Micron Biodiesel	1.00
- Service Aux Fuel Tank And Pump.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Test Drive For Rattle Noise Over Bumper.replace Stripped Mounting Bolt For Front Bumper Brace.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	-1.00
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Tire Disposal Fee	4.00
	Tr416 Valve Stem	4.00
	Lt245/75r17 Tire	4.00
	18410 Pintle Pin	1.00
Hours 7.25	Labor: 435.00      Parts: 875.55	Total: 1,310.55
:		

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 944223      **Meter:** 13348      **In Date:** 10/06/2009      **Closed:** 10/15/2009

**Problem:** pm service also see notes on floor carpet

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- Inspect & service aux fuel tank.	Shop Supplies	1.00
- Rotate & balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Remove computer stand & misc items from cab for dealer warranty of floor mat.	70236 Fuel Filter 10 Micron Biodiesel	1.00
- To/from dealer for warrenty floor mat.	5w20 Engine Oil	7.00
- Shop Supplies	Floor Mat Set	1.00
Hours 8.25	Labor: 495.00	Parts: 104.58
:		Total: 599.58

**Workorder:** 1000116      **Meter:** 14564      **In Date:** 12/29/2009      **Closed:** 01/05/2010

**Problem:** Frt flat tire

- 8100 forest hill Blvd	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1002928      **Meter:** 15891      **In Date:** 03/23/2010      **Closed:** 03/23/2010

**Problem:** Needs hitch receiver

- Assemble pintal hitch & mount, install on truck.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	6033 Mounted Pintles Ball/pintle Hitch	1.00
	2571 Receiver Lock 5/8"	1.00
	2535 D.p. Hitch Mount	1.00
Hours 0.80	Labor: 48.00	Parts: 150.91
:		Total: 198.91

**Workorder:** 1003485      **Meter:** 16373      **In Date:** 04/05/2010      **Closed:** 04/13/2010

**Problem:** P.M service.

- P.m service.	<b>Parts List</b>	<b>Qty</b>
- Inspect & service aux fuel tank & pump.	Shop Supplies	1.00
- Repair R/f tire, rotate & balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	70236 Fuel Filter 10 Micron Biodiesel	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.75	Labor: 345.00	Parts: 58.65
:		Total: 403.65

**Workorder:** 1007070      **Meter:** 17638      **In Date:** 07/06/2010      **Closed:** 07/13/2010

**Problem:** P.M.service

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Service aux. fuel tank and replace filter.	Shop Supplies	1.00
- Repair right front tire.rotate and balance all four.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	70236 Fuel Filter 10 Micron Biodiesel	1.00
	5w20 Engine Oil	7.00
Hours 5.75	Labor: 345.00	Parts: 56.33
:		Total: 401.33

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1010410	<b>Meter:</b> 18410	<b>In Date:</b> 09/22/2010	<b>Closed:</b> 09/30/2010
<b>Problem:</b> Popping noise left front tire on turns.			
- Check front end for noise.transport vehicle to dealer for defective lower ball joints.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1012822	<b>Meter:</b> 18776	<b>In Date:</b> 11/17/2010	<b>Closed:</b> 11/29/2010
<b>Problem:</b> Noise on left front on turns and bumps.			
- Inspect And duplicate noise to front bumper contact fender.isolate and adjust front bumper.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1100788	<b>Meter:</b> 19385	<b>In Date:</b> 01/20/2011	<b>Closed:</b> 01/28/2011
<b>Problem:</b> Pm service,also see notes on bumper repair			
- P.m. Service.	<b>Parts List</b>		<b>Qty</b>
- Replace right headlamp.	Shop Supplies		1.00
- Inspect and service aux. fuel tank.	1372 Oil Filter Frm Ph2 Wix 51372		1.00
- Replace dome light bulb and cargo lamp bulbs.	70236 Fuel Filter 10 Micron Biodiesel		1.00
- Rotate and balance all tires.	5w20 Engine Oil		7.00
- Shop Supplies	31-20 Wiper Blades 20" Blade		2.00
	H6054 Sealed Beam		1.00
Hours 6.00	Labor: 360.00	Parts: 61.54	Total: 421.54
:			
<b>Workorder:</b> 1101692	<b>Meter:</b> 19427	<b>In Date:</b> 01/31/2011	<b>Closed:</b> 02/14/2011
<b>Problem:</b> damage to frt bumper			
- damage to frt bumper			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1103618	<b>Meter:</b> 20531	<b>In Date:</b> 04/04/2011	<b>Closed:</b> 04/07/2011
<b>Problem:</b> Had to jump start every morning.			
- Test starting and charging system.battery failed load test after recharge.replace failed battery with new.	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
	Group 65 Battery (mtc Bxt-65-850)		1.00
Hours 1.00	Labor: 60.00	Parts: 130.75	Total: 190.75
:			
<b>Workorder:</b> 1107441	<b>Meter:</b> 22320	<b>In Date:</b> 07/15/2011	<b>Closed:</b> 07/25/2011
<b>Problem:</b> Pm service.			
- Perform pm service.	<b>Parts List</b>		<b>Qty</b>
- Perform auxiliary fuel tank service and replace fuel filter.	Shop Supplies		1.00
- Rotate and balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372		1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243		1.00
	24006 Fuel Filter Diesel And Gas		1.00
	5w20 Engine Oil		7.00
Hours 4.75	Labor: 285.00	Parts: 33.39	Total: 318.39
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1111085      **Meter:** 23701      **In Date:** 10/18/2011      **Closed:** 10/24/2011  
**Problem:** Right turn signal inop and low tire pressure warning light on.

- Test and replace failed right rear turn signal lamp bulb with new.	<b>Parts List</b>	<b>Qty</b>
	3157 Tail Light Bulbs	1.00
Hours 0.50	Labor: 30.00	Parts: 0.61
:		Total: 30.61

**Workorder:** 1200175      **Meter:** 25127      **In Date:** 01/05/2012      **Closed:** 01/19/2012  
**Problem:** Pm service and check tires.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service auxiliary fuel tank and install new fuel filter.	Shop Supplies	1.00
- Install four new tires.nitrogen fill and balance all four.	24006 Fuel Filter Diesel And Gas	1.00
- Perform wheel alignment complete.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	D3tz2457b Brake Pedal Pad	1.00
	Tpms8 Strap Tps 17" (motorcraft)	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
Hours 8.25	Labor: 495.00	Parts: 841.58
:		Total: 1,336.58

**Workorder:** 1206342      **Meter:** 29018      **In Date:** 07/06/2012      **Closed:** 07/19/2012  
**Problem:** Pm service.

- Perform pm service.	<b>Parts List</b>	<b>Qty</b>
- Install new front brake pads and resurface both front brake rotors.adjust and repack wheel bearings.service calipers and perform brake fluid flush.automated bleed hydraulic system with scan tool.	Shop Supplies	1.00
- Inspect and replace broken left tail lamp assembly with new.	24006 Fuel Filter Diesel And Gas	1.00
- Inspect and service auxiliary fuel tank and replace fuel filter.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all four tires.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	Front Brake Oad Set	1.00
	5w20 Engine Oil	7.00
	2232 Brake Fluid Quart	1.00
	31-20 Wiper Blades 20" Blade	2.00
	Left Tail Light Assembly	1.00
Hours 10.25	Labor: 615.00	Parts: 171.86
:		Total: 786.86

**Workorder:** 1207032      **Meter:** 29018      **In Date:** 07/19/2012      **Closed:** 07/30/2012  
**Problem:** damage to hood, lft side of bed & rear bumper

- damage to hood, lft side of bed & rear bumper	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1208097	<b>Meter:</b> 29047	<b>In Date:</b> 08/27/2012	<b>Closed:</b> 08/31/2012
<b>Problem:</b> Check engine light on and off and runs rough.			
- Diagnose check engine lightperform power balance test.replace defective #2 coil.clear codes and test drive.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Black Boot Coil	1.00
Hours 3.00	Labor: 180.00	Parts: 67.72	Total: 247.72
:			
<b>Workorder:</b> 1211172	<b>Meter:</b> 29793	<b>In Date:</b> 11/16/2012	<b>Closed:</b> 11/16/2012
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1301289	<b>Meter:</b> 32310	<b>In Date:</b> 02/05/2013	<b>Closed:</b> 02/21/2013
<b>Problem:</b> P.M. service and check brake lights.			
- P.m. Service.		<b>Parts List</b>	<b>Qty</b>
- Inspect and service aux. fuel system.		5w20 Engine Oil	7.00
- Replace right brake light bulb.		1372 Oil Filter	1.00
- Install new fire extinguisher with bracket.		31-20 Wiper Blades 20	2.00
- Rotate and balance all tires.		Fire Extinguisher	1.00
- Shop Supplies		Fuel Filter	1.00
		Miniature Bulb	1.00
		Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 135.49	Total: 480.49
:			
<b>Workorder:</b> 1301545	<b>Meter:</b> 32038	<b>In Date:</b> 02/13/2013	<b>Closed:</b> 02/13/2013
<b>Problem:</b> 1 - Wash ticket(s) issued			
- 1 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1305037	<b>Meter:</b> 35132	<b>In Date:</b> 05/21/2013	<b>Closed:</b> 05/29/2013
<b>Problem:</b> Towed in for left rear tire flat.			
- Repair and balance left rear tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1305182	<b>Meter:</b> 35090	<b>In Date:</b> 05/21/2013	<b>Closed:</b> 05/28/2013
<b>Problem:</b> LR flat			
- Tow From: croc To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1307469	<b>Meter:</b> 36482	<b>In Date:</b> 07/25/2013	<b>Closed:</b> 07/25/2013
<b>Problem:</b> 1 - Key(s) issued			
- 1 - Key(s) issued			
		<b>Parts List</b>	<b>Qty</b>
		Duplicate Vehicle Keys	1.00
Hours 0.20	Labor: 12.00	Parts: 3.00	Total: 15.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1400028      **Meter:** 40540      **In Date:** 01/02/2014      **Closed:** 01/21/2014  
**Problem:** P.M. service and tailgate protector missing and remove locking hitch pin.

<ul style="list-style-type: none"> <li>- Perform pm service.</li> <li>- Fabricate and replace failed hitch pintle pin and chain with new.install new tail gate cap.inspect and replace both fail windshield washer nozzles with new.</li> <li>- Diagnose for blower speed inop.test and replace failed blower resistor with new.</li> <li>- Inspect and service auxiliary fuel tank.</li> <li>- Rotate and balance all four tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Napagold Fuel Filter</li> <li>Napagold Air Filter</li> <li>Wiper Blade</li> <li>Washer Fluid Concentr</li> <li>Used Fire X Refurbished</li> <li>Pintle Pin W/chain</li> <li>Blower Resistor</li> <li>Napagold Fuel Filter</li> <li>Pin W/clip 5/8 For Hitch</li> <li>Moulding</li> <li>Washer Nozzle</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> </ul>	
Hours 7.25	Labor: 435.00	Parts: 208.54	Total: 643.54

**Workorder:** 1406821      **Meter:** 43255      **In Date:** 07/10/2014      **Closed:** 07/25/2014  
**Problem:** P.m. service.

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Inspect and service auxillary fuel system.</li> <li>- Test battery and charging system.replace bad battery.</li> <li>- resurface rear brake rotors,replace rear pads.service and lube rear calipers.flush and bleed system. and test drive.</li> <li>- Rotate and balance all tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Used Fire X Refurbished</li> <li>Wiper Blade</li> <li>Napagold Fuel Filter</li> <li>Battery</li> <li>Rear Pads</li> <li>Brake Cleaner</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 9.25	Labor: 555.00	Parts: 251.48	Total: 806.48

**Workorder:** 1407768      **Meter:** 43542      **In Date:** 08/06/2014      **Closed:** 08/22/2014  
**Problem:** Install ladder rack.

<ul style="list-style-type: none"> <li>- Remove tool boxes and transfer fuel tank to acess fabrication and install ladder rack.reinstall fuel tank and tool boxes. after installing rack.</li> <li>- Test and replace open left headlamp seal beam assembly.</li> <li>- Computer diagnose For Abs warning on.codes C1145 and C1234 Replace right front Abs wheel speed sensor.clear codes and test drive.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Halogen Lamp</li> <li>Sensor Asy</li> <li>Ladder Rack</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 11.50	Labor: 690.00	Parts: 698.92	Total: 1,388.92



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1500808      **Meter:** 45040      **In Date:** 01/23/2015      **Closed:** 02/09/2015  
**Problem:** Pm service.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Wiper Blade	2.00
	Brake Cleaner	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 47.78
:		Total: 332.78

**Workorder:** 1502980      **Meter:** 46048      **In Date:** 03/23/2015      **Closed:** 03/31/2015  
**Problem:** Multiple nails in both front tires.

- Replace and balance two tires.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
	Lt245/75r17 Tire	2.00
Hours 1.00	Labor: 60.00	Parts: 301.97
:		Total: 361.97

**Workorder:** 1511407      **Meter:** 49179      **In Date:** 11/06/2015      **Closed:** 11/23/2015  
**Problem:** Pm service.

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Replace both worn front suspension bump stops.	Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.	Wiper Blade	2.00
- Replace all six worn and broken body bushings.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	179636492 Lt245-75r17	2.00
	Body Mount Kit	2.00
	Body Mount Kit	4.00
	bumper	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 12.25	Labor: 735.00	Parts: 1,082.04
:		Total: 1,817.04

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1512210      **Meter:** 49261      **In Date:** 12/03/2015      **Closed:** 12/16/2015  
**Problem:** Check engine light on.

<ul style="list-style-type: none"> <li>- Diagnose for check engine light on.code P0300 .replace eight spark plugs and two ignition coils.fabricate and remove five broken spark plugs.</li> <li>- Perform fuel injection service.and intake decarb service.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Spark Plug 8.00</li> <li>Coil Assembly 2.00</li> <li>Injector Cleaner 1.00</li> <li>Intake Cleaner Kit 1.00</li> <li>5068 Penetrating Oil 1.00</li> <li>Throttle Body Cleaner 1.00</li> <li>Shop Supplies 1.00</li> </ul>	<p>Hours 9.50 :</p>	<p>Labor: 570.00      Parts: 362.93      Total: 932.93</p>
---	---	-------------------------	--

**Workorder:** 1600876      **Meter:** 49926      **In Date:** 01/26/2016      **Closed:** 02/04/2016  
**Problem:** Check engine light on.ABS warning light on and off intermittently.

<ul style="list-style-type: none"> <li>- Computer diagnose for Abs light on.code C1155 and C1235.replace defective left front wheel speed sensor.clear codes and road test.</li> <li>- Transport vehicle to and from dealer for replacing catalytic converters.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Sensor Asy 1.00</li> <li>Shop Supplies 1.00</li> </ul>	<p>Hours 4.50 :</p>	<p>Labor: 270.00      Parts: 78.55      Total: 348.55</p>
---	--	-------------------------	---

**Workorder:** 1605638      **Meter:** 51443      **In Date:** 06/01/2016      **Closed:** 06/09/2016  
**Problem:** P.M. service.

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Inspect and service aux fuel system.</li> <li>- Service transmission.flush and refill system.</li> <li>- Pressure test and inspect cooling system.flush and refill system.</li> <li>- Rotate and balance all tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil 7.00</li> <li>Napagold Oil Filter 1.00</li> <li>Napagold Fuel Filter 1.00</li> <li>Napagold Air Filter 1.00</li> <li>20" Wiper Blade 2.00</li> <li>Stg Wheel Cov - Ford 1.00</li> <li>Napagold Fuel Filter 1.00</li> <li>Atp Filter 1.00</li> <li>Syn-atf Trans Fluid S 20.00</li> <li>Peak Global 2.00</li> <li>Shop Supplies 1.00</li> </ul>	<p>Hours 9.25 :</p>	<p>Labor: 555.00      Parts: 224.17      Total: 779.17</p>
---	--	-------------------------	--

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1613055      **Meter:** 54423      **In Date:** 12/27/2016      **Closed:** 01/20/2017  
**Problem:** P.M. Service.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	7.00
- Replace worn out rear bump stops.	Napagold Oil Filter	1.00
- Replace toolbox lid struts.	Non-chlor Brake Clnr	1.00
- Replace left headlamp.	Used Fire X Refurbished	1.00
- Inspect and service aux. fuel system.	20" Wiper Blade	2.00
- Rotate and balance tires.	Battery	1.00
- Shop Supplies	Real Suspension Bumpstops	2.00
	Halogen Lamp	1.00
	Napagold Fuel Filter	1.00
	Support	2.00
	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 310.54
:		Total: 745.54

**Workorder:** 1705827      **Meter:** 56690      **In Date:** 06/12/2017      **Closed:** 06/15/2017  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service Aps fuel system.	5w20 Engine Oil	7.00
- Service rear differential.	Napagold Oil Filter	1.00
- Replace two front tires.balance and rotate all four.	Napagold Fuel Filter	1.00
- Check and replace defective left front door check.	20" Wiper Blade	2.00
- Complete front end alignment and road test.	Used Fire X Refurbished	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	75w140 Ford Axle Lube	2.00
	Friction Modifier	2.00
	Clr Rtv Silcn Sealant	1.00
	Non-chlor Brake Clnr	1.00
	179636492 Lt245-75r17	2.00
	Tr416 Valve Stem	2.00
	left door check asy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.25	Labor: 615.00	Parts: 708.00
:		Total: 1,323.00

**Workorder:** 1708770      **Meter:** 57394      **In Date:** 09/06/2017      **Closed:** 09/07/2017  
**Problem:** Left headlight inop.

- Test and replace left headllamp assembly.retest.	<b>Parts List</b>	<b>Qty</b>
	Halogen Lamp	1.00
Hours 0.50	Labor: 30.00	Parts: 13.01
:		Total: 43.01

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1800525      **Meter:** 58746      **In Date:** 01/17/2018      **Closed:** 01/25/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	20" Wiper Blade	2.00
	Napagold Fuel Filter	1.00
	2-pk 3in Spot Mirror	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 39.95
:		Total: 324.95

**Workorder:** 1807175      **Meter:** 59969      **In Date:** 07/16/2018      **Closed:** 07/19/2018  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose rattle in rear . Replace both rear shocks .retest .	Napagold Oil Filter	1.00
Replace upper and lower ball joint on both side in front.	5w20 Engine Oil	7.00
- R&r defective cracked belt.	Napagold Air Filter	1.00
- Inspect and service auxiliary fuel tank.	Used Fire X Refurbished	1.00
- Perform complete front end alignment and road test.	20" Wiper Blade	2.00
- Rotate and balance all four tires. Nitrogen filled tires.	Gas Grande Shock	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Ball Joint	2.00
	Ball Joint	2.00
	Belt	1.00
	Shop Supplies	1.00
Hours 13.55	Labor: 813.00	Parts: 435.79
:		Total: 1,248.79

**Workorder:** 1809707      **Meter:** 61419      **In Date:** 09/20/2018      **Closed:** 09/24/2018  
**Problem:** Rear passenger light out.

- Test and replace right brake light bulb and socket .	<b>Parts List</b>	<b>Qty</b>
	Stp Trn TI Lgt Socket	1.00
	Boxed Miniatures	1.00
Hours 0.50	Labor: 30.00	Parts: 10.64
:		Total: 40.64

**Workorder:** 1810455      **Meter:** 61698      **In Date:** 10/11/2018      **Closed:** 10/17/2018  
**Problem:** Rattle in front over bumps .

- Diagnose rattle . Replace both defective front shocks . Test drive.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Gas Grande Fleet Shoc	2.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 118.77
:		Total: 185.77

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1900518      **Meter:** 62521      **In Date:** 01/14/2019      **Closed:** 01/22/2019  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service auxiliary fuel tank .	Napagold Oil Filter	1.00
- Rotate and high speed balance all four tires . Nitrofill alll.	5w20 Engine Oil	7.00
- Shop Supplies	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 318.25	Parts: 55.92
:		Total: 374.17

**Workorder:** 1901996      **Meter:** 62737      **In Date:** 02/21/2019      **Closed:** 04/17/2019  
**Problem:** Noise from rear end and burning smell.

- R&r rear wheels and inspect brakes and suspension for loose parts.replace defective shock absorber.check rear differential fluid.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Gas Grande Shock	1.00
	Shop Supplies	1.00
Hours 2.50	Labor: 167.50	Parts: 58.07
:		Total: 225.57

**Workorder:** 1907227      **Meter:** 63697      **In Date:** 07/15/2019      **Closed:** 07/18/2019  
**Problem:** P.M. service .

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Inspect and service aux fuel tank .	Napagold Oil Filter	1.00
- Test and replace both tool box struts and cross box .	5w20 Engine Oil	7.00
- Rotate and high speed balance all four tires . Nitrofill all.	22" Wiper Blade	2.00
- Shop Supplies	Wd40 Spr	1.00
	Ford Triton Pvc Swc	1.00
	Napagold Fuel Filter	1.00
	Support	2.00
	Shop Supplies	1.00
Hours 5.25	Labor: 351.75	Parts: 111.56
:		Total: 463.31

**Workorder:** 1911809      **Meter:** 66342      **In Date:** 11/14/2019      **Closed:** 11/14/2019  
**Problem:** Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00