

**Palm Beach County Fleet Management
Asset Maintenance History**

10183713 2011 FORD F350 Utility Body, 1 Ton, W/Medium Duty Crane

Workorder: 1108821 **Meter:** 343 **In Date:** 08/19/2011 **Closed:** 08/25/2011
Problem: fill def tank

- Parts only	Parts List	Qty
	Def Diesel Exh Fluid (mtc Pm27jug 2.5, Pm27d 55)	7.00
Hours 0.00	Labor: 0.00	Parts: 9.90
:		Total: 9.90

Workorder: 1108822 **Meter:** 343 **In Date:** 08/19/2011 **Closed:** 08/19/2011
Problem: Pre Delivery Inspection

- Pre Delivery Inspection	Hours 4.00	Labor: 240.00	Parts: 0.00	Total: 240.00
	:			

Workorder: 1113319 **Meter:** 4292 **In Date:** 12/20/2011 **Closed:** 12/27/2011
Problem: Right rear outer tire flat.

- Install new tire to the right rear outer wheel.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Lt245/75r17 Tire Mounted On Rim	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 152.50
:		Total: 212.50

Workorder: 1201149 **Meter:** 5519 **In Date:** 02/02/2012 **Closed:** 02/08/2012
Problem: Nail in front driver's side tire

- Remove nail from left front tire & check for leak. Tire is not leaking. Check & adjust air pressure.	Hours 0.25	Labor: 15.00	Parts: 0.00	Total: 15.00
	:			

Workorder: 1201152 **Meter:** 5546 **In Date:** 02/02/2012 **Closed:** 02/24/2012
Problem: Pm service.Wiper blades and left front tire.

- P.m. Service.	Parts List	Qty
- Inspect and service crane.	Shop Supplies	1.00
- Repair left front tire,rotate and balance all six.	Ph10890 Oil Filter Mtc FI2051 Wix 57151	1.00
- Complete wheel alignment.test drive.	3615 Fuel Filter Frm K10826 Wix 33615	1.00
- Shop Supplies	1259 Hydr Filter Lbf Frm P1653a Wix 51259	2.00
	Aw68 Hydro Fluid Hydraulic Oil 68	5.00
	15/40 Oil	13.00
	Def Diesel Exh Fluid (mtc Pm27jug 2.5, Pm27d 55)	25.00
	7090blk Frt Floor Mats (rubber Queen)	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	05046 Battery Protector (crc)	1.00
Hours 10.00	Labor: 600.00	Parts: 210.09
:		Total: 810.09

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1204435 **Meter:** 9007 **In Date:** 05/10/2012 **Closed:** 05/16/2012
Problem: Check engine light on.

- Transport vehicle to dealer for check engine light. P249c. (replace Egr temp sensor and particulate filter)	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1208080 **Meter:** 12243 **In Date:** 08/24/2012 **Closed:** 09/17/2012
Problem: P.M. service and recall # 12834

- P.m Service.	Parts List	Qty
- Replace four tires,rotate and balance all six.	Shop Supplies	1.00
- Inspect and service crane.	Ph10890 Oil Filter Mtc FI2051 Wix 57151	1.00
- Transport vehicle to dealer for recall #12b34(pcm recal.)	3615 Fuel Filter Frm K10826 Wix 33615	1.00
- Shop Supplies	9902 Air Filter Frm Ca10888 Wix 49902	1.00
	1259 Hydr Filter Lbf Frm P1653a Wix 51259	2.00
	Aw68 Hydro Fluid Hydraulic Oil 68	3.00
	Def Diesel Exh Fluid (mtc Pm27jug 2.5, Pm27d 55)	14.00
	15/40 Oil	13.00
	Used Firex Refurbed Fire Extingshers	1.00
	Tire Disposal Fee	4.00
	Tire Lt245/75r17	4.00
Hours 10.00	Labor: 600.00	Parts: 918.67
:		Total: 1,518.67

Workorder: 1210931 **Meter:** 14306 **In Date:** 11/08/2012 **Closed:** 11/28/2012
Problem: Air hose between compressor and tank failed.

- R&r failed air line between compressor and air tank to acess,fabricate and repair same.test and replace failed compressor cooling fan assembly with new.	Parts List	Qty
- Shop Supplies	Fan	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 4.00	Labor: 240.00	Parts: 277.34
:		Total: 517.34

Workorder: 1302089 **Meter:** 16714 **In Date:** 02/28/2013 **Closed:** 02/28/2013
Problem: Tire

- Tire Service front of Americal Oil Change - Tire			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1302090 **Meter:** 16714 **In Date:** 02/28/2013 **Closed:** 02/28/2013
Problem: Service

- Tire Service frt of American Oil change - Service			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1303284 **Meter:** 18404 **In Date:** 04/04/2013 **Closed:** 04/11/2013
Problem: P.M. service .

- Perform pm service.	Parts List	Qty
- Inspect and service hydraulic crane.	15-40 Oil	14.00
- Inspect and replace failed hitch pintle pin with new.	Napagold Oil Filter	1.00
- Perform wheel alignment complete.fabricete and install new	31-22 Wiper Blades 22	2.00
cams to both upper ball joints to change caster and camber	Napagold Fuel Filter	1.00
angles.	Def Diesel Exh Fluid	22.00
- Install two new tires to front wheels.nitrogen fill and balance	Napa Trans Filter	1.00
all six.	Aw68 Hydro Fluid Hydr	2.00
- Shop Supplies	Brake Cleaner	1.00
	18410 Pintle Pin	1.00
	Caster-camber Bushing	2.00
	Shop Supplies	1.00
	Lt245/75r17 Tire	2.00
Hours 10.55	Labor: 633.00	Parts: 524.17
:		Total: 1,157.17

Workorder: 1305125 **Meter:** 20335 **In Date:** 05/23/2013 **Closed:** 06/13/2013
Problem: Check engine light on.Wrench light on.Constantly goes into exhaust regen.

- Transport vehicle to dealer for Dpf sensor warranty.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1309982 **Meter:** 24715 **In Date:** 10/02/2013 **Closed:** 10/22/2013
Problem: Pm service

- P.m. Service.	Parts List	Qty
- Test batteries and charging system.recharge and retest	15-40 Oil	14.00
batteries,both batteries failed load test.replace both batteries.	Napagold Oil Filter	1.00
- Inspect and sertvice crane.	Napagold Fuel Filter	1.00
- Repl;ace four tires,rotate and balance all six.	Wiper Blade	2.00
- Resurface rear brake rotors,replace rear brakes	Used Fire X Refurbished	1.00
pads.service and lube rear calipers.flush and bleed system	Battery	2.00
and test.	Napa Hydraulic Filtr	2.00
- Replace broken vise.	179636492 Lt245-75r17	4.00
- Shop Supplies	Tr416 Valve Stem	4.00
	Brake Cleaner	1.00
	66997 Combo Vise Rigid	1.00
	Def Quart	22.00
	Battery	2.00
	Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 16.00	Labor: 960.00	Parts: 2,433.21
:		Total: 3,393.21

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1310857 **Meter:** 25302 **In Date:** 10/30/2013 **Closed:** 10/31/2013
Problem: Both LED brake lamps failed.

- Test and replace both failed Led brake lamp assemblies with new.	Parts List	Qty
	Led Sup Mdl 44 42 Dio	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 122.51
:		Total: 182.51

Workorder: 1401251 **Meter:** 29081 **In Date:** 02/06/2014 **Closed:** 03/06/2014
Problem: Check engine light on and P.m. service.

- P.m. Service.	Parts List	Qty
- Transport vehicle to dealer for check engine light(map Sensor)	15-40 Oil	13.00
- Inspect and service crane.	Napagold Oil Filter	1.00
- Rotate and balance all six tires.	Air Filter (gold), Air Panel	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Wiper Blade	2.00
	Napa Hydraulic Filtr	2.00
	Cx05-0145 Hook Latch	1.00
	Def Quart	16.00
	Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 159.23
:		Total: 669.23

Workorder: 1405353 **Meter:** 31535 **In Date:** 06/02/2014 **Closed:** 06/18/2014
Problem: Check engine light on.

- Transport vehicle to and from dealer For check engine lifght on to reprogram Pcm with latest up date calibration.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1406390 **Meter:** 32196 **In Date:** 06/30/2014 **Closed:** 07/14/2014
Problem: Check engine light on .

- Transport vehicle to and from dealer for check engine light on P21b0 replacing failed reductant tank assembly with new under factory warranty.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1407150 **Meter:** 32971 **In Date:** 07/21/2014 **Closed:** 07/30/2014
Problem: Top off hydraulic fluid.

- Check and top-off hydraulic fluid.	Parts List	Qty
- Shop Supplies	Aw68 Hydro Fluid Hydr	20.00
	Shop Supplies	1.00
Hours 0.25	Labor: 15.00	Parts: 49.10
:		Total: 64.10

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407770 **Meter:** 33343 **In Date:** 08/06/2014 **Closed:** 08/19/2014
Problem: Install ladder rack.

- Install ladder rack.	Parts List	Qty
- Pm service.	15-40 Oil	13.00
- Service hoisting device.	Napagold Oil Filter	1.00
- Install two tires.rotate and balance all six.	Napagold Fuel Filter	1.00
- Complete front end alignment and roadtest.	Wiper Blade	2.00
- Shop Supplies	Napa Hydraulic Filtr	2.00
	179636492 Lt245-75r17	2.00
	Def Quart	10.00
	Ladder Rack	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 13.75	Labor: 825.00	Parts: 1,256.97
:		Total: 2,081.97

Workorder: 1408894 **Meter:** 34316 **In Date:** 09/03/2014 **Closed:** 09/15/2014
Problem: Check over crane problem in hoist up or down.

- Diagnose crane hoist inop.test electrical sstem.repair loose connection in pendant for hoist power.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1501174 **Meter:** 38831 **In Date:** 02/02/2015 **Closed:** 02/19/2015
Problem: P.m. service.

- Pm service.	Parts List	Qty
- Inspect and service crane.	Used Fire X Refurbished	1.00
- Rotate and balance all six tires.	Bulb	1.00
- Shop Supplies	Napa Hydraulic Filtr	2.00
	Macs Chain Cable Lube	1.00
	Def Quart	24.00
	15-40 Oil	13.00
	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
	Air Filter (gold), Air Panel	1.00
	Wiper Blade	2.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 189.41
:		Total: 579.41

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1507149 **Meter:** 44502 **In Date:** 07/17/2015 **Closed:** 08/04/2015
Problem: Pm service.Wiper blades.Check brakes,rear lights and tires.

	Parts List	Qty
- P.m. Service.		
- Inspect and service crane.	Napagold Oil Filter	1.00
- Replace flour tires,rotate and balance all six.	Fuel Filter Ford Only	1.00
- Replace right tail lamp.	Wiper Blade	2.00
- Resurface front and rear brake rotors,replace brake pads.service and lube calipers.flush and bleed system and test drive.	Coolant Ford Gold	3.00
	Used Fire X Refurbished	1.00
- Shop Supplies	Def Quart	22.00
	15-40 Oil	28.00
	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
	Air Filter (gold), Air Panel	1.00
	Wiper Blade	2.00
	Napa Hydraulic Filtr	3.00
	179636492 Lt245-75r17	6.00
	Led Sup Mdl 44 42 Dio	1.00
	Brake Pad	1.00
	Brake Pads	1.00
	lube	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 18.50	Labor: 1,110.0	Parts: 2,181.16
:	0	Total: 3,291.16

Workorder: 1512583 **Meter:** 50334 **In Date:** 12/14/2015 **Closed:** 01/19/2016
Problem: Pm service.

	Parts List	Qty
- Pm service.		
- Replace left rear turnsignal lamp bulb.	15-40 Oil	13.00
- Replace two tires.rotate and balance all six.	Napagold Oil Filter	1.00
- Inspect and service crane.replace defective emergency stop switch on pendant..	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Led Sup Mdl 44 42 Dio	1.00
	179636492 Lt245-75r17	2.00
	Napa Hydraulic Filtr	2.00
	Emergency Switch	1.00
	Def Quart	9.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 9.00	Labor: 540.00	Parts: 845.75
:		Total: 1,385.75

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603783 **Meter:** 53544 **In Date:** 04/11/2016 **Closed:** 04/15/2016
Problem: Has to jump start in A/M.

- Recharge both batteries.test battery and charging system.replace both batteries.	Parts List	Qty
	Battery	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 238.82
:		Total: 358.82

Workorder: 1605782 **Meter:** 55993 **In Date:** 06/06/2016 **Closed:** 07/11/2016
Problem: P.M. service and vibration in front tires and recall 14E03

- P.m. Service.	Parts List	Qty
- Service transmission.flush and refill system.	15-40 Oil	13.00
- Inspect and service crane and outriggers.	Napagold Oil Filter	1.00
- Replace and rewire back up alarm.	Napagold Fuel Filter	1.00
- Replace leaking front shocks.	Air Filter (gold), Air Panel	1.00
- Replace and adjust broken right rear utility door hinge.	22" Wiper Blade	2.00
- Rotate and balance all six tires.	Wd40 16oz	1.00
- Complete wheel alignment.test drive.	Trams Filter	1.00
- Transport vehicle to dealer for recall #14e03.	Syn-atf Trans Fluid S	20.00
- Replace broken intake to intercooler hose.	Napa Hydraulic Filtr	2.00
- Shop Supplies	Alarm	1.00
	Gas Grande Fleet Shoc	2.00
	Def Quart	25.00
	Pintle Mount	1.00
	Slip Plate Spray 12oz	1.00
	Hinge	1.00
	Air Tube	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 19.50	Labor: 1,170.0	Parts: 804.42
:	0	Total: 1,974.42

Workorder: 1606756 **Meter:** 55993 **In Date:** 06/29/2016 **Closed:** 07/05/2016
Problem: Wont drive pass 30mph

- Tow From: 8100 Forest Hill Blvd To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1608458 **Meter:** 58739 **In Date:** 08/16/2016 **Closed:** 08/30/2016
Problem: DEF light on.Outriggers too low.

- Diagnose Def light.refill system.clear code.	Parts List	Qty
- Replace missing pad on right out rigger.raise both out rigger cylinders higher per request.	Def Quart	10.00
	Sand Pad	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 146.15
:		Total: 326.15

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610883 **Meter:** 60992 **In Date:** 10/21/2016 **Closed:** 10/31/2016
Problem: P.M. service and check engine noise and RPMs.higher than normal.

- P.m. Service.	Parts List	Qty
- Inspect and service crane.	Oil Filter Motorcraft	1.00
- Diagnose noise coming from engine compartment.replace noisy alternator and belt.	15-40 Oil	13.00
	22" Wiper Blade	2.00
- Replace four tires,rotate and balance all six.	Used Fire X Refurbished	1.00
- Replace both brake lamps.	Fuel Filter Kit	1.00
- R&r rear driveshaft and replace 'u' joints.	Napa Hydraulic Filtr	2.00
- Replace cooling fan clutch.	Altenator	1.00
- Service and clean induction system.flush injectors.	Drive Belt	1.00
- Shop Supplies	179636492 Lt245-75r17	4.00
	4 Led S T T Lamp	2.00
	clutch assy	1.00
	Aw68 Hydro Fluid Hydr	4.00
	U Joint	2.00
	Def Bulk Qts	12.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 19.50	Labor: 1,170.00	Parts: 2,074.89
:	0	Total: 3,244.89

Workorder: 1612460 **Meter:** 62596 **In Date:** 12/05/2016 **Closed:** 12/27/2016
Problem: Right rear outter tire going flat.

- Repair and balance right rear tire.	Parts List	Qty
- Replace serpentine belt.clean pulleys.	Drive Belt	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 126.25
:		Total: 366.25

Workorder: 1612551 **Meter:** 62456 **In Date:** 12/06/2016 **Closed:** 12/07/2016
Problem: repair/flat tire

- Tow From: 8100 forest hill blvd To: lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1703542 **Meter:** 64901 **In Date:** 04/06/2017 **Closed:** 04/10/2017
Problem: Service Call

- Tire Service 8100 Forest Hill Blvd - Service Call			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1703845 **Meter:** 65305 **In Date:** 04/17/2017 **Closed:** 04/28/2017
Problem: air compressor not working properly

- Ck Compressor inop at times 175psi	Replace pressure switch	Parts List	Qty
		Napagold Air Filter	1.00
- Shop Supplies		175psi Pressure Switch	1.00
		Shop Supplies	1.00
		Freight Charge	1.00
Hours 3.00	Labor: 180.00	Parts: 56.98	Total: 236.98
:			

Workorder: 1704257 **Meter:** 65305 **In Date:** 04/27/2017 **Closed:** 05/11/2017
Problem: P.M. Service

- P.m. service.		Parts List	Qty
- Replace two tires and balance all six.nitrofill tires.		Napagold Oil Filter	1.00
- Completed rear differential service.		15-40 Oil	13.00
- Tighten front left cabinet door shock mount.replace missing middle right side fold down door chain.		Napagold Fuel Filter	1.00
		Used Fire X Refurbished	1.00
- Reloomed trailer lights harness over rear cross member.		22" Wiper Blade	2.00
- Replace passenger side upper and lower balljoints		Washer Fluid Concentr	1.00
- Install adjusting collar.completed four wheel alignment.		Air Filter (gold), Air Panel	1.00
- Inspected and service crane.		Slip Plate Spray 12oz	1.00
- Shop Supplies		179636492 Lt245-75r17	2.00
		Ptex Ultra Grey 3oz	1.00
		Non-chlor Brake Clnr	1.00
		75w140 Ford Axle Lube	4.00
		Ball Joint	1.00
		Ball Joint	1.00
		Napa Hydraulic Filtr	2.00
		1qt Syngear Oil 75-90	4.00
		Door Chain	1.00
		Aw68 Hydro Fluid Hydr	2.00
		Def Bulk Qts	18.00
		Fab Loom-split Poly	1.00
		Caster-camber Bushing	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 15.60	Labor: 936.00	Parts: 1,077.14	Total: 2,013.14
:			

Workorder: 1705628 **Meter:** 65450 **In Date:** 04/05/2017 **Closed:** 06/06/2017
Problem: Flat Repair

- Tire Service 8100 Forest Hill Blvd - Flat Repair			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706806 **Meter:** 65752 **In Date:** 07/12/2017 **Closed:** 07/17/2017
Problem: Wipers stay on.

- Computer diagnose wipers.no codes .monitor pid data.r&r	Parts List	Qty
defective wiper switch .retest.	Switch Asy	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.80	Labor: 108.00	Parts: 43.33
:		Total: 151.33

Workorder: 1709345 **Meter:** 67441 **In Date:** 09/26/2017 **Closed:** 09/27/2017
Problem: Check exhaust fluid.

- Fill Def with 2.5 gals.retest.	Parts List	Qty
- Replace interior dome lamp bulb.	Blue Df	1.00
- Shop Supplies	Map Lamp	1.00
	Shop Supplies	1.00
Hours 0.80	Labor: 48.00	Parts: 17.81
:		Total: 65.81

Workorder: 1711301 **Meter:** 68091 **In Date:** 11/16/2017 **Closed:** 11/29/2017
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace faulty roof marker lamp bulb with new.	15-40 Oil	13.00
- Inspect and service hydraulic crane.	Napagold Oil Filter	1.00
- Repair right rear outer flat tire .rotate and balance all six tires.	Napagold Fuel Filter	1.00
	22" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Bulb	1.00
	Napa Hydraulic Filtr	2.00
	Blue Df	1.00
	Shop Supplies	1.00
Hours 7.80	Labor: 468.00	Parts: 124.82
:		Total: 592.82

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804536 **Meter:** 71297 **In Date:** 05/01/2018 **Closed:** 07/12/2018
Problem: P.M. service , check oil leak and trans leak, left front assist handle broken.

<ul style="list-style-type: none"> - P.m. service. - Check and replace left rear clearance light bulb and right tail light. - Test and replace defective trailer plug connector and fabricate wiring as needed. - Inspect and service crane . Replace leaking Pto solenoid . - Check for oil leak .remove transmission and upper oil pan to replace rear engine cover and rear main seal and lower pan . Drain and flush cooling system . Refill all fluids .clean under carriage .test drive . inspect for leaks. - Fabricate and install two grab handles in rear of utility bed . install step in rear of truck. Replace left a-pillar trim panel. - Balance and rotate all six tires . Nitrofill. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Oil O Pan Asy</td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td align="right">2.00</td></tr> <tr><td>Gasket</td><td align="right">1.00</td></tr> <tr><td>15-40 Oil</td><td align="right">13.00</td></tr> <tr><td>Napagold Oil Filter</td><td align="right">1.00</td></tr> <tr><td>Napagold Fuel Filter</td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td align="right">1.00</td></tr> <tr><td>Front Inner Apillar W/handle</td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td align="right">2.00</td></tr> <tr><td>pto solenoid</td><td align="right">1.00</td></tr> <tr><td>Boxed Miniatures</td><td align="right">1.00</td></tr> <tr><td>Freight</td><td align="right">1.00</td></tr> <tr><td>M C Lamp</td><td align="right">1.00</td></tr> <tr><td>trailer plug</td><td align="right">1.00</td></tr> <tr><td>Napa Hydraulic Filtr</td><td align="right">2.00</td></tr> <tr><td>Ptex Ultra Grey 3oz</td><td align="right">1.00</td></tr> <tr><td>Grab Handles</td><td align="right">2.00</td></tr> <tr><td>Blue Df</td><td align="right">1.00</td></tr> <tr><td>Hitch Pin Lock</td><td align="right">1.00</td></tr> <tr><td>Engine Oil Stop Leak</td><td align="right">3.00</td></tr> <tr><td>Cover Ring</td><td align="right">1.00</td></tr> <tr><td>Seal Assembly</td><td align="right">2.00</td></tr> <tr><td>Shield</td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td align="right">1.00</td></tr> <tr><td>Hose Clamp</td><td align="right">1.00</td></tr> <tr><td>Step</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table>	Parts List	Qty	Oil O Pan Asy	1.00	Gasket	1.00	Gasket	2.00	Gasket	1.00	15-40 Oil	13.00	Napagold Oil Filter	1.00	Napagold Fuel Filter	1.00	Gasket	1.00	Used Fire X Refurbished	1.00	Front Inner Apillar W/handle	1.00	22" Wiper Blade	2.00	pto solenoid	1.00	Boxed Miniatures	1.00	Freight	1.00	M C Lamp	1.00	trailer plug	1.00	Napa Hydraulic Filtr	2.00	Ptex Ultra Grey 3oz	1.00	Grab Handles	2.00	Blue Df	1.00	Hitch Pin Lock	1.00	Engine Oil Stop Leak	3.00	Cover Ring	1.00	Seal Assembly	2.00	Shield	1.00	Gasket	1.00	Gasket	1.00	Hose Clamp	1.00	Step	1.00	Shop Supplies	1.00
Parts List	Qty																																																														
Oil O Pan Asy	1.00																																																														
Gasket	1.00																																																														
Gasket	2.00																																																														
Gasket	1.00																																																														
15-40 Oil	13.00																																																														
Napagold Oil Filter	1.00																																																														
Napagold Fuel Filter	1.00																																																														
Gasket	1.00																																																														
Used Fire X Refurbished	1.00																																																														
Front Inner Apillar W/handle	1.00																																																														
22" Wiper Blade	2.00																																																														
pto solenoid	1.00																																																														
Boxed Miniatures	1.00																																																														
Freight	1.00																																																														
M C Lamp	1.00																																																														
trailer plug	1.00																																																														
Napa Hydraulic Filtr	2.00																																																														
Ptex Ultra Grey 3oz	1.00																																																														
Grab Handles	2.00																																																														
Blue Df	1.00																																																														
Hitch Pin Lock	1.00																																																														
Engine Oil Stop Leak	3.00																																																														
Cover Ring	1.00																																																														
Seal Assembly	2.00																																																														
Shield	1.00																																																														
Gasket	1.00																																																														
Gasket	1.00																																																														
Hose Clamp	1.00																																																														
Step	1.00																																																														
Shop Supplies	1.00																																																														
Hours 25.80 :	Labor: 1,548.0 0	Parts: 1,360.55	Total: 2,908.55																																																												

Workorder: 1807427 **Meter:** 71587 **In Date:** 07/20/2018 **Closed:** 07/25/2018
Problem: Hard cold start.

<ul style="list-style-type: none"> - Check batteries and charging system . After fully charging batteries both failed load test . Replace both defective batteries . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Battery</td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table>	Parts List	Qty	Battery	2.00	Shop Supplies	1.00
Parts List	Qty						
Battery	2.00						
Shop Supplies	1.00						
Hours 2.00 :	Labor: 120.00	Parts: 259.28	Total: 379.28				

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808317 **Meter:** 71826 **In Date:** 08/14/2018 **Closed:** 09/04/2018
Problem: Engine loud at idle.

<ul style="list-style-type: none"> - Diagnose engine /transmission noise . Remove Pto and disassemble to replace bearing . Remove transmission pan to adjust Pto engagement depth . Flush and refill transmission .test drive. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Pto Bearing 1.00 oil auto 12.00 Shop Supplies 1.00 Freight Charge 1.00 	<p>Qty</p>	
Hours 6.00	Labor: 360.00	Parts: 169.88	Total: 529.88
:			

Workorder: 1900809 **Meter:** 73795 **In Date:** 01/22/2019 **Closed:** 02/13/2019
Problem: P.M. service and check engine light on .

<ul style="list-style-type: none"> - P.m. service. - Inspect and service crane . - Computer diagnose check engine light ,code P246e . R&r all four Egt temp sensors . Clear code and reprogram Pcm with up dated calibration . - Pressure test cooling system . R&r leaking primary radiator and both thermostats . Flush and refill coolant . - Rotate and balance all six tires . Nitrofill all. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 1.00 15-40 Oil 13.00 22" Wiper Blade 2.00 Washer Fluid Concentr 1.00 Blue Df 2.00 Napagold Fuel Filter 1.00 Napa Hydraulic Filtr 2.00 Sensor 4.00 radiator 1.00 Anti Freeze Motorcraft 3.00 thermostat 1.00 thermostat 2.00 O Ring 1.00 O Ring 1.00 Shop Supplies 1.00 	<p>Qty</p>	
Hours 17.90	Labor: 1,199.30	Parts: 1,242.69	Total: 2,441.99
:			

Workorder: 1902512 **Meter:** 74381 **In Date:** 03/06/2019 **Closed:** 03/07/2019
Problem: Right wiper coming apart.

<ul style="list-style-type: none"> - Test and replace defective right side wiper blade. Retest . 	<p>Parts List</p> <ul style="list-style-type: none"> 22" Wiper Blade 1.00 	<p>Qty</p>	
Hours 0.20	Labor: 13.40	Parts: 3.48	Total: 16.88
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1907385 **Meter:** 76005 **In Date:** 07/17/2019 **Closed:** 07/25/2019
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Inspect and service crane . Service and inspect both outriggers and hoses. - Check and inspect all body bushings .r&r all six body bushings . - Rotate and high speed balance all six tires . Nitrofill all. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 22" Wiper Blade Washer Fluid Concentr Napagold Oil Filter 15-40 Oil Used Fire X Refurbished Napagold Fuel Filter Ford Triton Pvc Swc Blue Df Napa Hydraulic Filtr Body Mount Kit Body Mount Kit Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 2.00 1.00 1.00 13.00 1.00 1.00 1.00 1.00 2.00 4.00 2.00 1.00 	
Hours 14.00	Labor: 938.00	Parts: 754.19	Total: 1,692.19
:			

Workorder: 1910802 **Meter:** 77114 **In Date:** 10/22/2019 **Closed:** 10/22/2019
Problem: Transition Prep Charge

<ul style="list-style-type: none"> - Transition Prep Charge 	Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
	:			