

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10189846    2013 FORD F350 Utility Body, 1 Ton, Gas**

**Workorder:** 1303658    **Meter:** 311    **In Date:** 04/15/2013    **Closed:** 04/15/2013  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 4.00                      Labor: 240.00              Parts: 0.00                      Total: 240.00  
 :

**Workorder:** 1309634    **Meter:** 8318    **In Date:** 09/24/2013    **Closed:** 10/08/2013  
**Problem:** Pm service and wiper blades.

- P.m. Service.

- Replace two tires,rotate and balance all six.

- Complete wheel alignment.test drive.

- Shop Supplies

**Parts List**

	<b>Qty</b>
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Floor Mat-2pc Rub Bk	1.00
5w20 Engine Oil	7.00
Tr416 Valve Stem	2.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 9.00                      Labor: 540.00              Parts: 566.13                      Total: 1,106.13  
 :

**Workorder:** 1405592    **Meter:** 17257    **In Date:** 06/06/2014    **Closed:** 06/18/2014  
**Problem:** P.M. service and front grill broken and left front utility door inop.

- Perform pm service.

- Install six new tires.nitrogen fill and balance all six.

- Inspect and replace broken front grill assembly with new.also replace failed right side lock cylinder for tool box with new.

- Shop Supplies

**Parts List**

	<b>Qty</b>
5w20 Engine Oil	7.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Lt245/75r17 Hankook Tire	6.00
Tr416 Valve Stem	6.00
Grille	1.00
Lock Clinder	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours 8.00                      Labor: 480.00              Parts: 1,962.70                      Total: 2,442.70  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1504316      **Meter:** 29602      **In Date:** 04/28/2015      **Closed:** 05/07/2015  
**Problem:** Pm service.Tires and wiper blades.

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Replace two tires.rotate and balance all six.</li> <li>- Check starting and charging system.battery failed loadtest after recharge.replace defective battery.</li> <li>- Replace broken hitch pintle pin and chain.</li> <li>- Replace front brake pads and resurface both front brake rotors.service calipers and bleed brake system.replace grease seals and repack front wheel bearings.</li> <li>- Complete front end alignment and roadtest.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>kit brake</li> <li>Seal</li> <li>Cap</li> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Wiper Blade</li> <li>Napagold Air Filter</li> <li>Washer Fluid Concentr</li> <li>179636492 Lt245-75r17</li> <li>Battery 65</li> <li>Pintle Pin W/chain</li> <li>Brake Cleaner</li> <li>1401 Brake Fluid Bra</li> <li>Shop Supplies</li> <li>Tire Disposal Fee</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>7.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> </ul>
Hours 15.50 :	Labor: 930.00      Parts: 859.98	Total: 1,789.98

**Workorder:** 1601153      **Meter:** 36760      **In Date:** 02/02/2016      **Closed:** 02/11/2016  
**Problem:** P.M. Service

<ul style="list-style-type: none"> <li>- Pm service.</li> <li>- Replace four tires.rotate and balance all six.</li> <li>- Replace rear brake pads Service calipers.resurface rear brake rotors.test drive.</li> <li>- Complete front end alignment.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Napagold Air Filter</li> <li>22" Wiper Blade</li> <li>Used Fire X Refurbished</li> <li>179636492 Lt245-75r17</li> <li>Brake Pad</li> <li>Brake Pad</li> <li>Stg Wheel Cov - Ford</li> <li>Shop Supplies</li> <li>Tire Disposal Fee</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>4.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>4.00</li> </ul>
Hours 14.50 :	Labor: 870.00      Parts: 1,241.74	Total: 2,111.74

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1608450      **Meter:** 45606      **In Date:** 08/16/2016      **Closed:** 08/30/2016  
**Problem:** P.M. service and had to jump start .

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Replace four tires,rotate and balance all six.</li> <li>- Complete wheel alignment.test drive.</li> <li>- Fabricate and install new front asset #.</li> <li>- Service transmission.flush and refill system.</li> <li>- Test battery and charging system.recharge and retest battery,failed load test.replace defective battery.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Napagold Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>179636492 Lt245-75r17</td><td></td><td align="right">4.00</td></tr> <tr><td>Atp Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Syn-atf Trans Fluid S</td><td></td><td align="right">20.00</td></tr> <tr><td>Trams Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Battery 65</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">4.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Napagold Oil Filter		1.00	5w20 Engine Oil		7.00	Napagold Air Filter		1.00	Washer Fluid Concentr		1.00	22" Wiper Blade		2.00	179636492 Lt245-75r17		4.00	Atp Filter		1.00	Syn-atf Trans Fluid S		20.00	Trams Filter		1.00	Battery 65		1.00	Shop Supplies		1.00	Tire Disposal Fee		4.00	
<b>Parts List</b>		<b>Qty</b>																																							
Napagold Oil Filter		1.00																																							
5w20 Engine Oil		7.00																																							
Napagold Air Filter		1.00																																							
Washer Fluid Concentr		1.00																																							
22" Wiper Blade		2.00																																							
179636492 Lt245-75r17		4.00																																							
Atp Filter		1.00																																							
Syn-atf Trans Fluid S		20.00																																							
Trams Filter		1.00																																							
Battery 65		1.00																																							
Shop Supplies		1.00																																							
Tire Disposal Fee		4.00																																							
Hours 13.50 :	Labor: 810.00	Parts: 1,358.40	Total: 2,168.40																																						

**Workorder:** 1703350      **Meter:** 53159      **In Date:** 04/04/2017      **Closed:** 04/18/2017  
**Problem:** P.M. Service.Nail in right side tire.Tail light out.

<ul style="list-style-type: none"> <li>- P.m. Service.</li> <li>- Pressure test inspect cooling system.flush and refill system.</li> <li>- Replace two tires,rotate and balance all six.</li> <li>- Resurface front brake rotors,replace calipers and pads.flush and bleed system.</li> <li>- Repair left brake lamp wiring.</li> <li>- Complete wheel alignment.test drive.</li> <li>- Shim and adjust bumper brackets.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Napagold Air Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>Anti Freeze Motorcraft</td><td></td><td align="right">2.00</td></tr> <tr><td>179636492 Lt245-75r17</td><td></td><td align="right">2.00</td></tr> <tr><td>Tr416 Valve Stem</td><td></td><td align="right">2.00</td></tr> <tr><td>Reman/ca</td><td></td><td align="right">1.00</td></tr> <tr><td>Reman/ca</td><td></td><td align="right">1.00</td></tr> <tr><td>B Fluid Dot 3-32oz</td><td></td><td align="right">1.00</td></tr> <tr><td>Non-chlor Brake Clnr</td><td></td><td align="right">1.00</td></tr> <tr><td>Wheel Seal - Front Wheel</td><td></td><td align="right">2.00</td></tr> <tr><td>Front Brake Pad</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	5w20 Engine Oil		7.00	Napagold Oil Filter		1.00	Napagold Air Filter		1.00	Used Fire X Refurbished		1.00	Anti Freeze Motorcraft		2.00	179636492 Lt245-75r17		2.00	Tr416 Valve Stem		2.00	Reman/ca		1.00	Reman/ca		1.00	B Fluid Dot 3-32oz		1.00	Non-chlor Brake Clnr		1.00	Wheel Seal - Front Wheel		2.00	Front Brake Pad		1.00	22" Wiper Blade		2.00	Shop Supplies		1.00	Tire Disposal Fee		2.00	
<b>Parts List</b>		<b>Qty</b>																																																			
5w20 Engine Oil		7.00																																																			
Napagold Oil Filter		1.00																																																			
Napagold Air Filter		1.00																																																			
Used Fire X Refurbished		1.00																																																			
Anti Freeze Motorcraft		2.00																																																			
179636492 Lt245-75r17		2.00																																																			
Tr416 Valve Stem		2.00																																																			
Reman/ca		1.00																																																			
Reman/ca		1.00																																																			
B Fluid Dot 3-32oz		1.00																																																			
Non-chlor Brake Clnr		1.00																																																			
Wheel Seal - Front Wheel		2.00																																																			
Front Brake Pad		1.00																																																			
22" Wiper Blade		2.00																																																			
Shop Supplies		1.00																																																			
Tire Disposal Fee		2.00																																																			
Hours 16.50 :	Labor: 990.00	Parts: 988.91	Total: 1,978.91																																																		

**Workorder:** 1705090      **Meter:** 53540      **In Date:** 05/23/2017      **Closed:** 05/23/2017  
**Problem:** 1 - Key(s) issued

<ul style="list-style-type: none"> <li>- 1 - Key(s) issued</li> </ul>	<table border="0"> <thead> <tr> <th align="left" colspan="2"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Duplicate Vehicle Keys</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>		<b>Qty</b>	Duplicate Vehicle Keys		1.00	
<b>Parts List</b>		<b>Qty</b>						
Duplicate Vehicle Keys		1.00						
Hours 0.30 :	Labor: 18.00	Parts: 3.00	Total: 21.00					

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1710687      **Meter:** 58667      **In Date:** 10/30/2017      **Closed:** 11/16/2017

**Problem:** P.M. service ,steering wheel cover,wipers only work on high,pipe box,and ticking noise from engine.

<ul style="list-style-type: none"> <li>- P.m. service.</li> <li>- Tune up engine .replace all sixteen spark plugs .replace # 1 and # 2 coils .replace ignition wires.</li> <li>- Perform induction system cleaning .flush injectors.clear all codes with computer.</li> <li>- Fabricate and install inverter in vehicle. Diagnose wipers with computer code B1008 wiper control switch failed .r&amp;r with new switch .retest.</li> <li>- Body mounts failed ,front and rear .r&amp;r with six body mounts.left front seat recline handle broken .r&amp;r with new.</li> <li>- Rotate and high speed balance all six tires .repair left rear inner flat tire.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Cb185-150 Cir Brkr</li> <li>Terminal</li> <li>Cabl/lug</li> <li>Bulk Battery Cable</li> <li>Bulk Battery Cable</li> <li>Fab Loom-split Poly</li> <li>5w20 Engine Oil</li> <li>Napagold Oil Filter</li> <li>Napagold Air Filter</li> <li>22" Wiper Blade</li> <li>Stg Wheel Cov - Ford</li> <li>Used Fire X Refurbished</li> <li>Al3z12029b</li> <li>Spark Plug</li> <li>Espak Plug Wire</li> <li>Espak Plug Wire</li> <li>Silicone Spray 10oz</li> <li>Injector Cleaner</li> <li>Intake Cleaner Kit</li> <li>Switch</li> <li>Cpi 1575 Inverter 1500 W</li> <li>Body Mount Kit</li> <li>Body Mount Kit</li> <li>Espak Plug Wire</li> <li>Coil Asy</li> <li>Hadle</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>2.00</li> <li>6.00</li> <li>9.00</li> <li>4.00</li> <li>13.00</li> <li>7.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>16.00</li> <li>4.00</li> <li>4.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>8.00</li> <li>2.00</li> <li>4.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 27.50 :	Labor: 1,650.00 0	Parts: 1,990.00	Total: 3,640.00

**Workorder:** 1712110      **Meter:** 60593      **In Date:** 12/11/2017      **Closed:** 02/12/2018

**Problem:** Order and install pipe bin on top of right side utility box.

<ul style="list-style-type: none"> <li>- Fabricate and install pipe bin on top of right side utility box.fabricate mount and straps for water tank mounted on top of pipe bin.</li> <li>- Diagnose noise from A/c blower motor .r&amp;r defective blower motor .retest.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Cir Rtv Silcn Sealant</li> <li>Blower Motor</li> <li>open top pipe box</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 7.10 :	Labor: 426.00	Parts: 1,277.51	Total: 1,703.51

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1805087      **Meter:** 62631      **In Date:** 05/16/2018      **Closed:** 05/29/2018  
**Problem:** P.M. service ,new vise ,noise in front on turns ,steering wheel cover.

<ul style="list-style-type: none"> <li>- P.m. service. Test drive for noise . Only noise heard was from pipe bin on rear of truck.</li> <li>- Replace rear brake rotors and pads and calipers .flush and bleed brake system .test drive.</li> <li>- Remove and replace vise and fabricate mounting holes.</li> <li>- Replace four tires .rotate and balance all six tires. Nitrogen fill tires.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td align="right">7.00</td></tr> <tr><td>22" Wiper Blade</td><td align="right">2.00</td></tr> <tr><td>Ford Triton Pvc Swc</td><td align="right">1.00</td></tr> <tr><td>Big G Degreaser 1 Gal</td><td align="right">1.00</td></tr> <tr><td>B Fluid Dot 3-32oz</td><td align="right">1.00</td></tr> <tr><td>Non-chlor Brake Clnr</td><td align="right">2.00</td></tr> <tr><td>Hd Workshop Vise</td><td align="right">1.00</td></tr> <tr><td>179636492 Lt245-75r17</td><td align="right">4.00</td></tr> <tr><td>Real Brake Pad</td><td align="right">1.00</td></tr> <tr><td>Brake Rotor</td><td align="right">2.00</td></tr> <tr><td>Brake Caliper</td><td align="right">1.00</td></tr> <tr><td>Brake Caliper</td><td align="right">1.00</td></tr> <tr><td>Seal</td><td align="right">2.00</td></tr> <tr><td>Axle Gasket</td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td align="right">4.00</td></tr> </tbody> </table>	<b>Parts List</b>	<b>Qty</b>	Napagold Oil Filter	1.00	5w20 Engine Oil	7.00	22" Wiper Blade	2.00	Ford Triton Pvc Swc	1.00	Big G Degreaser 1 Gal	1.00	B Fluid Dot 3-32oz	1.00	Non-chlor Brake Clnr	2.00	Hd Workshop Vise	1.00	179636492 Lt245-75r17	4.00	Real Brake Pad	1.00	Brake Rotor	2.00	Brake Caliper	1.00	Brake Caliper	1.00	Seal	2.00	Axle Gasket	2.00	Shop Supplies	1.00	Tire Disposal Fee	4.00
<b>Parts List</b>	<b>Qty</b>																																				
Napagold Oil Filter	1.00																																				
5w20 Engine Oil	7.00																																				
22" Wiper Blade	2.00																																				
Ford Triton Pvc Swc	1.00																																				
Big G Degreaser 1 Gal	1.00																																				
B Fluid Dot 3-32oz	1.00																																				
Non-chlor Brake Clnr	2.00																																				
Hd Workshop Vise	1.00																																				
179636492 Lt245-75r17	4.00																																				
Real Brake Pad	1.00																																				
Brake Rotor	2.00																																				
Brake Caliper	1.00																																				
Brake Caliper	1.00																																				
Seal	2.00																																				
Axle Gasket	2.00																																				
Shop Supplies	1.00																																				
Tire Disposal Fee	4.00																																				
Hours 13.00	Labor: 780.00      Parts: 1,809.06      Total: 2,589.06																																				

**Workorder:** 1806892      **Meter:** 63968      **In Date:** 07/05/2018      **Closed:** 07/12/2018  
**Problem:** Had to jump start in A.M. A/C blows warm .

<ul style="list-style-type: none"> <li>- A/c performance test .r&amp;r defective evaporator ,and condensor and seals .recover and evacuate system and complete charge to factory spec. Retest A/c performance.</li> <li>- Check battery and charging system .battery failed load test after full recharge. R&amp;r defective battery.</li> <li>- Shop Supplies</li> </ul>	<table border="0"> <thead> <tr> <th align="left"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Freon Lv Shop 2</td><td align="right">2.00</td></tr> <tr><td>E8 A/c Oil Univ W Dye</td><td align="right">1.00</td></tr> <tr><td>Battery 65</td><td align="right">2.00</td></tr> <tr><td>Seal Kits</td><td align="right">2.00</td></tr> <tr><td>Kit O</td><td align="right">1.00</td></tr> <tr><td>Condenser</td><td align="right">1.00</td></tr> <tr><td>Evaporator Core</td><td align="right">1.00</td></tr> <tr><td>Battery</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>	<b>Qty</b>	Freon Lv Shop 2	2.00	E8 A/c Oil Univ W Dye	1.00	Battery 65	2.00	Seal Kits	2.00	Kit O	1.00	Condenser	1.00	Evaporator Core	1.00	Battery	1.00	Shop Supplies	1.00
<b>Parts List</b>	<b>Qty</b>																				
Freon Lv Shop 2	2.00																				
E8 A/c Oil Univ W Dye	1.00																				
Battery 65	2.00																				
Seal Kits	2.00																				
Kit O	1.00																				
Condenser	1.00																				
Evaporator Core	1.00																				
Battery	1.00																				
Shop Supplies	1.00																				
Hours 12.80	Labor: 768.00      Parts: 1,163.90      Total: 1,931.90																				

**Workorder:** 1806900      **Meter:** 63933      **In Date:** 07/05/2018      **Closed:** 07/05/2018  
**Problem:** 1 - Key(s) issued

<ul style="list-style-type: none"> <li>- 1 - Key(s) issued</li> </ul>	<table border="0"> <thead> <tr> <th align="left"><b>Parts List</b></th> <th align="right"><b>Qty</b></th> </tr> </thead> <tbody> <tr><td>Duplicate Vehicle Keys</td><td align="right">1.00</td></tr> </tbody> </table>	<b>Parts List</b>	<b>Qty</b>	Duplicate Vehicle Keys	1.00
<b>Parts List</b>	<b>Qty</b>				
Duplicate Vehicle Keys	1.00				
Hours 0.30	Labor: 18.00      Parts: 3.00      Total: 21.00				

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1810683      **Meter:** 66729      **In Date:** 10/17/2018      **Closed:** 10/22/2018  
**Problem:** PM Service, Flat tire - inside pass side.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Check and replace trailer plug connector . Fabricate wiring as needed.	Napagold Oil Filter	1.00
- Replace two tires . Rotate and balance all six tires . Nitrofill all.	5w20 Engine Oil	7.00
- Complete alignment and road test.	Used Fire X Refurbished	1.00
- Shop Supplies	Mac Wite Lithium Gres	1.00
	22" Wiper Blade	2.00
	trailer plug	1.00
	Tr416 Valve Stem	2.00
	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.00	Labor: 670.00	Parts: 504.51
:		Total: 1,174.51

**Workorder:** 1904638      **Meter:** 70461      **In Date:** 04/29/2019      **Closed:** 05/13/2019  
**Problem:** P.M. service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Test and replace defective washer jets .	5w20 Engine Oil	8.00
- Test and replace rear marker light assembly .	Napagold Oil Filter	1.00
- Repair right rear outer tire . Balance and rotate all six tires . Nitrofill all .	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Napagold Air Filter	1.00
	Washer Nozzle	2.00
	Led M C Lamp	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 502.50	Parts: 70.22
:		Total: 572.72

**Workorder:** 1906794      **Meter:** 71097      **In Date:** 06/28/2019      **Closed:** 07/02/2019  
**Problem:** Screw in drivers rear inside tire.

- Repair left rear tire and balance . Nitrofill all.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00
:		Total: 70.00

**Workorder:** 1909328      **Meter:** 72340      **In Date:** 09/10/2019      **Closed:** 09/16/2019  
**Problem:** Check suspension .

- Test drive . replace both front body mount and all four rear mounts . Retest .	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Body Mount Kit	4.00
	Body Mount Kit	2.00
	Shop Supplies	1.00
Hours 6.00	Labor: 402.00	Parts: 608.94
:		Total: 1,010.94

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1910945      **Meter:** 73243      **In Date:** 10/23/2019      **Closed:** 11/02/2019  
**Problem:** PM Service, Light Bar inop.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Diagnose light bar inop . Disassemble light bar to test and replace control module board . Retest .	Napagold Oil Filter	1.00
- Rotate and balance all six tires .nitrofill all.	5w20 Engine Oil	7.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Mac Wite Lithium Gres	1.00
	Circuit Board - Liberty Lightbar	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 547.50	Parts: 568.41
:		Total: 1,115.91

**Workorder:** 1913024      **Meter:** 73858      **In Date:** 12/19/2019      **Closed:** 12/19/2019  
**Problem:** Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			