

**Palm Beach County Fleet Management
Asset Maintenance History**

10193009 2013 TORO GRNDSMSTR 7200 Mower, Zero Turn Radius (Ztr), 72"

Workorder: 1308569 **Meter:** 1 **In Date:** 08/26/2013 **Closed:** 08/26/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1500252 **Meter:** 285 **In Date:** 01/08/2015 **Closed:** 01/20/2015
Problem: Pm service.

- Pm service.
- Shop Supplies

Parts List	Qty
15w40 Bulk Tank Pahoee	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours 4.00 Labor: 240.00 Parts: 37.99 Total: 277.99
:

Workorder: 1510149 **Meter:** 484 **In Date:** 10/06/2015 **Closed:** 10/14/2015
Problem: Pm service.

- Pm service.
- Replace worn deck belts and belt tension spring. Replace scalp wheels as needed.
- Replace blades.
- Test run to check all functions.
- Shop Supplies

Parts List	Qty
15w40 Bulk Tank Pahoee	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Rotary Blade	3.00
V-belt	1.00
V-belt	1.00
Torsion Spring	1.00
Roller Scalp	2.00
Tube-spanner	2.00
Tube Spacer	2.00
Screw	2.00
Shop Supplies	1.00

Hours 7.50 Labor: 450.00 Parts: 409.57 Total: 859.57
:

Workorder: 1600557 **Meter:** 520 **In Date:** 01/19/2016 **Closed:** 01/22/2016
Problem: Replace scalp wheels as needed.

- Replace worn out scalp wheels.
- Shop Supplies

Parts List	Qty
Deck Roller	2.00
K5371-42110 Gauge Whe	2.00
Shop Supplies	1.00

Hours 1.50 Labor: 90.00 Parts: 86.51 Total: 176.51
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603802 **Meter:** 563 **In Date:** 04/11/2016 **Closed:** 04/12/2016
Problem: Replace scalp whels as needed.

- Replace damaged scalp wheels.	Parts List	Qty
- Shop Supplies	Roller Scalp	2.00
	Tube Spacer	2.00
	Tube-spanner	2.00
	Screw	2.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 68.54
:		Total: 128.54

Workorder: 1604453 **Meter:** 546 **In Date:** 04/28/2016 **Closed:** 05/12/2016
Problem: Replace scalp wheels as needed.

- Replace scalp wheels as needed.	Parts List	Qty
- Shop Supplies	Roller Scalp	2.00
	Roller,deck	1.00
	Roller	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 115.45
:		Total: 175.45

Workorder: 1605961 **Meter:** 570 **In Date:** 06/09/2016 **Closed:** 06/14/2016
Problem: Replace broken scalp wheels as needed.

- Replace broken scalp wheels.	Parts List	Qty
- Repair Lr tire.	Roller Scalp	2.00
- Shop Supplies	Tube Spacer	2.00
	Tube-spanner	2.00
	Slime Tire Sealant	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 76.16
:		Total: 196.16

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701307 **Meter:** 744 **In Date:** 02/08/2017 **Closed:** 02/16/2017
Problem: Pm service

- Pm service.	Parts List	Qty
- Replace worn front caster wheels.	Napagold Oil Filter	1.00
- Replace missing scalp wheels.	15w40 Bulk Tank Pahoee	4.00
- Replace blades.	Napagold Oil Filter	1.00
- Test run to check all functions.	Napagold Air Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Slime Tire Sealant	2.00
	Napa Hydraulic Filtr	1.00
	Roller Scalp	1.00
	Rotary Blade	3.00
	Tube Spacer	1.00
	Tube-spanner	1.00
	Screw	1.00
	15-6.00x6 Ribbed Tire	2.00
	Rubber Deflector Assy	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 1,023.13
:		Total: 1,503.13

Workorder: 1803469 **Meter:** 1047 **In Date:** 04/03/2018 **Closed:** 04/10/2018
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace worn blades.	15w40 Bulk Tank Pahoee	4.00
- Replace worn deck rollers and broken hood latch.	Napagold Oil Filter	1.00
- Replace shorted starter motor.	Napagold Fuel Filter	1.00
- Test run to check all functions.	Napagold Air Filter	1.00
- Shop Supplies	Deck Roller	2.00
	Shaft	2.00
	Powersport Starter	1.00
	Rotary Blade	3.00
	Rubber Latch	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 466.82
:		Total: 946.82

Workorder: 1807053 **Meter:** 1088 **In Date:** 07/11/2018 **Closed:** 07/12/2018
Problem: Flat tire.

- Repair Rr tire and straighten rim.	Parts List	Qty
- Shop Supplies	Slime Tire Sealant	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 15.23
:		Total: 105.23

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810979 **Meter:** 1168 **In Date:** 10/24/2018 **Closed:** 11/06/2018
Problem: List.

<ul style="list-style-type: none"> - Pto working intermittently. Replace malfunctioning pto switch. Replace sticking deck lift switch. - Replace damaged scalp wheels. - Replace damaged hood latch brackets. - Test run. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Pto Switch Switch Spst On-off-on Tube-spanner Tube Spacer Roller Scalp catch latch Shop Supplies Freight Charge 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 2.00 2.00 2.00 2.00 1.00 1.00 	
Hours 3.50 :	Labor: 234.50	Parts: 182.14	Total: 416.64

Workorder: 1813073 **Meter:** 1189 **In Date:** 12/28/2018 **Closed:** 12/31/2018
Problem: List.

<ul style="list-style-type: none"> - Test run to verify complaints. Checked pto circuit and wiring, checked engine and seat switch wiring. No problem found. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 	
Hours 1.00 :	Labor: 67.00	Parts: 3.00	Total: 70.00

Workorder: 1902480 **Meter:** 1234 **In Date:** 03/06/2019 **Closed:** 03/11/2019
Problem: Replace blades

<ul style="list-style-type: none"> - Replace blades - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Rotary Blade Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 3.00 1.00 	
Hours 1.00 :	Labor: 67.00	Parts: 106.86	Total: 173.86

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1903315 **Meter:** 1251 **In Date:** 03/27/2019 **Closed:** 04/11/2019
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace damaged anti scalp blade guard.	Napagold Oil Filter	1.00
- Replace worn rollers as needed.	15w40 Bulk Tank Pahokee	4.00
- Replaced cracked fan belt and radiator hoses.	Napagold Fuel Filter	1.00
- Replaced damaged radiator fan.	Napagold Air Filter	1.00
- Replaced worn front and rear tires.	1gal Rtu Antifreeze	2.00
- Shop Supplies	Lower Radiator Hose	1.00
	Anti-scalp Cup	3.00
	Spacer-roller	1.00
	Shaft,roller	1.00
	Roller,deck	1.00
	Deck Roller	2.00
	Roller	1.00
	24x12.00-12/4 Car	2.00
	15-6.00x6 Ribbed Tire	2.00
	Engine Fan	1.00
	Pto Drive Belt	1.00
	Upper Radiator Hose	1.00
	V-belt	1.00
	Slime Tire Sealant	2.00
	Slime Tire Sealant	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 12.50	Labor: 837.50	Parts: 1,761.92
:		Total: 2,599.42

Workorder: 1909523 **Meter:** 1344 **In Date:** 09/17/2019 **Closed:** 09/24/2019
Problem: Blades shutting off, Replace blades

- Replace damaged blades.	Parts List	Qty
- Replace damaged air filter assy.	Rotary Blade	3.00
- Check Pto circuit and wiring. Replace faulty Pto switch.	Air Cleaner Assy	1.00
- Replace worn idler pulley on mower deck.	Pto Switch	1.00
- Shop Supplies	Pulley	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 5.00	Labor: 335.00	Parts: 476.74
:		Total: 811.74

Workorder: 1910619 **Meter:** 1346 **In Date:** 10/15/2019 **Closed:** 10/17/2019
Problem: Blades shutting off

- Checked pto clutch and wiring, test ran mower per complaint. No problem found.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 146.00	Parts: 4.00
:		Total: 150.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1912805 **Meter:** 1378 **In Date:** 12/16/2019 **Closed:** 12/16/2019
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			