



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V49391**

In Date: 05/16/2012  
Close Date: 07/18/2012

Meter Reading: 266.00

**Problem?**

Set up new Vehicle

**Task performed:**

1. SET UP DUAL BATTERY SYSTEM.
2. INSTALLED SEAT COVERS ON DRIVER AND PASSENGER SEATS.
3. INSTALL RUNNING BOARDS.
4. START TO FABRICATE TOOL BOX FOR BACK SEAT.
5. FINISH FABRICATION OF REAR TOOL BOX.
6. CUT AND INSTALL RUBBER MATS ON BAD SHELF
7. MOUNT FENDER LIGHTS AND LIGHTS ON PUSH BUMPER.
8. FAB SHELF FOR BEL ON TRUCK INSTALL LIGHTS EQ. BACK UP CAMERA ETC. MOUNT ALL EQ. ON TRUCK.

Parts	Quantity
14005061RETAINER BATTERY	1
1817PLUG	1
251685TUBE STEP	1
25825642F-CABLE	1
443758C2-32-25 LATCH LEVER LOCKING	2
48-60BATTERY	1
5025TERMINAL BOX	1
50R03ZCRLIGHT LED RED TIR 6	4
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	2
5TSMACMOUNT 500 TIR SER CHROME	4
8126482-2106 TOGGLE GUARD	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
C1123-T91SEAT COVER	1
FHLP-6TANK CLIP	2
KD-UN-5-SFUSE 6-SF BRACKET	1
KR-CCLCATHODE COMPARTMENT LIGHT	5
PLCM7200CAMERA KIT W 7 IN MONITOR	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	2
S775COUPLER	1
UMVS111611STRAP	2
UMVS162511STRAP	2

**Workorder: V50761**

In Date: 07/11/2012  
Close Date: 07/25/2012

Meter Reading: 266.00

**Problem?**

In the new CP5 Vehicle, the cab refrigertor is not operating, nor is the rear view mirror back up cam. Not sure if this is related to ar electrical problem with the rear mounted radio.

**Task performed:**

REPAIRED BAD GROUND WIRE.

Parts	Quantity
NO PARTS USED	



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V50972**

In Date: 07/19/2012  
Close Date: 08/06/2012

Meter Reading: 804.00

**Problem?**

the panel that holds the batteries and TIC is not bolted so it moves freely. EMS5

**Task performed:**

Parts

Quantity

REPAIRED REAR PANEL ON REAR COMPARTMENT.

NO PARTS USED

**Workorder: V54510**

In Date: 01/01/1900  
Close Date: 12/19/2012

Meter Reading: 7,888.00

**Problem?**

B inspection

**Task performed:**

Parts

Quantity

B inspection

NO PARTS USED

Vendor?: ROGER DEAN

**Workorder: V54526**

In Date: 12/08/2012  
Close Date: 12/20/2012

Meter Reading: 7,930.00

**Problem?**

smoke from under hood

**Task performed:**

Parts

Quantity

FOUND SHOE CHARGER FUSE HOLDER MELTED AT TERMINAL BLOCK UNDER HOOD. DID NOT HAVE FUSE HOLDER REPLACED WITH WERE. CHARGER INTERNALLY FUSED. HOLDER MELTED BECAUSE OF DOOR CONNECTION TO TERMINAL BLOCK.

NO PARTS USED

**Workorder: V54151**

In Date: 12/03/2012  
Close Date: 01/03/2013

Meter Reading:

**Problem?**

the back up camera is not working ems 5

**Task performed:**

Parts

Quantity

REPAIRED BLOWN FUSE AND REWIRED POWER WIRE.

NO PARTS USED



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V54322**

In Date: 12/09/2012

Meter Reading:

Close Date: 01/03/2013

**Problem?**

Was put in the IBEM 12-3-12, back up camera does not work. Can not see to back up. Call 561-307-8146 Captain 5 station 57

**Task performed:**

Parts

Quantity

REPAIRED BACK UO CAM.

NO PARTS USED

**Workorder: V57390**

In Date: 05/01/2013

Meter Reading: 14,254.00

Close Date: 05/01/2013

**Problem?**

BATTERY DEAD EMS 5

**Task performed:**

Parts

Quantity

TRAVEL TO HQ TRUCK WOULD NOT START  
CHECKED ELECTRICAL SYSTEM EVERYTHING  
GOOD WHILE CHECKING IGNITION FOUND NONE GM  
KEY IN SWITCH USED STOCK KEY AND TRUCK  
STARTED LINE.

NO PARTS USED

**Workorder: V57479**

In Date: 05/04/2013

Meter Reading: 14,844.00

Close Date: 05/10/2013

**Problem?**

Service Engine oil soon prompt came on. EMS5

**Task performed:**

Parts

Quantity

B inspection  
oil and filter

NO PARTS USED

make spare key

**Vendor?:** ROGER DEAN

**Workorder: V58409**

In Date: 06/13/2013

Meter Reading: 16,113.00

Close Date: 06/21/2013

**Problem?**

Rear tires need to be inspected and possibly need to be replaced

**Task performed:**

Parts

Quantity

CHECKED TIRES AND NEED TO BE REPLACED  
CALLED SHOP.

NO PARTS USED



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V57643**

In Date: 05/10/2013  
Close Date: 09/10/2013

Meter Reading: 14,254.00

**Problem?**

Replace front tires

**Task performed:**

REPAIRED DO-440-0513-17660

Parts

NO PARTS USED

Quantity

**Workorder: V59934**

In Date: 08/20/2013  
Close Date: 09/13/2013

Meter Reading: 19,893.00

**Problem?**

oil leak ems 5

**Task performed:**

CHECKED FOR OIL LEAK, FOUND OIL FILTER LEAKING REPAIRED AND ROAD TESTE.

Parts

NO PARTS USED

Quantity

**Workorder: V60458**

In Date: 09/12/2013  
Close Date: 09/19/2013

Meter Reading: 20,983.00

**Problem?**

B-inspection

**Task performed:**

1. PERFORM B-INSPECTION.
2. ROTATE TIRES AND ADJUST PRESSURE TO FACTORY SPECS.
3. DRIVE TO TIRE SHOP. CALAHAN TIRE AND WAIT FOR TWO FRONT TIRE TO BE INSTALLED. DRIVE BACK TO OUR SHOP.

Parts

57060OIL FILTER	1
AF1518 42488 FILTER AIR-SUBURB	1

Quantity

**Workorder: V61217**

In Date: 10/12/2013  
Close Date: 10/23/2013

Meter Reading: 22,906.00

**Problem?**

Replace rear tires

**Task performed:**

REPLACE REAR TIRES.

Parts

NO PARTS USED

Quantity

**Vendor?:** CALLAGHAN TIRE



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V61313**

In Date: 10/17/2013  
Close Date: 10/23/2013

Meter Reading: 23,018.00

**Problem?**

Rear interior light bar (behind driver's side) is dangling from one side. Currently the light bar is being held up with a tie strap. ems :

**Task performed:**

REPAIRED REAR LIGHT BAR THAT FELL OFF IN REAR.

Parts

NO PARTS USED

Quantity

**Workorder: V61943**

In Date: 11/12/2013  
Close Date: 11/21/2013

Meter Reading: 24,342.00

**Problem?**

No start

**Task performed:**

CHECKED BATTERIES FOUND NO GOOD. REMOVED AND REPLACED BATTERIES CHECKED CHARGING SYSTEM ALL CHECKED OK.

Parts

24-60BATTERY GROUP 24

48-60BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1

1

2

**Workorder: V62864**

In Date: 12/21/2013  
Close Date: 12/31/2013

Meter Reading:

**Problem?**

1. emergency rear light bar within the camper top does not work. Also, rear emergency lights on light bar on top of cab don't work.
2. The back up/rear camera will not work at all EMS 5

**Task performed:**

1. WORK ON LIGHTS.
2. REPAIR REAR LIGHTS, REPLACE REAR FENDER LIGHTS WITH REDI GLUE. REPAIR WIRES ON CONTROL CONSOLE.

Parts

50R03ZCRLIGHT LED RED TIR 6

5W30BENGINE OIL

Quantity

2

6

**Workorder: V62914**

In Date: 12/23/2013  
Close Date: 12/31/2013

Meter Reading: 26,853.00

**Problem?**

B-inspection

**Task performed:**

PREFORM B INSPECTION.

Parts

57060OIL FILTER

AF1518 42488 FILTER AIR-SUBURB

Quantity

1

1



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V63161**

In Date: 01/06/2014

Meter Reading: 26,853.00

Close Date: 01/13/2014

**Problem?**

Repair lighting inside box Re-install door in box

**Task performed:**

Parts

Quantity

1. CHECK OUT ALL LIGHT REPAIR LIGHTS IN RESR  
CHECK ALL FUSES AND CHECK OUT GROUND ALL  
WORKING.

NO PARTS USED

2. REPAIR SIDE DOOR, MISSING BOLTS, REPLACE  
AND TIGHTEN ADJUST LOCKS OK.

3. REPAIR REAR DOOR IN BACK COMPARTMENT OF  
TRUCK INSTALLED NEW SCREW AND BOLTS ON  
BRAKES, REPAIR BOTH EMS LIGHTS IN REAR  
WINDOW.

**Workorder: V63264**

In Date: 01/09/2014

Meter Reading: 27,027.00

Close Date: 01/16/2014

**Problem?**

Replace rear tires

**Task performed:**

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor?: GOOD YEAR

**Workorder: V59396**

In Date: 07/29/2013

Meter Reading:

Close Date: 01/21/2014

**Problem?**

The rear view camera display is not working. Will not either turn on or there is no power to it. E 33

**Task performed:**

Parts

Quantity

REPAIRS COMPLETED.

NO PARTS USED



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V62328**

In Date: 11/27/2013  
Close Date: 01/27/2014

Meter Reading: 25,535.00

**Problem?**

interior light that is mounted to the rear end of the camper top is falling apart. EMS 5

**Task performed:**

1. REPAIRED LIGHT THAT WAS FALLING OFF.

Parts

NO PARTS USED

Quantity

**Workorder: V63831**

In Date: 01/29/2014  
Close Date: 02/25/2014

Meter Reading:

**Problem?**

Rear view camera has stopped working again. During the night the flickering bright white display is extremely annoying. Video display will not turn off either. EMS 5

**Task performed:**

REPAIRED REAR VIEW MIRROR CAM THAT HAD BAD DISPLAY.

Parts

PLCM7200CAMERA KIT W 7 IN MONITOR

1

Quantity

**Workorder: V65237**

In Date: 03/26/2014  
Close Date: 03/27/2014

Meter Reading: 31,251.00

**Problem?**

No start at HQ

**Task performed:**

WENT TO HEADQUARTERS TO JUMP EMS TRACK, BROUGHT BACK TO SHOP TO TEST BATTERY AND CHECK CHARGER FOUND ONE BATTERY R&R BATTERY AND TEST SHORE CHARGER OK.

Parts

48-60BATTERY

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

1

1

Quantity

**Workorder: V66488**

In Date: 05/14/2014  
Close Date: 05/16/2014

Meter Reading: 33,768.00

**Problem?**

B-inspection

**Task performed:**

B-inspection  
Inspect brakes and rotate tires  
Replaced air filter  
Replaced wiper blades  
Vendor?: AL PACKER

Parts

NO PARTS USED

Quantity



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V66645**

In Date: 05/21/2014

Meter Reading:

Close Date: 06/10/2014

**Problem?**

Board on back of tray in bed of truck needs to be reattached.

**Task performed:**

Parts

Quantity

repaired slide out tray that board has came off .

NO PARTS USED

**Workorder: V67124**

In Date: 06/10/2014

Meter Reading:

Close Date: 08/06/2014

**Problem?**

squeaking in brakes and broken garage door opener EMS 5

**Task performed:**

Parts

Quantity

WORK WAS COMPLETE ON W/O V66488

NO PARTS USED

**Workorder: V68438**

In Date: 08/05/2014

Meter Reading: 37,786.00

Close Date: 08/12/2014

**Problem?**

cap 5 flat repair

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V68723**

In Date: 08/16/2014

Meter Reading: 38,383.00

Close Date: 08/29/2014

**Problem?**

Backup camera not working DC 5

**Task performed:**

Parts

Quantity

Traced out problem with unit. Found broken wire in frame.

PLCM7200CAMERA KIT W 7 IN MONITOR

1





3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V69424**

In Date: 09/16/2014  
Close Date: 09/17/2014

Meter Reading: 39,875.00

**Problem?**

stuck in mud

**Task performed:**

Truck was stuck in mud at fire scene. Removed truck from mud at scene.

Parts

NO PARTS USED

Quantity

**Workorder: V69663**

In Date: 09/24/2014  
Close Date: 10/30/2014

Meter Reading: 40,147.00

**Problem?**

Vehicle is difficult to start. Needs new batteries.

**Task performed:**

1. Load tested batteries. Tested OK. Checked all connections.
2. Repaired bad connections on battery charger.
3. Travel to HQ. Dead unit. Upon arrival, unit started right up. Check battery - good condition - 13.7 volts. Check alternator output - 13.9 volts. All systems operating normally.
4. Removed and replaced batteries.

Parts

24-60BATTERY GROUP 24

48-60BATTERY

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1

1

2

**Workorder: V70100**

In Date: 10/13/2014  
Close Date: 10/30/2014

Meter Reading: 40,973.00

**Problem?**

cooler for meds inop

**Task performed:**

Traced out problem with cooler not working, found broken wire-repaired and tested.

Parts

NO PARTS USED

Quantity



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V70598**

In Date: 10/31/2014  
Close Date: 10/31/2014

Meter Reading: 41,709.00

**Problem?**

B-inspection

**Task performed:**

B-inspection

Parts

NO PARTS USED

Quantity

Vendor?: AL PACKER

**Workorder: V70607**

In Date: 10/31/2014  
Close Date: 11/03/2014

Meter Reading: 41,619.00

**Problem?**

Back up camera inop

**Task performed:**

1. Back up camera inoperable. Power cable cut, short to ground. Damaged screen and camera. Remove system and install new unit. Rewire and secure.

Parts

PLCM7200CAMERA KIT W 7 IN MONITOR

Quantity

1

**Workorder: V71011**

In Date: 11/18/2014  
Close Date: 11/18/2014

Meter Reading: 42,552.00

**Problem?**

Replace tires

**Task performed:**

replace tires

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN TIRE

**Workorder: V74193**

In Date: 03/26/2015  
Close Date: 03/26/2015

Meter Reading:

**Problem?**

Driver side headlight on CP5 needs to be replaced.

**Task performed:**

replace d/side headlight

Parts

H11H11-55WLL BULB LOW BEAM 92095787

Quantity

1



3/2/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10187974

**GMC SIERRA 2500 HD TRUCK EMS OR RESCUE CAPTAIN**

**Workorder: V75035**

**In Date:** 04/30/2015

**Close Date:** 07/07/2015

**Meter Reading:** 50,205.00

**Problem?**

outside b inspection

**Task performed:**

outside b service

wiper blades

**Vendor?:** AL PACKER

Parts

Quantity

NO PARTS USED



# Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10187974) 2012 - GMC SIERRA 2500 HD Spare Ems 57

10187974

## CSHOP-2015-3346

Comments: **WONT START EMS 57**

Date Opened 10-13-2015 Date Finished 10-27-2015 Meter 1 Reading: 58,086

### TASKS PERFORMED

### Q PARTS

BATTERY

2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY  
1 BATTERY; BATTERY GROUP 24  
1 BATTERY; BATTERY

## CSHOP-2015-507

Comments: **FLAT LF EMS5**

Date Opened 5-7-2015 Date Finished 5-8-2015 Meter 1 Reading: 49,395

### TASKS PERFORMED

### NO PARTS USED

TIRES & WHEELS

## CSHOP-2015-559

Comments: **TIRE WARNING ON EMS57 HAD TIRE WORK DONE LAST WEEK AT CALLAGHAN**

Date Opened 5-11-2015 Date Finished 5-20-2015 Meter 1 Reading: 50,679

### TASKS PERFORMED

### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
DIAGNOSE ELECTRICAL  
TIRES & WHEELS

## CSHOP-2015-668

Comments: **B-INSPECTION AL PACKER**

Date Opened 5-15-2015 Date Finished 5-15-2015 Meter 1 Reading: 50,579

### TASKS PERFORMED

### NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

**Asset Work Order History 10187974**

**CSHOP-2016-1508**

Comments: EMS 57

Date Opened 3-30-2016

Date Finished

4-4-2016

Meter 1 Reading:

65,626

**TASKS PERFORMED**

**Q PARTS**

HEADLIGHTS LOW BEAM

1 BULB; H11-55WLL BULB LOW BEAM 92095787  
1 BULB; H11-55WLL BULB LOW BEAM 92095787

**Service Requests:**

03/29/2016

LIGHTS / 19: LOOSE / REPAIR

LOW BEAM HEADLIGHT ON PASSENGER SIDE IS OUT ON EMS57 VEHICLE

**CSHOP-2016-175**

Date Opened 1-13-2016

Date Finished

1-13-2016

Meter 1 Reading:

61,672

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

**CSHOP-2016-2770**

Comments: B SERVICE

Date Opened 6-9-2016

Date Finished

7-5-2016

Meter 1 Reading:

70,492

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

**CSHOP-2016-3466**

Comments: EMS 57 GOING TO CALLAGHAN TO HAVE TIRE REPAIRED 8-16-16

Date Opened 7-19-2016

Date Finished

9-13-2016

Meter 1 Reading:

73,882

**TASKS PERFORMED**

**Q PARTS**

TIRES & WHEELS  
CAB-INTERIOR ACCESSORIES

1 NEWPART; DOOR PANEL

**Service Requests:**

07/15/2016

BODY / 19: LOOSE / REPAIR

SHORE LINE NOT EJECTING FROM VEHICLE. SPOKE TO TOMMY AND HE SAID TO SPRAY WITH WD40. STILL NOT EJECTING.

08/16/2016

TIRES / 19: LOOSE / REPAIR

BAD TIRES- DRIVER FRONT TIRE LEAKING AIR AND DRIVER DOOR INSIDE HANDLE MISSING/BROKEN

**Asset Work Order History 10187974**

**CSHOP-2016-4132**

Date Opened 8-22-2016 Date Finished 8-22-2016 Meter 1 Reading: 72,861

**TASKS PERFORMED**

**NO PARTS USED**

REAR TIRES

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2016-4573**

Date Opened 9-20-2016 Date Finished 9-23-2016 Meter 1 Reading: 74,430

**TASKS PERFORMED**

**Q PARTS**

DIAGNOSE ELECTRICAL  
BODY EXTERIOR

1 BATTERY; BATTERY  
1 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY  
1 CHARGER; AUTO EJECT 20 AERO OTL3925

---

**CSHOP-2016-4707**

Comments: EMS 57

Date Opened 9-29-2016 Date Finished 10-3-2016 Meter 1 Reading: 74,821

**TASKS PERFORMED**

**NO PARTS USED**

CAB-INTERIOR ACCESSORIES

**Service Requests:**

09/23/2016 SERVICE REQUEST / 19: LOOSE / REPAIR  
BACK UP CAMERA IS NOT GETTING A SIGNAL. ALL WIRES ARE CONNECTED.

---

**CSHOP-2016-4934**

Date Opened 10-17-2016 Date Finished 11-7-2016 Meter 1 Reading: 76,578

**TASKS PERFORMED**

**Q PARTS**

SIREN

1 SIREN; SIREN DRIVER SMALL

**Service Requests:**

10/23/2016 SERVICE REQUEST / 18: LEAKING / REPAIR  
SIREN IS CUTTING OUT RANDOMLY. I CHECKED ALL THE WIRES AND CONNECTIONS THAT I CAN SEE AND NONE APPEAR LOOSE. IF I SHUT IT OFF AND TURN THE POWER BACK ON IT STARTS WORKING AGAIN. I ALSO CONFIRMED THE PA MIC WAS NOT BEING ACTIVATED.

---

**CSHOP-2016-4959**

Date Opened 10-18-2016 Date Finished 10-18-2016 Meter 1 Reading: 75,311

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**Asset Work Order History 10187974**

**CSHOP-2016-508**

Comments: **CALLAGHAN REPLACED ALL TIRES**

Date Opened 2-1-2016 Date Finished 2-1-2016 Meter 1 Reading: 62,512

**TASKS PERFORMED**

**NO PARTS USED**

TIRES ALL

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2016-5294**

Date Opened 11-10-2016 Date Finished 11-10-2016 Meter 1 Reading: 76,923

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

**3 A/C; FREON LB**

**Service Requests:**

---

11/10/2016 A/C / 12: BROKEN / REPAIR  
A/C ISSUE A/C NOT BLOWING COLD.

11/10/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST AIR BAG SERVICE LIGHT COMES ON INTERMITTENTLY.

---

**CSHOP-2016-5460**

Comments: **A/C INOP EMS 57**

Date Opened 11-22-2016 Date Finished 11-22-2016 Meter 1 Reading: 77,328

**TASKS PERFORMED**

**NO PARTS USED**

AIR CONDITIONING

---

**CSHOP-2016-5624**

Comments: **EMS57**

Date Opened 12-2-2016 Date Finished 12-27-2016 Meter 1 Reading: 78,722

**TASKS PERFORMED**

**NO PARTS USED**

SAFTEY-EMERGENCY EQUIPMENT  
CAB-INTERIOR ACCESSORIES

**Service Requests:**

---

12/01/2016 BODY / 19: LOOSE / REPAIR  
WHILE CLEANING THE TRUCK THIS MORNING, I NOTED WHAT APPEARS TO BE OVERSPRAY OR RUST ON THE EXTERIOR FINISH OF THE TRUCK. IT DID NOT WASH OFF AND WOULD NOT BUFF OUT WITH TURTLE WAX AND HAND BUFFING. THE VEHICLE HAS BEEN GONE FOR SERVICE AND JUST CAME BACK YESTERDAY AFTERNOON. IT WAS NOT LIKE THIS PRIOR TO LEAVING FOR SERVICING.

12/01/2016 SERVICE REQUEST / 18: LEAKING / REPAIR  
BACK UP CAMERA IS NOT OPERATING.

12/13/2016 SERVICE REQUEST / 19: LOOSE / REPAIR  
REAR BACK UP CAMERA NOT WORKING.

---

**Asset Work Order History 10187974**

**CSHOP-2016-5688**

Comments: **A/C INOP**

Date Opened 12-6-2016 Date Finished 12-6-2016 Meter 1 Reading: 77,453

**TASKS PERFORMED**

**NO PARTS USED**

AIR CONDITIONING

**VENDOR?** AL PACKER

---

**CSHOP-2016-683**

Comments: **TIRE PRESSURE INDICATOR CHANGE OIL LIGHT ON**

Date Opened 2-11-2016 Date Finished 2-11-2016 Meter 1 Reading: 62,946

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM  
FAULT CODE  
TIRES ALL

---

**CSHOP-2016-808**

Comments: **HEADLIGHT OUT**

Date Opened 2-19-2016 Date Finished 2-19-2016 Meter 1 Reading: 63,480

**TASKS PERFORMED**

**Q PARTS**

HEADLIGHTS LOW BEAM

1 BULB; H11-55WLL BULB LOW BEAM 92095787

---

**CSHOP-2016-810**

Comments: **CAP5, PLEASE INSTALL LONG VELCRO STRAPS LOOSELY OVER GEAR BEHIND DRIVER AND PASSENGER SEAT**

Date Opened 2-19-2016 Date Finished 4-5-2016 Meter 1 Reading: 65,626

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
INSTRUMENTS-GAUGES-WARNING &

---

**CSHOP-2017-1151**

Date Opened 2-23-2017 Date Finished 2-23-2017 Meter 1 Reading: 81,617

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**CSHOP-2017-1288**

Date Opened 3-2-2017 Date Finished 4-25-2017 Meter 1 Reading: 84,576

**TASKS PERFORMED**

**Q PARTS**

DIAGNOSE ELECTRICAL

1 BATTERY; BATTERY

---



**Asset Work Order History 10187974**

**CSHOP-2017-2478**

Comments: **QUALITY CHECK**

Date Opened 4-27-2017 Date Finished 4-28-2017 Meter 1 Reading: 84,686

**TASKS PERFORMED**

**Q PARTS**

QUALITY CHECK-REPAIRS  
CHARGING SYSTEM

1 5TN; AUTO CHAGRE 2000  
1 FLUID; MOTOR OIL 3360  
2 1AD; BATTERY 48A

**CSHOP-2017-2490**

Date Opened 4-27-2017 Date Finished 4-27-2017 Meter 1 Reading: 84,651

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY

**VENDOR?** AL PACKER

**CSHOP-2017-3700**

Date Opened 6-22-2017 Date Finished 9-1-2017 Meter 1 Reading: 90,410

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY  
TIRE

**VENDOR?** AL PACKER

**Service Requests:**

06/22/2017 BRAKES / 19: LOOSE / INSPECT  
BRAKE ISSUES: FRONT BRAKES MAKING SQUEALING NOISE

06/22/2017 SERVICE REQUEST / 19: LOOSE / REPAIR  
SERVICE REQUEST: CHANGE OIL SOON MESSAGE ON

**CSHOP-2017-5160**

Date Opened 9-1-2017 Date Finished 9-1-2017 Meter 1 Reading: 89,875

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

**CSHOP-2017-5383**

Date Opened 9-15-2017 Date Finished 9-20-2017 Meter 1 Reading: 91,439

**TASKS PERFORMED**

**Q PARTS**

BATTERY

1 6KU; AUTO CHAGER AC2000 12V  
1 6KU; AUTO CHAGER AC2000 12V  
1 NONSTOCK; FREIGHT CHARGE

**Asset Work Order History 10187974**

**CSHOP-2017-6660**

Date Opened 11-19-2017 Date Finished 11-30-2017 Meter 1 Reading: 94,883

WON'T START

**TASKS PERFORMED**

**NO PARTS USED**

---

FUEL PUMP

---

**CSHOP-2018-1032**

Date Opened 2-20-2018 Date Finished 2-27-2018 Meter 1 Reading: 101,020

**TASKS PERFORMED**

**Q PARTS**

---

CAB-INTERIOR ACCESSORIES

1 1GM; HANDLE  
1 9AP; COVERCRAFT SNAP RING TIRE SAVERS  
1 NONSTOCK; FREIGHT CHARGE  
1 9AP; COVERCRAFT SNAP RING TIRE SAVERS

---

**Service Requests:**

02/19/2018 SERVICE REQUEST / 18: LEAKING / REPAIR  
THE DRIVER'S SEAT BACK RECLINER LEVER IS NOT WORKING, SEEMS STRIPPED. THEREFORE, IT IS NOT POSSIBLE TO ADJUST SEAT BACK OF DRIVER'S SEAT

---

**CSHOP-2018-1249**

Date Opened 3-1-2018 Date Finished 3-1-2018 Meter 1 Reading: 101,237

**TASKS PERFORMED**

**Q PARTS**

---

ALTERNATOR-GENERATOR

1 1AD; ALTERNATOR

---

**CSHOP-2018-1705**

Date Opened 3-26-2018 Date Finished 3-26-2018 Meter 1 Reading: 102,213

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2018-194**

Date Opened 1-9-2018 Date Finished 1-9-2018 Meter 1 Reading: 97,654

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**Asset Work Order History 10187974**

**CSHOP-2018-2366**

Date Opened 4-30-2018 Date Finished 4-30-2018 Meter 1 Reading: 104,022

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2018-2419**

Date Opened 5-2-2018 Date Finished 5-2-2018 Meter 1 Reading: 104,073

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**CSHOP-2018-3126**

Date Opened 6-5-2018 Date Finished 6-6-2018 Meter 1 Reading: 0

**TASKS PERFORMED**

**Q PARTS**

TOWING HITCH

1 9AP; TOW STRAP

---

**CSHOP-2018-4240**

Date Opened 7-30-2018 Date Finished 7-31-2018 Meter 1 Reading: 109,252

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
BATTERY  
DIAGNOSE ELECTRICAL

2 1AD; BATTERY

---

**Service Requests:**

07/30/2018 STARTER / 18: LEAKING / REPAIR  
VEHICLE WILL NOT START WITHOUT BEING PLUGGED IN

---

**CSHOP-2018-4568**

Date Opened 8-15-2018 Date Finished 8-15-2018 Meter 1 Reading: 110,105

**TASKS PERFORMED**

**NO PARTS USED**

TRANSMISSION

---

**CSHOP-2018-4625**

Date Opened 8-16-2018 Date Finished 8-16-2018 Meter 1 Reading: 110,145

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**Asset Work Order History 10187974**

**CSHOP-2018-4756**

Date Opened 8-22-2018 Date Finished 10-3-2018 Meter 1 Reading: 111,770

**TASKS PERFORMED**

**Q PARTS**

---

CRANKING SYSTEM

1 6KU; AC2000 12V PLC TEN8  
2 1AD; BATTERY

---

**CSHOP-2018-4873**

Date Opened 8-27-2018 Date Finished 8-27-2018 Meter 1 Reading: 110,156

**TASKS PERFORMED**

**NO PARTS USED**

---

TRANSMISSION

**VENDOR?** AL PACKER

---

**CSHOP-2018-4916**

Date Opened 8-29-2018 Date Finished 8-29-2018 Meter 1 Reading: 110,156

**TASKS PERFORMED**

**NO PARTS USED**

---

SHIFTER CONTROLS-SELECTOR

**VENDOR?** AL PACKER

---

**CSHOP-2018-6387**

Date Opened 11-9-2018 Date Finished 11-10-2018 Meter 1 Reading: 0

**TASKS PERFORMED**

**Q PARTS**

---

REPAIR FROM PM - DECALS/CLEANLINESS

1 9AP; DECALS

---

**CSHOP-2018-7021**

Date Opened 12-10-2018 Date Finished 1-8-2019 Meter 1 Reading: 116,477

**TASKS PERFORMED**

**Q PARTS**

---

HEADLIGHTS HIGH BEAM

-1 LMP; LAMP  
1 LMP; LAMP  
1 LMP; HALOGEN BULB

---

**CSHOP-2019-1093**

Date Opened 2-27-2019 Date Finished 2-27-2019 Meter 1 Reading: 116,905

**TASKS PERFORMED**

**NO PARTS USED**

---

STEERING

**VENDOR?** AL PACKER

---

**Asset Work Order History 10187974**

**CSHOP-2019-1516**

Comments: **FRIDGE POWER CORD NOT HOOKED UP**

Date Opened 3-22-2019 Date Finished 3-22-2019 Meter 1 Reading: 116,905

**TASKS PERFORMED**

**NO PARTS USED**

CAB-INTERIOR ACCESSORIES

---

**CSHOP-2019-156**

Comments: **AT PACKER RIGHT NOW FOR REPAIRS / THEY WILL PM IT WHILE IT`S THERE**

Date Opened 1-9-2019 Date Finished 1-22-2019 Meter 1 Reading: 116,484

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**CSHOP-2019-4156**

Comments: **MOVE SCBA BRKTS & 2 MORE MOUNTING STRAPS**

Date Opened 8-7-2019 Date Finished 8-12-2019 Meter 1 Reading: 118,746

**TASKS PERFORMED**

**Q PARTS**

FIRE FIGHTING EQUIPMENT

3 6ZA; STRAP2544  
1 MMM; TAPE

---

**CSHOP-2019-4307**

Date Opened 8-15-2019 Date Finished 8-15-2019 Meter 1 Reading: 118,273

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**SSHOP-2019-286**

Date Opened 9-9-2019 Date Finished 10-24-2019 Meter 1 Reading: 119,127

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?** AL PACKER

---