# WorkOrder

55345 Palm Tran Connection
v 2.2


**WorkOrder: 51066726**
**Invoice Number:** 55345-51066726

**Client Department:**

| | | | |
|---|---|---|---|
| **MRC:** | 55345M | **Equipment:** | 5419 |
| WO Desc: | | | Ford E350 Champion Crusaders |
| PM A | | **VIN:** | 1FDEE3FL5FDA06822 |
| **Requested By:** | CVERGARA | **Status:** | 40 |
| **Created By:** | CVERGARA | **Priority:** | 1 |
| **Class:** | WO | **Driver:** | |
| **Arrangement:** | Unassigned | **Phone:** | |
| **Potential Warranty:** | No | **ETA:** | |

| Chronology | | |
|---|---|---|
| **Reported** | Mar 22, 2018 | 10:04 AM |
| **Started** | Mar 22, 2018 | |
| **Completed** | Mar 22, 2018 | 10:56 PM |
| **Down Time** | | |

| Meter | Reading | UOM |
|---|---|---|
| WO | | DH |
| Life | 191,229 | DH |
| System | 191,404 | DH |

**WorkOrder Notes**

| Line | Comment |
|---|---|
| 10 | COMPLAINT:pmA<br><br>CAUSE:Service<br><br>CORRECTION:Perform pmA Service<br>Oil filter B329 qty1<br>Engine oil 5w20 qty7 Qts<br>Air filter PA4075 qty1 |

**Activity: 10** **999 TOTAL VEHICLE**

**Activity Note:** Light Medium Duty PMI
**Reason for Repair:** 08 - Preventive Maintenance
**Work Accomplished:** 06 - Inspect
**Part Failure:** -

**Activity Comments**

## Parts Issued

| Date | Part Number | | Description | Qty. | Each | Extended |
|---|---|---|---|---|---|---|

## Labor Posted

| Date | Technician | Hours | Rate | Extended |
|---|---|---|---|---|
| 22-Mar-18 | Gaspard,Ronald | 1.50 | 0.00 | 0.00 |

**Activity 10 Sub Total**

| | |
|---|---|
| Parts: | 0.00 |
| Labor: | 0.00 |
| Labor Hours: 1.50 | |
| Sublet Parts: | 0.00 |
| Sublet Labor: | 0.00 |
| **Activity Sub Total** | **0.00** |

**Activity: 20** **999 TOTAL VEHICLE**

**Activity Note:** PM A
**Reason for Repair:** 08 - Preventive Maintenance
**Work Accomplished:** A - PM Level A
**Part Failure:** -

**Activity Comments**

## Parts Issued

**WorkOrder: 51066726**
**Invoice Number:** 55345-51066726

**Client Department:**

| | | | |
|---|---|---|---|
| **MRC:** | 55345M | **Equipment:** | 5419 |
| WO Desc: | | | Ford E350 Champion Crusaders |
| PM A | | **VIN:** | 1FDEE3FL5FDA06822 |
| **Requested By:** | CVERGARA | **Status:** | 40 |
| **Created By:** | CVERGARA | **Priority:** | 1 |
| **Class:** | WO | **Driver:** | |
| **Arrangement:** | Unassigned | **Phone:** | |
| **Potential Warranty:** | No | **ETA:** | |

| Date | Part Number | | Description | Qty. | Each | Extended |
|---|---|---|---|---|---|---|
| 22-Mar-18 | PA4075 | | FILTER, AIR, PAPER SAME AS AF25590 | 1.00 | 5.27 | 5.27 |
| 22-Mar-18 | B329 | | FILTER, OIL (USE FGA0000399/FSC0000399) | 1.00 | 1.96 | 1.96 |

## Labor Posted

| Date | Technician | Hours | Rate | Extended |
|---|---|---|---|---|
| 22-Mar-18 | Gaspard,Ronald | 1.00 | 0.00 | 0.00 |

**Activity 20 Sub Total**

| | |
|---|---|
| Parts: | 7.23 |
| Labor: | 0.00 |
| Labor Hours: 1.00 | |
| Sublet Parts: | 0.00 |
| Sublet Labor: | 0.00 |
| **Activity Sub Total** | **7.23** |

**Activity: 30** **999 TOTAL VEHICLE**

| | |
|---|---|
| **Activity Note:** | PRAMETER |
| **Reason for Repair:** | 05 - Inspection, Routine |
| **Work Accomplished:** | 06 - Inspect |
| **Part Failure:** | - |

**Activity Comments**

## Parts Issued

| Date | Part Number | | Description | Qty. | Each | Extended |
|---|---|---|---|---|---|---|

## Labor Posted

| Date | Technician | Hours | Rate | Extended |
|---|---|---|---|---|
| 22-Mar-18 | Gaspard,Ronald | 0.20 | 0.00 | 0.00 |

**Activity 30 Sub Total**

| | |
|---|---|
| Parts: | 0.00 |
| Labor: | 0.00 |
| Labor Hours: 0.20 | |
| Sublet Parts: | 0.00 |
| Sublet Labor: | 0.00 |
| **Activity Sub Total** | **0.00** |

**WorkOrder 51066726 Grand Total**

| | |
|---|---|
| Parts: | 7.23 |
| Labor: | 0.00 |
| Labor Hours: 2.70 | |
| Sublet Parts: | 0.00 |
| Sublet Labor: | 0.00 |
| **WorkOrder Grand Total** | **7.23** |

# WorkOrder

55345 Palm Tran Connection
v 2.2


**WorkOrder: 51066726**
**Invoice Number:** 55345-51066726

**Client Department:**

| | | | |
|---|---|---|---|
| **MRC:** | 55345M | **Equipment:** | 5419 |
| WO Desc: | | | Ford E350 Champion Crusaders |
| PM A | | **VIN:** | 1FDEE3FL5FDA06822 |
| **Requested By:** | CVERGARA | **Status:** | 40 |
| **Created By:** | CVERGARA | **Priority:** | 1 |
| **Class:** | WO | **Driver:** | |
| **Arrangement:** | Unassigned | **Phone:** | |
| **Potential Warranty:** | No | **ETA:** | |

## Recent Repair History

| WorkOrder | Date Completed | Life Meter | Class | Description |
|---|---|---|---|---|
| 51423052 | 6-Jul-18 | 209,517 | WO | PM A |
| 51422692 | 12-Jun-18 | 205,370 | WO | PM A |
| 51352860 | 12-Jun-18 | 199,899 | WO | PM C |
| 51116958 | 17-May-18 | 195,067 | WO | PM A |
| 51066726 | 22-Mar-18 | 191,229 | WO | PM A |
| 51021142 | 28-Feb-18 | 187,251 | WO | PM B |

## Scheduled Preventative Maintenance

| Nest | PM | WorkOrder | Due Date | Due Life Meter | Due Meter Reading | Due Life Meter 2 | Due Meter Reading 2 |
|---|---|---|---|---|---|---|---|

## Other Open Repairs

| WorkOrder8 | Date Reported | Life Meter | Class | Description |
|---|---|---|---|---|
| 51484883 | 5-Jul-18 | 209,517 | WO | Rear Tire& Exhaust Hanger |
| 51352804 | 16-May-18 | 195,067 | WO | FOLLOWUP- ¿replace rear brakes |

**PH: Work Order: 51066726 Desc: PM A**
**Equip: 5419 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL5FDA06822**

**LH: 10 Desc: Light Medium Duty PMI**
**Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-MAR-18**

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| 10,000 | SECTION 1 Preparation and Drive On (In Lot) Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,100 | Safety Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,110 | FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,120 | FRA Check All Warning Lights and Alarms | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,130 | FRA Check Automatic Transmission Neutral Start Operation | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,140 | Check Service Brakes | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,150 | FRA Start Engine and Listen for Any Unusual Noises | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,160 | FRA Check Instruments and Horns | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,170 | Check Fast Idle | Done | | RGASPARD | Mar 22, 2018 9:51:04 PM | No | |
| 10,180 | Check Starter Protection Circuit | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 10,190 | Check Reverse Warning System | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,100 | Check Parking Brake | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,110 | Check HVAC Switches and Other Controls | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,120 | FRA Inspect Windshields, Mirror and Sun Visor Condition | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,130 | FRA Check Wiper and Washer Operation | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,140 | Road Test: Check for Proper Operation | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,150 | Perform Brake Test | Done | | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,152 | Decelerometer Results Test 1 | FEET | na | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,154 | Decelerometer Results Test 2 | FEET | na | RGASPARD | Mar 22, 2018 9:51:05 PM | No | |
| 11,156 | Decelerometer Results Test 3 | FEET | na | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 11,161 | FRA Check/Record Oil Pressure / @1500 rpm | Pounds per Square Inch | na | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 11,162 | FRA Check/Record Water Temperature | Degree Fahrenheit | na | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 11,170 | FRA Check Door Operation | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 11,180 | FRA Check Operation of All Other Accessories | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,000 | SECTION 2 Interior Circle Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| 20,210 | Check Condition of Operator's Area | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,220 | Check Accelerator and Brake Pedals | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,230 | FRA Check Wiring Under Dash | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,240 | FRA Check Interior Lights | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,250 | FRA Check Interior Electrical Panels | Done | | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,260 | Check Stop Request System | - | na | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,270 | Check Fare Box Mounting (If Applicable) | - | na | RGASPARD | Mar 22, 2018 9:51:06 PM | No | |
| 20,280 | Check Seats, Seat Belts, Hand Rails and Floor Covering | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 20,290 | Check for Physical Damage, Water Leaks, and Graffiti | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 22,100 | Check Emergency Windows and Glass Condition | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 22,110 | Check Emergency Hatches | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 22,120 | Check All Safety Equipment | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,000 | SECTION 3 Exterior Circle Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,310 | Check Passenger Doors | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,320 | Inspect Step-well and Hand Rails | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,330 | Check Wheelchair Lift Operation | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,340 | FRA Check Destination Sign and Run Box | - | na | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,350 | FRA Inspect Mirror and Mountings | Done | | RGASPARD | Mar 22, 2018 9:51:07 PM | No | |
| 30,360 | Check for Physical Damage and Decals | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 30,370 | Check Wiper Blade and Arm Condition | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 30,380 | Check Exterior Compartment Doors | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 30,390 | FRA Check Fuel Tank Cap | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 33,100 | Check Lights and Reflectors | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 33,110 | Check License Plate, Permits and State Inspection Decals | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 40,000 | SECTION 4 Engine Compartment Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 40,410 | FRA Check Engine Compartment/Condition for Fire Risk | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 40,420 | Check Hood | Done | | RGASPARD | Mar 22, 2018 9:51:08 PM | No | |
| 40,430 | Check Fan, Shroud and Radiator | Done | | RGASPARD | Mar 22, 2018 | No | |

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| | | | | | 9:51:09 PM | | |
| 40,440 | Test Coolant System Using Test Strips and Record Results | - | na | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,441 | Inhibitor Test Pass or Fail (Indicate with a Yes or No) | No | na | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,442 | Freeze Point | Degree Fahrenheit | na | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,450 | FRA Check Coolant Recovery System Condition & for Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,460 | Record Antifreeze Protection Level Using Refractometer | - | na | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,461 | Refractometer Reading | Degree Fahrenheit | na | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,470 | Pressure Test Cooling System and Check for Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,480 | FRA Check Coolant Hose Condition | Done | | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 40,490 | FRA Check Alternator Mount and Condition | Done | | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 44,100 | FRA Check Fuel Control and Transmission Connections | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,110 | FRA Check Master Cylinder Fluid Level | Done | | RGASPARD | Mar 22, 2018 9:51:09 PM | No | |
| 44,120 | FRA Check All Belts for Condition, Alignment and Tension | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,130 | FRA Check Exhaust System | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,140 | FRA Check Intake System | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,150 | FRA Inspect Turbocharger | - | na | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,160 | FRA Inspect Power Steering and Hydraulic Fluid | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,170 | FRA Check All Engine or Belt Driven Components | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,180 | FRA Check for Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,190 | FRA Perform Battery Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:10 PM | No | |
| 44,200 | FRA Check Battery Box Corrosion, Cables and Hold-Downs | Done | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 50,000 | SECTION 5  Steering System Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 50,510 | Check Entire Steering System | Done | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,000 | SECTION 6  Tires and Wheel Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,610 | FRA Check and Record Air Pressure | Done | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,611 | Air Pressure RF | 70 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,612 | Air Pressure LF | 70 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,613 | Air Pressure RRO | 65 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| 60,614 | Air Pressure RRI | 65 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,615 | Air Pressure LRI | 65 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:11 PM | No | |
| 60,616 | Air Pressure LRO | 65 Pounds per Square Inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,620 | Check Valve Stems and Caps | Done | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,630 | Check and Record Tread Depth | Done | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,631 | Tread Depth RF | 7 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,632 | Tread Depth LF | 8 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,633 | Tread Depth RRO | 6 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,634 | Tread Depth RRI | 7 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,635 | Tread Depth LRI | 7 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,636 | Tread Depth LRO | 7 32nds of an inch | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,640 | Check for Mismatched Tread or Casing Design | Done | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,650 | Check Sidewall Wear | Done | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,660 | Inspect for Cuts and Tears | Done | | RGASPARD | Mar 22, 2018 9:51:12 PM | No | |
| 60,670 | Check Dual Mating With Square | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 60,680 | Check Wheels for Cracks and Loose Lugs | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 60,690 | Check Tires for Irregular or Alignment Wear | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 66,100 | FRA Check Outer Hubs for Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,000 | SECTION 7 Under Vehicle Inspection | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,710 | Check Vibration Damper | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,720 | Check Engine and Transmission Mounts | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,730 | FRA Check Starter | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,740 | FRA Check Bottom of Engine for Fluid Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,750 | FRA Check Transmission for Leaks | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,760 | FRA Check Differential Breather and Fluid | Done | | RGASPARD | Mar 22, 2018 9:51:13 PM | No | |
| 70,770 | FRA Check Exhaust System | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 70,780 | Check Driveline, U-joint and Slip Yokes | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 70,790 | Check All Body Mounts and Chassis Frame | Done | | RGASPARD | Mar 22, 2018 | No | |

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| | | | | | 9:51:14 PM | | |
| 77,100 | FRA Check Security, Integrity and Length of Ground Straps | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,110 | FRA Check Fuel Tank | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,120 | Check Suspension Components | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,130 | FRA Check Brake Pad Thickness and Rotor for Wear | Done | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,131 | Brake Pad Thickness LF | 6 Inch | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,132 | Brake Pad Thickness RF | 6 Inch | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,133 | Brake Pad Thickness LR | 7 Inch | | RGASPARD | Mar 22, 2018 9:51:14 PM | No | |
| 77,134 | Brake Pad Thickness RR | 7 Inch | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,135 | Brake Rotor LF | 38 Inch | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,136 | Brake Rotor RF | 38 Inch | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,137 | Brake Rotor LR | 36 Inch | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,138 | Brake Rotor RR | 36 Inch | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,140 | FRA Check Brake Hoses | Done | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,150 | Check King Pins | - | na | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 77,160 | FRA Check for Loose or Noisy Wheel Bearings | Done | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 80,000 | SECTION 8 PMI Report Completion | Done | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 80,810 | Completion of PMI Report | Done | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 90,000 | SECTION 9 Completion of PMI | Done | | RGASPARD | Mar 22, 2018 9:51:15 PM | No | |
| 90,910 | Vehicle Returned to predetermined location | Done | | RGASPARD | Mar 22, 2018 9:51:16 PM | No | |

**LH: 20 Desc: PM A**
**Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-MAR-18**

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| 100,000 | "A" PMI SERVICING ITEMS | Done | | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 101,000 | FRA Change Oil Filters | Yes | | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 102,000 | FRA Drain Engine Oil | Yes | | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 103,000 | FRA Check Transmission Fluid | Done | | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 104,000 | Lubricate Chassis | - | na | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 105,000 | Replace or Clean A/C Filters | Done | | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 107,000 | FRA Change Primary Fuel Filter | No | na | RGASPARD | Mar 22, 2018 9:52:04 PM | No | |
| 108,000 | Lube all pivoting Mechanisms | Done | | RGASPARD | Mar 22, 2018 9:52:05 PM | No | |

**LH: 30 Desc: PRAMETER**

## Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-MAR-18

| Line | Inspection | RESULTS | Notes | Performed By | Date Inspected | Follow Up | Follow Up WO |
|---|---|---|---|---|---|---|---|
| 10 | Have you successfully completed the Personal Risk Assessment? | Done | | RGASPARD | Mar 22, 2018 9:52:33 PM | No | |
| 20 | Miles | | | | | No | |
| 30 | Kilometers | | | | | No | |
| 40 | Hours | | | | | No | |