WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51423052
Invoice Number: 55345-51423052

Client Department:			
MRC:	55345M	**Equipment:**	5419
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL5FDA06822
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 5, 2018	10:44 AM
Started	Jul 5, 2018	
Completed	Jul 6, 2018	12:05 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,517	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage CORRECTION:. Change Oil & Filter. Lube all Pivoting Points .clean Batteries .check brakes .replace A/C Filter. Parts# B329 Qty (1) Oil5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jul-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
05-Jul-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder: 51423052
Invoice Number: 55345-51423052

Client Department:

MRC:	55345M	**Equipment:**	5419
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL5FDA06822
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jul-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note:	PRAMETER
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	06 - Inspect
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jul-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51423052 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51423052	6-Jul-18	209,517	WO	PM A
51484883	6-Jul-18	209,517	WO	Rear Tire& Exhaust Hanger

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51423052
Invoice Number: 55345-51423052

Client Department:

MRC:	55345M	**Equipment:**	5419
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL5FDA06822
Requested By:	DCARTER	**Status:**	40
Created By:	DCARTER	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51422692	12-Jun-18	205,370	WO	PM A
51352860	12-Jun-18	199,899	WO	PM C

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51484883	5-Jul-18	209,517	WO	Rear Tire& Exhaust Hanger
51352804	16-May-18	195,067	WO	FOLLOWUP- ¿replace rear brakes

PH: Work Order: 51423052 Desc: PM A
Equip: 5419 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL5FDA06822

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 05-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 5, 2018 11:41:38 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 5, 2018 11:41:38 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jul 5, 2018 11:41:39 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 5, 2018 11:41:41 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 5, 2018 11:41:41 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 5, 2018 11:41:40 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 5, 2018 11:41:41 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 5, 2018 11:41:41 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jul 5, 2018 11:41:41 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 5, 2018 11:41:41 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 5, 2018 11:41:41 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jul 5, 2018 11:41:41 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 5, 2018 11:41:41 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jul 5, 2018 11:41:42 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 5, 2018 11:41:43 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
40,420	Check Hood	Done		DARTHURS	Jul 5, 2018 11:41:44 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 5, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:41:45 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 5, 2018 11:41:45 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 5, 2018 11:41:45 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 5, 2018 11:41:45 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 5, 2018 11:41:46 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 5, 2018 11:41:46 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 5, 2018 11:41:46 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jul 5, 2018 11:41:47 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:48 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:48 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,631	Tread Depth RF	9 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:49 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,633	Tread Depth RRO	2 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,634	Tread Depth RRI	2 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,635	Tread Depth LRI	2 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,636	Tread Depth LRO	2 32nds of an inch		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jul 5, 2018 11:41:50 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jul 5, 2018 11:41:51 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 5, 2018 11:41:51 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 5, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:41:52 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		DARTHURS	Jul 5, 2018 11:41:52 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,135	Brake Rotor LF	1.553 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,136	Brake Rotor RF	1.554 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,137	Brake Rotor LR	1.415 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,138	Brake Rotor RR	1.414 Inch		DARTHURS	Jul 5, 2018 11:41:53 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jul 5, 2018 11:41:54 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jul 5, 2018 11:41:54 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 05-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 5, 2018 11:42:46 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jul 5, 2018 11:42:46 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jul 5, 2018 11:42:46 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jul 5, 2018 11:42:46 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jul 5, 2018 11:42:47 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jul 5, 2018 11:42:47 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 5, 2018 11:42:47 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jul 5, 2018 11:42:47 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 5, 2018 11:43:13 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	