



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V13059

In Date: 02/05/2008 Meter Reading: 118.00
Close Date: 02/05/2008

Problem?
TINT FRONT WINDOWS DC-5

Task performed:	Parts	Quantity
tint front windows DC5 - 60 Minute Auto Tin j	NO PARTS USED	

Vendor?: 60 MINUTE AUTO

Workorder: V14117

In Date: 03/26/2008 Meter Reading: 118.00
Close Date: 03/31/2008

Problem?
Install Auto eject and battery Charger

Task performed:	Parts	Quantity
1. wire up and install charger syst. wire up and install cold cathode light.	091-20WP-120AUTO EJECT	1
	0913912CHARGER 2000	1
	KR-CCLCATHODE COMPARTMENT LIGHT	2

Workorder: V14336

In Date: 04/07/2008 Meter Reading: 458.00
Close Date: 04/10/2008

Problem?
repair battery charger ems 7

Task performed:	Parts	Quantity
1.battery charger inoperable,fuseblown,installed new fuse and tested ok now.	NO PARTS USED	

Workorder: V14319

In Date: 04/07/2008 Meter Reading:
Close Date: 04/11/2008

Problem?
Vehicle will not start. This happened last night as well. The charging system shows 1 bar on each side only, so I believe the shoreline is not keeping the battery charged. dc5

Task performed:	Parts	Quantity
1. vehicle hard to start. found no problem w/ charger. hard starting due to fuel delivery problem	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V14902

In Date: 05/06/2008

Meter Reading: 858.00

Close Date: 05/12/2008

Problem?

install proximaty alarm dc5 istall floor mats

Task performed:

install forewarn sys; wire up unit; install floor mats. j

Parts	Quantity
19166591FLOOR MAT	1
19166603FLOOR MATS REAR	1
20-425HITCH PIN	1
PSOPD1013USE PD2343 BACK-UP RADAR	1

Workorder: V15928

In Date: 06/23/2008

Meter Reading: 1,288.00

Close Date: 07/10/2008

Problem?

INSTALL EQUIPMENT NEW VEHICLE SET UP DC-5

Task performed:

1. Setup new vehicle.
2. Setup new vehicle.
3. Setup new DC; install box; wire u unit; install TIC charger; install SCBA brkt. j

Parts	Quantity
5025TERMINAL BOX	1

Workorder: V16442

In Date: 07/18/2008

Meter Reading: 1,794.00

Close Date: 07/23/2008

Problem?

repair fuse block roger dean

Task performed:

Repair fuse block - Roger Dean j

Parts	Quantity
NO PARTS USED	

Vendor?: ROGER DEAN

Workorder: V16395

In Date: 07/16/2008

Meter Reading:

Close Date: 07/29/2008

Problem?

Service Airbag message is displayed in the dashboard message center. DC5

Task performed:

1. sent to roger dean for repair.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V17042

In Date: 08/14/2008
Close Date: 08/25/2008

Meter Reading: 2,925.00

Problem?

WILL NOT START DC-5

Task performed:

1. installed new battery and checked battery charger

Parts

Quantity

65-72BXT65750 BATTERY

1

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

1

Workorder: V17346

In Date: 08/27/2008
Close Date: 09/29/2008

Meter Reading:

Problem?

Front A/C not working properly. Blows hot air. dc5

Task performed:

WARRANTY

Parts

Quantity

NO PARTS USED

Sent to Roger Dean for repair. j

Workorder: V17854

In Date: 09/22/2008
Close Date: 09/30/2008

Meter Reading: 4,280.00

Problem?

light bar 10-7 dc5

Task performed:

trace problem with light bar 10-7 repair connection in console

Parts

Quantity

NO PARTS USED

Workorder: V17977

In Date: 09/27/2008
Close Date: 10/07/2008

Meter Reading: 4,636.00

Problem?

INSTALL NETTING DC5

Task performed:

1- installed netting for breathing bottles

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V19162

In Date: 11/18/2008
Close Date: 01/07/2009

Meter Reading: 7,572.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC5

Task performed:

1. Test drive, B-Inspection; change oil/filter; replc air filter.
2. install LED light to brush bar.
3. Install "rubber" sys.
4. Jump start brtry; figure problem w/wrong btrys/cables for second brtry.
5. Run starter cable & rem wrg btry & charge btry.
6. Travel to Muffler shop for tail pipe fabrication & back.
7. Cut off tail pipe & install new fabricated pipe & cut to length.
8. Rem rear seat & radio equipmt.
9. Install cables, btrys & holddowns. j

Parts	Quantity
371104371104 SWITCH ROCKER MOM.	1
42487USE CA8756 AIR FILTER	1
48-60BATTERY	2
57060OIL FILTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V20524

In Date: 01/22/2009
Close Date: 02/06/2009

Meter Reading: 1.00

Problem?

INSTALL PARTION BEHIND FRONT SEAT, INSTALL FLOOR. DC-5

Task performed:

- Reinstall (1) seat in rear of truck; fab floor pan plate; mnt in truck; move radio head & wiring. j

Parts	Quantity
NO PARTS USED	

Workorder: V19163

In Date: 11/18/2008
Close Date: 03/06/2009

Meter Reading:

Problem?

INSTALL WHITE STROBE LIGHTS ON THE SIDE OF THE CHROME GRILL WHICH IS ON THE FRONT OF THE VEHICLE. DC

Task performed:

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V22840

In Date: 04/28/2009

Meter Reading: 11,190.00

Close Date: 05/05/2009

Problem?

REPLACE NETTING, DC,5

Task performed:

Replc d netting in rear of truck. j

Parts

Quantity

NO PARTS USED

Workorder: V24070

In Date: 06/15/2009

Meter Reading: 13,581.00

Close Date: 06/19/2009

Problem?

ON CALL NO EME LTS DC5

Task performed:

No lights on radio or laptop; power all out; replc (2) fuese 40AMP & 40 AMP max. j

Parts

Quantity

NO PARTS USED

Workorder: V24161

In Date: 06/17/2009

Meter Reading: 13,748.00

Close Date: 06/22/2009

Problem?

B inspection and repairs D/C5 (al packer ford)

Task performed:

B-Inspection/repairs D/C5 - Al Packer Ford j

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V23863

In Date: 06/05/2009

Meter Reading: 12,011.00

Close Date: 06/23/2009

Problem?

REPLACE BATTERY, CHECK SHORE CHARGER, DC-5

Task performed:

Went to Stn57; fnd DC5 completely dead; tried charging btry & cld not save; change btry - shore charger also inop; did not have part. j

Parts

Quantity

65-72BXT65750 BATTERY

1

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V23899

In Date: 06/08/2009

Meter Reading: 13,149.00

Close Date: 06/23/2009

Problem?

DC 5 BATTER CHARGER 10-7

Task performed:

Parts

Quantity

Duplicate ticket (see W/O 23863) j

NO PARTS USED

Workorder: V24753

In Date: 07/13/2009

Meter Reading: 14,590.00

Close Date: 07/28/2009

Problem?

We need two rechargeable flashlights hardwired in DC5 and BC5 vehicles.

Task performed:

Parts

Quantity

Lights will be installed at shop on B-Inspection. j

NO PARTS USED

Workorder: V25360

In Date: 08/06/2009

Meter Reading:

Close Date: 08/27/2009

Problem?

Install dry chem extinguisher on DC 5 vehicle.

Task performed:

Parts

Quantity

Installed dry chem extinguisher. j

NO PARTS USED

Workorder: V25469

In Date: 08/12/2009

Meter Reading: 15,737.00

Close Date: 09/11/2009

Problem?

A/C VENTS BROKEN DC5

Task performed:

Parts

Quantity

1. Replcd A/C vents.
2. Rear extension off; rep brkt. j

15217394A/C VENT

4



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V26570

In Date: 09/30/2009

Meter Reading:

Close Date: 11/06/2009

Problem?

excessive wear noted on rt front tire dc5

Task performed:

Parts

Quantity

R/F tire worn; installed spare. j

NO PARTS USED

Chkd tires & chkd ok. j

Workorder: V26768

In Date: 10/08/2009

Meter Reading: 17,479.00

Close Date: 11/16/2009

Problem?

alignment D/C5 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Alignment DC5 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V26769

In Date: 10/08/2009

Meter Reading: 17,479.00

Close Date: 11/16/2009

Problem?

replace all 4 tires D/C 5 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Replace all (4) tires DC5 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V27973

In Date: 11/29/2009

Meter Reading: 19,904.00

Close Date: 12/07/2009

Problem?

need to call DC5 about this

Task performed:

Parts

Quantity

See W/O 27974 j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V27089

In Date: 10/22/2009

Meter Reading:

Close Date: 12/09/2009

Problem?

After DC 5 vehicle was washed, water was dripping from the inside upper doom light above computer. Water may have come through the large circular Millennium antenna on top of vehicle.

Task performed:

resealed top roof at GPS lap. j

Parts

NO PARTS USED

Quantity

Workorder: V27983

In Date: 11/29/2009

Meter Reading: 19,904.00

Close Date: 01/11/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC5

Task performed:

- B-INSPECTION
- 2. REPLC WIPER BLADES.
- 3. REP AUTO-EJECT-LOOSE WIRES; ___ BUILD; REP SOCKET.
- 4. REP BACKUP ALARM; LOOSE FUSE. J

Parts

15W40BSYN OIL BULK QTS 6
 25877402WIPER BLADES NEW GM 22 IN 2
 516TIRE INFLATOR 1
 57060OIL FILTER 1
 CA875642487 FILTER AIR 1
 S448GAUGE TIRE TREAD DEPTH 1
 S777COUPLING NIPPLE 1

Quantity

Workorder: V27974

In Date: 11/29/2009

Meter Reading:

Close Date: 01/13/2010

Problem?

Auto ejector on shoreline does not work. DC5

Task performed:

Shoreline inop; rewired btrys & tested. j

Parts

NO PARTS USED

Quantity

Workorder: V27719

In Date: 11/16/2009

Meter Reading:

Close Date: 01/14/2010

Problem?

Rear backup warning not working. Rear shoreline connector working intermittently. DC5 at 57

Task performed:

Rear Shoreline inop; rep connection on btry charger. j

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V30974

In Date: 03/23/2010
Close Date: 04/22/2010

Meter Reading: 9,470.70

Problem?

replace 1 tire at sta 57 (outside agency-boulevard tire)

Task performed:

replc (1) tire at Stn57 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V31733

In Date: 04/23/2010
Close Date: 04/27/2010

Meter Reading: 25,588.00

Problem?

air bag warning light on DC5

Task performed:

Rep under WARRANTY on R.O 31743 j

Parts

Quantity

NO PARTS USED

Workorder: V31828

In Date: 04/27/2010
Close Date: 05/06/2010

Meter Reading: 25,588.00

Problem?

A inspection D/C 5

Task performed:

A-Inspection; air R/R tire. j

Parts

Quantity

NO PARTS USED

Workorder: V31743

In Date: 04/23/2010
Close Date: 05/12/2010

Meter Reading: 26,285.00

Problem?

B inspection and repairs DC5 (outside agency-schumacher buick)

Task performed:

B-Inspection/repairs DC5 - Schumacher Buick j

Parts

Quantity

NO PARTS USED

Vendor?: SCHUMACHER BUICK



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V34049

In Date: 08/05/2010
Close Date: 09/09/2010

Meter Reading: 29,601.00

Problem?

DC5 vehicle: 2 out of 3 12v power ports are 10-7 in center console. Both rear hatch florescent lights over command board 10-7/both work when shoreline is plugged in. Interior cab lights do not work when door is opened.

Task performed:

rep 12V lights in rear & rep power ports. j

Parts

NO PARTS USED

Quantity

Workorder: V34551

In Date: 08/26/2010
Close Date: 09/29/2010

Meter Reading: 30,422.00

Problem?

Every time the vehicle is started the MDC losses the wireless connection. Then it has to re-establish the connection before it start working.

Task performed:

Replc btrys that were bad. j

Parts

48-60BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

2

Workorder: V35097

In Date: 09/21/2010
Close Date: 10/01/2010

Meter Reading: 30,422.00

Problem?

REPLACE TIRES CALLAGHAN

Task performed:

Replc tires - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V35098

In Date: 09/21/2010
Close Date: 10/01/2010

Meter Reading: 30,422.00

Problem?

FRONT END ALIGNMENT DC 5 CALLAGHAN

Task performed:

Front end alignment DC5 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V35021

In Date: 09/17/2010

Meter Reading: 30,422.00

Close Date: 10/06/2010

Problem?

B inspection and repairs (outside agency-schumacher)

Task performed:

Parts

Quantity

B-Inspection/repairs - Schumacher j

NO PARTS USED

Vendor?: SCHUMACHER

Workorder: V34213

In Date: 08/12/2010

Meter Reading: 30,020.00

Close Date: 10/20/2010

Problem?

DC5 TIC spare battery charger 10-7.

Task performed:

Parts

Quantity

Rep power wire on charger. j

NO PARTS USED

Workorder: V34993

In Date: 09/16/2010

Meter Reading: 30,422.00

Close Date: 12/22/2010

Problem?

right front tire needs down to wear bars

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V36140

In Date: 11/02/2010

Meter Reading: 33,126.00

Close Date: 12/27/2010

Problem?

2 of the 3 cigarette lighter outlets on the console do not work. DC5

Task performed:

Parts

Quantity

(1) TRAVELED TO ST57 TO REPAIR CIGARETTE LIGHTER OUTLETS IN DC5 VEHICLE. REPLACED FUSES ON REAR OUTLETS. OK. J.W.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V36945

In Date: 12/06/2010
Close Date: 02/07/2011

Meter Reading: 34,267.00

Problem?

Leak sensor/valve stem was damaged during tire change. Tech placed new stem on. Need leak sensor/transmitter re-installed. DC

Task performed:

Unit was reprogrammed & light went out on air sys.
j

Parts

Quantity

NO PARTS USED

Workorder: V36846

In Date: 12/03/2010
Close Date: 02/16/2011

Meter Reading: 34,267.00

Problem?

Tire flat at sta 55

Task performed:

Flat tire Stn55 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V38367

In Date: 02/08/2011
Close Date: 02/24/2011

Meter Reading: 36,572.00

Problem?

TIC spare battery light not coming on when battery is placed in the holder. Charging battery ? D/C5

Task performed:

Fnd uit charging btry at this time. j

Parts

Quantity

NO PARTS USED

Workorder: V38508

In Date: 02/14/2011
Close Date: 02/24/2011

Meter Reading: 37,077.00

Problem?

Check engine light came on again. Tom was here in am and looked at and went away. Later in day came back on. dc5

Task performed:

Truck will need to go to GMC. j

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V38648

In Date: 02/20/2011
Close Date: 03/07/2011

Meter Reading: 37,301.00

Problem?

change engine oil light is on. Oil checked and @ 3/4. also the Low tire sensor light has been on for awhile needs to be fixed. sta 5

Task performed:

Need to go to dealer for svc. j

Parts

Quantity

NO PARTS USED

Workorder: V38556

In Date: 02/16/2011
Close Date: 03/09/2011

Meter Reading: 37,077.00

Problem?

Check engine light is on. Vehicle working fine. Sta 57

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V38741

In Date: 02/23/2011
Close Date: 03/09/2011

Meter Reading: 37,301.00

Problem?

Pulls to left. dc5

Task performed:

Replc rear LED light & tested. j

Parts

Quantity

60R00XRRBRAKE/TAILLIGHT LED

2

Workorder: V39346

In Date: 03/21/2011
Close Date: 03/21/2011

Meter Reading: 38,537.00

Problem?

loss of all emergency lite's and siren, DC-5

Task performed:

1. check lite and siren, found blown 40 amp fuse, r&r fuse

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V38892

In Date: 03/01/2011 Meter Reading: 37,741.00

Close Date: 03/23/2011

Problem?

B INSPECTION DC5 (outside agency-Oil Change Services)

Task performed:

Work performed by Oil Change Services j

Parts

NO PARTS USED

Quantity

Workorder: V39286

In Date: 03/18/2011 Meter Reading: 37,301.00

Close Date: 03/24/2011

Problem?

check engine light on dc5

Task performed:

C/O "check eng light"; fnd code for evap sys; cleaned code & replcd fuel tank cap. j

Parts

2582733520915842 FUEL CAP SUBURBAN

1

Workorder: V39644

In Date: 04/04/2011 Meter Reading: 38,997.00

Close Date: 04/14/2011

Problem?

ON CALL CHECK ENG LT ON DC5

Task performed:

1. Chk eng light on; P0449 evap emission sys intermittent; chkd for loose fuel cap or recovery concerns cleared. Codes ok to operate - no drivability problems; needs to come to shop.
2. Tire monitor sys problem unknown; chkd tire press, poss problem w/sensor or monitor. j

Parts

NO PARTS USED

Quantity

Workorder: V39983

In Date: 04/18/2011 Meter Reading: 39,899.00

Close Date: 04/29/2011

Problem?

check engine light on,tire sensor lt. on,fuel guage shows full all the time, battery light comes on intermittantly dc5 (outside agency-Roger Dean)

Task performed:

Check engine light on, tire sensor lt; fuel gauge - Roger Dean j

Parts

NO PARTS USED

Quantity

Vendor?: ROGER DEAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V40249

In Date: 04/29/2011

Meter Reading: 39,939.00

Close Date: 05/03/2011

Problem?

Check engine light is on. (just came back from shop day before yesterday), Sta 57.

Task performed:

Parts

Quantity

Chkd eng codes; fnd code for vapor sys; needs to be pressurized & chk for leaks (dealer). j

NO PARTS USED

Workorder: V39538

In Date: 03/29/2011

Meter Reading: 38,852.00

Close Date: 05/05/2011

Problem?

The interior lights directly above the MDC leak water in heavy rain. Could be the GPS locator on the roof. DC 5

Task performed:

Parts

Quantity

Resealed roof. j

NO PARTS USED

Workorder: V39539

In Date: 03/29/2011

Meter Reading: 38,852.00

Close Date: 05/05/2011

Problem?

Sometimes a red "battery" light comes on in the dash panel and it says "Check battery charging system". The vehicle works fine. Sometimes on when driving or parked. No pattern observed. DC 5

Task performed:

Parts

Quantity

1. Travel to Stn571; w/for truck to get back frm call; chk btrys - ok; chk alt - ok; order new alt - is going bad.

25968616ALTERNATOR 08 SURB

1

2. Seal u wires on lite bar & antenna on roof; wtr leak in cab when raining; return to shop. j

Workorder: V39853

In Date: 04/12/2011

Meter Reading: 39,462.00

Close Date: 05/13/2011

Problem?

I think fuel gauge is not right. Put in 15.5 gallons and gauge marked just above full. The other day was 3/4 full and it took 26.5 gallons. DC 5

Task performed:

Parts

Quantity

Truck needs tank to be rem to get to sender. j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V40620

In Date: 05/14/2011

Meter Reading: 40,899.00

Close Date: 06/09/2011

Problem?

Both rear window red emergency lights are loose and missing screws. They are starting to face downward and are not visible from the rear. DC5

Task performed:

Parts

Quantity

Rep rear lights in rear.

j

NO PARTS USED

Workorder: V42527

In Date: 08/03/2011

Meter Reading: 44,069.00

Close Date: 08/31/2011

Problem?

B Inspection with Oil Change Services

Task performed:

Parts

Quantity

OUTSIDE B INSPECTION OIL CHANGE SERVICES

NO PARTS USED

Vendor?: OIL CHANGE SERVICES

Workorder: V43520

In Date: 09/08/2011

Meter Reading: 45,340.00

Close Date: 09/08/2011

Problem?

repair brush guard.

Task performed:

Parts

Quantity

remove bracket and b--t straight on press and reinstalled alignment of gard buff out left front fender and bar to gard clean engine light

NO PARTS USED

Workorder: V43508

In Date: 09/08/2011

Meter Reading: 45,340.00

Close Date: 09/09/2011

Problem?

BRUSH GAURD FALLING OFF DC5

Task performed:

Parts

Quantity

call out to st 57
DC 5 was hit in front
bush gard bent down
check to see if it was ok to stay on OK
need to bring to shop for repair

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V44737

In Date: 10/28/2011

Meter Reading: 47,490.00

Close Date: 11/28/2011

Problem?

Loose battery clamps. Needs new battery clamps will not tighten, battery charging system light on. Outside B inspection.

Task performed:

Parts

Quantity

Rep cables & tested. j

NO PARTS USED

P.M. UNIT ROGER DEAN

Vendor?: ROGER DEAN

Workorder: V45352

In Date: 11/22/2011

Meter Reading:

Close Date: 12/16/2011

Problem?

Please check back up alarm. The vehicle is at the shop now for service.

Task performed:

Parts

Quantity

REPLACED BELTS AND ALTERNATOR

12576447BELT

1

12626222BELT

1

2088133707-08 2 WIRE GM

1

48-60BATTERY

1

65-72BXT65750 BATTERY

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

Workorder: V45317

In Date: 11/21/2011

Meter Reading: 48,398.20

Close Date: 12/28/2011

Problem?

replace tires

Task performed:

Parts

Quantity

REPLACE TIRES.

NO PARTS USED

Vendor?: CALLAGHAN TIRE

Workorder: V46123

In Date: 12/28/2011

Meter Reading: 49,760.00

Close Date: 01/13/2012

Problem?

Back up alarm does not work dc5

Task performed:

Parts

Quantity

THERE IS NO BACK UP ALARM INSTALLED ON TRUCK.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V46647

In Date: 01/17/2012

Meter Reading: 51,009.00

Close Date: 02/03/2012

Problem?

Wig wag not working. It needs repair. Sta 57

Task performed:

REPAIRED WIG-WAG AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V46686

In Date: 01/19/2012

Meter Reading: 51,009.00

Close Date: 02/10/2012

Problem?

right front headlight strobe not working. Also change engine oil soon message display is showing, Sta 57

Task performed:

1. STROBE OUT IN FRONT, REPLACED.
2. BACK-UP ALARM INOP - REPAIRED BAD CONNECTION.

Parts

01046301700S30HACP STROBE CLEAR

1

Quantity

Workorder: V48677

In Date: 04/14/2012

Meter Reading: 51,751.00

Close Date: 05/11/2012

Problem?

Brakes are squeaking.

Task performed:

ROAD TESTED/TESTED OK

Parts

NO PARTS USED

Quantity

Workorder: V50770

In Date: 07/11/2012

Meter Reading: 58,336.00

Close Date: 07/25/2012

Problem?

Engine Oil light on. DC 5

Task performed:

CLEARED OIL LIGHT AND RESET COMPT.

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V51967

In Date: 08/29/2012
Close Date: 09/13/2012

Meter Reading: 60,214.00

Problem?

REPAIR FLAT

Task performed:

REPAIR FLAT

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE

Workorder: V52387

In Date: 09/14/2012
Close Date: 09/14/2012

Meter Reading: 60,756.00

Problem?

B inspection

Task performed:

B inspection
oil and filter change

Parts

NO PARTS USED

Quantity

Vendor?: ROGER DEAN

Workorder: V52386

In Date: 09/14/2012
Close Date: 09/20/2012

Meter Reading: 60,717.00

Problem?

place unit stickers on rear windows

Task performed:

INSTALL STICKERS REAR SIDE WINDOWS.

Parts

NO PARTS USED

Quantity

Workorder: V53805

In Date: 11/15/2012
Close Date: 01/03/2013

Meter Reading:

Problem?

Left side of dash, where knobs are for the lights was pushed in accidentally. Knobs still work DC 5

Task performed:

REPLACED DASH PANELS.

Parts

25810643PLATE

Quantity

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V55564

In Date: 02/05/2013
Close Date: 02/12/2013

Meter Reading: 66,270.00

Problem?

B INSPECTION DC 5

Task performed:

B inspection
replace engine belts

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

Workorder: V55626

In Date: 02/07/2013
Close Date: 02/21/2013

Meter Reading: 65,955.00

Problem?

alignment

Task performed:

ALIGNMENT

Vendor?: CALLAGHAN TIRE

Parts

Quantity

NO PARTS USED

Workorder: V55627

In Date: 02/07/2013
Close Date: 02/21/2013

Meter Reading: 65,955.00

Problem?

replace tires

Task performed:

REPLACE TIRES.

Vendor?: CALLAGHAN TIRE

Parts

Quantity

NO PARTS USED

Workorder: V57683

In Date: 05/13/2013
Close Date: 05/13/2013

Meter Reading: 69,740.00

Problem?

Battery off gassing DC5

Task performed:

REPLACED BATTERIES TESTED SHORELINE AND TRUCK CHARGING SYSTEM OK.

Parts

Quantity

48-60BATTERY

1

65-72BXT65750 BATTERY

1

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59112

In Date: 07/16/2013
Close Date: 07/19/2013

Meter Reading: 72,989.00

Problem?

No start ST58 zone

Task performed:

NO START/STARTER/GET STARTED AND BROUGHT BACK TO STATION WILL GET STARTER IN THE MORNING.

Parts

Quantity

NO PARTS USED

Workorder: V59115

In Date: 07/16/2013
Close Date: 07/19/2013

Meter Reading: 72,989.00

Problem?

Swap out DC5 at shop

Task performed:

STARTER INOP/DID NOT HAVE CORRECT STARTER/HELPED SWIP OUT AT SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V59131

In Date: 07/16/2013
Close Date: 07/25/2013

Meter Reading: 73,111.00

Problem?

B-Inspection Replace starter

Task performed:

B-inspection
Replace starter
Replaced wiper blades

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

Workorder: V59379

In Date: 07/26/2013
Close Date: 07/26/2013

Meter Reading: 73,122.00

Problem?

Exhaust leak Replace steering wheel

Task performed:

Replaced steering wheel
Replaced r/s exhaust manifold gasket and repaired head bolt

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59125

In Date: 07/16/2013

Meter Reading: 72,989.00

Close Date: 07/31/2013

Problem?

Front emergency led's inop

Task performed:

DIAGNOSE FRONT EMERGENCY LIGHTS IN/OP - FOUND PULLED GROUND AND HOT/LEAD. RESPLICE WIRES HEAT SHRINK AND REPLACE WIRE LOOM SECURE LOOM TEST OK.

Parts

Quantity

C1123-T91SEAT COVER

1

Workorder: V59636

In Date: 01/01/1900

Meter Reading: 73,122.00

Close Date: 08/06/2013

Problem?

Steering wheel worn Exhaust leak

Task performed:

Replaced steering wheel
Repaired exhaust leak

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

Workorder: V59404

In Date: 07/29/2013

Meter Reading: 72,989.00

Close Date: 08/09/2013

Problem?

coolant leak

Task performed:

HEATER HOSE ASSEMBLY BROKEN REPAIRED.

Parts

Quantity

NO PARTS USED

Workorder: V59542

In Date: 08/04/2013

Meter Reading: 72,989.00

Close Date: 08/19/2013

Problem?

The 2 rear work lights for the command area are not working. The 2 fluoresenct lights. Maybe a fuse . DC5

Task performed:

1. REPAIRED BAD CONNECTION FOR COMMAND LIGHTS.
2. REPAIRED REAR DOOR MOLDING THAT WAS COMING OFF.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V59989

In Date: 08/22/2013
Close Date: 08/26/2013

Meter Reading: 73,892.00

Problem?

Right side Daylight Running Light - Right Front is out.

Task performed:

WENT TO 57 CALLED CHIEF - CHIEF CAME TO STATION - REMOVED BULB DID NOT HAVE CORRECT BULB REASSEMBLED AND INFORMED CHIEF OF REPAIRS.

Parts

NO PARTS USED

Quantity

Workorder: V60169

In Date: 08/29/2013
Close Date: 09/16/2013

Meter Reading: 74,131.00

Problem?

Please fix running light and flasher thats on the front grill. It's about to fall off. Also, TIC back up battery won't charge. Needs to be replaced, thanks!

Task performed:

1. REPAIRED RUNNING LIGHTS, REPLACED BULB.
2. REPAIRED TIC CHARGER THAT WAS OUT.

Parts

RSR03ZCRLIGHT LED RED TIR3 SERIES

Quantity

2

Workorder: V61669

In Date: 10/31/2013
Close Date: 11/15/2013

Meter Reading:

Problem?

Right rear brake light out DC 5

Task performed:

1. REMOVED TAIL LIGHT AND REPAIRED ALL LIGHTS AND REPAIRED WIRES.
2. REPAIRED AIR PACK COMPARTMENT DOOR IN REAR.

Parts

01046301700S30HACP STROBE CLEAR
3157TAIL LIGHT BULBS

Quantity

1
10

Workorder: V62509

In Date: 12/05/2013
Close Date: 12/05/2013

Meter Reading: 79,549.00

Problem?

need new wiper blades, DC-5

Task performed:

1. replace wiper blads

Parts

25877402WIPER BLADES NEW GM 22 IN

Quantity

2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V62579

In Date: 12/09/2013

Meter Reading: 79,549.00

Close Date: 12/13/2013

Problem?

ON CALL CHECK ENGINE LT ON DC 5

Task performed:

FOUND LOW ON COOLANT- REFILLED AND ROAD TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V62551

In Date: 12/30/2013

Meter Reading:

Close Date: 01/03/2014

Problem?

B-inspection

Task performed:

1. B-INSP.
2. ASSIST NORRIS W/ B-INSP.
3. REPLACED WIPER BLADES.
4. REMOVE AND REPLACE LIC PLATE BULB.
5. FRT SUSPENSION ADJUST VEHICLE RIDE HIGH ON FRT SUSPENSION- AJUSTMENT OF FRONT TORSION BARS NECESSARY TO ADJUST RIDE HIGHT.
6. ASSIST LARSON W/ FRT SUSPENSION.
7. FOR WARN SYSTEM CHECK IN PARTS FOR "FORWARN SYSTEM" PARTS -NG- FORMAN SYSTEMS ARE OBSLETE- TEAR OUT OLD SYSTEM AND INSTALL NEIVER STYLE SYSTEM- INCLUDING ALL NEW WIRING.
8. REPLACE BRKTS.
9. REPLACED HYDRO BOOST- LEAKING OIL INSIDE AND OUT.
10. REPLACE BOTH F & R BRAKES.
11. ASSIST NORRIS W/ COMPLETE FRT AND R BRAKES.

Parts

1601BRADAR BACKUP	1
19210706PADS 08 SUB	1
19210707PAD KIT	1
194BULB	2
20940395BOOSTER HYDRO	1
22853025HEADLAMP HOUSING	1
22853026HEADLAMP HOUSING	1
24-60BATTERY GROUP 24	1
25877402WIPER BLADES NEW GM 22 IN	2
57060OIL FILTER	1
65-72BXT65750 BATTERY	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
CA875642487 FILTER AIR	1

Quantity

Workorder: V63243

In Date: 01/08/2014

Meter Reading:

Close Date: 01/17/2014

Problem?

SUV just came back from PM and the brakes are vibrating badly when braking code 3. Appears rotors are warped. Also, tire pressure sensor front left is bad. The TIC base is loose and needs to be fastened down. dc 5

Task performed:

REMOVE END REPLACE FRONT ROTORS TEEST FOR OPERATION. IS GOOD NOW. NO PROBLEM.

Parts

15942195ROTOR FRT

Quantity

2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V62754

In Date: 12/17/2013
Close Date: 01/27/2014

Meter Reading: 80,100.00

Problem?

repair seat belt

Task performed:

REPLACED SEAT BELT THAT WOULD NOT LATCH.

Parts

19121537SEAT BELT

Quantity

1

Workorder: V63136

In Date: 01/05/2014
Close Date: 02/06/2014

Meter Reading:

Problem?

TIC charger needs to be screwed down. DC 5

Task performed:

REMOVED TIC CHARGER AND REINSTALLED UNIT.

Parts

NO PARTS USED

Quantity

Workorder: V63864

In Date: 02/20/2014
Close Date: 03/05/2014

Meter Reading: 82,354.00

Problem?

Replace headlight assemblies

Task performed:

REMOVED HEADLIGHTS AND INSTALLED NEW HEADLIGHT ASSEMBLIES AND WIRED.

Parts

6819634283068-1963428-30 LENS CLR
VTX609CVERTEX SINGLE WHITE

Quantity

3

2

Workorder: V57143

In Date: 04/19/2013
Close Date: 03/25/2014

Meter Reading: 68,403.00

Problem?

B-inspection [roger dean]

Task performed:

REPAIRED BY OUTSIDE VENDER ROGER DEAN.

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V63926

In Date: 02/03/2014

Meter Reading:

Close Date: 03/28/2014

Problem?

Requested new strobes/lights and new grill on DC5.

Task performed:

1. REPLACED LIGHT BAR LENS/REPAIRED LENS ON REAR AND SIDE OF TRUCK.
2. INSTALLED NEW LED LIGHTS IN FRONT OF TRUCK AND REAR.

Parts

Quantity

65-72BXT65750 BATTERY	1
6819634283068-1963428-30 LENS CLR	6
78-72BATTERY GROUP 78	2
9LLENSKT1LIBERTY LENS KIT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
M9RCRED 9M LIGHT	2

Workorder: V66486

In Date: 05/14/2014

Meter Reading: 87,975.00

Close Date: 05/16/2014

Problem?

B-inspection Noise in front wheel

Task performed:

- B-inspection
- Inspect brakes and rotate tires
- Replaced left front hub assy
- Replaced pinion seal
- Replaced l/f tire pressure monitor

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V66107

In Date: 04/30/2014

Meter Reading: 87,468.00

Close Date: 05/22/2014

Problem?

No start

Task performed:

REMOVED AND REPLACED BATTERIES.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V66237

In Date: 05/05/2014

Meter Reading:

Close Date: 05/23/2014

Problem?

The auto eject is not functioning on the plug to vehicle. Also, a cabinet hinge is broken on the command box inside the truck.

Task performed:

1. REPAIRED CABINET HINGE AND REPAIRED DOOF
2. CHECKED FOR NOISE IN LEFTFRONT SOUND LIKE BEARING NOISE-WILL SWAP OUT IN AM.

Parts

NO PARTS USED

Quantity

Workorder: V67315

In Date: 06/18/2014

Meter Reading:

Close Date: 07/03/2014

Problem?

Engine light is on.

Task performed:

- CHECKED FOR CODES FOUND P0562 NEED TO REPLACE FUEL SOLENOID.

Parts

25932571VALVE EVAP SYSTEM

Quantity

1

Workorder: V66266

In Date: 05/05/2014

Meter Reading:

Close Date: 07/09/2014

Problem?

Hearing rubbing noises in the front end of truck. Appears to be coming from left front wheel.

Task performed:

- repairs done at outside agency on ticket v66486.

Parts

NO PARTS USED

Quantity

Workorder: V67651

In Date: 07/09/2014

Meter Reading: 91,241.00

Close Date: 07/11/2014

Problem?

repair hand light DC 5

Task performed:

1. Installed handlight on side console.
2. Replaced battery and tested charging system.

Parts

24-60BATTERY GROUP 24

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V67749

In Date: 07/08/2014

Meter Reading:

Close Date: 07/18/2014

Problem?

The reverse light is out on the Battalion Chief Vehicle.

Task performed:

Parts

Quantity

replaced bulb in rear tail light and repaired socket.
insalled new flashlight on center console.

NO PARTS USED

Workorder: V64491

In Date: 02/24/2014

Meter Reading:

Close Date: 07/22/2014

Problem?

Right Front Tire is very slick/bald. Needs a new tire. May balance and alignment .

Task performed:

Parts

Quantity

REPAIRED BY TIRE SOLES

NO PARTS USED

Vendor?: TIRE SOLES

Workorder: V68702

In Date: 08/15/2014

Meter Reading: 93,686.00

Close Date: 08/20/2014

Problem?

replace tires

Task performed:

Parts

Quantity

Replace tires.

NO PARTS USED

Vendor?: ELPEX

Workorder: V68704

In Date: 08/15/2014

Meter Reading: 93,686.00

Close Date: 08/20/2014

Problem?

flat repair

Task performed:

Parts

Quantity

Flat repair.

NO PARTS USED

Vendor?: TIRESOLES OF BROWARD



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V68923

In Date: 08/25/2014

Meter Reading: 94,545.00

Close Date: 09/03/2014

Problem?

Change oil soon is coming up on the computer. sticker says change at 92972 shows now at 94451

Task performed:

Parts

Quantity

B-inspection

NO PARTS USED

Inspect flywheel and replace starter

Replaced tire sensors and reprogram

Replaced shocks

Vendor?: AL PACKER

Workorder: V68180

In Date: 07/25/2014

Meter Reading:

Close Date: 09/16/2014

Problem?

Left side reverse light not working.

Task performed:

Parts

Quantity

ck, with road tech work is complete on job

15862654HARNES

1

22787445HARNES

1

Workorder: V70044

In Date: 10/10/2014

Meter Reading: 96,659.00

Close Date: 10/29/2014

Problem?

A/C inop

Task performed:

Parts

Quantity

Check unit for A/C not working. Found A/C low on freon due to leak at high pressure valve. Charge and seal valve. Test for operation, it's ok.

NO PARTS USED

Workorder: V70021

In Date: 10/09/2014

Meter Reading: 96,508.00

Close Date: 10/30/2014

Problem?

a/c not working well

Task performed:

Parts

Quantity

Went to HQ, found compressor not engaged. Installed gauges pressure, check fuses, relays and control panel blinking. Check for codes, no codes return to shop.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V70037

In Date: 10/10/2014
Close Date: 10/30/2014

Meter Reading: 96,659.00

Problem?

Tommy was already notified that the AC is not working again.

Task performed:

A/C problem
Repaired A/C reset compt and road tested.

Parts

NO PARTS USED

Quantity

Workorder: V70092

In Date: 10/13/2014
Close Date: 10/30/2014

Meter Reading: 96,834.00

Problem?

The battery went dead and it had to be jump started. Seems to be cranking slow. pjk

Task performed:

Traced out problem with not starting. Found bad ground,
repaired and tested

Parts

NO PARTS USED

Quantity

Workorder: V70895

In Date: 11/13/2014
Close Date: 11/21/2014

Meter Reading: 98,385.00

Problem?

REPLACE WIPER BLADES DC 5

Task performed:

Replaced wiper blades

Parts

91-20WIPER BLADE 20 IN

Quantity

2

Workorder: V71918

In Date: 12/29/2014
Close Date: 12/31/2014

Meter Reading: 100,598.00

Problem?

battery dead

Task performed:

1. Travel to 58, replaced battery group 65
2. Travel to DC location jump station truck.

Parts

65-72BXT65750 BATTERY

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

Quantity

1

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V72335

In Date: 01/14/2015
Close Date: 01/16/2015

Meter Reading: 100,924.00

Problem?

Tiresoles 4 tires

Task performed:

WORK REPAIRS AS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V72035

In Date: 01/03/2015
Close Date: 01/20/2015

Meter Reading:

Problem?

rear passenger brake light OOS.

Task performed:

Repaired bad connection on tail light.

Parts

Quantity

NO PARTS USED

Workorder: V72144

In Date: 01/09/2015
Close Date: 01/20/2015

Meter Reading: 101,138.00

Problem?

Al Packer B-Inspect & replace radiator

Task performed:

REPAIRS AS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V75041

In Date: 04/30/2015
Close Date: 04/30/2015

Meter Reading: 106,809.00

Problem?

outside b inspection

Task performed:

outside b inspection
replace headlight
wiper blades
replace battery

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10174225

SUBURBAN LS SUV CHEVY SUBURBAN

Workorder: V74088

In Date: 03/22/2015

Meter Reading:

Close Date: 05/01/2015

Problem?

Lens for emergency light fell off. Missing screw. Lens for right front quarter panel. Lens and 1 screw on the District Chief's desk. DC 7

Task performed:

Parts

Quantity

- 1. Repaired light tested.

50R03ZCRLIGHT LED RED TIR 6

1

Workorder: V74107

In Date: 03/23/2015

Meter Reading:

Close Date: 05/01/2015

Problem?

I spoke to Tommy about this already. The cover for the E-light needs to be replaced fixed. It appears the in-side bracket is broken so the screw(s) won't hold.

Task performed:

Parts

Quantity

- 1. Removed light repaired and tested.

NO PARTS USED

Workorder: V74575

In Date: 04/12/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

The front left side(passenger side) emergency flasher is out next to the headlight DC 5

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10174225) 2008 - CHEVROLET SUBURBAN LS Suv Chevy Suburban

10174225

CSHOP-2015-1250

Comments: **BATT 5 TIRE BALANCE**

Date Opened: 6-18-2015 Date Finished: 6-18-2015 Meter 1 Reading: 107,843

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-379

Comments: **1 WIG WAG INOP DC5 1 TIRE LOW SENSOR ON**

Date Opened: 4-30-2015 Date Finished: 5-4-2015 Meter 1 Reading: 106,873

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 BULB; 35 WATT BULB
1 9IP; LAMP HOLDER MR11

CSHOP-2015-383

Comments: **OUTSIDE B INSPECTION, REPLACE HIGH BEAM HEADLIGHT, INSTALLED NEW BATTERIES, WIPER BLADES, AND INSPECT BRAKE SYSTEM.**

Date Opened: 4-30-2015 Date Finished: 4-30-2015 Meter 1 Reading: 106,867

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2015-476

Comments: **B INSPECTION TEST AND REPLACE BATTERIES WIPER BLADES INSPECT BRAKES /ROTATE TIRES REPLACED R/S HIGH BEAM P.O. 043015-15948**

Date Opened: 5-6-2015 Date Finished: 5-6-2015 Meter 1 Reading: 106,867

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2015-709

Comments: **AUTO EJECT INOP DC5 NOW CALLED BATTALION 57**

Date Opened: 5-19-2015 Date Finished: 5-21-2015 Meter 1 Reading: 106,868

TASKS PERFORMED

NO PARTS USED

AUTO-EJECT

Asset Work Order History 10174225

CSHOP-2016-1354

Date Opened: 3-21-2016 Date Finished 3-21-2016 Meter 1 Reading: 111,528

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

VENDOR? AL PACKER

CSHOP-2016-1670

Date Opened: 4-8-2016 Date Finished 4-8-2016 Meter 1 Reading: 111,538

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-2136

Comments: **A/C 10-7**

Date Opened: 5-3-2016 Date Finished 5-9-2016 Meter 1 Reading: 111,540

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2016-2902

Date Opened: 6-16-2016 Date Finished 6-16-2016 Meter 1 Reading: 112,916

TASKS PERFORMED

NO PARTS USED

SENSOR

VENDOR? AL PACKER

CSHOP-2016-4015

Date Opened: 8-15-2016 Date Finished 8-15-2016 Meter 1 Reading: 114,643

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Asset Work Order History 10174225

CSHOP-2016-4866

Date Opened: 10-11-2016 Date Finished 10-25-2016 Meter 1 Reading: 115,379

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STARTER

1 NEWPART; STARTER

Service Requests:

-
- 10/08/2016 TIRES / 12: BROKEN / SENT TO DEALER FOR REPAIRS.
BAD TIRES; THE RIGHT FRONT TIRE HAS A BOLT IN THE TREAD.
 - 10/08/2016 ENGINE / 12: BROKEN / SENT TO DEALER FOR REPAIRS.
ENGINE: THE OIL LIFE IS AT 0%.
 - 10/18/2016 SERVICE REQUEST / 11: BINDS/STICKS / SENT TO DEALER FOR REPAIRS.

CSHOP-2016-5170

Date Opened: 10-31-2016 Date Finished 10-31-2016 Meter 1 Reading: 115,385

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-864

Comments: **BC57 CHECK ENGINE LIGHT**

Date Opened: 2-23-2016 Date Finished 3-7-2016 Meter 1 Reading: 111,347

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-WARNING &

Service Requests:

-
- 02/22/2016 ENGINE / 19: LOOSE / REPAIR
CHECK ENGINE LIGHT ON . CRUISE CONTROL INOPERATIVE. LIGHT COMES ON WHEN "ON" WHEN DEPRESSED, BUT
WILL NOT ENGAGE CRUISE FOR SPEED.

CSHOP-2017-1456

Comments: **SPECIAL OPS DECALS ARE HERE**

Date Opened: 3-8-2017 Date Finished 5-2-2017 Meter 1 Reading: 117,847

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
BODY EXTERIOR

Asset Work Order History 10174225

CSHOP-2017-2493

Comments: **CHECK BATTERIES**

Date Opened: 4-27-2017 Date Finished 4-27-2017 Meter 1 Reading: 141,879

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY 48A

CSHOP-2017-2818

Comments: **NOTIFIED CALLAGHAN 5-12-17**

Date Opened: 5-12-2017 Date Finished 5-22-2017 Meter 1 Reading: 117,847

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

05/11/2017 TIRES / 18: LEAKING / EXCHANGE - NEW
LEFT FRONT TIRE LEAKING AIR WITH VISUAL PIECE OF METAL STICKING OUT OF TIRE. VEHICLE PARKED AT PBCFR STATION 58. KEYS IN OFFICERS QUARTERS IF NEEDED.

CSHOP-2017-3930

Date Opened: 7-3-2017 Date Finished 7-24-2017 Meter 1 Reading: 118,509

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

1 9IP; FLASHER-WHELEN HEADLIGHT HIGH BEAM

CSHOP-2017-4067

Date Opened: 7-10-2017 Date Finished 7-18-2017 Meter 1 Reading: 118,509

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-4183

Date Opened: 7-18-2017 Date Finished 7-18-2017 Meter 1 Reading: 118,509

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? AL PACKER

Asset Work Order History 10174225

CSHOP-2017-4335

Date Opened: 7-26-2017

Date Finished

8-9-2017

Meter 1 Reading:

118,862

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
LIGHTING SYSTEM
CRANKING SYSTEM
SIREN

2 NOE; HOLD DOWN
2 1AD; BATTERY

CSHOP-2017-5780

Date Opened: 10-5-2017

Date Finished

12-14-2017

Meter 1 Reading:

120,315

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 9AP; OIL CHANGE KIT
4 2TP; RED N TACKY GREASE
1 9AP; BATTERY
1 9AP; AIR FILTER
1 9AP; SPARK PLUG WIRE
1 9AP; BREAK AWAY SWITCH
1 9AP; SPARK PLUG

CSHOP-2017-66

Date Opened: 1-4-2017

Date Finished

1-19-2017

Meter 1 Reading:

116,630

TASKS PERFORMED

NO PARTS USED

ELECTRICAL
CAB-INTERIOR ACCESSORIES

CSHOP-2017-7138

Date Opened: 12-14-2017

Date Finished

1-3-2018

Meter 1 Reading:

120,443

TASKS PERFORMED

Q PARTS

TRAILER

4 9AP; WHEEL 15X5 550
4 9AP; TIRE
1 9AP; TIRE MOUNT

CSHOP-2018-2354

Date Opened: 4-30-2018

Date Finished

4-30-2018

Meter 1 Reading:

120,903

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History 10174225

CSHOP-2018-3694

Date Opened: 7-2-2018 Date Finished 7-9-2018 Meter 1 Reading: 122,042

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-1998

Date Opened: 5-3-2019 Date Finished 5-3-2019 Meter 1 Reading: 125,516

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2020-2201

Date Opened: 4-24-2020 Date Finished 4-24-2020 Meter 1 Reading: 128,828

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

RADIO-2018-134

Comments: REMOVE 10141507, INSTALL 10205587 INTO DC-900 10174225

Date Opened: 3-1-2018 Date Finished 3-1-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

03/01/2018 RADIO / /
REMOVE AND INSTALL NEW MOTOROLA MOBILE RADIO INTO DC-900

SSHOP-2020-219

Date Opened: 7-1-2020 Date Finished 7-28-2020 Meter 1 Reading: 129,173

TASKS PERFORMED

Q PARTS

BATTERY

- 1 6KU; AC2000 12V PLC TEN 8
 - 2 GRO; FUSEHOLD
 - 1 8GR; PLUG 5 15P 15A 125VAC
 - 2 8GR; PLUG 5 15P 15A 125VAC
 - 4 GRO; FUSEHOLD
 - 2 1AD; BATTERY GROUP 48
 - 3 9EM; BOOT
 - 2 NW; FUSE HOLDER
 - 1 6KU; AUTO EJECT
-

Asset Work Order History 10174225

SSHOP-2020-294

Comments: **INSTALL NEW LED PELICAN LIGHT**

Date Opened: 8-26-2020 Date Finished 8-26-2020 Meter 1 Reading: 129,282

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

SSHOP-2020-39

Date Opened: 1-28-2020 Date Finished 1-28-2020 Meter 1 Reading: 128,140

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
