			Report	Description: Work Or	rder H	listory by Asset	t and System Code			
Print Date:	10/6/2020	1	WO Close Date <u>Asset# Ran</u> g	·	to to	08/19/2020 PT1302	System Code Range:	1100	to	9700
BUS# S	YS Code	<u>SYS C</u>	ode Description							
PT1302	1100	INTER	IOR CLEAN	Tota	al Line	Count for Syster	m Code <mark>1100</mark> :	3		Cause-Reason
Work Order # 2016191	Line# 1	<u>Close Date</u> 08/19/2020	Employee# 862	Description of W		RIORFUELED			S	CHEDULED SERVICE
4000007	4	04/00/0040	050						S	CHEDULED SERVICE
1808387 1809055	1	04/26/2018	656 827	INTERIOR CLEANCO					S	CHEDULED SERVICE
PT1302	1200							2		<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of W		Count for Syster		2	S	CHEDULED SERVICE
1906958	4	05/28/2019	828	R/R CLAMP ON HOSE		OOLANT RESER	RVIOR			PERATOR COMPLAINT
1905853	4	03/29/2019	828	REPLACE COOLANT F	RESEF	RVOIR CAP AND	HOSE CLAMP			
PT1302	1201	TROU	BLESHOOT COOLING	SYS Tota	al Line	Count for Syster	n Code <mark>1201</mark> :	2		<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of W					OF	PERATOR COMPLAINT
1804317	1	05/22/2018	837	TROUBLESHOOT COC					OF	PERATOR COMPLAINT
1805694	3	03/29/2018	837	t/s overhet vehicle need	ds radi	iator and thermas	tat			
PT1302	1202	WATE	R PUMP	Tota	al Line	Count for Syster	n Code <mark>1202</mark> :	2		<u>Cause-Reason</u>
<u>Work Order #</u> 1922775	<u>Line#</u> 6	<u>Close Date</u> 12/18/2019	<u>Employee#</u> 783	Description of W NEED WATER PUMP	<u>ork</u>				OF	PERATOR COMPLAINT
1922775	7	12/18/2019	783	R/R WATER PUMP					OF	PERATOR COMPLAINT
PT1302	1204	FAN M	IOTOR REPL	Tota	al Line	Count for Syster	n Code 1204 :	1		<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	Description of W	'ork				OF	PERATOR COMPLAINT
1803231	8	03/13/2018	837	RR FAN ASSEMBLY						
PT1302	1206	RADIA	TOR REPL	Tota	al Line	Count for Syster	n Code <mark>1206</mark> :	1		<u>Cause-Reason</u>
<u>Work Order #</u> 1805694	Line# 4	<u>Close Date</u> 03/29/2018	Employee# 837	<u>Description of W</u> removed radiator -wip w		on parts			OF	PERATOR COMPLAINT

			Report	Descript	ion: Work O	rder	History by Ass	et and System Code			
			WO Close Date	Range:	07/11/2013	to	08/19/2020	System Code Range:	1100	to	9700
Print Date: 1	10/6/2020		Asset# Rang	e:	PT1302	to	PT1302				
BUS# SY	/S Code	SVS Co	de Description	_							
PT1302	<u>1208</u>		NG SYS LINES/HOSES	D	Tot	al Lin	e Count for Syst	om Codo 1208 :	6		Cause-Reason
					escription of W		e count for Syst		0		PERATOR COMPLAINT
<u>Work Order #</u> 1805694		Close Date 03/29/2018	Employee# 809				radiator and chee	ak for looks		UF	
1003094	5	03/29/2010	009	ii uppei i	aulator nose ,	meu					PERATOR COMPLAINT
1803231	3	03/13/2018	837		E COOLANT H					UF	ERATOR COMPLAINT
1003231	3	03/13/2016	037	REIVIOVE		103E	-0019			0	
4000004	4	00/40/0040	007			100F				OF	PERATOR COMPLAINT
1803231	4	03/13/2018	837	INSTALL	COOLANT -	105E				05	
1700011	•	04/00/0040	040							OF	PERATOR COMPLAINT
1722944	3	01/03/2018	818	R/R COC	DLANT OVER	-LOW	HOSEBLED/F	ILLED COOLING SYTEM			
4700400	•	04/00/0040	007			• -				OF	PERATOR COMPLAINT
1723468	3	01/22/2018	837	FOUNDI	LEALK AT HE	AIEF	HUSE -REMOV	ED HOSE ASSYM AND BA	ITERY		
										OF	PERATOR COMPLAINT
1723468	4	01/22/2018	837	INSTALL	NEW HEATE	RHC	SE ASSYM				
PT1302	1210	SURGE	TANK REPAIR		Tot	al Lin	e Count for Syst	em Code 1210 :	1		<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	De	escription of W	/ork				OF	PERATOR COMPLAINT
1922775	8	12/18/2019	783	PURGE,	REPURGE, T	OPPE	ED OFF COOLAN	ITROAD TEST			
PT1302	1211	SURGE	TANK REPL		Tot	al Lin	e Count for Syst	em Code 1211 :	1		Cause-Reason
Work Order #	Line#	Close Date	Employee#	De	escription of W	/ork				OF	PERATOR COMPLAINT
1722944	2	01/03/2018	818	R/R ECP	ANSION TAN	KFC	OUND FLOW HO	SE BROKENPOO			
PT1302	1300	AIR CO	ND\HEATING SYSTEM	1	Tot	al Lin	e Count for Syst	em Code <mark>1300</mark> :	1		<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	De	escription of V	/ork				OF	PERATOR COMPLAINT
1610733	2	07/29/2016	820	FOUND	CONNECTOR	FOR	ACTIVE SHUTT	ER UNPLUGGED-PLUGGE	D IN & TES	STED-V	VORKING FINE

			Report	Description: Work Order History by A	sset and System Code		
Print Date:	10/6/2020	.	WO Close Date	C C	System Code Rang	je: 1100	to 9700
		-	<u>Asset# Rang</u>	e: PT1302 to PT1302			
BUS#	SYS Code	<u>SYS (</u>	Code Description				
PT1302	1301	TROU	IBLESHOOT AC SYSTE	M Total Line Count for Sy	stem Code 1301 :	9	Cause-Reason
Work Order #			Employee#	Description of Work			OPERATOR COMPLAINT
1610733	1	07/29/2016	756	TROUBLESHOOT AC SYSTEM-CK ACS	END TO FORD-ACTIVE SI	HUTTERS STA	
	_						OPERATOR COMPLAINT
1609822	2	07/12/2016	797	TROUBLESHOOT AC SYSTEM			
17000 / /		04/00/00 : -	0.40				
1722944	1	01/03/2018	849	TROUBLESHOOT AC SYSTEMCAR OVI	ER HEATING DUE TO LOV	V COOLANT(
40007777		10/10/00/10	000		<u> </u>		OPERATOR COMPLAINT
1922775	2	12/18/2019	866	AC COMPRESSOR LINE LEAKING PO			
4045400	4	44/00/0040	000				SCHEDULED SERVICE
1615408	1	11/08/2016	809	T/8S A/C SYSTEM			
4700000	4	04/40/0047	700				OPERATOR COMPLAINT
1700829	1	01/19/2017	762	TROUBLESHOOT AC SYSTEMLOW ON	FREON		
1700014	1	01/10/2017	752	TROUBLESHOOT AC SYSTEMTOO MU			
1700914	1	01/19/2017	152	TROUBLESHOUT AC SYSTEMTOO MU	CH FREUNREMOVE/RE	PLC CORREC	OPERATOR COMPLAINT
1701148	1	02/02/2017	818	T/S A/C SYSTEM			OPERATOR COMPLAINT
1701140	I	02/02/2017	010	I/S A/C STSTEM			OPERATOR COMPLAINT
1701148	2	02/02/2017	762	RECOVERED FREON FROM SYSTEM			OPERATOR COMPLAINT
PT1302	1303		OMPRESSOR REPL	Total Line Count for Sy	stem Code 1303 :	1	Cause-Reason
Work Order #			Employee#	Description of Work			SCHEDULED SERVICE
1701148	3	02/02/2017	809	R/R A/C COMPRESSOR			
PT1302	1310	A/C L	INES/HOSES REPL	Total Line Count for Sy	stem Code 1310 :	1	Cause-Reason
Work Order #	<u> Line#</u>	Close Date	Employee#	Description of Work			OPERATOR COMPLAINT
1922775	4	12/18/2019	783	R/R AC LINE			
PT1302	1317	A/C S	YSTEM PUMP DOWN	Total Line Count for Sy	stem Code 1317 :	1	Cause-Reason
Work Order #	<u> Line#</u>		Employee#	Description of Work			OPERATOR COMPLAINT
1922775	3	12/18/2019	783	RECOVER FREON			

Busite Discue Proce Proce Proce BUSIE SYS Code SYS Code SYS Code Description SYS Code SYS Code Description Volk Order # Line# Close Date Employee# Description of Work OPERATOR COMPLAINT 1922775 5 12/18/2019 783 RECHARGE OPERATOR COMPLAINT 1701148 4 02/02/2017 809 CHARGED A/C 1.5 POUND OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 02/02/2017 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1815408 1 Close Date Employee# Description of Work OPERATOR COMPLAINT 1815408				Report	Descriptio	n: Work Or	der	History by As	set and Sys	tem Code			
Busit SYS Code SYS Code SYS Code Description P1302 1318 A/C SYSTEM RE-CHARGE Total Line Count for System Code 1318 : 7 Cause-Reason Vork Order # 1922775 Line# Close Date 12/18/2019 Employee# 783 Description of Work RECHARGE OPERATOR COMPLAINT 1701148 4 02/02/2017 809 CHARGED A/C 1.5 POUND OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 170148 5 02/02/2017 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1815694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1815408 1 Cause-Reason OPERATOR COMPLAINT OPERATOR COMPLAINT 181080/2016				WO Close Date	Range: 0	07/11/2013	to	08/19/2020	Systen	n Code Range:	1100	to	9700
T1302 1318 A/C SYSTEM RE-CHARGE Total Line Count for System Code 1318 : 7 Cause-Reason Voik Order # 1922775 Line # 5 Line # 2/18/2019 Temployee# 783 Employee# RECHARGE OPERATOR COMPLAINT 1922775 5 12/18/2019 Temployee# 783 Description of Work RECHARGE OPERATOR COMPLAINT 1922775 5 0/10/2017 809 CHARGED A/C 1.5 POUND OPERATOR COMPLAINT 1701148 4 0/2/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 0/2/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 170148 5 0/2/02/2017 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1615408 Line# Classe Reason OPERATOR COMPLAINT OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM </th <th>Print Date:</th> <th>10/6/2020</th> <th>)</th> <th>Asset# Rang</th> <th>ge: F</th> <th>PT1302</th> <th>to</th> <th>PT1302</th> <th></th> <th></th> <th></th> <th></th> <th></th>	Print Date:	10/6/2020)	Asset# Rang	ge: F	PT1302	to	PT1302					
Vork Order # 1922775 Line# 5 Lose Date 12/10/2019 Employee# 783 Description of Work RECHARGE OPERATOR COMPLAINT 1701148 4 02/02/2017 809 CHARGED A/C 1.5 POUND OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1701148 4 11/08/2016 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECOVER FREON OPERATOR COMPLAINT 1805694 1 Inder Close Date Employee# Description of Work RECOVER FREON OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM <t< th=""><th>BUS# S</th><th>YS Code</th><th><u>SYS C</u></th><th>ode Description</th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th></t<>	BUS# S	YS Code	<u>SYS C</u>	ode Description									
Display Display <t< th=""><th>PT1302</th><th>1318</th><th>A/C SY</th><th>STEM RE-CHARGE</th><th></th><th>Tota</th><th>l Lin</th><th>e Count for Sys</th><th>stem Code 13</th><th>318 :</th><th>7</th><th></th><th>Cause-Reason</th></t<>	PT1302	1318	A/C SY	STEM RE-CHARGE		Tota	l Lin	e Count for Sys	stem Code 13	318 :	7		Cause-Reason
1701148 4 02/02/2017 809 CHARGED A/C 1.5 POUND OPERATOR COMPLAINT 1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1700829 2 01/19/2017 762 ADDED FREON-RAN ACOK @THIS TIME OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM OPERATOR COMPLAINT 1806694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1806694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1806694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1806694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1806694 7 03/29/2018 809 RECOVER FREON OPERATOR COMPLAINT 1615408 1 A/C SYSTEM VACUUM Total Line Count for System Code 1335 : 2 Cause-Reason 171302 133 A/C SYSTEM VACUUM Description of Work OPERATOR COMPLAINT OPERATOR COMPLAINT 1615408 11/08/2016 809	<u>Work Order #</u> 1922775						ork						
1701148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 170148 5 02/02/2017 809 REPLACED O-RING OPERATOR COMPLAINT 1700829 2 01/19/2017 762 ADDED FREONRAN ACOK @THIS TIME OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM SCHEDULED SERVICE 1906958 2 05/28/2019 828 TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1815408 2 11/08/2016 Employee# Description of Work RECOVER FREON OPERATOR COMPLAINT 1815408 3 A/C SYSTEM VACUUM Total Line Count for System Code 1335<:	1701148	4	02/02/2017	809	CHARGED							O	PERATOR COMPLAINT
1700829 2 01/19/2017 762 ADDED FREON-RAN ACOK @THIS TIME OPERATOR COMPLAINT 1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM SCHEDULED SERVICE 1906958 2 05/28/2019 828 TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECOVER FREON OPERATOR COMPLAINT 1615408 2 11/08/2016 Employee# Description of Work OPERATOR COMPLAINT 1615408 3 11/08/2016 B09 RECOVER FREON OPERATOR COMPLAINT 1615408 3 11/08/2016 B09 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATO	1701140	-	02/02/2011	003	ONAROLD	701.010						O	PERATOR COMPLAINT
1700829 2 01/19/2017 762 ADDED FREONRAN ACOK @THIS TIME OPERATOR COMPLAINT 1815408 4 11/08/2016 809 RECHARGE A/C SYSTEM SCHEDULED SERVICE 1906958 2 05/28/2019 828 TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM 1 Cause-Reason 271302 1334 A/C SYSTEM EVACUATION Total Line Count for System Code 1334 : 1 Cause-Reason 070K Order # 11/08/2016 Employee# Description of Work Colese Date OPERATOR COMPLAINT 1615408 2 Close Date Employee# Description of Work OPERATOR COMPLAINT 1615408 1 Close Date Employee# Description of Work OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694<	1701148	5	02/02/2017	809	REPLACED	O-RING							
1615408 4 11/08/2016 809 RECHARGE A/C SYSTEM SCHEDULED SERVICE 1906958 2 05/28/2019 828 TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM Total Line Count for System Code 1334 : 1 Cause-Reason 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM Total Line Count for System Code 1334 : 1 Cause-Reason Verk Order # Line# Close Date Employee# Description of Work OPERATOR COMPLAINT 1615408 11/08/2016 Employee# Description of Work OPERATOR COMPLAINT 1615408 11/08/2016 Employee# Description of Work OPERATOR COMPLAINT 1615408 3 11/08/2016 Employee# Description of Work OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694	1700000	2	01/10/2017	760			•		A (~			O	PERATOR COMPLAINT
1906958 2 05/28/2019 828 TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM Image: Colspan="2">OPERATOR COMPLAINT 1805694 7 03/29/2018 809 RECHARGED A/C SYSTEM OPERATOR COMPLAINT 1615408 2 11/08/2016 Employee# Description of Work OPERATOR COMPLAINT 1615408 3 A/C SYSTEM VACUUM Total Line Count for System Code 1335 : 2 Cause-Reason Vork Order # Line# Close Date Employee# Description of Work OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT 1805694 6 03/29/2018 809 VACUUM A/C SYSTEM SCHEDULED SERVICE <tr< td=""><td>1700829</td><td>2</td><td>01/19/2017</td><td>762</td><td>ADDED FR</td><td>EONRAN /</td><td>40</td><td></td><td>ΛE</td><td></td><td></td><td>O</td><td>PERATOR COMPLAINT</td></tr<>	1700829	2	01/19/2017	762	ADDED FR	EONRAN /	40		ΛE			O	PERATOR COMPLAINT
1906958205/28/2019828TOP OFF AC SYSTEM WITH 1/2LBS OF REFRIGERANTOPERATOR COMPLAINT1805694703/29/2018809RECHARGED A/C SYSTEM1Cause-Reason213021334A/C SYSTEM EVACUATIONTotal Line Count for System Code 1334 :1Cause-ReasonVork Order #Line#Close DateEmployee#Description of WorkOPERATOR COMPLAINT1615408211/08/2016809RECOVER FREONOPERATOR COMPLAINT16154083A/C SYSTEM VACUUMTotal Line Count for System Code 1335 :2Cause-ReasonVork Order #Line#Close DateEmployee#Description of WorkOPERATOR COMPLAINT1615408311/08/2016809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMSCHEDULED SERVICE1805694603/29/2018809VACUUM A/C SYSTEMSCHEDULED SERVICE18056941400ELECTRICAL SYSTEMSCHEDULED SERVICESCHEDULED SERVICE1805694603/29/2018828ELECTRICAL SYSTEMSCHEDULED SERVICE18066941008/07/2019746CHECK ENGINE ALARM OUT-NO CODESSCHEDULED SERVICE1816907	1615408	4	11/08/2016	809	RECHARG	E A/C SYST	EM						
1805694703/29/2018809RECHARGED A/C SYSTEMPT13021334A/C SYSTEM EVACUATIONTotal Line Count for System Code 1334 :1Cause-ReasonVork Order # 1615408211/08/2016809Description of Work RECOVER FREONOPERATOR COMPLAINTPT13021335A/C SYSTEM VACUUMTotal Line Count for System Code 1335 :2Cause-ReasonPT13021335A/C SYSTEM VACUUMDescription of Work RECOVER FREON0PERATOR COMPLAINTPT13021335A/C SYSTEM VACUUMDescription of Work RECOVER FREON0PERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT DOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT DOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT DOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT DEscription of Work CHECK ENGINE ALARM OUTNO CODESSCHEDULED SERVICE1816907108/06/2018828ELECTRICAL SYSTEM CHECK ENGINE ALARM OUTNO CODESSCHEDULED SERVICE OPERATOR COMPLAINT OPERATOR COMPLAINT OPERA										_		S	CHEDULED SERVICE
1805694703/29/2018809RECHARGED A/C SYSTEM1302133A/C SYSTEM EVACUATIONTotal Line Count for System Code 1334 :1Cause-ReasonVork Order # 1615408Line# 2Ciose Date 11/08/2016Employee# 809Description of Work RECOVER FREONOPERATOR COMPLAINT213021335A/C SYSTEM VACUUMTotal Line Count for System Code 1335 :2Cause-ReasonVork Order # 1615408Line# 3Ciose Date 11/08/2016Employee# 809Description of Work VACUUM A/C SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMSCHEDULED SERVICE1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR ComPLAINT OPERATOR COMPLAINT1805694603/29/2018828ELECTRICAL SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAINT1816907108/06/2018828ELECTRICAL SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAI	1906958	2	05/28/2019	828	TOP OFF A	CSYSTEM	WIII	H 1/2LBS OF R	EFRIGERAN	I			PERATOR COMPLAINT
Vork Order # 1615408Line# 2Close Date 11/08/2016Employee# 809Description of Work RECOVER FREONOPERATOR COMPLAINTPT13021335A/C SYSTEM VACUUMTotal Line Count for System Code 1335 : 22Cause-ReasonVork Order # 1615408Line# 3Close Date 11/08/2016Employee# 809Description of Work VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMSCHEDULED SERVICE1816907108/06/2018828ELECTRICAL SYSTEMSCHEDULED SERVICE1801315802/09/2016764SENT TO A/L PACKER FORDOPERATOR COMPLAINT0PERATOR COMPLAINT074SENT TO A/L PACKER FORDOPERATOR COMPLAINT	1805694	7	03/29/2018	809	RECHARGI	ED A/C SYS	TEM					0	
ControlationEntrolControlationEntrolEntrolation1615408211/08/2016809RECOVER FREONPT13021335A/C SYSTEM VACUUMTotal Line Count for System Code 1335 :2Cause-ReasonVork Order #Line#Close DateEmployee#Description of Work VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1816907108/06/2018828ELECTRICAL SYSTEMSCHEDULED SERVICE1816907108/06/2018828ELECTRICAL SYSTEMOPERATOR COMPLAINT1601315802/09/2016764SENT TO A/L PACKER FORDOPERATOR COMPLAINT	PT1302	1334	A/C S	STEM EVACUATION		Tota	l Lin	e Count for Sys	stem Code 13	34 :	1		Cause-Reason
PT13021335A/C SYSTEM VACUUMTotal Line Count for System Code 1335 :2Cause-ReasonVork Order # 1615408Line# 3Close Date 11/08/2016Employee# 809Description of Work VACUUM A/C SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1816907108/06/2018828ELECTRICAL SYSTEMSCHEDULED SERVICE1816907108/06/2018828ELECTRICAL SYSTEMOPERATOR COMPLAINT1601315802/09/2016764SENT TO A/L PACKER FORDOPERATOR COMPLAINT	Work Order #		Close Date				ork					OI	PERATOR COMPLAINT
Vork Order # 1615408Line# 3Close Date 11/08/2016Employee# 809Description of Work VACUUM A/C SYSTEMOPERATOR COMPLAINT OPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT1805694603/29/2018809VACUUM A/C SYSTEMOPERATOR COMPLAINT2010ELECTRICAL SYSTEMTotal Line Count for System Code 1400 :4Cause-Reason2011Close Date 4Employee# 08/07/2019Description of Work 746SCHEDULED SERVICE1816907108/06/2018828ELECTRICAL SYSTEMSCHEDULED SERVICE1601315802/09/2016764SENT TO A/L PACKER FORDOPERATOR COMPLAINT OPERATOR COMPLAINT					RECOVER								
Initial	PT1302							e Count for Sys	stem Code 13	35 :	2		
1805694 6 03/29/2018 809 VACUUM A/C SYSTEM OPERATOR COMPLAINT PT1302 1400 ELECTRICAL SYSTEM Total Line Count for System Code 1400 : 4 Cause-Reason Vork Order # 1914449 Line# 4 Close Date 08/07/2019 Employee# 746 Description of Work CHECK ENGINE ALARM OUTNO CODES SCHEDULED SERVICE 1816907 1 08/06/2018 828 ELECTRICAL SYSTEM SCHEDULED SERVICE 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT												O	PERATOR COMPLAINT
1805694 6 03/29/2018 809 VACUUM A/C SYSTEM PT1302 1400 ELECTRICAL SYSTEM Total Line Count for System Code 1400 : 4 Cause-Reason Vork Order # 1914449 Line# 4 Close Date 08/07/2019 Employee# 746 Description of Work CHECK ENGINE ALARM OUTNO CODES SCHEDULED SERVICE 1816907 1 08/06/2018 828 ELECTRICAL SYSTEM OPERATOR COMPLAINT 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT	1015408	3	11/08/2016	809	VACUUM A	AC STSTEN	/1					0	
Vork Order # 1914449 Line# 4 Close Date 08/07/2019 Employee# 746 Description of Work CHECK ENGINE ALARM OUTNO CODES SCHEDULED SERVICE 1816907 1 08/06/2018 828 ELECTRICAL SYSTEM SCHEDULED SERVICE 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT	1805694	6	03/29/2018	809	VACUUM A	/C SYSTEM	l					U	PERATOR COMPLAINT
Vork Order # 1914449 Line# 4 Close Date 08/07/2019 Employee# 746 Description of Work CHECK ENGINE ALARM OUTNO CODES SCHEDULED SERVICE 1816907 1 08/06/2018 828 ELECTRICAL SYSTEM SCHEDULED SERVICE 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT	PT1302	1400	ELECI	FRICAL SYSTEM		Tota	l Lin	e Count for Sys	stem Code 14	00 :	4		Cause-Reason
1914449 4 08/07/2019 746 CHECK ENGINE ALARM OUTNO_CODES SCHEDULED SERVICE 1816907 1 08/06/2018 828 ELECTRICAL SYSTEM OPERATOR COMPLAINT 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT	Work Order #	Line#	Close Date	Employee#	Desc							S	CHEDULED SERVICE
1816907 1 08/06/2018 828 ELECTRICAL SYSTEM OPERATOR COMPLAINT 1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT OPERATOR COMPLAINT					CHECK EN	IGINE ALA	RM C	UTNO COD	ES				
1601315 8 02/09/2016 764 SENT TO A/L PACKER FORD OPERATOR COMPLAINT	1816907	1	08/06/2018	828	ELECTRIC	AL SYSTEM						S	CHEDULED SERVICE
OPERATOR COMPLAINT	/ / . / .											O	PERATOR COMPLAINT
	1601315	8	02/09/2016	764	SENT TO A	VL PACKEF	r FOI	עא					
	1601315	8	02/09/2016	664	SENT TO A	A/L PACKEF	r foi	RD				U	

			Repor	t Description: Work O	order History by Ass	et and System Code			
			WO Close Date	e Range: 07/11/2013	to 08/19/2020	System Code Rang	e: 1100	to	9700
Print Date:	10/6/2020)	Asset# Rar	<u>ige:</u> PT1302	to PT1302				
<u>BUS#</u> S	YS Code	<u>SYS C</u>	ode Description						
PT1302	1401	TROUE	BLESHOOT ELECTRI		al Line Count for Syst	em Code 1401 :	7		<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of W					RATOR COMPLAINT
1510847	1	08/04/2015	752	T/S ELECTRICALS - F	OUND INTERIOR LT.	ON JUMP START. CH B	ATTERY -OK	PUT BA	TTERY ON CHAF
								SC	HEDULED SERVICE
1511332	1	08/12/2015	753	t/s electrical					
								OPE	RATOR COMPLAINT
1513549	1	10/06/2015	762	t/s electrical				_	
	-								HEDULED SERVICE
1415402	2	10/23/2014	809	CHECK FOR POWER	AT WIPER - MOTOR I	NONE PRESENT - CHE	CK FUSES, AL		
101-00-		10/10/2010							
1315997	1	12/12/2013	762	IS ELEC (RICAL S - C	CHECKED POWER TO	COMPUTER STAND FL	JSE. POSS PF		
								OPE	RATOR COMPLAINT
2002337	1	02/13/2020	864	TROUBLESHOOT ELE	ECTRICALSJUMP E	BATTERY			
		00/11/12000						OPE	RATOR COMPLAINT
2013947	13	08/11/2020	833	REAR WIPER WOULD	D NOT WORK WOULD	BLOW FUSE F42			
PT1302	1402		NATOR REPL		al Line Count for Syst	em Code <mark>1402</mark> :	2		Cause-Reason
Work Order #		Close Date	Employee#	Description of W	<u>Vork</u>			OPE	RATOR COMPLAINT
1513549	2	10/06/2015	762	removed altenator				0.05	
4540540	0	40/00/0045	750					OPE	RATOR COMPLAINT
1513549	3	10/06/2015	756	r/r alternator					
PT1302	1407	BATTE	RIES CHECK		al Line Count for Syst	em Code 1407 :	2		<u>Cause-Reason</u>
Work Order #	Line#		Employee#	Description of W				OPE	RATOR COMPLAINT
1418785	1	12/30/2014	820	BATTERIES CHECK -	NEED REPLACEMEN	Т			
								OPE	RATOR COMPLAINT
2002337	2	02/13/2020	864	PERFORMED BATTER	RY LOAD TESTGOO	DCHARGING			
PT1302	1408	BATTE	RIES REPLACE		al Line Count for Syst	em Code <mark>1408</mark> :	5		<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of W					RATOR COMPLAINT
1418785	2	12/30/2014	820	REMOVED/REPLACE	D BATTERY BUT TO F	REMOVE THE BATTERY	/ - I HAD TO R	REMOVE	D THE WIPERS,
								OPE	RATOR COMPLAINT
2013947	14	08/11/2020	783	RR BARTTERY					
								OPE	RATOR COMPLAINT
1513549	5	10/06/2015	756	r/r battery					
								SC	HEDULED SERVICE
1511332	2	08/12/2015	753	batteries replace					
								OPE	RATOR COMPLAINT
1723468	5	01/22/2018	837	INSTALL BATTERY AN	ND CHECK CHARGIN	G SYSTEM			

			Report	Description: Work Or	rder History by Ass	et and System Code			
			WO Close Date	Range: 07/11/2013	to 08/19/2020	System Code Range:	1100	to	9700
Print Date:	10/6/2020)	Asset# Rang	<u>ge:</u> PT1302	to PT1302				
<u>BUS#</u>	SYS Code	<u>SYS C</u>	ode Description						
PT1302	1409	EXTER	RIOR LIGHTING	Tota	al Line Count for Syst	tem Code 1409 :	10		<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of W				OPEI	RATOR COMPLAINT
1612502	1	09/02/2016	797	EXTTERIOR LIGHTING	G REWIRED AND REI	PLACED LIGHT BULB			
								SCH	IEDULED SERVICE
1815093	2	07/16/2018	828	REPALCE RIGHT FRO	NT LIGHT BULB				
								OPEI	RATOR COMPLAINT
1822592	1	10/17/2018	756	R/R LAMP					
	_							SCH	IEDULED SERVICE
1500377	3	01/12/2015	809	R/R L/R TAIL LIGHT BU	ULB			:	
	_							OPEI	RATOR COMPLAINT
2009462	2	05/27/2020	27	PART ON LINE 2				:	
								OPEI	RATOR COMPLAINT
1905853	7	03/29/2019	828	REPALCE DRIVER LIC	CENSE PLATE BULB				
	-								IEDULED SERVICE
1714133	2	08/11/2017	818	BOTTOM AMBER LIGH	HT RUNNING LIGHT	SOCKET FELL OUT OF TU	JRN SINGAL		
0000400		05/07/0000	700					OPEI	RATOR COMPLAINT
2009462	1	05/27/2020	798	EXTERIOR LIGHTING	i				
1010100		00/07/00/0	750					OPEI	RATOR COMPLAINT
1612488	1	09/27/2016	752	EXTERIOR LIGHTING	-REPAIR WIRE			0.0.5	
4540404	4	00/04/0045	70.4					OPEI	RATOR COMPLAINT
1513164	1	09/21/2015	791	EXTERIOR LIGHTING-	REPLC BLOWN BRA	KE LIGHT			
PT1302	1425	CANC	EIVER REPAIR\REPLA		al Line Count for Syst	tem Code 1425 :	1		<u>Cause-Reason</u>
Work Order #			Employee#	Description of W	<u>'ork</u>			SCH	IEDULED SERVICE
1308394	2	07/11/2013	736	Installed canceiver					
PT1302	2201	TROU	BLESHOOT STEERING	SYS Tota	al Line Count for Syst	tem Code 2201 :	2		<u>Cause-Reason</u>
Work Order #	Line#		Employee#	Description of W					RATOR COMPLAINT
1911717	1	07/29/2019	849	T/S STEERING SYSTE	M -CAR PULLS TO T	THE RIGH /ROAD TEST CH	HECKED FRO		
								OPEI	RATOR COMPLAINT
1812021	1	06/08/2018	837	TROUBLESHOOT STE	ERING SYSTEMTIF	RES NEED ROTATING			
PT1302	2208	FRON	T END ALIGNMENT	Tota	al Line Count for Syst	tem Code 2208 :	1		Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of W				SCH	IEDULED SERVICE
2013947	12	08/11/2020	783	NEED ALIGNMENT -AL	LIGNMENT DONE				
PT1302	2214	TIE RO	DD ENDS REPL	Tota	al Line Count for Syst	tem Code 2214 :	1		Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of W				SCF	IEDULED SERVICE
Work Order #		Oldae Date			Ork			001	

			Repo	r <mark>t Descrip</mark>	tion: Work O	rder	History by Ass	et and System Code			
			WO Close Dat	e Range:	07/11/2013	to	08/19/2020	System Code Range:	1100	to	9700
Print Date: 1	0/6/2020)	Asset# Rai	nge:	PT1302	to	PT1302				
BUS# SY	S Code	SYS C	ode Description								
PT1302	2215		PINS REPL		Tot	ol I in	e Count for Syste	om Codo 2215 :	1		Cause-Reason
							e count for Syste		I		CHEDULED SERVICE
Work Order #	Line#	Close Date	Employee# 783		escription of W	OIK				3	CHEDULED SERVICE
2013947	5	08/11/2020	103	control a	arms removed						
PT1302	2223	SWAY	BAR BUSHING REPL	ACE	Tota	al Lin	e Count for Syste	em Code 2223 :	1		<u>Cause-Reason</u>
Work Order #	Line#	<u>Close Date</u>	Employee#	<u>D</u>	escription of W	<u>ork</u>				S	CHEDULED SERVICE
2013947	11	08/11/2020	783	installed	lines and com	plete	d front end job				
PT1302	2300	SUSPE	INSION SYSTEM		Tota	al Lin	e Count for Syste	em Code 2300 :	2		<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	<u>D</u>	escription of W	/ork				S	CHEDULED SERVICE
2013947	9	08/11/2020	833	install dr	riverside lower	fram					
										OF	PERATOR COMPLAINT
2013947	10	08/11/2020	833	INSTAL	L PASSENGE	r si	DE LOWER FRA	ME			
PT1302	2401	FRONT	AXLE		Tota	al Lin	e Count for Syste	em Code <mark>2401</mark> :	1		<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	D	escription of W	/ork				OF	PERATOR COMPLAINT
1601315	4	02/09/2016	797	REPLAC	CE CV JOINT						
PT1302	2403	FRONT	HUB BEARINGS RE	PL	Tota	al Lin	e Count for Syste	em Code <mark>2403</mark> :	3		Cause-Reason
Work Order #	Line#	Close Date	Employee#	D	escription of W	/ork				S	UPERVISOR DEFECT
1601315	3	02/09/2016	819	R/R FR	ONT BEARING	6					
										S	UPERVISOR DEFECT
1601315	3	02/09/2016	756	R/R FR	ONT BEARING	3					
										S	UPERVISOR DEFECT
1601315	3	02/09/2016	797	R/R FR	ONT BEARING	3				-	
	•					-					

			Report	Description: Work O	order History by Ass	set and System Code		
			WO Close Date	Range: 07/11/2013	to 08/19/2020	System Code Range:	1100	to 9700
Print Date:	10/6/2020)	Asset# Rang	<u>ge:</u> PT1302	to PT1302			
<u>BUS#</u>	SYS Code	<u>SYS Co</u>	de Description					
PT1302	2500	BODY			al Line Count for Sys	tem Code 2500 :	14	<u>Cause-Reason</u>
Work Order # 1906958	<u>‡ Line#</u> 7	<u>Close Date</u> 05/28/2019	Employee# 828	<u>Description of W</u> R/R HEATSHIELD	<u>Vork</u>			SCHEDULED SERVICE
1906958	3	05/28/2019	828	REPAIR HEATSHIELD				SCHEDULED SERVICE
1710031	5 1	06/08/2017	818	SECURED UNDER C				OPERATOR COMPLAINT
1911717	4	07/29/2019	849			HANDLE INSIDE TRUNK AR		OPERATOR COMPLAINT
1500377	4	01/12/2015	756	INSTALLED MISSING		-	EA	SCHEDULED SERVICE
1617062	4	12/15/2016	809	BODY		JARGE		OPERATOR COMPLAINT
1805694	8	03/29/2018	809					OPERATOR COMPLAINT
1412425	1	09/10/2014	752	BODY-ORDER PART				OPERATOR COMPLAINT
1412425	2	09/10/2014	819	REPLC HANDLE				OPERATOR COMPLAINT
1905853	6	03/29/2019	828	REPLACE REAR WIPE	ER BLADE			OPERATOR COMPLAINT
2003488	1	03/05/2020	869	BODYR/R NEW LAI				SCHEDULED SERVICE
1505561	1	04/09/2015	818	BODY REPAIR				OPERATOR COMPLAINT
1824091	2	11/12/2018	797	REPLACE SEAT HAN	DLE			OPERATOR COMPLAINT
1905853	2	03/29/2019	828	REPLACE SCREWS C				OPERATOR COMPLAINT
PT1302	2501	ACCIDE	NT DAMAGE REPAIR	R Tota	al Line Count for Sys	tem Code 2501 :	1	Cause-Reason
Work Order # 1516303	<u>ŧ Line#</u> 1	<u>Close Date</u> 01/20/2016	<u>Employee#</u> 27	<u>Description of W</u> accident damage repai		Auto Body		OPERATOR COMPLAINT

			Report	Description: Work Order History by Asset and System Code		
			WO Close Date	Range: 07/11/2013 to 08/19/2020 System Code Range	je: 1100	to 9700
Print Date:	10/6/2020		Asset# Rang	ge: PT1302 to PT1302		
<u>BUS#</u> S	<u>YS Code</u>	<u>SYS Cod</u>	e Description			
PT1302	2505	WIPERS		Total Line Count for System Code 2505 :	4	Cause-Reason
Work Order #			Employee#	Description of Work		OPERATOR COMPLAINT
1604606	1	04/01/2016	752	WIPERSREPLC RIGHT SIDE MOTOR WIPERS		
						OPERATOR COMPLAINT
1605329	1	04/20/2016	752	REPLACE WIPERS		
						SCHEDULED SERVICE
1914449	2	08/07/2019	746	REPLCD BOTH WIPERS		
						SCHEDULED SERVICE
2013947	2	08/11/2020	783	wiper charge cut only		
PT1302	2506	DOORS		Total Line Count for System Code 2506 :	3	<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
2010045	1	06/04/2020	864	DOORSL/REAR DOESNT CLOSEREPAIRED DOOR LATCH		
						OPERATOR COMPLAINT
2010045	2	06/04/2020	864	R/R REAR DOOR LATCH ASSEMBLYPOO		
						OPERATOR COMPLAINT
2010045	3	06/04/2020	864	R/R DOOR LATCH		
PT1302	2511	DRIVER	SEATS	Total Line Count for System Code 2511 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1810921	1	05/29/2018	780	DRIVER SEATS -RR CUSHIONS COVERS AND BACK SPRING		
						OPERATOR COMPLAINT
1810921	1	05/29/2018	837	DRIVER SEATS -RR CUSHIONS COVERS AND BACK SPRING		
						OPERATOR COMPLAINT
1617062	2	12/15/2016	809	REPLACED DRIVER SEAT CUSHIONS, COVER BOTTOM AND BA	СК	
PT1302	2601	TROUBL	ESHOOT BRAKES	Total Line Count for System Code 2601 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1601315	7	02/09/2016	809	T/S BRAKES		
PT1302	2603	FRONT R	ELINE	Total Line Count for System Code 2603 :	1	Cause-Reason
Work Order #		Close Date	Employee#	Description of Work	-	SCHEDULED SERVICE
1714133	3	08/11/2017	809	R/R FRONT BRAKE PADS		
PT1302	2604	REAR RE		Total Line Count for System Code 2604 :	1	Cause-Reason
Work Order #		Close Date	Employee#	Description of Work	-	SCHEDULED SERVICE
1714133	<u>Line#</u> 4	08/11/2017	809	R/R REAR BRAKE PADS		
PT1302	2616		SOR REPLACE	Total Line Count for System Code 2616 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
		02/09/2016	809	R/R L/F ABS SPEED SENSOR		

			Report	Description: Work Orde	er History by Asset	t and System Code			
			WO Close Date	Range: 07/11/2013 to	08/19/2020	System Code Range:	1100	to	9700
Print Date:	10/6/2020)	Asset# Ran	<u>ie:</u> PT1302 to	o PT1302				
BUS# S	YS Code	SYS Code	<u> Description</u>						
PT1302	2800	ENGINE			ine Count for Syster	m Code <mark>2800</mark> :	5		<u>Cause-Reason</u>
<u>Work Order #</u> 1601392	Line# 3	<u>Close Date</u> 02/01/2016	Employee# 747	Description of Work	<u>x</u>			OF	PERATOR COMPLAINT
1001392	3	02/01/2010	747	ADDED OIL TO ENGINE				S	CHEDULED SERVICE
1906958	6	05/28/2019	828	REPLCD EVAP CANISTE	R & SOLENOID				
								OF	PERATOR COMPLAINT
1602704	4	03/02/2016	818	RR THROTTLE BODY				~	PERATOR COMPLAINT
1919027	4	11/14/2019	783	RECEIVED EVAP PARTS	S			OF	
	•				-			OF	PERATOR COMPLAINT
1810921	3	05/29/2018	837	RR 02 SENSORS					
PT1302	2801	TROUBLE	ESHOOT ENGINE		ine Count for Syster	n Code 2801 :	12		<u>Cause-Reason</u>
Work Order #			Employee#	Description of Work					PERATOR COMPLAINT
1905853	3	03/29/2019	828	.CEL CODE PO451 EVAP	ORATIVE SYSTEM	PURGE VALVE IS DEFE	STIVE POC		PERATOR COMPLAINT
1919027	1	11/14/2019	783	TROUBLESHOOT ENGIN	NECODE 451CH	K FOR LEAKSROAD TE	ST	01	
								OF	PERATOR COMPLAINT
1919027	2	11/14/2019	783	TROUBLESHOOT ENGIN	NEORDERED PRI	ESSURE SENSOR			
1922775	1	12/18/2019	866	TROUBLESHOOT ENGIN				OF	PERATOR COMPLAINT
1922115	1	12/10/2019	800	TROUBLESHOOT ENGIN	NECHECKFORE	ATAUST FUNES		OF	PERATOR COMPLAINT
1602572	1	02/22/2016	828	t/s engine					
								OF	PERATOR COMPLAINT
1602704	1	03/02/2016	818	T/S ENIGINE				~	
1603108	1	03/02/2016	828	T/S ENGINE DTC ACTIVE	E ON EVAPORATE	SYSTEM		S	CHEDULED SERVICE
1000100	•		020					OF	PERATOR COMPLAINT
1602704	3	03/02/2016	818	NEED THROTTLE BODY	AND CODE P211 EN	NGINE WENT INTO LIMP	MODE		
4000070	0	00/14/0010	000					OF	PERATOR COMPLAINT
1802873	3	02/14/2018	832	NO LEAKS FOUND-CLE	ARED CODES			OF	PERATOR COMPLAINT
1911717	3	07/29/2019	849	CHECKED ENGINE CODE	E HAS A PO451 EVA	P PRESSURE SENSOR	CODE NEE		
						-			PERATOR COMPLAINT
1803231	6	03/13/2018	837	T/S NENGINE - MOTOR N	MOUNT UPPER TRA	ANS MOUNT -2 HOUR T	RANS MOL		
1600000	1	07/12/2016	707					OF	PERATOR COMPLAINT
1609822	1	07/12/2016	797	TROUBLESHOOT ENGIN	IEUK/DIAGNUSE E	INGINEINO CODES			

Print Date 108/202 System Code Rame: 100 10 100 Print Date 106/202 Assett Rame: PT1302 10 PT1302 SVS Code SYS Code				Report	Description: Work O	rder History by Ass	et and System Code		
Assets Priod D Priod BUSE SYS Code SYS Code SYS Code SYS Code SYS Code Cases-Reason P11302 2809 AR INTAKE SYSTEM REPAIR Total Line Count for System Code 2809 : 2 Cases-Reason Work Order # 1602572 2 2 222/2016 Employee# Description of Work OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REM/D PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wirring OPERATOR COMPLAINT P11302 2810 AIR FILTER REPL Total Line Count for System Code 2810 : 1 Cases-Reason York Order # Line# Close Date Employee# Description of Work SCHEDULED SERVICE P11302 2816 ENDINE CASKETT/SEALS REPL Total Line Count for System Code 2816 : 2 Cases-Reason York Order # Line# Close Date Employee# Description of Work SCHEDULED SERVICE 196968 5 OS(28/2019 828 COMPLETE VALVE COVER, INSTALL COL PACKS, LINESWIP SCHEDULED SERVICE 1960661 5				WO Close Date I	Range: 07/11/2013	to 08/19/2020	System Code Range:	1100	to 9700
PT1302 2809 AIR INTAKE SYSTEM REPAIR Total Line Count for System Code 2809 :: 2 Cause-Reason Work Order # 1900572 Line# Close Date 2 Employee# 202/2/2016 Employee# 288 Close Date 2 Close Date 2 OPERATOR COMPLAINT oPERATOR COMPLAINT 000000000000000000000000000000000000	Print Date: 1	0/6/2020)	Asset# Rang	<u>e:</u> PT1302	to PT1302			
Work Order # 1802572 Line# Close Date 2 Employee# 828 Description of Work clean throttle body and clear out codes OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wiring OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wiring OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wiring OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wiring SCHEDULED SERVICE 1919028 2816 ENGINE GASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason 1906958 5 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, LINES-WIP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 10/14/2018 857 RMOTOR MOUNTS REPL Total Line Count for System Code 2818 : 1	BUS# SY	S Code	SYS C	ode Description					
Initial State 2 0/222/2016 628 clean throtitle body and clear out codes OPERATOR COMPLAINT 1919027 5 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wining OPERATOR COMPLAINT PT1302 2810 AIR FILTER REPL Total Line Count for System Code 2810 : 1 Cause-Reason Work Order #1 Line# Close Date Employee# Description of Work SCHEDULED SERVICE PT1302 2816 ENGINE CASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason Work Order #1 Line# Close Date Employee# Description of Work SCHEDULED SERVICE 1906958 5 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, LINESWP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER OPERATOR COMPLAINT 1906957 1 Cause-Reason OPERATOR COMPLAINT OPERATOR COMPLAINT 1906958 8 05/28/2019 828 REMOTOR MOUNTS OPERATOR COMPLAINT <td>PT1302</td> <td>2809</td> <td></td> <td>TAKE SYSTEM REPAIR</td> <td>t Tota</td> <td>al Line Count for Syst</td> <td>em Code 2809 :</td> <td>2</td> <td>Cause-Reason</td>	PT1302	2809		TAKE SYSTEM REPAIR	t Tota	al Line Count for Syst	em Code 2809 :	2	Cause-Reason
PT1302 251 11/14/2019 783 REMVD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator winting PT1302 2810 AIR FILTER REPL Total Line Count for System Code 2810 : 1 Cause-Reason Work Order # 17/14/33 Line# 6 Close Date Employee# Employee# Description of Work RIR RIR FILTER Total Line Count for System Code 2816 : 2 Cause-Reason PT1302 2816 ENGINE GASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason Vork Order # 1906958 Infed 5 Glose Date Employee# Description of Work RIR RIR FILTER Total Line Count for System Code 2816 : 1 Cause-Reason 1906958 5 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER Cause-Reason 1906958 1 Cause-Reason OPERATOR COMPLAINT Complant 1906958 1 Cause-Reason OPERATOR COMPLAINT 191027 2819 ENGINE SWIT/SENS/THERM NE									OPERATOR COMPLAINT
1919027 5 11/14/2019 783 REMUD PLENUM, CRANK CASE FILTER, PVC, ORDERED alternator wiring PT1302 2810 ARR FLER REPL Total Line Count for System Code 2810 : 1 Cause-Reason Work Order # 1714133 Line 6 Colligion of Work 6 Description of Work RR AIR FILTER Total Line Count for System Code 2816 : 2 Cause-Reason PT1302 2816 ENGINE GASKET SISEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason 1906958 5 56/28/2019 828 ChOPLETE VALVE COVER GASKET-REMV COIL PACKS, LINES-WIP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, GASKET -REMV COIL PACKS, WINDSHIELD COVER Cause-Reason 971302 2818 ENGINE MOUNTS REPL Total Line Count for System Code 2818 : 1 Cause-Reason 971302 2819 ENGINE MOUNTS REPL Total Line Count for System Code 2819 : 3 Cause-Reason 971302 2819 ENGINE MOUNTS REPL Total Line Count for System Code 2819 : 3 Cause-Reason 971302 2819 ENGINE MOUNTS REPL Total Line Count for System Code 2819 : 3 Cause-Reason </td <td>1602572</td> <td>2</td> <td>02/22/2016</td> <td>828</td> <td>clean throttle body and</td> <td>clear out codes</td> <td></td> <td></td> <td></td>	1602572	2	02/22/2016	828	clean throttle body and	clear out codes			
PT1302 2810 AIR FILTER REPL Total Line Count for System Code 2810 : 1 Cause-Reason Work Order # 1714133 Line# 6 Close Date Employee# 809 Description of Work R/R AIR FILTER SCHEDULED SERVICE PT1302 2816 ENGINE GASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason Work Order # 1906958 Line# 05/28/2019 SCHEDULED SERVICE SCHEDULED SERVICE 1906958 05/28/2019 828 R/R VALVE COVER GASKETREMV COIL PACKS, LINESWIP SCHEDULED SERVICE 1906958 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 18032317 03/33/2018 837 RR MOTOR MOUNTS OPERATOR COMPLAINT 18032317 03/39/2019 828 REPLACE EVAPORATIVE SYSTEM PURGE VALVE OPERATOR COMPLAINT 1919027 3 03/20/2016<	1010027	5	11/1//2010	783		ANK CASE EILTER P		rina	OPERATOR COMPLAINT
Work Order # 17/14/33 Line# 6 Close Date 08/11/2017 Employee# 809 Description of Work R/R AIR FILTER SCHEDULED SERVICE PT1302 2816 ENGINE GASKETS/SEALS REPL 1906958 Total Line Count for System Code 2816 : 5 2 Cause-Reason SCHEDULED SERVICE 1906958 5 05/28/2019 B28 R/R VALVE COVER GASKET-REMV COIL PACKS, LINESWIP SCHEDULED SERVICE SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER OPERATOR COMPLAINT 1803231 7 03/13/2018 837 RR MOTOR MOUNTS OPERATOR COMPLAINT 1919027 3 11/14/2019 783 REPLE VAP VALVE-STILL 1 CODE-ORDERED PVC OPERATOR COMPLAINT 1906958 5 03/29/2019 828 CLEAN UP CONNECTIONS OPERATOR COMPLAINT 1906927 7 11/14/2019 783		-				-		•	
Initial Triation Initial Construction Initial Construction Initial Construction Initial Construction PT1302 2816 ENGINE GASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason Work Order # Line # Close Date Employee# Description of Work SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER GASKET-REMV COIL PACKS, LINESWIP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER OPERATOR COMPLAINT 1903231 7 03/13/2018 837 Remotore Mork OPERATOR COMPLAINT 191302 2819 Ensployee# Description of Work OPERATOR COMPLAINT 19190277 3 11/14/2019 783 REPLACE EVAPORATIVE SYSTEM PURGE VALVE OPERATOR COMPLAINT 1905653 5 03/29/2019 828 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>em Code 2810 :</td><td>1</td><td></td></td<>							em Code 2810 :	1	
PT1302 2816 ENGINE GASKETS/SEALS REPL Total Line Count for System Code 2816 : 2 Cause-Reason Work Order # Line# Close Date Employee# Description of Work SCHEDULED SERVICE 1906958 8 05/28/2019 828 R/R VALVE COVER GASKETREMV COIL PACKS, LINESWIP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER OPERATOR COMPLAINT 1803231 7 03/13/2018 837 R MOTOR MOUNTS Description of Work OPERATOR COMPLAINT 1919027 3 11/ref Close Date Employee# Description of Work OPERATOR COMPLAINT 1919027 3 03/29/2016 828 REPLACE EVAPORATIVE SYSTEM PURGE VALVE OPERATOR COMPLAINT <td></td> <td></td> <td></td> <td></td> <td></td> <td><u>/ork</u></td> <td></td> <td></td> <td>SCHEDULED SERVICE</td>						<u>/ork</u>			SCHEDULED SERVICE
Work Order # 1966958 Line# 5 Close Date 05/28/2019 Employee# 828 Description of Work R/R VALVE COVER GASKET-REMV COIL PACKS, LINESWIP SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER SCHEDULED SERVICE 190697 10 ENGINE SWIT/SENS/THERM RE 03/13/2018 Total Line Count for System Code 2819 : 3 Cause-Reason Work Order # 1919027 11/14/2019 783 REPL EVAP VALVE-STILL 1 CODEORDERED PVC OPERATOR COMPLAINT 1905853 5 03/29/2016 828 CLEAN UP CONNECTIONS OPERATOR COMPLAINT 1919027 8 11/14/2019 783 DEscription of Work DROPPED GAS TANK-R/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINT 1919		-							
Indication Indication <thindication< th=""> Indication Indication<td></td><td></td><td></td><td></td><td></td><td></td><td>em Code 2816 :</td><td>2</td><td></td></thindication<>							em Code 2816 :	2	
1906958 8 05/28/2019 828 COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVER PT1302 2818 ENGINE MOUNTS REPL Total Line Count for System Code 2818 : 1 Cause-Reason Work Order # 1803231 Case Date 7 Emgloyee# 03/13/2018 Emgloyee# 837 Total Line Count for System Code 2819 : 3 Cause-Reason PT1302 2819 ENGINE SWIT/SENS/THERM RE Total Line Count for System Code 2819 : 3 Cause-Reason PT1302 2819 ENGINE SWIT/SENS/THERM RE Total Line Count for System Code 2819 : 3 Cause-Reason Work Order # 1905853 Line# 5 Glose Date 03/22/2019 Employee# 828 REPLACE EVAP VALVE-STILL 1 CODE-ORDERED PVC OPERATOR COMPLAINT PT1302 282 FUEL LINES REPL Total Line Count for System Code 2822 : 2 Cause-Reason PT1302 282 FUEL LINES REPL Total Line Count for System Code 2822 : 2 Cause-Reason PT1302 282 FUEL LINES REPL Total Line Count for System Code 2822 : 2 Cause-Reason 1919027 7 11/14/2019 783 COMPLETED EVAP Description of Work OPERATOR COMPLAINT <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>PACKS LINES WIP</td> <td></td> <td>SCHEDULED SERVICE</td>							PACKS LINES WIP		SCHEDULED SERVICE
1906958805/28/2019828COMPLETE VALVE COVER, INSTALL COIL PACKS, WINDSHIELD COVERPT13022818ENGINE MOUNTS REPLTotal Line Count for System Code 2818 : 1Cause-ReasonWork Order # 1803311Close Date 7Employee# 03/13/2018Description of Work RR MOTOR MOUNTSOPERATOR COMPLAINTPT1302289ENGINE SWIT/SENS/THER METotal Line Count for System Code 2819 : 3Cause-ReasonPT1302Line # 2005 DateCose Date Employee#Description of Work RR MOTOR MOUNTSOPERATOR COMPLAINT1919027311/14/2019783Description of Work REPL EVAP VALVE-STILL 1 CODE-ORDERED PVCOPERATOR COMPLAINT1905853203/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT1905853203/29/2016828CLEAN UP CONNECTIONSOPERATOR COMPLAINT1919027711/14/2019783Description of Work REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT OPERATOR COMPLAINT19190272811/14/2019R83COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT OPERATOR COMPLAINT	1900900	5	03/20/2019	020			TACKO, LINEOWIT		SCHEDULED SERVICE
Work Order # 1803231 Line# 7 Close Date 03/13/2018 Employee# 837 Description of Work RR MOTOR MOUNTS OPERATOR COMPLAINT PT1302 2819 ENGINE SWIT/SENS/THERM RE Line# 1919027 Total Line Count for System Code 2819 : 3 Cause-Reason Work Order # 1919027 Line# 3 Close Date 11/14/2019 Employee# 783 Description of Work REPL EVAP VALVESTILL 1 CODEORDERED PVC OPERATOR COMPLAINT 1905853 5 03/29/2019 828 REPLACE EVAPORATIVE SYSTEM PURGE VALVE OPERATOR COMPLAINT 1603108 2 03/02/2016 828 CLEAN UP CONNECTIONS OPERATOR COMPLAINT 1905873 7 11/14/2019 783 Description of Work REPL EVAP VALVESTILL 1 CODEORDERED PVC OPERATOR COMPLAINT 1905873 5 03/02/2016 828 CLEAN UP CONNECTIONS OPERATOR COMPLAINT 1907 7 11/14/2019 783 Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINT 1919027 8 11/14/2019 783 COMPLETED EVAP & PVC CRANKCASE FILTER OPERATOR COMPLAINT 1919027	1906958	8	05/28/2019	828	COMPLETE VALVE CO	OVER, INSTALL COIL	PACKS, WINDSHIELD CO	VER	
International procession of the state o	PT1302	2818	ENGIN	E MOUNTS REPL	Tota	al Line Count for Syst	em Code 2818 :	1	Cause-Reason
PT13022819ENGINE SWIT/SENS/THERM RETotal Line Count for System Code 2819 : 3Cause-ReasonWork Order # 1919027Line# 3Close Date 11/14/2019Employee# 783Description of Work REPL EVAP VALVESTILL 1 CODEORDERED PVCOPERATOR COMPLAINT OPERATOR COMPLAINT1905853503/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT1603108203/02/2016828CLEAN UP CONNECTIONSOPERATOR COMPLAINTPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 : PERATOR COMPLAINT2Cause-Reason OPERATOR COMPLAINT1910927711/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT19190272827E.C.M. PROGRAMDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINT102704203/02/2016818RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-Reason OPERATOR COMPLAINTPT13022828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828 <t< td=""><td>Work Order #</td><td>Line#</td><td>Close Date</td><td></td><td></td><td>/ork</td><td></td><td></td><td>OPERATOR COMPLAINT</td></t<>	Work Order #	Line#	Close Date			/ork			OPERATOR COMPLAINT
Work Order # 1919027Line# 3Close Date 11/14/2019Employee# 783Description of Work REPL EVAP VALVESTILL 1 CODEORDERED PVCOPERATOR COMPLAINT OPERATOR COMPLAINT1905853503/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT1603108203/02/2016828CLEAN UP CONNECTIONSOPERATOR COMPLAINT16031072822FUEL LINES REPLTotal Line Count for System Code 2822 : Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINTOPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/124/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/124/2019818RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT19190272827E.C.M. PROGRAMDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT1910272828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT1910272828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COM	1803231	7	03/13/2018	837	RR MOTOR MOUNTS				
Instruction 1919027Interface 3Interface 11/14/2019REPLEVAP 783REPLEVAP VALVESTILL 1 CODEORDERED PVCOPERATOR COMPLAINT OPERATOR COMPLAINT1905853503/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVE OPERATOR COMPLAINTOPERATOR COMPLAINT OPERATOR COMPLAINT1603108203/02/2016828CLEAN UP CONNECTIONSOPERATOR COMPLAINT OPERATOR COMPLAINTPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-Reason OPERATOR COMPLAINT OPERATOR COMPLAINT DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINTOPERATOR COMPLAINT OPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT191027811/14/2019818RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINT1910272811/14/2019818COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT191027811/14/2019818COLECALIBRATED THROTTLE BODY POSITION SENSOR <td< th=""><th>PT1302</th><th></th><th></th><th></th><th></th><th></th><th>em Code 2819 :</th><th>3</th><th></th></td<>	PT1302						em Code 2819 :	3	
19058535OPERATOR COMPLAINT PERATOR COMPLAINT1905853503/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT1603108203/02/2016828CLEAN UP CONNECTIONS22Cause-ReasonPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-ReasonVork Order #11/14/2019783Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT 19190270PERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/14/2019818Description of Work 									OPERATOR COMPLAINT
1905853503/29/2019828REPLACE EVAPORATIVE SYSTEM PURGE VALVEOPERATOR COMPLAINT1603108203/02/2016828CLEAN UP CONNECTIONSOPERATOR COMPLAINTPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-ReasonWork Order # 191902711/14/2019Employee# 783Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINTOPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/12/2016Employee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINT160270422828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT COMPLAINT1713022828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-ReasonPT13022828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-ReasonWork Order #Line#Close DateEmployee#Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR0OPERATOR COMPLAINT	1919027	3	11/14/2019	783	REPLEVAP VALVE	STILL 1 CODEORDE	RED PVC		
1603108203/02/2016828CLEAN UP CONNECTIONSPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-ReasonWork Order #Line#Close DateEmployee#Description of Work DROPPED GAS TANK-R/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK DROPPED GAS TANK-R/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027810/14/2019783Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT10027042818MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-ReasonPT13022828MOTOR WASH ENGINEDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-ReasonWork Order #Line#Close Date Employee#Employee#Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1<	1005853	5	03/20/2010	828					OPERATOR COMPLAINT
1603108203/02/2016828CLEAN UP CONNECTIONSPT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-ReasonWork Order # 1919027Line# 7Close Date 11/14/2019Employee# 783Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT1919027811/14/2019783Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT10027042Close DateEmployee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-ReasonWork Order # Line#Line#Close DateEmployee# Employee#Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR0Work Order # Work Order #Line#Close DateEmployee# Employee#Description of Work Description of Work RECALIBRATED THROTTLE BODY POSITION SEN	1000000	0	00/20/2010	520					OPERATOR COMPLAINT
PT13022822FUEL LINES REPLTotal Line Count for System Code 2822 :2Cause-ReasonWork Order # 1919027Line# 7Close Date 11/14/2019Employee# 783Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK DPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINTPT13022827E.C.M. PROGRAMDescription of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-Reason OPERATOR COMPLAINTWork Order # Uork Order # Line#Line# Close Date Employee#Description of Work Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-Reason	1603108	2	03/02/2016	828	CLEAN UP CONNECT	IONS			
Work Order # 1919027Line# 7Close Date 11/14/2019Employee# 783Description of Work DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINT OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINTPT13022827E.C.M. PROGRAMTotal Line Count for System Code 2827 : 1Cause-ReasonWork Order # 16027042Close Date 03/02/2016Employee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 : 1Cause-ReasonWork Order # Line#Line#Close Date Close DateEmployee# Employee#Description of Work Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT	PT1302	2822	FUEL L	INES REPL	Tota	al Line Count for Syst	em Code 2822 :	2	Cause-Reason
1919027711/14/2019783DROPPED GAS TANKR/R FUEL PRESSURE SENSOR HOSEREINSTALLED GAS TANK OPERATOR COMPLAINT1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTEROPERATOR COMPLAINTPT13022827E.C.M. PROGRAMTotal Line Count for System Code 2827 :1Cause-ReasonWork Order # 1602704203/02/2016Employee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-ReasonWork Order # Line#Line# Close DateEmployee# Employee#Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR1Cause-ReasonWork Order # Line#Line# Close DateEmployee# Employee#Description of Work Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR0OPERATOR COMPLAINTWork Order # Line#Line# Close DateEmployee# Employee#Description of Work Description of Work Description of WorkOPERATOR COMPLAINT	Work Order #		Close Date	Employee#					OPERATOR COMPLAINT
1919027811/14/2019783COMPLETED EVAP & PVC CRANKCASE FILTERPT13022827E.C.M. PROGRAMTotal Line Count for System Code 2827 :1Cause-ReasonWork Order # 1602704Line # 2Close Date 03/02/2016Employee # 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-Reason OPERATOR COMPLAINTWork Order #Line #Close DateEmployee #Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOR0PERATOR COMPLAINT		7			DROPPED GAS TANK	R/R FUEL PRESSU	JRE SENSOR HOSEREIN	STALLED (GAS TANK
PT13022827E.C.M. PROGRAMTotal Line Count for System Code 2827 :1Cause-ReasonWork Order # 1602704Line# 2Close Date 03/02/2016Employee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINT OPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-ReasonWork Order # Line#Line# Close DateEmployee# Employee#Description of Work Description of Work Description of WorkOPERATOR COMPLAINT									OPERATOR COMPLAINT
Work Order # 1602704Line# 2Close Date 03/02/2016Employee# 818Description of Work RECALIBRATED THROTTLE BODY POSITION SENSOROPERATOR COMPLAINTPT13022828MOTOR WASH ENGINETotal Line Count for System Code 2828 :1Cause-ReasonWork Order #Line#Close DateEmployee#Description of WorkOPERATOR COMPLAINT	1919027	8	11/14/2019	783	COMPLETED EVAP &	& PVC CRANKCASE F	ILTER		
International of the state	PT1302	2827	E.C.M.	PROGRAM	Tota	al Line Count for Syst	em Code 2827 :	1	Cause-Reason
PT1302 2828 MOTOR WASH ENGINE Total Line Count for System Code 2828 : 1 Cause-Reason Work Order # Line# Close Date Employee# Description of Work OPERATOR COMPLAINT									OPERATOR COMPLAINT
Work Order # Line# Close Date Employee# Description of Work OPERATOR COMPLAINT	1602704	2	03/02/2016	818	RECALIBRATED THRO	OTTLE BODY POSITI	ON SENSOR		
	PT1302	2828	мото	R WASH ENGINE	Tota	al Line Count for Syst	em Code <mark>2828 :</mark>	1	Cause-Reason
2013947 15 08/11/2020 783 WAS HE ENGINE -CLEAN INTERIOR GLASS									OPERATOR COMPLAINT
	2013947	15	08/11/2020	783	WAS HE ENGINE -CLI	EAN INTERIOR GLA	SS		

			Penor	Descri	ntion: Work O	rdor	History by Ass	et and System Code			
Print Date:	10/6/2020		WO Close Date	Range:	07/11/2013 PT1302	to to	08/19/2020 PT1302	System Code Range	e: 1100	to	9700
BUS# SY	YS Code	<u>SYS Co</u>	de Description								
PT1302	2843	R&R EN	IGINE BREATHER FI	TER	Tota	l Lin	e Count for Syst	tem Code 2843 :	1		<u>Cause-Reason</u>
Work Order # 1919027		<u>Close Date</u> 11/14/2019	Employee# 783	r/r cra	Description of W nkcase filterrep		take alternator			OF	PERATOR COMPLAINT
PT1302	2900	TRANS	MISSION		Tota	l Lin	e Count for Syst	tem Code 2900 :	1		Cause-Reason
<u>Work Order #</u> 1714133		<u>Close Date</u> 08/11/2017	Employee# 809	R/R L	Description of W EFT FRONT AXI					S	CHEDULED SERVICE
PT1302	2918	TRANS	MOUNT REPLACE		Tota	l Lin	e Count for Syst	tem Code 2918 :	2		Cause-Reason
Work Order #	Line#	Close Date	Employee#		Description of W	ork				O	PERATOR COMPLAINT
1810921	4	05/29/2018	837	INSTA	LL TRANS MAIN	IT				OF	PERATOR COMPLAINT
1810921	2	05/29/2018	837	REMO	VED UPPER TR	ANS	MAINT -WIP				

			Repo	ort Descrip	tion: Work O	rder	History by Asse	t and System Code			
			WO Close Da	te Range:	07/11/2013	to	08/19/2020	System Code Rang	le: 1100	to	9700
Print Date:	10/6/2020)	<u>Asset# Ra</u>	nge:	PT1302	to	PT1302				
BUS#	SYS Code	SYS Cod	e Description								
PT1302	4000	TIRES			Tota	ıl Lin	e Count for Syste	m Code 4000 :	16		<u>Cause-Reason</u>
Work Order a	<u> Line#</u>	Close Date	Employee#		escription of W					OF	PERATOR COMPLAINT
1417562	1	12/02/2014	756	TIRES -	CK TIRES - NO	ONE	IN STOCK				
										OF	PERATOR COMPLAINT
1417562	2	12/02/2014	668	WENT T	O TIRE SHOP	FOR	TIRE REPLACEN	IENT			
										OF	PERATOR COMPLAINT
1417768	1	12/04/2014	764	TIRES -	SPARES TIRE	S					
										OF	PERATOR COMPLAINT
1815633	1	07/23/2018	828	TIRES	-REPAIR RIGH	T FR	ONT TIRE WITH	A PLUGCK ALL TIRES	3		
										OF	PERATOR COMPLAINT
1707714	1	05/04/2017	752	RR BOT	H REAR TIRE	S					
										S	CHEDULED SERVICE
1508928	2	06/22/2015	809	REPLAC	ED BOTH FR	ОИТ .	TIRES.				
										OF	PERATOR COMPLAINT
1416510	1	11/12/2014	752	TIRES -	REPAIR TIRE						
										OF	PERATOR COMPLAINT
1911717	2	07/29/2019	849	SWAPP	ED BOTH FRO	DNT	TIRES AND PUL	L WENT FROM RIGHT	TO LEFT SO	THE C	AR HAS A TIRE P
										s	CHEDULED SERVICE
1914449	3	08/07/2019	746	ADJUS1		RESS	URE ON ALL TIR	ES			
										OF	PERATOR COMPLAINT
1911717	5	07/29/2019	828	ROTAT	E TIRES AND F	REPL	ACE 2 FRONT TIF	RES			
-				-						OF	PERATOR COMPLAINT
1508979	2	06/22/2015	752		NT REPAIR-NE	EDS	NEW TIRF			51	
	-			00000		0				OF	PERATOR COMPLAINT
1508979	3	06/22/2015	809	REPLC	LEFT FRONT	FIRF				51	
	Ŭ		500	20						OF	PERATOR COMPLAINT
1507050	2	05/06/2015	752	REPAIR	ED FLAT TIRE					01	
1001000	2	00,00,2010	102								PERATOR COMPLAINT
1812021	2	06/08/2018	837	ROTATI	TIRES					01	
1012021	2	00,00,2010	507								PERATOR COMPLAINT
1913342	3	07/22/2019	786		ED TIRE L/R					Ur	
1313342	5	0112212019	700	NEFLAU							PERATOR COMPLAINT
1601315	1	02/09/2016	29		ND ALIGHNM					OF	
				IIRES F							
PT1302	4001	TIRE REF					e Count for Syste	m Code 4001 :	2		<u>Cause-Reason</u>
Work Order a		Close Date	Employee#		escription of W					OF	PERATOR COMPLAINT
1512210	2	08/31/2015	818	REMOV	ED & REPLAC	ED T	IRE				
										OF	PERATOR COMPLAINT
2010045	4	06/04/2020	864	REPAIR	RR TIRE						

			Report	Description: Work Or	r der H	listory by A	sset and	System Code			
			WO Close Date I	Range: 07/11/2013	to	08/19/2020	S	ystem Code Range	e: 1100	to	9700
Print Date:	10/6/2020	I	<u>Asset# Rang</u>	<u>e:</u> PT1302	to	PT1302					
BUS#	SYS Code	<u>SYS (</u>	Code Description								
PT1302	4012	R/F TI	RE REPLACEMENT	Tota	al Line	Count for Sy	ystem Coo	de 4012 :	2		<u>Cause-Reason</u>
Work Order 1702527	<u># Line#</u> 1	Close Date 02/14/2017	Employee# 773	Description of W R/F TIRE REPLACEME							
1500377	2	01/12/2015	809	R/R R/F TIRE						s	CHEDULED SERVICE
PT1302	4013	L/R/O	TIRE REPLACEMENT	Tota	al Line	Count for Sy	ystem Co	de 4013 :	4		<u>Cause-Reason</u>
<u>Work Order :</u> 1817097	<u># Line#</u> 1	<u>Close Date</u> 08/08/2018	Employee# 809	Description of W L/R/O TIRE REPLACE						OF	PERATOR COMPLAINT
2013947	3	08/11/2020	783	rr reat tires						S	CHEDULED SERVICE
1905853	1	03/29/2019	828	LRO TIRE REPLACEM	ENT -I	REPAIR TIRE	E WITH PI	LUG ROTATE ALI	_ TIRES AND	REPL	PERATOR COMPLAINT ACE 5 LUG NUTS PERATOR COMPLAINT
1824091	1	11/12/2018	797	LRO -REPLACEMENT							
PT1302	4015	R/R/O	TIRE REPLACEMENT			Count for Sy	ystem Co	de 4015 :	1		<u>Cause-Reason</u>
<u>Work Order</u> 2013947	<u># Line#</u> 4	<u>Close Date</u> 08/11/2020	<u>Employee#</u> 783	<u>Description of W</u> rr rear tuire	<u>ork</u>					S	CHEDULED SERVICE
PT1302	4017	L/M/O	TIRE REPLACEMENT	Tota	al Line	Count for Sy	ystem Co	de 4017 :	1		<u>Cause-Reason</u>
Work Order 1913342	<u># Line#</u> 4	<u>Close Date</u> 07/22/2019	Employee# 839	Description of W		SPARE BAG	CK IN PLA	ACE		OF	PERATOR COMPLAINT
PT1302	5002	RADIO	DS	Tota	l Line	Count for Sy	ystem Co	de 5002 :	2		<u>Cause-Reason</u>
Work Order 1808591	<u># Line#</u> 1	<u>Close Date</u> 04/30/2018	Employee# 24	Description of W RADIOS	<u>ork</u>					S	CHEDULED SERVICE
1918355	1	12/26/2019	27	RADIOSPART CHAR	RGE O	UT				S	CHEDULED SERVICE
PT1302	5004	AVL -	Repairs	Tota	al Line	Count for Sy	ystem Co	de 5004 :	1		<u>Cause-Reason</u>
Work Order 1311049	<u># Line#</u> 1	<u>Close Date</u> 09/06/2013	Employee# 707	Description of W AVL - REPAIRS. PART		LY					MECHANIC DEFECT
PT1302	8005	SHOP	EQUIPMENT REPAIRS	Tota	l Line	Count for Sy	ystem Co	de 8005 :	1		<u>Cause-Reason</u>
Work Order 2013947	<u># Line#</u> 7	<u>Close Date</u> 08/11/2020	Employee# 783	Description of W portable lift stuck stuck		adj lube				S	CHEDULED SERVICE

			Repor	t Descrip	otion: Work O	rder H	istory by Ass	et and System Code			
			WO Close Date	e Range:	07/11/2013	to (08/19/2020	System Code Range:	1100	to	9700
Print Date:	10/6/2020	0	<u>Asset# Ran</u>	<u>qe:</u>	PT1302	to	PT1302				
<u>BUS#</u> S	<u>YS Code</u>	<u>SYS C</u>	ode Description								
PT1302	8010	TRAVE	EL TIME - Road Call				Count for Syst	em Code <mark>8010</mark> :	10		<u>Cause-Reason</u>
Work Order #	Line#		Employee#		Description of W				Ν	AJOR	MECHANICAL BREAKDOWN
1913342	1	07/22/2019	786		L TIME ROAD ((THER	MECHANICAL BREAKDOWN
1723468	1	01/22/2018	818			CALL -C	GAVE P/U TRU	CK TO SUPERVISOR	Ν	AJOR	MECHANICAL BREAKDOWN
1512210	1	08/31/2015	818	ROAD (CALL				C	OTHER	MECHANICAL BREAKDOWN
1601392	1	02/01/2016	627	TRAVE	L TIME ROAD (CALL			Ν	AJOR	MECHANICAL BREAKDOWN
1803231	1	03/13/2018	837	TRAVE	EL TIME ROAD	CALL			Ν	IAJOR	MECHANICAL BREAKDOWN
1508979	1	06/22/2015	752	TRAVE	L TIME-ROAD	CALL			C	DTHER	MECHANICAL BREAKDOWN
1802873	1	02/14/2018	832	TRAVE	L TIME ROAD (CALL -S	SWAP WITH P	T1505	Ν	IAJOR	MECHANICAL BREAKDOWN
1805694	1	03/29/2018	753	travel tir	me road call -dr	ive car l	back		Ν	/AJOR	MECHANICAL BREAKDOWN
1805694	1	03/29/2018	820	travel tir	me road call -dr	ive car l	back				MECHANICAL BREAKDOWN
1507050	1	05/06/2015	752	ROAD	CALL						MECHANICAE BREAKBOWN
PT1302	8011		BLESHOOT ROAD CA				Count for Syst	em Code <mark>8011</mark> :	7		<u>Cause-Reason</u>
Work Order #	Line#		Employee#	_	Description of W					OF	PERATOR COMPLAINT
1805694	2	03/29/2018	753		ar no jump need					OF	PERATOR COMPLAINT
1805694	2	03/29/2018	820		ar no jump need					OF	PERATOR COMPLAINT
1802873	2	02/14/2018	832		A D CALL- RUN					OF	PERATOR COMPLAINT
1803231	2	03/13/2018	837			JLANI H	IUSE LEAKINO	G NEAR TRANS		OF	PERATOR COMPLAINT
1601392	2	02/01/2016	627		AD CALL					OF	PERATOR COMPLAINT
1723468	2	01/22/2018	818	T/ S RC	DAD CALL -HOS	SE IN R	EAR OF ENGI	NE LEAKING COOLANT		OF	PERATOR COMPLAINT
1913342	2	07/22/2019	786	T/S RO	A CALL -META	L IN TIF	RE				

			Report	t Descript	tion: Work O	rder	History by Asse	et and System Code			
			WO Close Date	Range:	07/11/2013	to	08/19/2020	System Code Range:	1100	to 9700	
Print Date: 1	10/6/2020)	Asset# Rang	ge:	PT1302	to	PT1302				
BUS# SY	<u>/S Code</u>	<u>SYS C</u>	ode Description								
PT1302	8015	Travel	Time - Parts Pick-Up		Tota	al Lin	e Count for Syste	em Code <mark>8015 :</mark>	1	Cause-Rea	son
Work Order #	Line#	Close Date	Employee#	D	escription of W	<u>ork</u>				SCHEDULED SI	ERVICE
2013947	8	08/11/2020	783	psarts at	t rear travel ttin	ne					
PT1302	8060	DRIVE	TO DEALER		Tota	al Lin	e Count for Syste	em Code <mark>8060 :</mark>	2	<u>Cause-Rea</u>	son
Work Order #	Line#	Close Date	Employee#	D	escription of W	/ork				SUPERVISOR D	EFECT
1601315	2	02/09/2016	627	DRIVE T	O DEALER						
										SUPERVISOR D	EFECT
1601315	2	02/09/2016	664	DRIVE T	O DEALER						
PT1302	9100	IN SRV	C GOLF/CAR/TRUC/V	AN P.M.	Tota	al Lin	e Count for Syste	em Code 9100 :	1	<u>Cause-Rea</u>	
Work Order #	Line#	Close Date	Employee#	D	escription of W	/ork				SCHEDULED SI	ERVICE
1308394	1	07/11/2013	736	Inservice	e completed						
PT1302	9103	4,000 N	AILE PM CARS				e Count for Syste	em Code <mark>9103 :</mark>	4	<u>Cause-Rea</u>	son
Work Order #	Line#		Employee#		escription of W	<u>ork</u>				OPERATOR COM	IPLAINT
1700029	1	01/05/2017	752	4.000 M	ILE PM CARS						
										SCHEDULED SI	ERVICE
1314734	1	11/18/2013	767	4K PM C	CARS - COMPL	ETE	D				
										SCHEDULED SI	ERVICE
1906958	1	05/28/2019	828	4K MILE	EPM CARS	СОМ	PLETE				
										SCHEDULED SI	ERVICE
1500377	1	01/12/2015	809	4,000 M	ILE PM CARS	- CO	MPLETED				
PT1302	9108	8,000 N	IILE PM CARS				e Count for Syste	em Code 9108 :	4	<u>Cause-Rea</u>	
Work Order #	Line#		Employee#		escription of W					SCHEDULED SI	ERVICE
1914449	1	08/07/2019	746	8K MILE	PM CARSC	OMF	LETED				
										OPERATOR COM	IPLAINT
1705851	1	04/08/2017	752	8.000 M	ILE PM						
										SCHEDULED SI	ERVICE
1400920	1	01/23/2014	767	8K MILE	PM CARS-CO	MPL	ETED				
										SCHEDULED SI	ERVICE
1505444	1	04/02/2015	818	8,000 M	ILE PM CARS	- COI	MPLETED				

WO Close Date <u>Asset# Rar</u> de Description VILE PM CARS <u>Employee#</u> 864 820 809 818 VILE PM CARS <u>Employee#</u> 783 818 767 820	Inge: PT1302 to PT1302 Total Line Count for System Code 9112 : Description of Work 12K MILE PMCOMPLETED 12K MILE PMCARS-complete PM service, vacuum cleaning, tire row 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars 16.000 mile pm cars	4 otate, car wash	Cause-Reason SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE SCHEDULED SERVICE
Employee# 864 820 809 818 VILE PM CARS Employee# 783 818 767	Description of Work 12K MILE PMCOMPLETED 12K MILE PMCARS-complete PM service, vacuum cleaning, tire ro 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 mile pm cars	otate, car wash	SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE <u>Cause-Reason</u> SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
Employee# 864 820 809 818 WILE PM CARS Employee# 783 818 767	Description of Work 12K MILE PMCOMPLETED 12K MILE PMCARS-complete PM service, vacuum cleaning, tire ro 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 mile pm cars	otate, car wash	SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE <u>Cause-Reason</u> SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
864 820 809 818 MILE PM CARS Employee# 783 818 767	12K MILE PMCOMPLETED 12K MILE PMCARS-complete PM service, vacuum cleaning, tire ro 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		SCHEDULED SERVICE SCHEDULED SERVICE SCHEDULED SERVICE Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
820 809 818 MILE PM CARS <u>Employee#</u> 783 818 767	12K MILE PMCARS-complete PM service, vacuum cleaning, tire ro 12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		SCHEDULED SERVICE SCHEDULED SERVICE Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
809 818 WILE PM CARS <u>Employee#</u> 783 818 767	12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		SCHEDULED SERVICE SCHEDULED SERVICE Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
809 818 WILE PM CARS <u>Employee#</u> 783 818 767	12,000 MILE PM CARS- COMPLETED 12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		SCHEDULED SERVICE Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
818 MILE PM CARS Employee# 783 818 767	12,000 MILE PM CARS- COMPLETE Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars	4	Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
MILE PM CARS Employee# 783 818 767	Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars	4	Cause-Reason SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
MILE PM CARS Employee# 783 818 767	Total Line Count for System Code 9116 : Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars	4	SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
Employee# 783 818 767	Description of Work 16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars	4	SCHEDULED SERVICE OPERATOR COMPLAINT SCHEDULED SERVICE
783 818 767	16,000 mile pm cars 16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		OPERATOR COMPLAINT
818 767	16.000 MILE PM CARS COMPLETED 16.000 mile pm cars		SCHEDULED SERVICE
767	16.000 mile pm cars		SCHEDULED SERVICE
767	16.000 mile pm cars		
			SCHEDULED SERVICE
820			SCHEDULED SERVICE
820			
020	16K MILE PM CAR - COMPLETED		
VILE PM CARS	Total Line Count for System Code 9120 :	3	<u>Cause-Reason</u>
Employee# 773	Description of Work 20.000 MILE PM INSPECTION COMPLETE		SCHEDULED SERVICE
113	20.000 MILE PM INSPECTION COMPLETE		SCHEDULED SERVICE
828	20.000 MILE PM CARS		
			SCHEDULED SERVICE
752	20,000 MILE PM CARS		
MILE PM CARS	Total Line Count for System Code 9124 :	4	<u>Cause-Reason</u>
Employee#	· · ·		OPERATOR COMPLAINT
181	24.000 MILE PM GARS		OPERATOR COMPLAINT
781	24.000 MILE PM CARS		
	-		SCHEDULED SERVICE
809	24,000 MILE PM CARS - COMPLETED		
			SCHEDULED SERVICE
752	24K MILE PM CARSCOMPLETE		
MILE PM	Total Line Count for System Code 9418 :	1	<u>Cause-Reason</u>
Employee#			OPERATOR COMPLAINT
	MILE PM CARS Employee# 781 781 809 752 MILE PM	VILE PM CARS Total Line Count for System Code 9124 : Employee# Description of Work 781 24.000 MILE PM CARS 781 24.000 MILE PM CARS 809 24,000 MILE PM CARS - COMPLETED 752 24K MILE PM CARSCOMPLETE VILE PM Total Line Count for System Code 9418 : Employee# Description of Work	VILE PM CARS Total Line Count for System Code 9124 : 4 Employee# Description of Work 4 781 24.000 MILE PM CARS 4 781 24.000 MILE PM CARS 4 809 24,000 MILE PM CARS - COMPLETED 52 752 24K MILE PM CARSCOMPLETE 1 VILE PM Total Line Count for System Code 9418 : 1 Employee# Description of Work 1

			Report	t Descrip	tion: Work O	rder	History by A	Asset a	and System Code			
	40/0/000		WO Close Date	e Range:	07/11/2013	to	08/19/2020		System Code Range:	1100	to	9700
Print Date:	10/6/202	-	<u>Asset# Ran</u>	ge:	PT1302	to	PT1302					
	SYS Code		Code Description									
PT1302	9700		RUN/ROAD TEST		Tota Description of W		e Count for S	system	Code 9700 :	14	0	Cause-Reason PERATOR COMPLAINT
<u>Work Order </u> 2010045	<u># Line#</u> 5	<u>Close Date</u> 06/04/2020	Employee# 864		ESTCLEAR		S LIGHT				0	PERATOR COMPLAINT
_0.00.0	C C	00,01,2020									0	PERATOR COMPLAINT
1602572	3	02/22/2016	828	road tes	t							
4744400	7	00/44/0047	000		TOT						S	SCHEDULED SERVICE
1714133	7	08/11/2017	809	ROAD T	EOI						0	PERATOR COMPLAINT
1919027	9	11/14/2019	783	ROAD -	TEST NO FUI	MES						
											0	PERATOR COMPLAINT
1810921	5	05/29/2018	837	raod tes	t						0	PERATOR COMPLAINT
1513549	4	10/06/2015	756	road tes	t						0	PERATOR COMPLAINT
											0	PERATOR COMPLAINT
1610733	3	07/29/2016	820	ROAD T	ESTOK						_	
1723468	6	01/22/2018	837	ROAD T	FST						O	PERATOR COMPLAINT
1720400	0	01/22/2010	037	NOAD 1	LUI						0	PERATOR COMPLAINT
1601315	5	02/09/2016	797	ROAD T	EST							
4040004	0	00/00/0040	007								0	PERATOR COMPLAINT
1812021	3	06/08/2018	837	ROAD T	EST						0	PERATOR COMPLAINT
1602704	5	03/02/2016	818	ROAD T	EST						0	
											S	SCHEDULED SERVICE
1914449	5	08/07/2019	746	ROAD -	TEST						~	
1803231	9	03/13/2018	837	ROAD -	TEST						0	PERATOR COMPLAINT
1000201	Ŭ	00,10,2010		1.07.10							0	PERATOR COMPLAINT
1803231	5	03/13/2018	837	ROAD T	EST - VEHICL	E HA	S VIBRATION	WHE	N INCLINE NEEDS MO	TOR MOU	NTS	