WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

Print Date: 10/3/2020 Asset# Range: PT0608 to PT0608

			Asset# Ran	<u>ge:</u> P10606 to P10606		
BUS# SY	S Code	SYS C	Code Description			
PT0608	1100	INTER	RIOR CLEAN	Total Line Count for System Code 11	00: 1	Cause-Reason
Work Order #	Line#		Employee#	Description of Work		SCHEDULED SERVICE
1911548	1	06/25/2019	658	INTERIOR CLEANCOMPLETED		
PT0608	1201	TROU	BLESHOOT COOLING	SYS Total Line Count for System Code 12	201 : 1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1905453	1	03/26/2019	783	TROUBLESHOOT COOLING SYSTEMORDERED PA	RTS	
PT0608	1206	RADIA	ATOR REPL	Total Line Count for System Code 12	206 : 1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1905453	2	03/26/2019	783	R/R RADIATOR		
PT0608	1215	THER	MOSTATS REPLACE	Total Line Count for System Code 12	.15: 1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1905453	3	03/26/2019	783	R/R THERMOSTAT & HOSESTOP OFF COOLANT		
PT0608	1300	AIR C	OND\HEATING SYSTE		300:	Cause-Reason
Work Order #	Line#		Employee#	Description of Work		OPERATOR COMPLAINT
1911860	2	06/27/2019	783	TIGHTEN VALVEADDED FREONPLACED CAP ON \	VALVE	
						SCHEDULED SERVICE
1811394	2	06/07/2018	837	R/R WIPERS		
						OPERATOR COMPLAINT
1211688	2	08/08/2012	797	INSTALL NEW PANNER SELECT DOOR OPENER & FU	JEL	
PT0608	1301	TROU	BLESHOOT AC SYSTE	M Total Line Count for System Code 13	5 5	<u>Cause-Reason</u>
Work Order #	Line#		Employee#	Description of Work		OPERATOR COMPLAINT
1911860	1	06/27/2019	783	TROUBLESHOOT AC SYSTEMLEAK @VALVE		
						OPERATOR COMPLAINT
1816789	1	08/06/2018	823	TROUBLESHOOT AC SYSTEMLOW IN FREONNO L	EAKS	
						OPERATOR COMPLAINT
1711541	4	07/03/2017	679	CHECK A/C SYSTEM		
						SCHEDULED SERVICE
1903378	1	02/18/2019	783	T/S A/C SYSTEM		
						OPERATOR COMPLAINT
1211688	1	08/08/2012	797	T/S A/C SYS - DIAGNOSE & FOUND VENT PAN SELEC	T DOOR OPENER	
PT0608	1318	A/C S	YSTEM RE-CHARGE	Total Line Count for System Code 13	18:	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1816789	2	08/06/2018	823	RECHARGE AC SSYTEM WITH 134A		
PT0608	1400	ELEC.	TRICAL SYSTEM	Total Line Count for System Code 14	100 : 1	Cause-Reason
Work Order #	<u>Li</u> ne#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1213191	1	09/11/2012	752	CIG LT NO POWER - REPAIR PROBLEM		
				Page 1 of 8		

Page 1 of 8

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

BUS#	SYS Code	SYS C	ode Description			
PT0608	1401	TROU	BLESHOOT ELECTRIC	CAL S Total Line Count for System Code 1401 :	8	Cause-Reason
Work Order	# Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1612348	1	09/02/2016	820	T/*S ELECTRICAL -BROKEN PEICE INSIDE SHIFTER		
						OPERATOR COMPLAINT
1612348	1	09/02/2016	832	T/*S ELECTRICAL -BROKEN PEICE INSIDE SHIFTER		
						OPERATOR COMPLAINT
1900607	1	01/15/2019	747	TROUBLESHOOT ELECTRICALSNO STRTDEAD BATTERYJU	JMPEDCKD E	BATTERY
						OPERATOR COMPLAINT
1506135	1	04/16/2015	760	T/S ELECTRICAL S - CHECK CHARGING SYSTEM CHECK BATTER	RY	
						OPERATOR COMPLAINT
1506135	1	04/16/2015	791	T/S ELECTRICAL S - CHECK CHARGING SYSTEM CHECK BATTER	₹Y	
						SCHEDULED SERVICE
854262	1	01/10/2008	771	REPLACE MIRROR CONTROL SWITCH.		
						OPERATOR COMPLAINT
1612348	2	09/02/2016	752	R/R SHIFTER		
						OPERATOR COMPLAINT
1007273	1	07/27/2010	762	Troubleshoot elec need bats.		
PT0608	1402	ALTER	RNATOR REPL	Total Line Count for System Code 1402:	1	Cause-Reason
Work Order	# Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1215508	2	10/31/2012	747	replc alternator		
PT0608	1408	BATTE	RIES REPLACE	Total Line Count for System Code 1408 :	4	Cause-Reason
Work Order	# Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1506135	2	04/16/2015	760	CHANGE BATTERY		
						OPERATOR COMPLAINT
1506135	2	04/16/2015	791	CHANGE BATTERY		
						OPERATOR COMPLAINT
1900607	2	01/15/2019	747	R/R BATTERY		
						OPERATOR COMPLAINT
1007273	2	07/27/2010	762	R&R Battery		

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

 Print Date:
 10/3/2020
 Asset# Range:
 PT0608
 to
 PT0608

# Close Date 03/23/2017 06/07/2018 10/06/2017 03/23/2017	RIOR LIGHTING Employee# 773 837 781 773	Total Line Count for System Code 1409 : Description of Work EXTERIOR LIGHTINGCKD RIGHT REAR TURN SIGNALNOT WORK R/R HEADLIGHT R/R ROADSIDE REAR TURN SIGNAL BULB	4 IING	Cause-Reason OPERATOR COMPLAINT SCHEDULED SERVICE SCHEDULED SERVICE
03/23/2017 06/07/2018 10/06/2017 03/23/2017 0 INTER # Close Date	773 837 781	EXTERIOR LIGHTINGCKD RIGHT REAR TURN SIGNALNOT WORK	IING	SCHEDULED SERVICE
06/07/2018 10/06/2017 03/23/2017 0 INTER # Close Date	837 781	R/R HEADLIGHT	ING	
10/06/2017 03/23/2017 INTER # Close Date	781			
10/06/2017 03/23/2017 INTER # Close Date	781			SCHEDULED SERVICE
03/23/2017 INTER # Close Date		R/R ROADSIDE REAR TURN SIGNAL BULB		SCHEDULED SERVICE
03/23/2017 INTER # Close Date		TATA TOTAL DOLD		
INTER	773			OPERATOR COMPLAINT
# Close Date		RIGHT REAR TURN SIGNALOK		
_	NOR LIGHTING	Total Line Count for System Code 1410 :	1	Cause-Reason
03/01/2011	Employee#	Description of Work		SCHEDULED SERVICE
03/01/2011	753	INT LIGHTING-INSTALL INT FRONT DASH STROBE LIGHT-HARDWIR	E	
3 INSTR	UMENTS & GAUGES	Total Line Count for System Code 1418 :	1	Cause-Reason
# Close Date	Employee#	Description of Work		SCHEDULED SERVICE
05/06/2019	783	REPAIRED MIRROR KNOB CONTROL		
CANC	EIVER REPAIR\REPLA	CE Total Line Count for System Code 1425 :	1	Cause-Reason
# Close Date	Employee#	Description of Work		SCHEDULED SERVICE
05/06/2019	783	GPS SPLITTER INSTALLED		
STEE!	RING SYSTEMS	Total Line Count for System Code 2200 :	1	Cause-Reason
# Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
08/27/2015	809	STEERING SYSTEMS-NEEDS L/F WHEEL BEARING-POO		
I TROU	BLESHOOT STEERING	SYS Total Line Count for System Code 2201 :	1	Cause-Reason
# Close Date	Employee#			OPERATOR COMPLAINT
06/13/2011	707	VOID		
SWAY	BAR BUSHING REPLA	ACE Total Line Count for System Code 2223 :	1	Cause-Reason
# Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
11/06/2014	773	REMOVED/REPLACED STABILIZER TOP BUSHING		
SUSP	ENSION SYSTEM	Total Line Count for System Code 2300 :	3	Cause-Reason
# Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
10/14/2014	819	REPLACE FRONT SWAY BAR BUSHINGS AND RODS		
		7.7.7.40		SCHEDULED SERVICE
	837	R/R BUSHING		
06/07/2018				OPERATOR COMPLAINT
3 #	# Close Date 08/27/2015 TROU # Close Date 06/13/2011 SWAY # Close Date 11/06/2014 SUSP # Close Date	# Close Date	# Close Date 08/27/2015 B09 STEERING SYSTEMS-NEEDS L/F WHEEL BEARING-POO TROUBLESHOOT STEERING SYS Total Line Count for System Code 2201: # Close Date 06/13/2011 707 VOID SWAY BAR BUSHING REPLACE Total Line Count for System Code 2223: # Close Date 11/06/2014 Employee# Description of Work REMOVED/REPLACED STABILIZER TOP BUSHING SUSPENSION SYSTEM Total Line Count for System Code 2300: # Close Date 11/06/2014 T73 REMOVED/REPLACED STABILIZER TOP BUSHING SUSPENSION SYSTEM Total Line Count for System Code 2300: # Close Date 10/14/2014 Employee# Description of Work REPLACE FRONT SWAY BAR BUSHINGS AND RODS	# Close Date Employee# Description of Work STEERING SYSTEMS-NEEDS L/F WHEEL BEARING-POO TROUBLESHOOT STEERING SYS Total Line Count for System Code 2201 : 1 # Close Date Employee# Description of Work VOID SWAY BAR BUSHING REPLACE Total Line Count for System Code 2223 : 1 # Close Date Employee# Description of Work Total Line Count for System Code 2223 : 1 # Close Date Employee# Description of Work REMOVED/REPLACED STABILIZER TOP BUSHING SUSPENSION SYSTEM Total Line Count for System Code 2300 : 3 # Close Date Employee# Description of Work REPLACE FRONT SWAY BAR BUSHINGS AND RODS

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

				<u></u>		
BUS# SY	'S Code	SYS C	ode Description			
PT0608	2301	TS SU	SPENSION SYSTEM	Total Line Count for System Code 2301 :	1	Cause-Reason
Work Order#	Line#		Employee#	Description of Work		OPERATOR COMPLAINT
1414818	1	10/14/2014	752	TS SUSPENSION SYSTEM - FOUND BAD SWAY BAR LINK BUSHI	NG P.O.D.	
PT0608	2401	FRON	ΓAXLE	Total Line Count for System Code 2401 :	2	Cause-Reason
Work Order#	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1504932	1	03/24/2015	631	FRONT AXLE - HUB/WHEEL BEARING ASSY - RIGHT FRONT		
						SCHEDULED SERVICE
1811394	3	06/07/2018	837	R/R RIGHT FRONT AXLE		
PT0608	2403	FRON	T HUB BEARINGS REI	PL Total Line Count for System Code 2403 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1512069	4	08/27/2015	756	R/R LEFT FRONT WHEEL BEARING-ROAD TEST-OK		
PT0608	2500	BODY		Total Line Count for System Code 2500 :	3	Cause-Reason
Work Order#	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
637798	1	07/05/2006	771	INSTALL REFLECTORS		
						OPERATOR COMPLAINT
1415812	2	11/06/2014	809	R/R WINDSHIELD WASHER PUMP		
						OPERATOR COMPLAINT
1512069	3	08/27/2015	809	REPAIRED ANTENNA		
PT0608	2505	WIPER	IS	Total Line Count for System Code 2505 :	9	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1908334	4	05/06/2019	783	INSTALLED WIPER		
						OPERATOR COMPLAINT
1204627	1	04/09/2012	756	WIPERS - R&R 2 BLADES		
						SCHEDULED SERVICE
1611056	2	08/09/2016	809	R/R FRONT WIPER BLADES		
						OPERATOR COMPLAINT
861993	1	09/26/2008	757	R/R W.WIPER BLADES &FLUID		
						SCHEDULED SERVICE
1518112	2	12/29/2015	818	REPLACED FRONT W/W BLADES		
	_					SCHEDULED SERVICE
1700699	2	01/25/2017	809	R/R WIPER BLADES		
1005:55	_	00/00/00		D/D MANDOLUELD MARKED TAXIII		OPERATOR COMPLAINT
1905453	4	03/26/2019	783	R/R WINDSHIELD WASHER TANK		ODED 4 TO
4445040	_	44/00/004	222	D/D DEAD MIDED DI ADE		OPERATOR COMPLAINT
1415812	3	11/06/2014	809	R/R REAR WIPER BLADE		ODED 4 TO 2 CO 4 TO 1
4540000	0	00/07/0045	000	D/D MIDED DI ADEC		OPERATOR COMPLAINT
1512069	2	08/27/2015	809	R/R WIPER BLADES		
				Page 4 of 8		

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

 Print Date:
 10/3/2020
 Asset# Range:
 PT0608
 to
 PT0608

BUS# SY	YS Code	SYS Cod	le Description			
PT0608	2603	FRONT F	RELINE	Total Line Count for System Code 2603:	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1811394	4	06/07/2018	837	R/R FRONT BRAKES & ROTORS		
PT0608	2604	REAR RE	ELINE	Total Line Count for System Code 2604:	1	<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1415812	4	11/06/2014	809	R/R REAR BRAKE PADS, HANDWARE KIT		
PT0608	2800	ENGINE		Total Line Count for System Code 2800:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		NORMAL WEAR
1700699	3	01/25/2017	752	INSTALL NEW P/S CAP		
						SCHEDULED SERVICE
744330	1	02/02/2007	771	CHANGED OIL AND FILTER - HAD WRONG OIL IN IT		
						OPERATOR COMPLAINT
1711541	2	07/03/2017	679	CHECK FUEL CAP REMOVED AND REINSTALLED SECURELY -C	LEAR CODE	2. 2. 0
						Coupe Beases
PT0608	2801		ESHOOT ENGINE	Total Line Count for System Code 2801 :	3	Cause-Reason
Work Order #	<u>Line#</u>		Employee#	Description of Work		OPERATOR COMPLAINT
1711541	1	07/03/2017	679	T/S ENGINE -CODE P0457 EVAP LEAK DETECTION FUEL CAP TI	PINS FAILED	
						OPERATOR COMPLAINT
1215508	1	10/31/2012	753	troubleshoot engine-find alternator noise NR (idle & tensioner pulley,	POO)	
						OPERATOR COMPLAINT
1309400	1	08/05/2013	767	TS ENG - ENG- NO TIRE. ENG TS. THE PRESSURE OF TIRE.		
PT0608	2817	ENGINE	PULLEYS/TENSION	IERS Total Line Count for System Code 2817 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1215508	3	10/31/2012	797	replc belt tensioner & pulley		
PT0608	2826	OUT OF	FUEL	Total Line Count for System Code 2826 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1412738	2	09/05/2014	779	OUT OF FUEL-PUT IN 1GAL GAS		
PT0608	4000	TIRES		Total Line Count for System Code 4000 :	3	<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1415812	<u>LINE#</u>	11/06/2014	<u>Employee#</u> 809	INSTALLED SPARE TIRE		2. <u>2. 2 </u>
1710012	3	11/00/2017	000	INOTALLED OF AIRE TIME		SCHEDULED SERVICE
4500500	0	00/00/0045	0.07	TOOK OAD TO TIDE OHOD DEDLAGED ALL A TIDES		SCHEDULED SEKVICE
1503528	2	03/03/2015	827	TOOK CAR TO TIRE SHOP REPLACED ALL 4 TIRES		
						OPERATOR COMPLAINT
1710671	1	06/19/2017	679	TIRESCK ALL TIRESNOTICED AIR LEAKR/R TIRE		

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

			AGGGEN TRUT	<u>110000</u> 110000		
BUS# SY	S Code	SYS C	ode Description			
PT0608	4004	TIRE P	RESSURE	Total Line Count for System Code 4004:	2	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1711541	3	07/03/2017	679	CHECK TIRE PRESSURE AND SET ALL 4 TIRES TO THER PROP	PER PSI - RESE	T TPINS
						SCHEDULED SERVICE
1309400	2	08/05/2013	767	CHECKING THE PRESSURE OF TIRE, WAS LOW. PUT ALL FOU	R (4) TIRES 351	PSI.
PT0608	8010	TRAVE	EL TIME - Road Call	Total Line Count for System Code 8010 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		NON - MECHANICAL BREAKDOWN
1412738	1	09/05/2014	779	TRAVEL TIME-ROAD CALL-RAN OUT OF GAS		
PT0608	9103	4,000 N	MILE PM CARS	Total Line Count for System Code 9103 :	4	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1718018	1	10/06/2017	781	4,000 MILE PM CARS- COMPLETE		
						SCHEDULED SERVICE
642330	1	12/04/2006	769	COMPLETED PM INSPECTION		
						SCHEDULED SERVICE
1415812	1	11/06/2014	820	4,000 MILE PM CARS - COMPLETED PM SERVICE/INSPECTION.	WASHED VEH	ICLE, VACUUM
						SCHEDULED SERVICE
1010308	1	10/22/2010	752	4K MILE PM CARS		
PT0608	9108		MILE PM CARS	Total Line Count for System Code 9108 :	5	Cause-Reason
		<u> </u>		Description of Work	<u>J</u>	SCHEDULED SERVICE
Work Order # 753336	<u>Line#</u> 1	Close Date 12/05/2007	<u>Employee#</u> 771	8000PM, OIL CHSANGE FUEL ROAD TEST		CONEDUCED CERVICE
700000	•	12/00/2007	,,,	OUGOT WI, OIL OTTO/INGLI GLE NO/ID TEOT		SCHEDULED SERVICE
747911	1	06/06/2007	771	PM COMPLETE.		CONEDUCED CERVICE
747311	Ī	00/00/2007	771	TIVI COIVII LETE.		SCHEDULED SERVICE
1104780	1	06/02/2011	752	8K MILE PM		SCHEDOLED SERVICE
1104700	ı	00/02/2011	732	OR WILE PWI		COUEDINED CEDVICE
4502520	4	02/02/2045	000	0.000 MILE DM CARC. COMPLETED		SCHEDULED SERVICE
1503528	I	03/03/2015	809	8,000 MILE PM CARS - COMPLETED		00115011150 0501105
1011201	4	00/07/0040	007	OK MILE DM CADO		SCHEDULED SERVICE
1811394	1	06/07/2018	837	8K MILE PM CARS		
PT0608	9112	12,000	MILE PM CARS	Total Line Count for System Code 9112 :	4	Cause-Reason
Work Order #	Line#		Employee#	<u>Description of Work</u>		SCHEDULED SERVICE
1908334	1	05/06/2019	783	18K MILE PMCOMPLETED		
						OPERATOR COMPLAINT
1508976	1	06/24/2015	707	VOIDED		
						SCHEDULED SERVICE
858591	1	06/05/2008	767	PM COMPLETE		
						SCHEDULED SERVICE
1110873	1	12/16/2011	752	12K MILE PM - COMPLETED		
				Page 6 of 8		
				I AUC U UI U		

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

BUS# SY	'S Code	SYS C	ode Description			
PT0608	9116	16,000	MILE PM CARS	Total Line Count for System Code 9116:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
864024	1	12/05/2008	756	PM COMPLETE		
						SCHEDULED SERVICE
1518112	1	12/29/2015	818	16.000 MILE PM		
						SCHEDULED SERVICE
1213218	1	09/12/2012	767	16K MILE PM - CARS - COMPLETED		
PT0608	9120	20,000	MILE PM CARS	Total Line Count for System Code 9120:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1310417	1	08/28/2013	767	20K PM CARS - COMPLETED		
						OPERATOR COMPLAINT
1611056	1	08/09/2016	809	20.000 MILE PM CARS		
						SCHEDULED SERVICE
907058	1	09/09/2009	791	completed 20k pm		
PT0608	9124	24,000	MILE PM CARS	Total Line Count for System Code 9124:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1003928	1	04/28/2010	752	24.000 MILE PM		
						SCHEDULED SERVICE
1700699	1	01/25/2017	809	24K MILE PM CARSCOMPLETED		
						SCHEDULED SERVICE
1405077	1	04/14/2014	767	24K MILE PM CARS		
PT0608	9480	SAFET	Y CHECK	Total Line Count for System Code 9480 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1911066	1	06/17/2019	746	SAFETY CHECK		

WO Close Date Range: 07/05/2006 to 06/27/2019 System Code Range: 1100 to 9700

BUS#	SYS Cod	SYS C	Code Description			
 PT0608	9700	TEST	RUN/ROAD TEST	Total Line Count for System Code 9700:	7	Cause-Reason
Work Order	# Line	# Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1911066	2	06/17/2019	746	ROAD TEST		
						SCHEDULED SERVICE
1811394	7	06/07/2018	837	ROAD TEST		
						OPERATOR COMPLAINT
1816789	3	08/06/2018	823	ROAD TEST		
						OPERATOR COMPLAINT
1911860	3	06/27/2019	783	ROAD TEST		
						OPERATOR COMPLAINT
1215508	4	10/31/2012	797	road test-ok		
						OPERATOR COMPLAINT
1414818	3	10/14/2014	819	ROAD TEST, GOOD TO GO		
	_					OPERATOR COMPLAINT
1711541	5	07/03/2017	679	ROAD TEST		