

**Palm Beach County Fleet Management
Asset Maintenance History**

10187854 2013 FORD TRANSIT CONNECT Mini Van, Animal Care

Workorder: 1302779	Meter: 307	In Date: 03/21/2013	Closed: 03/27/2013
Problem: take to dealer, rear door fob not working			
- Take van to dealer, rear door fob not working		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1303024	Meter: 307	In Date: 03/27/2013	Closed: 03/27/2013
Problem: 1061 - Pre Delivery Inspection			
- Pre Delivery Inspection			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			
Workorder: 1303208	Meter: 307	In Date: 04/02/2013	Closed: 04/18/2013
Problem: order 4 spare keys			
- parts only		Parts List	Qty
- Shop Supplies		Transit Keys	4.00
		Shop Supplies	1.00
Hours 0.00	Labor: 0.00	Parts: 365.66	Total: 365.66
:			
Workorder: 1303883	Meter: 710	In Date: 04/19/2013	Closed: 04/19/2013
Problem: Left rear tire flat.			
- Repair flat left rear tire.nitrogen fill and balance same.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1305989	Meter: 4663	In Date: 06/17/2013	Closed: 06/27/2013
Problem: P.m. service.			
- Perform pm service.		Parts List	Qty
- Rotate and balance all four tires.		5w20 Engine Oil	5.00
- Perform rear drum brake service and adjust brake shoes.		Napagold Oil Filter	1.00
- Shop Supplies		Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 19.33	Total: 259.33
:			
Workorder: 1309316	Meter: 8450	In Date: 09/13/2013	Closed: 09/25/2013
Problem: Pm service right rear tire flat.			
- P.m. Service.		Parts List	Qty
- Repair left front tire,replace one bent rim and rotate and balance all four.		Napagold Oil Filter	1.00
		5w20 Engine Oil	5.00
- Service and adjust rear brakes.		Floor Mat-2pc Rub Bk	1.00
- Shop Supplies		Wheel Assembly	1.00
		Tire Pressure Monitoring System Sensor (1.00
		Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 318.59	Total: 663.59
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1309568	Meter: 8415	In Date: 09/23/2013	Closed: 09/24/2013
Problem: repair chipped windsheild			
- Set up repairs for chipped windshield and ck		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1311119	Meter: 10439	In Date: 11/01/2013	Closed: 11/14/2013
Problem: Check over ac system.Blows warm in cab and kennel.			
- Check a/c system.pressures are good,vent outlet temp is 36 degrees.unable to duplicate complaint at this time.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
Workorder: 1312283	Meter: 12149	In Date: 12/09/2013	Closed: 12/13/2013
Problem: Pm service and low tire pressure warning light on.			
- Perform pm service.		Parts List	Qty
- Diagnose for low tire pressure warning light on.test and replace failed right front tire pressure sensor with new.nitrogen fill,rotate and balance all four tires.		5w20 Engine Oil	5.00
- Perform rear drum brake service and adjust brake shoes.		Napagold Oil Filter	1.00
- Shop Supplies		Tpms12 Sensor Tire Pr	1.00
		Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 96.28	Total: 441.28
:			
Workorder: 1401919	Meter: 16483	In Date: 02/27/2014	Closed: 03/11/2014
Problem: P.M. service.			
- P.m. Service.		Parts List	Qty
- Resurface front brake rotors,replace front pads.service and lube calipers.flush and bleed system.service and adjust rear brakes.		5w20 Engine Oil	5.00
- Rotate and balance all tires.		Napagold Oil Filter	1.00
- Shop Supplies		Exact Fit Blade	1.00
		Wiper Blade	1.00
		kit brake lin	1.00
		Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 101.29	Total: 596.29
:			
Workorder: 1402653	Meter: 16850	In Date: 03/19/2014	Closed: 03/19/2014
Problem: RF tire flat, put spare on or tow			
- Tow From: 7100 belvedere rd, barn area To: vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1402659	Meter: 16927	In Date: 03/19/2014	Closed: 03/20/2014
Problem: Towed in.Right front tire flat.			
- Repair right front tire flat.nitrogen fill and balance same.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1403214	Meter: 17675	In Date: 04/02/2014	Closed: 04/03/2014
Problem: Tire presure light flashing.			
- Diagnose low tire pressure warning light flashing.test and replace failed left front tire pressure sensor with new.	Parts List		Qty
- Shop Supplies	Tpms12 Sensor Tire Pr		1.00
	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 80.00	Total: 140.00
:			
Workorder: 1404660	Meter: 19796	In Date: 05/12/2014	Closed: 05/13/2014
Problem: Flat tire on Passenger Rear			
- Tire Service 7100 Belvedere rd (animal Care and Control) - Flat tire on Passenger Rear			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1404779	Meter: 20122	In Date: 05/15/2014	Closed: 05/28/2014
Problem: Pm, service and tire pressure warning light on.			
- Perform pm service.	Parts List		Qty
- Install two new tires to the front wheels.nitrogen fill and balance all four	5w20 Engine Oil		5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter		1.00
- Perform wheel alignment complete.	Exact Fit Blade		1.00
- Shop Supplies	Wiper Blade		1.00
	P20565r15conti Procont		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 8.25	Labor: 495.00	Parts: 362.30	Total: 857.30
:			
Workorder: 1407401	Meter: 23848	In Date: 07/28/2014	Closed: 08/11/2014
Problem: P.M. Service.Tow in,broken drive belt.			
- Perform pm service.	Parts List		Qty
- Check serpentine belt and pulley.replace frozen idler pulley and broken serpentine belt.	Napagold Oil Filter		1.00
- Rotate and balance all four tires.	5w20 Engine Oil		5.00
- Inspect and service rear brakes.	Napagold Air Filter		1.00
- Shop Supplies	V Belt		1.00
	Tensioner		1.00
	Shop Supplies		1.00
Hours 6.25	Labor: 375.00	Parts: 91.12	Total: 466.12
:			
Workorder: 1407873	Meter: 23848	In Date: 07/28/2014	Closed: 08/11/2014
Problem: smoke coming from engine, possibly drive belt broken			
- Tow From: 7100 Belvedere Rd. Acc To: vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1408251	Meter: 24398	In Date: 08/20/2014	Closed: 08/22/2014
Problem: Left brake light inop.			
- Test and replace open left brake lamp bulb.	Parts List		Qty
	Bulb		1.00
Hours 0.50	Labor: 30.00	Parts: 3.24	Total: 33.24
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1409351	Meter: 26012	In Date: 09/18/2014	Closed: 09/22/2014
Problem: Has to jump start.Clearance lamp on right rear side of bumper inop.			
- Recharge battery and test battery and charging system.battery failed load test.replace defective battery.	Parts List		Qty
	Battery		1.00
- Inspect and replace defective right rear marker light lense and socket (fall out of socket).	Rear Marker Lamp		1.00
	Marker Lamp Socket		1.00
- Diagnose noise coming from engine area.replace defective belt tensioner.	Bulb		1.00
	Belt Tensioner		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 2.50	Labor: 150.00	Parts: 298.36	Total: 448.36
:			

Workorder: 1409652	Meter: 26238	In Date: 09/25/2014	Closed: 09/30/2014
Problem: Check engine light on and engine runs rough.			
- Computer diagnose for check engine light on and runs rough.code P0351.pinpoint test and replace Cylinder #1defective ignition coil.clear code and retest.	Parts List		Qty
	Coil		1.00
	Shop Supplies		1.00
- Shop Supplies			
Hours 2.50	Labor: 150.00	Parts: 113.71	Total: 263.71
:			

Workorder: 1410412	Meter: 27275	In Date: 10/17/2014	Closed: 11/10/2014
Problem: Pm service.Check engine light on and run rough intermittently.			
- P.m. Service.	Parts List		Qty
- Replace two tires,rotate and balance all four.	5w20 Engine Oil		5.00
- Service and adjust rear brakes.	Napagold Oil Filter		1.00
- Transport vehicle to dealer for check engine light and runs rough.(replacepcm)	Wiper Blade		1.00
	Exact Fit Blade		1.00
- Shop Supplies	P205/65r15 Assurance		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 7.75	Labor: 465.00	Parts: 296.66	Total: 761.66
:			

Workorder: 1412333	Meter: 28374	In Date: 12/10/2014	Closed: 12/24/2014
Problem: Check engine light on.Body damage on rear.			
- Trasnsport vehicle to and from dealer for check engine light on.code P0351.swap #1 and #2 ignition coils.also dealer replace one front motor mount	Parts List		Qty
	Shop Supplies		1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			

Workorder: 1500566	Meter: 28374	In Date: 12/17/2014	Closed: 01/15/2015
Problem: damage to rear bumper			
- damage to rear bumper			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504130	Meter: 33893	In Date: 04/21/2015	Closed: 05/07/2015
Problem: Pm service .Ac blows warm air.			
- Pm service.	Parts List		Qty
- Inspect for noise and replace defective drive belt idler pulley.	5w20 Engine Oil		5.00
- Inspect and service rear drum brakes.	Napagold Oil Filter		1.00
- Repair right rear tire.rotate and balance all four.	Wiper Blade		1.00
- Transport vehicle to and from dealer for replacing defective ac compressor.	Wiper Blade		1.00
- Shop Supplies	Idler Pulley		1.00
	Shop Supplies		1.00
Hours 8.35	Labor: 501.00	Parts: 65.20	Total: 566.20
:			
Workorder: 1505254	Meter: 34382	In Date: 05/26/2015	Closed: 06/04/2015
Problem: Ac blows warm air.Check engine light on .Engine shakes.			
- Transport vehicle to and from dealer for replacing Pcm.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1505877	Meter: 34541	In Date: 06/12/2015	Closed: 06/25/2015
Problem: Check engine light on.Ac blows hot air.No power on acceleration.			
- Transport vehicle to and from dealer for repairing #1ignition coil over lay circuit.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1506690	Meter: 34876	In Date: 07/06/2015	Closed: 07/06/2015
Problem: Left power outlet inop.			
- Test and replace open 20 amps. fuse.			
Hours 0.25	Labor: 15.00	Parts: 0.00	Total: 15.00
:			
Workorder: 1506916	Meter: 35125	In Date: 07/13/2015	Closed: 07/15/2015
Problem: Rear ac not blowing any air.			
- Check rear a/c inop.diagnose and repair wiring to rear unit blower.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1509967	Meter: 40485	In Date: 10/01/2015	Closed: 10/13/2015
Problem: Right brake lamp inop.			
- Test and replace defective right brake lamp bulb.	Parts List		Qty
	Bulb		1.00
Hours 0.50	Labor: 30.00	Parts: 1.86	Total: 31.86
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1510626 **Meter:** 40950 **In Date:** 10/21/2015 **Closed:** 11/03/2015
Problem: P.M. service.

- Pm service.
- Replace front brake rotors and pads.service calipers.inspect and service rear brakes.
- Check pulleys and serpentine belt for noise in belt area.replace defective serpentine belt tensioner assembly.
- Replace two tires.rotate and balance all four.
- Complete front end alignment.test drive.
- Shop Supplies

Parts List	Qty
Spark Plug Asm	1.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Bigg Degreaser	1.00
Brake Pads	1.00
Front Brake Rotor	2.00
Belt Tensioner	1.00
P205/65r15 Assurance	2.00
5w20 Engine Oil	5.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 12.25 Labor: 735.00 Parts: 619.31 Total: 1,354.31
:

Workorder: 1602017 **Meter:** 44332 **In Date:** 02/25/2016 **Closed:** 02/26/2016
Problem: F/P flat tire

- Tire Service West Drew St and S 12th st - F/p flat tire

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1605249 **Meter:** 46081 **In Date:** 05/20/2016 **Closed:** 06/13/2016
Problem: P.M. Service.Check water leak at dome light.

- P.m. Service.
- replace two tires,rotate and balance all four.
- Remove headliner and leak check for water leak.replace radio antenna assemble and reseal base.
- Service and adjust rear brakes.
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	5.00
Napagold Oil Filter	1.00
Wiper Bleade Anco	1.00
18" wiper blades	1.00
P205/65r15 Assurance	2.00
Mast	1.00
Cable Am/ Fm Radio	1.00
Clr Rtv Silcn Sealant	1.00
Fasteners Pin	4.00
Fasteners Pin	4.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 8.00 Labor: 480.00 Parts: 343.89 Total: 823.89
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700694 **Meter:** 51139 **In Date:** 01/24/2017 **Closed:** 02/06/2017
Problem: P.M. Service.Interior light switch broke.

- P.m. Service.	Parts List	Qty
- Replace rear brake shoes and wheel cylinders.resurface rear brake drums.flush and bleed system.	5w20 Engine Oil	5.00
- Replace left axle output seal.	Napagold Oil Filter	1.00
- Replace one tire,rotate and balance all four.	Napagold Air Filter	1.00
- Service transmission.flush and refill system.	Wiper Bleade Anco	1.00
- Replace broken dome lamp assemble.	18" wiper blades	1.00
- Inspect and replace noisy belt tensioner and idler pulley.	Stg Wheel Cov - Ford	1.00
- Shop Supplies	Brk Fluid Dot 4-12oz	1.00
	Seal	1.00
	P205/65r15 Assurance	1.00
	Syn-atf Trans Fluid S	12.00
	Transmission Filter	1.00
	Brake Shoe	1.00
	Wheel Cyinders	2.00
	Nut	1.00
	Lamp Assy	1.00
	Idler Pulley	1.00
	Dr Blt Tensioner Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 13.75	Labor: 825.00	Parts: 708.33
:		Total: 1,533.33

Workorder: 1706440 **Meter:** 55264 **In Date:** 06/29/2017 **Closed:** 07/10/2017
Problem: P.M. Service.Dead battery.Check a/c and radio.

- P.m. service. Check radio operation .could not verify complaint.	Parts List	Qty
- Battery failed load test after recharge.check electrical system.replace bad battery.	5w20 Engine Oil	5.00
- Check A/c operation .aux fans inop.test circuits.replace failed in line fuse holder and fuse.fabricate wiring.evacuate and recharge system Leak test passed.	Napagold Oil Filter	1.00
- Replace worn front brake pads.resurface rotors,replace calipers,flush and bleedsystem.service rear brakes.test drive.	Wd40 Spr	1.00
- Rotate and balance four tires.nitrofill.	Battery	1.00
- Shop Supplies	Fuse Holder	1.00
	Freon Lv Shop 2	3.00
	Brk Fluid Dot 4-12oz	1.00
	Non-chlor Brake Clnr	1.00
	Brake Pads	1.00
	Brake Caliper	1.00
	Brake Caliper	1.00
	Shop Supplies	1.00
Hours 11.75	Labor: 705.00	Parts: 535.48
:		Total: 1,240.48

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1712476 **Meter:** 59345 **In Date:** 12/19/2017 **Closed:** 12/21/2017
Problem: P.M. service and spare on right rear and left front door handle broken.

- P.m. Service.	Parts List	Qty
- R/r driver door panel and replace inop door lock actuator.replace broken latch cable.	handle	1.00
- Replace worn out front motor mount.	Engine Mount	1.00
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	5.00
	18" wiper blades	1.00
	Wiper Bleade Anco	1.00
	P205/65r15 Assurance	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 7.75	Labor: 465.00	Parts: 433.23
:		Total: 898.23

Workorder: 1712482 **Meter:** 59345 **In Date:** 12/15/2017 **Closed:** 12/19/2017
Problem: Passenger Rear flat tire

- Tire Service Lake Lytal Park - Passenger Rear flat tire	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1806094 **Meter:** 63914 **In Date:** 06/14/2018 **Closed:** 06/25/2018
Problem: PM Service,TPMS light on.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Pressure test and inspect cooling system.flush and refill system.	5w20 Engine Oil	5.00
- Service and adjust rear brakes.	18" wiper blades	1.00
- Complete wheel alignment.	Wiper Bleade Anco	1.00
- Shop Supplies	P205/65r15 Assurance	2.00
	Anti Freeze Motorcraft	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.25	Labor: 615.00	Parts: 345.51
:		Total: 960.51

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808467 **Meter:** 65245 **In Date:** 08/16/2018 **Closed:** 08/28/2018
Problem: Computer stand issue, A/C only blows cold when driving, Thermometer for cages does not show temp.

- A/c performance test . Replace Cooling fan ,fuses, A/c compressor,accumulator,orifice,fan pigtail,and high side line from compressor to condenser. Flush system . Evac and complete recharge .replace temp read out.

- Shop Supplies

Parts List	Qty
Indoor/outdoor Thermometer Digital	1.00
Fan Resistor Connector	1.00
Cooling Fan Assembly	1.00
Bp Fmx-lp F Mx Fuse	2.00
Freon Lv Shop 2	3.00
office tube	1.00
A/c Seal Kit	1.00
Compressor	1.00
Accumulator	1.00
Flush Solvent	1.00
Tube Assy	1.00
Shop Supplies	1.00

Hours 8.50 Labor: 510.00 Parts: 1,415.27 Total: 1,925.27
 :

Workorder: 1812407 **Meter:** 66725 **In Date:** 12/05/2018 **Closed:** 12/20/2018
Problem: Left front turn signal out .P.M. service.

- Test and replace left front turn signal bulb .
 - P.m. service.
 - Test and replace left headlight bulb .
 - Replace broken sliding door wedges on both sides.
 - Inspect and service rear brakes .
 - Rotate and balance all four tires .
 - Shop Supplies

Parts List	Qty
Bulb	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	4.00
Boxed Capsules	1.00
Door Wedge Assembly	2.00
Wedge Asm	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours 6.05 Labor: 405.35 Parts: 94.97 Total: 500.32
 :

Workorder: 1812984 **Meter:** 66877 **In Date:** 12/21/2018 **Closed:** 12/27/2018
Problem: Right rear tire going flat.

- Repair right rear tire and balance . Nitrogen fill tires.
 - Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 67.00 Parts: 3.00 Total: 70.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1904314 **Meter:** 69406 **In Date:** 04/19/2019 **Closed:** 04/29/2019
Problem: PM Service, Check transmission.

<ul style="list-style-type: none"> - P.m. service. - Test drive , Inspect and service transmission . Flush and replace transmission filter . Computer scan for codes . No could and could not duplicate concern at this time . - Replace two tires and rotate and high speed balance all four tires . Nitrofill all. - Inspect and service rear brakes . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">5.00</td></tr> <tr><td>18" wiper blades</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Bleade Anco</td><td></td><td align="right">1.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>oil auto</td><td></td><td align="right">7.00</td></tr> <tr><td>Ptex Ultra Grey 3oz</td><td></td><td align="right">1.00</td></tr> <tr><td>Transmission Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>205/65/15 Tire Continental</td><td></td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">2.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		5.00	18" wiper blades		1.00	Wiper Bleade Anco		1.00	Washer Fluid Concentr		1.00	oil auto		7.00	Ptex Ultra Grey 3oz		1.00	Transmission Filter		1.00	205/65/15 Tire Continental		2.00	Shop Supplies		1.00	Tire Disposal Fee		2.00
Parts List		Qty																																			
Napagold Oil Filter		1.00																																			
5w20 Engine Oil		5.00																																			
18" wiper blades		1.00																																			
Wiper Bleade Anco		1.00																																			
Washer Fluid Concentr		1.00																																			
oil auto		7.00																																			
Ptex Ultra Grey 3oz		1.00																																			
Transmission Filter		1.00																																			
205/65/15 Tire Continental		2.00																																			
Shop Supplies		1.00																																			
Tire Disposal Fee		2.00																																			
Hours 8.25 :	Labor: 552.75 Parts: 493.14 Total: 1,045.89																																				

Workorder: 1904846 **Meter:** 69572 **In Date:** 05/02/2019 **Closed:** 05/07/2019
Problem: Rear a/c inop.

<ul style="list-style-type: none"> - Diagnose rear cage A/c inop . Replace defective blower switch and power relay . Retest . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Ptex Superbond Sm</td><td></td><td align="right">1.00</td></tr> <tr><td>Switch</td><td></td><td align="right">1.00</td></tr> <tr><td>Relay</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Ptex Superbond Sm		1.00	Switch		1.00	Relay		1.00	Shop Supplies		1.00
Parts List		Qty														
Ptex Superbond Sm		1.00														
Switch		1.00														
Relay		1.00														
Shop Supplies		1.00														
Hours 1.50 :	Labor: 100.50 Parts: 31.28 Total: 131.78															

Workorder: 1905259 **Meter:** 69674 **In Date:** 05/15/2019 **Closed:** 05/23/2019
Problem: Check engine light and transmission bangs into gear .

<ul style="list-style-type: none"> - Computer diagnose check engine light , code P0773 . R&r defective transmission assembly and replace transmission cooler , flush lines . Fill transmission fluid and road test . Reset Kam . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Tramission Assy</td><td></td><td align="right">1.00</td></tr> <tr><td>Tramission Oil Cooler</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Tramission Assy		1.00	Tramission Oil Cooler		1.00	Shop Supplies		1.00
Parts List		Qty											
Tramission Assy		1.00											
Tramission Oil Cooler		1.00											
Shop Supplies		1.00											
Hours 11.00 :	Labor: 737.00 Parts: 2,871.77 Total: 3,608.77												

Workorder: 1909506 **Meter:** 72031 **In Date:** 09/16/2019 **Closed:** 09/23/2019
Problem: P.M. service , left side sliding door inop and check battery .

<ul style="list-style-type: none"> - P.m. service. - Check battery and charging system after fully charging battery . Battery failed load test . R&r defective battery . - Check and replace leaking valve cover and clean excess oil . - Test and replace left side sliding door latch assmby . Retest . - Balance and rotate all four tires . Nitrofill all. - Inspect and service rear brakes . - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">5.00</td></tr> <tr><td>18" wiper blades</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Bleade Anco</td><td></td><td align="right">1.00</td></tr> <tr><td>Battery</td><td></td><td align="right">1.00</td></tr> <tr><td>Valve Cover Gasket</td><td></td><td align="right">1.00</td></tr> <tr><td>latch</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		5.00	18" wiper blades		1.00	Wiper Bleade Anco		1.00	Battery		1.00	Valve Cover Gasket		1.00	latch		1.00	Shop Supplies		1.00
Parts List		Qty																										
Napagold Oil Filter		1.00																										
5w20 Engine Oil		5.00																										
18" wiper blades		1.00																										
Wiper Bleade Anco		1.00																										
Battery		1.00																										
Valve Cover Gasket		1.00																										
latch		1.00																										
Shop Supplies		1.00																										
Hours 8.55 :	Labor: 572.85 Parts: 722.22 Total: 1,295.07																											

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1910330 **Meter:** 72355 **In Date:** 10/04/2019 **Closed:** 10/16/2019

Problem: Check engine light ,shaking, overheating and A/C inop.

- Computer diagnose check engine light , code P1299 . Perform pinpoint test . Pressure test cooling system . R&r leaking radiator ,thermostat ,and cap. Flush cooling system and refill . Clear codes and retest .	Parts List	Qty
	Thermostat	1.00
	Radiator Assy	1.00
- Shop Supplies	Anti Freeze Motorcraft	2.00
	Radiator Cap	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 511.00	Parts: 316.32
:		Total: 827.32

Workorder: 2003397 **Meter:** 72355 **In Date:** 04/03/2020 **Closed:** 04/03/2020

Problem: remove decals for surplus

- fremove extra decals	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 4.00
:		Total: 77.00

Workorder: 2003412 **Meter:** 72355 **In Date:** 04/03/2020 **Closed:** 04/03/2020

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			