K11491 2004 GMC 1500 Pickup, 1/2 Ton, W/8 Ft. Body

		K11491	200	4 GMC 1500 P	rickup, 1	/2 10n, W/8	Ft. Body			
Workorder: Problem:	439223 PRE-DE	Meter: LIVERY INSPE	0 CTION			In Date:	03/25/2004	Closed:	03/25/20	004
- Pre-delivery	Inspection	n								
		Hours 2.00 :		Labor:	100.00	Parts:	0.00	Total:	100.00	
Workorder: Problem:	439340 INSTALI	Meter: L STROBE LIGH	13 HT.			In Date:	03/26/2004	Closed:	03/30/20	004
- Fabricate &	Install Str	obe Light Assy.			Parts L	ist				Qty
- Shop Suppli	ies				Shop St	upplies				1.00
					Ds-167	Toggle Swit	ch (standard	l)		1.00
					Ds366	Red Pilot Li	ght			1.00
		Hours 3.00		Labor:	150.00	Parts:	10.09	Total:	160.09	
Workorder: Problem:	439912 FAB LIG	Meter: HT BRACKET	13			In Date:	04/01/2004	Closed:	04/13/20	004
- Fab Light Bi	racket				Parts L	ist				Qty
- Welding Su					Shop Su	upplies				1.00
	•				•	2 Alum Flat	Bar			1.00
					3/16x4x	12 Alum Pla	ate 5052			1.00
					1/4x2x4	x20 Alum A	ngle 6063			1.00
					1/4x2x2	4 Sq. Alum	Tube			3.00
		Hours 4.00		Labor:	200.00	Parts:	36.59	Total:	236.59	
Workorder: Problem:	443116 TAG CH	Meter:	472			In Date:	04/30/2004	Closed:	04/30/20	004
- Tag Charge	ı				Parts L	ist				Qty
0 0					Tag Cha	arge				1.00
		Hours 0.00		Labor:	•	_	34.35	Total:	34.35	
Workorder: Problem:	451244 SCREW	Meter:	1724			In Date:	07/19/2004	Closed:	07/22/20	004
- Tire Repair					Parts L	ist				Qty
- Shop Suppli	ies				Shop Su					1.00
		Hours 1.00		Labor:	•	Parts:	2.00	Total:	52.00	
Workorder:	462100	Meter:	3470	INED TIE DOV	VNIC	In Date:	11/18/2004	Closed:	11/19/20	004
		RVICE,NEEDS 4	+ DED L	INER HE DOV		. ,				•
- Pms Service		.			Parts L					Qty
- Install Bed L		Jowns.			Shop St		L4 DL 47 \^"	F4040		1.00
- Shop Suppl	ies						bf Ph47 Wix	51040		1.00
						Motor Oil	4 A al			5.00
		II 0.75				Stake Pocke		-	400.0=	4.00
		Hours 2.75		Labor:	137.50	Parts:	42.57	ı otal:	180.07	

Workorder: 552076 Meter: 6496 Problem: P.M.SERVICE		In Date: 08/03/2005 Closed: 08/05/2	2005					
- Pm Service		Parts List	Qty					
- R&r All 4 Tires		Shop Supplies						
- Cooling Sys Pressure Test; Tighten Hose Clamps		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00					
- Shop Supplies		10w30 Motor Oil	5.00					
		773430430 235/75r16 Wrangler St SI	4.00					
Hours 4.50 :	Labor:	225.00 Parts: 424.13 Total: 649.13						
Workorder: 635845 Meter: 8606 Problem: P.M.SERVICE		In Date: 03/16/2006 Closed: 03/20/2	2006					
- Pm Service		Parts List	Qty					
- Shop Supplies		Shop Supplies	1.00					
		Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00					
		6678 Air Filter Frm Ca8755a Wix 46678	1.00					
		3481 Fuel Filter Frm G3727 Wix 33481	1.00					
		10w30 Motor Oil	5.00					
Hours 2.00	Labor:	100.00 Parts: 33.57 Total: 133.57						
Workorder: 636870 Meter: 8777 Problem: STROBE LIGHT SWITCH BROKEN		In Date: 04/05/2006 Closed: 04/06/2	2006					
- Check & Replace Strobe Light Switch.		Parts List	Qty					
		Ds-167 Toggle Switch (standard)	4 00					
		20 TO Toggio Omion (Glandara)	1.00					
Hours 0.50 :	Labor:	. , ,	1.00					
Hours 0.50 : Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING.	Labor:	. , ,						
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING.	Labor:	25.00 Parts: 4.62 Total: 29.62						
: Workorder: 732494 Meter: 10925	Labor:	25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2	2007					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING Repair And Balance Right Rear Tire.	Labor:	25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies	2007 Qty					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire Shop Supplies		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies	2007 Qty 1.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire. - Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE,CHECK LIGHTS		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2	Qty 1.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00	2007 Qty 1.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire. - Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2 Parts List	Qty 1.00 2007 Qty					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire. - Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service - Replace Broken Rr Tail Light With Wires.		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2 Parts List Shop Supplies	2007 Qty 1.00 2007 Qty 1.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire. - Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service - Replace Broken Rr Tail Light With Wires. - Replace Fr Tires And Balance		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2 Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040	Qty 1.00 Qty 1.00 1.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire. - Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service - Replace Broken Rr Tail Light With Wires. - Replace Fr Tires And Balance - Alignment		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2 Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 10w30 Motor Oil	Qty 1.00 2007 Qty 1.00 1.00 5.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service - Replace Broken Rr Tail Light With Wires Replace Fr Tires And Balance - Alignment - Nitro Fill Tires		Parts List Shop Supplies Date: 01/10/2007 Closed: 01/109/2	Qty 1.00 Qty 1.00 1.00 5.00 2.00					
: Workorder: 732494 Meter: 10925 Problem: R/R TIRE LEAKING. - Repair And Balance Right Rear Tire Shop Supplies Hours 1.00 : Workorder: 732673 Meter: 10956 Problem: P.M SERVICE, CHECK LIGHTS - Perform Pm Service - Replace Broken Rr Tail Light With Wires Replace Fr Tires And Balance - Alignment - Nitro Fill Tires - Road Test.		25.00 Parts: 4.62 Total: 29.62 In Date: 01/08/2007 Closed: 01/09/2 Parts List Shop Supplies 55.00 Parts: 2.00 Total: 57.00 In Date: 01/10/2007 Closed: 01/19/2 Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 15224178 R/rear Tail Light Assembly	Qty 1.00 Qty 1.00 1.00 5.00 2.00 1.00					

Workorder: Problem:	738567 SLOW (CRANK	Meter: ING	11966			In Date:	05/14/2007	Closed:	05/15/20	07
- Test Starting	g And Ch	arging S	Sys.char	e And Test	Battery.	Parts L	ist				Qty
Battery Failed						Shop S	upplies				1.00
Warranty.						•	'8 Battery (a	cd 78ps)			1.00
- Shop Suppli	ies					·	• `	. ,			
		Hours :	1.00		Labor:	55.00	Parts:	94.81	Total:	149.81	
Workorder: Problem:	739714 FLAT TI	IRE	Meter:	12145			In Date:	06/06/2007	Closed:	06/08/20	07
- Repair R/f T	ire					Parts L	ist				Qty
- Shop Suppli	ies					Shop S	upplies				1.00
		Hours	1.00		Labor:	55.00	Parts:	2.00	Total:	57.00	
Workorder: Problem:	742195 P.M. SE	RVICE	Meter:	12729			In Date:	07/30/2007	Closed:	08/06/20	07
- Pm Service						Parts L	ist				Qty
- Balance And	d Refill Al	I 4 Tires	S.			Shop S	upplies				1.00
- Inspect Steering Sys For Fluid Leaks L/s Seals On Rack &						6678 A	x 46678		1.00		
Pinion Unit Leaking,r&r Rack And Pinion Assy Bleed & Flush						Ph3387		1.00			
Pwst Sys.						10020 I	njector Clea	ner Don't Red	order		1.00
- Speedometer Sticks At 130 Mph Perform Cluster Diagnostics. R&r Instrument Cluster And Reprogram Sys.							Motor Oil				5.00
- Wheel Align		annoni C	oldotol 7 ti	ia reprogra	iii Oyo.	Dash/cl		1.00			
- Shop Suppli						31-22 V	Viper Blades	22" Wiper Bla	ade		2.00
опор сарри	100					22-1000	Rack And	Pinion			1.00
		Hours	10.50		Labor:	577.50	Parts:	744.02	Total:	1,321.52	
Workorder: Problem:	834634 P.M SE	RVICE	Meter:	14320			In Date:	02/26/2008	Closed:	02/29/20	08
- Pm Service						Parts L	ist				Qty
- Rotate & Hig	gh Speed	Baland	e 4 Tires	.refill W/nitre	ogen.	Shop S	upplies				1.00
- Shop Suppli						Ph3387	a Oil Filter L	.bf Ph47 Wix s	51040		1.00
						3481 Fu	uel Filter Frr	m G3727 Wix	33481		1.00
								ner Don't Red			1.00
							Motor Oil				5.00
								22" Wiper Bl	ade		2.00
							•	d Fire Extings			1.00
		Hours	3.00		Labor:	180.00		48.29		228.29	
Workorder: Problem:	835687 FLAT TI	IRE	Meter:	14410			In Date:	03/18/2008	Closed:	03/19/20	08
- Repair Flat	Line					Parts L	ist				Qty
- Shop Suppli						Shop S					1.00
		Hours	1.00		Labor:	-	Parts:	2.00	Total:	62.00	

Workorder: 838421 Meter: 14924 Problem: CHECK TIRES & ALIGNMENT	In Date: 05/13/2008 Closed:	05/14/2008
- Mount,balance And Nitro Fill 2 New Tires And Mount On	Parts List	Qty
Front	Shop Supplies	1.00
- Complete Front End Alignment Test Drive.	Tire Disposal Fee	2.00
- Shop Supplies	773430430 235/75r16 Wrangler St Sl	2.00
Hours 4.00 Labor:	•	468.02
Workorder: 846616 Meter: 17129 Problem: P.M SERVICE	In Date: 11/03/2008 Closed:	11/06/2008
- Pm Service	Parts List	Qty
- Pressure Test And Inspect Cooling Sys.flush And Refill	Shop Supplies	1.00
Sys.	6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Service Trans.flush And Refill	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Rotate And High Speed Balance All 4 Tires.nitro Fill To	3481 Fuel Filter Frm G3727 Wix 33481	1.00
Specs.	Wd40 Spray Lube Stock# 405540002	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Syn/atf Trans Fluid Synthetic	12.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 6.50 Labor:	390.00 Parts: 149.55 Total:	539.55
Workorder: 937353 Meter: 19622 Problem: PARK BRAKE RELEASE CABLE BROKEN.P.	In Date: 05/04/2009 Closed:	05/11/2009
Troblem: Trutt bit it the telephole of blee bit often.	VISLITATOL	
- Pm Service	Parts List	Qty
		Qty 1.00
- Pm Service	Parts List	-
- Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill.	Parts List Shop Supplies	1.00
- Pm Service- Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill.- Replace Left Rear Brake Bulb.	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00 1.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean	1.00 1.00 1.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable	1.00 1.00 1.00 1.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil	1.00 1.00 1.00 1.00 5.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade	1.00 1.00 1.00 1.00 5.00 2.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs	1.00 1.00 1.00 1.00 5.00 2.00 1.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. - Shop Supplies 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00
 - Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill. - Replace Left Rear Brake Bulb. - Replace Broken Parking Brake Release Cable. - Complete Front End Alignment. Test Drive. - Shop Supplies 	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00 2.00
- Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill Replace Left Rear Brake Bulb Replace Broken Parking Brake Release Cable Complete Front End Alignment. Test Drive Shop Supplies Hours 7.80 : Workorder: 939305 Meter: 20458	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s 468.00 Parts: 329.93 Total: In Date: 06/22/2009 Closed:	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00 2.00 797.93
- Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill Replace Left Rear Brake Bulb Replace Broken Parking Brake Release Cable Complete Front End Alignment. Test Drive Shop Supplies Hours 7.80 : Workorder: 939305 Meter: 20458 Problem: CHECK REAR TIRES.	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s 468.00 Parts: 329.93 Total: In Date: 06/22/2009 Closed:	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00 2.00 797.93
- Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill Replace Left Rear Brake Bulb Replace Broken Parking Brake Release Cable Complete Front End Alignment. Test Drive Shop Supplies Hours 7.80 Labor: : Workorder: 939305 Meter: 20458 Problem: CHECK REAR TIRES Mount, Hi Speed Balance And Nitrofill 2 Tires.put On Front.	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s 468.00 Parts: 329.93 Total: In Date: 06/22/2009 Closed:	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00 2.00 797.93
- Pm Service - Mount 2 Nfew Tires On Front. Balance All 4, Nitro Fill Replace Left Rear Brake Bulb Replace Broken Parking Brake Release Cable Complete Front End Alignment. Test Drive Shop Supplies Hours 7.80 Labor: : Workorder: 939305 Meter: 20458 Problem: CHECK REAR TIRES Mount, Hi Speed Balance And Nitrofill 2 Tires.put On Front.	Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean Parking Brake Release Handlewcable 10w30 Motor Oil 31-22 Wiper Blades 22" Wiper Blade 3157 Tail Light Bulbs Tire Disposal Fee 183680418 P235/75r16 Wrangler Sr-a 109s 468.00 Parts: 329.93 Total: In Date: 06/22/2009 Closed: Parts List Shop Supplies	1.00 1.00 1.00 1.00 5.00 2.00 1.00 2.00 2.00 797.93 Qty 1.00

Workorder: 1000275 Meter: 23438 Problem: P.M service, check radio speakers.	In Date: 01/07/2010 Closed:	01/22/2010
- P.m service.	Parts List	Qty
- Test audio system, replace R/f speaker behind door panel	Shop Supplies	1.00
- Test & replace L/r tail lamp bulb, replace R/f running lamp	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
bulb & socket.	3481 Fuel Filter Frm G3727 Wix 33481	1.00
 Test starting & charging system, charge & test battery, replace battery. 	10w30 Motor Oil	5.00
- R&r driver seat for repair.	R/f Speaker / 19116642	1.00
- Rotate & balance all four tires.	Used Firex Refurbed Fire Extingshers	1.00
- Take seat to upholstry shop for repairs, P/u when ready.	Ls94 Bulb Socket Drive Light (acd)	1.00
- Shop Supplies	4114k Bulb (acd)	1.00
	3157 Tail Light Bulbs	1.00
	Group 78 Battery (acd 78ps)	1.00
Hours 8.30 Labors	498.00 Parts: 198.20 Total:	696.20
Workorder: 1006399 Meter: 26075 Problem: Left front tire flat also see notes on brake light	In Date: 06/17/2010 Closed: out.	06/18/2010
- Test and replace failed right brake lamp bulb with new.	Parts List	Qty
- Repair and balance left front tire.	Shop Supplies	1.00
- Shop Supplies	3157 Tail Light Bulbs	1.00
- Shop Supplies	_	1.00 92.80
- Shop Supplies	_	
- Shop Supplies	90.00 Parts: 2.80 Total:	92.80
- Shop Supplies Hours 1.50 : Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed:	92.80
- Shop Supplies Hours 1.50 Eabors Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak - Perform pm service.	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed: Parts List	92.80 07/21/2010 Qty
- Shop Supplies Hours 1.50 Eabor: Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak - Perform pm service. - Perform rear differential service.	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed: Parts List Shop Supplies	92.80 07/21/2010 Qty 1.00
- Shop Supplies Hours 1.50 Eabors Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak - Perform pm service. - Perform rear differential service. - Repair right front tire flat.rotate and balance all four tires.	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed: Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040	92.80 07/21/2010 Qty 1.00 1.00
- Shop Supplies Hours 1.50 Eabors Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak - Perform pm service. - Perform rear differential service. - Repair right front tire flat.rotate and balance all four tires.	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed: Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean	92.80 07/21/2010 Qty 1.00 1.00 1.00
- Shop Supplies Hours 1.50 Eabors Workorder: 1007352 Meter: 26570 Problem: P.M. service and right front tire has slow leak - Perform pm service. - Perform rear differential service. - Repair right front tire flat.rotate and balance all four tires.	90.00 Parts: 2.80 Total: In Date: 07/13/2010 Closed: Parts List Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 09997 Brake Clean 10w30 Motor Oil	92.80 07/21/2010 Qty 1.00 1.00 1.00 5.00

Workorder: 1100070 Meter: 29645 Problem: P.M. service and strobe light mount loose.	In Date: 01/03/2011 Closed:	01/20/2011
- Perform pm service.	Parts List	Qty
- Fabricate,install and secure strobe lamp bracket.test and	Shop Supplies	1.00
replace faild switch with new.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Diagnose clunking noise in steering system.inspect and replace failed steering intermediate shaft with new.	3481 Fuel Filter Frm G3727 Wix 33481	1.00
- Diagnose blower motor concern.test and replace failed	09997 Brake Clean	1.00
blower motor, resistor and harness with new.fabricate, repair	10w30 Motor Oil	5.00
and secure wire harness.	Used Firex Refurbed Fire Extingshers	1.00
- Transport vehicle to and from central auto trim shop for	Ds366 Red Pilot Light	1.00
repairing head liner.	19153614 Steer Shaft Intermediate (gmc)	1.00
- Repair two flat tires.nitrogen fill,rotate and balance all four.	Pt2195 Pigtail Blower Motor (acd)	1.00
- Shop Supplies	15-81683 Blower Motor (acd)	1.00
	22807123 Resistor Blower Motor (acd)	1.00
Hours 10.75 Labor:	645.00 Parts: 380.73 Total:	1,025.73
Workorder: 1108241 Meter: 33525 Problem: P.M. service.		08/18/2011
- P.m. Service.	Parts List	Qty
- Replace right side back up light.	Shop Supplies	1.00
- Replace and balance all four tires.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Remove left door and replace upper and lower bushings ad pins.	6678 Air Filter Frm Ca8755a Wix 46678	1.00
- Complete wheel alignment.	10w30 Motor Oil	5.00
- Shop Supplies	89025539 Door Hinge Bushing Kit (gmc)	2.00
опор оцррноз	Used Firex Refurbed Fire Extingshers	1.00
	31-22 Wiper Blades 22" Wiper Blade	2.00
	3157 Tail Light Bulbs	1.00
	183680418 P235/75r16 Wrangler Sr-a 109s	4.00
Have 0.50	Tire Disposal Fee	4.00
Hours 9.50 Labor:	570.00 Parts: 725.62 Total:	1,295.62
Workorder: 1110097 Meter: 34380 Problem: Abs and brake lights on .and A/C blower inop.	In Date: 09/21/2011 Closed:	09/29/2011
- Computer diagnose for abs light on pin test and replace	Parts List	Qty
failed ignition switch with new.clear codes with scan tool and	Shop Supplies	1.00
road test Shop Supplies	Ignition Switch	1.00

Workorder: Problem:	1205211 P.M. service.	Meter:	38202			In Date:	06/04/2012	Closed:	06/21/20)12	
- P.m. Service	Э.				Parts Lis	st .				Qty	
- Replace righ	nt headlamp.				Shop Sup	plies				1.00	
				vice and	d 3481 Fuel Filter Frm G3727 Wix 33481 1.						
•	lush and bleed	-	nd test drive.		22514722	2 O-ring S	eal Fuel Filter	(acd 217-45	52)	2.00	
	balance all tires	i.			Ph3387a	Oil Filter L	_bf Ph47 Wix 5	51040		1.00	
- Shop Suppli	es				Mkd792 F	Rear Pads				1.00	
					2232 Bra	ke Fluid Q	uart			1.00	
					10w30 M	otor Oil				5.00	
					31-22 Wi	per Blades	s 22" Wiper Bla	ade		2.00	
					Used Fire	ex Refurbe	d Fire Extings	hers		1.00	
					9006 Bull	o Assy				1.00	
	Hours :	s 7.50		Labor:	450.00	Parts:	104.54	Total:	554.54		
Workorder: Problem:	1303009 P.M. service.	Meter:	42516			In Date:	03/27/2013	Closed:	04/05/20)13	
- Perform pm	service.				Parts Lis	it				Qty	
- Test and replace failed left D.r.l bulb and socket with new.fabricate and insulate wiring.				10w30 Motor Oil Napagold Oil Filter							
- Install two new tires to the front wheels.nitrogen fill and									1.00		
balance all fou			J			l Fuel Filte				1.00 2.00	
- Shop Suppli	es				Washer F	per Blades	5 22			1.00	
						י ex Refurbe	nd F			1.00	
					4114k Bu					1.00	
						Socket D)riv			1.00	
						18 P235-7				2.00	
					Shop Sup		0110			1.00	
					Tire Disp	•				2.00	
	Hours	s 4.75		Labor.	285.00		434.18	Total:	719.18	2.00	
· · ·	:		10001								
Workorder: Problem:	1312474 Pm service.	Meter:	46024			In Date:	12/16/2013	Closed:	12/19/20	013	
- Perform pm	service.				Parts Lis	st .				Qty	
	and charging			dtest	10w30 M	otor Oil				5.00	
•	replace failed b	-			Napagolo	Oil Filter				1.00	
 Install two n balance all fou 	ew tires to the f	ront whee	els.nitrogen fill a	and	Used Fire	X Refurb	ished			1.00	
- Shop Suppli					Group 78	•				1.00	
Chiep Cuppii					1836804	18 P235-7	5r16			2.00	
					Shop Sup	oplies				1.00	
					Tire Disp					2.00	
	Hours :	s 5.00		Labor:	300.00	Parts:	500.94	Total:	800.94		

Workorder: Problem:	1408879 Pm service	Meter: 490 and install custo	041 mer supplied to		In Date: of truck be	09/03/2014 ed.	Closed:	09/22/201	4		
- Pm service.				Parts Lis	t				Qty		
	diagnose wir	per electrical for	wiper and wash						5.00		
		er motor assemb		Napagold					1.0		
	hment and ir	nstall used tool b	ox on driver sid						2.0		
ront of bed .				•	Napagold Fuel Filter						
•		e and balance al	I four.		Washer Fluid Concentr						
- Shop Suppli	es			Reman W	/iper Moto		1	1.0			
				Shop Sup	plies			1	1.0		
	Ho	ours 6.50	Lab	or: 390.00	Parts:	148.27	Total:	538.27			
Vorkorder:	1504993	Meter: 518	847		In Date:	05/15/2015	Closed:	05/29/201	5		
Problem:	Pm service.	.Check trailer plu	ıg,radio,speakeı	and tires.							
- Pm service.				Parts Lis	t				Qt		
		defective front of		lso 10w30 M	otor Oil			5	5.0		
•	•	ig receptacle due	eto corrosion.	Napagold	Oil Filter			1	1.0		
Replace and				Napagold	Napagold Oil Filter						
Perform tran	Used Fire	Used Fire X Refurbished									
Complete from	Wiper Bla	de			2	2.0					
Shop Suppli	Stg Whee		•		1	1.0					
- опор оцррпез			Vinyl Elec	•				1.0			
				Trailer Co					1.0		
				Syn-atf Ti	rans Fluid	S			6.0		
				Speaker				2.0			
				18368041	8 P235-7			4.0			
				Filter Kit	ممالم			1.0			
				Shop Sup					1.0		
	Ho	ours 11.25	Lab	Tire Dispo or: 675.00		1,015.99	Total:	1,690.99	4.0		
	:										
Vorkorder: Problem:	1511220 Pm service.	Meter: 530 Flat tire.Missing.	696 wheel covers.		In Date:	11/02/2015	Closed:	11/23/201	5		
- Pm service.				Parts Lis	t				Qt		
- Resurface fr	ont brake rot	tors.replace front	t brake	10w30 M	otor Oil				5.0		
ads.service o	•			Napagold	Oil Filter			1	1.0		
		ing system.batte	ry failed loadtes	^{it} Wiper Bla	de			2	2.0		
_	•	ective battery.	all four	Napagold	Fuel Filte	er		1	1.0		
- Repair right front tire.rotate and balance all four.				Napagold	Napagold Air Filter				1.0		
· Shop Suppli	53			Disc Brak	Disc Brake Pads				1.0		
				Group 78	Battery		1	1.0			
				Battery C	able Bolt			2	2.0		
				Auter Cap	Wheel			2	2.0		
				Shop Sup	plies			1	1.0		

Workorder:	1604221	Meter:	55270			In Date:	04/21/2016	Closed:	04/29/20)16
	_	ough and stall			Danie I	•-4				01-
coil.clear code		diagnose and I drive.	repair wiring	Ю	Parts Li					Qty
- Shop Suppli					Test Co					1.00
		Hours 2.00		Labor	Shop St 120.00		48.17	Total	168.17	1.00
	:	10u15 2.00		Labor.	120.00	rans.	40.17	TOtal.	100.17	
Workorder: Problem:	1605034 P.M. Serv	Meter:	55453			In Date:	05/13/2016	Closed:	05/20/20)16
- P.m. Service	э.				Parts L	ist				Qty
		turn off.perfori	m pin point		10w30 N	Motor Oil				5.00
test.replace de		•			Napago	ld Oil Filter				1.00
 Power steer rack & pinnion 		fluid low.inspe	ect and replac	ce leaking	22" Wip	er Blade				2.00
•			takina too lor	na to	Used Fi	re X Refurbi	ished			1.00
- Diagnose check engine light, engine taking too long to reach operating temperature.replace themostat.flush and ref					Reman	Rack And P	inion			1.00
cooling system.clear codes.					Psf Qt 1.0					
- Complete wheel alignment.test drive.					Thermostat 1.00					
- Rotate and balance all tires.					Peak GI	lobal Antifrz				1.00
- Shop Suppli	es				Reman	Wiper Moto	r			1.00
					V-ribbed	d Belt				1.00
					Shop St	upplies				1.00
	}	Hours 14.00		Labor:	840.00	Parts:	455.89	Total:	1,295.89)
Workorder: Problem:	1606102 Towed for	Meter:	55590			In Date:	06/14/2016	Closed:	06/21/20)16
- Diagnose ar	nd replace	defective starte	er.		Parts L	ist				Qty
- Shop Suppli	-									1.00
					Shop St	upplies				1.00
	H ·	Hours 1.25		Labor:	75.00	Parts:	180.68	Total:	255.68	
Workorder: Problem:	1606116 No start	Meter:	55502			In Date:	06/14/2016	Closed:	06/14/20)16
- Tow From: A	Aiport-short	t term parking	To: Lv shop							
		Hours 0.00	·	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1607879 Rear view	Meter: mirror fell off.	56083			In Date:	08/01/2016	Closed:	08/10/20)16
- Reglue rear	view mirror				Parts L	ist				Qty
Ü						iew Mir Adh	Cd			1.00
	ŀ	Hours 0.50		Labor:	30.00	Parts:	3.86	Total:	33.86	

Workorder: 1613241 Meter: 57294 Problem: P.M. Service.	In Date: 12/30/2016	Closed: 01/30/201	7				
- P.,m. Service.	Parts List		Qty				
- Replace right headlamp bulb and connector.	10w30 Motor Oil						
- Pressure test and inspect cooling system replace leaking	Napagold Oil Filter	2	2.00				
heater hoses.flush and refill system.	22" Wiper Blade	4	4.00				
- Replace broken right rear wheel stud and lug nut.rotate and	Washer Fluid Concentr	2	2.00				
balance tires.	183680418 P235-75r16	2	2.00				
- Test batterry and charging system.replace bad battery.	Non-chlor Brake Clnr	1	1.00				
Replace broken pintle pin.Shop Supplies	Brake Rotor	2	2.00				
- Shop Supplies	Bulb	2	2.00				
	Ptex Rview Mir Adh Cd	1	1.00				
	Used Fire X Refurbished	1	1.00				
	Napagold Fuel Filter	1	1.00				
	Disc Brake Pads	1	1.00				
	Stg Wheel Cov - Chevy	1	1.00				
	Drain Plug		1.00				
	9006 Headlight	1	1.00				
	Halogen Capsule		1.00				
	Heater Hose Assembly		1.00				
	Hose		1.00				
	Peak Global Antifrz		2.00				
	Rear Wheel Nut		1.00				
	Wheel Stud		1.00				
	Battery		1.00				
	Pintle Pin W/clip		1.00				
	Hose Clamp		2.00				
	Shop Supplies		1.00				
Hours 8.50 Labor:	Tire Disposal Fee 510.00 Parts: 912.23	0 Total: 1,422.23	0.00				
<u> </u>							
Workorder: 1802780 Meter: 59487 Problem: PM Service, Check AC/Heater.	In Date: 03/14/2018	Closed: 03/23/2018	8				
- P.m. Service.	Parts List		Qty				
- Replace and balance four new tires.	10w30 Motor Oil	5	5.00				
- Diagnose heater issue.replace temp door actuator and	Napagold Oil Filter	1	1.00				
recalibrate all system actuators.	Drain Plug	1	1.00				
- Transport vehicle to upholstery shop to repair headliner.	Napagold Fuel Filter	1	1.00				
- Shop Supplies	Used Fire X Refurbished	1	1.00				
	22" Wiper Blade	2	2.00				
	183680418 P235-75r16	4	4.00				
	Actuator	1	1.00				
	Headliner R&r	1	1.00				
	Shop Supplies	1	1.00				
	Tire Disposal Fee	4	4.00				
Hours 6.50 Labor:	390.00 Parts: 1,373.88	Total: 1,763.88					

:

Workorder: 1812372 Meter: 61094 Problem: P.M. service.		In Date:	12/05/2018	Closed:	12/13/2018		
- P.m. service.		Parts List			Qty		
- Replace both rear bump stops .		Napagold Oil Filte	er		1.00		
- Replace missing tail handle bezel .		10w30 Motor Oil			5.00		
- Rotate and balance all four tires. Nitrofill all.		Engine Oil Stop L	eak		1.00		
- Shop Supplies		Washer Fluid Cor	ncentr		1.00		
		22" Wiper Blade	2.00				
		Bump Stopers		2.00			
		Tail Gate Handle		1.00			
		Shop Supplies			1.00		
Hours 3.70	Labor:	247.90 Parts	s: 139.98	Total:	387.88		
Workorder: 1905644 Meter: 62160 Problem: PM Service		In Date:	05/29/2019	Closed:	06/05/2019		
- P.m. service.		Parts List			Qty		
- Rotate and balance all four tires . Nitrofill all tires .		Napagold Oil Filter					
- Shop Supplies		10w30 Motor Oil			5.00		
		Washer Fluid Cor	ncentr		1.00		
		22" Wiper Blade			2.00		
		Used Fire X Refu	rbished		1.00		
		Napagold Fuel Fil	1.00				
		. •					
		Shop Supplies			1.00		

Workorder: 1913036 Meter: 63703 Problem: PM Service		In D	ate:	12/20/2019	Closed:	01/08/2020
- P.m. service.		Parts List				Qty
- Charge battery fully . Test battery and charging syste	m .	Drain Plug	1.00			
Battery failed load test . R&r defective battery .,		10w30 Motor		5.00		
 Replace rear brake rotors and pads . Service calipers Flush and bleed brake system . Road test . 	3.	Napagold Oil	Filter		1.00	
- Replace broken tailgate handle and bezel .		22" Wiper Bla	ade			2.00
- Pressure test and inspect cooling system . Replace le	akina	Washer Fluid	Conce	entr		1.00
intake gaskets . Flush and refill coolant . Retest .	Sakiriy	Battery				1.00
- Perform tune up . Replace cap and rotor and all six s	park	Brake Rotor				2.00
plugs and wire set .		Brake Pad				1.00
- Performair intake decarb and cleaning , clean throttle	body .	Non-chlor Bra	ake Clr	nr		1.00
- Rotate and balance all four tires . Nitrofill all.		B Fluid Dot 3	-32oz			1.00
- Shop Supplies		Tailgate Hand	dle			1.00
		Tail Gate Har		1.00		
		Intake Gaske	t			1.00
		Dex Coolant	Engine)		2.00
		Distributor Ro		1.00		
		Distributor Ca		1.00		
		41-993 Spark	kplug			6.00
		Splg Wire				1.00
		Permatex				1.00
		Intake Cleane	er Kit			1.00
		Shop Supplie	es			1.00
Hours 17.50 :	Labor:	1,277.5 0	Parts:	751.33	Total:	2,028.83
Workorder: 2000979 Meter: 63769 Problem: Rear brakes hanging up .		In D	ate:	01/29/2020	Closed:	02/10/2020
- Diagnose brakes hanging up . Replace both rear bral	ke	Parts List				Qty
calipers . Flush and bleed brake system . Replace one		Reman Brake	e Calip	er		1.00
and lug nut on left rear axle . Road test .		Reman Brake	e Calip	er		1.00
- Shop Supplies		B Fluid Dot 3	-32oz			1.00
		Rear Wheel N	Nut			1.00
		L/r Wheel Stu	ıd			1.00
		Shop Supplie	es			1.00
Hours 2.60	Labor:			139.33	Total:	1.00 329.13