		10 <sup>.</sup>	185032	2011 FOR	) F150 P	ickup, 1/2 1	Γon			
Workorder:	1105228	Meter:	0			In Date:	05/17/2011	Closed:	05/17/2	011
Problem:	Pre Delivery I	nspection								
- Pre Delivery	Inspection									
	Hour	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder:		Meter:	1127			In Date:	06/24/2011	Closed:	06/30/2	011
Problem:	Driver's mirro	r broke.Ins	tall cargo	net						
- Inspect and	replace damag	ae driver si	de mirror	with new.	Parts L	ist				Qty
- Fabricate ar	nd secure cargo	o net in cal	bed with	new hooks	Shop Si	upplies				1.00
and anchors.					Mirror G	Blass				1.00
- Shop Suppli										
	Hour :	s 2.00		Labor:	120.00	Parts:	87.25	Total:	207.25	
Workorder:	1108918	Meter:	2790			In Date:	08/23/2011	Closed:	08/25/2	011
Problem:	Left rear tire f	lat.								
- Repair flat le	eft rear tire.nitro	ogen fill an	d balance	same.	Parts L	ist				Qty
- Shop Suppli	es				Shop Si	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1108979 need 1 extra l	Meter: key	2929			In Date:	08/24/2011	Closed:	08/25/2	011
- Make and p	rogram 1 extra	kev			Parts L	ist				Qty
- Shop Suppli	-				164-r80	40 Ignition k	Key 2011- Nev	wer (ford)		1.00
					Shop Si	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	25.25	Total:	85.25	
Workorder:		Meter:	5236			In Date:	10/06/2011	Closed:	10/24/2	011
	Pm service		0_00							•••
- Perform pm	service.				Parts L	ist				Qty
- Rotate and I	palance all four	tires.			Shop Si	upplies				1.00
- Shop Suppli	es				Ph1057	5 Oil Filter N	Atc FI500s Wi	x 57502		1.00
					5w20 E	ngine Oil				6.00
					Used Fi	rex Refurbe	d Fire Extings	shers		1.00
	Hour	s 3.00		Labor:	180.00	Parts:	33.83	Total:	213.83	
Workorder: Problem:	1203619 Pm service.	Meter:	9715			In Date:	04/17/2012	Closed:	04/26/2	012
- P.m. Service	Э.				Parts L	ist				Qty
	palance all tires	3.			Shop Si					1.00
- Shop Suppli	es					• •	Atc FI500s Wi	x 57502		1.00
						ngine Oil				7.00
	Hour	s 3.00		Labor:	180.00	-	22.27	Total:	202.27	
	:									

Workorder: Problem:	1203958 1 - Wash tick	Meter: et(s) issued	9567 1			In Date:	04/26/2012	Closed:	04/26/2012
- 1 - Wash tick	ket(s) issued								
	Hou :	irs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1207037 damage frt b	Meter: umper, rgt f	11587 rt fender &	head It		In Date:	07/19/2012	Closed:	07/30/2012
- damage frt b	umper, rgt frt	fender & h	ead It						
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1210728 P.M. Service	<b>Meter:</b> .Repair lap	14117 op stand.			In Date:	11/02/2012	Closed:	11/30/2012
- P.m. Service	).				Parts L	.ist			Qt
- Install floor r	nats.				5w20 E	ngine Oil			7.0
- Rotate and b	alance all tire	s.			Ph1057	75 Oil Filter N	Лt		1.0
- Shop Suppli	es				Ca1026	62 Air Filter N	Лt		1.0
					31-22 V	Viper Blades	s 22		2.0
					Used F	irex Refurbe	d F		1.0
					Floor N	lat-2pc Rub	Bk		1.0
					Shop S	Supplies			1.0
	Hou :	irs 3.25		Labor:	195.00	Parts:	99.58	Total:	294.58
Workorder: Problem:	1306104 Pm service.V	Meter: Vrench ligh	18676 on and off.	Runs rough	۱.	In Date:	06/18/2013	Closed:	07/30/2013
- P.m. Service	<b>)</b> .				Parts L	ist			Qt
- Rotate and b	alance all fou	ır tires.			5w20 E	ngine Oil			6.0
- Transport ve	hicle to deale	r for wrencl	n light on.(p	0722,trans.	Ph1057	75 Oil Filter N	Лt		1.0
connector.)					Wiper E	Blade			2.0
- Shop Suppli	es				Shop S	Supplies			1.0
	Hou :	ırs 5.00		Labor:	300.00	Parts:	35.71	Total:	335.71
Workorder:	1400736	Meter:	22555			In Date:	01/09/2014	Closed:	01/31/2014
Problem:	damage to re	ear bumper	& tail gate						
- damage to re	ear bumper &	tail gate							
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

	401270 Pm service a	Meter: nd check fo	22710 or noise wher	n Ac is on.		In Date:	02/06/2014	Closed:	02/19/2014
- P.m. Service.					Parts L	ist			Qt
- Check noise in			s on.replace		5w20 E	ngine Oil			7.0
dewfective blend			n volio to por	** • • <b>1</b>	Napago	1.0			
- R&r driveshaft clunking noise a			p yoke to cor	rect	Wiper B	2.0			
- Rotate and ba	-					re X Refurbi			1.0
- Shop Supplies	5					rd Lck Blue	Lg		1.0 1.0
					Repair I	emp. Blend ≺it			1.0
					Shop Si				1.0
	Hou	rs 6.75		Labor:	405.00	••	126.01	Total:	531.01
Workorder: 1 Problem: [	: 405009 Damage mirre	Meter: or.	24955			In Date:	05/22/2014	Closed:	05/29/2014
- Remove pass	enger door p	anel and r	eplace broker	n mirror	Parts L	ist			Qt
assemble.					Mirror				1.0
- Shop Supplies	5				Shop S	upplies			1.0
	Hou	rs 1.00		Labor:	60.00	Parts:	240.59	Total:	300.59
Workorder: 1 Problem: F	409005 Pm service.C	Meter: heck batte	26840 ry.			In Date:	09/08/2014	Closed:	09/22/2014
<ul> <li>Pm service.</li> </ul>									
					Parts L				Qt
- Check battery				oad test	5w20 E	ngine Oil			7.0
	eplace defect	tive battery		oad test	5w20 Ei Napago	ngine Oil Id Oil Filter			7.0 1.0
- Check battery after recharge.re	eplace defect balance all fo	tive battery our tires.	<i>.</i>	oad test	5w20 Ei Napago Wiper B	ngine Oil Id Oil Filter Iade			7.0 1.0 2.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> </ul>	eplace defect palance all fo plete front end	tive battery our tires.	<i>.</i>	oad test	5w20 En Napago Wiper B Washer	ngine Oil Id Oil Filter Iade Fl	shed		7.0 1.0 2.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and backers</li> <li>Perform comp</li> </ul>	eplace defect palance all fo plete front end	tive battery our tires.	<i>.</i>	oad test	5w20 En Napago Wiper B Washer Used Fi	ngine Oil Id Oil Filter Iade Fl re X Refurbi	ished		7.0 1.0 2.0 1.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and backers</li> <li>Perform comp</li> </ul>	eplace defect palance all fo plete front end	tive battery our tires.	<i>.</i>	oad test	5w20 En Napago Wiper B Washer Used Fi Battery	ngine Oil Id Oil Filter Iade Fl re X Refurbi			7.0 1.0 2.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and backers</li> <li>Perform comp</li> </ul>	eplace defect palance all fo plete front end	tive battery our tires.	<i>.</i>	oad test	5w20 En Napago Wiper B Washer Used Fi Battery	ngine Oil Id Oil Filter Iade Fl re X Refurbi 65 17 Adventur			7.0 1.0 2.0 1.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and backers</li> <li>Perform comp</li> </ul>	eplace defect palance all fo plete front end	tive battery our tires.	<i>.</i>	oad test	5w20 En Napago Wiper B Washer Used Fi Battery 235 75r Shop Se	ngine Oil Id Oil Filter Iade Fl re X Refurbi 65 17 Adventur			7.0 1.0 2.0 1.0 1.0 1.0 4.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> <li>Perform comp</li> </ul>	eplace defecto palance all fo plete front end s	tive battery our tires.	<i>.</i>		5w20 En Napago Wiper B Washer Used Fi Battery 235 75r Shop Se	ngine Oil Id Oil Filter Iade Fl re X Refurbi 65 17 Adventur upplies posal Fee		Total:	7.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> <li>Perform comp</li> <li>Shop Supplies</li> </ul>	eplace defect palance all fo plete front end s Hour : 1409022	tive battery our tires. d alignmen	<i>.</i>		5w20 El Napago Wiper B Washer Used Fi Battery 235 75r Shop So Tire Dis	ngine Oil Id Oil Filter Iade Fl re X Refurbi 65 17 Adventur upplies posal Fee	e	Total: Closed:	7.0 1.0 2.0 1.0 1.0 1.0 4.0 4.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> <li>Perform comp</li> <li>Shop Supplies</li> </ul>	Hour Hour Hour Hour Hour Hour Hour Hour	tive battery our tires. d alignmen rs 7.50 Meter:	v. it.road test.		5w20 El Napago Wiper B Washer Used Fi Battery 235 75r Shop So Tire Dis	ngine Oil Id Oil Filter Idade Fl re X Refurb 65 17 Adventur upplies posal Fee Parts:	e 1,167.42		7.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0 4.0 1.0 4.0 1.0
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> <li>Perform comp</li> <li>Shop Supplies</li> </ul> Workorder: 1 Problem: N	eplace defecto palance all fo plete front end s Hour 1409022 No start d Floor Vista	tive battery our tires. d alignmen rs 7.50 Meter:	v. it.road test.		5w20 En Napago Wiper B Washer Used Fi Battery 235 75r Shop So Tire Dis 450.00	ngine Oil Id Oil Filter Idade Fl re X Refurb 65 17 Adventur upplies posal Fee Parts:	re 1,167.42 09/08/2014		7.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0 4.0 1,617.42
<ul> <li>Check battery after recharge.re recharge.re - Replace and b - Perform comp</li> <li>Shop Supplies</li> <li>Workorder: 1         Problem: N         - Tow From: 2n     </li> <li>Workorder: 1</li> </ul>	eplace defecto palance all fo plete front end s Hour 1409022 No start d Floor Vista	tive battery our tires. d alignmen rs 7.50 Meter: Garage rs 0.00 Meter:	v. it.road test.	Labor:	5w20 En Napago Wiper B Washer Used Fi Battery 235 75r Shop So Tire Dis 450.00	ngine Oil Id Oil Filter Idade Fl re X Refurbi 65 17 Adventur upplies posal Fee Parts: In Date:	re 1,167.42 09/08/2014	Closed:	7.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0 4.0 1,617.42
<ul> <li>Check battery after recharge.re</li> <li>Replace and b</li> <li>Perform comp</li> <li>Shop Supplies</li> <li>Workorder: 1</li> <li>Problem: N</li> <li>Tow From: 2n</li> <li>Workorder: 1</li> </ul>	eplace defector palance all foo plete front end s Hour i 409022 No start d Floor Vista Hour i 1410122 damage to frt	tive battery our tires. d alignmen rs 7.50 Meter: Garage rs 0.00 Meter:	nt.road test. 26840	Labor:	5w20 En Napago Wiper B Washer Used Fi Battery 235 75r Shop So Tire Dis 450.00	ngine Oil Id Oil Filter Iade Fl re X Refurbi 65 17 Adventur upplies posal Fee Parts: In Date: Parts:	re 1,167.42 09/08/2014 0.00	Closed: Total:	7.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0 4.0 1.0 4.0 1.617.42 09/08/2014

Workorder: Problem:	1505133 Pm service.	Meter:	27338		I	n Date:	05/20/2015	Closed:	06/02/2015
- P.m. Service	Э.				Parts List	t			Qty
- Replace bot	h leaking rear	shocks.			5w20 Eng	ine Oil			6.00
- Rotate and I	balance tires.				Napagold	Oil Filter			1.00
- Shop Suppli	ies				Wiper Bla	de			2.00
					Real Shoo	ck			2.00
					Shop Sup	plies			1.00
	Hou :	ırs 4.00		Labor:	240.00	Parts:	176.20	Total:	416.20
Workorder:	1511419	Meter:	27616		I	n Date:	11/06/2015	Closed:	11/06/2015
Problem:	3 - Wash tick	et(s) issued	d						
- 3 - Wash tic	ket(s) issued								
	Hou	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:		Meter:	28213		I	n Date:	11/16/2015	Closed:	11/24/2015
				d toko off					
Problem:	P.M. service	and cluckir	ig at stops an	u lake on	0.				
Problem: - Pm service.	P.M. service	and cluckin	ig at stops an		Parts List	t			Qty
- Pm service. - Inspect for r	noise when sto	opping and							<b>Qt</b> 6.00
- Pm service. - Inspect for r shaft clean an	noise when sto d lube slip joir	opping and t			Parts List	jine Oil			-
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou	opping and t			Parts List 5w20 Eng	ine Oil Oil Filter	shed		6.00
- Pm service. - Inspect for r shaft clean an	noise when sto d lube slip joir balance all fou	opping and t			<b>Parts List</b> 5w20 Eng Napagold	ine Oil Oil Filter X Refurbi			6.00 1.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou	opping and t			Parts List 5w20 Eng Napagold Used Fire	ine Oil Oil Filter X Refurbi Iuid Conce			6.00 1.00 1.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou	opping and t			Parts List 5w20 Eng Napagold Used Fire Washer F	ine Oil Oil Filter X Refurbi luid Conce de			6.00 1.00 1.00 1.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou	opping and t			Parts List 5w20 Eng Napagold Used Fire Washer F Wiper Bla	ine Oil Oil Filter X Refurbi luid Conce de	entr		6.00 1.00 1.00 2.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou	opping and t			Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Bla Repair Kit	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo	entr		6.00 1.00 1.00 1.00 2.00 1.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> </ul>	noise when sto d lube slip joir balance all fou ies	opping and t		ve drive	Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Bla Repair Kit Stg Whee	ine Oil Oil Filter X Refurbi luid Conce de de I Cov - Fo plies	entr	Total:	6.00 1.00 1.00 2.00 1.00 1.00
- Pm service. - Inspect for r shaft clean an - Rotate and I - Shop Suppli	noise when sto d lube slip joir balance all fou ies	opping and the second s	take off.remov	ve drive Labor:	Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de de I Cov - Fo plies	entr rd	Total: Closed:	6.00 1.00 1.00 1.00 2.00 1.00 1.00
- Pm service. - Inspect for r shaft clean an - Rotate and I - Shop Suppli	hoise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service	opping and the second s	take off.remov	ve drive Labor:	Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts:	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and I</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service.</li> </ul>	hoise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service	opping and the second s	take off.remov 33734 turnsignal ligh	ve drive Labor:	Parts List 5w20 Eng Napagold Used Fire Washer Fl Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts:	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78 03/23/2016
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and l</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service</li> <li>Replace two</li> </ul>	noise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service	opping and total art tires. ars 4.25 <b>Meter:</b> and check lbs,left rear	take off.remov 33734 turnsignal ligh	ve drive Labor:	Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Blac Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts: <b>In Date:</b> t Oil Filter	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78 03/23/2016
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and l</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service</li> <li>Replace two</li> <li>Rotate and l</li> </ul>	noise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service o turnsignal bu	opping and the second s	take off.remov 33734 turnsignal ligh	ve drive Labor: nts.	Parts List 5w20 Eng Napagold Used Fire Washer Fi Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts: <b>n Date:</b> t Oil Filter	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78 03/23/2016 <b>Qty</b> 1.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and l</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service</li> <li>Replace two</li> <li>Rotate and l</li> </ul>	hoise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service o turnsignal bu balance all fou d replace front	opping and the second s	take off.remov 33734 turnsignal ligh	ve drive Labor: nts.	Parts List 5w20 Eng Napagold Used Fire Washer F Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts: <b>n Date:</b> t Oil Filter	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78 03/23/2016 Qty 1.00 6.00
<ul> <li>Pm service.</li> <li>Inspect for r shaft clean an</li> <li>Rotate and l</li> <li>Shop Suppli</li> </ul> Workorder: Problem: <ul> <li>Pm service</li> <li>Replace two</li> <li>Rotate and l</li> <li>Make up and</li> </ul>	hoise when sto d lube slip joir balance all fou ies Hou 1602684 P.M. service o turnsignal bu balance all fou d replace front	opping and the second s	take off.remov 33734 turnsignal ligh	ve drive Labor: nts.	Parts List 5w20 Eng Napagold Used Fire Washer Fl Wiper Bla Repair Kit Stg Whee Shop Sup 255.00	ine Oil Oil Filter X Refurbi luid Conce de l Cov - Fo plies Parts: <b>n Date:</b> t Oil Filter jine Oil Blade	entr rd 86.78		6.00 1.00 1.00 2.00 1.00 1.00 341.78 03/23/2016 03/23/2016 Qty 1.00 6.00 2.00

Workorder: Problem:	1605920 P.M. service	Meter:	37924		lı	n Date:	06/08/2016	Closed:	06/21/20	016
- P.m. Servic	9.				Parts List					Qty
	efill transmisio	n svstem.			5w20 Engi					6.00
	st and inspect		tem.replace le	eaking	Napagold		1.00			
	nd thermostat.			g	22" Wiper		2.00			
- Rotate and	balance all tire	es.			Washer Fl			1.00		
- Shop Suppl	ies				Syn-atf Trans Fluid S					13.00
					Water Pun					1.00
					Thermosta	•				1.0
					Gasket					1.00
					Ford Red	Antifreeze	Э			2.00
					Gasket					1.00
					Thermosta	at Gasket				1.00
					Shop Supp	olies				1.00
	Hou	ırs 8.50		Labor:	510.00	Parts:	315.26	Total:	825.26	
Norkorder: Problem:	1608569 Check engin	Meter: e light on.	41096		lı	n Date:	08/17/2016	Closed:	08/31/20	016
- Diagnose cl	neck engine lig	ght.p2610.re	eflash Pcm pe	r Tsb 12	Parts List					Qt
-2-16.clear co							-			
- Perform pin poit test for P0455.perform evap system bay test.replace defective purge valve.clear code and retest.					Valva Asy					1.00
- Perform pin test.replace d	poit test for P efective purge	0455.perfor			Valva Asy Shop Supp	olies				
- Perform pin test.replace d	poit test for P efective purge ies	0455.perfor		est.			36.35	Total:	216.35	
- Perform pin test.replace d - Shop Suppl Workorder:	poit test for P efective purge ies	0455.perfor valve.clear urs 3.00 Meter:	43774	est.	Shop Supp 180.00		36.35 10/13/2016	Total: Closed:	216.35	1.00
- Perform pin est.replace de - Shop Suppl Workorder: Problem:	poit test for P efective purge ies Hou : 1610598 P.M. service	0455.perfor valve.clear urs 3.00 Meter:	43774	est.	Shop Supp 180.00	Parts: n Date:				1.00
- Perform pin test.replace de - Shop Suppl Workorder: Problem: - P.m. Service	poit test for P efective purge ies Hou : 1610598 P.M. service e.	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00	Parts: n <b>Date:</b>				1.00 016 Qty
<ul> <li>Perform pin test.replace de Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00	Parts: n Date: Oil Filter				1.00 016 <b>Qty</b> 1.00
<ul> <li>Perform pin test.replace de Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00 In Parts List Napagold 5w20 Engi	Parts: n Date: Oil Filter ine Oil				1.00 016 <b>Qty</b> 1.00 6.00
<ul> <li>Perform pin test.replace de Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00	Parts: n Date: Oil Filter ine Oil Blade	10/13/2016			1.00 016 1.00 6.00 2.00
<ul> <li>Perform pin test.replace de Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper	Parts: n Date: Oil Filter ine Oil Blade uid Conc	10/13/2016 entr			1.00 016 016 1.00 6.00 2.00 1.00
<ul> <li>Perform pin test.replace de - Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	est.	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl Used Fire	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb	10/13/2016 entr			1.00 016 1.00 6.00 2.00 1.00 1.00
<ul> <li>Perform pin est.replace de</li> <li>Shop Suppl</li> </ul> <b>Workorder:</b> <b>Problem:</b> <ul> <li>P.m. Service</li> <li>Repair one</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and ies	0455.perfor valve.clear urs 3.00 <b>Meter:</b> and wiper	43774 blades.	Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb plies	10/13/2016 entr	Closed:		1.0 016 <b>Qt</b> 1.0 6.0 2.0 1.0 1.0
<ul> <li>Perform pin test.replace de</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> <li>Shop Suppl</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and ies	0455.perfor valve.clear urs 3.00 Meter: and wiper balance all urs 4.00 Meter:	43774 blades. four. 46017	Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl Used Fire Shop Supp 240.00	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb plies Parts: n Date:	10/13/2016 entr ished	Closed:	10/26/20	1.0 016 <b>Qt</b> 1.0 6.0 2.0 1.0 1.0 1.0
<ul> <li>Perform pin test.replace de</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> </ul>	poit test for Prefective purgeries Hou: 1610598 P.M. service e. tire,rotate and ies Hou: 1612561 Clicking nois	0455.perfor valve.clear urs 3.00 Meter: and wiper balance all urs 4.00 Meter: e in dash a	43774 blades. four. 46017 nd fire extingu	Labor: Labor: Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer FI Used Fire Shop Supp 240.00	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb plies Parts: n Date: n.	10/13/2016 entr ished 42.98	Closed: Total:	282.98	1.00 016 Qt; 1.00 2.00 1.00 1.00 1.00 017
<ul> <li>Perform pin test.replace de</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>Diagnose cl</li> </ul>	poit test for P efective purge ies Hou : 1610598 P.M. service e. tire,rotate and ies Hou : 1612561	0455.perfor valve.clear urs 3.00 Meter: and wiper balance all urs 4.00 Meter: e in dash an nder dash.r	43774 blades. four. 46017 nd fire extingu	Labor: Labor: Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl Used Fire Shop Supp 240.00 In acket broken Parts List	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb plies Parts: n Date: n.	10/13/2016 entr ished 42.98 12/07/2016	Closed: Total:	282.98	1.00 016 Qty 1.00 2.00 1.00 1.00 1.00 017 Qty
<ul> <li>Perform pin test.replace de</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>Diagnose cl temperature b</li> </ul>	poit test for Prefective purgeries Hou: 1610598 P.M. service e. tire,rotate and ies Hou: 1612561 Clicking noise un	0455.perfor valve.clear urs 3.00 Meter: and wiper balance all urs 4.00 Meter: e in dash an nder dash.r	43774 blades. four. 46017 nd fire extingu eplace defecti	Labor: Labor: Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl Used Fire Shop Supp 240.00 In Acket broker Parts List A/c Mode	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb plies Parts: n Date: n.	10/13/2016 entr ished 42.98 12/07/2016 Motor	Closed: Total:	282.98	Qty 1.00 6.00 2.00 1.00 1.00 1.00 017 Qty 1.00
<ul> <li>Perform pin test.replace de</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>P.m. Service</li> <li>Repair one</li> <li>Shop Suppl</li> <li>Workorder: Problem:</li> <li>Diagnose cl temperature b</li> </ul>	poit test for Prefective purgeries Hou: 1610598 P.M. service e. tire,rotate and ies Hou: 1612561 Clicking noise un lend door actu- ken extinguisi	0455.perfor valve.clear urs 3.00 Meter: and wiper balance all urs 4.00 Meter: e in dash an nder dash.r	43774 blades. four. 46017 nd fire extingu eplace defecti	Labor: Labor: Labor:	Shop Supp 180.00 In Parts List Napagold 5w20 Engi 22" Wiper Washer Fl Used Fire Shop Supp 240.00 In acket broken Parts List	Parts: n Date: Oil Filter ine Oil Blade uid Conc X Refurb olies Parts: n Date: n. Actuator racket Fir	10/13/2016 entr ished 42.98 12/07/2016 Motor	Closed: Total:	282.98	1.00 016 Qty 1.00 2.00 1.00 1.00 1.00 017 Qty

# Palm Beach County Fleet Management Asset Maintenance History

Hours 2.50 :

Workorder: Problem:	1700168 3 - Wash		Meter: (s) issued	46350			In Date:	01/06/2017	Closed:	01/06/20	017
- 3 - Wash ticl	ket(s) issue	ed									
	ŀ	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1702651 P.M. serv		Meter:	49725			In Date:	03/15/2017	Closed:	03/29/20	017
- P.m. Service	Э.					Parts Li	ist				Qty
- R&r and stra			bumper	brackets,and	replace	5w20 Ei	ngine Oil				6.00
damage bump						Napago	ld Oil Filter				1.00
- Rotate and b		es.				22" Wip	er Blade				2.00
- Shop Suppli	es					Real Bu	Imper Cover	,			1.00
						Shop Su	upplies				1.00
	ŀ	Hours	4.50		Labor:	270.00	Parts:	164.50	Total:	434.50	
Workorder:	1705486		Meter:	52486			In Date:	06/01/2017	Closed:	06/02/20	017
Problem:	Left rear t	ire goi	ing flat.								
- Repair left re					lled on	Parts Li	ist				Qty
left rear of veh		es nitro	ogen fille	d.		Shop Su	upplies				1.00
- Shop Suppli											
	ŀ	Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1707304		Meter:	54817			In Date:	07/25/2017	Closed:	08/08/20	017
Problem:	P.M. serv	ice.									
- P.m. service						Parts Li	ist				Qty
- Replaced tw	o tires.higl	h spee	ed balanc	e all four .nitro	o filled.	Napago	ld Oil Filter				1.00
- Inspect real	r differentia	al.flush	and rep	laced gear oil		5w20 Er	ngine Oil				6.00
- Replaced fro	ont brake p	ads a	nd calipe	rs.machined r	rotors	22" Wip	er Blade				2.00
and burnished	bleed all b	orakes	· ·			Washer	Fluid Conce	entr			1.00
- Complete fo	ur wheel a	lignme	ent.			Used Fi	re X Refurbi	shed			1.00
- Shop Suppli	es					235 75r	17 Adventur	e			2.00
						Friction	Modifier				1.00
						75w140	Ford Axle L	ube			3.00
						Non-chl	or Brake Clr	۱r			1.00
						brake flu	uid				1.00
						Front Br	rake Pad				1.00
						caliper					1.00
						caliper					1.00
						Shop St	upplies				1.00
							posal Fee				2.00
	ł	Hours	11.00		Labor:	660.00	-	940.02	Total:	1,600.02	
	:										

Workorder: Problem:	1710608 Left rear tire g	Meter: oing flat.	57803			In Date:	10/26/2017	Closed:	10/31/20	017
- Repair left re	ear tire and bal	ance .nitro	gen fill tires.		Parts L	ist				Qty
- Shop Suppli	es				Shop S	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1711987	Meter:	59027			In Date:	12/06/2017	Closed:	12/07/20	017
Problem:	Left rear tail lig	ght lens br	oken.							
- R&r broken	left tail light ler	าร.			Parts L	ist				Qty
- Shop Suppli	es				Lamp A	ssembly				1.00
					Shop S	upplies				1.00
	Hour :	s 0.50		Labor:	30.00	Parts:	161.18	Total:	191.18	
Workorder: Problem:	1712058 3 - Wash ticke	Meter: et(s) issued	59027 d			In Date:	12/08/2017	Closed:	12/08/20	)17
- 3 - Wash tic	ket(s) issued									
	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1800732 P.M. service.	Meter:	60312			In Date:	01/22/2018	Closed:	01/31/20	018
- P.m. service	<b>)</b> .				Parts L	ist				Qty
	r brake pads a			ar rotors	5w20 E	ngine Oil				6.00
	sh brake syster	•			Napago	old Oil Filter				1.00
	high speed bala	ance all fo	ur tires.		Napago	old Air Filter				1.00
- Shop Suppli	es				22" Wip	er Blade				2.00
					Washer	Fluid Conce	entr			1.00
					Caliper	w/ Pads &ar	mp; Hdwr - R/	rr (eclipse)		1.00
					Caliper	w/ Pads &ar	mp; Hdwr - L/	rr (eclipse)		1.00
					Non-chl	lor Brake Clr	nr			1.00
					B Fluid	Dot 3-32oz				1.00
					Shop S	upplies				1.00
	Hour	s 6.50		Labor:	390.00	• •	223.13	Total:	613.13	
Workorder: Problem:	1805507 1 - Detail Veh	Meter: icle Wash	62596 Ticket(s) Issue	ed		In Date:	05/30/2018	Closed:	05/30/20	)18
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	led							
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1805544 2 - Wash ticke	Meter: et(s) issued	62596 d			In Date:	05/31/2018	Closed:	05/31/20	)18
- 2 - Wash tic	ket(s) issued									
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	:									

Workorder: Problem:	1806980 3 - Wash ticket	Meter: (s) issued	64232 I			In Date:	07/09/2018	Closed:	07/09/2018
- 3 - Wash ticl	ket(s) issued								
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1808048 P.M. service.	Meter:	65147			In Date:	08/06/2018	Closed:	08/16/2018
- P.m. service	·.				Parts L	ist			Qty
	ng and charging	systems	. Battery failed	d load	Napago	ld Oil Filter			1.00
test . R&r defe				- 11 (		ngine Oil			6.00
- Replace two tires . Nitroger	tires . Rotate a	nd high sp	beed balance	all four	22" Wip	er Blade			2.00
-	cked belts ,both	A/c and r	nain drive belt		Ford Tri	ton Pvc Swo	C		1.00
•	it end alignment				Battery				1.00
- Shop Suppli	e e					k P235 75r1	7 Dp At		2.00
					V Belt				1.00
					A/cv Be				1.00
					Shop Su				1.00
						posal Fee			2.00
	Hours	8.70		Labor:	522.00	Parts:	665.84	Total:	1,187.84
Workorder: Problem:	1809832 Dead battery, J	<b>Meter:</b> lump star	66271 t if wont jump,	tow in to	o shop.	In Date:	08/06/2018	Closed:	09/24/2018
- Tow From: 1	5857 60th St N	. Rpb To:	Lv shop						
	Hours :		·	Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1810120 2 - Wash ticket	Meter: (s) issued	66517			In Date:	09/28/2018	Closed:	09/28/2018
- 2 - Wash ticl	ket(s) issued								
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1811805 3 - Wash ticket	Meter: (s) issued	68675 I			In Date:	11/16/2018	Closed:	11/16/2018
- 3 - Wash tic	ket(s) issued								
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Palm Beach County Fleet Management
Asset Maintenance History

Workorder: Problem:	1900365 P.M. service .	Meter:	69825			In Date:	01/09/2019	Closed:	01/22/201	9
- P.m. service	۶.				Parts Lis	t				Qty
	st cooling syste	m . R&r fa	iled heater ho	ose.	Napagold					1.00
Flush coolant	and refill.				5w20 Eng		6	6.00		
	Remove drive s				22" Wiper	2	2.00			
	palance all four	tires. Nitro	ofill all.		Washer F	1	1.00			
- Shop Suppli	es				Used Fire			1.00		
					Anti Freez			2.00		
					Hose					1.00
					Repair Ki					1.00 1.00
	Hour	s 6.50		Labor:	Shop Sup 435.50	•	222.12	Total	657.62	1.00
	:	3 0.00		Labor.	400.00	1 8113.	222.12	rotai.	007.02	
Workorder: Problem:	1904127 5 - Wash ticke	Meter: et(s) issued	69825 I			In Date:	04/16/2019	Closed:	04/16/201	9
- 5 - Wash tic	ket(s) issued									
	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1909908 P.M. Service.I	<b>Meter:</b> Bent rim or	72408 n passenger s	side.		In Date:	09/25/2019	Closed:	10/10/201	9
- P.m. service	).				Parts Lis	t				Qty
	nt rear bent rim				Napagold	I Oil Filter			1	1.00
	e. Rotate and				5w20 Eng	gine Oil			7	7.00
	st and inspect o top off coolant		tem . R&r lea	king	22" Wiper	r Blade			2	2.00
- Shop Suppli						luid Conc				1.00
						X Refurb				1.00
						on Pvc Sw	-	0		1.00
							toring System	Sensor (		1.00
					Wheel As	sy ze Motorci	raft			1.00 1.00
					Coolant F		ian			1.00
					Shop Sup					1.00
	Hour :	s 6.00		Labor:	438.00		582.75	Total:	1,020.75	
Workorder: Problem:	1911510 2 - Wash ticke	Meter: et(s) issued	72763 I			In Date:	11/05/2019	Closed:	11/05/201	9
- 2 - Wash tic	ket(s) issued									
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1912125 remove gps &	Meter: extra deca	72854 als			In Date:	11/22/2019	Closed:	12/02/201	9
- remove Gps	& extra decals	5			Parts Lis	t				Qty
- Shop Suppli					Shop Sup	plies				1.00
	Hour :	s 1.50		Labor:	109.50	Parts:	4.00	Total:	113.50	

Workorder: Problem:	1912145 Transition Pre	Meter: ep Charge	72763			In Date:	11/22/2019	Closed:	11/22/2019
- Transition P	rep Charge								
	Hou :	ırs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00