



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V3933**

In Date: 08/15/2006  
Close Date: 08/18/2006

Meter Reading:

**Problem?**

TINT FRONT WINDOWS R-26 (60 MINUTE)

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: 60 MINUTE

**Workorder: V3890**

In Date: 08/11/2006  
Close Date: 08/28/2006

Meter Reading: 344.00

**Problem?**

B Inspection R26

Task performed:

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0041BRACKET TOOL	2
14-7014HGR-1 HELMET HOOK	3
5269LPVM-5 SM MOUNT	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
LPVM-7LG MOUNT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UMVS111611STRAP	2
UMVS162511STRAP	2

**Workorder: V4272**

In Date: 09/06/2006  
Close Date: 09/08/2006

Meter Reading:

**Problem?**

gas gauge goes back and forth R26

Task performed:

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4451**

In Date: 09/14/2006  
Close Date: 09/21/2006

Meter Reading: 122.00

**Problem?**

bracket on bottom of rescue truck bent. Bracket that holds air tank struck high area in driveway, bent the bracket. Truck in service but needs repair. R26

**Task performed:**

1. BRACKET FOUND TO BE BENT BUT STILL SERVICABLE. VEHICLE LEFT IN SERVICE NEW BRACKET ORDERED.

Parts

NO PARTS USED

Quantity

**Workorder: V4615**

In Date: 09/26/2006  
Close Date: 10/03/2006

Meter Reading: 2,119.00

**Problem?**

WONT START R 26

**Task performed:**

1. TRAVELED TO STN 26 FOR A CALL OF R-26 NOT STARTING. FOUND SWITCH ON DASH IN THE OFF POSITION. MAKE SIGN TO LEAVE SWITCH IN THE ON POSITION.

Parts

NO PARTS USED

Quantity

**Workorder: V4650**

In Date: 09/29/2006  
Close Date: 10/16/2006

Meter Reading: 186.00

**Problem?**

The airhorn is not functioning on Rescue 26

**Task performed:**

1. TRAVELED TO STN 26 ADJUSTED AIR HORN, TEST/ OK. AIR HORN NO WIN GOOD WORKING ORDER.

Parts

1681AIR HORN KIT GROVER

2

Quantity

**Workorder: V4703**

In Date: 10/02/2006  
Close Date: 10/16/2006

Meter Reading: 198.20

**Problem?**

Rear door intermediatley works to lower rear vehicle. R26

**Task performed:**

1. TRAVLED TO STN 26. CHECKED REAR DOOR WITH DRIVER FOUND NO PROBLEMS, TOLD DRIVER TO MONITOR.

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4782**

In Date: 10/06/2006  
Close Date: 10/16/2006

Meter Reading: 203.00

**Problem?**

At 45MPH the front end shakes while braking. Will not do it at other speeds. R26

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 26, TEST DRIVE, FOUND SMALL VIBRATION . WILL MONATOR.

NO PARTS USED

**Workorder: V4781**

In Date: 10/06/2006  
Close Date: 10/23/2006

Meter Reading: 203.00

**Problem?**

Battery light on dash comes on and reads 12 volts and voltage on the computer screen reads 13 volts R26

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 26. DASH BATT READING OFF BY 1 VOLT. TOLD DRIVER TO USE U-MAX METER.

NO PARTS USED

**Workorder: V4808**

In Date: 10/09/2006  
Close Date: 10/23/2006

Meter Reading: 13.30

**Problem?**

Plug where the Onshore electric plugs in does not diconnect when truck is started

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 26 CHECKED TRUCK, SHORE LINE WILL NOT DISCONNECT WHEN TRUCK IS STARTED. AMERICAN LAFRANCE WILL BE BACK ON 10-10-2006.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5649**

In Date: 12/02/2006  
Close Date: 12/05/2006

Meter Reading: 6,959.00

**Problem?**

check transmission. transmission is slipping. E-26

**Task performed:**

1. DRIVE TO STA 26 CHECK TRANS PROBLEM FOUND LOW VOLTAGE TO ECM CHECK, LOCATE AND REPAIR LOOSE GROUND FOR TRANS ECM AT FRAME CONNECTION.
2. REAR DOOR WILL NOT DUMP SUSPENSION REPLACE BAD SWITCH ASS.
3. POWER WINDOWS 10-7 CHANGE FUSE TO 20 AMP PER SERVICE BULLETIN #54-213

Parts	Quantity
MFG-01894ALUMN BACKING PLATE	2
SS598STARTER SOLENOID FORD TYPE	1
SWT1277EL57755 SWITCH DOOR 2PCS	2

**Workorder: V6139**

In Date: 01/08/2007  
Close Date: 01/09/2007

Meter Reading: 9,162.00

**Problem?**

on call check eng lt on r26

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V6397**

In Date: 01/22/2007  
Close Date: 01/26/2007

Meter Reading: 9,937.00

**Problem?**

ON CALL R26 STUCK

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V6851**

In Date: 02/20/2007  
Close Date: 03/06/2007

Meter Reading: 11,656.00

**Problem?**

replace tires at callaghan r26

**Task performed:**

1. Replace tires at Callaghan Ent R26

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN ENT



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6785**

In Date: 02/15/2007  
Close Date: 03/07/2007

Meter Reading: 11,656.00

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

1. B Inspection
2. Replaced all tires
3. Rear air dump inop. Found metal shavings at proximity switch. Removed shavings and test ok
4. Repaired A/C condenser line leak
5. R/S fuel tank cover screws stripped and missing. Replaced as needed and tightened cover
6. Several rear compartment door out of adjustment and loose. Secured and adjusted doors

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0714021GASKET 2 1/2"	1
2FC00ZCR4 IN ROUND LED	1
31-24WIPER BLADES	2
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

**Workorder: V7181**

In Date: 03/12/2007  
Close Date: 03/19/2007

Meter Reading: 13,141.00

**Problem?**

brake lights flickering when brake is applied / air dump not dumping when supposed to.

**Task performed:**

1. Drive to station. Checked plug in connection on brake switch. ok
2. Drive to station. Replaced air valve for door and switch at door. Test ok

Parts	Quantity
NRG-27-SNC-010RA12-19779-0 VALVE ASSY	1

**Workorder: V7279**

In Date: 03/19/2007  
Close Date: 03/22/2007

Meter Reading: 775.00

**Problem?**

Door alarm will not stop. R26

**Task performed:**

Repaired by Medic Master

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7229**

In Date: 03/16/2007  
Close Date: 03/26/2007

Meter Reading: 756.00

**Problem?**

Air dump rear, is OOC. R26

**Task performed:**

Repaired by Medic Master

Parts

Quantity

NO PARTS USED

**Workorder: V7267**

In Date: 03/19/2007  
Close Date: 03/26/2007

Meter Reading: 756.00

**Problem?**

Rear dump is not working properly. R26

**Task performed:**

Repaired by Medic Master

Parts

Quantity

NO PARTS USED

**Workorder: V7851**

In Date: 04/23/2007  
Close Date: 04/24/2007

Meter Reading: 16,055.00

**Problem?**

air tank on bottom of r26 damaged from a hump in the driveway of a call they were on. R26

**Task performed:**

Repaired broken air hose on air tank.

Parts

Quantity

NO PARTS USED

**Workorder: V8093**

In Date: 05/04/2007  
Close Date: 05/08/2007

Meter Reading: 956.80

**Problem?**

Back up alarm and light is OOC. R-26

**Task performed:**

Found plug bad; rewired & loose wires on backup alarm;  
test ok

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V8264**

In Date: 05/15/2007  
Close Date: 06/11/2007

Meter Reading: 1,003.10

**Problem?**

engine clutch fan seems to stay engaged too long while driving. water temp. in normal range. r26

**Task performed:**

Parts

Quantity

1. drive to sta, check air valve going to fan, temp went to 180 fan on dosnt go below 180 or higher than 180. System working like it is suposed to

NO PARTS USED

**Workorder: V8619**

In Date: 06/05/2007  
Close Date: 06/21/2007

Meter Reading:

**Problem?**

FRONT GRILLE ON RESCUE 26 FALLING OFF, BOLTS MISSING AND GRILLE IS SAGGING r26

**Task performed:**

Parts

Quantity

1. Install missing bolts right side of grill

NO PARTS USED

**Workorder: V8837**

In Date: 06/13/2007  
Close Date: 06/26/2007

Meter Reading: 195,383.00

**Problem?**

repair stretcher R26 (outside agency-emsar medco equipment repair)

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO

**Workorder: V8860**

In Date: 06/15/2007  
Close Date: 06/29/2007

Meter Reading: 7,132.60

**Problem?**

R26 is low on oil

**Task performed:**

Parts

Quantity

1. Drive to sta. Drop off oil. Truck not at sta  
2. Vacation

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V8972**

In Date: 06/22/2007  
Close Date: 07/02/2007

Meter Reading: 20,232.00

**Problem?**

110 a/c innop R26

**Task performed:**

1. Drive to Stn; chk 110 wiring; fnd brkr bad; go to shop get new; installed-test ok
2. Drive to Stn installed battry chgr light-test ok

Parts

Quantity

032-0116549297 BATTERY INDICATOR

1

**Workorder: V8958**

In Date: 06/22/2007  
Close Date: 07/03/2007

Meter Reading: 20,232.00

**Problem?**

R26 stuck in sand

**Task performed:**

Rescue beached in sand; could not attempt w/winch on truck; called Sister's Towing

Parts

Quantity

NO PARTS USED

**Workorder: V8959**

In Date: 06/22/2007  
Close Date: 07/03/2007

Meter Reading: 20,232.00

**Problem?**

winch out unit sisters towing r26

**Task performed:**

Winch out - Sisters Towing

Parts

Quantity

NO PARTS USED

Vendor?: SISTERS TOW

**Workorder: V9069**

In Date: 06/29/2007  
Close Date: 07/05/2007

Meter Reading: 1,163.20

**Problem?**

driverside undercarrage led light(round) fell out. part located in station 26. see officer. R26

**Task performed:**

1. DRIVE TO STATION. REINSTALLED LED LIGHT. BENT BRACKET TO FIT LIGHT. TEST-OK.

Parts

Quantity

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9375**

In Date: 07/17/2007      Meter Reading: 1,244.00  
Close Date: 07/19/2007

**Problem?**

Rescue 26 is very low on oil.

**Task performed:**

Parts

Quantity

1. DRIVE TO STA. GIVE OIL TO STA. FILL TRUCK UP WITH OIL. LOOK FOR LEAKS- ALL OK.

NO PARTS USED

**Workorder: V9405**

In Date: 07/18/2007      Meter Reading: 21,870.00  
Close Date: 07/19/2007

**Problem?**

air leak-cannot build over 50 psi R26

**Task performed:**

Parts

Quantity

1. TRAVEL TO STA 26. FOUND BAD PURGE VALVE. R&R PURGE VALVE- OK.

800404USE K022105 PURGE KIT AD-IP-IS

1

**Workorder: V9569**

In Date: 07/27/2007      Meter Reading: 1,272.00  
Close Date: 08/07/2007

**Problem?**

air horn ooc R26

**Task performed:**

Parts

Quantity

1. Replc belts  
2. Front shock oil leak L/S; replc front shocks  
3. Air leaks; rep air leaks; replc air solenoid  
4. Rear pat compt A/C condensor fan inop; fnd conn @ relay burnt; rep condensor fan wiring; cleand condensor

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9565**

**In Date:** 07/26/2007

**Meter Reading:** 22,195.00

**Close Date:** 08/10/2007

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R26**

**Task performed:**

1. B-Inspection
1. Rear brakes worn; replc rear brake shoes
2. rear tires worn; replc rear tires
3. Svc trans
4. Svc air dryer purge valve
5. Shop meeting
6. cleanup shop & hazmat cabaint
7. Front A/C not working well; replc discharge hose; installed new fittings dryer & evap proble
8. washers clogged; clnd nozzles & replc blades
9. Rear compt door panels & latches loose; adj all doors/latches
10. Dlvr to Stn26
11. Air horns inop; air leak at solenoid; rep leak & adj horn

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
4407S08-6462BS 45 DEG FITTING 8 SB1312	1
4909SCUT AND FAB FITTING	1
5003547USE K022105 PURGE VALVE REB KIT M2	1
5008414CARTRIDGE DC100	1
87123USE 9185 RELAY CONNECTOR 99025	2
01-29866-118BELT ALT. M2	1
29526898 29548988 TRANS FILTER ALLISON	1
65140FRONT SHOCK NEW M2	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
921LIGHT BULB	10
9550 BELT	1
ABPN83319744USE 7197 DRYER M2	1
EL36010RELAY SCENE LIGHT EL37000	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	1
S-706PIGTAIL SOCKET	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1

**Workorder: V9630**

**In Date:** 07/30/2007

**Meter Reading:** 22,195.00

**Close Date:** 09/07/2007

**Problem?**

**replace tires at callaghan ent r26**

**Task performed:**

Replace tires - Callaghan

**Parts**

**Quantity**

NO PARTS USED

**Vendor?:** CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4821**

In Date: 10/07/2006  
Close Date: 10/15/2007

Meter Reading: 3,782.00

**Problem?**

Will not start on-call R26

**Task performed:**

WILL NOT START, DOOR ALARM GOING OFF,

Parts

Quantity

ESX120105112STARTER RELAY ESX-120-105112

1

**Workorder: V11285**

In Date: 10/28/2007  
Close Date: 11/07/2007

Meter Reading: 25,909.00

**Problem?**

BACK UP CAMERA AND PT. COMPARTMENT CAMERA IS NOT FUNCTIONAL R-26

**Task performed:**

DRIVE TO STN; CHK UNDER CONSOLE FOR LOOSE CONNECTION & REAR OF PATIENT COMPT; TALK WITH ...ABOUT GETTING CODES FROM VMUX

Parts

Quantity

NO PARTS USED

**Workorder: V11564**

In Date: 11/12/2007  
Close Date: 11/16/2007

Meter Reading: 1,607.20

**Problem?**

R26 is low on oil and coolant.

**Task performed:**

drive to stn; coolant leak @ upper hose; tighten pressure; chk -ok j

Parts

Quantity

NO PARTS USED

**Workorder: V11595**

In Date: 11/14/2007  
Close Date: 11/16/2007

Meter Reading: 1,607.20

**Problem?**

No brake lights when applying the brakes. r26

**Task performed:**

DRIVE TO STN; W/TRUCK; REPLC AIR VALVE UNDER TRUCK; TEST OK J

Parts

Quantity

NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V11718**

In Date: 11/21/2007      Meter Reading: 1,607.20  
Close Date: 11/30/2007

**Problem?**

O2 bypass knob is stripped off. R26

**Task performed:**

drive to Stn; Replc knob; test ok      j

Parts

Quantity

TH0104BYPASS VALVE 02 OXYGEN

1

**Workorder: V11907**

In Date: 12/04/2007      Meter Reading: 29,736.00  
Close Date: 12/10/2007

**Problem?**

The pressure guage for the m tank leaks O2. Do not need to swap out the entire regulator. Just need a new pressure guage. The guage leaks through the front of the plastic. There's a small hole in the plastic.e26

**Task performed:**

1. replaced leaking O2 gauge in L1 compartment
2. traveled to station

Parts

Quantity

MG-C23SPMGC23 GAUGE

1

**Workorder: V11945**

In Date: 12/06/2007      Meter Reading: 29,736.00  
Close Date: 12/18/2007

**Problem?**

yellow light box on r26 , switch is broken .

**Task performed:**

1. Travel to 26.
2. Repair switch on light box.

Parts

Quantity

NO PARTS USED

**Workorder: V12602**

In Date: 01/15/2008      Meter Reading: 1,891.60  
Close Date: 01/31/2008

**Problem?**

drivers side windows inoperative front and rear. r26

**Task performed:**

1. Replc bad fuse
2. Travel to Stn26      j

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V12687**

**In Date:** 01/18/2008

**Meter Reading:** 33,064.00

**Close Date:** 01/31/2008

**Problem?**

b inspection and repairs as needed r26

**Task performed:**

B-Inspection Walther & Vasko

1. B-Inspection - Walther

2. Replace all tires

3. R/R under truck Lt bracket; rep/reinstall

4. Trans cooler leak; rep leak at cooler

5. Trans cooler bolts msgng; replc msgng fasteners

6. Heater control valve leak pat compt; readj-test; tighten fasteners.

7. B-Svc & A/C filters

8. Pat compt door striker MIA; replc striker; adj for proper function j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

15W40BSYN OIL BULK QTS

24

42809AIR FILTER M2

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

ACX-84534LUG NUT COVER PK10

3

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

STP594115449 STRIKER PIN

1

VCC/36000006A/C FILTER CAB M2

1

**Workorder: V12804**

**In Date:** 01/24/2008

**Meter Reading:** 1,936.00

**Close Date:** 02/04/2008

**Problem?**

Top A/C unit making a loud vibration noise. M. Lehan inspected and recommended replacement of unit. r26

**Task performed:**

Chk A/C; noise getting louder longer; it sures need to come to shop to replace unit. j

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V12766**

**In Date:** 01/23/2008

**Meter Reading:** 33,848.00

**Close Date:** 02/06/2008

**Problem?**

replace tires at callaghan r26

**Task performed:**

Replace tires - Callaghan j

**Parts**

**Quantity**

NO PARTS USED

**Vendor?:** CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4049**

In Date: 08/21/2006

Meter Reading:

Close Date: 02/07/2008

**Problem?**

Headset broke while adjusting.R26

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V13165**

In Date: 02/11/2008

Meter Reading: 35,542.00

Close Date: 02/12/2008

**Problem?**

NO LIGHTS IN REAR OF TRUCK, R-26

**Task performed:**

Parts

Quantity

1. Drive to station, R & R fuse, test OK

NO PARTS USED

**Workorder: V13317**

In Date: 02/18/2008

Meter Reading: 25,073.00

Close Date: 02/20/2008

**Problem?**

front emergency lights not working properly on R26

**Task performed:**

Parts

Quantity

1. Drive to station, found bad ground on front emergency lights, rewire, test OK

NO PARTS USED

**Workorder: V13686**

In Date: 03/05/2008

Meter Reading: 37,201.00

Close Date: 03/07/2008

**Problem?**

emergency lights on front hood notworking R26

**Task performed:**

Parts

Quantity

1. Drive to station, found bad ground wire for emergency lighting and replaced fuse for windows.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V13890**

In Date: 03/13/2008

Meter Reading:

Close Date: 03/18/2008

**Problem?**

BOTTOM NADER PIN ON REAR DOOR OF RESCUE, ON THE DRIVERS SIDE HITS THE DOOR WHEN YOU SHUT IT AND DOES NOT ALWAYS CLOSE. R26

**Task performed:**

Parts

Quantity

1. Drive to station, tighten nadar pin and adjusted, test OK

NO PARTS USED

**Workorder: V16084**

In Date: 07/01/2008

Meter Reading: 45,107.00

Close Date: 07/03/2008

**Problem?**

wipers come on witout turning on

**Task performed:**

Parts

Quantity

1. wipers coming on without turning on switch. remove conector put dielectric grease on connections and road test. Did not correct problem repalce switch and recheck npf

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V15842**

**In Date:** 06/19/2008

**Meter Reading:** 45,107.00

**Close Date:** 07/09/2008

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

1. C-Inspection
2. Rear brakes worn; replc rear brakes.
3. Replc batteries-due; svc battry box slide tray.
4. Air leak w/brakes release; fnd leak @ electric/air solenoid bank; replc gasket & solenoid.
5. O2 sys leaks; gauge fective; replc gauge @ regulator.
6. Svc P/S
7. Svc coolant-weak
8. Pat
9. Condensor fan inop rear; motor bad & burn connector @ relay; replcd fan motor & rep wiring.
10. Wont build air pressure sometimes; dryer hanging up; replc purge valve & air gov.
11. Exh leak; pipe loose @ muffler; reinstated exh properly & rep trim cover.
12. Grill placard falling off; 2-sided tape not holding; rem tape & installed properly.

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
032-0116549297 BATTERY INDICATOR	1
15W40BSYN OIL BULK QTS	24
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
60027FAN A/C COND 12IN 860026-2-W	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
090-0278STRECHER BAR NEW	1
22-54273-000CLIP RETAINER VENT	4
284358GOVERNOR D-2	1
87499RY48 RELAY	1
3744BRAKE DRUM REAR	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
78R536078R5360M 2PK FILTER AIR COND	1
MG-C23SPMGC23 GAUGE	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
DOOR5LEXAN 9 X 38 1/2 IN	1
LTC1020606LATCH	1
HNG5451HINGE - CHROME	1
NRG-7030-80MODULE SEAL	2





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V15978**

In Date: 06/25/2008  
Close Date: 07/23/2008

Meter Reading: 45,107.00

**Problem?**

replace tires at shop callaghan r 26

**Task performed:**

Replace tires at shop R26 - Callaghan

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

**Workorder: V16402**

In Date: 07/17/2008  
Close Date: 07/28/2008

Meter Reading: 2,649.00

**Problem?**

Requesting S.C.B.A. bracket mounted in the driver copartment for driver airpack r26

**Task performed:**

Drive to Stn; installed air pack holder; test ok. j

Parts

101-124-000CRASH RESTRAINT STRAPS  
KD-UN-6-SFBRACKET

Quantity

2  
2

**Workorder: V17291**

In Date: 08/25/2008  
Close Date: 08/29/2008

Meter Reading: 48,834.20

**Problem?**

ON CALL WINCH OUT R26

**Task performed:**

Pull out truck from \_\_\_\_\_.

Parts

NO PARTS USED

Quantity

**Workorder: V18232**

In Date: 10/08/2008  
Close Date: 10/20/2008

Meter Reading: 2,975.50

**Problem?**

Center console screen blanks out. R26

**Task performed:**

Drive to Stn; chk connection; rework wiring; test ok.  
j

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18233**

In Date: 10/08/2008  
Close Date: 10/21/2008

Meter Reading: 2,975.50

**Problem?**

The bolt cutter is missing a nut from the srew. R26

**Task performed:**

Drive to Stn; replaced bolt & nut; test ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V18279**

In Date: 10/11/2008  
Close Date: 10/21/2008

Meter Reading: 2,990.70

**Problem?**

R26 is low on oil. Could we please get a case of oil for the station.

**Task performed:**

See W/O 18303 j

Parts

15W40QSYN OIL QT

Quantity

12

**Workorder: V18293**

In Date: 10/12/2008  
Close Date: 10/29/2008

Meter Reading: 2,997.70

**Problem?**

Need engine oil. Levels are low. R26

**Task performed:**

Drive to Stn; put (2) qt in eng; drop off oil. j

Parts

NO PARTS USED

Quantity

**Workorder: V18618**

In Date: 10/27/2008  
Close Date: 11/05/2008

Meter Reading: 3,063.00

**Problem?**

The lock on the back pt's door, jams. It hard to close due to mechanism gets in the way. R26

**Task performed:**

drive to Stn; lube & repair door latch; test ok. j

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18619**

In Date: 10/27/2008  
Close Date: 11/05/2008

Meter Reading: 3,063.00

**Problem?**

The vehicle pulls to the right R26

**Task performed:**

Test drive unit; chk linkage & steering; talk with Ed Ehrke about alignment. j

Parts

NO PARTS USED

Quantity

**Workorder: V19221**

In Date: 11/20/2008  
Close Date: 11/26/2008

Meter Reading: 3,143.70

**Problem?**

Engine coolant level is LOW on Rescue 26.

**Task performed:**

Drive to Stn; fill; pressure check; tighten hose clamp; test ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V18705**

In Date: 10/29/2008  
Close Date: 12/09/2008

Meter Reading: 53,060.30

**Problem?**

front end alignment r26 at callaghan

**Task performed:**

Front end alignment R26 at Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

**Workorder: V19252**

In Date: 11/21/2008  
Close Date: 12/09/2008

Meter Reading: 54,382.20

**Problem?**

REPLACE FRONT TIRES AT CALLAGHAN R26

**Task performed:**

Replace front tires R26 at Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

## ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

### Workorder: V19730

In Date: 12/14/2008

Meter Reading: 3,242.60

Close Date: 01/02/2009

#### Problem?

Lights on the driver side outside, at the top are out. The one at the driver side top rear outside of the pt box. R-26

#### Task performed:

Drive to Stn; (5) lights out; started replacing lights; got call out; wait till come back; finished job. j

#### Parts

CLR9185209186-1500-20 MARKER LT.AMBER LED

#### Quantity

4

### Workorder: V20006

In Date: 12/29/2008

Meter Reading: 57,289.80

Close Date: 01/08/2009

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED R26

#### Task performed:

1. B-Inspection
2. Rerouted trans cooler line; was rubbing frame.
3. Under step light loose; sec brkt.
4. Repositioned air pack release cables; they were on the wrng side of the seats.
5. Replcd belts.
6. Replcd water pump.
7. Replcd grip tape on steps. j

#### Parts

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0000902051FILTER FUEL 03 MERCEDES

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

1045-257-101SEAT CONTROL CABLE RIGHT 51 IN

1

15W40BSYN OIL BULK QTS

24

42809AIR FILTER M2

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

DDE/A0279976048O-RINGS M2 WATER PUMP

2

DDE/N00000001072SEAL RING M2 WATER PUMP

2

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

N007603014104WASHER SEAL

2

01-29866-118BELT ALT. M2

1

DDE-R90620043019062006301 WATER PUMP SOME M2 CI

1

9062030015PIPE SOCKET TO WP

1

DDE-0052035975A0052032675 THERMOSTAT ELEMENT M

2

DDE-9062030180GASKET SOCKET TO HEAD M2

1

9550 BELT

1

CORECORE CHARGE

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

#### Workorder: V20218

In Date: 01/08/2009

Meter Reading: 3,309.00

Close Date: 02/04/2009

#### Problem?

coolant leak on r26

#### Task performed:

1. Fnd/rep coolant leak; topped off coolant.
2. Eng belt torn; replcd belt. j

#### Parts

01-29866-118BELT ALT. M2

#### Quantity

1

#### Workorder: V21060

In Date: 02/12/2009

Meter Reading: 59,069.00

Close Date: 02/23/2009

#### Problem?

WINDSHIELD WASHER INOP, R-26

#### Task performed:

Drive to stn; rep washer & rear of inside box; molding falling off.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V21121

In Date: 02/15/2009

Meter Reading: 3,428.00

Close Date: 02/24/2009

#### Problem?

Low radiator fluid needs to be filled. R26

#### Task performed:

Drive to Stn; Fill reservoir; pressure test; tighten clamps; test ok. j

#### Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

#### Quantity

1

#### Workorder: V21496

In Date: 03/03/2009

Meter Reading: 61,221.70

Close Date: 03/03/2009

#### Problem?

inspect truck- hit curb R26

#### Task performed:

Chkd out frnt end of truck; also chkd underside & road test; fnd no problems; recommended frt end alignment. j

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V21492**

In Date: 03/03/2009

Meter Reading: 61,221.70

Close Date: 03/09/2009

**Problem?**

on call unit hit median while driving r26

**Task performed:**

Drive to Stn; chk vibration; fnd no damage to under carriage; alignment suspected to be out. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V21602**

In Date: 03/06/2009

Meter Reading: 61,221.70

Close Date: 03/11/2009

**Problem?**

coolant leak R26

**Task performed:**

1. Ck for coolant leak; fnd T-stat hsnng & pipe flange gskt leaking; drained hot coolant; rem hoses, brkts, clamps & pipes; R/R gskt & o-rings; filled rad; press test; ck ok; clnd eng.
2. Cln bay; floor bench, btry cores, etc. j

**Parts**

DDE/0209971148A0249972848 SEAL RING  
 N917003022003GASKET/SEAL M2 WATER PUMP

2  
1

**Quantity**

**Workorder: V21569**

In Date: 03/05/2009

Meter Reading: 61,221.70

Close Date: 03/12/2009

**Problem?**

CHECK OIL LEAK R26

**Task performed:**

drive to Stn; coolant on floor; pressure chk leak on block top of eng; need to come to shop. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V22317**

In Date: 04/04/2009

Meter Reading: 3,641.40

Close Date: 04/16/2009

**Problem?**

rear a/c in patient compartment no cooling while driving one interior light out in pt. compartment over bench seat. R26

**Task performed:**

Drive to Stn; fnd leak; rep o-ring, vac & fill; test ok. j

**Parts**

NO PARTS USED

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22693**

In Date: 04/20/2009  
Close Date: 04/28/2009

Meter Reading: 3,703.10

**Problem?**

Mechanic was in and stated that the Vista screen function buttons and cover need to be replaced. The buttons stick in the down position freezing the functions. R26

**Task performed:**

Drive to Stn; installed new button in vista & cover; test ok. j

Parts

Quantity

NO PARTS USED

**Workorder: V22710**

In Date: 04/21/2009  
Close Date: 04/28/2009

Meter Reading: 3,703.10

**Problem?**

need engine oil sta26

**Task performed:**

Bring stn oil; put (2) qts in rescue. j

Parts

Quantity

15W40QSYN OIL QT

12

**Workorder: V23331**

In Date: 05/18/2009  
Close Date: 05/20/2009

Meter Reading: 66,309.00

**Problem?**

ON CALL R26 ROOF A/C COVER LOOSE

**Task performed:**

Secured alum diamond plate cover arnd roof A/C msgng screws. j

Parts

Quantity

NO PARTS USED

**Workorder: V23477**

In Date: 05/22/2009  
Close Date: 06/12/2009

Meter Reading: 3,807.00

**Problem?**

ac in patient compartment not cooling R-26

**Task performed:**

T-shoot 110 roof A/C. j

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22859**

**In Date:** 04/28/2009

**Meter Reading:** 65,035.00

**Close Date:** 06/16/2009

**Problem?**

C inspection R-26

**Task performed:**

- B-Inspection & go to Stn26 to get truck; wait for wapout; drive to shop.
- 2. R/R unit; rebuild purge & cln out.
- 3. Replcd btry charge unit lights; btry charger is working; tested ok.
- 4. REeplcd bolts in rear door latches; adj linkage.
- 5. R/R ultra violet light starter; unit bad; replc unit; retest; replcd grnd strap on unit.
- 6. Rep P/S; return line leak; refill sys.
- 7. Adj A/C belt.
- 8. Brakes frn/rear, drums.
- 9. Fuel up fork lift truck; go fill diesel... j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
032-0116549297 BATTERY INDICATOR	1
15-22150-06OIL PLUG ADAPTER MBE900	1
15W40BSYN OIL BULK QTS	25
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
42809AIR FILTER M2	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A7125MPT ADAPTOR	1
ACX-84534LUG NUT COVER PK10	16
FREIGHTSHIPPING CHARGES	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1
1500900017000USE 9 X 14 FILTER	1
5003547USE K022105 PURGE VALVE REB KIT M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
516TIRE INFLATOR	1

**Workorder: V23881**

**In Date:** 06/07/2009

**Meter Reading:** 3,882.60

**Close Date:** 06/18/2009

**Problem?**

rescue 26 needs a new sharps container wall mount. and sharps container as well

**Task performed:**

- Drive to Stn; mnt unit; test ok. j

Parts	Quantity
NO PARTS USED	





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24085**

In Date: 06/15/2009      Meter Reading: 3,900.30  
Close Date: 06/24/2009

**Problem?**

top clearance light passenager side out R16

**Task performed:**

1. Go to Stn16 & chk light out on cab/box.
  2. Go to Stn16 & replcd R/F corner box marker lamp.
- j

Parts	Quantity
CLR9185209186-1500-20 MARKER LT.AMBER LED	1

**Workorder: V24074**

In Date: 06/15/2009      Meter Reading: 3,900.30  
Close Date: 07/02/2009

**Problem?**

driverside windsheild washer not working R26

**Task performed:**

Hose clogged; cln; test ok.      j

Parts	Quantity
NO PARTS USED	

**Workorder: V24396**

In Date: 06/27/2009      Meter Reading: 3,913.00  
Close Date: 07/08/2009

**Problem?**

Pulls to the right slightly while driving R26

**Task performed:**

drive to Stn; chk frnt end tire; fill to 110 each; test drove; ok.      j

Parts	Quantity
NO PARTS USED	

**Workorder: V24458**

In Date: 06/30/2009      Meter Reading: 3,913.00  
Close Date: 07/08/2009

**Problem?**

front ac works intermittly r26

**Task performed:**

drive to Stn; replc evap fan; test ok.      j

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/36000006A/C FILTER CAB M2	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24470**

In Date: 06/30/2009  
Close Date: 07/10/2009

Meter Reading: 68,405.00

**Problem?**

replace rear tires at sta 26 callaghan

**Task performed:**

Replace rear tire at Stn26 - Callaghan j

**Parts**

NO PARTS USED

**Quantity**

Vendor?: CALLAGHAN

**Workorder: V24755**

In Date: 07/14/2009  
Close Date: 07/15/2009

Meter Reading: 69,856.00

**Problem?**

ON CALL PATIENT A/ C 10-7 R26

**Task performed:**

Fnd pat compt compressor locked up; swapped out unit at shop. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V24770**

In Date: 07/14/2009  
Close Date: 07/27/2009

Meter Reading: 69,856.00

**Problem?**

repair a/c r 26/ a inspection and any repairs

**Task performed:**

1. Fnd belt burtn off & compressor locked up; recover freon; leak test sys; (2) hose fittings leaking; rem allhose holddowns, tie-wraps etc.; R/R comp, dryer & fittings; flushed sys; leak test; vac sys; rem pulleys & cleared charged A/C; ck opn; ck ok.
2. A-Inspection
3. Btry box slides not working; cln/lubed slides; ck opn; ck ok.
4. Frnt grill loose; rep mnts & replcd msng bolts. j

**Parts**

- 071601A07-0602A DRIER A/C 7118 1
- 203FFBEARING PULLEY 1
- 4411S08-6962BS 90 DEGREE SB1322 1
- 4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT 1
- 5790COMPRESSOR A/C 1
- 680-10LAMERICAN FLAG W UV CLEAR LEFT 1
- 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1
- 91-22WIPER BLADE 2
- 9550 BELT 1

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25792**

In Date: 08/26/2009

Meter Reading: 4,134.00

Close Date: 09/03/2009

**Problem?**

shore power not operating back R26

**Task performed:**

Parts

Quantity

Drive to Stn; chk shoreline & brkr in truck; fnd loose wire on plug-in on truck; rework; test ok. j

NO PARTS USED

**Workorder: V26161**

In Date: 09/10/2009

Meter Reading: 72,372.30

Close Date: 09/16/2009

**Problem?**

PAITIENT A/C 10-7 R26

**Task performed:**

Parts

Quantity

drive to Stn; replcd fan & filter; test ok. j

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/36000006A/C FILTER CAB M2

1

**Workorder: V26187**

In Date: 09/10/2009

Meter Reading: 4,134.00

Close Date: 09/30/2009

**Problem?**

r26 got scratched on drivers side above side compartment

**Task performed:**

Parts

Quantity

drive to Stn; chk damage on unit; report back to Ed. Ehrke. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

## ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V26275**

**In Date:** 09/15/2009

**Meter Reading:** 72,372.30

**Close Date:** 10/13/2009

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

- Road test & B-Inspection
- 2. Grnd lite electrical wire hanging; secure wire.
- 3. Fuel cap needs painting; paint fuel cap.
- 4. Operator complaint turn signal activates windshield wiper blade; dia fault; unable to duple fault; sys operating as normal.
- 5. Replc cab rear A/C filter; chk dashboard filter; filter lcean, no need to replc.
- 6. Markeer lite out; rem bulb lown & install new LED marker lite.
- 7. Replc worn windshield wiper blade; add bug solvent to washer fluid & top off reservoir.
- 8. L-2 door hold open & tool holders loose; secure all screws, nuts & belts.
- 9. Tigten all loose locks & lube asy.
- 10. Secure side entrance door panel & replc msng screws.
- 11. Dia & rep cab A/C failure.
- 12. Complete A/C rep; dryers saturated, vac sys after replc & charge; sys working normal.
- 13. Rear door glass seal coming out; rem, cln channel for strip & reinstall.
- 14. Fuel pump & line; chk valve svc repair.
- 15. Assisted Mac w/repairs(Reines).
- 16. Diss components & rem fuel pump schedule replacement; reassemble, torque all nuts, bolts & fittings to mfr's specs.
- 17. L/frnt tire cut; rem both tires & install new tires.
- 18. Road test unit after fuel pump & line replacement.

j

**Parts**

**Quantity**

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	4
719707-0614AAC DRIER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
8201L17-3428 ESTER OIL E7	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
9060910580FUEL PUMP GASKET M2	1
9060920510FUEL CHECK VALVE	1
91-22WIPER BLADE	2
A17-14297-000HOOD LIFT CLY A17-14297-002 M2	1
A9060901276A9060903376 FUEL LINE	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DDE-0076030102007603016102 WASHER OIL SENDER	1
DDE-R0040910501FUEL PUMP M2	1
RD-5-7063-OP07-2618AA/C DRIER 7155	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	3

**Workorder: V27064**

**In Date:** 10/21/2009

**Meter Reading:** 4,304.00

**Close Date:** 11/02/2009

**Problem?**

cab A/C INOP R26

**Task performed:**

- drive to Stn; low on freon; fnd fitting loose; tighten; fill; test ok. j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V27065**

In Date: 10/21/2009  
Close Date: 11/02/2009

Meter Reading: 4,304.00

**Problem?**

roof spot light broke R26

**Task performed:**

drive to Stn; replc swt in cntrl console; test ok.

j

Parts

2020-DDASH MOUNT REMOTE CONTROL

Quantity

1

**Workorder: V26891**

In Date: 10/14/2009  
Close Date: 11/16/2009

Meter Reading: 74,546.40

**Problem?**

replace 2 tires R26 loose wheels at vista (outside agency-callaghan tire)

**Task performed:**

Replace (2) tires R26, loose wheels - Callaghan

j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

**Workorder: V27513**

In Date: 11/09/2009  
Close Date: 11/17/2009

Meter Reading: 76,285.80

**Problem?**

ON CALL HEADLIGHT 10-7 R26

**Task performed:**

Take call for Jeff on headlight; out on R26. j

j

Parts

9006XSLLEHEADLAMP M2 HI

Quantity

1

**Workorder: V27885**

In Date: 11/23/2009  
Close Date: 11/23/2009

Meter Reading: 4,444.00

**Problem?**

cab is blowing air but it is not cold R26

**Task performed:**

See wo 27837

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V27837**

In Date: 11/20/2009

Meter Reading: 4,347.80

Close Date: 11/30/2009

**Problem?**

front passenger air conditioning not blowing cold air possibly needs freon. R26

**Task performed:**

Parts

Quantity

Ck cab A/C; fnd sys low; topped off freon level; ck opn;  
ck ok. j

NO PARTS USED

**Workorder: V28319**

In Date: 12/14/2009

Meter Reading: 79,060.80

Close Date: 01/15/2010

**Problem?**

REPAIR FLAT TIRE

**Task performed:**

Parts

Quantity

Repair flat tire - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V28478**

In Date: 12/18/2009

Meter Reading: 4,528.30

Close Date: 02/01/2010

**Problem?**

backup alarm sounds after truck is put into neutral. R26

**Task performed:**

Parts

Quantity

Chkd backup alarm; cld not duplicate customer concern.  
j

NO PARTS USED

**Workorder: V28744**

In Date: 01/02/2010

Meter Reading: 4,566.90

Close Date: 02/01/2010

**Problem?**

ST. 26 rescue right head light and AC is not cold. Brakes have air leak. Truck will be down for PM on monday. R26

**Task performed:**

Parts

Quantity

1. Replcd hi/lo beam bulbs for right headlight.  
2. CC/O air brake leak; traced leak to faulty quick disconnect air line fittings at foot valve; replcd fittings & rechkd.  
3. C/O A/C not cold; fnd freon charge low; recovered sys; vac, recharge & leak chkd. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V29238**

In Date: 01/19/2010  
Close Date: 02/01/2010

Meter Reading: 81,332.80

**Problem?**

on call r26 a/c 10-7

**Task performed:**

Rep A/C don fan wires, node; filled A/C. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V28704**

In Date: 12/30/2009  
Close Date: 02/17/2010

Meter Reading: 80,603.80

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

- C-Service
- 2. Replcd all (4) btrys.
- 3. Replcd eng air filter.
- 4. Svc diff; also seal leak in diff at secondary plug for temp sender.
- 5. Svc air dryer.
- 6. Press tested cooling sys & fnd coolant leak at heater control valve under body for pat compt; tighten hose clamp at valve & retested sys.
- 7. Adj rear suspension air bag inkage away frm diff hsnng; (rubbing torque arm).
- 8. Replcd wiper blades.
- 9. Pat fuel tank cap.
- 10. replcd cab frt A/C filter.
- 11. Replcd rear cab A/C filter.
- 12. Replcd pat compt air filter.
- 13. replcd pat compt side entry door; inner door latch bezel w/new style bezel (cracked).
- 14. Replcd clamps on air pack brkt in L-2 compt.
- 15. Grnd opening of door latch on pat compt rear door at Nader pin cvr. also grnd down Nader pin cvr; also grnd down Nader pin cvr-scraping/binding.
- 16. Replcd belts.
- 17. C/O right frt hub cab leaking oil; fnd hub was over filled; rem approx 3 oz of oil; cldn hub & reinstalled wheel cover.
- 18. Replcd squad bench shocks.
- 19. replcd pat compt cabinet open shocks.
- 20. Replcd R-3 pat compt dome light bulb.
- 21. Replcd ground light & gromet under right frt cab step.
- 22. Replcd serpentine belt tension. j

**Parts**

- 000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1
- 0000902051FILTER FUEL 03 MERCEDES 1
- 0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1
- 01-29866-118BELT ALT. M2 1
- 15W40BSYN OIL BULK QTS 24
- 2FC00ZCR4 IN ROUND LED 1
- 4070091740 GROMMET T/L 4 IN 1
- 42809AIR FILTER M2 1
- 5008414CARTRIDGE DC100 1
- 9005SX9005XS HIGH BEAM BULB 1
- 9006XSSLHEADLAMP M2 HI 1
- 9550 BELT 1
- DDE/A9062003170BELT TENSIONOR MERCEDES 1
- HAN-1LBEZEL AND HANDLE 1
- HLD3999GSS1715UV 30LB STRUT GAS 2
- HP-31DBATTERY 950CCA HP-31D 4
- 1501450007750USE 0775145 1
- 78R536078R5360M 2PK FILTER AIR COND 1
- 91-22WIPER BLADE 2
- BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY 4
- 322502BULB PATIENT GH22 1
- GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB 2
- 906-181-00-86OIL FILTER M2 SPINNER 57140 1
- K022105PURGE VALVE AD-IP-IS 1
- S3226FL02FUEL FILTER 33813 L/F # LFF5851 1
- VCC/36000006A/C FILTER CAB M2 1

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V29084**

In Date: 01/13/2010 Meter Reading: 80,603.80

Close Date: 02/25/2010

**Problem?**

replace all 4 rear tires R26 (outside agency-callaghan tire)

**Task performed:**

Replace all (4) tires R26 - Callaghan j

**Parts**

NO PARTS USED

**Quantity**

Vendor?: CALLAGHAN

**Workorder: V29841**

In Date: 02/09/2010 Meter Reading: 82,697.40

Close Date: 03/09/2010

**Problem?**

park brake hanging up r26

**Task performed:**

1. Went to Stn26; fnd park valve asy leaking; rem dash panels; R/R park valve; ran/ck ok.  
2. Fnd rear brakes not releasing; T-shoot both brake chambers; rem both rear brake chambers; swapped fittings; wrng chambers; reinstated old chambers; ordered parts; informed driver/captain of problm.  
3. Went to Stn26; replc both rear brake chambers; rem lines, fittings & chambers; replc chambers; ran/ck opn; ck ok; fnd brake valve leaking \_\_\_\_; rem piggy-back valves; R/R valve; replc air lines; ck for leaks; ck ok. j

**Parts**

801315PARKING VALVE NEWER M2 5009249	1
FREIGHTSHIPPING CHARGES	154
GC2430XLLONG STROKE BRAKE CHAMBER	2
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	1
R810021CLEVIS KIT	2

**Quantity**

**Workorder: V30510**

In Date: 03/06/2010 Meter Reading: 84,784.30

Close Date: 03/25/2010

**Problem?**

a/c not properly working on rescue 26. no cold air. R26

**Task performed:**

Went to Stn26; fnd cab A/C level low; added reon; ran/ck opn; ck ok. has leak; needs to be checked at PM.  
j

**Parts**

NO PARTS USED

**Quantity**





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V30871**

In Date: 03/19/2010  
Close Date: 04/02/2010

Meter Reading: 84,784.30

**Problem?**

door ajar alarm active although all doors closed. R26

**Task performed:**

travel to Stn26; chk all compt door switches; cln btry tray switch; NPF at this time j

Parts

NO PARTS USED

Quantity

**Workorder: V29155**

In Date: 01/14/2010  
Close Date: 04/08/2010

Meter Reading: 4,566.90

**Problem?**

broken door holders broken during back acc. with dents in area of holders r26

**Task performed:**

1. C/O damage of rear door; door holders brkn off on bottom & door dented leaving 1/2" gap around window fram at bottom.
2. Fnd rear door damaged; needs to be rep at PM; poss needs to go to body shop.
3. Chk for air leaks; fnd "piggy-back" valve leaking at rear\_\_\_; did not have valve on truck; ret the following day; rem clamps/valves; R/R end valve; ck for leaks; ck ok. j

Parts

NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS

1

Quantity

**Workorder: V30997**

In Date: 03/24/2010  
Close Date: 04/20/2010

Meter Reading: 84,784.30

**Problem?**

nader pin cover on the back of rescue 26 broke off and needs replaced

**Task performed:**

Went to Stn26; rem old cvr; drilled/mntd new pin cvr. j

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V31115**

In Date: 03/29/2010

Meter Reading: 84,784.30

Close Date: 04/20/2010

**Problem?**

check for freon leak R26 (have added freon several times)

**Task performed:**

Went to Stn26; fnd pat A/C not cooling; topped off freon level; did not see any leaks; fnd condenser fan relay hot; R/R relay & terms; took amp draw on fans 10amp; ck opn; ck ok. j

**Parts**

87401RY-30T RELAY 5 PIN 12V

**Quantity**

1

**Workorder: V31109**

In Date: 03/29/2010

Meter Reading: 84,784.30

Close Date: 04/21/2010

**Problem?**

patient a/c not very cold R26 (on-call)

**Task performed:**

Went to Stn26 from Stn14; chk veh; add freon. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V31460**

In Date: 04/12/2010

Meter Reading: 84,784.30

Close Date: 04/30/2010

**Problem?**

EGR cooler leaking internally R26

**Task performed:**

2. Fill coolant bottle to proper level; pressurize sys; chk for leaks; no external leaks fnd; poss EGR cooler or head gskt.  
2. Assist larson w/check out - Murray. j

**Parts**

NO PARTS USED

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V31574**

**In Date:** 04/15/2010

**Meter Reading:** 87,535.00

**Close Date:** 04/30/2010

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R26**

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

## ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

### B-Inspection

2. Adj all tire press; rep two of the tire extensions to take air.
3. Replc bad rad cap.
4. Polish out headlight & front LED lite cvrs (very dull).
5. Replc wiper blades & adj washer nozzles.
6. Btry slide draw; cln/blow out sand, stones, mud & other road debris frm roller tracks; lube/work draw until easy to pull/push.
7. Replc bulb in R/frnt fender turn indicator.
8. Cln out heavy road debris frm rear A/C pat area condensor (packed w/mud/shell rock).
9. Pulls slightly to right; set up on jack stands & switch tires frm side to side.
10. Replc (5) fixtures for under truck grnd lites; makeup pigtail wiring for all (5) before installed (3) mntng brkts brkn; rep/set steady on pattern frm flashing pattern on all (5) after installed.
11. Cab A/C sys keeps loosing freon & needs to be recharged every week; this has been an on-going problem; first chk over both frnt/rear sys; fnd several problems; charge out A/C compressor leaking out shaft; replc leaking hose inside condensor box; replc both cab frnt/rear dryers; vac down sys & recharge; also cln out mud/road debris frm condensor.
12. Compressor belt on rear pat area A/C sys is too long & wearing off back side of belt on fan pulley; isntall 1/2" shorted belt & also install new bearing in adjustment pulley.
13. install (8) msng wheel nut cvrs.
14. C/O rear pat area A/C sys; blows only cool; fnd only a small seepage frm lo-side Shraeder valve; replc Shraeder after freon recovery; evac & recharge.
15. Ft/R pat area ovrhd lite inop; rem fixture lens & replc burnt out bulb.
16. Rem L/rear cab step & take to weld sop; align brkn mntng brkts; grind down old welds & reweld; reinstall step asy.
17. Diss rear pat area doors; sev window frame screws were frozen & stripped out thrd inserts making screw removal very difficult in window frame;
  - After diss make up a pull jig to use w/a com-a-long & pull & straighten both doors; now drill out & install all new window frame inserts in both doors.
  - In weld shop make up new cross bars for each door; install crossbars & bore a 2-1/2" hole in center of bars to except lite fixtures;
  - removal of bottom door latches was also very difficult because screws that hold the latches were rusted & frozen; had to cut latches to pieces W/O doing damage to doors.
  - install new latches & when setting pull rods, noticed that these latches were not to safety code & only had a single lock instead of a double lock;

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	2
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
05-17223-002RAD CAP 20 LB	1
15W40BSYN OIL BULK QTS	24
194-ABULB	2
2FC00ZCR4 IN ROUND LED	5
776477-774475USE 63152	1
8433D-876USE 776477-774475 CARRIER ROOF UNIT	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	8
DRC401202840048 DOOR GRABBER	1
LTC594111656-16 LATCH R/H MEDIC MASTER	2
LTC594211657-16 LATCH L/H MEDIC MASTER	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
9545BELT M2 ENGINE	1
203FFBEARING PULLEY	1
357182HOSE ASSY	1
DRC4011DRC4011 D-GRABBER DOOR HO	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
8201L17-3428 ESTER OIL E7	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

- rem latches & bring back to parts dept to get proper latches; NOTE: parts had to order proper latches & will install when received; replc door edge weather stripping; adj strikers, etc.

18. Install new style 120V roof A/C unit; install heat sys & mod inside ovrhd grab rail to work w/new A/C sys; test out A/C & heat sys; both ok.

19. Performed quality control check. j

## Workorder: V33115

In Date: 06/24/2010      Meter Reading: 91,733.90  
Close Date: 06/29/2010

### Problem?

CHECK AND REMOVE HEAT STRIP FROM 110 A/C IF INSTALLED (COULD CAUSE FIRE IN UNIT) RETURN HEAT STRIP TO PARTS ROOM R26

### Task performed:

Went to 26; rem inside panel & heating element; reassembled. j

Parts	Quantity
NO PARTS USED	

## Workorder: V31465

In Date: 04/12/2010      Meter Reading: 87,535.00  
Close Date: 07/16/2010

### Problem?

Repair engine(outside agency-florida detroit diesel) R26

### Task performed:

Order control unit - So Fla Emergency Veh j

Repair eng R26 - Fla Detroit j

Vendor?: FLA DETROIT

Parts	Quantity
NO PARTS USED	

## Workorder: V33322

In Date: 07/04/2010      Meter Reading: 91,733.90  
Close Date: 08/02/2010

### Problem?

front a/c fan no working (dash) and rear a/c leaking inside from condensation.R26

### Task performed:

Went to 26; fnd cab blower inop; rem panels; R/R blower, harness & cab A/C filter; ran/ck ok. ja

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000038AC WIRE HARNESS	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33378**

In Date: 07/07/2010      Meter Reading: 92,589.00  
Close Date: 08/02/2010

**Problem?**

front dash ac unit quit working again. r26

**Task performed:**

went to 26; rem panels; traced/rep connection; ok ok.  
j

Parts

NO PARTS USED

Quantity

**Workorder: V33561**

In Date: 07/15/2010      Meter Reading: 92,589.00  
Close Date: 08/11/2010

**Problem?**

R26 damage to light, needs replaced r26

**Task performed:**

1. Went to 26; fnd rear corner clear lens brkn; light works; ordered.
2. Went to 26; rep LED light mnt; replc lense; ck ok.  
ja

Parts

68-3983813-30LENS 4500 BAR CLEAR

1

Quantity

**Workorder: V33463**

In Date: 07/12/2010      Meter Reading: 92,589.00  
Close Date: 08/12/2010

**Problem?**

The running light underneath the drivers side door broke off while driving down a bumpy dirt road and was dragging on the ground.it ha ssince been wedged in a space under the cab and moved out of the way till repair. r26

**Task performed:**

Rep done on W.O. 33530      ja

Parts

NO PARTS USED

Quantity

**Workorder: V33530**

In Date: 07/13/2010      Meter Reading: 92,589.00  
Close Date: 08/12/2010

**Problem?**

ground light driver side broke off. r26

**Task performed:**

Fnd light & brkt damaged; rep mnt; reinstalled; rep wires/light; ck ok.      ja

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34178**

In Date: 08/11/2010  
Close Date: 08/31/2010

Meter Reading: 94,418.50

**Problem?**

patient a/c leaking water r26

**Task performed:**

Went to 26; fnd shoreline A/C not draining; fnd unit grnd loose; resecured to roof & sealed; diss cvr & evap box; clnd drain/debris; ck ok. ja

Parts

NO PARTS USED

Quantity

**Workorder: V34575**

In Date: 08/27/2010  
Close Date: 09/15/2010

Meter Reading: 95,670.80

**Problem?**

a/c blower in front cab not working properly. Blows very little air or no air at all.R26

**Task performed:**

Went to 26; rem panels; fnd A/C filter bad; R/R filter; ran/ck ok. j

Parts

VCC/36000006A/C FILTER CAB M2

Quantity

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34264**

**In Date:** 08/13/2010

**Meter Reading:** 95,683.00

**Close Date:** 09/16/2010

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

- 1. C-Inspection
- 2. Cln btrys/cables; load test.
- 3. Chk all computer codes; fnd (3) cts grid heater; clear inactive codes.
- 4. Rem air clnr & clnd filter/hsng.
- 5. Tighten L-2 hook.
- 6. Secure L-3 hinge brkt bolts.
- 7. Jeff tighten all door skin screws.
- 8. Lube latches,.
- 9. Lock in turtle tile in compts.
- 10. File R-3 latch & adj strker.
- 11. Fill washer bottle & add concentrate frm parts room.
- 12. Rear A/C cool; chkd gauge press & added 8 oz. freon.
- 13. Rear brakes.
- 14. Adj brakes.
- 15. Replc tire valve stem nut.
- 16. Jackup veh for tire guy.
- 17. Parts waiting for brakes.
- 18. Trans svc.
- 19. Replc wiper blades.
- 20. Rem old non-skid strip frm pat compt side door step & install new; trim loose strips where needed.
- 21. Drill out holes in O2 top brkt & install bolts w/wing nuts for securing O2 bottle.
- 22. Coolant svc.
- 23. press chk cooling sys; fnd upper rad hose clmp leak & poss wtr pump; tightened hose clmp; wash veh eng & rech; ok.
- 24. Chk toe angle - ok.
- 25. Replcd rear A/C filter; install protective grill; De Burr grill.
- 26. Worked on freeing up rear tailboard compt & lock cyl; lube/adj latch; cln out mud frm compt & isntall drain plug.
- 27. Replcd LR side clearance lights; splice wire.
- 28. Replc magnetic door alarm switch on compt under rear entry door-shortcd.
- 29. Sec wires under truck at rear crossmember-loose/hanging.
- 30. Adj/tighten pat compt shelf - loose. j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
3744BRAKE DRUM REAR	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
CLR9185109186-1500-10 MARKER LT. RED LED	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SWT54912SWITCH DOOR LGHT	1
PR338324070 WIX FILTER WATER	1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34791**

In Date: 09/07/2010

Meter Reading: 95,670.80

Close Date: 09/23/2010

**Problem?**

rear ac leaking water again. R26

**Task performed:**

Parts

Quantity

Fnd roof mnt loose; reposition unit; tightened unit; ck ok.

NO PARTS USED

j

**Workorder: V34790**

In Date: 09/07/2010

Meter Reading: 95,670.80

Close Date: 09/27/2010

**Problem?**

some component lost its nuts and is hanging loose r26

**Task performed:**

Parts

Quantity

Went to 26; fnd node loose; remntd diode; ck ok.

NO PARTS USED

j

**Workorder: V34498**

In Date: 08/25/2010

Meter Reading: 95,670.80

Close Date: 09/28/2010

**Problem?**

replace all tires boulevard r26

**Task performed:**

Parts

Quantity

Replc all tires R26 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD TIRE

**Workorder: V35992**

In Date: 10/28/2010

Meter Reading: 100,122.40

Close Date: 11/17/2010

**Problem?**

R26 shoreline fails to deploy after truck is cranked. Truck stalls when parking is released.

**Task performed:**

Parts

Quantity

Shoreline fails to eject - loose mnt inside; tightened

NO PARTS USED

mntng. j



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V36026**

In Date: 10/29/2010  
Close Date: 11/18/2010

Meter Reading: 100,122.40

**Problem?**

CLEARANCE LIGHTS TOP LEFT SIDE R26

**Task performed:**

1. Travel to stn; L/S markers inop; replc (2) LEDS.
2. Inside drawer inop; slider screws stripped; rep slider.  
j

Parts	Quantity
CLR9185109186-1500-10 MARKER LT. RED LED	3
CLR9185209186-1500-20 MARKER LT.AMBER LED	3

**Workorder: V36096**

In Date: 11/01/2010  
Close Date: 11/18/2010

Meter Reading: 100,122.40

**Problem?**

Pt cab a/c unit blowing war air. R26

**Task performed:**

1. Pat compt A/C inop; low refrigerant; rep hi-side Schrader leak & added 1.5 lbs. R134A.
2. Pat A/C shuts down intermittently; t-stat sticking; t-shoot A/C & ordered new t-stat. j

Parts	Quantity
R1061-30SWITCH THERMOSTATIC CONTROL	1

**Workorder: V34941**

In Date: 09/14/2010  
Close Date: 12/22/2010

Meter Reading: 96,608.60

**Problem?**

rear left nader pin cover broken on exit doors. r26

**Task performed:**

- (1) TRAVELED TO ST 26 TO REPAIR NADER PIN COVER ON R26 EXIT DOOR. DRILLED AND REPLACED PIN COVER. OK. J.W.

Parts	Quantity
NO PARTS USED	

**Workorder: V35986**

In Date: 10/28/2010  
Close Date: 12/22/2010

Meter Reading: 100,122.40

**Problem?**

left front hub appears to have oil leakage R26

**Task performed:**

- Travel to stn; L/F hub oil leak - hub cap asy - replc. j

Parts	Quantity
4537BULB 100W SPOT	1
CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	2



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37087**

In Date: 12/11/2010  
Close Date: 12/22/2010

Meter Reading: 102,516.80

**Problem?**

R26 stretcher catch broken. small spring loaded pin malfunctioned. R26

**Task performed:**

(1) TRAVELED TO ST26 TO REPAIR PROBLEM WITH STRETCHER HOLDING MOUNT IN R26. CHECKED OUT AND AND REPLACED STRETCHER LOCK BAR. OK. J.W.

Parts	Quantity
090-0278STRECHER BAR NEW	1

**Workorder: V36870**

In Date: 12/03/2010  
Close Date: 01/05/2011

Meter Reading: 101,801.70

**Problem?**

Left rear mud flap hanging due to missing bolts. R26

**Task performed:**

1. Drive to Stn26; chk heater valves.
2. C/O R/side grd lights per lux; fnd wires pulled out of plug; repair.
3. L/R mud flap msng; replc. j

Parts	Quantity
15W40QSYN OIL QT	1
B2420LP-SMUD FLAP 24 X 24	1

**Workorder: V36963**

In Date: 12/07/2010  
Close Date: 01/05/2011

Meter Reading: 102,298.80

**Problem?**

headlight drivers side out . r26

**Task performed:**

Headlight inop; replc headlight bulb. j

Parts	Quantity
9006XSLLEHEADLAMP M2 HI	1

**Workorder: V36969**

In Date: 12/07/2010  
Close Date: 01/05/2011

Meter Reading: 102,298.80

**Problem?**

groundlights out r26

**Task performed:**

See WO 36881 j

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V36914**

In Date: 12/06/2010  
Close Date: 01/06/2011

Meter Reading: 102,298.80

**Problem?**

on call winch out unit r 26

**Task performed:**

Travel to scene; R26 winched out by Westway Towing;  
travel home. j

Parts

NO PARTS USED

Quantity

**Workorder: V36622**

In Date: 11/23/2010  
Close Date: 01/11/2011

Meter Reading: 101,625.00

**Problem?**

flat tire R26

**Task performed:**

Flat tire R26 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

**Workorder: V37371**

In Date: 12/22/2010  
Close Date: 01/18/2011

Meter Reading: 103,470.00

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R26

**Task performed:**

- (1) "B" INSPECTION AND NEEDED REPAIRS.
- (2) REPLACED AIR TANK SUPPORT BRACKET.
- (3) CLEANED CONDENSER AND RADIATOR VENTS.
- (4) REMOVED RIGHT FENDER AND FUEL TANK VALANCE TO GAIN ACCESS TO EXHAUST LEAK. DISASSEMBLED EXHAUST, ORDERED PARTS. INSTALLED NEW EXHAUST PIPE.
- (5) R&R WIPER BLADES.
- (6) SECURED AXE BRACKET ON L-2 COMPARTMENT
- (7) LUBED ALL DOORS AND LATCHES.
- (8) REPLACED CLAMP ON UPPER HOSE TO STOP LEAK.
- (9) ADJUSTED AIR PRESSURE IN TIRES.
- (10) INSTALLED NEW EXHAUST PIPE AND REINSTALLED FENDER. ROAD TESTED OK.
- (11) REPLACED COOLANT RESERVOIR THAT IS LEAKING. TOP OF FLUID.

J.W.

Parts

- 000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1
- 0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1
- 01-29866-118BELT ALT. M2 1
- 04-22430-000EXHAUST PIPE 1
- 05-23195-000Z05-30740-000 SURGE TANK 1
- 136578-07825AIR RESTRICION SENSOR 1
- 20A-400CLAMP 4" 33969 2
- 91-22WIPER BLADE 2
- 9545BELT M2 ENGINE 1
- A04-19184-000620-997-05-90 TURBO CLAMP M2 1
- S3226FL02FUEL FILTER 33813 L/F # LFF5851 1
- 12-14352-000AIR TANK BRACKET M2 2
- 15W40BSYN OIL BULK QTS 24
- 42809AIR FILTER M2 1
- 906-181-00-86OIL FILTER M2 SPINNER 57140 1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37930**

In Date: 01/20/2011      Meter Reading: 102,516.80  
Close Date: 01/27/2011

**Problem?**

repair stretcher R26 (outside agency-medco)

**Task performed:**

Rep stretcher R26 - Medco      j

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO

**Workorder: V38170**

In Date: 01/31/2011      Meter Reading: 104,413.00  
Close Date: 02/03/2011

**Problem?**

Left rear inside tire flat on R26. (on-call))

**Task performed:**

Flat tire L/R outer. Called stn - called Boulevard Tire  
j

Parts

Quantity

NO PARTS USED

**Workorder: V38145**

In Date: 01/29/2011      Meter Reading: 104,413.00  
Close Date: 02/04/2011

**Problem?**

REPLACE VALVE STEM EXTENSION

**Task performed:**

Travel to stn; Replc valve stem ext brkn; replc.      j

Parts

Quantity

404-100 VALVE CORE      8

440-5 VALVE EXT.      2

AMH-1AMH-1 VALVE EXTENSION      1

**Workorder: V38143**

In Date: 01/29/2011      Meter Reading: 104,413.00  
Close Date: 02/08/2011

**Problem?**

Left rear inside tire flat on R26. (outside agency-Boulevard tire)

**Task performed:**

Left rear inside tire flat R26 - Boulevard      j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V38188**

In Date: 02/01/2011

Meter Reading: 104,413.00

Close Date: 02/23/2011

**Problem?**

drivers side head light wire loose causing light to not always work R26

**Task performed:**

Parts

Quantity

Drive to stn; left headlight inop sometimes; connector  
brutn; rep connector; needs to order new one. j

NO PARTS USED

**Workorder: V38600**

In Date: 02/17/2011

Meter Reading: 105,673.30

Close Date: 02/24/2011

**Problem?**

intermittent battery compartment alarm under driver side sounding in truck when compartment is closed. (problem fixed on  
02/17/2011). R26

**Task performed:**

Parts

Quantity

Travel to stn; Btry box open warning on; sensor dirty;  
cld sensor \_\_\_\_.

NO PARTS USED

**Workorder: V38601**

In Date: 02/17/2011

Meter Reading: 105,673.30

Close Date: 02/24/2011

**Problem?**

wipers engage temporarily when turning. problem looked at but not corrected on 02/17/2011 R26

**Task performed:**

Parts

Quantity

Travel to stn; wipers work intermittently; poss resistor  
connection for body cntrl module; cld connections @  
ECM & add dielectric grease. j

NO PARTS USED

**Workorder: V39192**

In Date: 03/14/2011

Meter Reading: 106,905.30

Close Date: 03/22/2011

**Problem?**

Blower inop R26

**Task performed:**

Parts

Quantity

Travel to 26; w/for rescue to return; replcd A/C filter,  
blower motor & wire harness. j

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/36000006A/C FILTER CAB M2

1

VCC/83000038AC WIRE HARNESS

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V39573**

In Date: 03/31/2011

Meter Reading: 107,573.60

Close Date: 04/05/2011

**Problem?**

Patainet a/c inop R26

**Task performed:**

Parts

Quantity

Trvel to 26; charged A/C sys; noticed belt frayed; repl fan belt also. j

01-29866-118BELT ALT. M2

1

**Workorder: V39815**

In Date: 04/10/2011

Meter Reading: 108,041.00

Close Date: 04/14/2011

**Problem?**

brocken door lock key for the back of r26. key in capt office drawer.

**Task performed:**

Parts

Quantity

Travel to stn; issued key for cabinet #TM202. j

NO PARTS USED

**Workorder: V39929**

In Date: 04/14/2011

Meter Reading: 108,793.50

Close Date: 04/20/2011

**Problem?**

replace rear tires r 26

**Task performed:**

Parts

Quantity

Replace rear tires R26 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD

**Workorder: V40623**

In Date: 05/15/2011

Meter Reading: 110,787.50

Close Date: 05/18/2011

**Problem?**

SHORELINE A/C OOS FOR R26

**Task performed:**

Parts

Quantity

Travel to 26; 110 V A/C 10-7. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V41108**

**In Date:** 06/04/2011

**Meter Reading:** 111,450.70

**Close Date:** 06/07/2011

**Problem?**

rear a/c unit is leaking onto stretcher. R26

**Task performed:**

1. Travel to 26; CIn drain for A/C.

2. Installed new headlights. j

**Parts**

**Quantity**

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40646**

**In Date:** 05/16/2011

**Meter Reading:** 111,124.00

**Close Date:** 06/14/2011

**Problem?**

**C INSPECTION AND REPAIRS AS NEEDED R 26**

**Task performed:**

1. C-Svc
2. Replcd eng air filter.
3. Replc wiper blades; cln debris frm windshield washer squirters & topped off reservoir.
4. R/R instrument cluster to replc air brake gauge module - leaking air.
5. Replcd frnt cab A/C filter.
6. Replc rear cab A/C filter.
7. Replc pat compt air filter.
8. Paint fuel cap.
9. Cln'd numerous connection in btry distribution box; also rep main btry cable end at junction stud.
10. R/R trans cooler mntng brkt to straighten - bent.
11. Replc both rear mud flaps - ripped.
12. Replc both rear air bags - leaking.
13. Svc air dryer.
14. Replcd grd light/brkt under driver's door step; rep wiring on grd light under pass frt door; straighten numerous grd light brkts under cab/pat compt.
15. Secured valnce panel oveer right side cab step - falling off.
16. Replcd non-skid on driver's side steps.
17. replc right side siren spkr.
18. Replcd badly blown right rear wheel seal; cln'd all related parts: drum, hub asy, spindle, etc.
19. Replcd rear brake shoes.
20. Replc frt tires frm stock in bldg 3.
21. Svc P/S sys.
22. Drilled/remntd holddown brkts in L-2 compt - stripped; also replc numerous msng screws for holddown brkts.
23. Rem inner door panel on right rear pat compt entry door to access door latch asy; cln'd,lubed/adj latch/linkage - binding.
24. C/O wipers going on/off on their own; diss steering column & treated plug w/dialectric grease for t-signal switch as per Mikey.
25. Replc eng oil filter cap - leaking.
26. Replc door latch on pass frt door - brkn.
27. Replc lo-side line fitting at compressor for pat compt - leaking; vac sys/recharged; sys is now working properly.
28. Lube/adj all cab/body latches, hinges & holdopens.
29. Replc right hi-beam bulb & rewired light socket.
30. Delivered truck to stn 26. j

Parts	Quantity
0/2-311-610-372SDUEL AIR GAUGE M2	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
14-15612-000GASKET RVR PWR STRG M2	1
15W40BSYN OIL BULK QTS	25
366555GTL6 13 X 19 FILTER	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
52-24682-2313 TERMINAL BLOCK 8 POST	1
78R536078R5360M 2PK FILTER AIR COND	1
8201L17-3428 ESTER OIL E7	1
9005SX9005XS HIGH BEAM BULB	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
K022105PURGE VALVE AD-IP-IS	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
DDE-0000100285OIL CAP M2	1
16-15762-00016-19471-000 AIR BAG	2
380003ASEAL	1
B2420LP-SMUD FLAP 24 X 24	2
401581GASKET AXLE FL80 R002435	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
MFG01876GROUND LT BRACKET	1
A06-51039-000USE A06-75732-004 HEAD LIGHT ASSY	1
A06-51039-001A06-75732-005 RH HEAD LIGHT ASSY	1
A18-42549-003DOOR LATCH RIGHT	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V41673**

In Date: 06/29/2011      Meter Reading: 112,578.50  
Close Date: 06/30/2011

**Problem?**

On board oxygen leaking. Sta 26.

**Task performed:**

Travel to 26; chkd for O2 leak; cld not find.      j

Parts

Quantity

NO PARTS USED

**Workorder: V41850**

In Date: 07/07/2011      Meter Reading: 113,189.90  
Close Date: 07/12/2011

**Problem?**

Water pouring in from a/c. Sta 26.

**Task performed:**

Rem A/C unit; resealed arnd unit & arnd unit cvr; cldnd drain vents.      j

Parts

Quantity

NO PARTS USED

**Workorder: V43575**

In Date: 09/11/2011      Meter Reading: 116,916.30  
Close Date: 09/14/2011

**Problem?**

ejector system for shore power not working. R26

**Task performed:**

travel to 26 r&r auto eject

Parts

Quantity

NO PARTS USED

**Workorder: V44088**

In Date: 10/03/2011      Meter Reading: 118,004.30  
Close Date: 10/03/2011

**Problem?**

no rear a/c.

**Task performed:**

cleaned out both condensers and charged rear unit ok

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V44278**

In Date: 10/11/2011

Meter Reading: 118,384.00

Close Date: 10/12/2011

**Problem?**

Rear a/c leak blowing warm.

**Task performed:**

**Parts**

**Quantity**

TRAVEL TO ST 16 FOUND A/C LOW ON FREON, CHARGED FREON VEHICLE CALLED OUT, TRAVEL HOME, THIS VEHICLE HAS LEAK AND NEEDS ONE CONDENSER FAN, TRAVEL HOME

NO PARTS USED

**Workorder: V44271**

In Date: 10/11/2011

Meter Reading: 118,384.00

Close Date: 10/13/2011

**Problem?**

Replace condensor fans.

**Task performed:**

**Parts**

**Quantity**

Travel to 26; replcd condensor fans & charged A/C.  
j

60027FAN A/C COND 12IN 860026-2-W

2

**Workorder: V44414**

In Date: 10/15/2011

Meter Reading:

Close Date: 10/19/2011

**Problem?**

shore line power is not working when plugged into rescue 26

**Task performed:**

**Parts**

**Quantity**

checked 110v a/c working fine

NO PARTS USED

**Workorder: V45029**

In Date: 11/07/2011

Meter Reading:

Close Date: 11/09/2011

**Problem?**

Batterys low vehicle hard to start and when running remains in high idle, Sta 26.

**Task performed:**

**Parts**

**Quantity**

C/O hard starting; fnd lot of loose wires on frame & power studs; replc shoreline indicator on side of truck; shoreline charger not charging; bad fuse in charger & GFI tripped; reset ok.  
j

032-0116549297 BATTERY INDICATOR

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V44463**

**In Date:** 10/18/2011

**Meter Reading:** 119,339.00

**Close Date:** 11/15/2011

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R 26**

**Task performed:**

- B-Inspection
- 2. Install pat compt L1, L2, L3 shocks.
- 3. Dia A/C leak.
- 4. Rem step & replc frnt A/C condensor fan motors & rep A/C hose to condensor.
- 5. Rem old grip tape & install new tape rear pat door.
- 6. Install pat A/C evap, dryer & expansion valve & dryer to evap hose & A/C filter.
- 7. Fab brkt for parking valve holddown.
- 8. Rem rear window seal; cln/install.
- 9. Adj rear door striker.
- 10. Tighten all compt door screws.
- 11. Install wiperblades.
- 12. Tighten center console lid; drill/tap (2) screw holes.

j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
071601A07-0602A DRIER A/C 7118	1
08-5061BFITTING A/C 4389	1
08-6062BUSE 08-6962BS FITTING A/C 4403 SB1302	1
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	5
4410S 08-6961B FITTING	1
4411S08-6962BS 90 DEGREE SB1322	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
HLD3999GSS1715UV 30LB STRUT GAS	6
RD-5-7063-OP07-2618AA/C DRIER 7155	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1
1100-SDC-RHHEATER EVAPORATOR ASSY 06 MEDIC MAS	1
160012-2012A EXPANSION VALVE 71R8301	1
1501450007750USE 0775145	1
16-31438915 VALVE CORE A/C 3544706C1	2
322502BULB PATIENT GH22	1
906LIGHT BULB 12CP	1
921LIGHT BULB	1
HE50477VENT	2
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	2
S775COUPLER	1
RD-5-7123-0 18-2108 FIVE BLADE FAN 3382	2
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2

**Vendor?: TIRESOLES**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45631**

**In Date:** 12/05/2011

**Meter Reading:** 120,523.60

**Close Date:** 12/06/2011

**Problem?**

low oil.

**Task performed:**

phone call only, driver rechecked oil on 26 ok need oil delivered on monday to st 26

**Parts**

15W40QSYN OIL QT

**Quantity**

12

travel to 26 dropped off oil and checked all units ok

**Workorder: V45714**

**In Date:** 12/08/2011

**Meter Reading:** 120,523.60

**Close Date:** 12/09/2011

**Problem?**

Accident damage.

**Task performed:**

travel to st 26, found vehicle air tank pushed into drive shaft and air line broke, used service truck winch to pull tank away from drive shaft

**Parts**

12-14352-000AIR TANK BRACKET M2

5004049GOV CHK VALVE KIT M2

**Quantity**

2

1

repair airline at governor, vehicle needs to come to shop for repair in am, travel home

replaced tank brackets at shop, replaced governor and valve, plug leaking drain valve replaced unload--fitting tie strap air lines to tank test for leaks ok ordered drain valve

**Workorder: V45880**

**In Date:** 12/15/2011

**Meter Reading:**

**Close Date:** 12/19/2011

**Problem?**

the bolt protector had to be removed because it was blocking back door of rescue from closing

**Task performed:**

TRAVEL TO STA 26 REPLACED NADE 2 PIN COVER.

**Parts**

5004961NDRAIN VALVE M2

**Quantity**

1

REPLACED AIR DRYER POP OFF VEHICLE.



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46430**

In Date: 01/09/2012  
Close Date: 01/10/2012

Meter Reading: 122,195.20

**Problem?**

Low voltage alarm.

**Task performed:**

1. DIAGNOSE FAULT FOUND ALTERNATOR DEFECTIVE - REMOVE ALTINATOR. INSTALL NEW ALTINATOR.
2. WHILE ALTINATOR OFF FOUND TURBO CONTRADE VALVE LINE LOOSE. SECURE LINE.
3. A/C ON TOP OF ALTINATOR BRACKET BROKEN - REMOVE ASSEMBLY HAD IT WELD AND REASSEMBLE AND INSTALLED.
4. WELD UP BROKEN BRACKET TO ALTERNATOR.

Parts	Quantity
A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC	1

**Workorder: V46744**

In Date: 01/21/2012  
Close Date: 02/07/2012

Meter Reading: 122,696.00

**Problem?**

rear scene light not working, passenger side, Sta 26

**Task performed:**

- TRAVEL TO STATION REMOVED LIGHT BAR COVER CHANGED BULB. REINSTALLED LT BAR COVERS.

Parts	Quantity
MR1135 WATT BULB	2

**Workorder: V46855**

In Date: 01/26/2012  
Close Date: 02/07/2012

Meter Reading: 123,199.40

**Problem?**

the glass on the downward looking mirror on the passenger side of rescue 26 is broke

**Task performed:**

- REPAIRED MIRROR.

Parts	Quantity
A22-59713-001MIRROR HEAD	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V47090**

In Date: 02/04/2012

Meter Reading: 124,019.00

Close Date: 02/07/2012

**Problem?**

Driver side outside rear tire needs to be replaced.Sta 26

**Task performed:**

Parts

Quantity

TRAVEL TO STA 26 - CHECKED ALL TIRES LRO AND RRO WORN. RF TIRE WORN - ALL 6 TIRES TO BE REPLACED.

NO PARTS USED

**Workorder: V47157**

In Date: 02/07/2012

Meter Reading: 124,019.00

Close Date: 02/09/2012

**Problem?**

Replace six tires

**Task performed:**

Parts

Quantity

REPLACE SIX TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V47642**

In Date: 02/29/2012

Meter Reading: 125,082.80

Close Date: 03/06/2012

**Problem?**

REPLACE WIPERS R 26

**Task performed:**

Parts

Quantity

REPLACED BLADES.

91-22WIPER BLADE

2

**Workorder: V44159**

In Date: 10/05/2011

Meter Reading: 118,004.30

Close Date: 03/09/2012

**Problem?**

Nader pin covers on the rear doors. One needs replaced and one needs fixed. Sta 26.

**Task performed:**

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V44279**

In Date: 10/11/2011  
Close Date: 03/09/2012

Meter Reading: 118,384.00

**Problem?**

rear a/c warm.

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V48009**

In Date: 03/16/2012  
Close Date: 03/27/2012

Meter Reading: 125,904.70

**Problem?**

Rear door stuck

**Task performed:**

Parts

Quantity

TRAVEL TO ST 26 PULL APART REAR DOOR FROM INSIDE PULL WINDOWS GET DOOR OPEN FOUND ROD FELL OFF DOOR HANDLE ON LOWER LATCH ADJUST LATCHES AND LUBE STRAP ROD SO WON'T HAPPEN AGAIN.

NO PARTS USED

**Workorder: V48624**

In Date: 04/12/2012  
Close Date: 04/30/2012

Meter Reading: 126,984.70

**Problem?**

WHEN CONNECTED TO SHORE POWER REAR A/C DOES NOT KICK ON, FRONT CAB A/C ALSO NOT BLOWING COOL AIF 26

**Task performed:**

Parts

Quantity

CHARGED FRONT A/C WITH FREON RETEST BREAKER IN STATION FOR SHORELINE.

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48653**

**In Date:** 04/13/2012

**Meter Reading:** 127,726.60

**Close Date:** 05/01/2012

**Problem?**

C INSPECTION R26

**Task performed:**

1. C-INSPECTION.
2. C-INSPECTION.
3. SERVICE POWER STEERING.
4. REPLACE ENGINE AND CAB AIR FILTERS.
5. CLEAN ALL SAND AND ROCKS FROM BATTERY TRAY SLIDES, RE-LUBE.
6. STRAIGHTEN AND TIGHTEN ALL GROUND LIGHT BRACKETS.
7. R&R RIGHT REAR UPPER MARKER LIGHT.
8. SERVICE AIR DRYER.
9. R&R ENGINE BELTS.
10. R&R WIPER BLADES.
11. PULL REAR WHEELS OFF CHECK BRAKES, MEASURE AGAINST NEW SHORES 70%.
12. REMOVE AND RE-GLUE REAR DOOR SEALS.
13. TIGHTEN AND ADJUST ALL DOOR LATCHES, PINS AND HOLD OPENS MOUNTS.
14. REPLACE LEFT REAR MUD FLAP.
15. REPLACE DRIVER'S DOOR MOLDING AND SILL.
16. RESECURE SHORPIES DRAW SLIDES.
17. Q.C. VEHICLE AFTER REPAIRS.
18. CHECK FOR AIR LEAKS, REPLACE QUICK CONNECT FITTINGS ON AIR TANK AND TWO AIR SOLENOIDS ON REAR CROSS MUMPER.
19. GET REAR STAIR CH?? COMPART OPEN, STRAIGHTEN LATCH, CLEAN OUT SAID, LUBE.
20. REMOVE SIDE EXHAUST PIPE HEAT SHROD AND REPLACE MISSING NUT ON EXHAUST U-BOLT.
21. REPLACE PATIENT COMPT CABINETS HOLD OPENS.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
5008414CARTRIDGE DC100	1
18-46375-00018-46375-004 TREAD PLATE LH M2	1
42809AIR FILTER M2	1
440STEM EXTENSION	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
B2420LP-SMUD FLAP 24 X 24	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
K022105PURGE VALVE AD-IP-IS	1
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	3
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
HLD3999GSS1715UV 30LB STRUT GAS	2
A22-54624-001DOWN VIEW MIRROR M2	1

**Workorder: V50428**

**In Date:** 06/26/2012

**Meter Reading:** 131,201.40

**Close Date:** 06/28/2012

**Problem?**

the spare batt 2 stretcher on rescue 26 with not incline at the head

**Task performed:**

EMS CAPT HAS CONTACTED MEDCO.

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V50669**

In Date: 07/07/2012

Meter Reading: 131,772.40

Close Date: 07/09/2012

**Problem?**

Pt. Compt. A/C not cooling R 26

**Task performed:**

A/C NOT WORKING IN PATIENT COMPARTMENT.

Parts

NO PARTS USED

Quantity

**Workorder: V50637**

In Date: 07/05/2012

Meter Reading: 131,637.70

Close Date: 07/10/2012

**Problem?**

air condition not working in the cab R 26

**Task performed:**

- TRAVEL TO 26 FREON PRESSURES HIGH CLEANED OUT CONDENSER AND RECHECKED OK. CHECKED CAB A/C FILTER OK.
- TRAVEL TO 26 REPLACED CAB BLOWER MOTOR AND HARNESS.

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

**Workorder: V51029**

In Date: 07/21/2012

Meter Reading: 132,388.90

Close Date: 07/26/2012

**Problem?**

the plug in auto ejector for r26 has burns to face of the plug and will no longer plug in.

**Task performed:**

TRAVEL TO 26 REPLACED PLUG FOR AUTO EJECT.

Parts

NO PARTS USED

Quantity

**Workorder: V51149**

In Date: 07/27/2012

Meter Reading: 132,294.90

Close Date: 08/01/2012

**Problem?**

rear light , bottom right : next to bumper. On OIC side. Small light : coming off bracket. R26

**Task performed:**

REPLACED BEZEL FOR REAR EMERGENCY LIGHT.

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51469**

In Date: 08/08/2012  
Close Date: 08/09/2012

Meter Reading: 133,057.60

**Problem?**

the rear ac is leaking into the patient compartment. it is dripping onto the stretcher and onto the pt.

**Task performed:**

- 1. TRAVEL TO 26 FOUND DRAIN TUBES CLOGGED. CLEANED TUBES OK.
- 2. ASSIST WITH REPAIRS.

Parts

Quantity

NO PARTS USED

**Workorder: V52071**

In Date: 08/31/2012  
Close Date: 09/06/2012

Meter Reading: 134,407.90

**Problem?**

front hubs have water contamination. needs to come to shop

**Task performed:**

- 1.CHECKED OIL FOR WATER CONTAMINATION

Parts

Quantity

NO PARTS USED

**Workorder: V52122**

In Date: 09/04/2012  
Close Date: 09/13/2012

Meter Reading: 134,647.00

**Problem?**

ON CALL AIR LEAK E 26

**Task performed:**

- 1. AIR LEAK FROM UNDER HOOD FOUND 2 PUSH LOCK FITTINGS ON BRAKE VALVE LEAKING CHANGED FITTINGS AND CHK OK.

Parts

Quantity

NO PARTS USED

**Workorder: V52185**

In Date: 09/06/2012  
Close Date: 09/13/2012

Meter Reading: 134,829.00

**Problem?**

ON CALL SMELL BRAKES R 26

**Task performed:**

- 1. TRVL TO PALMS WEST CHK BRAKES R/R BRAKE STICKING GREASE AND ADJUST SLACK ADJUSTER ALSO NEED REAR SHOES AND CANS

Parts

Quantity

2000071102000072100 SOLENOID HALE PRIMER

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51852**

**In Date:** 08/24/2012

**Meter Reading:**

**Close Date:** 09/17/2012

**Problem?**

curb light below Driver side rear passenger door fell out while in JW Corbett and needs new grommet.

**Task performed:**

TRVL TO 26 REPAIRED GROUND LIGHT.

Parts

NO PARTS USED

Quantity





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V52142**

**In Date:** 09/04/2012

**Meter Reading:** 134,647.00

**Close Date:** 09/24/2012

**Problem?**

**B INSPECTION AND NEEDED RPAIRS**

**Task performed:**

1. DASH A/C NOT BLOWING-REPLACED DIRTY AIR FLOW FILTER FOUND TEMP BLEND ACTUATOR NOT WORKING-LOOSE ELECTRICAL PLUG AND PIN.
2. A/C NOT GETTING COLD ENOUGH-BLEND DOOR OPERATING NORMAL-SHUT OFF HEATER FLUID CONTROL VALVE. VACCUM SYSTEM AND CONTROL
3. DRAINING AIR TANK MOUNTING GASKET BENT-RELEASE TANK STRAPS REWIRE BENT BRACKET AND INSTALL.
4. FRT AND REAR BRAKES- REMOVE WHEELS AND DISASSYM BRAKES CLEAN BRAKE PARTS REASSYMBLE REAR BRAKES INSTALL FRT BRAKES
5. L/SISE FRT BOTTOM SHOCK BOLT MISSING PUT-CLEAN BOLT AND INSTALL AND SECURE NEW NUT.
6. TIRES ON REAR LOW ON AIR. INFLATE TO SPECS REMOVE NAIL FRM TIRE CHK FOR LEAK NO LEAK FOUND.
7. PACENT COMPT- LIGHT TAIL/ WARNING LIGHT AND SIDE CAB WARNING INOP-REMOVE AND INSTALL NEW PACENT COMP LIGHT REPROGRAMM TAIL WARNING AND REPLACE SIDE WARNING LIGHT.
8. BATTERY SLIDES HARD TO OPEN-CLEAN AND LUBRICATE TRUCK.
9. UNIT PULL TO RGHT-CHK TOE-IN/ TOE-OUT FOUND 1/2 INCH OUT ADJUST THE ROD BALL JOUNT SWAP LFT TO RHT TIRES AND RECHK ADJUST ROAD TEST
10. OK FOR PULLING TO THE RIGHT-TEST DROVE TORQUE ALL U BOLTS CHK OK.
11. MULIT FUNTION TURN SIGNAL CONTROL ACTIVATE WIPER CONTROL INTERMITING-REMOVE CONTROLE AND INSTALL NEW CONTROLER.
12. AIR HORN NEED ADJUSTING-ADJUST AIR HORN TUNE.
13. Q.A
14. FOUND DOOR LADDERSTOPPER LOOSE-TIGHTENED AND ADJUSTED DOOR CHK OK.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
07-18904-090TRANS DIPSTICK	1
12-14352-000AIR TANK BRACKET M2	2
322502BULB PATIENT GH22	1
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
404-100 VALVE CORE	6
50R03ZCRLIGHT LED RED TIR 6	1
5790COMPRESSOR A/C	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RES	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V52599**

In Date: 09/24/2012

Meter Reading: 135,243.00

Close Date: 09/26/2012

**Problem?**

REAR DOOR WONT CLOSE R 26

**Task performed:**

1. NATOR PIN COVER WEDGE BETWEEN DOOR PIN REMOVED INSIDE DOOR PANEL LOOSEN LOCKING DEVICE RELEASE LOCK, REPOSITION NATOR PIN AND REASSEMBLE.
2. R/REAR DOOR LOWER GLASS LOOSE IN FRAME, SECURE LOOSE SCREWS. NEED TO BE PROPERLY SECURED ON NEXT P.M SCHEDULE.
3. REMOVED SCREWS AND GLASS AND REINSTALLED OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V52668**

In Date: 09/26/2012

Meter Reading: 13,454,141.60

Close Date: 09/27/2012

**Problem?**

paitent a/c 10-7 r 26

**Task performed:**

CHK COMPRESSOR FAN FOUND ONE NOT WORKING AND THE OTHER FAN MOTOR VERY HOT SO I REMOVED FANS, BLOW OUT CONDENSER COIL AND RECOVERED SYST FOUND FREON LOW, CHARGED SYST AND REPLACED BOTH FANS AND WIRE END ON RELAY RAN SYST AND HIGH SIDE WAS STILL A LITTLE HIGH SO CLEAN CONDENSER W/ SOAP WATER.

**Parts**

60027FAN A/C COND 12IN 860026-2-W

2

**Quantity**

**Workorder: V53779**

In Date: 11/14/2012

Meter Reading: 137,318.40

Close Date: 11/16/2012

**Problem?**

A inspection - remove 26 placards, stickers

**Task performed:**

1. A INSP
2. ADJUST AIR HORNS.
3. RESECURE ALL GROUND LIGHT BRAKETs.
4. CHECK PATIENT A/C PULL DOWN AND RECHARGE.

**Parts**

02034294100LENS RETNR 4500 LITE BAR

2

607141-05USE 61H01 COPMPARTMENT LIGHT

2

MR1135 WATT BULB

2

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V53827**

In Date: 11/16/2012  
Close Date: 11/21/2012

Meter Reading: 137,318.40

**Problem?**

REPLACE REAR TIRES

**Task performed:**

REPLACE REAR TIRES.

**Parts**

NO PARTS USED

**Quantity**

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V54012**

In Date: 11/26/2012  
Close Date: 11/28/2012

Meter Reading: 137,318.40

**Problem?**

INSTALL STRYKER HOOK

**Task performed:**

INSTALL STRYKER AT STATION.

**Parts**

6092036018J HOOK STRYKER

**Quantity**

1

**Workorder: V53286**

In Date: 10/24/2012  
Close Date: 12/19/2012

Meter Reading:

**Problem?**

SMALL OIL LEAK COMING FROM DIP STICK. I BELIEVE THIS WAS BROKEN AND CHANGED POSSIBLY NOT THE CORRECT ONE. R26

**Task performed:**

TRAIN TEST 23 ORDER NEW DIP STICK.

**Parts**

A4440101372DIP STICK OIL

**Quantity**

1

**Workorder: V54748**

In Date: 01/02/2013  
Close Date: 01/25/2013

Meter Reading: 138,650.00

**Problem?**

door lock button not locking doors R45

**Task performed:**

REPAIRED DOOR LOCKS.

**Parts**

NO PARTS USED

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55557**

**In Date:** 02/05/2013

**Meter Reading:** 139,937.00

**Close Date:** 02/06/2013

**Problem?**

A inspection

**Task performed:**

1. A-INSPECTION.
2. CAB GLOVE BOX LOOSE; CAB COAT HOOK MISSING - INSTALL NEW COAT HOOK AND SECURE CAB GLOVE BOX.
3. CAB A/C COOL BUT ONLY AT COMPRESSOR PULLEY - CHECK FREON LOW - VACUUM SYSTEM CHECK FOR LEAK NO VACUUM LOST, CHARGE UNIT TO SPECS. OPERATE.
4. ENGINE OIL LOW-FILL TO PROPER LEVEL; TRANSMISSION OIL LOW - FILL TO PROPER LEVEL.
5. O2 COMPARTMENT LIGHT INOP. AUXILARY LIGHT INOP - REWIRE AND INSTALL NEW BULB ASSEMBLY.
6. CAB REAR A/C FILTER AND 110 A/C FILTER - REMOVE AND INSTALL NEW CAB FILTER, REMOVE 110 A/C FILTER BLOW OUT SCREEN AND REINSTALL.
7. NATOR PIN COVER BROKEN - REMOVE, RETAP SCREW HOLES, DRILL NEW MOUNTING HOLES IN PIN COVER AND INSTALL.
8. REAR PACENT DOOR PANEL; R-1 COMP DOR PANEL MISSING SCREWS RESECURE D OOR PANELS, REPLACE MISSING FASTNERS, RETAP ANCHER HOLES; L-2 TOOL HOLDER LOOSE, REPLACE MISSING FASTENERS AND SECURE.
9. OFFICER SEAT MOLDING LOOSE AND HAND RAILING ON DOOR - DISASSEMBLE SECURE LOOSE TORQUES SCREW AND REASSEMBLE AND SECURE MOLDING.

**Parts**

**Quantity**

621714 IN LIGHT

1

78R536078R5360M 2PK FILTER AIR COND

1

**Workorder: V55883**

**In Date:** 02/20/2013

**Meter Reading:** 140,379.60

**Close Date:** 03/07/2013

**Problem?**

A inspection

**Task performed:**

1. PERFORM A SERVICE.
2. REPLACED WIPER BLADES.
3. REPLACED AIR LINE UNION AT FOOT VALVE. (AUDIBLE AIR LEAK).
4. REPLACED FRT TIRES WITH TIRES FROM BUILDING #3.

**Parts**

**Quantity**

1893BULB

1

91-22WIPER BLADE

2





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56761**

**In Date:** 04/01/2013

**Close Date:** 04/16/2013

**Meter Reading:** 141,699.70

**Problem?**

C INSPECTION SR 18

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

1. C-INSPECTION.
2. C-INSPECTION CONTINUED.
3. R&R CENTRIFUGAL OIL FILTER HOUSING - BRNG AREA CRACKED AND BRNG LOOSE.
4. SERVICE REAR AXLE.
5. TIGHTEN ALL HARDWARE ON DOUBLE DOORS OF COMPT L-1.
6. ADJ ALL TIRE PRESSURES TO 110 PSI.
7. R&R STRIKER. STRAIGHTEN IT. REINSTALL AND ADJ STRIKER. LUBE LATCH ASSY OF SQUAD BENCH.
8. OVERHAUL AIR DRYER.
9. CLEAN TRANSMISSION OF OIL. CHECK AND RETORQUE ALL CONTROL BODY AND FILTER BOLT;
10. COMPT OPEN LIGHT AND ALARM ALWAYS ON. DIAGNOSE, FOUND BAD WIRING AT REAR SWITCH.
11. FINISH WIRING REPAIR ON COMPT OPEN SYSTEM AND TEST.
12. DIAGNOSE AND REPAIR BACK UP ALARM. R&R ALARM NEW ONE IS DIFFERENT WIRING. CUT, SPLICE AND HEAT SHRINK CONNECTIONS.
13. REMOVE REAR BUMPER FOR WELDING REPAIR
14. HOOK UP LAP TOP TO CHECK 20 FAULT CODES DETECTED ON QUICK SCHNNER. NO CODES ABOUT ANY ENGINE PROBLEMS.
15. PATIENT A/C NOT COLD - DIAGNOSE A/C SYSTEM LOW FREON FIND LEAK R&R BOTH SCHRADER VALVES. DISCH EVAC AND RECHARGE A/C SYSTEM AND TEST OK.
16. NOISE IN ENGINE AREA R&R FAN BELTS CHECK ALL IDLER PULLEY BRINGS AND TENSIONER BRNG. R&R A/C BELT IDLER PULLEY R&R BRNG. REINSTALL AND ADJ.
17. CUT OUT OLD WELDS ON STEEL BUMPER CUT OUT CRACKS AND REWELD BUMPER, WELD UP ALUM PLATE OVER BUMPER BUSTED ALSO CUT AND WELD. HELP INSTALLING ON TRUCK.
18. INSTALL AND ALIGN REPAIRED REAR BUMPER ASSY.
19. R&R AIR FILTER HOUSING. R&R SEAL BETWEEN HOUSING AND TURBO DUCT.
20. Q. C. TRUCK.
21. REMOVE ACCREDIDATION STICKERS AND ADHESIVE.
22. COMPT OPEN ON AGAIN RECHECK SYSTEM R&R BATTERY TRAY SWITCH.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
03-35087-002SEAL DUCT AIR 6.0	1
1501450007750USE 0775145	1
16-31438915 VALVE CORE A/C 3544706C1	2
4010051SENSOR TEMP	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
575BACKUP ALARM ECCO 107 DEC	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A9061840408SPINNER OIL FILTER COVER M2	1
K022105PURGE VALVE AD-IP-IS	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SWT54912SWITCH DOOR LGHT	1
SWT54930SWITCH DOOR	1
203FFBEARING PULLEY	1
15W40BSYN OIL BULK QTS	30



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58693**

In Date: 06/26/2013

Meter Reading: 145,651.80

Close Date: 06/28/2013

**Problem?**

A/C compressor locked up

**Task performed:**

TRAVEL TO ST 38 CHECK OUT A/C SYSTEM COMP. BEARING LOCKED UP TAKE DRIVER TO SHOP FOR TRUCK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V58745**

In Date: 06/26/2013

Meter Reading: 145,651.80

Close Date: 07/08/2013

**Problem?**

A/C compressor locked up

**Task performed:**

1. RECOVERED SYSTEM, UNTANGLED BROKEN BELT FROM PULLEYS AND REMOVED. REPLACED COMPRESSOR AND DRYER, REPLACED BELT ON REAR A/C COMPRESSOR. INSTALL NEW BELT FOR FRONT COMPRESSOR.
2. VACUUMED SYSTEM AND RECHARGED. ROAD TESTED. A/C FOR CAB IS NOW COOLING VERY WELL.

**Parts**

- 01-29866-118BELT ALT. M2
- 533303-0609 A/C COMPRESSOR M2 4485
- 719707-0614A AC DRIER M2
- 9550 BELT

**Quantity**

- 1
- 1
- 1
- 1

**Workorder: V58878**

In Date: 07/05/2013

Meter Reading: 145,981.00

Close Date: 07/19/2013

**Problem?**

running light wire is loose/free hanging under step board on officer side.SR@31

**Task performed:**

1. RECHARGED A/C AND REPAIRED LEAK.
2. REWIRED UNDER BODY LIGHTS.

**Parts**

NO PARTS USED

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V59761**

In Date: 08/13/2013  
Close Date: 09/11/2013

Meter Reading: 148,031.00

**Problem?**

One of siren's speakers is not working. SR@74

**Task performed:**

1. TRAVEL TO ST 74 CHECK OUT STRETCHER LOCK R&R AND ADJUST LOCK.
2. R&R SIREN SPEAKER ON PASS SIDE RETURN TO SHOP.

Parts	Quantity
SD-210RXSIREN DRIVER SMALL	1

**Workorder: V61346**

In Date: 10/17/2013  
Close Date: 10/21/2013

Meter Reading: 149,208.70

**Problem?**

back up alarm sometimes works. recently got stuck beeping even in neutral and drive. had to restart vehicl twice to reset R73

**Task performed:**

TRAVEL TO 73 DRIVER COMPLAINT RESCUE ALARM STICKING COULD NOT DUPLICATE PROBLEM.

Parts	Quantity
NO PARTS USED	

**Workorder: V61432**

In Date: 10/21/2013  
Close Date: 10/25/2013

Meter Reading: 149,399.00

**Problem?**

front cab a/c is not working & passenger side scene light is out R73

**Task performed:**

DRIVER COMPLAINT A/C INOP CHARGED A/C SYSTEM AND CLEANED AIR FILTER.

Parts	Quantity
NO PARTS USED	

**Workorder: V62609**

In Date: 12/09/2013  
Close Date: 12/13/2013

Meter Reading:

**Problem?**

2 dome lights are out in the back of R73.

**Task performed:**

TRAVEL TO 73 DRIVER COMPLAINT DOME LIGHTS OUT R&R DOME LIGHT BULBS.

Parts	Quantity
322502BULB PATIENT GH22	2



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61067**

In Date: 10/07/2013  
Close Date: 12/17/2013

Meter Reading: 148,195.00

**Problem?**

B inspection BSR7 OCS

**Task performed:**

B INSPECTION OIL CHANGE SERVICES

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Vendor?: OIL CHANGE SERVICES

**Workorder: V65731**

In Date: 04/15/2014  
Close Date: 04/16/2014

Meter Reading:

**Problem?**

Main o2 regulator is leaking unable to use main o2 for pt treatment.

**Task performed:**

WENT TO ST-72 TO CHECK O2 REGULATR FOUND FITTING BAD ON REGULATOR R&R FITTNG.

**Parts**

**Quantity**

M54-13SPM5413 NIPPLE	1
REG041462369 O2 REGULATOR	1

**Workorder: V67316**

In Date: 06/18/2014  
Close Date: 06/20/2014

Meter Reading: 155,641.70

**Problem?**

Replace rear tires

**Task performed:**

Replace rear tires

**Parts**

**Quantity**

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V67022**

**In Date:** 06/06/2014

**Meter Reading:** 155,641.70

**Close Date:** 07/14/2014

**Problem?**

C inspection BSR7

**Task performed:**

- 1.C Inspection
- 2.C- Inspection
- 3.Replace , Engine , Cab and A/C filters
- 4.Sercure and
5. Check Cab A/C low on feeon. Check for leaks. None found. Re-charge.
- 6.R and R shorpres draw slides
- 7.Repair rear jump seat draw latch.
- 8.Torque U-bolts.
9. Service Transmitter
- 10.Replace lower R/R warning light.
11. Patient compartment rear top drawer is not closing. Re-mount slides.
- 12.Clean condensor
- 13.Repair battery tender light
- 14.Start R and R rear brake shoes and drums and wheel seals.
- 15.Finish rear brakes and seals.
- 16.Remove R/S step assembly and fuel tank bracket. Order bracket.
17. Re-secure draw slides on rear patient compartment drawers.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0775145PANEL FILTER	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
K022105PURGE VALVE AD-IP-IS	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
29526898 29548988 TRANS FILTER ALLISON	1
4070091740 GROMMET T/L 4 IN	2
61H01LED GROUND LITE CLEAR	2
322502BULB PATIENT GH22	1
91-22WIPER BLADE	2
921LIGHT BULB	1
3744BRAKE DRUM REAR	2
380003ASEAL	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
401581GASKET AXLE FL80 R002435	1
6804750148INSULATION	1
5632-1010 IN DRAWER SLIDES PR	1
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WIDE	9
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

**Workorder: V67811**

**In Date:** 07/10/2014

**Meter Reading:**

**Close Date:** 07/18/2014

**Problem?**

Rescue has small oil leak. Dripping on nice new bay floor.

**Task performed:**

Travel to 73, driver compalint oil leak was on space unit truck gone.

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69131**

**In Date:** 09/03/2014

**Meter Reading:** 157,341.10

**Close Date:** 09/04/2014

**Problem?**

rear wheel seal leaking

**Task performed:**

1. Remove left rear. wheel hub. Replace hub and axle seal. Clean up drum and brake shoes. Install drum, adjust rear brakes. Test for operation.

**Parts**

**Quantity**

380003ASEAL

1

401581GASKET AXLE FL80 R002435

1

2. Road test fuel AC on cab not cooling. Needs work.

3. Work on AC was a bit low charge to specs. Test is good now. Remove overused condensor from front of unit. Test for operation.

**Workorder: V70025**

**In Date:** 10/09/2014

**Meter Reading:** 158,324.00

**Close Date:** 10/29/2014

**Problem?**

Front cab A/C not blowing air.

**Task performed:**

Travel to 73, replaced blower motor and harness.

**Parts**

**Quantity**

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

**Workorder: V71001**

**In Date:** 11/17/2014

**Meter Reading:**

**Close Date:** 11/20/2014

**Problem?**

Air conditioning not working in the cab. It only blows hot air. SPARE B7 R

**Task performed:**

Travel to station 73, check out cab A/C inop add freon to check for leaks. Found small leak on condensor line shop will repair on return of R73.

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V69023**

In Date: 08/28/2014

Meter Reading:

Close Date: 12/18/2014

**Problem?**

Engine oil is leaking and another fluid is leaking in the area of the rear differential of the rescue. Dark fluid also appears to be caked on the rear axle of the rescue.

**Task performed:**

Parts

Quantity

Work done on 69131  
wheel seal

NO PARTS USED

**Workorder: V69982**

In Date: 10/07/2014

Meter Reading:

Close Date: 12/29/2014

**Problem?**

Front cab A/C not blowing.

**Task performed:**

Parts

Quantity

Front cab AC not blowing  
Freon add #71001 done

NO PARTS USED

**Workorder: V72428**

In Date: 01/19/2015

Meter Reading: 161,866.40

Close Date: 01/21/2015

**Problem?**

pat a/c line leaking

**Task performed:**

Parts

Quantity

1. Diagnose patient line leak. Leak check system and found no real leak. Recover freon and charge with correct amount. Leak check again. No leak found on patient compartment. A/C leak at condensor lines for cab A/C. Repaired on w/o 72297.

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167683

**ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72297**

**In Date:** 01/13/2015

**Meter Reading:** 161,866.40

**Close Date:** 01/22/2015

**Problem?**

a/c line leaking near condensor

**Task performed:**

1. Diagnose a/c lines leaking. Evacuate system. Removed step for access to condenser. Removed a/c lines and had new made up. Install lines, vacuum system. Charge a/c. Leak test. Step weld broken. Remove and clean bracket and step for welding. Install welded step. Performance check vehicle - ok. Drill holes in brackets for mounting.
2. Clean grind off old welds and re-weld step.

**Parts**

**Quantity**

492933HOSE & FITTINGS

1

**Workorder: V72488**

**In Date:** 01/21/2015

**Meter Reading:** 161,936.00

**Close Date:** 02/04/2015

**Problem?**

B inspection BSR7

**Task performed:**

1. B Inspection.
2. Replaced wiper blades.
3. Fill washer reservoir. Replaced cracked cap.
4. Remove metal placard frames and mastic. Clean and polish body.
5. Remove auxiliary a/c filter. Clean filter and protective grate.
6. Left and right air bag level rods turned sideways. Loosen lock nuts and reposition rods.
7. Left rear side clearance light dim. Replaced light and splice wires. Test.
8. Left rear cab door ground light inop. Diagnose problem and found bad connection in harness plug. Repair connection.
9. Volume control on patient radio inop. Found volume controlled by speaker and radio function purposely not effective.
10. Air horn sound quality bad. Rebuild air horns and adjust sound quality.
11. Right ground light bracket loose. Found screws stripped. Drill and tap threads. Drill out and straighten bracket. Install 1/4 x 20 bolts with Loctite.
12. Trans leak. Degrease tranes and lines. Road test vehicle. Re-check. Small leaks at case bolts where front bolts to mid section. Tighten bolts and valve body bolts. Drain 1 quart. Road test. Recheck leaks and level - ok.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

1094KIT-AIR HORN-GROVER

2

22-58581-000WASHER RESIVOR CAP

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

91-22WIPER BLADE

2

CLR9185109186-1500-10 MARKER LT. RED LED

1

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10167683

### ALS RESCUE ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V73822**

In Date: 03/12/2015  
Close Date: 04/23/2015

Meter Reading: 161,866.40

**Problem?**

batteries dead

**Task performed:**

1. Drive to station 73. Check batteries and replace with new ones. Test for operation, good now.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4

**Workorder: V73937**

In Date: 03/17/2015  
Close Date: 04/24/2015

Meter Reading: 162,056.60

**Problem?**

Rear door won't open

**Task performed:**

REPLACE DOOR HANDLE

Parts	Quantity
HND5948TM22676-02 HANDLE DOOR ENTRY	1
LTC594111656-16 LATCH R/H MEDIC MASTER	1

**Workorder: V73971**

In Date: 03/17/2015  
Close Date: 05/11/2015

Meter Reading:

**Problem?**

Door handle to side patient compartemnt door was broken off in an MVA this a.m. Unable to open door from outside. Door functions properly from inside the patient compartment. r73

**Task performed:**

1. Replaced broken door handle. Straightened aluminum around handle to make fit. Tested unit ok.

Parts	Quantity
10008145HANDLE LH HORTON	1
10008146HND5948 HANDLE RH HORTON	1



# Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10167683) 2006 - AMERICAN LAFRAN M2 Advanced Life Support Vehicle

10167683

## CSHOP-2015-1574

Comments: R74 A/C SMOKE AND SHOCK BOLT

Date Opened: 7-6-2015

Date Finished

7-6-2015

Meter 1 Reading:

163,264

### TASKS PERFORMED

NO PARTS USED

FRONT SHOCKS- STRUTS  
AIR CONDITIONING

## CSHOP-2015-1575

Comments: R74 SECURE FRONT SHOCK

Date Opened: 7-6-2015

Date Finished

7-8-2015

Meter 1 Reading:

163,264

### TASKS PERFORMED

NO PARTS USED

FRONT SHOCKS- STRUTS

## CSHOP-2015-1911

Comments: REPAIR RRO TIRE

Date Opened: 7-22-2015

Date Finished

7-22-2015

Meter 1 Reading:

163,264

### TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

## CSHOP-2015-2980

Comments: R72 CAB A/C HOT AND BLOWER SPEED IS SLOW THE ROOF AC TO THE PT COMPARTMENT IS LEAKING SIGNIFICANT AMOUNTS OF WATER ONTO THE FLOOR, PATIENTS AND EQUIPMENT AFTER BEING PLUGGED IN OVERNIGHT. THIS SHOULD BE REPAIRED ONCE OUR REGULAR R72 COMES BACK FROM PM. THANK U

Date Opened: 9-18-2015

Date Finished

9-23-2015

Meter 1 Reading:

165,794

### TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

1 FILTER; A/C FILTER CAB M2

**Asset Work Order History 10167683**

**CSHOP-2015-3468**

Comments: **RESCUE @73**

Date Opened: 10-16-2015      Date Finished 10-30-2015      Meter 1 Reading: 167,505

**TASKS PERFORMED**

**NO PARTS USED**

REPAIR FROM PM - O2 SYSTEM  
SUSPENSION

**Service Requests:**

10/16/2015      AIR RIDE / 11: BINDS/STICKS / ADJUST  
VEHICLE IS LEANING TO THE LEFT

10/16/2015      SERVICE REQUEST / 18: LEAKING / ADJUST  
MAIN O2 LEAKS.

**CSHOP-2015-3697**

Comments: **BATT 7 SPARE RESCUE LRI TIRE**

Date Opened: 11-2-2015      Date Finished 11-17-2015      Meter 1 Reading: 167,970

**TASKS PERFORMED**

**NO PARTS USED**

FRONT TIRES

**VENDOR?**      EARL COLVARD      BOULEVARD TIRE

**Service Requests:**

10/31/2015      OIL / 17: INSUFFICIENT LUBRICANT / LUBRICATE  
R273 REQUIRED 5 QT OF MOTOR OIL. THERE MAY BE A LEAK.

**CSHOP-2015-3989**

Comments: **BATT SPARE RESCUE 7**

Date Opened: 11-16-2015      Date Finished 11-16-2015      Meter 1 Reading: 167,970

**TASKS PERFORMED**

**NO PARTS USED**

FRONT TIRES

**VENDOR?**      ELPEX TIRE      TIRESOLES

**CSHOP-2016-1221**

Date Opened: 3-14-2016      Date Finished 3-18-2016      Meter 1 Reading: 169,655

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
SPOT LIGHTS

**1      BULB; BULB**

**Service Requests:**

03/14/2016      LIGHTS / 12: BROKEN / EXCHANGE - NEW  
OFFICER SIDE SCENE LIGHT NOT WORKING. NEEDS NEW LIGHT BULB.

**Asset Work Order History 10167683**

**CSHOP-2016-1880**

Date Opened: 4-21-2016

Date Finished

5-2-2016

Meter 1 Reading:

169,655

**TASKS PERFORMED**

PM SERVICE C RESCUE

**Q**

**PARTS**

---

1 FILTER; AIR FILTER M2  
1 FILTER; A/C FILTER CAB M2  
1 FILTER; 33634 FUEL FILTER WIX  
MERCEDES/FREIGHTLINE  
1 FILTER; OIL FILTER 03 57215 WIX  
MERCEDES/FREIGHTLINER  
1 FILTER; FUEL FILTER 33813 L/F # LFF5851  
1 FILTER; OIL FILTER M2 SPINNER 57140

---

**CSHOP-2016-1994**

Comments: **PM FOLLOW UPS**

Date Opened: 4-27-2016

Date Finished

7-18-2016

Meter 1 Reading:

169,920

**TASKS PERFORMED**

WIPER BLADES  
COOLING SYSTEM  
FAULT CODE  
SPOT LIGHTS  
LIGHTING SYSTEM  
ELECTRICAL  
STEERING  
AIR DRIER  
AIR SYSTEM  
BODY DAMAGE ACCIDENT  
DOOR PANEL  
GLOVE BOX  
CAB-INTERIOR ACCESSORIES  
CABLES- HEATER-DEFROSTER  
QUALITY CHECK-REPAIRS  
AIR CONDITIONING

**Q**

**PARTS**

---

1 9IP; PLUG RAD. DRAIN  
1 NEWPART; GRID HEATER  
1 MOUNT; DASH MOUNT REMOTE CONTROL  
1 LIGHT; 600 LIGHT ASSY WPB  
1 LIGHT; 4 IN LIGHT  
1 LIGHT; TOP CLEARANCE LIGHT M2  
1 9IP; 4 IN ROUND LED  
1 LIGHT; 9186-1500-20 MARKER LT.AMBER LED  
1 FILTER; 2503221C1 FILTER POWER STEERING  
1 GASKET; GASKET RVR PWR STRG M2  
1 VALVE; PURGE VALVE AD-IP-IS  
1 BRAKE; CARTRIDGE DC100  
2 WIPER; WIPER BLADE  
2 STRUT; GSS1715UV 30LB STRUT GAS  
1 A/C; HVAC UNIT ROOF MOUNTED  
1 BULB; PLS11W/TUV BULB A/C RESCUES  
1 9IP; ACTUATOR  
1 FILTER; 78R5360M 2PK FILTER AIR COND  
1 FILTER; PANEL FILTER

---

**Asset Work Order History 10167683**

**CSHOP-2016-4173**

Date Opened: 8-24-2016      Date Finished      9-28-2016      Meter 1 Reading:      170,132

**TASKS PERFORMED**

**Q      PARTS**

---

CB RADIO	1	GASKET; GASKET AXLE FL80 R002435
FAULT CODE	1	9IP; SEAL
REAR HUB SEAL-GASKET	2	BRAKE; 16-19471-000 AIR BAG
SUSPENSION	1	DRYER; 07-0602A DRIER A/C 7118
ABS CODES	1	FILTER; CAB FILTER RED DOT
AIR SYSTEM	1	COMPRESSOR; COMPRESSOR A/C
AIR CONDITIONING		

**Service Requests:**

---

08/24/2016      ENGINE / 19: LOOSE / REPAIR  
CHECK ENGINE LIGHT IS ILLUMINATED... A/C BLOWS WARM AT TIMES AND THE COOLING FAN OPERATION IS INTERMITTENT (DOES NOT STAY ON WHEN THE A/C IS ON) AND IS SPORADIC WHEN CONTROLLING ENGINE TEMPERATURE... IT DID NOT COME ON AT ALL WITH THE COOLANT TEMP ABOVE 200 DEGRESS. SHUT THE TRUCK OFF AND LET IT COOL AT WHICH TIME THE FAN CAME ON AND KEPT THE TEMP AROUND 160. ALSO, THE TRUCK MOUNTED COMMUNICATIONS RADIO WILL NOT POWER UP.

---

**CSHOP-2016-4595**

Comments:      **SPARE RESCUE AT ST73**

Date Opened: 9-21-2016      Date Finished      9-21-2016      Meter 1 Reading:      169,920

**TASKS PERFORMED**

**NO PARTS USED**

---

BODY EXTERIOR  
CAB-INTERIOR ACCESSORIES

**Service Requests:**

---

09/20/2016      DOOR / 19: LOOSE / REPAIR  
VEHICLE DOORS. BACK REAR DOOR OF PATIENT COMPARTMENT. SENSOR IS FAULTY AND CAUSING THE OPEN DOOR ALARM TO SOUND. WHEN DOOR IS COMPLETELY SHUT.

09/21/2016      SERVICE REQUEST / 19: LOOSE / REPAIR  
SIDE COMPARTMENT ON DRIVERS SIDE THAT HOLDS SPLINTS ETC. WILL NOT OPEN AND CANNOT GET GEAR AND MEDICAL SUPPLIES OUT.

---

**CSHOP-2016-4601**

Comments:      **DOOR OPEN WARNING ON**

Date Opened: 9-22-2016      Date Finished      9-22-2016      Meter 1 Reading:      170,132

**TASKS PERFORMED**

**Q      PARTS**

---

BODY - WORK COMPARTMENT EMER	1	DOOR; DOOR MAGNETS
	1	STARTER; PARTNER STARTER PULLEY

---

**Asset Work Order History 10167683**

**CSHOP-2016-4821**

Date Opened: 10-7-2016      Date Finished      10-11-2016      Meter 1 Reading:      171,314

**TASKS PERFORMED**

**NO PARTS USED**

OXYGEN SENSOR

**Service Requests:**

10/06/2016      SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW  
SERVICE REQUEST: MAIN OXYGEN LINE LEAKING

**CSHOP-2016-4950**

Date Opened: 10-17-2016      Date Finished      10-19-2016      Meter 1 Reading:      171,584

**TASKS PERFORMED**

**NO PARTS USED**

CAB-INTERIOR ACCESSORIES

**Service Requests:**

10/13/2016      BODY / 12: BROKEN / REPAIR  
BODY ISSUE, TOP ROOFLINE MOLDING, RED IN COLOR, MISSING BETWEEN OFFICERS DOOR AND REAR OFFICERS SIDE DOOR

**CSHOP-2016-5482**

Comments:      **BATT 7 SPARE RESCUE**

Date Opened: 11-23-2016      Date Finished      12-20-2016      Meter 1 Reading:      175,074

**TASKS PERFORMED**

**Q      PARTS**

MIRRORS

1      NEWPART; REINFORCEMENT  
1      NEWPART; REINFORCEMENT  
1      NEWPART; CLAMP KIT  
1      NEWPART; CLAMP KIT  
1      NEWPART; COVER BACK SPOT MIRROR  
1      NEWPART; COVER BACK SPOT MIRROR

**Service Requests:**

11/22/2016      SERVICE REQUEST / 12: BROKEN / INSPECT  
SERVICE REQUEST SHORE POWER CHARGING LIGHTS STOPPED ILLUMINATING

11/23/2016      MIRROR / 14: CRACKED / INSPECT  
MIRROR ISSUE. OFFICER SIDE, BLIND SPOT MIRROR DETACHED FROM MIRROR FRAME.

11/23/2016      BODY / 12: BROKEN / INSPECT  
BODY ISSUE. NOT PRIORITY, TOP PANEL ON DRIVER SIDE B-POST FELL OFF

**Asset Work Order History 10167683**

**CSHOP-2016-5725**

Date Opened: 12-8-2016      Date Finished      12-14-2016      Meter 1 Reading:      174,891

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
TIRES ALL

7      A/C; FREON LB

**Service Requests:**

-----  
12/08/2016      TIRES / 13: CHIPPED / INSPECT  
BAD TIRE ON REAR DRIVER SIDE MISSING A CHUNK

---

**CSHOP-2016-5999**

Comments:      **73 RESCUE CONVEX MIRROR FELL OFF NEED REPLACED**

Date Opened: 12-27-2016      Date Finished      1-4-2017      Meter 1 Reading:      175,975

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
MIRRORS

1      NEWPART; REINFORCEMENT

**Service Requests:**

-----  
12/27/2016      MIRROR / 23: NOT CONNECTED / EXCHANGE - NEW  
MIRROR ISSUE-OFFICER SIDE DISTANCE/ BUBBLED MIRROR FELL OFF AND IS MISSING. NEEDS TO BE REPLACED ASAP.

---

**CSHOP-2016-6075**

Date Opened: 12-28-2016      Date Finished      2-15-2017      Meter 1 Reading:      179,349

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRES & WHEELS

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2017-1215**

Comments:      **REPAIRS FROM PM**

Date Opened: 2-27-2017      Date Finished      2-28-2017      Meter 1 Reading:      176,254

**TASKS PERFORMED**

**Q      PARTS**

---

FIRE FIGHTING EQUIPMENT  
WIPER BLADES  
LIGHTING SYSTEM  
CHARGING SYSTEM  
TRANSMISSION  
CAB-INTERIOR ACCESSORIES  
SEALS AND GASKETS  
A/C FILTER SCREENS

1      FILTER; A/C FILTER CAB M2  
2      1AN; WIPERS  
1      LIGHT; TOP CLEARANCE LIGHT M2  
1      9IP; OVAL AUTO EJECT COVER  
1      FILTER; 78R5360M 2PK FILTER AIR COND

---



**Asset Work Order History 10167683**

**CSHOP-2017-570**

Date Opened: 1-25-2017      Date Finished      3-2-2017      Meter 1 Reading:      176,254

**TASKS PERFORMED**

PM SERVICE B

<u>Q</u>	<u>PARTS</u>
1	9IP; 33634 FUEL FILTER WIX MERCEDES/FR
26	9OC; SYN 15W40
1	FILTER; FUEL FILTER 33813 L/F # LFF5851
1	FILTER; OIL FILTER M2 SPINNER 57140
1	FIL; NAPAGOLD OIL FILTER
1	FILTER; 0000925208 FILTER HEAD CAP NEW NUMBER
1	FILTER; 0000925208 FILTER HEAD CAP NEW NUMBER

---

**CSHOP-2017-5754**

Comments: **REAR PATIENT DOOR OPEN WARNING SOUNDING R72**

Date Opened: 10-3-2017      Date Finished      10-5-2017      Meter 1 Reading:      176,950

**TASKS PERFORMED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ANTIFREEZE  
ALARM-BUZZER-WARNING LIGHT  
A/C LOW FREON

<u>Q</u>	<u>PARTS</u>
2	FLUID; COOLANT ANTIFREEZE GAL
-2	9OC; COOLANT
2	9OC; COOLANT
1	5TN; ADAPTOR, DOOR SWITCH
1	5TN; SWITCH, DOOR
1	5EF; SWITCH

---

**CSHOP-2017-6562**

Date Opened: 11-13-2017      Date Finished      11-14-2017      Meter 1 Reading:      177,350

**TASKS PERFORMED**

PM SERVICE C RESCUE

<u>Q</u>	<u>PARTS</u>
26	9OC; SYN 15W40
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPA GOLD OIL FILTER
1	FIL; NAPAGOLD FUEL FILTER
26	FLUID; SYN OIL BULK QTS
-26	9OC; SYN 15W40
1	FIL; NAPAGOLD OIL FILTER

---

**Asset Work Order History 10167683**

**CSHOP-2017-6584**

Comments: **PM FOLLOW UPS SEE "RELATED FILES"**

Date Opened: 11-14-2017      Date Finished 12-12-2017      Meter 1 Reading: 177,350

**TASKS PERFORMED**

GROUND LIGHT BODY  
EQUIPMENT MOUNTING BRACKETS  
WIPER BLADES  
RADIATOR  
FAULT CODE  
REPAIR FROM PM - BELTS  
REPAIR FROM PM - ENGINE  
REPAIR FROM PM - TRANSMISSION  
AIR CONDITIONING

**Q      PARTS**

1      9ME; LG MOUNT  
2      1AN; 22" WIPER BLADE  
1      2FL; FAN  
-1      NBH; FLEETRANNER BELT  
1      2FL; HORTON FAN CLUTCH M2  
1      2FL; IDLER PULLEY  
1      BRG; ALTERNATOR BEARING  
1      BRG; ALTERNATOR BEARING  
1      NBH; SERPENTINE BELT  
1      9IP; FRE04 RADIATOR  
1      NBH; V-BELT  
1      NBH; FLEETRANNER BELT  
-1      9OC; BULK TRANS SYN  
1      9OC; BULK TRANS SYN  
1      9IP; ALLISON TRANS FLUID GAL  
4      9XX; AC FREON 10199801

**CSHOP-2017-7147**

Comments: **QC BEFORE SENDING BACK TO ST73**

Date Opened: 12-14-2017      Date Finished 12-21-2017      Meter 1 Reading: 177,350

**TASKS PERFORMED**

QUALITY CHECK-REPAIRS  
COOLING SYSTEM  
AIR SYSTEM  
BELT(S)- A-C COMPRESSOR

**Q      PARTS**

1      9IP; EL35674 DIODE PACK GRAY  
1      TEM; NEW COMPRESSOR  
1      TEM; FILTER DRIER  
1      TEM; FILTER DRIER

**CSHOP-2018-2078**

Comments: **CALL OUT TICKET, PAT A/C INOP**

Date Opened: 4-15-2018      Date Finished 4-19-2018      Meter 1 Reading: 178,036

**TASKS PERFORMED**

**NO PARTS USED**

A/C COMPRESSOR

**Service Requests:**

04/14/2018      A/C / 18: LEAKING / CHARGED SYSTEM, WILL NEED TO HAVE LINES REPLACED  
A/C ISSUE-FRONT CAB AC IS NOT WORKING ON R74/SPARE

**Asset Work Order History 10167683**

**CSHOP-2018-2192**

Comments: **SR74**

Date Opened: 4-19-2018

Date Finished

5-3-2018

Meter 1 Reading:

178,215

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

04/19/2018

A/C / 18: LEAKING / ADJUST

A/C ISSUE. FRONT PASSENGER COMPARTMENT A/C UNITS BOTH BLOW HOT AIR.

**CSHOP-2018-2399**

Comments: **SPARE RESCUE AT 74**

Date Opened: 5-2-2018

Date Finished

5-16-2018

Meter 1 Reading:

178,452

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**Service Requests:**

05/02/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

AIR LEAK TO BOTH BANKS. HAVING TO WAIT FOR BANKS TO FILL PRIOR TO RESPONDING, DELAYING RESPONSE TIMES.

**CSHOP-2018-2823**

Comments: **R74**

Date Opened: 5-21-2018

Date Finished

5-31-2018

Meter 1 Reading:

178,815

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS

1

1WL; 600 SERIES RED LED W/O FLANGE

**Service Requests:**

05/21/2018

LIGHTS / 12: BROKEN / EXCHANGE - NEW

VEHICLE LIGHTS NOT WORKING THE RED EMERGENCY LIGHT ON THE DRIVER SIDE ON THE HOOD IS NOT WORKING. NEEDS A NEW BULB I BELIEVE.

**CSHOP-2018-2867**

Date Opened: 5-23-2018

Date Finished

5-25-2018

Meter 1 Reading:

178,668

**TASKS PERFORMED**

**NO PARTS USED**

WAIT TIME TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

05/23/2018

A/C / 43: WEAK / REPAIR

A/C ISSUE- CAB A/C NOT BLOWING COLD

**Asset Work Order History 10167683**

**CSHOP-2018-54**

Date Opened: 1-3-2018      Date Finished      1-5-2018      Meter 1 Reading:      177,350

**TASKS PERFORMED**

**Q      PARTS**

---

AIR SYSTEM

1      2FL; DOUBLE CHECK VALVE  
1      9LO; VALVE  
1      VALVE; VALVE DOUBLE CHECK

---

**CSHOP-2018-5784**

Date Opened: 10-13-2018      Date Finished      10-19-2018      Meter 1 Reading:      179,394

**TASKS PERFORMED**

**Q      PARTS**

---

PM SERVICE B

1      FIL; NAPAGOLD FUEL FILTER  
12      9AP; BRAKE CLEAN  
2      1AN; WIPERS  
1      FIL; NAPAGOLD FUEL FILTER  
30      4PC; 15W40 PREMIUM BLUE OIL  
1      FIL; NAPAGOLD OIL FILTER

---

**CSHOP-2018-5906**

Comments:      **PM REPAIR TICKET**

Date Opened: 10-17-2018      Date Finished      10-22-2018      Meter 1 Reading:      179,394

**TASKS PERFORMED**

**NO PARTS USED**

---

TRANSMISSION  
GRILLE  
AIR CONDITIONING

---

**CSHOP-2018-6957**

Comments:      **REAR DOOR STUCK CLOSED R273**

Date Opened: 12-7-2018      Date Finished      12-11-2018      Meter 1 Reading:      180,149

**TASKS PERFORMED**

**NO PARTS USED**

---

CAB & BODY MOUNT

**Service Requests:**

---

12/07/2018      DOOR / 19: LOOSE / REPAIR  
                         PATIENT COMPARTMENT REAR DOOR DOES NOT OPEN, GETS STUCK ON BOTTOM LATCH.

---

**Asset Work Order History 10167683**

**CSHOP-2018-7117**

Date Opened: 12-16-2018      Date Finished      12-26-2018      Meter 1 Reading:      180,771

**TASKS PERFORMED**

**Q      PARTS**

CRANKING SYSTEM

**4      1AD; BATTERY 31 SERIES**

**Service Requests:**

---

12/16/2018      STARTER / 12: BROKEN / EXCHANGE - NEW  
BATTERIES ARE DEAD. YESTERDAY C-SHIFT HAD TO CHARGE THE BATTERIES FOR AN 1 HOUR AND A HALF PER LT. THOMAS.

---

**CSHOP-2019-1868**

Comments:      **QA INSPECTION**

Date Opened: 4-10-2019      Date Finished      4-16-2019      Meter 1 Reading:      180,995

**TASKS PERFORMED**

**NO PARTS USED**

QUALITY CHECK-REPAIRS  
DASH CONTROLS  
A/C FILTER SCREENS

**CSHOP-2019-2315**

Date Opened: 5-1-2019      Date Finished      5-1-2019      Meter 1 Reading:      181,000

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM

**Service Requests:**

---

04/30/2019      RADIATOR / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
RADIATOR OR RADIATOR HOSE LEAKING

---

**CSHOP-2019-2648**

Comments:      **SHORELINE CHARGER INOP AT ST72**

Date Opened: 5-22-2019      Date Finished      5-22-2019      Meter 1 Reading:      181,415

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SHORELINE CHARGER  
AIR CONDITIONING

---

**Asset Work Order History 10167683**

**CSHOP-2019-3264**

Date Opened: 6-24-2019      Date Finished      6-24-2019      Meter 1 Reading:      181,597

**TASKS PERFORMED**

**Q      PARTS**

---

PM SERVICE C RESCUE

26      4PC; 15W40 PREMIUM BLUE OIL  
1      9IP; OIL DRAIN GASKET M2  
1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPA GOLD OIL FILTER  
1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPAGOLD OIL FILTER  
1      FIL; NAPAGOLD AIR FILTER

---

**CSHOP-2019-3289**

Comments:      **PM FOLLOW UPS**

Date Opened: 6-24-2019      Date Finished      7-17-2019      Meter 1 Reading:      181,658

**TASKS PERFORMED**

**Q      PARTS**

---

SCBA BRACKETS  
STORAGE CABINET EMERGENCY VEH  
WIPER BLADES  
LIGHTING SYSTEM  
TRANSMISSION  
AIR SYSTEM  
AIR HORN  
GRILLE  
INTERIOR TRIM-MOLDINGS-UPHOLS  
DOOR PANEL  
A/C FILTER SCREENS

4      4AH; GAS SPRING, 7.5", 45LB  
2      4AH; GASSPRING  
2      1AN; 22" WIPER BLADE  
1      5FS; MAP LIGHT LED 18 IN  
4      9AP; BRAKE CLEAN  
1      TWD; PURGEVALVEKIT  
1      FIL; NAPAGOLD AIR FILTER  
1      TWD; VALVE KT  
1      8GR; FOOT SWITCH  
1      2FL; TREADPLATE RH  
1      FIL; NAPA CABIN AIR FILTER

---

**CSHOP-2019-4006**

Date Opened: 8-1-2019      Date Finished      8-9-2019      Meter 1 Reading:      182,318

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

1      2FL; HARNESS, BLOWER  
1      2FL; MOTOR, BLOWER

**Service Requests:**

08/09/2019      A/C / 38: SHORTED / EXCHANGE - NEW  
A/C ISSUE/ AC IN THE FRONT (NON-PT COMPT) IS NOT BLOWING COLD AT ALL

---

**CSHOP-2019-4641**

Date Opened: 8-30-2019      Date Finished      9-9-2019      Meter 1 Reading:      182,318

**TASKS PERFORMED**

**NO PARTS USED**

---

PRE TRIP INSPECTION

---

**Asset Work Order History 10167683**

**CSHOP-2019-511**

Date Opened: 1-27-2019

Date Finished

5-7-2019

Meter 1 Reading:

181,000

**TASKS PERFORMED**

	<b><u>Q</u></b>	<b><u>PARTS</u></b>
FAULT CODE	1	9IP; STARTER RELAY ESX-120-105112
ECU-ECM	1	2FL; DISTRIBUTION BLOCK
ENGINE AND ACCESSORIES	1	TWD; C-1COCK DRAIN
TERMINAL BLOCK	1	2DD; PREHEATER GRID
SWITCH-ELECTRICAL	1	2FL; SEAL
SOLENOID	1	MBI; AIR PRESSURE VALVE
FUSE	1	2DD; CONTROL MODULE
DIAGNOSE ELECTRICAL	4	9AP; BRAKE CLEAN
TRANSMISSION	2	2DD; SOLENOID
CAB & BODY MOUNT	1	2DD; VALVE BODY HARNESS
AIR CONDITIONING	1	2DD; SENSOR
	1	2DD; FILTER INTERNAL
	1	2DD; OIL LEVEL
	4	2DD; SOLENOID
	1	2DD; FILTER KIT, TRANS, SUMP 4"
	1	2DD; SOLENOID ASM
	1	9IP; D PADDLE HANDLE
	1	MAC; MAC WITE LITHIUM GRES

**Service Requests:**

01/27/2019

BODY / 12: BROKEN / REPAIR

PT. COMPARTMENT DOOR WILL NOT OPEN SOMETIMES DUE TO LATCH MECHANISM NOT WORKING PROPERLY.

**CSHOP-2019-516**

Comments: **TRANS SHIFTER HAD NO POWER, NOW IS WORKING, PLEASE CHECK FOR CODES AND CHECK CONNECTIONS  
REPLACE STEERING WHEEL PLEASE I ORDERED A NEW ONE THANKS!**

Date Opened: 1-27-2019

Date Finished

2-6-2019

Meter 1 Reading:

180,995

**TASKS PERFORMED**

	<b><u>Q</u></b>	<b><u>PARTS</u></b>
CRANKING SYSTEM	1	9IP; STEERING WHEEL M2
STEERING WHEEL	1	2FL; HORN BUTTON

**CSHOP-2019-5532**

Date Opened: 10-21-2019

Date Finished

10-25-2019

Meter 1 Reading:

182,318

**TASKS PERFORMED**

	<b><u>Q</u></b>	<b><u>PARTS</u></b>
TRAVEL TO BE CHARGED TO WORK ORDER AIR CONDITIONING	1	9HC; HOSE S CUSTOM

**Service Requests:**

10/20/2019

A/C / 18: LEAKING / REPAIRED

A/C ISSUE. NOT BLOWING COLD.

**Asset Work Order History 10167683**

**CSHOP-2019-5812**

Date Opened: 11-5-2019

Date Finished

12-18-2019

Meter 1 Reading:

184,978

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
REAR WINDOW

**Service Requests:**

11/05/2019

BODY / 19: LOOSE / REPAIR

BODY ISSUE REAR DOOR WINDOW READY TO FALL OUT CHECK BOTTOM OF SAME DOOR THANKS

---

**CSHOP-2019-6111**

Date Opened: 11-21-2019

Date Finished

12-2-2019

Meter 1 Reading:

184,271

**TASKS PERFORMED**

**NO PARTS USED**

---

DOOR

---



**Asset Work Order History 10167683**

**CSHOP-2019-6546**

Date Opened: 12-18-2019

Date Finished

3-4-2020

Meter 1 Reading:

185,094

**TASKS PERFORMED**

QUALITY CHECK-REPAIRS  
WATER PUMP  
COOLING SYSTEM  
OIL  
STARTER  
ALTERNATOR-GENERATOR  
CAB & BODY MOUNT  
AIR SYSTEM  
A/C COMPRESSOR  
AIR CONDITIONING

**Q**

**PARTS**

---

1 2FL; LINE  
1 2DD; WATER PUMP  
2 2DD; THERMOSTAT  
2 2DD; 2DD  
1 2DD; HOSE UPPER RAD  
1 2DD; PIPE BREATHER  
1 2FL; 2FL  
1 2FL; OIL COOLER  
1 NCB; BLASTER PENETRANT  
1 2DD; 2DD  
2 2DD; 2DD  
1 2DD; SENSOR OIL PRESSURE  
1 2DD; HOSE  
1 2FL; LINE  
1 PTX; PERMATEX  
1 2DD; FITTING  
1 2DD; GASKET  
1 2DD; TEMP SENSOR OIL  
1 2FL; PULLEY IDLER  
1 2DD; 2DD  
1 9HC; 9HC  
1 2FL; 2FL  
2 9ES; PUMP TRANSFER 12VDC  
2 9HC; FITTING BRASS  
1 9AP; HAND SOAP PUM TOTAL TRK  
1 9HY; MAKO HOSE  
1 9HD; HOSE CUSTOM  
1 9HY; MISC BRASS AND HOSE  
2 NOL; NAPA GAL 15W40  
1 9AP; SORBENT PAD  
1 1AD; STARTER NEW 12 TOOTH 38MT 12V  
1 1AD; ALTERNATOR 320A  
2 5AH; GAS SPRING  
2 TWD; TRUCK AIR SLEEVE  
1 2FL; VALVE CAB LEVELING  
1 BK; TIRE CRAYON  
1 2FL; CLUSTER  
2 2FL; VALVE RAPID DUMP  
1 GRO; SWITCH BOOT  
1 GRO; SWITCH  
1 SVP; COMPRSOR  
1 TEM; FIL/DRY  
1 TEM; EXPANSION VALVE  
1 TWD; MEI  
1 9HC; HOSE AND FITTINGS

---

**Asset Work Order History 10167683**

**CSHOP-2020-1244**

Date Opened: 3-2-2020

Date Finished

4-28-2020

Meter 1 Reading:

185,094

**TASKS PERFORMED**

**Q PARTS**

CAB-INTERIOR ACCESSORIES

1 2FL; COVER HVAC  
3 2FL; SCREW

**CSHOP-2020-1731**

Date Opened: 3-27-2020

Date Finished

3-30-2020

Meter 1 Reading:

185,094

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SAFTEY-EMERGENCY EQUIPMENT

**CSHOP-2020-3020**

Date Opened: 6-8-2020

Date Finished

7-9-2020

Meter 1 Reading:

185,329

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
COMPARTMENT LIGHT BODY  
WIPER BLADES  
ENGINE AND ACCESSORIES  
SPOT LIGHTS  
ELECTRICAL  
TRANSMISSION  
POWER STEERING PUMP  
AIR DRIER  
STROBE LIGHTS  
AIR CONDITIONING

2 1AN; WIPER BLADE 24 IN  
1 2FL; GASKET  
1 8HD; TAPE GP DUCT  
1 9IP; DIAPHRAM SEAL  
3 WLD; BRASS WIRE BRUSH  
7 9IP; GROMET VALVE COVER  
1 2FL; CAP OIL  
1 2FL; GASKET  
1 2FL; COLLAR  
1 TWD; LIGHT  
1 9ME; VISTA V MUX DISPALY  
2 NCB; GEL ENGINE DEGREASER  
1 FIL; POWER STEERING FILTER  
-1 TWD; PURGE VALVE KIT  
1 TWD; PURGE VALVE KIT  
1 FIL; NAPAGOLD AIR FILTER  
1 TWD; TWD  
2 1WL; LIGHT LED RED TIR6  
1 1WL; TIER 2 STRAIGHT LED RED  
1 1WL; TIER 2 STRAIGHT LED RED  
1 1WL; TIR6 LIGHT CHROME BEZEL  
1 CRC; FOAMING COIL CLEANER  
1 SVP; EXPVLVE  
1 FIL; NAPA CABIN AIR FILTER  
1 TEM; EXPANSION VALVE

**Asset Work Order History 10167683**

**CSHOP-2020-3025**

Comments: **SPARE RESCUE AT 74**

Date Opened: 6-9-2020

Date Finished

6-11-2020

Meter 1 Reading:

185,094

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
WIPER BLADES

2 1AN; 22 WIPER BLADE

**Service Requests:**

06/09/2020

W/S WIPER / 12: BROKEN / REPAIR  
WIPERS BAD

**CSHOP-2020-3177**

Comments: **WE WILL GET THIS IN TO FINISH THE REPAIRS AND LUBE OIL AND FILTER AFTER R74 IS RETURNED**

Date Opened: 6-16-2020

Date Finished

7-9-2020

Meter 1 Reading:

185,329

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER  
20 4PC; 15W40 PREMIUM BLUE OIL  
1 FIL; FIL  
1 FIL; NAPA GOLD OIL FILTER  
1 FIL; NAPAGOLD FUEL FILTER

**CSHOP-2020-3209**

Date Opened: 6-18-2020

Date Finished

6-24-2020

Meter 1 Reading:

185,094

**TASKS PERFORMED**

**NO PARTS USED**

SUSPENSION  
AIR CONDITIONING

**CSHOP-2020-4299**

Date Opened: 8-19-2020

Date Finished

9-11-2020

Meter 1 Reading:

185,329

**TASKS PERFORMED**

**Q PARTS**

RADIATOR

1 2DD; CORE DAMAGED MISSING

**RADIO-2016-247**

Comments: **FOUND THE MDC DOCK REMOVED AND TILT BRACKET UNABLE TO TIGHTEN PROPERLY. ADJUSTMENT KNOB WAS JAMMED TIGHT AND COULD NOT BE REMOVED. REPLACED THE TILT BRACKET AND REMOUNTED THE DOCK.**

Date Opened: 4-27-2016

Date Finished

4-27-2016

Meter 1 Reading:

169,655

**TASKS PERFORMED**

**NO PARTS USED**

RADIO

**Service Requests:**

04/27/2016

RADIO / /  
MDC DOCK WAS REMOVED FROM THE PEDESTAL BY UNKNOWN PERSONS. NEEDS TO BE REMOUNTED.

**Asset Work Order History 10167683**

**RADIO-2018-622**

Comments: **REMOVAL 10141629, INSTALL 10204838 INTO SB7-R - 10167683**  
Date Opened: 6-11-2018      Date Finished      6-11-2018      Meter 1 Reading:      0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

---

06/11/2018      RADIO / /  
REMOVAL & INSTALL OF MOBILE RADIO INTO SPARE BATT7 RESCUE

---

**RADIO-2018-623**

Comments: **COMPLETED INSTALL ON ANOTHER TICKET**  
Date Opened: 6-11-2018      Date Finished      6-11-2018      Meter 1 Reading:      0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

---

06/04/2018      RADIO / /  
RADIO ISSUES/ RADIO INSIDE TRUCK BEEPS WHEN TRYING TO CALL DISPATCH AND WILL NOT TRANSMIT NOR RECEIVE / R74 `<[SCHEDULED INSTALL FOR FRIDAY 6/8 @ STATION 74]>`

---

**RADIO-2019-313**

Date Opened: 4-12-2019      Date Finished      4-12-2019      Meter 1 Reading:      0

**TASKS PERFORMED**

**NO PARTS USED**

RADIO

**Service Requests:**

---

04/12/2019      RADIO / /  
REPLACED SERIAL AND INTERFACE CABLE FROM FIRECOM BOX TO CENTER CONSOLE.

---

**RADIO-2019-450**

Comments: **HEADSET SYSTEM DISCONNECTED FROM RADIO**  
Date Opened: 5-28-2019      Date Finished      5-28-2019      Meter 1 Reading:      0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

---

05/22/2019      RADIO / /  
CHASING GREMLINS IN RADIO 10204838, IN SPARE BAT7 RESCUE

---