



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V131**

In Date: 10/07/2005  
Close Date: 10/13/2005

Meter Reading:

**Problem?**

FRONT A/C INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V284**

In Date: 10/18/2005  
Close Date: 11/02/2005

Meter Reading:

**Problem?**

MAP LIGHT CAME OFF MOUNTING, R-31

Task performed:

Parts

Quantity

LF18TS-LEDMAP LIGHT LED 18 IN

1

**Workorder: V418**

In Date: 11/02/2005  
Close Date: 11/03/2005

Meter Reading:

**Problem?**

AIR LEAK AT TANK, P/SIDE HEADLIGHT LOOSE, R-31

Task performed:

Parts

Quantity

800405PURGE VALVE KIT

1

**Workorder: V468**

In Date: 10/26/2005  
Close Date: 11/15/2005

Meter Reading:

**Problem?**

air leak-several lights out R31

Task performed:

Parts

Quantity

800034VALVE PARKING BRK.

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V709**

In Date: 11/28/2005

Meter Reading:

Close Date: 12/12/2005

**Problem?**

ELEC, FEDERAL Q NOT WORKING ON SIREN, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V760**

In Date: 12/01/2005

Meter Reading:

Close Date: 12/12/2005

**Problem?**

MIRROR ON R/SIDE BROKEN, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V1066**

In Date: 12/29/2005

Meter Reading:

Close Date: 12/29/2005

**Problem?**

AIR HORNS INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V978**

In Date: 12/20/2005

Meter Reading:

Close Date: 01/04/2006

**Problem?**

WINDOW HANDLE INOP, MARKER LIGHTS INOP, L/REAR DOME LIGHT INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1102**

In Date: 01/03/2006

Meter Reading:

Close Date: 01/11/2006

**Problem?**

R/SIDE HEADLIGHT NEEDS AJUSTMENT, CHECK FRONT TIRES, R-31

**Task performed:**

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V1171**

In Date: 01/11/2006

Meter Reading: 35,197.00

Close Date: 02/01/2006

**Problem?**

B INSPECTION R31

**Task performed:**

See B Inspection pre-printed form

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
322502BULB PATIENT GH22	3
52-24WIPER BLADES ANCO 24	2
58525852 COUPLING	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	4
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A0631088000CABLE BATT. NEG.	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
HLD3999GSS1715UV 30LB STRUT GAS	4
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	1
R90PFILTER FUEL 33231	1
SAHSVS2510STRAP	2
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V1622

In Date: 02/24/2006

Close Date: 03/06/2006

Meter Reading:

#### Problem?

A/C 10-7 R31

Task performed:

Parts

Quantity

203FFBEARING PULLEY

2

9425BELT MERCEDES RESCUE 12.5X1075 OE

1

### Workorder: V1665

In Date: 02/28/2006

Close Date: 03/27/2006

Meter Reading:

#### Problem?

L/FRONT HEADLIGHT INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1903**

In Date: 03/20/2006

Meter Reading: 39,307.00

Close Date: 04/11/2006

**Problem?**

B INSPECTION R31 OIL LEAK

**Task performed:**

See B Inspection pre-printed form

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	8
203FFBEARING PULLEY	2
322502BULB PATIENT GH22	1
3744BRAKE DRUM REAR	2
4864JBRALTERNATOR 270 A	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DDE-9061801210FILTER HOUSING	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Vendor?: CENT0002

**Workorder: V652**

In Date: 11/21/2005

Meter Reading:

Close Date: 05/11/2006

**Problem?**

repair stretcher on R31 ( medco equipt. repair ) replaced backrest spring cylinder \$ 219.46

**Task performed:**

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V931**

In Date: 12/14/2005

Meter Reading:

Close Date: 05/11/2006

**Problem?**

BOLT MISSING OUT OF F/PASS SIDE SEAT, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2470**

In Date: 05/03/2006

Meter Reading:

Close Date: 05/12/2006

**Problem?**

AIR PACK BRACKET BROKEN D/SIDE, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2634**

In Date: 05/16/2006

Meter Reading:

Close Date: 05/19/2006

**Problem?**

REAR 110V A/C INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2859**

In Date: 06/05/2006

Meter Reading:

Close Date: 06/14/2006

**Problem?**

SPOT LIGHT INOP, TURN SIGNALS INOP, PLASTIC HANDLE ON INSIDE DOOR INOP, CHECK STRETCHER, R-31

Task performed:

Parts

Quantity

HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V2875**

In Date: 06/06/2006

Meter Reading:

Close Date: 06/14/2006

**Problem?**

SIREN INOP, R-31

Task performed:

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT

1

**Workorder: V3185**

In Date: 06/28/2006

Meter Reading:

Close Date: 06/30/2006

**Problem?**

REPLACE CONVEX MIRROR R31

Task performed:

Parts

Quantity

980-412173 MIRROR 8 IN

1

**Workorder: V3290**

In Date: 07/05/2006

Meter Reading:

Close Date: 07/07/2006

**Problem?**

DOOR LATCH 10-7 R31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V3506**

In Date: 07/18/2006

Meter Reading:

Close Date: 07/21/2006

**Problem?**

110 AC 10-7 R31

Task performed:

Parts

Quantity

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3472**

In Date: 07/14/2006

Meter Reading:

Close Date: 07/25/2006

**Problem?**

SIDE DOOR STICKS, MED DRAWER IN PT COMPT INOP, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V3572**

In Date: 07/20/2006

Meter Reading:

Close Date: 07/27/2006

**Problem?**

CHECK TIRES, AND ROAD TEST FOR POOR RIDE R31

Task performed:

Parts

Quantity

161657700065489 SHOCK REAR NEW RESCUE

2

SA66613SHOCK FRONT RESC

2





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3711**

**In Date:** 07/31/2006

**Meter Reading:**

**Close Date:** 08/04/2006

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R31

**Task performed:**

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01068234000CTACTLD1 CONTROL PANEL TRAFFIC	1
032-0116549297 BATTERY INDICATOR	1
31-24WIPER BLADES	2
322502BULB PATIENT GH22	1
6806970098SEAL DOOR	2
6808300174VENT A/C RH	2
91513AMBER LENS	1
921LIGHT BULB	1
98003RREFLECTOR RED 40132 GROTE	3
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA8193AIR FILTER 46744 WIX	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

**Workorder: V3865**

**In Date:** 08/10/2006

**Meter Reading:**

**Close Date:** 08/10/2006

**Problem?**

UNIT WILL NOT START ON CALL R 31

**Task performed:**

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3895**

In Date: 08/14/2006

Meter Reading:

Close Date: 08/18/2006

**Problem?**

WILL NOT START, WIRE'S BURNT UP, R-31

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V3917**

In Date: 08/14/2006

Meter Reading:

Close Date: 08/22/2006

**Problem?**

TOW VEHICLE FROM GREENACRES STA-2 TO SHOP (SISTERS)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: SISTERS TOWING

**Workorder: V3939**

In Date: 08/15/2006

Meter Reading:

Close Date: 08/23/2006

**Problem?**

AIR IN FUEL SYSTEM /REAIR ELECTRICAL PROBLEM R31

Task performed:

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0000902051FILTER FUEL 03 MERCEDES 1

R90PFILTER FUEL 33231 1

**Workorder: V3767**

In Date: 08/03/2006

Meter Reading:

Close Date: 09/08/2006

**Problem?**

REPLACE TIRES AT CALLAGHAN R 31

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4473**

In Date: 09/18/2006

Meter Reading: 49,838.00

Close Date: 09/26/2006

**Problem?**

HOOD LATCH BROKEN R-31

**Task performed:**

Parts

Quantity

1. ON CALL GO TO STN 31 R/R HOOD LATCHES.

NO PARTS USED

**Workorder: V4905**

In Date: 10/16/2006

Meter Reading: 52,334.00

Close Date: 10/18/2006

**Problem?**

TRUCK WILL NOT START, R-31

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 31 FOR CALL OUT REPAIR. FOUND & TIGHTEN LOSE STARTER WIRING. TEST/ FAILED

190114036842 29MT 9 TOOTH STARTER

1

2. REPLACED STARTER & SOLENOID. TEST/ PASSED- VEHICLE NOW IN GOOD WORKING ORDER.

ESX120105112STARTER RELAY ESX-120-105112

1

**Workorder: V5388**

In Date: 11/14/2006

Meter Reading: 54,219.00

Close Date: 11/28/2006

**Problem?**

air horns not working properly. drivers side not functioning. R31

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 31. ADJUSTED AIR HORNS, TESTED/ OK.

NO PARTS USED

**Workorder: V5574**

In Date: 11/28/2006

Meter Reading: 55,171.00

Close Date: 12/01/2006

**Problem?**

REPLACE CONVEX MIRROR R31

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 31. ADJUSTED AIR HORNS.

980-412173 MIRROR 8 IN

1

2. REPLACED BULBS IN CHECK OUT LIGHT.



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5675**

**In Date:** 12/04/2006

**Meter Reading:** 56,264.00

**Close Date:** 12/04/2006

**Problem?**

REPAIR HEAD LIGHT R31

**Task performed:**

1. replace head light

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5724**

**In Date:** 12/07/2006

**Meter Reading:** 56,264.00

**Close Date:** 12/15/2006

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R 31**

**Task performed:**

1. PERFORM PM 'B' INSPECTION.
2. POWER STEERING SYSTEM SERVICE.
3. REMOVE WORN TIRES AND INSTALL NEW TIRES.
4. MARKER LIGHT & SIDE WORK LIGHT INOP. R/R LIGHTS.
5. DIAGNOSE LIGHT BAR SIDE LED FAILURE- FOUND FAILURE IN LIGHT BAR POWER PACK- BAD UNITE IS UNDER WARRANTY. REMOVE POWER PACK & INSTALL NEW POWER PACK.
6. LOAD TEST & SERVICE BATTERY.
7. CHECK FOR FAULT CODES ON BRAKING SYSTEM, ENGINE AND TRANI.
8. REAR A/C ULTRA VIOLET BULB BLOWN, R/R UV BULB.
9. REMOVE CLOGGED FILTER, BLEW OUT & CLEANED& REINSTALLED.
10. DOOR LOCK AND MOLDING REPLACED.
11. CAB BULKHEAD PADDING LOOSE- REMOVE CLEAN AND REINSTALL.
12. REMOVE WORN WIPER BLADES & INSTALL NEW ONES.
13. REAR END FRAIN RAIL BOLTS LOOSE- CHECK FOR CRACKS, NONE FOUND.
14. AIR LEAK, FIND AND REPAIRED.
15. DAMAGE L/R MUD FLAP, R/R MUD FLAP.
16. FRONT END VIBRATION, CHECK ALIGNMENT, ROAD TEST. R/R FRONT SHOCK AND ROAD TEST. NO MORE VIBRATIONS.
17. WATER IN FUEL LIGHT ON. CLEAN SENSOR DID NOT CORRECT FAULT. REMOVE & INSTALL NEW SENSOR IN GLASS BOWL. FAULT CORRECTED.
18. CAB ROOF JOINT OPEN. CLEAN IN SPECT & RESEAT WITH MARINE SEALANT.
19. CLEAN TOOLS, EQUIPMENT & WORK AREA.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
007985006541SCREW OBSOLETE	1
01-0269477-00BALLAST 4 CHANNEL LED LIGHTBAR 01-02	1
12105QUICK DRAIN	3
2436A432436A43 MUD FLAP 24X36	1
52-24WIPER BLADES ANCO 24	2
9EFLANGEFLANGE CHROME	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
SA66613SHOCK FRONT RESC	2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5747**

In Date: 12/08/2006      Meter Reading: 56,264.00  
Close Date: 12/21/2006

**Problem?**

REPLACE TIRES AT CALLAGHAN ENT

**Task performed:**

Parts

Quantity

1. Replaced tires at Callsghan Ent. R31

NO PARTS USED

Vendor?: CALLAGHAN ENT.

**Workorder: V6041**

In Date: 01/02/2007      Meter Reading: 57,681.00  
Close Date: 01/02/2007

**Problem?**

ON CALL R31 STUCK

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V6203**

In Date: 01/10/2007      Meter Reading: 5,295.00  
Close Date: 01/17/2007

**Problem?**

airpack bracket on officer side is broken and the airpack is loose. RE31

**Task performed:**

Parts

Quantity

1. Installed new air bottle holder

KD-UH-6-SHSCBA MOUNT 45 MIN

1

2. Adjusted all cab door latches

UH-6CYLINDER CLIPS

2

3. Repaired bad connection for roof mounted spot light

**Workorder: V6167**

In Date: 01/09/2007      Meter Reading: 5,295.00  
Close Date: 01/18/2007

**Problem?**

Passenger side, front seat, SCBA C-Clamp that holds the SCBA tank in place, on top, came loose and came off of the rack. Need to be replaced, SCBA not secure w/o it. R31

**Task performed:**

Parts

Quantity

1. WORK ORDER COMPLETED ON ANOTHER WORK ORDER.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6468**

In Date: 01/25/2007  
Close Date: 02/02/2007

Meter Reading: 5,441.00

**Problem?**

side door to box does not open from the inside. handle not operating lock.R31

**Task performed:**

1. Adjusted door linkage

Parts

Quantity

NO PARTS USED

**Workorder: V7340**

In Date: 03/23/2007  
Close Date: 03/26/2007

Meter Reading: 62,800.00

**Problem?**

COMP DORR 10-7 R31

**Task performed:**

Adjusted door linkage

Parts

Quantity

NO PARTS USED

**Workorder: V7786**

In Date: 04/18/2007  
Close Date: 04/24/2007

Meter Reading: 64,471.00

**Problem?**

install frame rail campain r31

**Task performed:**

1.install I sert per campain weld up cracks grind out bolt bolt holes that dont line up gind bottom of I sert hitting on frame web not flush

Parts

Quantity

25-SF350-000L-SERT REINFORCEMENT

1

**Workorder: V7737**

In Date: 04/16/2007  
Close Date: 04/26/2007

Meter Reading: 64,471.00

**Problem?**

on call alt braket and belt 10-7 r31

**Task performed:**

A/C belt missing, bracket broken; replaced belt/bracket;

Parts

Quantity

9425BELT MERCEDES RESCUE 12.5X1075 OE

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7795**

**In Date:** 04/18/2007

**Meter Reading:** 64,471.00

**Close Date:** 05/04/2007

**Problem?**

replace tires at callaghan ent r31

**Task performed:**

Replace tire

Parts

Quantity

NO PARTS USED

**Vendor?:** CALLAGHAN

---





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7759**

**In Date:** 04/16/2007

**Meter Reading:** 64,471.00

**Close Date:** 05/08/2007

**Problem?**

b inspection and repairs as needed r31

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### B-Inspection

1. R/R air dryer & rebuild unit
2. Work on cab door light ckt & ajar; fnd open wires in doors on cab; repair wiring
3. R/R door gaskets on cab; R/R door panels & front latches; adj strikers
4. R/R rear tires
5. R/R rear shocks
6. R/R wipers & marker light-repair wiring; R/R pat compt lights
7. R/R rear dump valves-adj height; test; readjust valves
8. R/R A/C filters & A/C vent pass side; R/R vac vent on side of truck in rear; R/R rear comp door shocks; tighten/replc msng door screws.
9. R/R med compt-door not the same; install new latch; redrill latches/hinges.
10. R/R water pump & T-stats; R/R/ rad cap; drainplug brkn off in rad.
11. R/R belts & A/C bearing; chkout A/C sys; fnd bad fan mtr; replc/retest unit & add freon

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1212BTURTLE TILE 12X12 BLACK	4
161657700065489 SHOCK REAR NEW RESCUE	2
16301BALL STUD	2
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
203FFBEARING PULLEY	1
23-09901-110HEX NUT 5/8	2
322502BULB PATIENT GH22	1
3530016HOSE HURST 16 ORANGE	2
373-1.5E-Z LOK BRACKET	2
52-24WIPER BLADES ANCO 24	2
5269LPVM-5 SM MOUNT	6
5C-91345C-9134 LOUVER	1
6806970098SEAL DOOR	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
C938-22AH7600-22 TRAY SLIDES 22 IN HD	1
CA8193AIR FILTER 46744 WIX	1
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE-9062030180GASKET SOCKET TO HEAD M2	2
DDE/R9062003701WATER PUMP SOME M2	1
DOOR5LEXAN 9 X 38 1/2 IN	2
EAA-8700-90ULIFT SUPPORT GSS6364UL 90LB	1
EXO3AH00015SPLUG RAD. DRAIN	1
FREIGHTSHIPPING CHARGES	1
HLD3999GSS1715UV 30LB STRUT GAS	7
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	1
KD-UN-6-SFBRACKET	4
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1
PAPCAXE COVER PLASTIC W/CHAIN	1
R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1
S4640024430VALVE LEVELIN	2
SS-25SC5025 SUCTION SCREEN	1
TH69LSSPREADER MOUNTING HURST	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

UMVS-0811-11STRAP ZICO	1
UMVS111611STRAP	1
UMVS254411STRAP 46 IN	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VML-T1413T3248 SIGHT GLASS	1

**Workorder: V8643**

In Date: 06/07/2007      Meter Reading: 66,920.00  
Close Date: 06/26/2007

**Problem?**  
REAR A/C 10-7 R31

Task performed:	Parts	Quantity
1. Cleaned condensor fans and recharged system and tested	NO PARTS USED	

**Workorder: V8508**

In Date: 05/31/2007      Meter Reading: 6,140.00  
Close Date: 06/28/2007

**Problem?**  
Passenger side rear scene light burnt out e31

Task performed:	Parts	Quantity
1. Found no light out	NO PARTS USED	
2. Repaired foam leak at foam filter		

**Workorder: V8935**

In Date: 06/20/2007      Meter Reading: 67,870.00  
Close Date: 07/02/2007

**Problem?**  
emer rd service callaghan ent r31

Task performed:	Parts	Quantity
1. emergency road service	NO PARTS USED	

Vendor?: CALLAGHAN TIRE



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9182**

In Date: 07/06/2007 Meter Reading: 68,968.00

Close Date: 07/06/2007

**Problem?**

REPLACE TWO TIRES AT STA 31

**Task performed:**

Replace (2) tires STN31 - Callaghan

**Parts**

NO PARTS USED

**Quantity**

Vendor?: CALLAGHAN

**Workorder: V9183**

In Date: 07/06/2007 Meter Reading: 68,968.00

Close Date: 07/18/2007

**Problem?**

auto eject innop R31

**Task performed:**

1. AUTO EJECT INOP- REMOVED AUTO EJECT AND INSTALLED NEW ONE.
2. ADJUSTED ALL AIR PACK BRACKETS IN ALL SEATS.
3. READJUSTED STRETCHER MOUNT THAT WAS NOT WORKING.

**Parts**

0915520120AUTO EJECT 20 AERO OTL3925

1

**Workorder: V9687**

In Date: 08/02/2007 Meter Reading: 70,573.00

Close Date: 08/07/2007

**Problem?**

rear round lights in the patient compartment are out. Appears to be the bulbs. R31

**Task performed:**

installed new bulbs in rear

**Parts**

322502BULB PATIENT GH22

4

**Workorder: V9742**

In Date: 08/06/2007 Meter Reading: 70,573.00

Close Date: 08/07/2007

**Problem?**

brake pedal low r31

**Task performed:**

road tested; fnd brake pedal loqw; adj free play in pedal

**Parts**

NO PARTS USED

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9996**

In Date: 08/20/2007      Meter Reading: 71,347.00  
Close Date: 08/31/2007

**Problem?**  
REAR LOAD LIGHTS INOP, R-31

Task performed:	Parts	Quantity
Traced out problem w/rear load ights; fnd bad connectin & rep	NO PARTS USED	

**Workorder: V10140**

In Date: 08/27/2007      Meter Reading: 6,669.10  
Close Date: 09/17/2007

**Problem?**  
Left speaker for the siren is not working r31

Task performed:	Parts	Quantity
1. Assist Tom; siren speaker & went to Stn31 2. installed new siren speaker	SD-210RXSIREN DRIVER SMALL	1

**Workorder: V10774**

In Date: 10/02/2007      Meter Reading: 74,034.00  
Close Date: 10/03/2007

**Problem?**  
REPAIR LEFT WINDOW R31

Task performed:	Parts	Quantity
1. REPLACED WINDOW CRANK 2. RECHARGED REAR A/C AND CLEANED CONDENSOR FANS	A1818557002HANDLE-WINDOW	1

**Workorder: V5241**

In Date: 11/06/2006      Meter Reading: 53,494.00  
Close Date: 10/15/2007

**Problem?**  
ON CALL DOOR OPEN LT ON R31

Task performed:	Parts	Quantity
1. REPLACE 4 PT LIGHT IN PT COMPARTMENT	91822OBSOLETE USE SERV TKS SWITCH - DOOR	2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V10978**

**In Date:** 10/12/2007

**Meter Reading:** 74,335.00

**Close Date:** 10/22/2007

**Problem?**

REAR A/C (110V) INOP, PT LIGHTS INOP, R-31

**Task performed:**

Parts

Quantity

NO PARTS USED

---



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11221**

**In Date:** 10/24/2007

**Meter Reading:** 75,538.00

**Close Date:** 11/09/2007

**Problem?**

b inspection and repairs as needed r31

**Task performed:**

1. Tavel to stn & PU truck
2. B-Inspection
3. Exh leak; ness to rem exh manifold & replc bolts, gaskets & manifold  
 10/25/07 5.0 hrs  
 10/26/07 2.0 hrs  
 11/1/07 2.5 hrs Total 9.5
4. trans svc, filter & fluids
5. A/C comp leaki ng oil; ness to R/R/ comp/dryer
6. R/R/ frnt/rear brake shoes & drums; adj
7. Replc outside window moldings & replc inside left moldings
8. Stretcher not locking; ness to R/R/ lock ass

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
07-0608A7160 DRIER A/C FRTLNR ABP-N83-319714	1
29526898 29548988 TRANS FILTER ALLISON	1
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
4412S08-6963BS FITTING A/C	1
4909SCUT AND FAB FITTING	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 DRYER	1
6737200054673-720-00-54 SEAL WINDOW	4
6807200253GUIDE METAL	1
6809870055SEAL CAB WINDOW	1
6809880678STUD DZ	2
6809940145CLIP	2
72R311018-2640 VENT A/C NEW # 1719	1
9061420057SEAL RING EXHAUST MANIFOLD	2
9061421101EXHAUST MANIFOLD CENTER	1
9061421201EXHAUST MANIFOLD R/L	2
A04-19184-000620-997-05-90 TURBO CLAMP M2	1
A1834388002MOLD L/H	2
A22309300011490 A/C SWITCH	1
ABPN833181091512 SWITCH A/C 22-36474	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA8193AIR FILTER 46744 WIX	1
DDE/9049900412EXHAUST BOLTS	24
DDE/9061420280USE A9261420080 EXHAUST MANIFOLD (	3
DOOR5LEXAN 9 X 38 1/2 IN	1
HP-31DBATTERY 950CCA HP-31D	4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RES	2
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
WKL7281LIGHT THINLINE	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
78R536078R5360M 2PK FILTER AIR COND	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V10979**

In Date: 10/12/2007

Meter Reading: 74,335.00

Close Date: 11/26/2007

**Problem?**

REPLACE REAR OUTER TIRE D/SIDE R-31 (CALLAGHAN)

**Task performed:**

Replc rear outer tire D/Side R31 - Callaghan

j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

**Workorder: V11311**

In Date: 10/29/2007

Meter Reading: 75,538.00

Close Date: 11/26/2007

**Problem?**

repair L/R outer tire R31 (outside agency-callaghan tire)

**Task performed:**

Repair L/R outer tire R31 - Callaghan

j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

**Workorder: V11536**

In Date: 11/09/2007

Meter Reading: 7,051.00

Close Date: 12/06/2007

**Problem?**

Rear scene light out. r31

**Task performed:**

1. Replaced bulb in rear scene light.

Parts

35753EXHAUST CLAMP 3 1/2

42449DOWNSPOUT EXHAUST

H35DSN12BULB 35W DUAL FILAMENT DOME

H35SN12BULB

Quantity

1

1

2

2

**Workorder: V11823**

In Date: 11/30/2007

Meter Reading: 76,514.00

Close Date: 12/06/2007

**Problem?**

repair seat r31

**Task performed:**

1. Right side air seat Inop. Replaired broken air line.

Parts

NO PARTS USED

Quantity





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6477**

In Date: 01/26/2007  
Close Date: 12/10/2007

Meter Reading: 59,165.00

**Problem?**

COMP OPEN WARNING LT STAYING ON R31

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V12212**

In Date: 12/24/2007  
Close Date: 01/04/2008

Meter Reading: 73,947.00

**Problem?**

Lt. seat in front cab unable to hold air pressure causing it to sit very low

**Task performed:**

Parts

Quantity

1. Repaired supply hose that was leaking causing seat to come down.
2. Coolent leak, repaired coolent leak.

NO PARTS USED

**Workorder: V6466**

In Date: 01/25/2007  
Close Date: 01/08/2008

Meter Reading: 5,441.00

**Problem?**

interior cab lights do not come on when doors open. R31

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V7299**

In Date: 03/21/2007  
Close Date: 01/14/2008

Meter Reading: 5,789.00

**Problem?**

The lightbox in R31 does not light. Indicator light is working. Buld might be byrnt out.

**Task performed:**

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V12560**

In Date: 01/14/2008

Meter Reading: 80,019.00

Close Date: 01/18/2008

**Problem?**

BIOHAZARD COMP 10-7 R34

**Task performed:**

Parts

Quantity

1. Replaced med drawer slides.

NO PARTS USED

**Workorder: V12312**

In Date: 01/02/2008

Meter Reading: 7,444.50

Close Date: 01/24/2008

**Problem?**

The brake pressure does occur until the brake pedal is half way to the floor then the truck stops abruptly. r31

**Task performed:**

Parts

Quantity

1. Road tested truck found when brakes applied truck nose dives. Adjust all brakes and tested again.

NO PARTS USED

**Workorder: V12580**

In Date: 01/14/2008

Meter Reading: 80,019.00

Close Date: 02/04/2008

**Problem?**

repair patient lights

**Task performed:**

Parts

Quantity

Replc bad buls in patient compt. j

LB-D30BULB QUARTZ HAL. 12V 150W

1

**Workorder: V2306**

In Date: 04/20/2006

Meter Reading:

Close Date: 02/07/2008

**Problem?**

REAR 110V A/C INOP, R-31

**Task performed:**

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V2776**

In Date: 05/26/2006

Meter Reading:

Close Date: 02/07/2008

**Problem?**

DRIVER SEAT BELT BROKEN, R-31

**Task performed:**

Parts

Quantity

IMMF11358SEAT BELTS

1

**Workorder: V3449**

In Date: 07/13/2006

Meter Reading:

Close Date: 02/07/2008

**Problem?**

PATIENT COMP DOOR STICKING MED DRAWER TRACKS 10-7

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V13507**

In Date: 02/26/2008

Meter Reading: 7,717.50

Close Date: 03/04/2008

**Problem?**

the side door in the pt. compartment will not open from the inside R34

**Task performed:**

Parts

Quantity

1. readjusted door linkage
2. turn signal inop, found bad connection at steering.
3. rear a/c warm, clean condencer fan and retesred.

NO PARTS USED

**Workorder: V13801**

In Date: 03/11/2008

Meter Reading: 83,346.00

Close Date: 03/19/2008

**Problem?**

POWER STEERING 10-7 R34

**Task performed:**

Parts

Quantity

1. Rear step, installed new fold down rear step

MFG9980B351262 FOLDING STEP 45.25

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V13882**

In Date: 03/13/2008

Meter Reading: 7,707.00

Close Date: 03/26/2008

**Problem?**

driver's side inside tire flat, passenger side outside tire low. r34 callaghan

**Task performed:**

Parts

Quantity

Driver's side inside tire flat; passenger side outside tire low; R34 - Callghan  
j

NO PARTS USED

Vendor?: CALLGHAN

**Workorder: V14174**

In Date: 03/31/2008

Meter Reading: 84,984.00

Close Date: 03/31/2008

**Problem?**

on call patient a/c 10-7 r34

**Task performed:**

Parts

Quantity

No A/C; cleaned condensor fans & recharged unit.  
j

NO PARTS USED

**Workorder: V14279**

In Date: 04/04/2008

Meter Reading: 84,984.00

Close Date: 04/10/2008

**Problem?**

CHECK TIRES R34

**Task performed:**

Parts

Quantity

vehicle needed all 6 tires replaced. performed work @ callaghan tire

NO PARTS USED

**Workorder: V14257**

In Date: 04/03/2008

Meter Reading: 7,786.90

Close Date: 04/18/2008

**Problem?**

R34 .Rear Tires has low tread pattern Replace all 6 tires (outside agency- Callaghan tire)

**Task performed:**

Parts

Quantity

Rear tires has low tread pattern; replc all (6) tires - Callaghan  
j

NO PARTS USED

Vendor?: CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14520**

In Date: 04/17/2008

Meter Reading: 85,730.00

Close Date: 04/22/2008

**Problem?**

SPOTLIGHT R-34

**Task performed:**

1. repaired broken wire on spot light.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V14737**

In Date: 04/28/2008

Meter Reading: 86,397.00

Close Date: 05/09/2008

**Problem?**

B inspection and repairs as needed r34

**Task performed:**

- B-Inspection - Costner
- 2. Svc air dryer
- 3. R/R batry charger LED indicator
- 4. R/R halogen tool bracket
- 5. Tighten/lube all loose door holdopns.
- 6. Replc upper box marker lights
- 7. B-Inspection - Vasko
- 8. R/R inside door trim & handle rear pat compt.
- 9. R/R compt light bulbs(4).
- 10. Adj doors on L1/R1 compt; water leaking in.
- 11. R/R 110V A/C unit
- 12. R/R/ air compressor-leaking oil.

**Parts**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

032-0116549297 BATTERY INDICATOR 1

06343136400-RING COMPRESSOR 1

107796DRYER KIT AD9 -NEW 1

107800VALVE CHECK AD9 1

15W40BSYN OIL BULK QTS 24

52-24WIPER BLADES ANCO 24 2

5269LPVM-5 SM MOUNT 1

78R536078R5360M 2PK FILTER AIR COND 1

800405PURGE VALVE KIT 1

A9062030702A9062037302 COMPRESSOR LINE 1

AEVDOOR LOCK BEZEL 1

CLR9185209186-1500-20 MARKER LT.AMBER LED 2

DDE/A9061800720TURBO OIL LINE 1

FREIGHTSHIPPING CHARGES 2

N007603014104WASHER SEAL 4

R90PFILTER FUEL 33231 1

RA9061303015COMPRESSOR 1

RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL 1

UNT7744USE PINK A/C FILTER MEDIC MASTER 1

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V15032

In Date: 05/12/2008

Meter Reading: 86,967.00

Close Date: 05/13/2008

#### Problem?

water leaking from the light fixtures in the pt compartment on R34.

#### Task performed:

1. roof a/c drain/broken/repaired drain
2. patient comp lights inop/bulb/installed new.

#### Parts

322502BULB PATIENT GH22

#### Quantity

1

### Workorder: V15264

In Date: 05/22/2008

Meter Reading: 87,406.00

Close Date: 06/06/2008

#### Problem?

repair comp door r34

#### Task performed:

1. Drive to Stn; adjusted walk in door side; test ok. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V14983

In Date: 05/10/2008

Meter Reading: 7,902.10

Close Date: 06/17/2008

#### Problem?

left side rear window will nor roll up when crnked with handle R-34

#### Task performed:

1. drive to station. r/r handle, tested ok

#### Parts

508RED58EC20RU STROBE-RED SURFACE MOUNT

A1818557002HANDLE-WINDOW

#### Quantity

1

1

### Workorder: V15098

In Date: 05/14/2008

Meter Reading: 8,017.20

Close Date: 06/17/2008

#### Problem?

The traffic advisor lights do not work in the high mode, and there is no switch to change lights from left, right, center, or scatter. The tv monitor isn't very bright during the daylight hours, may need a new monitor. R-34

#### Task performed:

1. drive to sta. replaced control box.

#### Parts

01068234000CTACTLD1 CONTROL PANEL TRAFFIC

#### Quantity

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V15439

In Date: 06/02/2008

Meter Reading: 7,976.60

Close Date: 07/01/2008

#### Problem?

rear passenger window is broken, it will roll down but it slips when roll it up. R34

#### Task performed:

1. replaced window crank.

#### Parts

A1818557002HANDLE-WINDOW

#### Quantity

2

### Workorder: V15225

In Date: 05/20/2008

Meter Reading: 7,937.00

Close Date: 07/02/2008

#### Problem?

CO alarm in the pt compartment of Rescue 34, alarm sounding

#### Task performed:

1. A/C unit; recharged A/C unit & tested.
2. Rep backup monitor; replc monitor & tested.
3. 110 outlet plug inop; replc outlet plug. j

#### Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

MNT587148Z671 ALARM CARBON MONOXIDE

#### Quantity

1

1

### Workorder: V15941

In Date: 06/24/2008

Meter Reading: 88,972.00

Close Date: 07/09/2008

#### Problem?

PARTS ONLY OIL FOR STA 34

#### Task performed:

Parts only; no labor. j

#### Parts

15W40QSYN OIL QT

#### Quantity

12

### Workorder: V15961

In Date: 06/24/2008

Meter Reading: 8,050.70

Close Date: 07/16/2008

#### Problem?

back up monitor screen malfunctioning 06-24-2008 20:39 JF R34

#### Task performed:

Replaced LCD monitor with repaired on. j

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V16160

In Date: 07/04/2008

Meter Reading: 8,085.30

Close Date: 07/18/2008

#### Problem?

flashing red emergency lights on the front grill of the rescue 34 not working

#### Task performed:

#### Parts

#### Quantity

1. Traced out problem with front lights; fnd bad connection on compt - pin 32.

NO PARTS USED

2. Rear A/C blowing warm/ recharged A/C unit. j

### Workorder: V16190

In Date: 07/07/2008

Meter Reading: 8,085.30

Close Date: 07/18/2008

#### Problem?

TURN SIGNALS NOT OPERATING r19

#### Task performed:

#### Parts

#### Quantity

drive to Stn; plug came out; hook in; test ok. j

NO PARTS USED

### Workorder: V17252

In Date: 08/22/2008

Meter Reading: 92,108.00

Close Date: 08/25/2008

#### Problem?

repair air leak r34

#### Task performed:

#### Parts

#### Quantity

Pull apart dash; fnd Humphrey valve leaking; replace valve. j

SU68088VALVE DUMP 310 HUMPHREY

1

### Workorder: V17444

In Date: 09/02/2008

Meter Reading: 92,427.00

Close Date: 09/19/2008

#### Problem?

REPAIR AIR LEAK R34 ON CALL

#### Task performed:

#### Parts

#### Quantity

purge valve leaking; replc purge valve. j

800405PURGE VALVE KIT

1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V17612**

In Date: 09/10/2008

Meter Reading: 92,872.70

Close Date: 09/29/2008

**Problem?**

REAR DOOR WONT OPEN R34

**Task performed:**

Parts

Quantity

Disassemble door and adjust door linkage.  
Back-up camera inoperable, traced problem and found bad connection.  
O2 Leak - Repaired leak at main bottle.

NO PARTS USED

**Workorder: V15060**

In Date: 05/13/2008

Meter Reading: 7,916.80

Close Date: 10/20/2008

**Problem?**

left rear window of passenger compt. window roll-up handle messed up. also need sm. dry chem ext. R34

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V15440**

In Date: 06/02/2008

Meter Reading: 7,976.60

Close Date: 10/20/2008

**Problem?**

I pretty sure the monitor is going bad. No matter how you adjust the color or brightness it still hard to see/use. Maybe the plastic hood is needed. R34

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V18364**

In Date: 10/16/2008

Meter Reading: 135.70

Close Date: 10/28/2008

**Problem?**

Engine coolant is leaking from the looking glass on the reseviior. r34

**Task performed:**

Parts

Quantity

Coolant leak; replcd coolant level glass. j

SPR-W58-1TEE PLASTIC

2

VML-T1413T3248 SIGHT GLASS

2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18365**

In Date: 10/16/2008

Meter Reading: 135.70

Close Date: 10/28/2008

**Problem?**

Plexi-glass sliders on cabinet doors extremely hard to move/slide. Needs lubrication. r34

**Task performed:**

Parts

Quantity

Cleaned & greased glass doors to slide. j

NO PARTS USED

**Workorder: V18407**

In Date: 10/18/2008

Meter Reading: 146.70

Close Date: 10/30/2008

**Problem?**

RESCUE 34 AIR FILTER MINDER IS BROKEN AND NEED TO BE REPLACED

**Task performed:**

Parts

Quantity

1. Replaced filter minder that was broken.
2. Coolant leak; replc sight glass on coolant tank.
3. O2 leak; rep fitting on O2 bottle. j

22-51374-000SENSOR AIR RESTRICTION

1

**Workorder: V18715**

In Date: 10/30/2008

Meter Reading: 94,724.00

Close Date: 11/07/2008

**Problem?**

AIR HORNS INOP, R-34

**Task performed:**

Parts

Quantity

Adjusted air horns. j

NO PARTS USED

**Workorder: V18959**

In Date: 11/10/2008

Meter Reading: 95,174.20

Close Date: 11/14/2008

**Problem?**

DOOR ALARM GOING OFF E 18 ON CALL

**Task performed:**

Parts

Quantity

drive to stn; look for short disconnected alarm, not light; will get drawing at shop. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18862**

In Date: 11/04/2008

Meter Reading: 8,550.70

Close Date: 11/18/2008

**Problem?**

R34 fusepanel is broken on the passengers side R34

**Task performed:**

Replaced fuel panel. j

Parts

Quantity

6806870807COVER FUSE PANEL

1

6809881078DZ STUD

2

6809940145CLIP

2

**Workorder: V19071**

In Date: 11/14/2008

Meter Reading: 95,500.90

Close Date: 11/20/2008

**Problem?**

check brakes r34

**Task performed:**

Drive to Stn; chk brakes front 80%; rear 70%. j

Parts

Quantity

NO PARTS USED

**Workorder: V19588**

In Date: 12/08/2008

Meter Reading: 94,981.60

Close Date: 12/15/2008

**Problem?**

a/c 10-7 r34

**Task performed:**

1-A/C inop, found no power to relay. rewired relay and tested.

2-Replaced SL-40 handlight charger.

Parts

Quantity

NO PARTS USED

**Workorder: V19709**

In Date: 12/12/2008

Meter Reading: 35.30

Close Date: 01/05/2009

**Problem?**

The a/c system in back of rig (Pt. area) has been cutting on and off. When the truck is plugged in at the station it is fine. It seems once the emergency lights are off the back a/c shuts off. R-34

**Task performed:**

Rear tail lights out; replcd rear LED light. j

Parts

Quantity

53962OVAL LED LIGHT TAIL TURN.

2

66815WIRE HARNESS FOR LED

2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19710**

In Date: 12/12/2008  
Close Date: 01/05/2009

Meter Reading: 35.30

**Problem?**

The new upholstery is nice in R34. The front passenger seat does not raise. There seems to be no air pressure to raise the seat. Thanks RLT. Frisbie

**Task performed:**

Rep air line for seat. j

Parts

Quantity

NO PARTS USED

**Workorder: V19881**

In Date: 12/21/2008  
Close Date: 01/06/2009

Meter Reading: 8,557.30

**Problem?**

R34 fuel gauge dash background light is out

**Task performed:**

Replcd bulb in fuel gauge. j

Parts

Quantity

6808260099BULB

5

AMAY101506DASH BULB

5



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19134**

**In Date:** 11/18/2008

**Meter Reading:** 95,883.00

**Close Date:** 01/09/2009

**Problem?**

**C INSPECTION AND REPAIRS AS NEEDED R34**

### Task performed:

- 1. C-Service
- 2. R/R door latches, both front doors.
- 3. R/R all (4) door rubber.
- 4. R/R svc P/S filter.
- 5. R/R air filter.
- 6. Replcd lug cover.
- 7. Replc left rear whee inflater.
- 8. Svc diff fluid.
- 9. R/R both wiperblades.
- 10. Replc air line R-front seal.
- 11. R/R drove btry on end.
- 12. R/R door latch cover.
- 13. R/R UV light in rear A/C unit.
- 14. Replc draw roller rear compt.
- 15. R/R flourescent light rear.
- 16. Paint fuel cap.
- 17. R/R A/C filters.
- 18. R/R rear door rubber seal.
- 19. Cln door swtch for light going on/off.
- 20. Installed new heater control cable.
- 21. Rem fuel pump off frnt of eng.
- 22. R/R light in A/C cotrol panel.
- 23. Replcd new fuel pump on eng.
- 24. Rep plackers on rear of truck.
- 25. Replc volume knob on radio.
- 26. Installed both frnt seat back in trk.
- 27. Installed (2) new A/C fan on condensor.
- 28. C/O if node #3 code was gone; chk to see if A/C shutoff; ok at this time. j

### Parts

### Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	3
00009247080000925208 FILTER HEAD CAP NEW NUMBER	1
0127110042BELT MERCEDES MOTORS	1
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
22-49905-000CABLE HEATER	1
52-24WIPER BLADES ANCO 24	2
60027FAN A/C COND 12IN 860026-2-W	2
6806890001LOCK DASH	3
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
ACX-84534LUG NUT COVER PK10	4
AEVDOOR LOCK BEZEL	2
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
SLD5362USE 12 IN DRAWER SLIDE 10 IN	2
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
DDE-R0040910501FUEL PUMP M2	1
9060910580FUEL PUMP GASKET M2	1
CORECORE CHARGE	1

**Workorder: V19466**

**In Date:** 12/02/2008

**Meter Reading:** 85,069.00

**Close Date:** 01/14/2009

**Problem?**

**REPAIR STRETCHER R34**

### Task performed:

Repair stretcher R34 - Medco j

### Parts

### Quantity

NO PARTS USED

**Vendor?:** MEDCO



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20263**

In Date: 01/09/2009

Meter Reading: 8,785.60

Close Date: 01/26/2009

**Problem?**

airhorn not working properly..., air leaks on the air system. r34

**Task performed:**

Parts

Quantity

1- drive to training and adjusted air horn, tested ok. training is using the truck will have to look for air leaks later.

NO PARTS USED

2- checked for air leaks found none at this time.

**Workorder: V20532**

In Date: 01/22/2009

Meter Reading: 98,681.00

Close Date: 02/11/2009

**Problem?**

Rear door latch 10-7 R34 (on-call)

**Task performed:**

Parts

Quantity

1- Call out to repair rear door, working rear latch broken off, installed new one.

HND5948TM22676-02 HANDLE DOOR ENTRY

1

**Workorder: V21007**

In Date: 02/10/2009

Meter Reading: 99,574.20

Close Date: 02/23/2009

**Problem?**

REAR PT. COMPT. LIGHTS INOP, R-34

**Task performed:**

Parts

Quantity

No light in rear; fnd bad ground & rep. j

NO PARTS USED

**Workorder: V21038**

In Date: 02/11/2009

Meter Reading: 99,574.20

Close Date: 02/25/2009

**Problem?**

repair spot light r34

**Task performed:**

Parts

Quantity

Installed new controller for spotlight. j

21481SEARCHLIGHT CONTROL

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V17520**

In Date: 09/05/2008  
Close Date: 03/02/2009

Meter Reading: 8,294.30

**Problem?**

rear door of pt cab is vrey hard to open from the inside.

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V18699**

In Date: 10/29/2008  
Close Date: 03/02/2009

Meter Reading: 8,550.70

**Problem?**

officer side air horn not functioning... R-34

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V19295**

In Date: 11/24/2008  
Close Date: 03/04/2009

Meter Reading: 85,069.00

**Problem?**

REPAIR FLAT AT SHOP E18

**Task performed:**

Parts

Quantity

Repair flat at shop E18 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V21348**

In Date: 02/26/2009  
Close Date: 03/06/2009

Meter Reading: 99,906.90

**Problem?**

check brakes / repair spot light r34

**Task performed:**

Parts

Quantity

1. Truck stopping too hard; readj brakes & road tested.
2. Roof spotlight; replcd roof spotlight controller.
3. Rear A/C warm; recharged unit. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V21820**

In Date: 03/16/2009

Meter Reading: 101,426.50

Close Date: 03/23/2009

**Problem?**

rear door 10-7 r34

**Task performed:**

1. Pat light out; replcd pat lights.
2. Rear door hard to open; adj rear door linkage. j

**Parts**

**Quantity**

322502BULB PATIENT GH22

3

**Workorder: V22332**

In Date: 04/06/2009

Meter Reading: 102,449.60

Close Date: 04/17/2009

**Problem?**

REPLACE FUEL FILTERS R34

**Task performed:**

- Replcd fuel filter for bad fuel. j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0000902051FILTER FUEL 03 MERCEDES

1

R90PFILTER FUEL 33231

1

RK211131311FUEL BOWL KIT NON-HEATED

1

**Workorder: V22466**

In Date: 04/11/2009

Meter Reading: 5,963.00

Close Date: 04/29/2009

**Problem?**

R34, power cord ejector does not eject cord when truck is started. Truck must then started in override and plug removed by hand. jsilbert r34

**Task performed:**

1. Auto-eject plug inop; replc unit.
2. Rear back-up camera inop; fnd bad connection.
3. Air leak; chkd for air leaks & rep.
4. A/C fan making noise; readj brkt. j

**Parts**

**Quantity**

0915520120AUTO EJECT 20 AERO OTL3925

1





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22855**

**In Date:** 04/28/2009

**Meter Reading:** 103,454.70

**Close Date:** 05/07/2009

**Problem?**

B inspection and related repairs R34

**Task performed:**

1. Went to PU truck; truck not ready; returned to shop; went back & PU truck.
2. B-Inspection.
3. Replc btry; R/R (4) btrys; had to get btry from S. truck; restocked svc truck when btrys were restocked.
4. Ck alt output at alt & alt btry; ck ok; ck all connections; ck ok; ck voltage drops on cables; ck ok.
5. Ck 110V A/C; rem cover; rep air chute; plugged in & ran unit; ck ok.
6. Rep L-side compt door support; fnd holes stripped out of side mnt; drilled/installed new bolts & nut certs; tightened all catch latches; ck ok.
7. No cab A/C or blower; ck all fuses brkrs & relays; T-shoot bad blower swtch; needs swtch.
8. Ck alignment; ck toe alignment; ck ok.
9. R/R frnt turn signal side lenses & bulb; ck ok.
10. R/R 911 decals.
11. R/R btry swtch.
12. R/R step grip tape.
13. R/R blower swtch.
14. Rem & reinstall rear window moldings.
15. Rem P/S return line; trim/reinstall.
16. C/O reverse lights; NPF at this time. j

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1500900017000USE 9 X 14 FILTER	1
15W40BSYN OIL BULK QTS	24
194BULB	3
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6804660102POWER STEERING HOUSING	1
75908SWITCH BATTERY MASTER 300A	1
91513AMBER LENS	2
ABPN8332229011-3050 SWITCH BLOWER	1
R90PFILTER FUEL 33231	1
HP-31DBATTERY 950CCA HP-31D	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4

**Workorder: V23237**

**In Date:** 05/12/2009

**Meter Reading:** 103,954.40

**Close Date:** 05/12/2009

**Problem?**

REPAIR STRETCHER R34 EMSAR

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Vendor?:** MEDCO



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V23002**

In Date: 05/04/2009

Meter Reading: 103,454.70

Close Date: 05/14/2009

**Problem?**

repair charging system r34

**Task performed:**

Rem parts to gain access to rem/install new alt; ressemble & operate charging sys; chk sys; sys operating at normal range; charging at 13.9 full load. j

Parts

Quantity

1504046PS SIGHT GLASS WPB

2

1504052SIGHT GLASS ORING WPB

2

4867JB320 UPGRADE ALTERNATOR

1

**Workorder: V23008**

In Date: 05/04/2009

Meter Reading: 103,454.70

Close Date: 05/14/2009

**Problem?**

on call r 34 low voltge alarm going off

**Task performed:**

C/O truck low voltage alarm going off; switch out-truck bad alt; VC/O unit; not serviceable on road. j

Parts

Quantity

NO PARTS USED

**Workorder: V23427**

In Date: 05/21/2009

Meter Reading: 104,243.60

Close Date: 06/02/2009

**Problem?**

water leak in cab r34

**Task performed:**

Resealed top of roof for water leak. j

Parts

Quantity

NO PARTS USED

**Workorder: V23682**

In Date: 06/01/2009

Meter Reading: 104,701.20

Close Date: 06/02/2009

**Problem?**

ON CALL R34 AIR LEAK

**Task performed:**

Chkd for air leak & fnd no air leak at this time; road tested & tested ok. j

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V23691**

In Date: 06/01/2009  
Close Date: 06/04/2009

Meter Reading: 104,701.20

**Problem?**

tow unit from 34 to shop

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: SISTERS

**Workorder: V22935**

In Date: 04/30/2009  
Close Date: 06/05/2009

Meter Reading: 103,454.70

**Problem?**

replace all 6 tires R34 (outside agency-callaghan tire)

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V23692**

In Date: 06/01/2009  
Close Date: 06/16/2009

Meter Reading: 104,701.20

**Problem?**

on call air leak r34

**Task performed:**

Parts

Quantity

C/O air leak; fnd air line to dryer w/hole in hose; replc hose & take truck out of svc. Truck coming to shop-no brake on rear. j

NO PARTS USED

**Workorder: V23705**

In Date: 06/01/2009  
Close Date: 06/24/2009

Meter Reading: 104,701.20

**Problem?**

repair brakes r34

**Task performed:**

Parts

Quantity

1. Lift veh & chk condition of rear brakes; set up on stands & replc shoes, drums & spring kits; chk seals for leakage; none at this time; chk anti-lock wheel sensors; free up; all seems ok at this time.
2. Rem old blown out air hose line frm under chassis; rem temporary hose used for j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V24385

In Date: 06/26/2009

Meter Reading: 105,771.20

Close Date: 07/06/2009

#### Problem?

Open door alarm not turning off. States that "passenger door ajar". R34

#### Task performed:

Parts

Quantity

1. Door open light on; rep door switch.
2. A/C warm; recharged sys.
3. Aut-eject inop; rep 110 connection. j

NO PARTS USED

### Workorder: V24766

In Date: 07/14/2009

Meter Reading: 8,961.90

Close Date: 07/28/2009

#### Problem?

Shore line plug is bad. It sparks when you try to plug in the shore line. r36

#### Task performed:

Parts

Quantity

1. 110 outlet shorting out; replcd power cord.
2. A/C recharged.
3. Rear pat lights out; fnd bad grnd. j

NO PARTS USED

### Workorder: V24710

In Date: 07/12/2009

Meter Reading: 8,950.20

Close Date: 07/29/2009

#### Problem?

Air condition in the cab not blowing. Front controls are not working at all and back seat is just blowing air. R34

#### Task performed:

Parts

Quantity

1. Chkd rear A/C & recharged unit & tested.
2. A/C controls inop; rep frnt controls. j

NO PARTS USED

### Workorder: V25022

In Date: 07/23/2009

Meter Reading: 898.00

Close Date: 08/05/2009

#### Problem?

The air conditioner in the patient compartment is not blowing cold air. The air in the cab is working fine. R-34

#### Task performed:

Parts

Quantity

- A/C inop; A/C condensor fans inop; rep connection. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V25270

In Date: 08/04/2009

Meter Reading: 107,857.10

Close Date: 08/24/2009

#### Problem?

A/C INOP, R-34

#### Task performed:

A/C inop; rep bad connection on switch. j

Parts

Quantity

NO PARTS USED

### Workorder: V25956

In Date: 09/01/2009

Meter Reading: 9,101.50

Close Date: 09/21/2009

#### Problem?

spot light spining without being prompted r34

#### Task performed:

Went to Stn34; rem spot light control switch; fnd switch asy apart; reassembled wires, connectors & switch asy; ck opn-ck ok; installed swtch; returned to shop. j

Parts

Quantity

NO PARTS USED

### Workorder: V26066

In Date: 09/05/2009

Meter Reading: 108,918.90

Close Date: 09/21/2009

#### Problem?

on call winch out unit r34

#### Task performed:

Winch out R34. j

Parts

Quantity

NO PARTS USED

### Workorder: V26128

In Date: 09/09/2009

Meter Reading: 108,918.90

Close Date: 10/02/2009

#### Problem?

RADIO SPEAKER FALLING OFF R34

#### Task performed:

1. Rep speaker that was falling off.
2. Shoreline inop; rep auto-eject plug.
3. Brakes not stopping; readj brakes. j

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V26835**

In Date: 10/13/2009

Meter Reading: 111,419.40

Close Date: 10/26/2009

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R34

**Task performed:**

1. C-Inspection
2. R/R air dryer & purge valve.
3. Reinstall R/R upper panel in cab.
4. Chk/recharge frnt/rear A/C sys.
5. Replc bench seat shocks; tighten brkts.
6. Quality control chk of truck.
7. Chk for air leaks; R/R D2 gov.
8. R/R driver/pass upper door moldings.
9. T-shoot; R/R door light inop; replc pin switch; rep wire in door.
10. Tighten/adj tracks for rear jumpseat draw; reinstall latch.
11. R/R eng belts.
12. R/R rear medical decals.
13. Tighten/adj all compt doorhinges/latches.
14. Remount L-3 door hinges.
15. R/R steering wheel.
16. Drifts to right; adj frnt brakes; swap frnt wheels. j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	28
194BULB	1
284358GOVERNOR D-2	1
322502BULB PATIENT GH22	1
800405PURGE VALVE KIT	1
91823SWITCH SWT5499 MED MASTER	2
921LIGHT BULB	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	4
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
ACX-84534LUG NUT COVER PK10	2
CA8193AIR FILTER 46744 WIX	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
R90PFILTER FUEL 33231	1
6804640001NEW# 3184640001 STEERING WHEEL	1

**Workorder: V26350**

In Date: 09/21/2009

Meter Reading: 101,226.10

Close Date: 11/06/2009

**Problem?**

REPAIR REAR A/C R34

**Task performed:**

1. Recharged rear A/C that was not cooling.
2. Rear door not opening; rep latch. j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V27382**

In Date: 11/03/2009

Meter Reading: 101,985.80

Close Date: 12/09/2009

**Problem?**

AIR DUMP 10-7 R34

**Task performed:**

- 1. Siren inop; rep bad grnd.
- 2. Pat lights out; replcd. j

**Parts**

**Quantity**

01-0862064-00SIREN FRONT SIDE

1

322502BULB PATIENT GH22

4

**Workorder: V28092**

In Date: 12/03/2009

Meter Reading: 113,220.40

Close Date: 01/14/2010

**Problem?**

wrap exhaust R34

**Task performed:**

- No cab A/C; rep rear A/C that was low on charge. j

**Parts**

**Quantity**

ABPN8332229011-3050 SWITCH BLOWER

1

**Workorder: V28764**

In Date: 01/04/2010

Meter Reading: 114,743.30

Close Date: 01/26/2010

**Problem?**

COMP. DOOR HANDLE 10-7 R34

**Task performed:**

- Replcd brkn handle on side of rescume. j

**Parts**

**Quantity**

HND5948TM22676-02 HANDLE DOOR ENTRY

1

**Workorder: V29157**

In Date: 01/15/2010

Meter Reading: 115,290.20

Close Date: 02/18/2010

**Problem?**

back up lights / alarm 10-7 r34

**Task performed:**

- rep rear backup lights; fnd bad connection. j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28889**

In Date: 01/07/2010  
Close Date: 02/22/2010

Meter Reading: 114,743.30

**Problem?**

HEATER 10-7 R34

**Task performed:**

1. Opened heater valve & rem air frm line.
2. Spotlight inop; rep connection. j

Parts

Quantity

NO PARTS USED

**Workorder: V29526**

In Date: 01/29/2010  
Close Date: 03/19/2010

Meter Reading: 116,009.00

**Problem?**

Air leak R34

**Task performed:**

Traced out air leaks & rep. j

Parts

Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

**Workorder: V30161**

In Date: 02/23/2010  
Close Date: 03/19/2010

Meter Reading: 117,672.50

**Problem?**

REPAIR A/C R34

**Task performed:**

Recharged cab A/C that was low. j

Parts

Quantity

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V30841**

**In Date:** 03/18/2010

**Meter Reading:** 119,571.60

**Close Date:** 04/06/2010

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R34**

**Task performed:**

- B-Inspection
- 2. Replc frnt brake shoes & all hardware; adj brakes.
- 3. Replc air dryer purge valve.
- 4. Replcd inner compt door gas cyc assist.
- 5. replcd roof marker lite.
- 6. ReRe loose stay mnts on L-3 compt
- 7. Replcd side LED strobe.
- 8. Replcd pat compt door lamp bulbs.
- 9. Replcd A/C filters.
- 10. Rep squad bench latch; replcd latch so bench locks into place.
- 11. replcd mud flaps; one was msng, TAE other was torn; had to cut to size & drill mntng holes.
- 12. Search for air leaks; fnd plug on rear tank leaking; rep w/new thrd tape; fnd air bag leaking; replc air bags; cld not locate any more listable leaks with soap.
- 13. 13. Trave to 34 & back to drop off rescue.
- 14. Quality check truck.
- 15. Backup camera not available; given safety vision system to install; started rem old sys; fnd screw in pumper; hooked screw up & tested; put wiring all back & ret safety vison.
- 16. Test drove; took back to to Stn34; rep lites in cab just before delivery.
- 17. Replc wiper blades.
- 18. Replc btry tender indicator.
- 19. Door ajar lite faulty; rem bezel, pull out & chk wiring; screws holding in panel stripped; fnd/rep wire connection & rep wiring.
- 20. Rem backup camera; take to parts; item out of stock; received permission to order new one; isntalled existing one back on dash. j

**Parts**

**Quantity**

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
032-0116549297 BATTERY INDICATOR	1
15W40BSYN OIL BULK QTS	26
16-15762-00016-19471-000 AIR BAG	2
322502BULB PATIENT GH22	2
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
B2420LP-SMUD FLAP 24 X 24	2
HLD3999GSS1715UV 30LB STRUT GAS	8
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2
R90PFILTER FUEL 33231	1

**Workorder: V25468**

**In Date:** 08/12/2009

**Meter Reading:** 108,234.30

**Close Date:** 04/13/2010

**Problem?**

**REPAIR 110 A/C**

**Task performed:**

- 1. 110 A/C inop; rep relay in unit that had water in it.
  - 2. Door open light on; fnd water in switch; rep & tested.
- j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V30666**

In Date: 03/12/2010

Meter Reading: 118,895.10

Close Date: 04/21/2010

**Problem?**

REPAIR STRETCHER LATCH R34

**Task performed:**

Adj stretcher latch that was not working. j

Parts

Quantity

NO PARTS USED

**Workorder: V30092**

In Date: 02/19/2010

Meter Reading: 117,485.10

Close Date: 04/22/2010

**Problem?**

replace all 6 tires (outside agency-boulevard)

**Task performed:**

Replace all (6) tires - Boulevard j

Parts

Quantity

370150ASEAL

2

D6176M121-83014 ROTORS RESCUE

2

Vendor?: BOULEVARD TIRE

**Workorder: V31298**

In Date: 04/06/2010

Meter Reading: 120,116.20

Close Date: 05/01/2010

**Problem?**

PAITIENT A/C 10-7

**Task performed:**

recharged A/C & tested. j

Parts

Quantity

NO PARTS USED

**Workorder: V31682**

In Date: 04/21/2010

Meter Reading: 120,560.40

Close Date: 05/11/2010

**Problem?**

REPAIR PAITIENT A/C R34

**Task performed:**

Recharged rear A/C that was blowing warm. j

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V31709

In Date: 04/22/2010

Meter Reading: 120,560.40

Close Date: 05/11/2010

#### Problem?

BRAKES SMOKING E 34

#### Task performed:

Road tested; chkd brakes; fnd retarder off. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V32152

In Date: 05/12/2010

Meter Reading: 92,108.00

Close Date: 05/20/2010

#### Problem?

rear a/c intermittant R34

#### Task performed:

Replcd A/C board, temp prob & rewired sys; tested sys & road tested. j

#### Parts

RCB BOXBOX/COVER FOR RCB3000

RCB-3000CONTROL BOARD USE WITH CM3000

#### Quantity

1

1

### Workorder: V32082

In Date: 05/09/2010

Meter Reading: 121,652.40

Close Date: 05/21/2010

#### Problem?

The toggle switch MOD air/heat keeps defaulting to off. On call at 0109 hrs crew watch control screen with air/heat switching from off to on to off. R34

#### Task performed:

Went to 34; waited for rescue; chkd pat A/C; fnd to be intermittent; brought to shop; narrowed down to control board; need more info on how to wire new board. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V32262

In Date: 05/18/2010

Meter Reading: 122,122.30

Close Date: 05/24/2010

#### Problem?

repair door ajar lt

#### Task performed:

Travel to Stn34; fnd frt pass door switch causing problem; rem switch & cind; no switch on truck; problem still intermittent with that ckt; poss wtr in connections; rescue called out on accident scene.

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V32282**

**In Date:** 05/18/2010

**Meter Reading:** 122,122.30

**Close Date:** 06/03/2010

**Problem?**

**C INSPECTION AND REPAIRS AS NEEDED R34**

**Task performed:**

- C-Service.
- 2. R/R left rear cab seat to be sent out for rep-ripped/torn.
- 3. Rebuilt air brake dryer.
- 4. Replcd rear brakes/drums-worn.
- 5. Replcd eng air filter.
- 6. Replc rear cab A/C filter.
- 7. Painted fuel cap.
- 8. Replcd pat compt A/C filter.
- 9. C/O left rear cab door alarm intermittent; replcd switch; now working properly.
- 10. Replcd replaced driver's door outer handle/latch-brkn.
- 11. Replcd driver's door panel-ripped/torn.
- 12. Trimmed seat belt cvrs-split/falling off.
- 13. Replcd all (4) cab door trims-brkn.
- 14. Replcd cab door w/strip for L/rear door-ripped/torn.
- 15. Replcd both rear cab door jam latches-bent.
- 16. Replcd pass side frnt door panel-falling apart.
- 17. Replcd eqmpt holddown in L-2 compt.
- 18. Replcd L-2 compt door reflector-brkn.
- 19. Replcd pat compt side entry door reflector-brkn.
- 20. Installed out of svc stickers.
- 21. Sec L-3 compt door hinge mnts.
- 22. Sec/tightened R-1 compt lower door latch-loose.
- 23. Replcd wiper blades.
- 24. Replcd brkn "T" fitting in washer plumbing for windshield.
- 25. Replc pat compt A/C door holdopen shocks.
- 26. Installed velcro in L-1 compt for O2 wrench hold down-msng.
- 27. Replcd flourescent tube in pat compt floor lites.
- 28. Chkd charging sys; fnd alt output low; replcd alt; charging normally now.
- 29. Rep oil leak due to loose plug fitting on filler hsgng during alt replacement; clnd oil residue frm eng & rechkd.
- 30. Rplc bulb in cab roof spotlight.
- 31. Road tested truck after rear brake job.
- 32. Adj air horns R/side frzn & inop; L/side out of tunel.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
18753-0455H7935-1 SPOT LIGHT BULB SPT6008	1
3744BRAKE DRUM REAR	2
4867JB320 UPGRADE ALTERNATOR	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
6807201470DOOR PANEL L/H	1
6807201570DOOR PANEL R/H	1
6807600070HANDLE DOOR EXT L/H	1
6809880278TURN PLUG	5
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91822OBSOLETE USE SERV TKS SWITCH - DOOR	1
98003RREFLECTOR RED 40132 GROTE	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
AST4000ASENSOR O2 REGULATOR	1
CA8193AIR FILTER 46744 WIX	2
HLD3999GSS1715UV 30LB STRUT GAS	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
P119325AIR FILTER NUT	1
R90PFILTER FUEL 33231	1
SPR-W58-1TEE PLASTIC	1

j



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V31963**

In Date: 05/04/2010

Meter Reading: 120,775.20

Close Date: 06/04/2010

**Problem?**

rear a/c inop R34

**Task performed:**

Parts

Quantity

Recharged A/C & tested. j

NO PARTS USED

**Workorder: V32223**

In Date: 05/15/2010

Meter Reading: 122,122.30

Close Date: 06/08/2010

**Problem?**

The O2 alarm on action area of R34 is alarming intermittently for no apparent reason, O2 tank is full, all outlets are close, no obvious leak noted. Alarms with the system turned on or off equally.

**Task performed:**

Parts

Quantity

Replcd O2 alarm sensor. j

NO PARTS USED

**Workorder: V32413**

In Date: 05/25/2010

Meter Reading: 122,122.30

Close Date: 06/14/2010

**Problem?**

repair seat r34 central

**Task performed:**

Parts

Quantity

Repair seat R34 - Central Auto j

NO PARTS USED

**Vendor?:** CENTRAL AUTO



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V32577

In Date: 06/01/2010

Meter Reading: 122,700.60

Close Date: 06/21/2010

#### Problem?

pitient a/c 10-7 r34

#### Task performed:

1. Chkd A/C sys; relocated temp probe sys; worked for a short time & shut down; jump relay.
2. Swapped out of truck will rewire unit; outside multiple
3. Dia A/C problem
4. Dia A/C problem. j

#### Parts

#### Quantity

11-26521487 SWITCH NC O 340 - C 210 HIGH PRESS	1
142211-2028 SWITCH PRESS OPEN-6 CLOSE-34	1
6806890001LOCK DASH	1
6809881078DZ STUD	1
6809940145CLIP	1
71R31001331 THERMOSTAT A/C	1
CM3000DISPLAY BOARD HOSELINE	1
RCB-3000CONTROL BOARD USE WITH CM3000	1

### Workorder: V32533

In Date: 06/01/2010

Meter Reading: 122,122.30

Close Date: 06/25/2010

#### Problem?

AC goes off and on in pt compartment while driving down the road. R34

#### Task performed:

Rewire A/C; installed jumper wire. j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V27990

In Date: 11/30/2009

Meter Reading: 9,353.00

Close Date: 07/13/2010

#### Problem?

the spotlight on top of the rescue is stuck pointing to the passengers side. Spotlight turns off and on but will not rotate in the 180 degree path. R34

#### Task performed:

Verified job. j

#### Parts

#### Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33480**

In Date: 07/12/2010      Meter Reading: 124,668.50  
Close Date: 07/23/2010

**Problem?**

Officer's seat door handle is broken. R34

**Task performed:**

Officer inner door handle brkn; replc handle.    j

Parts

Quantity

6807200575HANDLE DOOR

1

**Workorder: V33774**

In Date: 07/24/2010      Meter Reading: 125,234.80  
Close Date: 07/26/2010

**Problem?**

the radio is not working in the cab or the MOD. R34

**Task performed:**

REPORTED TO RADIO SHOP 07/26

Parts

Quantity

NO PARTS USED

**Workorder: V33519**

In Date: 07/13/2010      Meter Reading: 124,668.50  
Close Date: 08/13/2010

**Problem?**

REPAIR FLAT TIRE R34 BOULEVARD

**Task performed:**

Repair flat tire R34 - Boulevard      ja

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

**Workorder: V33823**

In Date: 07/27/2010      Meter Reading: 125,546.80  
Close Date: 08/16/2010

**Problem?**

Window will only roll down about 1/2" before stopping. R34

**Task performed:**

Rep window regulator that was jammed.      ja

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34088**

**In Date:** 08/06/2010

**Meter Reading:** 126,057.00

**Close Date:** 08/27/2010

**Problem?**

A inspection and repairs (from 34)

**Task performed:**

1. No start.
2. A-Inspection
3. L/R/I tire low - valve core leaking; air tire, locate leak; replc valve core.
4. Air tires - low.
5. Eng oil low - top off fluids.
6. Mirrors loose - tightened.
7. Drivers window wont open; wrong screw in arm rest; isntalled proper length screw.
8. Btry tender light flashing - wired backwards; rep bty tender wiring.
9. Rem backing frm American LaFrance emblem; rem backing.
10. Pat compt side door hard to open; latches out of time; rem panel & reset latches; also R/R brkn & stripped screw.
11. (2) medic drawers inop; not shimmed properly; rem shims frm sliders & rep latch asy.
12. Pulls to the right - frnt tire wear; rotated frnt tires & road tested.
13. (1) pat compt dome inop; installed new bulb.
14. Replc dash valve leaking.
15. Air leak in dash; (2) fittings wont seal; replcd fittings; also tightened fittings in dash.
16. Pat compt A/C not cooling; loose connector at \_\_\_\_\_ switch; rep wiring. ja

**Parts**

**Quantity**

032-0116549297 BATTERY INDICATOR	1
322502BULB PATIENT GH22	1
800034VALVE PARKING BRK.	1
921LIGHT BULB	1

**Workorder: V34344**

**In Date:** 08/17/2010

**Meter Reading:** 126,332.00

**Close Date:** 09/17/2010

**Problem?**

Air horns are not working.... r31

**Task performed:**

Replcd air horn solenoid for air horns. j

**Parts**

**Quantity**

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34667**

In Date: 09/01/2010  
Close Date: 09/27/2010

Meter Reading: 126,942.00

**Problem?**

repair air pack braket

**Task performed:**

Install new lock release on rear air packs. j

Parts

Quantity

101-124-000CRASH RESTRAINT STRAPS

2

**Workorder: V34672**

In Date: 09/01/2010  
Close Date: 09/27/2010

Meter Reading: 126,942.00

**Problem?**

SET UP UNIT FOR SERVICE R48

**Task performed:**

Set up for svc. j

Parts

Quantity

L PLACARD INSERTLARGE PLACARD INSERT CARD

2

S PLACARDFRONT AND BACK PLACARD

1

**Workorder: V34665**

In Date: 09/01/2010  
Close Date: 09/28/2010

Meter Reading: 126,942.00

**Problem?**

REPLACE WINDSHIELD R48

**Task performed:**

Replc windshield R48 - Charlies Auto j

Parts

Quantity

NO PARTS USED

Vendor?: CHARLIES AUTO GLASS

**Workorder: V34470**

In Date: 08/23/2010  
Close Date: 10/19/2010

Meter Reading: 126,942.00

**Problem?**

R31 [spare] has no hook/latch to catch stretcher from rolling out sr at 31

**Task performed:**

Installed new latch for stretcher. j 10/20/10

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35348**

In Date: 10/02/2010  
Close Date: 11/01/2010

Meter Reading: 127,130.70

**Problem?**

The brakes at 90% pressure " brake" too hard and causes the rescue to stop to abrupt. E48

**Task performed:**

- 1 adjusted foot brake
- 2 look for air leak fnp

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V35937**

In Date: 10/26/2010  
Close Date: 11/03/2010

Meter Reading: 128,140.50

**Problem?**

REPAIR BRAKES AS NEEDED

**Task performed:**

- 1. Test drove; ck all brake linings; 90% in frnt; 85% in rear; rem rear brake chamber clevis pins; adj rod length; rechk adjustment; ck ok; test drove; ck ok.
- 2. Rem rear axle slack adjusters; replc/adj; greased "S" cams/slacks; test drove; ck ok; ck frnt axle adjustment; ck ok; clnd bay. j

**Parts**

R802446AUTO SLACK ADJ  
R802447AUTO SLACK ADJ

1  
1

**Quantity**

**Workorder: V35649**

In Date: 10/14/2010  
Close Date: 11/09/2010

Meter Reading: 127,712.00

**Problem?**

light switch on rear right door patient compartment and light switch on passenger side of patient compartment is not working. R48

**Task performed:**

- Chk light switch & fnd switch working j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V35791**

In Date: 10/20/2010  
Close Date: 11/09/2010

Meter Reading: 127,731.30

**Problem?**

Brakes grab really bad when braking and jolt the truck. Headlights need to be adjusted right headlight lights up the sidewalk and swale leaving dark area in front. Search light won't swivle, stuck facing passenger side. R48

**Task performed:**

- 1. Readj all brakes adj free play in foot pedal road tested w/driver; driver states 100% better.
- 2. Spotlight inop; rep bad grnd.
- 3. Headlights need adjustment; adj/tested. j

**Parts**

21481SEARCHLIGHT CONTROL  
286171BRAKE VALVE E-6 NEW

1  
1

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35717**

In Date: 10/18/2010

Meter Reading: 127,731.30

Close Date: 11/12/2010

**Problem?**

emergency lights in the grille are not working. R48

**Task performed:**

Parts

Quantity

FNP w/lights in grill. j

NO PARTS USED

**Workorder: V36311**

In Date: 11/09/2010

Meter Reading: 128,715.90

Close Date: 11/16/2010

**Problem?**

rear outside tires are wearing down to the wear bars. r48

**Task performed:**

Parts

Quantity

Rear outside tires are wearing down to wear bars R48 -  
Boulevard j

NO PARTS USED

**Vendor?:** BOULEVARD TIRE

**Workorder: V36314**

In Date: 11/09/2010

Meter Reading: 128,715.90

Close Date: 11/30/2010

**Problem?**

seems to be an air leak, both airtanks bled down to 50psi in :30min. Also noticed both air tank levels are not equal, I assume they are suppose to be equal, right? R48

**Task performed:**

Parts

Quantity

(1) TRAVELED TO ST48 TO REPAIR AIR LEAK IN R48.  
REMOVED AND REPLACED WITH A NEW TREADLE  
VALVE / MIKE. CHECKED AND REPAIRED A LEAK AT  
THE COMPRESSOR AND AIR TANK DRAIN. TEST  
DROVE OK. J.W.

103385NDRAIN COCK

2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V34515**

In Date: 08/25/2010  
Close Date: 12/02/2010

Meter Reading: 127,055.00

**Problem?**

B INSPECTIOJN AND REPAIRS AS NEEDED R48

**Task performed:**

1. service transmission
2. B inspection
3. Remove stickers from rear compt. doors
4. R&R wiper blades clean washer and nozzles
5. Horn 10-7 found water in horn R&R horn
6. Check codes in engine and trans. found inactive codes cleared codes road test and recheck npf

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
52-24WIPER BLADES ANCO 24	2
A0631117000HORN HIGH NEW # 06-52125-039	1
R90PFILTER FUEL 33231	1

**Workorder: V36246**

In Date: 11/07/2010  
Close Date: 12/16/2010

Meter Reading: 128,715.90

**Problem?**

Rescue 48 turn signals stopped working last night. R48

**Task performed:**

- (1) TRAVELED TO ST48 TO REPAIR R48 TURN SIGNALS. REPLACED THE FLASHER IN THE SYSTEM. OK.
- (2) ADJUSTED STRETCHER LATCH THAT HOLDS STRETCHER IN PLACE IN THE PATIENT COMPARTMENT. IT WAS HARD TO OPEN . DONE.  
J.W.

Parts	Quantity
EL12FLASHER ELECTRONIC	2

**Workorder: V32117**

In Date: 05/10/2010  
Close Date: 12/22/2010

Meter Reading: 121,652.40

**Problem?**

Check out patient compartment A/C inop. R34

**Task performed:**

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33765**

In Date: 07/24/2010

Meter Reading: 125,546.80

Close Date: 12/22/2010

**Problem?**

pt. compartment a.c. leaks water on the bay floor, even when set to 80 degrees. R34

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V35271**

In Date: 09/30/2010

Meter Reading: 126,942.00

Close Date: 12/22/2010

**Problem?**

R48 needs mounting bracket for dry chem extinguisher installed. ( check with C shift officer)

**Task performed:**

Parts

Quantity

R48 NEEDS MOUNTING BRACKET FOR DRY CHEM EXT INSTALLED. ???

NO PARTS USED

(1) INSTALLED BOLT CUTTER/PRY BAR.

(2) O2 LEAK. REPAIRED LEAK AT THE BOTTLE CONNECTION.

(3) AIR LEAK. REPAIRED LEAKS FOUND.

**Workorder: V35335**

In Date: 10/01/2010

Meter Reading: 127,105.50

Close Date: 12/22/2010

**Problem?**

Tools mounted in driver compartment. R48

**Task performed:**

Parts

Quantity

Remounted tools in L1 compartment

NO PARTS USED

**Workorder: V35336**

In Date: 10/01/2010

Meter Reading: 127,105.50

Close Date: 12/22/2010

**Problem?**

R 48 main o2 leak repair.

**Task performed:**

Parts

Quantity

Rep leak on O2 bottle & tested. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35363**

In Date: 10/04/2010  
Close Date: 12/22/2010

Meter Reading: 127,130.70

**Problem?**

AIR DUMP HAS LEAK FOR LOWERING AND RAISING REAR ON RESCUE. R48

**Task performed:**

Parts

Quantity

(1) AIR DUMP ON R48 LEAKING AIR. TESTED SYSTEM ON FOUND NO LEAK. OK.

NO PARTS USED

J.W.

**Workorder: V37267**

In Date: 12/19/2010  
Close Date: 12/22/2010

Meter Reading: 130,348.40

**Problem?**

patient airbags are not holding air while the truck is not running. r48

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V37271**

In Date: 12/20/2010  
Close Date: 01/10/2011

Meter Reading: 130,303.80

**Problem?**

Very bad air dump leak. r48

**Task performed:**

Parts

Quantity

1. Chkd/air leaks; fnd leveling valve on left side leaking; will need to come to shop to have valves replc.
2. R/R both rear leveling valves; adj rods. j

S4640024430VALVE LEVELIN

2

**Workorder: V36784**

In Date: 12/01/2010  
Close Date: 01/11/2011

Meter Reading: 129,077.00

**Problem?**

\*\* CORECTION on last entry: \*\*\* shore line for R48 is good --- problem with R48 itself. Auxiliary A/C not running to keep back end cold.

**Task performed:**

Parts

Quantity

Call stn - all A/C units working. j

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37369**

In Date: 12/22/2010      Meter Reading: 130,452.70  
Close Date: 01/11/2011

**Problem?**

check-out light button does not function. r48

**Task performed:**

Rep bad connection on relay for C/O lights. j

Parts

NO PARTS USED

Quantity

**Workorder: V37384**

In Date: 12/22/2010      Meter Reading: 130,646.40  
Close Date: 02/07/2011

**Problem?**

passengers side rear window opening mechanism does not work. R48

**Task performed:**

Window handle brkn - replc handle. j

Parts

A1818557002HANDLE-WINDOW

Quantity

1

**Workorder: V37452**

In Date: 12/28/2010      Meter Reading: 130,646.40  
Close Date: 02/07/2011

**Problem?**

R48's rear suspension seems very stiff.

**Task performed:**

1. Readj rear air bag & road tested.
2. Chkd rear A/C; recharged & rep leak. j

Parts

NO PARTS USED

Quantity

**Workorder: V37879**

In Date: 01/18/2011      Meter Reading: 131,948.00  
Close Date: 02/25/2011

**Problem?**

slow air leak in R48's brakes. Had to wait for system to come up on late night call.

**Task performed:**

Chkd for air leaks; fnd none at this time. j

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38113**

In Date: 01/27/2011

Meter Reading: 132,556.10

Close Date: 02/25/2011

**Problem?**

rear air suspection not holding air when truck is off. R48

**Task performed:**

Chkd problem w/air bags; FNP. j

Parts

NO PARTS USED

Quantity

**Workorder: V38542**

In Date: 02/15/2011

Meter Reading: 133,705.00

Close Date: 02/25/2011

**Problem?**

ON CALL TURBO 10-7 R48

**Task performed:**

Noise from engine - turbo blown; swaped out. j

Parts

NO PARTS USED

Quantity

**Workorder: V38573**

In Date: 02/16/2011

Meter Reading: 133,705.00

Close Date: 02/28/2011

**Problem?**

TURBO 10-7 R48

**Task performed:**

1. Dia low power problem; test drive to verify problem; rem intake to turbo; fnd turbo locked up.
2. Rem charge air cooler/radiator.
3. Rem turbo.
4. install turbo.
5. Assemble charge cooler to radiator.
6. Install charge cooler & raditor in veh; connect all lines/hoses; fill radiator & test; ok. j

Parts

DDE-5411870080GASKET OIL RETURN TUBE TURBO

1

DDE/A0289976348TURBO ORINGS

1

DDE/EA9060969899TURBOCHARGER

1





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38576**

**In Date:** 02/16/2011

**Meter Reading:** 134,111.00

**Close Date:** 03/07/2011

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R 48

**Task performed:**

- C-Inspection
- 2. Test btrys - NG; replc btrys, cln terms.
- 3. Coolant svc.
- 4. P/S svc.
- 5. Replcd belts.
- 6. Press chk cooling sys; fnd one leak at hose clamp; tightened clamp & rechk - ok.
- 7. Drill out & install nut certs for L-3 door hinge; install new bolts & tighten.
- 8. Relock turtle deck tog in L3 & L4.
- 9. Msng screw in rear pat door; drill/tap new threads & install new screw.
- 10. tighten all door panels, latches & loose handles.
- 11. Lube all latches.
- 12. Dia air leaks; fnd rear dump valve leaking; R/R valve; also fnd leak beh dash at Humphrey valve.
- 13. Replc LR valve stem brkt & lugnut cvr; no parts charged out.
- 14. Replcd rear cab A/C filter & clnd rear pat compt filters.
- 15. Dia R/rear door light inop; fnd bad connection; rep connection.
- 16. Replcd L/rear mud flap; cut/drill to size.
- 17. Rem fuel cap, cln, prime, paint & reinstall.
- 18. Attach blanket storage metal trim & action area padded trim; tighten radio headset hook.
- 19. Chk for O2 leaks - ok; install tank holding brkt.
- 20. Replc fender spash shield.
- 21. Test run veh & chk for leaks; top off fluids. j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
15W40BSYN OIL BULK QTS	24
17125540001712554004 SHIELD SPLASH R/H	1
401148DUMP VLVE AIR SLOAN	1
6809880678STUD DZ	4
78R536078R5360M 2PK FILTER AIR COND	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
B2420LP-SMUD FLAP 24 X 24	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
SU68088VALVE DUMP 310 HUMPHREY	1
UMVS111611STRAP	2

**Workorder: V38158**

**In Date:** 01/30/2011

**Meter Reading:** 132,683.80

**Close Date:** 03/08/2011

**Problem?**

rescue 48 front cab A/C on cooling(either front cab unit)...Patient compartment seems ok...thanks

**Task performed:**

recharged cab A/C & chkd for leaks. j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38275**

In Date: 02/04/2011

Meter Reading: 133,168.10

Close Date: 03/09/2011

**Problem?**

Front A/C not working properly. R48

**Task performed:**

Parts

Quantity

1. Recharged A/C & rep leaks.
2. Side entry door hard to open; rep door hinge & adj linkage. j

NO PARTS USED

**Workorder: V38299**

In Date: 02/04/2011

Meter Reading: 133,417.00

Close Date: 03/09/2011

**Problem?**

REAR DUMP NOT WORKING PROPERLY. ADVISED TOMMY OF PROBLEM. R48

**Task performed:**

Parts

Quantity

Adj rear air bags & tested sys. j

NO PARTS USED

**Workorder: V38316**

In Date: 02/07/2011

Meter Reading: 133,417.00

Close Date: 03/09/2011

**Problem?**

Temperature switch once turned to heat does not come off heat Vent switch blows to windshield and window causing fog the windshield over. r48

**Task performed:**

Parts

Quantity

Readj temp cntrl cable & tested. j

NO PARTS USED

**Workorder: V39167**

In Date: 03/14/2011

Meter Reading: 135,157.00

Close Date: 03/14/2011

**Problem?**

patient compartment suspension airbags possibly leaking.drivers side leaks down after vehicle sits in the bay for an hour or so. sta 48.

**Task performed:**

Parts

Quantity

1. travel to sta.48
2. check driver side air bag, adjust both air bags and recheck ok...

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38746**

In Date: 02/24/2011      Meter Reading: 133,705.00  
Close Date: 03/21/2011

**Problem?**

REPLACE FRONT TIRES R 48

**Task performed:**

Replc front tires R48 - Boulevard      j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

**Workorder: V39143**

In Date: 03/14/2011      Meter Reading: 135,157.00  
Close Date: 04/05/2011

**Problem?**

R48's stretcher has a bad loading wheel. It needs replaced. R48 (outside agency-medco equipment repair)

**Task performed:**

R48 stretcher has bad loading wheel - Medco      j

Parts

NO PARTS USED

Quantity

Vendor?: MEDCO

**Workorder: V39863**

In Date: 04/12/2011      Meter Reading: 136,879.80  
Close Date: 04/12/2011

**Problem?**

over head padding above rear entry door fell down, R-48

**Task performed:**

1. found rear overhead panel above rear entry door fell down and ripped wires going to brake lite, install new butt connectors and reinstall panel.

Parts

NO PARTS USED

Quantity

**Workorder: V39511**

In Date: 03/29/2011      Meter Reading: 136,189.90  
Close Date: 05/06/2011

**Problem?**

remote control spot light on cab not working....Thanks R48

**Task performed:**

Rep spotlight.      j

Parts

J254HALOGEN BULB 1000 WATT WPB  
Q1500T3/CLLB-M15 240 V BULB

Quantity

2  
3



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V41175**

In Date: 06/07/2011      Meter Reading: 138,410.00  
Close Date: 06/07/2011

**Problem?**

Rescue 48 turbo problems has no power. Sta 48.

**Task performed:**

1. travel to sta-48, check unit for no power, found turbo hose clamp broken
2. travel to s/shop for parts, return to sta-48 install hose and new clamp

Parts

Quantity

NO PARTS USED

**Workorder: V41190**

In Date: 06/08/2011      Meter Reading: 138,410.00  
Close Date: 06/13/2011

**Problem?**

On call- R48- boost leak.

**Task performed:**

FF says sounds like a siren when on full throttle; test drove to confirm; fnd wrong size clamp installed on inlet hose to cooler; had to go to shop for part; R/R clamp; test drove - all ok.      j

Parts

Quantity

NO PARTS USED

**Workorder: V42176**

In Date: 07/21/2011      Meter Reading: 140,325.20  
Close Date: 08/08/2011

**Problem?**

door alarm going off R 48

**Task performed:**

repaired rear door switch

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42457**

**In Date:** 08/01/2011

**Meter Reading:** 142,904.00

**Close Date:** 08/15/2011

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R 48**

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

B INSPECTION	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
REPLACED RF FENDER MARKER LIGHT BULB	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
	103385NDRAIN COCK	1
REMOVED RR DOOR LIGHT SWITCH AND CLEANED CONTACTS AND GROUND. CHECKED OPERATION OF SWITCH AND LIGHT OK	1250E473PLUG DRAIN REAR END FREIGHTLINER	1
	223-485V91-8301 85 PSI CLOSED 67 OPEN PREEURE PF	1
	322502BULB PATIENT GH22	1
RF RITE VALVE CORE LEAKING - REPLACED CORE AND AIRED ALL TIRES TO SPEC	404-100 VALVE CORE	1
	78R536078R5360M 2PK FILTER AIR COND	1
	GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
COOLER LINE LEAK AT RADIATOR. TIGHTEN FITTING, CLEAN AND INSPECT OK	LF18TS-LEDMAP LIGHT LED 18 IN	1
	R90PFILTER FUEL 33231	1
ADD S/X FLUID CHECK FOR ANY LEAKS OK		
DIANOSE REMOTE SPOT LIGHT INOP - FOUND BAD GROUND REPAIR GROUND CONNECTION		
REPLACED MAP LIGHT - DRILL AND TAP NEW HOLES, SPLICE WIRING, AND HEAT SHRINK. REPLACED FLEX CABLE HOLDER. TEST OK		
REMOVE FRT LIGHT BAR COVERS AND REPAIR CONNECTION FOR FRT CORNER LIGHT		
REPLACED MISSING REAR A/C FILTER AND FRT EXPANDED METERS		
REPLACED LR PATIENT CAMPT BULB		
REPLACED REAR PATIENT COMPARTMENT FLOURESENT BULBS		
ADJ LEVELING VALVES FOR PROPER RIDE HEIGHT		
DIANOSE AIR HORSN SOUNDING WEAK. FOUND R AIR HORN GASKET BAD AND AIR HORNS OUT OF ADJ. REPLACED GASKET AND ADJ AIR HORNS		
DIAGNOSE CITY HORNS INOP FOUND BAD CONNECTION AT ONE OF THE HORNS REPAIR CONNECTION TEST OK		
CLEAN AND PAINT FUEL CAT		
DIAGNOSE AIR LEAKS FOUND PROTECTION VALVE ON SECONDARY TANK LEAKING AND FITTING ON PASS AIR SEAT. REPLACED PROTECTION VALVE INSTALL A DRAIN VALVE FOR SECONDARY TANK AND R&R POSS SEAT AND REPLACED AIR LINE AND FITTINGS.		



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42625**

In Date: 08/07/2011

Meter Reading: 141,344.90

Close Date: 08/15/2011

**Problem?**

REPLACE REAR TIRES

**Task performed:**

Parts

Quantity

Replc rear tires - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD

**Workorder: V42849**

In Date: 08/16/2011

Meter Reading: 141,823.60

Close Date: 09/12/2011

**Problem?**

Patient compartment ac not cooling. Sta 48.

**Task performed:**

Parts

Quantity

REPAIRED AC UNIT AND TESTED

NO PARTS USED

**Workorder: V42819**

In Date: 08/15/2011

Meter Reading: 141,823.60

Close Date: 09/19/2011

**Problem?**

Rear pt A/C keeps turning on and off on its own (Screen/thermostat on wall powers on and off constantly), Sta 48.

**Task performed:**

Parts

Quantity

repaired bad connection on relay

NO PARTS USED

**Workorder: V43115**

In Date: 08/29/2011

Meter Reading: 142,276.40

Close Date: 09/19/2011

**Problem?**

on call patient a/c 10-7 R 48

**Task performed:**

Parts

Quantity

CLEANED CONDENSER FANS AND TESTED A/C

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43874**

In Date: 09/23/2011

Meter Reading: 145,352.90

Close Date: 09/26/2011

**Problem?**

Radio mike need replacing. It was previously checked out and nothing has been correctes.d. When s button depressed it intermittenly transmits. Sta 48.

**Task performed:**

Parts

Quantity

printed and delivered to radio shop.

NO PARTS USED

CHECK OUT COULDNT REPAIR LET RADIO SHOP KNOW TO REPLACE MIC

**Workorder: V42925**

In Date: 08/19/2011

Meter Reading: 141,987.30

Close Date: 10/07/2011

**Problem?**

Requesting 3 hooks for hanging equipment in the back of the cab. 1 on each side of back window & 1 on wall behind driver seat for hanging radio... thx! R48

**Task performed:**

Parts

Quantity

installed hook in rear

NO PARTS USED

**Workorder: V44556**

In Date: 10/20/2011

Meter Reading: 147,181.40

Close Date: 10/28/2011

**Problem?**

Rear a/c warm.

**Task performed:**

Parts

Quantity

found bad connection on relay for condencer fans

NO PARTS USED

**Workorder: V44595**

In Date: 10/21/2011

Meter Reading:

Close Date: 11/07/2011

**Problem?**

Please fix or replace Kussmall Auto-eject outlet for the shore-line on Rescue48. It fits loose and is tripping the breaker in the patie compartment... Thx... R48

**Task performed:**

Parts

Quantity

REPLACED AUTO EJECT PLUG

0915520120AUTO EJECT 20 AERO OTL3925

1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V44794**

In Date: 10/31/2011

Meter Reading: 147,686.00

Close Date: 11/07/2011

**Problem?**

Check engine light on. Sta 48

**Task performed:**

Parts

Quantity

Fnd low on coolant; rep leak. j

NO PARTS USED

**Workorder: V45065**

In Date: 11/09/2011

Meter Reading: 148,296.50

Close Date: 11/09/2011

**Problem?**

burning smell from inside of cab, R-48

**Task performed:**

Parts

Quantity

1. travel to sta-48 check for burning smell in rescue,, found handheld spot light laying face down on floor mat in the on position, burned the spot light and floor mat, Tommy will replace spot light on 11/10/11 will be on vacation. travel back to s/shop

NO PARTS USED

**Workorder: V44712**

In Date: 10/26/2011

Meter Reading:

Close Date: 11/14/2011

**Problem?**

FRONT AC BLOWING HOT. R48

**Task performed:**

Parts

Quantity

Rep condensor fans & tested. j

NO PARTS USED

**Workorder: V45155**

In Date: 11/14/2011

Meter Reading:

Close Date: 12/02/2011

**Problem?**

HAND HELD SPOT LIGHT NOT WORKING. R48

**Task performed:**

Parts

Quantity

replaced handheld spot light

NO PARTS USED

repaired stretcher latch



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45410**

In Date: 11/25/2011

Meter Reading:

Close Date: 12/12/2011

**Problem?**

Shore line recepticle not ejecting shoreline. Occasionally, sparks when connecting shoreline to vehicle.R48

**Task performed:**

Parts

Quantity

found no problem with auto eject

NO PARTS USED

**Workorder: V45742**

In Date: 12/08/2011

Meter Reading:

Close Date: 12/16/2011

**Problem?**

ac in patient compartment and in the cab not cooling.

**Task performed:**

Parts

Quantity

REPAIRED CONDENCER FAN CONNECTION AND  
REWired DELAY.

NO PARTS USED

REPAIRED MAP LIGHT.



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46109**

**In Date:** 12/27/2011

**Meter Reading:** 151,191.20

**Close Date:** 01/09/2012

**Problem?**

**C INSPECTION AND REPAIRS R48**

**Task performed:**

1. PER "C" SERVICE
2. PAINT FUEL CAP
3. REPLACE WIPER BLADES
4. REPLACED REAR CAB A/C FILTER
5. REPLACED PATIENT COMPARTMENT A/C FILTER
6. REPLACED ALL FOUR DOOR TRIMS (BROKEN)
7. REPLACED TWO CAB DOOR WEATHERSTRIPS
8. REPLACED T/S SIDE MARKER LIGHT LENSES (CRACKED)
9. CLEANED DEBRIS FROM WINDSHIELD SQUIRTERS
10. REPLACED ENGINE AIR FILTER
11. REPLACED FLORSCENT LIGHTS IN PATIENT COMPARTMENT
12. INSTALLED HEADSET HOOKS IN CAB
13. LUBED, ADJUSTED AND TIGHTENED ALL CAB AND PATIENT COMPARTMENT DOOR LATCHES, HOLD OPENS AND HINGES.
14. REPLACED PATIENT COMPARTMENT SIDE ENTRY DOOR INNER LATCH/HANDLE ASSEMBLY. (BROKEN/STRIPPED)
15. INSTALLED AIR PACK BRACKETS
16. REPAIRED ACCESS DOOR ABOVE LEFT REAR CAB DOOR. (BENT/FALLING OFF)
17. REMOVED, CLEANED AND REINSTALLED REAR ENTRY DOOR GLASS GASKET. (FALLING OUT)
18. REPLACED ALL AIR TANK PULL CORD DRAINS WITH PETCOCK STYLE DRAINS
19. REBUILT AIR DRYER
20. SERVICED DIFF.
21. REPLACED FRONT TIRES WITH TIRES FROM BUILDING THREE
22. REPLACED REAR AXLE BRAKE SHOES, DRUMS AND HARDWARE
23. REPLACED ALL FOUR A/C DASH VENT DEFUSERS
24. ROAD TESTED AND RECHECKED BRAKE ADJUSTMENT
25. QA. INSPECTION

**Parts**

**Quantity**

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
103385NDRAIN COCK	4
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
14-7014HGR-1 HELMET HOOK	3
1501450007750USE 0775145	1
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CA8193AIR FILTER 46744 WIX	1
HAN-1LBEZEL AND HANDLE	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
R90PFILTER FUEL 33231	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45175**

In Date: 11/14/2011

Meter Reading: 148,755.70

Close Date: 01/13/2012

**Problem?**

Please install the 3 hooks in the Rescue... E 48

**Task performed:**

DONE AT SHOP.

Parts

Quantity

NO PARTS USED

**Workorder: V46057**

In Date: 12/24/2011

Meter Reading: 151,191.20

Close Date: 01/13/2012

**Problem?**

the temporary switch turning on the overhead lights on the rear door is inoperable

**Task performed:**

1. REPAIRED OVER HEAD LIGHT REPAIRED MELTED WIRES.

2. PRESSURE TESTED FOR COLLENT LEAK.

Parts

Quantity

NO PARTS USED

**Workorder: V46747**

In Date: 01/21/2012

Meter Reading: 152,493.80

Close Date: 01/27/2012

**Problem?**

Patient compartment AC blowing room temperature. Sta 48

**Task performed:**

A/C IN PT WORKING - CAB A/C NEEDED A CHARGE AND REPAIRED LEAK.

Parts

Quantity

NO PARTS USED

**Workorder: V46840**

In Date: 01/25/2012

Meter Reading: 152,606.40

Close Date: 02/03/2012

**Problem?**

medical glove holder in patient compartment broken R 48

**Task performed:**

REPLACED GLOVE HOLDER.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46851**

In Date: 01/25/2012      Meter Reading: 152,606.40  
Close Date: 02/03/2012

**Problem?**

PLEASE ADD ANOTHER GLOVE HOLDER TO R-48 REAR PASSENGER COMPARTMENT...THANK YOU

**Task performed:**

Parts ----- Quantity

1. A/C INOP - REPAIRED AND TESTED.
2. DROPPED OFF GLOVE HOLDER.

NO PARTS USED

**Workorder: V47481**

In Date: 02/22/2012      Meter Reading:  
Close Date: 02/22/2012

**Problem?**

Unusaul smell (burning) ..... batteries drain without being plugged in between calls to 12 volts. R-48

**Task performed:**

Parts ----- Quantity

1. check for burning smell, found alternator bad, replace alternator.

4867JB320 UPGRADE ALTERNATOR

1

**Workorder: V47452**

In Date: 02/21/2012      Meter Reading: 154,678.00  
Close Date: 02/27/2012

**Problem?**

flat tire 48

**Task performed:**

Parts ----- Quantity

FLAT TIRE 48.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V47829**

In Date: 03/08/2012      Meter Reading: 155,760.90  
Close Date: 03/16/2012

**Problem?**

From cab AC blowing warm to hot air. Sta 48

**Task performed:**

Parts ----- Quantity

FOUND BAR CONNECTION ON CONDENSOR FANS.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48213**

In Date: 03/27/2012  
Close Date: 03/27/2012

Meter Reading: 157,122.50

**Problem?**  
flat tire

**Task performed:**

Parts

Quantity

FLAT TIRE.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V48234**

In Date: 03/27/2012  
Close Date: 03/28/2012

Meter Reading: 157,122.50

**Problem?**  
Repalce other 3 tires that were down to the wear bar

**Task performed:**

Parts

Quantity

REPLACE OTHER 3 TIRES THAT WERE DOWN TO THE WEAR BAR.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V48185**

In Date: 03/26/2012  
Close Date: 04/02/2012

Meter Reading: 157,026.80

**Problem?**  
air stem support bracket broke off on the drivers side rear wheel, needs to be replaced. Sta 48

**Task performed:**

Parts

Quantity

1. REPAIR REAR DOOR LATCH THAT WAS HARD TO OPEN.
2. REMOVE AIR STEM BRACKET.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48363**

In Date: 04/02/2012

Meter Reading: 157,515.20

Close Date: 04/03/2012

**Problem?**

ON CALL LOST POWER R 48

**Task performed:**

ARRIVED AT STATION AND START UNIT - CHECK FOR CODES - NO CODES FOUND - BOOST AIR PRESSURE SIGNAL IN DIAGNOSTIC SETTING - CHECK AIR SUPPLY TUBES. ALL IN TIGHT AND SECURE - AIR FLOW MINDED IN NORMAL POSITION - TEST DRIVE UNIT AND CHECK IN DIAGNOSTIC MODE VIA LAP TOP - UNIT IN SERVICE.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V48320**

In Date: 03/31/2012

Meter Reading: 157,515.20

Close Date: 04/20/2012

**Problem?**

PLASTIC PANEL CLIP BROKEN ON OFFICER'S SIDE---WIRE COVER R48

**Task performed:**

REPLACED FUSE PANEL COVER.

**Parts**

6806870807COVER FUSE PANEL

6809881078DZ STUD

6809940145CLIP

**Quantity**

1

2

2

**Workorder: V48730**

In Date: 04/17/2012

Meter Reading: 158,657.60

Close Date: 05/03/2012

**Problem?**

B INSPECTION R 48

**Task performed:**

1. B insp.
2. replace pat. a/c filter
3. l/side upper pat. box amber marker lite inop, replace lite assy.
4. r/side cab marker lite inop, replace bulb
5. d/side door handle missing screw, replace screw
6. city horn and hands free siren inop. on steering wheel, found contact on steering column dirty, remove and sand brass contact, reinstall ok
7. replace cab a/c filter

**Parts**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

0000902051FILTER FUEL 03 MERCEDES

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1501450007750USE 0775145

78R536078R5360M 2PK FILTER AIR COND

CLR9185109186-1500-10 MARKER LT. RED LED

R90PFILTER FUEL 33231

**Quantity**

1

1

1

1

1

1

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48507**

In Date: 04/07/2012

Meter Reading:

Close Date: 05/04/2012

**Problem?**

Door handle on driver's door is breaking off.

**Task performed:**

repair completed on w/o#48730

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V50947**

In Date: 07/18/2012

Meter Reading: 158,831.90

Close Date: 07/24/2012

**Problem?**

A INSPECTION AND ANY NEEDED REPAIRS SR16

**Task performed:**

1. A- INSPECTION AND CORRECT TIRE PRESSURES.
2. REPAIR CAB ELEC PANEL COVER. R&R R/S DASH R&R TRANS COMPUTER R&R COMPUTER MTNG PLATE R&R DASH END CAP.LOWER ASSY. DASH NEEDS 1/4 TURN FEMALE NUT NONE IN STOCK - MADE MY OWN WAY OF SECURING PANEL COVER.
3. REPAIR BROKEN WIRING AT DOOR HINGE AREA FOR DOOR LIGHTS.
4. L-1 COMPT LIGHTS DON'T WORK. TEST LIGHTS OK DIAGNOSE CIRCUIT - OPEN TRACE WIRING FIND OPEN - REPAIR.
5. R&R R/F FENDER TURN SIG/MARKET LT AND HARNESS ASSY.
6. R&R R/F TOP MARKER LIGHT ASSY.

**Parts**

- 6808200020LIGHT ASSY. TURN SIGNAL
- 6809881078DZ STUD
- 6809940145CLIP
- CLR9185209186-1500-20 MARKER LT.AMBER LED

**Quantity**

- 1
- 1
- 1
- 1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V52383**

In Date: 09/14/2012

Meter Reading: 160,477.10

Close Date: 09/24/2012

**Problem?**

A INSPECTION AND NEEDED REPAIRS

**Task performed:**

1. A INSPECT
2. A INSPECT
3. FRT DOME LIGHT INOP-WORKS WHEN TURN ON OR REAR DOOR OPEN CHK SWITCH RUN CONSTANTLY AND LINE CURRENT ALL GOOD- ADVISED BY E.E FOREMEN ASSEMBLE UNIT LET IT GO.
4. CAB R/R DOOR LIGHT INOP-LED LIGHT GOOD-CHK WIRES ROUND GROUND WIRE LOOSE AND DOOR SWITCH- CORRECT FAULT.
5. PACENT COMPT CABINET LOCK FELL OFF-REINSTAL LOCKING ASSEMBLE AND ADJUST LOCKING CATCH MECHANISM.
6. L-3 DOOR HOLDER BLOCK LOOSE-SCREW HOLES WORN OUT- DISASSEMBLE RETAP NEW SUPPORT HOLES AND REASSEMBLE.
7. HORN INOP- FOUND LOOSE GROUND WIRE IN STEERING CONTROL BUTTON-REATTACH GROUND WIRE TO STEERING HORN BOTTON.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V52800**

In Date: 10/02/2012

Meter Reading: 160,477.10

Close Date: 10/04/2012

**Problem?**

batteries change by road mechanic at st17

**Task performed:**

TRAVEL TO 17 R&R BATTERIES.

**Parts**

**Quantity**

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31DBATTERY 950CCA HP-31D

4

**Workorder: V52908**

In Date: 10/07/2012

Meter Reading: 160,477.10

Close Date: 10/16/2012

**Problem?**

Drivers side headlight points into oncoming traffic. Unable to adjust because bracket is not installed correctly, adjusting screw is n attached to bracket. R 17

**Task performed:**

TRAVEL TO 17 REPAIRED HEADLIGHT ADJUSTED.

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V53212**

In Date: 10/19/2012  
Close Date: 10/22/2012

Meter Reading: 160,477.10

**Problem?**

A Inspection

**Task performed:**

A INSPECTION.

Parts

Quantity

NO PARTS USED

**Workorder: V53600**

In Date: 11/07/2012  
Close Date: 11/14/2012

Meter Reading: 161,111.00

**Problem?**

A inspection

**Task performed:**

1. A INSP
2. L AIR BAG DEFLATED- AIR SYSTEM TO OPERATING PSI-CHK AIR BAG FOR LEAK CHK LEVELING VALVE FOR PROPER OPERATION AND LEAK CHECK AIR LINES AND FITTING NO LEAK FOUND AIR BAGS OPERATING NORMAL.
3. CAB R/R DOOR LIGHT INOP-FOUND BAD GROUND TO LED ASSEMBLY-REPAIR BAD GROUND.
4. CAB REAR L/R HEAD PADDLING OFF- CLEAN AND REMOUNT.

Parts

Quantity

NO PARTS USED

**Workorder: V54389**

In Date: 12/12/2012  
Close Date: 12/12/2012

Meter Reading: 162,150.00

**Problem?**

A INSPECTION

**Task performed:**

1. A INSP
2. R&R HOLD OPEN ON MEDICAL CABINET.
3. DIAGNOSE CAB DOME LTS DO NOT COME ON WITH 2 FRONT DOOR COULD NOT FIND PROBLEM QUICKLY. AS PER STEVE REINES-LEAVE AS IS.

Parts

Quantity

HLD3999GSS1715UV 30LB STRUT GAS

2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54930**

In Date: 01/08/2013

Meter Reading:

Close Date: 02/01/2013

**Problem?**

stretcher latch does not work properly. Tried lubricating and still does not latch stretcher w/o forcefully hitting undercarriage. R 39

**Task performed:**

**Parts**

**Quantity**

REPLACED STREAMER LATCH AND SWAPED OUT STREAMER.

NO PARTS USED

**Workorder: V55563**

In Date: 02/05/2013

Meter Reading: 164,152.10

Close Date: 02/08/2013

**Problem?**

C inspection

**Task performed:**

**Parts**

**Quantity**

1. C INSP
2. PATIENT COMPT FIRE EXTINGUISHER BRACKET NOT CORRECT FOR FIRE EXTINGUISHER GRIND OFF STRAP. MOUNT BRACKET IN NEW LOCATION AND INSTALL VELCROW STRAP.
3. PATIENT COMPT SHELF LOOSE AND LAYING ON FLOOR OF CABINET POSITIONED SHELF AND TIGHTENED SCREWS.
4. ADJ RADIO COMPT LATCH AND SECURE ADJ LOCK NUT.
5. REBUILD DRYER AND PIRGE VALVE.
6. PAINT FUEL CAP.
7. REPLACED BELTS.
8. DIAGNOSE NO CITY HORNS. FOUND HIGH RESISTANCE IN STEERING COLUMN CONTACT AREA. CLEAN CONTACT.
9. PATIENT COMPT LATELY BROKEN REPLACED WITH DIFFERENT STYLE LATCH REMOVED LEAKING LATCH AND MODIFIED ADJ BOLT.
10. Q.C TRUCK.
11. RELACED PATIENT COMPT HIGH BEAM.
12. BATTERY TRAY BOLTS LOOSE AND MISSING, REMOVED BATTERIES AND INSTALL BOLTS WHERE MISSING AND TIGHTENED THE OTHERS. INSTALL BATTERIES AND HOLD DOWN.
13. REPLACED DRIVERS SEAT BELT.
14. REPLACED WIPES BLADES.
15. TORQUE U-BOLTS.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
15W40BSYN OIL BULK QTS	26
252189LATCH TRIGGER W/LOCK	1
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
IMMF11358SEAT BELTS	1
R90PFILTER FUEL 33231	1
UMVS111611STRAP	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55075**

**In Date:** 01/14/2013

**Meter Reading:** 161,669.70

**Close Date:** 02/12/2013

**Problem?**

A insp SR 16

### Task performed:

1. A INSPECTION
2. LT. LENSES VERY DULL, BUFF OUT ALL REAR LENSES - BRAKE, TAIL, TURN AND BACK UP ALSO BUFF OUT LENSES ON REAR LT BAR AND TWO EMERG. LTS.
3. L-3 COMPT. HOLD OPEN HINGES FALLING OFF CHECK OUT LOOSSE HINGES - SCREWS HOLDING BLOCKS TO WALL.
4. AIR BAG SUSPENSION - AIR BAG SUSPENSION GOES FLATE IN ABOUT 2 HOURS - CHECK OUT SUSPENSION COMPONENTS - FIRST ALL THE MEASUREMENTS ON THE CONTROL RODS WERE AT DIFFERENT LENGTHS - THE HEIGHT CONTROL VALVES WERE INSTALLED WRONG REMOUNT HEIGHT VALVES - SET ALL THE CONTROL RODS TO EQUAL AND PROPER LENGTHS - SET UP HEIGHT - HEIGHT VALVES WOULD NOT MAINTAIN PROPERLY - INSTALL NEW HEIGHT VALVE AND RESET UP AGAIN - NOW HOLDS HEIGHT PROPERLY - FOUND AIR TANKS FOR BAGS WOULD LEAK DOWN 1, 2, 3 HOURS NEEDED TO CHANGE ONE SHUTTLE VALVE AND BOTH AIR DUMP VALVES NOW SYSTEM HODS PROPERLY
5. AIR SYSTEM LEAKS - THE VEHICLE AIR SYSTEM LEAKS DOWN TO 10-20 PSI IN ABOUT 5 HOURS AND ALL AIR OVERNITE - START FROM UNDER VEHICLE AND TEST FOR LAKS - ENG COMPT AND DASH - FOUND AS MANY AS EIGHT LEAKS FROM THE 3 AREAS - REPAIR ALL AND RETEST OVER NITE.
6. AIR SYSTEM SLOW TO FILL - CHECK OUT SYSTEM - AFTER SEVERAL TEST - FOUND PRIMARY CHECK VALVE IN OP AND WET/SECONDARY REPLACE BOTH AND RETEST - NOW FILLS PROPERLY.
7. RECHECK - AFTER SITTING FOR LONG WEEKEND RECHECK ALL SYSTEMS - AIR BAG SYSTEMS STILL FULL - PRIM TANK DOWN ONLY ABOUT 8 PSI AND SECONDARY DOWN AROUND 10 PSI - FOUND A VERY TINY LEAK IN ONE FITTING TIGHTEN UP NOW OK.

### Parts

### Quantity

223-485V91-8301 85 PSI CLOSED 67 OPEN PREEURE PF	1
401148DUMP VLVE AIR SLOAN	2
6804320901AIR TANK	1
800376 VALVE CHECK 90 DEG	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55846**

In Date: 02/19/2013  
Close Date: 02/20/2013

Meter Reading: 164,658.00

**Problem?**

A inspection

**Task performed:**

1. A-INSPECTION.
2. REPLACED L-4 DOOR REFLECTOR.
3. REPLACED R REAR PATIENT COMPT HIGH BEAM DOME.
4. LRO TIRE VALVE STEM STARTED LEAKING AFTER CHECKING PRESSURE. REPLACED VALVE STEM CORE AND AIRED TO PROPER PSI.

Parts	Quantity
322502BULB PATIENT GH22	1
98003RREFLECTOR RED 40132 GROTE	1

**Workorder: V56707**

In Date: 03/29/2013  
Close Date: 04/04/2013

Meter Reading: 165,897.40

**Problem?**

Quality check

**Task performed:**

CHECKED OUT TRUCK

Parts	Quantity
NO PARTS USED	

**Workorder: V50446**

In Date: 06/28/2012  
Close Date: 04/08/2013

Meter Reading: 159,581.40

**Problem?**

install stretcher hook

**Task performed:**

Parts	Quantity
6092036018J HOOK STRYKER	1

**Workorder: V52862**

In Date: 10/04/2012  
Close Date: 04/08/2013

Meter Reading: 160,477.10

**Problem?**

Rear door pin cover broken. r17

**Task performed:**

TRAVEL TO 17 REPLACED SAFETY COVER ON STRIKER PIN.

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56543**

In Date: 03/21/2013

Meter Reading: 165,511.00

Close Date: 04/22/2013

**Problem?**

Cab a/c inop R-34 Sr @ 34

**Task performed:**

Parts

Quantity

REPAIRED CAB A/C - REPAIRED CONNECTION.

NO PARTS USED

**Workorder: V56835**

In Date: 04/04/2013

Meter Reading: 166,294.50

Close Date: 05/10/2013

**Problem?**

A-inspection

**Task performed:**

Parts

Quantity

1. A-INSPECTION.
2. REFLECTIVE STRIPE - ALUMINUM REFLECTIVE STRIP WAS FIT AND TORN OUT OF RUBBER MOLDING UNDER PATIENT SIDE ENTRY - REMOVE BUMPER STRIP AND STRAIGHTEN ALIMINUM INSERT - REINSTALL IN RUBBER BUMPER AND REINSTALL ON VEHICLE.
3. REMOVE ACCREDITATION DECALS FROM SIDES OF VEHICLE - BUFF OUT AREA.
4. STARTER - REPLACE STARTER - NOTE: AT ONE TIME THIS STARTER WAS REMOVED OR REPLACE AND THE WRONG NUTS WERE USED TO REINSTALL - USS NUTS WERE FORCED ONTO METRIC STUDS - COULD NOT FIND ANY METRIC STUDS IN SHOP - HAD TO RUN DYE OVER MESSED UP THREADS - AND WAS ABLE TO FIND THREE NUTS TO MATCH NEW CUT THREADS - REINSTALL

190114036842 29MT 9 TOOTH STARTER

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58554**

**In Date:** 06/19/2013

**Meter Reading:** 167,644.60

**Close Date:** 06/27/2013

**Problem?**

no start SR16

**Task performed:**

1. START AND ROAD TEST.
2. AUTO EJECT INOP- CHECK BREAKER AND FOUND BREAKER TRIPPED - RESET CHECK FUSE AT IGNITION RELAY FUSE GOOD - PLUG IN CHARGER AND START UNIT AUTO EJECT WORKING NORMAL.
3. HARD START DIAGNOSE FAULT - FOUND FUEL FILTER HOUSING ASSEMBLY CHECK VALVE - REPLACE CHECK VALVE STILL LEAKING - USE FUEL PRESSURE TEST KIT FOUND RETURN LINE BANDED FITTING LOOSE AT BOTTOM OF MAIN FILTER SECURE BAD SO FITTING FILL PROFILTER AND OPERATE. FAULT CORRECTED.

**Parts**

**Quantity**

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
9060920510FUEL CHECK VALVE	1
N000000001070SEAL RING BANJO	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58755**

**In Date:** 06/28/2013

**Meter Reading:** 167,644.60

**Close Date:** 07/08/2013

**Problem?**

pat a/c warm

**Task performed:**

- CHECKED OUT PATIENT COMPARTMENT A/C, FOUND COMPRESSOR AND EXPANSION VALVE BAD. BEGAN CHANGING OUT FAULTY PARTS.
- CONTINUED PATIENT COMPARTMENT A/C REPAIR, REPLACED EXPANSION VALVE AND DRYER IN CONDENSER UNIT IN PATIENT COMPARTMENT. FOUND DESECANT IN EXPANSION VALVE. BLEW OUT AND CLEANED ALL RELATED HOSES AND LINES.
- CONTINUED. A/C REPAIR, CHANGED OUT COMPRESSOR, FABBED COMPRESSOR MOUNTING BRACKET ADAPT TO NEW COMPRESSOR.
- CONTINUED/COMPLETED A/C REPAIR, VACUMMED SYSTEM AND RECHARGED. TESTED SYSTEM. REAR A/C IS NOW COOLING PROPERLY. ALSO REPLACED IDLER PULLEY FOR A/C BELT. (NOISEY).
- CHECKED OUT BELT NOISES NOTICED AFTER A/C WAS COMPLETED. FOUND SERPENTENE, BELT NOISEY AND TENSIONER WARN BADLY BEGAN CHANGING BELTS AND TENSIONER.
- COMPLETED BELTS AND TENSIONER REPLACEMENT. BELTS ARE NOW QUIET AND TRACKING STRAIGHT.

**Parts**

**Quantity**

0127110042BELT MERCEDES MOTORS	1
071601A07-0602A DRIER A/C 7118	1
08-3492HFITTING A/C 5514	1
160012-2012A EXPANSION VALVE 71R8301	1
203FFBEARING PULLEY	1
532703-0602 COMPRESSOR U4735 4471	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
DDE/9062002470BELT TENSIONER MERCEDES	1

**Workorder: V59187**

**In Date:** 07/18/2013

**Meter Reading:** 167,811.00

**Close Date:** 07/18/2013

**Problem?**

A inspection, SR-16 (back from 42)

**Task performed:**

- A insp.
- replace bulb in pat. compt. lite

**Parts**

**Quantity**

322502BULB PATIENT GH22	1
-------------------------	---





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V59207**

In Date: 07/19/2013  
Close Date: 07/22/2013

Meter Reading: 167,811.00

**Problem?**

repair drawer

**Task performed:**

FOUND DRAWER SLIDE BROKEN - R&R SLIDE AND ADJUSTED - REASSEMBLED, REPAIRED AND INSTALLED SHORELINE INSIDE COVER - CHECK OK

**Parts**

**Quantity**

SLD5366HT4932-16 DRAWER SLIDE 16

1

**Workorder: V60002**

In Date: 08/23/2013  
Close Date: 09/23/2013

Meter Reading: 167,811.00

**Problem?**

Repair body damage

**Task performed:**

REMOVED BATTERIES (LEAKING). CHARGED OUT 4 BATTERIES IN PUT IN PATIENT COMPARTMENT. ALSO GOT NEW TIRE FROM INVENTORY AND PUT IN PATIENT COMPARTMENT FOR LEFT FRONT.

**Parts**

**Quantity**

A0631087000CABLE BATT. POS.

1

A0631088000CABLE BATT. NEG.

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31DBATTERY 950CCA HP-31D

4



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61816**

**In Date:** 11/05/2013

**Close Date:** 11/27/2013

**Meter Reading:** 167,811.00

**Problem?**

B inspection

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

1. B INSP.
2. REWIRE PLACARD FRAMES AND GLUE. REMOVED RIGHT FLAG DECAL. INSTALL PLASTIC FRAMES AND FLAG DECAL. MISSING ONE FRAME (ORDERED).
3. LOAD TEST BATTERIES CANNOT GET ACCURATE TEST, BATTERIES UNDER CHARGED. CHARGE BATTERIES AND RETEST (OK) FABRICATE BATTERY HOLD DOWN RODS (MISSING). DRILL HOLES FOR RODS INSTALL HOLD DOWN RODS TIGHTENED.
4. BATTERY BOX WONT LATCH- FOUND CABLES INTERFERRING WITH BACK OF COMPT. TIE STRAP CABLES UP TO BATTERY CABLES.
5. REPLACE WIPER BLADES AND SQUIRTER NOZZLES. ADJ NOZZLES FOR DIRECTION.
6. REMOVE LF SEAT FOR REPAIR.
7. COOLANT RESEVOIR DAMAGED. DRAIN COOLANT AND REMOVE HOSES AND RESEVOIR. NEW RESEVOIR TOP CAP AREA BENT. STRAIGHTEN RESEVOIR. TRNSFER LEVEL SWITCH. INSTALL RESEVOIR AND HOSES FILL SYSTEM AND LEAK CHECK.
8. REPLACED LEFT CORNER MARKER BULB CLEAN AND STRAIGHTEN CONTACTS.
9. RF SEAT BELT BUCKLE BROKEN. REPLACE SEAT BELT.
10. L/FRT AND L/REAR DOOR LAMPS BAD. REPLACED LAMPS. SPLICE AND HEAT SHRINK CONNECTIONS.
11. REPLACE FLOURESCENT BULBS IN PATIENT AREA.
12. L-3 LOOSE HINGES AND STRIKER ADJ. TIGHTEN HINGE SCREWS AND ADJ NADAR PIN.
13. FLOURESCENT LIGHT FIXTURE MISSING LENS NONE IN STOCK REPLACED FIXTURE WITH DIFFERENT STYLE. FABRICATE PLATES FOR MOUNTING DRILL AND POP RIVET PLATES FOR BODY SPLICE WIRE ENDS. HEAT SHRINK. MOUNT FIXTURES DRILL AND TAP THREADS. CLEAN FIXTURE.
14. JUMP SEAT TORN. REMOVE AND TAG SEAT FOR REPAIR.
15. ADJ HORIZONTAL PATIENT COMPT LATCH.
16. CLEAN PATIENT COMPT AND CAB.
17. CHECK TOE ANGLE- FOUND EXCESSIVE TOE IN ADJ TOE TO PROPER SPEC.
18. DIAGNOSE NO START- FOUND BROKEN WIRE TERMINAL AT BATTERY. REPLACED TERMINAL START VEHICLE AND ERASE CODES.
19. DIAGNOSE WATER IN FUEL LIGHT STAYING ON, FOUND BAD SENSOR, REPLACED SENSOR (OK).
20. SPOT LIGHT HAND HELD MISSING HANGING WIRE AND BRACKET BROKEN. REPLACED BRACKET AND INSTALL AND TIE STRAP IN SPOT

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
05-17223-000CAP RADIATOR 10 LB	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 DRYER	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
CA8193AIR FILTER 46744 WIX	1
HA24063HOOK WHEELED COACH	1
P616LIGHT ASSBLY	1
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
S PLACARDFRONT AND BACK PLACARD	1
SPRGW251WASHER NOZZLE	1
VML-T1555SURGE TANK	1
ACX-84534LUG NUT COVER PK10	10
52-24WIPER BLADES ANCO 24	2
SPRGW2612WASHER NOZZLE W/RELIEF	2
607141-05USE 61H01 COPMPARTMENT LIGHT	2
IMMF11358SEAT BELTS	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

- LIGHT TO FORM LOOP TO HANG BY.
- 21. REPLACED DAMAGED LUG NUT COVERS.
- 22. ALT BELT TORN. REMOVED BELT CHECK PULLIES- FOUND DAMAGED A/C COMPRESSOR PULLEY. RECOVER REMOVE COMPRESSOR CHECK AND ADD PROPER OIL TO NEW COMPRESSOR INSTALL COMPRESSOR. REPLACED HIGH SIDE SCHRADER CORE. VACUUM SYSTEM AND CHARGE. INSTALL BELTS TURN COMPRESSOR BY HAND 10 REVOLUTIONS. CONNECT ELECTRICAL START VEHICLE AND CHECK OPERATIONAL (OK).
- 23. REPLACE NON SKID STRIP ON SIDE PATIENT STEP. CUT TO SIDE.
- 24. ADJ AIR HORNS.
- 25. HEIGHT NOT EVEN IN REAR. (LEVEL VALVES NEW). ADJ REAR AIR BAG LEVEL VALVES FOR EVEN HEIGHT.
- 26. REMOVE FRT STROBES AND AIR HORNS FOR INSTALLATION OF DECALS.
- 27. INSTALL FRT DRIVERS SEAT AND REAR PATIENT COMPT JUMP (BACK FROM CENTRAL AUTO TRIM.
- 28. INTERMITTENT AIR LEAK ON PRIMARY SIDE. LEAK CHECK SYSTEM. REMOVE PARK BRAKE WASH PANEL AND CHECK FOR LEAK. CONNECT FIND LEAK AT THIS TIME. (HOLDING AIR).
- 29. INSTALL R/REAR PLASTIC PLACKARD FRAME.
- 30. INSTALL AIR HORNS AND STROBES AFTER STRIPING.
- 31. DIAGNOSE MORE AIR LEAKS. REPLACED MAKE SHIFT AIR CHUCK ON WETR TANK WITH PLUG.
- 32. Q.A.
- 33. REPAIR CONTACT ON R REAR DOOR SWITCH FOR LIGHT.

**Workorder: V63237**

**In Date:** 01/08/2014      **Meter Reading:** 169,270.00  
**Close Date:** 01/09/2014

**Problem?**

Noise and pull sometimes w/applying brakes

**Task performed:**

- 1. R&R FRONT.
- 2. ASSIST.

Parts	Quantity
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V63322**

In Date: 01/11/2014

Meter Reading:

Close Date: 01/14/2014

**Problem?**

Front A/C is not blowing any air out of it. R28

**Task performed:**

TRAVEL TO 28 DRIVER COMPLAINT A/C NOT BLOWING REPLACED BLOWER MOTOOR SWITCH.

Parts

Quantity

ABPN8332229011-3050 SWITCH BLOWER

1

**Workorder: V63887**

In Date: 01/31/2014

Meter Reading: 171,305.20

Close Date: 02/04/2014

**Problem?**

repalce rear tires

**Task performed:**

REPLACE REAR TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

**Workorder: V62290**

In Date: 02/11/2014

Meter Reading:

Close Date: 02/13/2014

**Problem?**

Air leak SR @55

**Task performed:**

AIR LEAK, AIR SWITCH LEAKING IN DASH. REPLACED SWITCH.

Parts

Quantity

FSC17491907NO SWITCH LOW AIR PRESSURE

2

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

**Workorder: V64217**

In Date: 02/13/2014

Meter Reading: 171,967.40

Close Date: 02/20/2014

**Problem?**

L/R/I flat

**Task performed:**

L/R FLAT.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V65004**

In Date: 03/17/2014

Meter Reading: 173,212.30

Close Date: 03/18/2014

**Problem?**

repair cab a/c

**Task performed:**

DIAGNOSE CAB A/C BLOWER INOP- FOUND BAD BLOWER MOTOR REMOVE DASH AND R&R BLOWER. SPLICE WIRING. TEST (OK) REINSTALL DASH CUT TERMINAL BLOCK FROM FAN SWITCH AND REPLACED WIRE TERMINAL.

Parts

Quantity

ABPN8330101701-0604 3924 BLOWER A/C BOA 852050000

1

**Workorder: V64177**

In Date: 02/12/2014

Meter Reading:

Close Date: 03/19/2014

**Problem?**

passenger rear window will not roll up or down. R55

**Task performed:**

REPAIRED WINDOW REGULATOR AND TESTED.

Parts

Quantity

NO PARTS USED

**Workorder: V65059**

In Date: 03/20/2014

Meter Reading: 173,212.30

Close Date: 03/21/2014

**Problem?**

A inspection

**Task performed:**

A INSP AND INFLATE LOW TIRES.

Parts

Quantity

NO PARTS USED

**Workorder: V65633**

In Date: 04/10/2014

Meter Reading:

Close Date: 04/22/2014

**Problem?**

Roof A/C unit cover blew off on Turnpike heading back to station from Training. All A/C components are exposed to weather.

**Task performed:**

NO COLEMAN A/C COVER IN PARTS UNIT, WILL BE FINE.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V64774**

In Date: 03/07/2014

Meter Reading: 173,212.30

Close Date: 04/29/2014

**Problem?**

A Inspection Cab A/C inop

**Task performed:**

Parts

Quantity

REPAIRED ON V65059.

NO PARTS USED

**Workorder: V66962**

In Date: 06/03/2014

Meter Reading: 174,586.50

Close Date: 06/17/2014

**Problem?**

repair no start issue

**Task performed:**

Parts

Quantity

won't start electrical problems.

NO PARTS USED

Vendor?: FLORIDA DETROIT DIES

**Workorder: V67247**

In Date: 06/16/2014

Meter Reading: 176,153.00

Close Date: 06/19/2014

**Problem?**

A inspection

**Task performed:**

Parts

Quantity

- 1) A services.
- 2) diagnosed csb a/c system cleaned condensor added freon checked ok.
- 3) removed driver mirror repaired bracket reinstalled.
- 4) repaired driver door warning light found broken wires repaired.  
installed valve stem extensions.

AMH-1AMH-1 VALVE EXTENSION

1

**Workorder: V67417**

In Date: 06/24/2014

Meter Reading: 176,657.00

Close Date: 06/25/2014

**Problem?**

replace right front tire

**Task performed:**

Parts

Quantity

replace right front tire

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V66290**

**In Date:** 05/06/2014

**Meter Reading:** 176,008.00

**Close Date:** 07/01/2014

**Problem?**

C inspection SR9, cab a/c inop

**Task performed:**

1. C-INSP.
2. C-INSP.
3. AFTER C-INSP VEH WOULD NOT START AFTER EACH ENG SHUT DOWN WITHOUT START AID. DIAGNOSE FUEL SYSTEM FOR AIR LEAKS.
4. AIR UP ALL 6 TIRES TO 110 PSI.
5. INSTALL NEW LOCK NUTS AND WASHERS ON AIR FILTERS HOUSING.
6. CAB DOME LIGHTS DONT COME ON WHEN OPEN DOORS. CHECK SWITCHES BOTH OK- NEED TO CHECK WIRING.
7. BEGIN R&R OF L/R CAB DOOR OUTER DOOR HANDLE AND LATCH ASSY.
8. FINISH R&R OF L/R CAB DOOR HANDLE AND LATCH ASSY.
9. REPAIR L/R DOOR PANEL MOUNTING. REMOVE SOME RIVETS AND DRILL HOLES TO INSTALL SMS ATTACHMENTS.
10. R&R GRILL INSTALL MISSING WELL NUT AND INSTALL NEW RETAINING SCREWS.
11. OVERHAUL AD-9 DRYER. HAD PROBLEM WITH BAND CLAMP AT END OF JOB. NO NEW CLAMP IN STOCK- HAD TO IMPROVISE TO MAKE THIS ONE WORK EXTRA TIME.
12. CAB A/C NOT COLD CHECK SYSTEM. R&R SCHRADRE VALVES R&R REC-DRYER EVAC AND RECHARGE SYSTEM.
13. CAB DOME LTS DONT COME ON WITH FRT DOORS. CHECK ENTIRE VEH WIRING UNTIL FOUND PROBLEM. REPAIRED CONNECTOR IN HEADLINER.
14. R&R WIPER BLADES.
15. R&R PATIENT A/C FILTER.
16. R&R CAB AUX A/C FILTER.
17. R&R CHECK VALVE IN FUEL SYSTEM AT REAR OF CYL HEAD L/S.
18. DIAGNOSE ENG NO START. CHECK FUEL SYSTEM. CHECK ENG ELCTRONIC CODES- COMPUTERS WONT READ SYSTEM. COMMLINE CORRECT. TRIED TO REMOVE HARNESS CONNECTOR ENG COMPUTER- BROKEN RELEASE SENT TO DETROIT DIESEL FOR REPAIRS.

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	2
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
07-0608A7160 DRIER A/C FRTLNR ABP-N83-319714	1
0775145PANEL FILTER	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
16-3148VALVE CORE A/C 8926	1
16-31498925 VALVE CORE	1
22-51950-000HEADLINER RETAINER PLUG	2
52-24WIPER BLADES ANCO 24	2
6807600070HANDLE DOOR EXT L/H	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9060920510FUEL CHECK VALVE	1
R90PFILTER FUEL 33231	2





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V66012**

In Date: 04/28/2014

Meter Reading:

Close Date: 07/07/2014

**Problem?**

Both A/C's in front cab blow hot R93

**Task performed:**

Parts

Quantity

REPAIRS DONE ON SREVICE,AT SHOP TICKET66290

NO PARTS USED

**Workorder: V66229**

In Date: 07/01/2014

Meter Reading:

Close Date: 07/08/2014

**Problem?**

Water leak from 110 a/c unit SR @ 33

**Task performed:**

Parts

Quantity

REPAIRED ON C SERVICE AT SHOP V66290

NO PARTS USED

**Workorder: V68337**

In Date: 08/01/2014

Meter Reading: 180,692.00

Close Date: 08/05/2014

**Problem?**

A inspection SR12

**Task performed:**

Parts

Quantity

- 1.Perform "A" Inspection.
- 2.Replace city horn. Adjust latch on patient compartment. Top off powering steering fluid.
- 3.Remove and replace driver door window trim.

A0631117000HORN HIGH NEW # 06-52125-039

1

A0631117003HORN LOW NEW #06-52125-041

1

A1834388002MOLD L/H

1

**Workorder: V68336**

In Date: 08/01/2014

Meter Reading: 180,692.00

Close Date: 08/12/2014

**Problem?**

A inspection SR9

**Task performed:**

Parts

Quantity

- 1."A" Inspection
- 2-4.Radiator remove and replace r/spot mirrir and smooth out sharp edges of oxygen holders from accident damage.
- 5.Remove and repair raidaitor. Continue from above repair.

477539HOSE & FITTING

1

980-412173 MIRROR 8 IN

1

A0516058001F10 RESCUE C RADIATOR

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V68985**

**In Date:** 08/27/2014

**Meter Reading:** 180,692.00

**Close Date:** 10/10/2014

**Problem?**

110 a/c cover, quality check

**Task performed:**

1. Start to repair and replace A/C system. 110V inoperable.

2. Repair and replace both right window regulators and crank handles. Clean out rear of rescue.

3. Repair and replace roof top A/C and install new roof top A/C. Rewire to to fit new unit.

**Parts**

**Quantity**

63152HVAC UNIT ROOF MOUNTED

1

6807200575HANDLE DOOR

1

**Workorder: V71380**

**In Date:** 12/03/2014

**Meter Reading:** 182,038.70

**Close Date:** 12/16/2014

**Problem?**

B inspection SR 9

**Task performed:**

1. Start dead spare engines and rescues in yard.

2."B" inspection and rpad test

3. Rear cab AC filter remove and install new one

4. Driver window molding broken-remove and install new molding

5. Cab AC compressor fitting leaking-recover freon-remove line-cut off fitting-install and crimp new fitting-vacuum system and charge with freeon and operate.

6. Rear light bar left upper back up light inop-remove lense-remove blown bulb-install new bulb and reassemble.

7. Left front turn signal out-remove blown bulb and install new bulb

8. SCBA tube-has sharp edges-grind down and polish ends.

9. Fire main mike damage-remove install new mike

10. Cab rear bulkhead padding fall off-clean surface install 2 sided 3m tape on padding-install padding and secure will screw.

11. Battery tray had to open-clean and lube slider

12. QC truck

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

56415CIG. LIGHTER ACCES.

1

78R536078R5360M 2PK FILTER AIR COND

1

923182-2151 SWITCH MOMENTARY 24-372

1

A1834388002MOLD L/H

1

R90PFILTER FUEL 33231

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72261**

In Date: 01/12/2015

Meter Reading:

Close Date: 01/29/2015

**Problem?**

The front driver side head light is out. R73

**Task performed:**

Parts

Quantity

1 Checked head lights. No problem found.

9007H9007 BULB ASSY

2

**Workorder: V72403**

In Date: 01/17/2015

Meter Reading:

Close Date: 01/29/2015

**Problem?**

driver side low beam headlight is out. Light only works on high beam R72

**Task performed:**

Parts

Quantity

Repaired low beam light.

H6054BLH6054CVC1 HEADLIGHT EXTRA BRIGHT

2

**Workorder: V72544**

In Date: 01/22/2015

Meter Reading:

Close Date: 01/29/2015

**Problem?**

The front left head light was turning off and on by itself. BATT 7 HQ sent Sta72 a spare head light. When Sta72 replaced the light frayed wire was noted that lead to the headlight. It was wrapped w/ elec. tape.

**Task performed:**

Parts

Quantity

Travel to ST 72. Repaired broken wire to left front head light.

NO PARTS USED

**Workorder: V72989**

In Date: 02/09/2015

Meter Reading:

183,526.20

Close Date: 02/10/2015

**Problem?**

A INSPECTION

**Task performed:**

Parts

Quantity

1. A Inspection. Top off coolant.
2. Cab marker light inop. Remove blown bulb and install new bulb.
3. Cab right rear door light inop. Found door switch faulty. Remove and install new door switch.

91823SWITCH SWT5499 MED MASTER

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10156663

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V73687**

In Date: 03/06/2015

Close Date: 03/17/2015

Meter Reading: 184,896.40

**Problem?**

Stretcher came loose

**Task performed:**

Parts

Quantity

1. Adj stretcher lock.

NO PARTS USED

**Workorder: V74471**

In Date: 04/06/2015

Close Date: 04/20/2015

Meter Reading: 30,717.00

**Problem?**

A inspection SR9

**Task performed:**

Parts

Quantity

A inspection

NO PARTS USED

**Workorder: V74286**

In Date: 03/30/2015

Close Date: 04/22/2015

Meter Reading:

**Problem?**

mud flap on left rear tire is hanging off @52

**Task performed:**

Parts

Quantity

1. Found bad ground wire- Repaired and tested will have crew monitor system.

NO PARTS USED



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10156663) 2004 - AMERICAN LAFRAN FL60 Advanced Life Support Vehicle

10156663

### CSHOP-2015-1185

Comments: PATIENT AC WARM SPARE RESCUE AT43

Date Opened: 6-15-2015 Date Finished 6-15-2015 Meter 1 Reading: 185,635

#### TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

### CSHOP-2015-1228

Comments: SR-9 AT STATION 43 MAJOR AIR LEAK

Date Opened: 6-17-2015 Date Finished 6-17-2015 Meter 1 Reading: 185,735

#### TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM

### CSHOP-2015-1312

Comments: SPARE RESCUE AT 43, STRETCHER LOCK NOT ENGAGING UNLESS IT IS FORCEFULLY HIT WITH THE STRETCHER

Date Opened: 6-22-2015 Date Finished 6-23-2015 Meter 1 Reading: 185,835

#### TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER  
CAB-INTERIOR ACCESSORIES

1 BAR; STRECHER BAR NEW

### CSHOP-2015-1518

Comments: CHECK WEAR ON FRONT DRIVERS SIDE TIRE

Date Opened: 7-2-2015 Date Finished 8-2-2015 Meter 1 Reading: 189,557

#### TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
REAR TIRES

**Asset Work Order History 10156663**

**CSHOP-2015-1541**

Comments: **A INSPECTION AUTO EJECT NOT HOLDING PLUG R43**

Date Opened: 7-6-2015

Date Finished 7-16-2015

Meter 1 Reading: 189,557

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
A INSPECTION	1	LIGHT; DOME LED LONG
OIL	-1	LIGHT; DOME LED LONG
LIGHTING SYSTEM	-2	BULB
AUTO-EJECT	2	BULB
AIR SYSTEM	1	LIGHT; LIGHT ASSBLY
DOOR	1	9IP; MOLD R/H
CAB-INTERIOR ACCESSORIES	1	FUSE; COVER FUSE PANEL
A/C FILTER SCREENS	1	FILTER; PANEL FILTER
	1	FILTER; 78R5360M 2PK FILTER AIR COND

**CSHOP-2015-2049**

Comments: **AIR LEAK WONT BUILD AIR PRESSURE SR 53**

Date Opened: 7-31-2015

Date Finished 8-8-2015

Meter 1 Reading: 189,557

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
AIR SYSTEM	1	VALVE; PURGE VALVE KIT

**CSHOP-2015-2115**

Comments: **REPLACE TIRE**

Date Opened: 8-4-2015

Date Finished 8-4-2015

Meter 1 Reading: 189,557

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** EARL COLVARD BOULEVARD TIRE

**CSHOP-2015-2374**

Comments: **SR9 C INSPECTION**

Date Opened: 8-18-2015

Date Finished 9-1-2015

Meter 1 Reading: 190,557

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
PM SERVICE C RESCUE	1	FILTER; FILTER FUEL 33231
	1	FILTER; OIL FILTER 03 57215 WIX
		MERCEDES/FREIGHTLINER
	25	FLUID; SYN OIL BULK QTS
	1	FILTER; 33634 FUEL FILTER WIX
		MERCEDES/FREIGHTLINE
	1	COUPLER; COUPLER

**Asset Work Order History 10156663**

**CSHOP-2015-2375**

Comments: **SR9 REPAIRS FROM PM**

Date Opened: 8-18-2015

Date Finished

9-1-2015

Meter 1 Reading:

190,557

**TASKS PERFORMED**

**Q PARTS**

SPOTLIGHT MOUNTING EQUIPMENT  
SCBA BRACKETS  
FIRE APPARATUS  
PANELS  
WASHER NOZZLE  
COOLING SYSTEM  
ENGINE AND ACCESSORIES  
LIGHTING SYSTEM  
FILTER  
TRANSMISSION  
AIR SYSTEM  
WINDOW CHANNEL  
DOOR  
BODY EXTERIOR  
DOOR PANEL  
CAB-INTERIOR ACCESSORIES  
HEATING AND VENTILATION  
A/C LOW FREON

3 9IP; HEADLINER RETAINER PLUG  
1 REGULATOR; 1462369 O2 REGULATOR  
1 9IP; WASHER NOZZLE  
1 9IP; WASHER NOZZLE W/RELIEF  
1 9IP; 146SL LIGHT-REMOTE SPOT  
1 FILTER; 29548988 TRANS FILTER ALLISON  
1 MODULE; 29554917 KIT MODULE  
1 MODULE; 29554917 KIT MODULE  
6 FLUID; ALLISON TRANS FLUID GAL  
2 BRAKE; CHAMBER 24/30  
1 WINDOW; MOLD L/H  
1 9IP; VENT A/C RH  
1 9IP; VENT A/C LH  
1 VALVE; 12-0615A VALVE EXPANSION FTRLNR 1606  
1 9IP; 7160 DRIER A/C FRTLNR ABP-N83-319714

**CSHOP-2015-2846**

Comments: **ON-CALL R31 IN SPARE HAS FUEL LEAK**

Date Opened: 9-11-2015

Date Finished

9-14-2015

Meter 1 Reading:

190,584

**TASKS PERFORMED**

**Q PARTS**

FUEL SYSTEM

1 LINE; A9060903376 FUEL LINE

**CSHOP-2015-2863**

Comments: **SR9 AT 31, OVERHEATING, PATIENT AC WARM LUIS AND KARL BRING BACK R31 TO STATION**

Date Opened: 9-11-2015

Date Finished

10-2-2015

Meter 1 Reading:

190,584

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM

**CSHOP-2015-3014**

Comments: **TOW UNIT TO FLORIDA DETROIT IN FORT PIERCE**

Date Opened: 9-21-2015

Date Finished

9-21-2015

Meter 1 Reading:

190,584

**TASKS PERFORMED**

**NO PARTS USED**

TOWING HITCH

**VENDOR?** WESTWAY TOWING

**Asset Work Order History 10156663**

**CSHOP-2015-3276**

Comments: **REPLACED 4 REAR TIRES**

Date Opened: 10-6-2015      Date Finished      11-3-2015      Meter 1 Reading:      191,736

**TASKS PERFORMED**

**NO PARTS USED**

REAR TIRES

**VENDOR?**      EARL COLVARD      BOULEVARD TIRE

---

**CSHOP-2015-3331**

Comments: **A INSPECTION, BACK FROM FLORIDA DETROIT FOR OVER HEAT AND FUEL LEAK**

Date Opened: 10-9-2015      Date Finished      10-13-2015      Meter 1 Reading:      190,686

**TASKS PERFORMED**

**NO PARTS USED**

A INSPECTION  
ENGINE AND ACCESSORIES

---

**CSHOP-2015-3768**

Comments: **SR@57**

Date Opened: 11-3-2015      Date Finished      11-4-2015      Meter 1 Reading:      191,843

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ELECTRICAL

**Service Requests:**

---

11/03/2015      A/C / 19: LOOSE / REPAIR  
FRONT CAB A/C IS BLOWING HOT

---

**CSHOP-2015-3997**

Comments: **ON-CALL SPARE RESCUE AT 24 BATTERY SWITCH ISSUE**

Date Opened: 11-17-2015      Date Finished      11-19-2015      Meter 1 Reading:      192,457

**TASKS PERFORMED**

**Q      PARTS**

SWITCH-ELECTRICAL

1      SWITCH; SWITCH BATTERY MASTER 300A

---

**CSHOP-2015-4406**

Comments: **A-INSP SPARE RESCUE**

Date Opened: 12-9-2015      Date Finished      12-10-2015      Meter 1 Reading:      193,973

DOT HORN NOT WORKING

**TASKS PERFORMED**

**Q      PARTS**

A INSPECTION  
TRANSMISSION  
HOSES-LINES & FITTINGS  
SAFTEY-EMERGENCY EQUIPMENT

1      HORN; HORN HIGH NEW # 06-52125-039  
1      HORN; HORN LOW NEW #06-52125-041

---



**Asset Work Order History 10156663**

**CSHOP-2015-4500**

Comments: **SR @57**

Date Opened: 12-16-2015      Date Finished 12-16-2015      Meter 1 Reading: 194,013

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

12/15/2015      A/C / 19: LOOSE / ADJUST  
HEARD HISSING SOUND FROM THE ENGINE COMPARTMENT. NOW CAB IS BLOWING HOT AIR FROM VENTS

12/16/2015      A/C / 18: LEAKING / REPAIR  
A/C IS NOT WORKING AT ALL BLOWS HOT AIR ONLY

**CSHOP-2015-538**

Comments: **A INSPECTION SR9 DAMAGE TO LEFT SIDE SCBA STORAGE COMPARTMENTS AND RUBRAIL RIGHT SIDE SCBA STORAGE DOOR MISSING**

Date Opened: 5-8-2015      Date Finished 5-12-2015      Meter 1 Reading: 185,750

**TASKS PERFORMED**

**Q      PARTS**

A INSPECTION  
DOOR  
BODY EXTERIOR

4      STRUT; GSS1715UV 30LB STRUT GAS  
1      9IP; AD0010-0 DOOR SCBA COMPT.  
22      9IP; GA48800 RUBRAIL INSET

**CSHOP-2015-669**

Comments: **ADJUST SCBA ON OFFICER SEAT ADJUST STRETCHER MOUNTING IF NEEDED**

Date Opened: 5-15-2015      Date Finished 5-22-2015      Meter 1 Reading: 185,432

**TASKS PERFORMED**

**NO PARTS USED**

SAFTEY-EMERGENCY EQUIPMENT

**CSHOP-2015-865**

Comments: **SR9 A INSPECTION**

Date Opened: 5-29-2015      Date Finished 5-29-2015      Meter 1 Reading: 185,432

**TASKS PERFORMED**

**NO PARTS USED**

A INSPECTION  
SAFTEY-EMERGENCY EQUIPMENT  
RUNNING BOARDS

**CSHOP-2015-963**

Comments: **R43 STRETCHER LOCK INOP**

Date Opened: 6-3-2015      Date Finished 6-3-2015      Meter 1 Reading: 185,535

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
STRETCHER

**Asset Work Order History 10156663**

**CSHOP-2016-1949**

Date Opened: 4-25-2016      Date Finished      4-29-2016      Meter 1 Reading:      194,307

**TASKS PERFORMED**

**NO PARTS USED**

CHARGING SYSTEM  
AIR CONDITIONING

---

**CSHOP-2016-2053**

Comments:      **SR @ ST42**

Date Opened: 4-29-2016      Date Finished      5-10-2016      Meter 1 Reading:      194,307

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM  
AIR CONDITIONING

**Service Requests:**

04/29/2016      A/C / 18: LEAKING / X  
CAB A/C IS OUT OF SERVICE, A/C ONLY BLOWS HOT AIR.

---

**CSHOP-2016-2274**

Date Opened: 5-11-2016      Date Finished      5-13-2016      Meter 1 Reading:      195,601

**TASKS PERFORMED**

**Q      PARTS**

A INSPECTION  
WIPERS-WASHER  
LIGHTING SYSTEM  
TRANSMISSION  
REAR TIRES  
REAR BRAKE PADS-SHOES  
REPAIR FROM PM - DECALS/CLEANLINESS  
AIR SYSTEM

2      BRAKE; KSMA3124710QP REAR BRAKE SHOE KIT  
2      BRAKE; BRAKE DRUM REAR

---

**CSHOP-2016-2802**

Comments:      **C SERVICE SR9**

Date Opened: 6-13-2016      Date Finished      6-16-2016      Meter 1 Reading:      196,291

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE C RESCUE

1      A/C; FREON LB  
1      FILTER; FILTER FUEL 33231  
1      FILTER; OIL FILTER 03      57215      WIX  
MERCEDES/FREIGHTLINER  
1      FILTER; 33634 FUEL FILTER      WIX  
MERCEDES/FREIGHTLINE  
24      9IP; SYN OIL QT

---

**Asset Work Order History 10156663**

**CSHOP-2016-2884**

Comments: **SPARE RESCUE AT 91**  
Date Opened: 6-16-2016      Date Finished: 6-16-2016      Meter 1 Reading: 196,329

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
TURN SIGNAL LIGHTS

**Service Requests:**

06/16/2016      HAZARD / 12: BROKEN / REPAIR  
TURN SIGNALS NOT WORKING

**CSHOP-2016-2942**

Comments: **SPARE R91**  
Date Opened: 6-20-2016      Date Finished: 6-21-2016      Meter 1 Reading: 196,663

**TASKS PERFORMED**

**Q      PARTS**

COOLING SYSTEM      1      VALVE; 3282/993282 SOLENOID VALVE SUTPHEN  
SEAT BELTS      1      9IP; IMMF11358A SEAT BELTS  
CAB-INTERIOR ACCESSORIES

**Service Requests:**

06/18/2016      SEATS / 12: BROKEN / REPAIRED  
SEATBELT DEPRESSOR ON DRIVERS SIDE SEAT IS STICKING.

**CSHOP-2016-2986**

Comments: **UNIT WILL NOT START**  
Date Opened: 6-21-2016      Date Finished: 6-30-2016      Meter 1 Reading: 197,366

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER      1      VALVE; PURGE VALVE KIT  
CRANKING SYSTEM  
AIR SYSTEM

**CSHOP-2016-3057**

Comments: **PATIENT A/C INOP ENGINE RUNNING HOT**  
Date Opened: 6-24-2016      Date Finished: 6-27-2016      Meter 1 Reading: 197,121

**TASKS PERFORMED**

**Q      PARTS**

RADIATOR      1      A/C; FREON LB  
AIR CONDITIONING

**CSHOP-2016-3162**

Comments: **OIL TO ST91 PARTS ONLY DELIVERED TO STATION**  
Date Opened: 7-1-2016      Date Finished: 8-6-2016      Meter 1 Reading: 199,234

**TASKS PERFORMED**

**Q      PARTS**

OIL      12      NEWPART; MOTOR OIL  
3      A/C; FREON LB

**Asset Work Order History 10156663**

**CSHOP-2016-3293**

Comments: **R91**

Date Opened: 7-7-2016

Date Finished

8-18-2016

Meter 1 Reading:

199,237

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?** STEWART & STEVENSON FDDA

**CSHOP-2016-3756**

Comments: **A INSPECTION FAN CLUTCH LOCKED UP**

Date Opened: 8-2-2016

Date Finished

9-7-2016

Meter 1 Reading:

199,367

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION

1

9IP; MOLD R/H

ENGINE AND ACCESSORIES

1

FILTER; PANEL FILTER

LIGHTING SYSTEM

1

BULB; BULB

BATTERY TRAY

1

LIGHT; HEADLIGHT EXTRA BRIGHT

BATTERY

1

LIGHT; HEADLIGHT EXTRA BRIGHT

DIAGNOSE ELECTRICAL

1

BULB; BULB

TRANSMISSION

1

LATCH; 11656-16 LATCH R/H MEDIC MASTER

DOOR STRIKER PLATE

1

LATCH; 11657-16 LATCH L/H MEDIC MASTER

DOOR

-4

BATTERY; BATTERY 950CCA HP-31D

DOOR LOCKS

4

BATTERY; BATTERY 950CCA HP-31D

DOOR PANEL

4

BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

SEAT FRONT

1

STARTER; 6842 29MT 9 TOOTH STARTER

CAB-INTERIOR ACCESSORIES

1

9IP; CABLE BATT. NEG.

CABIN AIR FILTER

1

9IP; BATTERY CABLE POS

AIR CONDITIONING

1

BATTERY; 549297 BATTERY INDICATOR

1

9IP; IGN SWITCH

1

ELECTRICAL; TERM BOX

1

SWITCH; SWITCH BATTERY MASTER 300A

1

CHARGER; AUTO EJECT 20 AERO OTL3925

1

LATCH; LATCH TRIGGER W/LOCK

6

PLUG; TURN PLUG

-1

LATCH; TRIGGER LATCH

1

LATCH; TRIGGER LATCH

1

FILTER; 78R5360M 2PK FILTER AIR COND

**CSHOP-2016-5223**

Date Opened: 11-3-2016

Date Finished

11-4-2016

Meter 1 Reading:

199,909

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

3

9IP; VALVE CORE

1

CAP; CAP A/C INTERNATIONAL

**Service Requests:**

11/03/2016

A/C / 12: BROKEN / REPAIR

A/C ISSUE BOTH FRONT AND BACK COMPARTMENTS NOT BLOWING COLD AIR.

**Asset Work Order History 10156663**

**CSHOP-2016-5239**

Comments: **PATIENT A/C INOP R241**

Date Opened: 11-7-2016 Date Finished 11-7-2016 Meter 1 Reading: 200,027

**TASKS PERFORMED**

**NO PARTS USED**

AIR CONDITIONING

**CSHOP-2016-5286**

Comments: **AT 41**

Date Opened: 11-9-2016 Date Finished 11-17-2016 Meter 1 Reading: 201,125

**TASKS PERFORMED**

**NO PARTS USED**

LIGHTING SYSTEM  
DIAGNOSE ELECTRICAL

**Service Requests:**

11/08/2016 SERVICE REQUEST / 19: LOOSE / REPAIR  
SERVICE REQUEST BOTH RIGHT AND LEFT TURNING SIGNALS DON'T WORK

11/12/2016 LIGHTS / 19: LOOSE / REPAIR  
RIGHT HEADLIGHT IS NOT WORKING ON R241 SPARE

**CSHOP-2016-5788**

Comments: **A INSPECTION**

Date Opened: 12-12-2016 Date Finished 12-27-2016 Meter 1 Reading: 202,158

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION  
PARK-CLEARANCE LIGHTS  
DIAGNOSE ELECTRICAL  
DOOR WEATHER MOLDING  
DOOR HINGE-PINS-BUSHINGS  
INTERIOR TRIM-MOLDINGS-UPHOLS

1 SWITCH; SWITCH BATTERY MASTER 300A

**CSHOP-2017-1183**

Date Opened: 2-25-2017 Date Finished 3-15-2017 Meter 1 Reading: 203,326

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 9IP; 33634 FUEL FILTER WIX MERCEDES/FR  
1 9IP; FILTER FUEL 33231  
1 FIL; NAPAGOLD OIL FILTER

**CSHOP-2017-2444**

Comments: **PRE TRIP INSPECTION**

Date Opened: 4-25-2017 Date Finished 4-26-2017 Meter 1 Reading: 205,389

**TASKS PERFORMED**

**NO PARTS USED**

SAFETY INSPECTION  
AM - FM RADIO  
LIGHT BAR

**Asset Work Order History 10156663**

**CSHOP-2017-3358**

Comments: **PRE TRIP**

Date Opened: 6-7-2017      Date Finished      6-7-2017      Meter 1 Reading:      205,389

**TASKS PERFORMED**

**NO PARTS USED**

QUALITY CHECK-REPAIRS

---

**CSHOP-2017-3613**

Date Opened: 6-19-2017      Date Finished      6-19-2017      Meter 1 Reading:      206,126

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SCBA BRACKETS

---

**Service Requests:**

06/17/2017      SERVICE REQUEST / 12: BROKEN / INSPECT  
SERVICE REQUEST R230 CO MONITOR DRAGER PAC 5500 ERROR CODE 240 AND 160

06/19/2017      SERVICE REQUEST / 11: BINDS/STICKS / REPAIR  
SERVICE REQUEST- SCBA MOUNT IN DRIVERS SIDE COMPARTMENT, BUCKLE IS NOT RELEASING

---

**CSHOP-2017-3773**

Date Opened: 6-26-2017      Date Finished      7-3-2017      Meter 1 Reading:      207,021

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
DOOR HANDLES    INSIDE-OUTSIDE      1      9IP; M1-63-8 LATCH STAINLESS

---

**Service Requests:**

06/24/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
DRAWER HANDLE BROKE IN PATIENT COMPARTMENT. UNABLE TO OPEN DRAWER

---

**CSHOP-2017-4109**

Comments: **@35**

Date Opened: 7-13-2017      Date Finished      7-17-2017      Meter 1 Reading:      207,473

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
WIPER BLADES      2      9IP; WIPER BLADES ANCO 24  
DIAGNOSE ELECTRICAL  
AIR CONDITIONING

---

**Service Requests:**

07/13/2017      SERVICE REQUEST / 18: LEAKING / REPAIR  
SERVICE REQUEST NEED NEW WINDSHIELD WIPERS. INCLEMENT WEATHER APPROACHING.

---

**Asset Work Order History 10156663**

**CSHOP-2017-4121**

Date Opened: 7-14-2017      Date Finished      7-15-2017      Meter 1 Reading:      207,371

**TASKS PERFORMED**

**NO PARTS USED**

---

AIR SYSTEM

**Service Requests:**

07/14/2017      SERVICE REQUEST / 18: LEAKING / REPAIR  
SERVICE REQUEST-PASSENGER SIDE AIR HORN NOT WORKING. SPARE RESCUE AT 35.

---

**CSHOP-2017-4854**

Date Opened: 8-18-2017      Date Finished      8-21-2017      Meter 1 Reading:      208,373

**TASKS PERFORMED**

**NO PARTS USED**

---

AIR CONDITIONING

**CSHOP-2017-5220**

Date Opened: 9-6-2017      Date Finished      9-6-2017      Meter 1 Reading:      208,762

**TASKS PERFORMED**

**NO PARTS USED**

---

ENGINE AND ACCESSORIES

**CSHOP-2017-6288**

Date Opened: 10-31-2017      Date Finished      11-6-2017      Meter 1 Reading:      208,936

**TASKS PERFORMED**

**Q      PARTS**

---

PM SERVICE C RESCUE

1      FIL; NAPAGOLD FUEL FILTER  
25      90C; SYN 15W40  
1      FIL; NAPAGOLD OIL FILTER  
1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPAGOLD AIR FILTER

---

**Asset Work Order History 10156663**

**CSHOP-2017-6850**

Comments: **REPAIRS FROM PM AT TIME OF REPAIRS MILES 208947 HOURS 16221**

Date Opened: 11-30-2017      Date Finished      2-9-2018      Meter 1 Reading:      212,520

**TASKS PERFORMED**

**Q      PARTS**

---

SIDE COMPARTMENT BODY	2	1AN; WIPER BLADES
WIPER BLADES	1	AVB; MINIATURE BULB
LIGHTING SYSTEM	1	9IP; MAP LIGHT LED 18 IN
ELECTRICAL	1	9IP; HORN CONTACT
FRONT TIRES	2	8HD; 18 IN 15W BULB
FRONT SPRING	1	2TK; FILTER
POWER STEERING PUMP	-1	2TK; FILTER
BRACKET	1	2TK; FILTER
REAR WINDOW		
SEAT REAR		
CAB-INTERIOR ACCESSORIES		
CABIN AIR FILTER		
AIR CONDITIONING		

---

**CSHOP-2017-83**

Date Opened: 1-4-2017      Date Finished      1-4-2017      Meter 1 Reading:      202,892

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---



**Asset Work Order History 10156663**

**CSHOP-2017-995**

Date Opened: 2-16-2017

Date Finished

3-15-2017

Meter 1 Reading:

203,326

**TASKS PERFORMED**

FAN CLUTCH  
COOLING SYSTEM  
SERPENTINE BELT TENSIONER  
SERPENTINE BELT  
OIL  
BATTERY TRAY  
BATTERY  
ALTERNATOR-GENERATOR  
CHARGING SYSTEM  
OIL COOLER-HEAT EXCHANGER  
REPAIR FROM PM - REAR SUSPENSION  
AIR DRIER  
AIR CONDITIONING

**Q**

**PARTS**

---

1	FAN; HT 650 FAN ASY.
2	2DD; GASKET
2	2DD; TRANSFER TUBE
1	BK; PTEX ULTRA BLACK 30Z
1	9IP; BEARING PULLEY
1	BELT; BELT MERCEDES RESCUE 12.5X1075 OE
1	NBH; SERPENTINE BELT
1	9IP; BELT TENSIONER MERCEDES
1	BRG; TRAN/BRG
1	2FL; BELT TIGHTENER
4	1AD; BATTERY 31 SERIES
1	ALTERNATOR; 320 UPGRADE ALTERNATOR
1	5TN; AUTO CHAGRE 2000
1	2FL; OIL COOLER GASKET
1	2FL; O RING SEAL
2	2FL; O RING SEAL
1	2FL; SENSOR OIL PRESSURE
1	2FL; SEAL O RING
1	2FL; OIL GASKET
1	2FL; OIL COOLER GASKET
1	2FL; TEMP SENSOR OIL
1	9HY; 9HY
2	NTH; COUPLER
2	9IP; VALVE LEVELIN
2	9IP; 16-19471-000 AIR BAG
1	9IP; PURGE VALVE KIT
1	9IP; A/C FITTING 4324
1	BK; 20 GAL POLY SPRAYER
4	9XX; 134A 10194654
5	9XX; 134A 10194654
1	NEWPART; A/C DYE
1	A/C; 17-3428 ESTER OIL E7
1	9IP; 7160 DRIER A/C FRTLNR ABP-N83-319714
1	NCB; PURPLE POWER 40 OZ
1	9IP; NODE HERCULES V-MUX
1	9IP; 03-0607 A/C COMPRESSOR U4482 USE 7169 D

---

**CSHOP-2018-1489**

Date Opened: 3-13-2018

Date Finished

3-13-2018

Meter 1 Reading:

214,169

**TASKS PERFORMED**

PM SERVICE B

**Q**

**PARTS**

---

1	FIL; NAPAGOLD FUEL FILTER
26	9IP; 15W40 MOTOR OIL NON SYN
1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD FUEL FILTER

---

**Asset Work Order History 10156663**

**CSHOP-2018-1603**

Comments: **REPAIRS FROM PM**

Date Opened: 3-19-2018

Date Finished

3-30-2018

Meter 1 Reading:

214,169

**TASKS PERFORMED**

**Q PARTS**

PROXIMITY SWITCH	1	9IP; SWITCH DOOR LGHT
WIPER BLADES	2	1AN; 22" WIPER BLADE
OXYGEN SENSOR	3	9ME; ZICO RATCHET STRAPS
FUEL TANK	1	BK; CLAMP
EXHAUST SYSTEM	5	FLUID; COOLANT ANTIFREEZE GAL
COOLING SYSTEM	5	9OC; GEAR OIL BULK
MULTIFUNCTION SWITCH	-5	9OC; GEAR OIL BULK
PARK-CLEARANCE LIGHTS	1	2FL; SWITCH
WIRING	1	2FL; HOUSING
AUTO-EJECT	1	6KU; COVER, ROUND, YELLOW
TRANSMISSION	1	FIL; NAPA TRANS FILTER
DIFFERENTIAL	-17	9OC; BULK TRANS SYN
TIRE	3	9OC; BULK TRANS SYN
RESERVOIR	17	9OC; BULK TRANS SYN
AIR DRIER	5	9IP; ALLISON TRANS FLUID GAL
AIR SYSTEM	14	GEAR; GEAR OIL SYN QT
AIR BAG SYSTEM	14	9OC; GEAR OIL BULK
FIRE EXTINGUISHER	-14	9OC; GEAR OIL BULK
AIR HORN	1	FIL; NAPA HYDRAULIC FILTER
DOOR WEATHER MOLDING	-4	9OC; BULK TRANS SYN
DOOR HINGE-PINS-BUSHINGS	4	9OC; BULK TRANS SYN
DOOR PANEL	4	9IP; ALLISON TRANS FLUID GAL
INSTRUMENTS-GAUGES-WARNING & HEATING AND VENTILATION	1	TWD; AD-9KIT MINOR
A/C FILTER SCREENS	1	TWD; AD-9KIT
	2	2DD; AIR BAG
	1	9HD; KIT
	1	2FL; MOLDING LH
	1	9IP; MOLD R/H
	1	9IP; 18-2640 VENT A/C NEW # 1719

**CSHOP-2018-179**

Date Opened: 1-9-2018

Date Finished

1-9-2018

Meter 1 Reading:

210,208

**TASKS PERFORMED**

**NO PARTS USED**

DOOR LATCH

**CSHOP-2018-1971**

Comments: **R48**

Date Opened: 4-9-2018

Date Finished

4-19-2018

Meter 1 Reading:

214,534

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER CAB-INTERIOR ACCESSORIES	1	2FL; LH WINDOW REGULATOR
--	---	--------------------------

**Service Requests:**

04/07/2018 WINDOW / 18: LEAKING / REPAIR  
DRIVER SIDE WINDOW WONT CLOSE COMPLETELY

**Asset Work Order History 10156663**

**CSHOP-2018-2326**

Comments: **R230 CALL BACK**

Date Opened: 4-28-2018

Date Finished 4-30-2018

Meter 1 Reading: 214,773

REAR DOOR INOP.

**TASKS PERFORMED**

**Q PARTS**

DOOR

1	9LO; REAR DOOR HANDLE
1	HANDLE; REAR DOOR HANDLE R/H HORTON

**Service Requests:**

---

04/28/2018 DOOR / 12: BROKEN / REPAIR  
VEHICLE DOOR FOR THE REAR PATIENT LOADING IS MALFUNCTIONING. THE DOOR WILL NOT OPEN FORM THE OUTSIDE. IT IS THE SPARE RESCUE AT STATION 30 DESIGNATED R230.

---

**CSHOP-2018-2373**

Comments: **SPARE RESCUE AT STATION 30**

Date Opened: 5-1-2018

Date Finished 5-7-2018

Meter 1 Reading: 215,212

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER

**Service Requests:**

---

05/01/2018 A/C / 18: LEAKING / REPAIR  
A/C ISSUE... LEAK FOUND WITHIN THE PATIENT COMPARTMENT AFTER ODD SMELL OF MOLD WAS NOTICED. POSSIBLY COMING FROM A/C.

---

**CSHOP-2018-2502**

Comments: **R230**

Date Opened: 5-7-2018

Date Finished 5-15-2018

Meter 1 Reading: 215,700

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ELECTRICAL

**Service Requests:**

---

05/06/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
THERE IS NO WAY TO CHARGE THE SAFETY PAD IN THE RESCUE. IT HAS TO BE TAKEN INTO THE STATION TO CHARGE. CAN AN CHARGING PORT BE ADDED TO THE TRUCK?

---

**Asset Work Order History 10156663**

**CSHOP-2018-2737**

Date Opened: 5-17-2018

Date Finished

6-12-2018

Meter 1 Reading:

215,927

**TASKS PERFORMED**

**Q PARTS**

STRETCHER	2	9AP; STRYKER BAR
CAB	2	5AH; GAS SPRING, 7.5", 29LB
SEAT FRONT	1	9IP; PLS11W/TUV BULB A/C RESCUES
AIR CONDITIONING	1	9AP; BLOWER MOTOR 12V UNIVERSAL
	1	TEM; T SWITCH
	1	WLD; BRASS WIRE BRUSH
	1	9HD; TAPE
	1	9HY; FITTINGS
	1	9AP; 9AP
	1	TEM; STEEL FILTER DRIER
	1	TEM; EXPANSION VALVE
	1	CRC; FOAMING COIL CLEANER

**Service Requests:**

05/17/2018 A/C / 18: LEAKING / REPAIR  
A/C ISSUE PT COMPARTMENT A/C NOT FUNCTIONING

05/18/2018 A/C / 18: LEAKING / REPAIR  
A/C ISSUE... A/C IN PATIENTS COMPARTMENT WILL TURN ON AND OFF WHILE THE VEHICLE IS IN MOTION. HOWEVER, MOST OF THE TIME THE A/C WILL NOT WORK AT ALL AND PATIENTS HAVE BEEN COMPLAINING.

**CSHOP-2018-325**

Comments: **SPARE RESCUE AT 19**

Date Opened: 1-16-2018

Date Finished

1-23-2018

Meter 1 Reading:

211,357

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
BODY EXTERIOR

**Service Requests:**

01/13/2018 BODY / 18: LEAKING / REPAIR  
BODY ISSUE, FRONT OFFICER SIDE BUMPER IS MISSING TWO BOLTS. BUMPER IS LOOSE

**CSHOP-2018-3865**

Comments: **SPARE RESCUE AT 51**

Date Opened: 7-9-2018

Date Finished

7-9-2018

Meter 1 Reading:

217,227

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

07/07/2018 A/C / 18: LEAKING / REPAIR  
AC IN DRIVER COMPARTMENT BLOWING HOT

**Asset Work Order History 10156663**

**CSHOP-2018-4098**

Date Opened: 7-21-2018      Date Finished      8-21-2018      Meter 1 Reading:      218,562

**TASKS PERFORMED**

**Q      PARTS**

DOOR      1      5EF; HORTON DOOR HANDLE RR SQUARE

**Service Requests:**

07/21/2018      BODY / 12: BROKEN / EXCHANGE - NEW  
BODY ISSUE. BACK PATIENT COMPARTMENT DOOR WONT OPEN. THE BACK LEFT DOOR TO THE RESCUES HANDLE IS BROKEN AND NOT ALLOWING THE DOOR TO OPEN.

**CSHOP-2018-4333**

Comments:      **R33**  
Date Opened: 8-2-2018      Date Finished      8-13-2018      Meter 1 Reading:      218,562

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE APPARATUS  
DOOR  
BODY EXTERIOR

**Service Requests:**

08/02/2018      BODY / 12: BROKEN / REPAIR  
BODY ISSUE- RIGHT BACK DOOR ON PATIENT COMPARTMENT IS BENT ON THE BOTTOM LEFT CORNER

08/02/2018      BODY / 12: BROKEN / REPAIR  
BODY ISSUE- PAINT IS PEALING OFF ON PASSENGER SIDE FRONT BODY PANEL BEHIND THE AIR HORN

08/02/2018      BODY / 12: BROKEN / REPAIR  
BODY ISSUE- FF SPARE SCBA TANK HOLDER IS MISSING PART OF COMPARTMENT CHUNK OF METAL MISSING FROM COMPARTMENT DOOR

**CSHOP-2018-4374**

Date Opened: 8-6-2018      Date Finished      8-7-2018      Meter 1 Reading:      218,562

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
HEADLIGHTS LOW BEAM

**Service Requests:**

08/04/2018      LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
PASSENGER SIDE HEADLIGHT IS NOT WORKING

08/04/2018      LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
VEHICLE LIGHTS NOT WORKING

**Asset Work Order History 10156663**

**CSHOP-2018-5581**

Date Opened: 10-1-2018      Date Finished      10-1-2018      Meter 1 Reading:      219,431

**TASKS PERFORMED**

**NO PARTS USED**

---

CAB-INTERIOR ACCESSORIES

**Service Requests:**

-----  
10/01/2018      DOOR / 18: LEAKING / REPAIR  
VEHICLE DOORS- DRIVER WINDOW OPEN AND DOES NOT GO UP.  
-----

**CSHOP-2018-5628**

Comments:      **SPARE RESCUE AT STATION 47 CHECK THE REAR TIRES AND ADVISE IF NEW ONES ARE NEEDED.**

Date Opened: 10-3-2018      Date Finished      10-3-2018      Meter 1 Reading:      219,431

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
TIRES & WHEELS

**Service Requests:**

-----  
10/02/2018      TIRES / 18: LEAKING / REPAIR  
BOTH REAR OUTSIDE TIRES WORN DOWN 265/70 R 19.5  
-----

**CSHOP-2018-5790**

Date Opened: 10-14-2018      Date Finished      10-16-2018      Meter 1 Reading:      220,397

**TASKS PERFORMED**

**Q      PARTS**

---

AIR DRIER

1      TWD; AD-9KIT MINOR

**CSHOP-2018-5830**

Date Opened: 10-15-2018      Date Finished      10-15-2018      Meter 1 Reading:      220,397

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRES ALL

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

**CSHOP-2018-5896**

Date Opened: 10-17-2018      Date Finished      10-17-2018      Meter 1 Reading:      220,397

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
DIAGNOSE ELECTRICAL  
AIR CONDITIONING

**Asset Work Order History 10156663**

**CSHOP-2018-6055**

Date Opened: 10-24-2018      Date Finished      11-1-2018      Meter 1 Reading:      220,864

**TASKS PERFORMED**

QUALITY CHECK-REPAIRS  
A INSPECTION  
HEADLIGHTS LOW BEAM  
AIR CONDITIONING

<b>Q</b>	<b>PARTS</b>
2	LMP; LAMP
2	9IP; FUSE 15 AMP NEW #BR315
2	MPE; RELAY
2	9IP; TUBE HOLDER ORIFACE
4	9XX; 134A 10194654
1	9HY; HOSE MADE
1	2TP; PAD FITTING
2	2CU; CONNECTOR
1	9IP; FITTING AC

---

**CSHOP-2018-6440**

Date Opened: 11-13-2018      Date Finished      11-16-2018      Meter 1 Reading:      220,864

**TASKS PERFORMED**

PM SERVICE C RESCUE

<b>Q</b>	<b>PARTS</b>
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD FUEL FILTER
26	4PC; 15W40 PREMIUM BLUE OIL

---

**CSHOP-2018-6463**

Date Opened: 11-14-2018      Date Finished      11-16-2018      Meter 1 Reading:      220,864

**TASKS PERFORMED**

WIPERS-WASHER  
REPAIR FROM PM - PATIENT COMPT  
LIGHTING SYSTEM  
REPAIR FROM PM - HOSES  
AIR HORN  
AIR CONDITIONING

<b>Q</b>	<b>PARTS</b>
2	1AN; 20" WIPER BLADE
4	8HD; 18 IN 15W BULB
3	9HD; KIT
1	BK; PTEX ULTRA GREY 3OZ
4	9AP; BRAKE CLEAN

---

**CSHOP-2019-1594**

Date Opened: 3-27-2019      Date Finished      4-8-2019      Meter 1 Reading:      221,315

**TASKS PERFORMED**

QUALITY CHECK-REPAIRS  
PARK-CLEARANCE LIGHTS  
CHARGING SYSTEM  
SWITCH-ELECTRICAL  
DOOR GLASS  
BODY EXTERIOR  
INTERIOR TRIM-MOLDINGS-UPHOLS

<b>Q</b>	<b>PARTS</b>
1	9IP; HANDLEWINDOW
1	2FL; MOLDING LH

---

**Asset Work Order History 10156663**

**CSHOP-2019-2316**

Date Opened: 5-1-2019      Date Finished      5-1-2019      Meter 1 Reading:      221,319

**TASKS PERFORMED**

**Q      PARTS**

---

CRANKING SYSTEM

4      1AD; BATTERY 31 SERIES

---

**CSHOP-2019-3232**

Date Opened: 6-21-2019      Date Finished      6-25-2019      Meter 1 Reading:      222,688

**TASKS PERFORMED**

**Q      PARTS**

---

MIRRORS  
AIR CONDITIONING

1      CRC; FOAMING COIL CLEANER

---

**CSHOP-2019-3867**

Date Opened: 7-25-2019      Date Finished      7-25-2019      Meter 1 Reading:      222,703

**TASKS PERFORMED**

**Q      PARTS**

---

PARK-CLEARANCE LIGHTS  
LIGHT BAR  
BODY EXTERIOR

1      GRO; CLRMKRLAMP  
2      MMM; MARINE5200FASTCURE  
1      MMM; MARINEADHSEALWHITE

---

**CSHOP-2019-4589**

Comments:      **HEAD LINER**

Date Opened: 8-28-2019      Date Finished      8-29-2019      Meter 1 Reading:      223,801

**TASKS PERFORMED**

**NO PARTS USED**

---

CAB

---

**CSHOP-2019-4590**

Comments:      **AT STATION 55 SAYS ON BOARD**

Date Opened: 8-28-2019      Date Finished      8-29-2019      Meter 1 Reading:      223,801

**TASKS PERFORMED**

**NO PARTS USED**

---

BODY - WORK COMPARTMENT EMER

**Service Requests:**

---

08/27/2019      SERVICE REQUEST / 19: LOOSE / REPAIR  
BACK UPPER DOOR PANEL IN PATIENT COMPARTMENT FALLING OFF WILL NOT STAY ATTACHED TO UPPER SILL

---



**Asset Work Order History 10156663**

**CSHOP-2019-479**

Comments: **CHECK CAB AND PAT A/C**

Date Opened: 1-25-2019      Date Finished 1-31-2019      Meter 1 Reading: 220,918

**TASKS PERFORMED**

AIR CONDITIONING

<b><u>Q</u></b>	<b><u>PARTS</u></b>
5	9XX; AC FREON 10199801
1	9IP; SWITCH A/C HIGH PRESSURE
5	9XX; AC FREON 10199801
1	TEM; FIL/DRY
1	TEM; ACCUMLTR
1	9HY; FITTINGS
1	BK; SPRAYER

**CSHOP-2019-4831**

Date Opened: 9-12-2019      Date Finished 9-17-2019      Meter 1 Reading: 223,917

**TASKS PERFORMED**

PM SERVICE B

<b><u>Q</u></b>	<b><u>PARTS</u></b>
1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; FIL

**CSHOP-2019-4856**

Date Opened: 9-13-2019      Date Finished 9-17-2019      Meter 1 Reading: 223,917

**TASKS PERFORMED**

RADIATOR  
AIR BAG SYSTEM  
DOOR HANDLES INSIDE-OUTSIDE

<b><u>Q</u></b>	<b><u>PARTS</u></b>
1	2FL; RAD CORE
2	2DD; AIR BAG
1	2FL; HANDLE, DOOR

**CSHOP-2019-5507**

Comments: **SPARE RESCUE AT 31**

Date Opened: 10-18-2019      Date Finished 1-10-2020      Meter 1 Reading: 225,130

**TASKS PERFORMED**

COOLING SYSTEM

**NO PARTS USED**

**Service Requests:**

10/18/2019      SERVICE REQUEST / 18: LEAKING / INSPECT  
                    COOLANT LEAK

**Asset Work Order History 10156663**

**CSHOP-2019-5555**

Comments: **SPARE AT 31**

Date Opened: 10-21-2019      Date Finished 10-30-2019      Meter 1 Reading: 225,130

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
QUALITY CHECK-REPAIRS  
WIPER BLADES  
COOLING SYSTEM  
SPOT LIGHTS  
SIREN  
BODY EXTERIOR  
CAMERA-MONITOR

2      1AN; WIPER BLADES  
1      2FL; HORN KIT LOW  
1      2FL; HORN KIT HIGH  
1      9ES; CAM SYS REAR VIEWLOOSE WIRE MECH MNT

**Service Requests:**

10/19/2019      RADIATOR / 18: LEAKING / REPAIR  
RADIATOR LEAKING- SLOW LEAK

**CSHOP-2019-606**

Date Opened: 1-31-2019      Date Finished 1-31-2019      Meter 1 Reading: 220,918

**TASKS PERFORMED**

**Q      PARTS**

CAMERA-MONITOR

1      9AP; LOOSE WIRE MECH MOUNT

**CSHOP-2019-6166**

Date Opened: 11-26-2019      Date Finished 11-26-2019      Meter 1 Reading: 225,130

**TASKS PERFORMED**

**NO PARTS USED**

VENDOR TIRE REPAIR/CHANGE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

**CSHOP-2019-887**

Comments: **PRE-TRIP RIGHT SIDE MIRROR LOOSE**

Date Opened: 2-15-2019      Date Finished 3-6-2019      Meter 1 Reading: 221,170

**TASKS PERFORMED**

**Q      PARTS**

PRE TRIP INSPECTION  
CRANKING SYSTEM  
AIR SYSTEM  
MIRRORS  
CAB-INTERIOR ACCESSORIES

2      MAC; SILICONE SPRAY 10OZ  
1      5EF; RH SIDE ENTRY HNDL LOCKING  
4      1AD; BATTERY 31 SERIES  
2      GRO; OEMSTYLE BOX MIRROR  
4      GRO; STEEL L BRACKET  
1      GRO; OEMSTYLE BOX MIRROR  
1      GRO; CONVEX MIRROR  
1      9IP; HT4932-16 DRAWER SLIDE 16  
1      9IP; HT4932-16 DRAWER SLIDE 16

**Asset Work Order History 10156663**

**CSHOP-2020-4034**

Comments: ROAD

Date Opened: 8-5-2020 Date Finished 8-18-2020 Meter 1 Reading: 225,357

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM  
A/C SYSTEM

**CSHOP-2020-4468**

Comments: NO OIL AND FILTERS

Date Opened: 8-28-2020 Date Finished 9-28-2020 Meter 1 Reading: 225,365

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE C RESCUE

**RADIO-2018-525**

Comments: REMOVE 10152159, INSTALL10208471 INTO SPARE RESCUE 4 - 10156663

Date Opened: 5-21-2018 Date Finished 5-21-2018 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

05/21/2018 RADIO / /  
REMOVE AND INSTALL MOBILE RADIO INTO SPARE RESCUE 4

**RADIO-2019-119**

Date Opened: 2-11-2019 Date Finished 2-11-2019 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

RADIO

**Service Requests:**

02/11/2019 RADIO / /  
REPLACED MDC POWER SUPPLY IN SPARE RESCUE AT STATION 37.

**SSHOP-2019-189**

Date Opened: 6-14-2019 Date Finished 6-14-2019 Meter 1 Reading: 222,313

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

3 9IP; FREON LB  
-3 9XX; 10177987 AC RECYCLER  
3 9XX; 10177987 AC RECYCLER