



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V035**

In Date: 01/01/1900  
Close Date: 10/07/2005

Meter Reading:

**Problem?**

STROBE LIGHT INOP, B-21

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V545**

In Date: 11/14/2005  
Close Date: 11/15/2005

Meter Reading:

**Problem?**

CHECK ENGINE LIGHT ON B21

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V343**

In Date: 10/27/2005  
Close Date: 12/07/2005

Meter Reading:

**Problem?**

exhuast damaged

Task performed:

Parts

Quantity

33961C35976 MUFFLER CLAMP

2

35799FLAT CLAMP 4 IN

2

40011EXHAUST FLEX 4 IN

10

**Workorder: V838**

In Date: 12/08/2005  
Close Date: 12/15/2005

Meter Reading:

**Problem?**

CHAIN SAW MISSING LARGE NUT ON CHAIN BAR, B-21

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V921**

In Date: 12/14/2005

Meter Reading:

Close Date: 03/20/2006

**Problem?**

L/SIDE STROBE LIGHT IN REAR INOP, B-21

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V1777**

In Date: 03/08/2006

Meter Reading:

Close Date: 03/27/2006

**Problem?**

PLATE UNDER RT REAR AIR BRAKE CAME OFF, B-21

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2084**

In Date: 04/04/2006

Meter Reading:

Close Date: 04/06/2006

**Problem?**

MARKER LIGHT INOP, PUMP PACKING, B-21

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V2292**

In Date: 04/18/2006

Meter Reading:

Close Date: 04/25/2006

**Problem?**

L/REAR STROBE LIGHT INOP, NEED AKRON 1702 NOZZLE, B-21

Task performed:

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V2479**

In Date: 05/04/2006

Meter Reading:

Close Date: 05/15/2006

**Problem?**

CHECK ENGINE LITE ON, B-21

**Task performed:**

See B Inspection pre-printed form

Parts

Quantity

NO PARTS USED

**Workorder: V2623**

In Date: 05/15/2006

Meter Reading:

Close Date: 06/02/2006

**Problem?**

REPLACE 2 FRONT TIRES, B-21 (CALLAGHAN)

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214

**Workorder: V2894**

In Date: 06/07/2006

Meter Reading:

Close Date: 06/08/2006

**Problem?**

CHECK ENGINE LIGHT ON, B-21

**Task performed:**

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V2909**

**In Date:** 06/08/2006

**Close Date:** 06/30/2006

**Meter Reading:** 9,270.00

**Problem?**

B INSPECTION, B-21

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

02036257300LINEAR REF. ASSY.	2
05-17223-000CAP RADIATOR 10 LB	1
1250STOW SHACKLE	1
18-45484-000LATCH L/H	1
19002YLIGHT MARKER AMBER	2
19200R46742 RED MARK/LIGHT 4 IN MARKER LIGHT	2
24-60BATTERY GROUP 24	1
24F-60BATTERY	1
38171048 PER PACK PACKING-PUMPS DARLEY	1
4020362171 GRO LAMP DOME 4 IN	2
4070091740 GROMMET T/L 4 IN	1
4419BULB	3
4579SRNO. 8 SPLICE REDUCED BARRIER HOSE	1
46792LIGHT MARKER	2
4MJ21CABLE ELECTRICAL	1
716907-0610A DRYER	1
8201L17-3428 ESTER OIL E7	1
91378905 VALVE KIT 2 IN AKRON	2
91388906 VALVE KIT 2.5 IN AKRON	3
91398907 VALVE KIT 3 IN AKRON	1
94993PIGTAIL TRUCKLITE 3-WIRE	1
A06-31083-000BATTERY CABLE POS	2
A22-41331-048A/C HOSE	1
AG-RDECK LIGHT ROUND BASE	2
B138-15ALENS AMBER	1
CA8193AIR FILTER 46744 WIX	1
CA8737AIR FILTER WIX 46562 L/F LAF4544	1
DOSZ-14448-ADOSZ-14448-A JUNCTION	1
FP588F33393 FUEL FILTER ISUZU 8-94414796	1
FREIGHTSHIPPING CHARGES	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	2
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R20P33614 FILTER FUEL	1
R90PFILTER FUEL 33231	1
S775COUPLER	1
U-24RWIPER REFILL	1
LFP5748FILTER OIL 57411	1
7001-30ESEAL	2
91368904 VALVE KIT 1 1/2 IN	2

Vendor?: EAST0002



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V3588**

In Date: 07/21/2006

Meter Reading:

Close Date: 07/27/2006

**Problem?**

two strobes on front of brush truck 10-7 b 21

**Task performed:**

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBE	3
68318341650AUSE 602000RU COMPLETE UNIT	4

**Workorder: V4045**

In Date: 08/21/2006

Meter Reading:

Close Date: 08/25/2006

**Problem?**

CHECK AND ADJUST PUMP PACKING B21

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V4148**

In Date: 08/28/2006

Meter Reading:

Close Date: 09/06/2006

**Problem?**

Hand Light does not work B21

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V4163**

In Date: 08/29/2006

Meter Reading:

Close Date: 10/10/2006

**Problem?**

check engine light on B 21 CUMMINS SE POWER

**Task performed:**

1. SENT B21 TO CUMMINS FOR CHECK ENGINE LIGHT.

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V4814**

In Date: 10/10/2006

Meter Reading:

Close Date: 10/16/2006

**Problem?**

emergency light on passenger side of b-21 is out

**Task performed:**

1. OLD BOLT STRIPED OUT. DRILL NEW HOLES, INSTALL NEW LIGHT AND TEST. TEST PASSED, NOW IN GOOD ORKING ORDER.

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

**Workorder: V5053**

In Date: 10/24/2006

Meter Reading:

Close Date: 10/25/2006

**Problem?**

Rear diff. breather missing spitting out oil. B21

**Task performed:**

1. WAIT FOR TRUCK, OUT ON A CALL.  
2. INSTALL NEW PLUG FOR VENT.

Parts

Quantity

NO PARTS USED

**Workorder: V5142**

In Date: 10/30/2006

Meter Reading:

8,374.00

Close Date: 11/14/2006

**Problem?**

UNIT STUCK ON CALL B21

**Task performed:**

1. winched brush truck out of mud

Parts

Quantity

NO PARTS USED

**Workorder: V6008**

In Date: 12/29/2006

Meter Reading:

Close Date: 01/03/2007

**Problem?**

Pump Packing Leaking bad B21

**Task performed:**

1. Adjusted pump packing

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V6202

In Date: 01/10/2007

Meter Reading: 8,374.00

Close Date: 01/16/2007

#### Problem?

Front right side strobe and right rear yellow strobe light not working. B21

#### Task performed:

1. R&R strobe lights ok

#### Parts

#### Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

2

### Workorder: V7790

In Date: 04/18/2007

Meter Reading: 936.00

Close Date: 05/03/2007

#### Problem?

b21 leaking water from main pump drain and packing

#### Task performed:

Repack pump; piping leaking; must lift pump up to replace.

Discussed with Ed E.

Rework coupling; test-ok

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V7855

In Date: 04/21/2007

Meter Reading: 977.00

Close Date: 05/03/2007

#### Problem?

Brush 21 has a emergency light that is located on the drivers side inbetween the cabinet doors that is out. Plus, even after the pump was repacked the pump is still leaking water.

#### Task performed:

Installed strobe lite; fnd bad cable & replaced; test ok

#### Parts

#### Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

373-2.5E-Z LOK BRACKET

5

38090003809000 GASKET DISCHARGE

2

7001-40ESEAL 4 IN

1

### Workorder: V8073

In Date: 05/03/2007

Meter Reading: 977.00

Close Date: 05/15/2007

#### Problem?

The B21 cab pump throttle is inoperative.

#### Task performed:

Fnd throttle stripped @ fitting; repair temper; did not have part on truck

R/R pump throttle; test ok.

#### Parts

#### Quantity

VCGTHOCONTROL

1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V9185

In Date: 07/06/2007  
Close Date: 07/09/2007

Meter Reading: 1,002.00

#### Problem?

Left front strobe lens cover is broken at screws and is about to fall off. Right rear marker light out.

#### Task performed:

1. DRIVE TO STA. R/R LENS COVER. TEST-OK.

#### Parts

68318341650AUSE 602000RU COMPLETE UNIT

#### Quantity

1

### Workorder: V10064

In Date: 08/22/2007  
Close Date: 09/11/2007

Meter Reading: 11,000.00

#### Problem?

A INSPECTION B-21

#### Task performed:

A-Inspection  
Rep marker lights

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V10077

In Date: 08/23/2007  
Close Date: 09/12/2007

Meter Reading: 1,002.00

#### Problem?

Pump pressure gauge in cab not reading the correct pressure B21

#### Task performed:

1. Drive to Stn; chk gauge; fnd sender bad; did not have one on truck  
2. Drive to stn; R/R sender; repack pump; test ok

#### Parts

102161TRANSDUCER 500 PSI  
322502BULB PATIENT GH22

#### Quantity

1  
2

### Workorder: V10169

In Date: 08/29/2007  
Close Date: 09/18/2007

Meter Reading: 1,002.00

#### Problem?

Need new case for chain saw. b21

#### Task performed:

Drive to Stn; put new case on chain saw

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V10904**

**In Date:** 10/09/2007

**Meter Reading:** 11,000.00

**Close Date:** 10/22/2007

**Problem?**

adjust pump packing b21

**Task performed:**

Drive to Stn; installed packing; test run ok

Parts

38171048 PER PACK PACKING-PUMPS DARLEY

Quantity

8

---



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

Workorder: V11874

In Date: 12/03/2007

Meter Reading: 11,000.00

Close Date: 12/10/2007

**Problem?**

C inspection and repairs as needed b21

**Task performed:**

1. Pick up and drop off truck at Sta. 21
2. "B" inspection
3. Service air dryer
4. Service pump gear case.
5. Service cooling system.
6. Service front and rear axles
7. Service transfer case.
8. Service transmission.
9. Door open warning alarm intermittent, repair all comp latches adjust and tighten all comp door strikes.
10. Replace all belts.
11. Replace wipers.
12. Air leak, replace governor.
13. Service float pumps (2)
14. SERVICE POWER STEERING.
15. Pack pump
16. R+R slack adj. over stroke, replace stack adj.
17. Drive batteries failed load test, replace batteries.

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	43
284358GOVERNOR D-2	1
29526898 29548988 TRANS FILTER ALLISON	1
496894496894 AIR FILTER	1
52-24WIPER BLADES ANCO 24	2
7534-B6HSSPARK PLUG	1
800405PURGE VALVE KIT	1
9510BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
CA8193AIR FILTER 46744 WIX	1
CA8737AIR FILTER WIX 46562 L/F LAF4544	1
FP588F33393 FUEL FILTER ISUZU 8-94414796	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	2
HPH6349AOIL FILTER 51748	1
J19LMUSE 1147 NGK SPARK PLUG	1
K080680BELT SAME AS 3281981 CUMMINS	1
LFP5748FILTER OIL 57411	1
PR338324070 WIX FILTER WATER	1
R20P33614 FILTER FUEL	1
R801073SLACK ADJUSTER ENG	2
R90PFILTER FUEL 33231	1
RK211131311FUEL BOWL KIT NON-HEATED	1
S448GAUGE TIRE TREAD DEPTH	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1
VML-T1413T3248 SIGHT GLASS	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V7067

In Date: 03/05/2007

Meter Reading: 925.00

Close Date: 12/10/2007

#### Problem?

Needs new pump packing.

#### Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V11797

In Date: 11/29/2007

Meter Reading: 11,000.00

Close Date: 12/12/2007

#### Problem?

PUMP PACKING LEAKING, NUMBER SIGN FALLING OFF, B-21

#### Task performed:

Parts

Quantity

1. Drive to Sta. drill, tap number on roof and repack pump.

NO PARTS USED

### Workorder: V12124

In Date: 12/18/2007

Meter Reading: 1,002.00

Close Date: 12/31/2007

#### Problem?

Pump panel lights not working on B21

#### Task performed:

Parts

Quantity

1. Travel to 21.  
2. Diagnosis and locate disconnected wiring on back of switch.

NO PARTS USED

### Workorder: V11982

In Date: 12/08/2007

Meter Reading: 1,002.00

Close Date: 01/15/2008

#### Problem?

Fuel gauge for vehicle on dash display goes to empty when pump is engaged. B-20

#### Task performed:

Parts

Quantity

1. Call Sta. Explain to driver how fuel guage works.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V13045

In Date: 02/04/2008  
Close Date: 02/11/2008

Meter Reading: 1,002.00

#### Problem?

Gear Oil leaking from pump gear case b21

#### Task performed:

1. Drive to station, flush out gear case and refill, test OK

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V13106

In Date: 02/07/2008  
Close Date: 02/11/2008

Meter Reading: 1,002.00

#### Problem?

Power steering unit hose leaking fluid. B-21

#### Task performed:

1. Drive to station, remove hose, take to make hose, have one made, replace hose, fill, test OK.

#### Parts

308092HYD HOSE

#### Quantity

1

### Workorder: V13578

In Date: 02/28/2008  
Close Date: 03/05/2008

Meter Reading: 11,000.00

#### Problem?

REPLACE RUSTED REAR WHEEL B21

#### Task performed:

1. Replace left rear wheel, rusted, replace wheel, cleaned and painted

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V13586

In Date: 02/28/2008  
Close Date: 03/14/2008

Meter Reading: 11,000.00

#### Problem?

replace rt rear tires b21

#### Task performed:

Replace right rear tires B21 - Callaghan j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V15582

In Date: 06/06/2008

Meter Reading: 11,536.00

Close Date: 06/16/2008

#### Problem?

B inspection and repairs as needed B21

#### Task performed:

6-9 Travel to 21

6-9 B inspection

#### Parts

#### Quantity

CA8193AIR FILTER 46744 WIX

1

CA8737AIR FILTER WIX 46562 L/F LAF4544

1

FP588F33393 FUEL FILTER ISUZU 8-94414796

1

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

1

HPH6349AOIL FILTER 51748

1

LFP5748FILTER OIL 57411

1

R20P33614 FILTER FUEL

1

R90PFILTER FUEL 33231

1

### Workorder: V15691

In Date: 06/12/2008

Meter Reading: 11,536.00

Close Date: 06/24/2008

#### Problem?

repair flat tire b21 callaghan

#### Task performed:

Repair flat tire B21 - C allaghan j

#### Parts

#### Quantity

NO PARTS USED

Vendor?: CALLAGHAN

### Workorder: V16619

In Date: 07/27/2008

Meter Reading: 1,095.30

Close Date: 08/01/2008

#### Problem?

NEED' S PELLETT PLACED IN PACKING GLAND DUE TO BEING ALMOST OUT OF ADJUSTMENT. B-21

#### Task performed:

1. drive to station. pack pump. test = ok

#### Parts

#### Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

## Workorder: V16701

In Date: 07/30/2008

Meter Reading: 1,095.30

Close Date: 08/07/2008

### Problem?

WATER AND GEAR OIL LEAKING FROM BREATHER ON GEAR BOX OF PUMP. B21

### Task performed:

1. drive to station drain gear case filled with oil/water filled up in short time send to shop for rebuild

### Parts

15W40QSYN OIL QT

### Quantity

12

## Workorder: V16943

In Date: 08/10/2008

Meter Reading: 1,095.30

Close Date: 08/12/2008

### Problem?

Panel lights on the back of the Brush 21 truck not working.

### Task performed:

Drive to Stn; fnd bad grnd going to lights; reworked grnd; test ok. j

### Parts

1141BULB

H35SN12BULB

TURBO5TUBE - STROBE

### Quantity

1

2

1

## Workorder: V16758

In Date: 07/31/2008

Meter Reading: 11,773.00

Close Date: 08/14/2008

### Problem?

pump gear case filling up with water- leaking oil and water from breather-check pump B21

### Task performed:

1. Rem all plug out of pump; replc w/ \_\_\_\_\_. fill pump & run; getting water in gear case.
2. Rem pump off of eng; diss pump.
3. R/R all parts in pump; cln/rem brkn stud; install new stud & all new parts as needed.
4. Finish installing all parts & fill gear case, pump & tank; run; chk; adj packing; cln & \_ pump.
5. Cln up shop floor/trash. j

### Parts

1721700305SS BEARING

1721900BEARING 307KDD

36005263600526 SEAL

36011163601116 O RING SUC HEAD

36052023605202 COTTER PIN

38090003809000 GASKET DISCHARGE

3809600GASKET PUMP CASING

38171048 PER PACK PACKING-PUMPS DARLEY

50033005003300 SHAFT - IMPELLER

5400342854003428 CASTLE NUT

WAT61401STRAINER 4 IN

### Quantity

1

1

1

1

1

1

2

8

1

1

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V17731

In Date: 09/16/2008

Meter Reading: 11,773.90

Close Date: 09/30/2008

#### Problem?

batteries dead on pump motor b21

#### Task performed:

1. Drive to Sta-21/R & R pump engine batteries/test run pump-(OK).

(R.T.)

Parts	Quantity
24-60BATTERY GROUP 24	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

### Workorder: V18926

In Date: 11/07/2008

Meter Reading: 1,095.30

Close Date: 11/14/2008

#### Problem?

replace right front turn signal, check right front strobe light. b21

#### Task performed:

drive to stn; replc turn signal & strobe & lens. j

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1
6808200020LIGHT ASSY. TURN SIGNAL	1
68318341650AUSE 602000RU COMLETE UNIT	2

### Workorder: V20584

In Date: 01/25/2009

Meter Reading: 1,095.30

Close Date: 02/11/2009

#### Problem?

B21 right front headlight not working

#### Task performed:

1- Drive to station. replacewd head light, tested ok.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

### Workorder: V21604

In Date: 03/06/2009

Meter Reading: 1,160.00

Close Date: 03/17/2009

#### Problem?

front emergency light mount is broken. (silver grill). mounting location is cracked and light is resting on bumper. B21

#### Task performed:

Drive to Stn; remove grill lights & installed new grill. j

Parts	Quantity
NO PARTS USED	





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V21612

In Date: 03/07/2009

Meter Reading: 1,160.00

Close Date: 03/17/2009

#### Problem?

emergency light on b 21 front grill found broken off and missing. needs to be replaced. asap B21

#### Task performed:

See W/O 21604 j

#### Parts

#### Quantity

SWT54918SW ROCKER DPDT RED/AMBER

1

SWT5492744435 ACTUATOR-BLACK

1

### Workorder: V21616

In Date: 03/07/2009

Meter Reading: 1,160.00

Close Date: 03/17/2009

#### Problem?

correction to earlier B21 repair request. It is the front grill that emergency light is mounted to that is broken. the emergency light is still connected but sitting on the front bumper in front of the grill.

#### Task performed:

See W/O 21604. j

#### Parts

#### Quantity

A17-14767-002GRILL BRUSH TRUCK

1

FREIGHTSHIPPING CHARGES

1

### Workorder: V21736

In Date: 03/12/2009

Meter Reading: 1,180.00

Close Date: 03/17/2009

#### Problem?

CLEVIS FOR SNATCH STRAP NEEDS REPLACING.NUMBER'S FOR CLEVIS ARE [WLL12T 11/4 b21

#### Task performed:

Travel to Stn21 & dropoff Chevis for tow strap. j

#### Parts

#### Quantity

1245-P-1030USE 13047

1

### Workorder: V21750

In Date: 03/12/2009

Meter Reading: 1,180.00

Close Date: 03/17/2009

#### Problem?

LEN'S ON RIGHT HAND TURN SIGNAL FRONT FENDER HAS CRACK b21

#### Task performed:

Drive to Stn; isntalled lense; test ok. j

#### Parts

#### Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V22066**

In Date: 03/25/2009 Meter Reading: 12,657.10  
Close Date: 03/30/2009

**Problem?**

VEHICLE STUCK IN THE WOODS, B-21

**Task performed:**

Drive to Locn; chk T-case oil & rear end; try to pull truck; locked up; rem axles; two to shop. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V22071**

In Date: 03/25/2009 Meter Reading: 12,657.10  
Close Date: 04/08/2009

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED B21 UNIT HAS REAR END OR T CASE PROBLEM

**Task performed:**

1. Rem drive shaft betwn rear end & T-case; chk out prob lem & isolate (T-case broke).
2. Assist Larson w/problem isolation - Levy.
- 3.C-Inspection
4. Replcd latch on jump line compt.
5. Replcd marker & compt bulbs that were out.
6. Rep air leak at T-case.
7. Sticking primer valve; rem/rebuild valve; reinstall.
8. Replcd brkn frnt diff.
9. Replcd eng belts; tensioner needs replacing; out of stock; ordered one & road tech can install.
10. A/C blows warm; heater valve stuck on heat; whole dash needs to be taken apart becayuse of brush season; will rep at later date.
11. Rep ight bar strobe pack.
12. Prepared svc truck for on-call. j

**Parts**

1156BULB 2  
 1157BULB 2  
 15W40BSYN OIL BULK QTS 40  
 334692100R5 HOSE 1  
 CYBS15165011USE UMVS111611 STRAP 2  
 PR338324070 WIX FILTER WATER 1  
 R20P33614 FILTER FUEL 1  
 R90PFILTER FUEL 33231 1  
 LFP5748FILTER OIL 57411 1  
 194BULB 10  
 9510BELT 1  
 K080680BELT SAME AS 3281981 CUMMINS 1  
 PVG-KITORING KIT 1  
 CA8193AIR FILTER 46744 WIX 1  
 CA8737AIR FILTER WIX 46562 L/F LAF4544 1  
 FP588F33393 FUEL FILTER ISUZU 8-94414796 1  
 FS1022FILTER FUEL WIX 33422 PS8689 FRAM 1  
 HPH6349AOIL FILTER 51748 1

**Quantity**



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V22117**

In Date: 03/26/2009  
Close Date: 04/13/2009

Meter Reading: 12,657.10

**Problem?**

tow unit to total truck sisters

**Task performed:**

Tow unit to Total Truck - Sisters j

Parts

Quantity

NO PARTS USED

Vendor?: SISTER

**Workorder: V22077**

In Date: 03/25/2009  
Close Date: 04/14/2009

Meter Reading: 12,657.10

**Problem?**

tow b 21 to shop b21 sisters towing

**Task performed:**

Tow B21 to shop - Sisters Towing j

Parts

Quantity

NO PARTS USED

Vendor?: SISTERS TOWING

**Workorder: V22433**

In Date: 04/09/2009  
Close Date: 04/20/2009

Meter Reading: 12,657.10

**Problem?**

replace belt tensioner b21

**Task performed:**

Went to Stn & replcd belt tensioner. j

Parts

Quantity

3937555TENSIONER BELT

1

**Workorder: V22614**

In Date: 04/17/2009  
Close Date: 05/04/2009

Meter Reading: 1,183.90

**Problem?**

FUEL GUAGE READ'S EMPTY AFTER SYSTEM HAS DONE IT'S SELF TEST B-21

**Task performed:**

1. Drive to Stn; chk sender- good; need instrument panel.
2. Drive to Stn; replcd instrument panel & test ok. j

Parts

Quantity

A2249250001 A22-49250-003 CLUSTER ASSY

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V22340**

In Date: 04/06/2009  
Close Date: 05/11/2009

Meter Reading: 12,657.10

**Problem?**

repair transfer case total truck

**Task performed:**

Repair T-case - Total Truck j

Parts

NO PARTS USED

Quantity

Vendor?: TOTAL TRUC K

**Workorder: V24564**

In Date: 07/04/2009  
Close Date: 07/27/2009

Meter Reading: 1,223.80

**Problem?**

right rear(top) clearance light is missing red cover. B21

**Task performed:**

drive to Stn; replcd marker; test ok. j

Parts

1893BULB

Quantity

10

**Workorder: V26435**

In Date: 09/24/2009  
Close Date: 09/30/2009

Meter Reading: 13,040.00

**Problem?**

A/C INOP, B-21

**Task performed:**

Drive to Stn; fnd connection in dash bad; rework; test ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V28880**

In Date: 01/06/2010  
Close Date: 01/26/2010

Meter Reading: 13,383.00

**Problem?**

intermittent operation of primer pump. b21

**Task performed:**

R/R primer pump on rear of truck. j

Parts

501-3090-00PRIMER PUMP MOTOR

Quantity

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V28932**

In Date: 01/08/2010      Meter Reading: 1,258.00  
Close Date: 02/12/2010

**Problem?**

Front grill strobe out and bottom grill broken B21

**Task performed:**

1. L/F grill strobe inop; replcd strobe lamp asy & lens.
2. Grill loose-mntng bolt stripped; rep grill mnt.
3. Chk grill; replcd screw; ck ok. j

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1
68318341650AUSE 602000RU COMPLETE UNIT	1

**Workorder: V29550**

In Date: 01/29/2010      Meter Reading: 13,383.00  
Close Date: 03/01/2010

**Problem?**

One pump panel light is out B21

**Task performed:**

- R/R bulb in R-1 & pump panel light. j

Parts	Quantity
NO PARTS USED	

**Workorder: V29655**

In Date: 02/02/2010      Meter Reading: 1,258.00  
Close Date: 03/01/2010

**Problem?**

rear left 1 1/2 discharge leaks please fix b21

**Task performed:**

1. Rem, rebuild & reinstall L/S 1-1/2" discharge vavel, recirc valve & tank-to-pump valve.
2. Wire tach hot lead, fuse lead & protect calibrate tach.
3. Dia nose frt hour meter inop; replcd hour meter & reconfigure wires.

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V29644**

**In Date:** 02/02/2010

**Meter Reading:** 13,383.00

**Close Date:** 03/09/2010

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED B21

**Task performed:**

- B-Inspection
- 2. Replc veh btrys; test, cln cables.
- 3. Test pump btrys-NG; rem btrys.
- 4. Rem wheels/drums; replc brake shoes, chambers/drums; adj brakes.
- 5. Rem R-1 handle; straightened bent door skin; drill new holes/install new handle.
- 6. B-inspection - lube chasis.
- 7. Replc marker light.
- 8. install pump motor btrys.
- 9. Dia problem w/tach on pump motor; rem tach.
- 10. Rescure all compt door shock mtng bolts.
- 11. Resecure exhaust.
- 12. Work on electrical problems w/tach \* hourmemter; drive to Stn17 & chk wiring.
- 13. install "no step" signs on compt doors.
- 14. Fill wtr tank & adj pump packing.
- 15. Rep brkn welds on rear brush guard; rep brkn frnt bumper step; weld up & add bolts.
- 16. Calibrate pump en tach.
- 17. Chk for air leak; R/R brake switch in cab.
- 18. install new tool holders in R-3 compt. j

**Parts**

**Quantity**

0040BRACKET	1
108-12FBEADED CHAIN W/CONN 12	1
15W40BSYN OIL BULK QTS	40
194BULB	1
24F-60BATTERY	2
333-193GAGE TACHOMETER	1
3600DBRAKE DRUM	2
6809881078DZ STUD	2
79L-SSD RING LATCH	1
91368904 VALVE KIT 1 1/2 IN	1
91388906 VALVE KIT 2.5 IN AKRON	1
91398907 VALVE KIT 3 IN AKRON	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CL200CL200 TOOL CLIP	1
FP588F33393 FUEL FILTER ISUZU 8-94414796	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	2
HPH6349AOIL FILTER 51748	1
LFP5748FILTER OIL 57411	1
MA15445NT3030 STD CHAMBER 30/30	2
R20P33614 FILTER FUEL	1
R90PFILTER FUEL 33231	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2
FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR	1
8534203HRS METER 85342-03	1

**Workorder: V29995**

**In Date:** 02/16/2010

**Meter Reading:** 13,383.00

**Close Date:** 03/18/2010

**Problem?**

small chunk out of front left tire sidewall on B21

**Task performed:**

- Fnd small piece on left frnt tire torn; rem chuck; tire ck ok. j

**Parts**

**Quantity**

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V29994

In Date: 02/16/2010 Meter Reading: 13,383.00  
Close Date: 03/19/2010

#### Problem?

Right front side red strobe out on B21

#### Task performed:

Went to Stn21; fnd R/hood strobe out; R/R strobe; needs lens replcd; R/R lens. j

#### Parts

#### Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

68318341650AUSE 602000RU COMPLETE UNIT

1

### Workorder: V30681

In Date: 03/12/2010 Meter Reading: 13,820.10  
Close Date: 04/02/2010

#### Problem?

winch out unit check 4 wheel drive B21

#### Task performed:

went out to scene where B21 was stuck; pulled out; chk udnerside for damage; all ok. j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V32619

In Date: 06/03/2010 Meter Reading: 1,315.90  
Close Date: 06/17/2010

#### Problem?

hosereel not working selnoid clicking reel motor tries to turn.j.g. B21

#### Task performed:

1. R/R motor w/Kevin, needed help installing.  
2. Went to 21; ck/rep grnds & terms at hose reel; need motor replcd; returned to 21; rem all connections/motor; R/R motor; gear & mnt plate; ran/ck ok. j

#### Parts

#### Quantity

9910-1119GEAR CHAIN DRIVE HANNA

1

9923-0008MOUNTING PLATE HANNAY

1

P56AN227MOTOR HOSE REEL

1

### Workorder: V33436

In Date: 07/09/2010 Meter Reading: 1,399.60  
Close Date: 07/23/2010

#### Problem?

PUMP PRIMER MOTOR SOUNDS VERY WEAK, ALSO PUMP PLUMBING LEAKING AT CONNECTION B-21

#### Task performed:

Travel to Stn21; chk primer; R/R primer moto/pump asy. j

#### Parts

#### Quantity

501-3090-00PRIMER PUMP MOTOR

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V34730

In Date: 09/03/2010

Meter Reading: 1,485.10

Close Date: 09/23/2010

#### Problem?

primer motor on pump b21

#### Task performed:

Went to 21; fnd no power to primer; rem panel/rep wires; ran primer/flushed primer; ck ok. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V32681

In Date: 06/06/2010

Meter Reading: 1,315.90

Close Date: 10/19/2010

#### Problem?

Rear emergency strobe light out. Primer for pump not working correctly. b21

#### Task performed:

completed j

#### Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

68318358710600 SER NON OPTIC AMBER

#### Quantity

1

1





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V35400**

**In Date:** 10/04/2010

**Meter Reading:** 14,449.00

**Close Date:** 12/06/2010

**Problem?**

C INSPECTION AND REPAIRS B 21

**Task performed:**

1. C insption
2. service cooling system
3. repair r/rear marker lite
4. rebuild l/side preconnect
5. r&r wiper blades
6. replace l/side spot light
7. r&r r/side west coast mirror
8. service p/s
9. service transmission
10. repair r/side door entry lite
11. service air dryer
12. repair r/side pump panel lite
13. repair l/side marker lite
14. service rear axel
15. service T case
16. service front axel

**Parts**

**Quantity**

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	2
15W40BSYN OIL BULK QTS	34
29526898 29548988 TRANS FILTER ALLISON	1
4020362171 GRO LAMP DOME 4 IN	1
4419BULB	1
52-24WIPER BLADES ANCO 24	2
78208920 VALVE ASSY. 2IN	1
800405PURGE VALVE KIT	1
CA8193AIR FILTER 46744 WIX	1
CA8737AIR FILTER WIX 46562 L/F LAF4544	1
FP588F33393 FUEL FILTER ISUZU 8-94414796	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
GRO716SGRO716S MIRROR S/S	1
HPH6349AOIL FILTER 51748	1
LFP5748FILTER OIL 57411	1
PR338324070 WIX FILTER WATER	1
R20P33614 FILTER FUEL	1
R90PFILTER FUEL 33231	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V35013**

In Date: 09/17/2010  
Close Date: 12/16/2010

Meter Reading: 1,485.10

**Problem?**

THE FRONT PUMP START SWITCH IS NOT WORKING. ONLY STARTS FROM REAR. B21

**Task performed:**

(1) TRAVELED TO ST21 TO REPAIR B21 FRONT STARTING PROBLEM FOR THE PUMP AT THE DASH BOARD. FOUND THE RELAY BAD. REPLACED WITH A NEW ONE. TESTED OK.

(2) FOUND OIL PRESSURE GAUGE NOT WORKING. REPLACED THE TRANSDUCER AT THE ENGINE FOR THE PUMP. TESTED AND CHECKED OUT OK.

J.W.

Parts	Quantity
102161TRANSDUCER 500 PSI	1
87499RY48 RELAY	1

**Workorder: V37421**

In Date: 12/27/2010  
Close Date: 01/10/2011

Meter Reading: 1,485.10

**Problem?**

ON CALL PRIMER 10-7 B21

**Task performed:**

Replcd primer pump. j

Parts	Quantity
501-3090-00PRIMER PUMP MOTOR	1

**Workorder: V37815**

In Date: 01/15/2011  
Close Date: 01/28/2011

Meter Reading: 2,584.00

**Problem?**

REAR WORKING LIGHT ON OFFICER SIDE IS NOT WORKING. B21

**Task performed:**

(1) TRAVELED TO ST-21 TO REPAIR THE REAR SPOT LIGHT ON B21. REPLACED BULB, OK. J.W.

Parts	Quantity
4419BULB	1
4435HEADLIGHT	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

## Workorder: V38007

In Date: 01/24/2011

Meter Reading: 2,584.00

Close Date: 01/28/2011

### Problem?

the spot mirror on the passenger side will not stay in place it faces the ground and the driver is not able to see the blind spot. R21

### Task performed:

(1) TRAVELED TO ST-21 TO REPAIR THE MIRROR ON R21. TIGHTENED THE CONVEC MIRROR AND ADJUSTED IT. J.W.

### Parts

NO PARTS USED

### Quantity

## Workorder: V38368

In Date: 02/08/2011

Meter Reading: 15,829.40

Close Date: 02/16/2011

### Problem?

Bolts broken on strobe mounted on passenger side of front grill. Light hanging off unit. B21

### Task performed:

Crew will secure light til repair is made; grill does not appear to be brkn; need new strobe asy - Scott.

### Parts

602000RULIGHT

1

### Quantity

Chkd strobe light on grill NPF. j

## Workorder: V38400

In Date: 02/09/2011

Meter Reading: 15,829.40

Close Date: 02/16/2011

### Problem?

power steering hose blown B21

### Task performed:

1. Travel to N. of Hamlan(?); R/R blon P/S hose; redo hose end; reinstall; fill P/S; send to shop for another hose hose made up.

2. Replc P/S press hose.

3. Added packing \_\_\_\_ to pump. j

### Parts

38171048 PER PACK PACKING-PUMPS DARLEY

3

### Quantity

## Workorder: V37836

In Date: 01/17/2011

Meter Reading: 2,584.00

Close Date: 02/28/2011

### Problem?

water level guage on rear pump panel not working. B21

### Task performed:

Chkd wtr level gauge; FNP. j

### Parts

NO PARTS USED

### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V38227**

In Date: 02/02/2011      Meter Reading: 2,584.00  
Close Date: 02/28/2011

**Problem?**

a/c in brush truck not working B21

**Task performed:**

Travel to Stn21; chkd A/C; fnd low on freon; topped off & chkd for leaks; ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V39359**

In Date: 03/22/2011      Meter Reading: 16,616.00  
Close Date: 03/22/2011

**Problem?**

DISPATCHED TO FIRE SCENE AND HELD ON STAND BY AT LOCATION.

**Task performed:**

DISPATCHED TO FIRE HELD ON STANDBY AT LOCATION.

Parts

NO PARTS USED

Quantity

**Workorder: V39296**

In Date: 03/19/2011      Meter Reading: 16,616.00  
Close Date: 03/24/2011

**Problem?**

Box hand light not working. B21

**Task performed:**

- Pump packing exccessive leaking; adj pump packing & operate pump.  
- Handlights inop; issued to handlight for brush truck.  
- R/frnt t-signal brkn off; rem light asy & install new t-signal asy. j

Parts

6808200020LIGHT ASSY. TURN SIGNAL

1

Quantity

**Workorder: V39367**

In Date: 03/22/2011      Meter Reading: 16,616.00  
Close Date: 03/24/2011

**Problem?**

Pump drian valve leakingaround threads on B21.

**Task performed:**

Travel to Stn21; repacked pump; still leaking; shaft bad; all packing needs replcd. j

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V39040

In Date: 03/08/2011

Meter Reading: 15,829.40

Close Date: 03/25/2011

#### Problem?

REPLACE FRONT TIRES TIRESOLES

#### Task performed:

Replc frnt tireds - Tiresoles j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: ELPEX

### Workorder: V39523

In Date: 03/29/2011

Meter Reading: 16,959.80

Close Date: 04/01/2011

#### Problem?

B21 dash brake lever leaking slowly. sta 21.

#### Task performed:

Travel to 21; replc dash valve. j

#### Parts

800034VALVE PARKING BRK.

#### Quantity

1

### Workorder: V40965

In Date: 05/30/2011

Meter Reading: 4,979.90

Close Date: 06/01/2011

#### Problem?

Nozzle holder bracket for front booster hose broken on Brush fire b21

#### Task performed:

Travel to 21; replc d nozzle brkt. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V41116

In Date: 06/05/2011

Meter Reading: 5,161.00

Close Date: 06/07/2011

#### Problem?

Water indicator light on back pump out. B21

#### Task performed:

Rep loose level gauge; travel to 21. j

#### Parts

102245111661 GAUGE TANK LEVEL CLASS 1

#### Quantity

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V41527**

In Date: 06/22/2011  
Close Date: 06/27/2011

Meter Reading: 5,774.00

**Problem?**

Pump problem, Sta 21.

**Task performed:**

Enroute - cancelled; travel home. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V41598**

In Date: 06/25/2011  
Close Date: 07/07/2011

Meter Reading: 5,774.00

**Problem?**

Emergency lights on back and sides of brush truck are not working, only on the front cab. E21

**Task performed:**

TRAVEL TO 21 CHECKED LIGHTS R&R 1 STROBE  
PACK AND REPLACED 2 LIGHTS  
HAS WIRING ISSUE WITH OTHER 2 - WILL RETURN  
AK

**Parts**

02036317300STROBE LINEAR REFLECTOR 6ELTUBE  
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL  
UPS64LXPOWER SUPPLY

**Quantity**

2  
1  
2

TRAVEL TO 21 REPARID REMAING LIGHTS AK

**Workorder: V41972**

In Date: 07/13/2011  
Close Date: 07/22/2011

Meter Reading: 5,774.00

**Problem?**

Right rear emergency light is out. B21

**Task performed:**

TRAVEL TO 21 REPAIED RR UPPER STROBE LIGHT.  
AK

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V42490**

In Date: 08/02/2011  
Close Date: 08/04/2011

Meter Reading: 6,168.40

**Problem?**

brush truck right rear strobe light is not working. Three panel lights are not working in rear of the truck. Sta21.

**Task performed:**

travel to 21 replaced rr strobe light and 1 panel light put  
bulbs in other panel lights

**Parts**

02036317300STROBE LINEAR REFLECTOR 6ELTUBE  
1141BULB  
120257100C2030-7110-30 CLEAR DOME STEP

**Quantity**

1  
10  
1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V42654**

In Date: 08/08/2011      Meter Reading: 6,168.40  
Close Date: 08/15/2011

**Problem?**

PUMP WON'T START--CHARGING BATTERY AT THIS TIME, Sta 21.

**Task performed:**

checked batteries after travel to station batteries below 6  
volts r&r batteries from shop

Parts	Quantity
24-60BATTERY GROUP 24	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

**Workorder: V42728**

In Date: 08/10/2011      Meter Reading: 6,223.20  
Close Date: 08/26/2011

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED SERVICE PUMP MOTOR

**Task performed:**

B SERVICE  
  
SERVICE PUMP MOTOR SERVICE GEAR CASE ALSO  
AND AIR LITTER  
  
R&R DOOR SEAL ON DRIVER DOOR  
REPLACE MISSING WA-- TANK  
REPAIR WIRES ON MAP LIGHT OK  
  
CHECK OUT AND REPLACE DOME LIGHT OK  
CHEKC AND REPAIR WIG WAG LIGHT - FOUND BAD  
FUSE  
R&R VOLT GAUGE ON PUMP PANEL  
  
REPAIR SIDE MAKER RIGHT SIDE  
REPAIR WIRES TO STEET HORN  
CHECK AND - FRONT HUBS OK

Parts	Quantity
15W40BSYN OIL BULK QTS	21
22-40867-000RESERVOIR	1
22-40868-000WASHER CAP WPB-FREIGHTLINER	1
46793-346793 AMBER MARKER LIGHT	1
75W90GEAR OIL SYN QT	1
A2254926000WASHER PUMP W/GROMMET	1
ABPN8332229011-3050 SWITCH BLOWER	1
CA8737AIR FILTER WIX 46562 L/F LAF4544	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LFP5748FILTER OIL 57411	1
R20P33614 FILTER FUEL	1
R90PFILTER FUEL 33231	1

REPAIR FRONT AC SYSTEM NOT WORKING AT ALL  
REPLACE BLOWER SWITCH FUSES AND RELAYS  
AND PRESSURE OK OWRKING

QA TRUCK



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V46098**

In Date: 12/27/2011

Meter Reading: 6,352.70

Close Date: 12/30/2011

**Problem?**

1. drivers side little amber running light lens missing. 2. bulbs out on one clear pump panel light 3. 3 bulbs out on lower little red running lights on rear near step B21

**Task performed:**

1. TRAVELED TO STA 21 REPLACED MISSING AMBER LENS. REPLACED 3 REAR MARKER LIGHTS, REPAIRED WIRE TO PUMP PANEL LIGHT.

2. REPLACED EXHAUST FLEX PIPE AND CLAMPS.

3. REPLACED LEAKING AIR TANK DRAIN VALVES.

**Parts**

**Quantity**

12105QUICK DRAIN	3
20A-400CLAMP 4" 33969	2
35200-RLIGHT MARKER LED RED	3
94862PIGTAIL LED MARKER LIGHTS	3
B138-15ALENS AMBER	1

**Workorder: V47129**

In Date: 02/07/2012

Meter Reading: 6,352.70

Close Date: 02/28/2012

**Problem?**

right rear turning signal not working and right front emergency light on grill falling off.

**Task performed:**

1. INSTALLED NEW REAR TURN SIGNAL LIGHT.

2. REINSTALLED FRONT LIGHT ON GRILL.

**Parts**

**Quantity**

02028345000REFLECTOR	1
----------------------	---

**Workorder: V47528**

In Date: 02/28/2012

Meter Reading: 6,352.70

Close Date: 03/06/2012

**Problem?**

check tires. please see Mike Lehan for more info

**Task performed:**

MEASURED TIRES AND RIMS FOR FIT.

**Parts**

**Quantity**

NO PARTS USED	
---------------	--

**Workorder: V47976**

In Date: 03/15/2012

Meter Reading: 7,033.00

Close Date: 04/03/2012

**Problem?**

B INSPECTION OIL CHANGE SERVICES B 21

**Task performed:**

B INSPECTION WITH OIL CHANGE

**Parts**

**Quantity**

NO PARTS USED	
---------------	--

Vendor?: OIL CHANGE SERVICES





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V48087**

In Date: 03/20/2012      Meter Reading: 19,940.00  
Close Date: 04/10/2012

**Problem?**

Rhood latch catch broken. Sta 21

**Task performed:**

REMOVED BROKEN LATCH INSTALLED NEW ONE.

Parts

17-14781-000PLASTIC HOOD LATCH

Quantity

1

**Workorder: V48574**

In Date: 04/11/2012      Meter Reading: 20,110.00  
Close Date: 04/24/2012

**Problem?**

recirculation valve is leaking pretty bad and needs immediate attention!leaks when pump is on or off. B21

**Task performed:**

REMOVED PLUMBING FROM MANIFOLD INSTALLED  
NEW PIPING RECONNECTED.

Parts

91368904 VALVE KIT 1 1/2 IN

Quantity

1

**Workorder: V48927**

In Date: 04/26/2012      Meter Reading: 20,270.00  
Close Date: 04/30/2012

**Problem?**

JUST REQUESTED 4" FEMALE TO 2 1/2 INCH MALE ADAPTOR FOR B21. WE ALSO NEED THE 4" MALE MOUNTING BRACKET  
SO IT CAN BE PERMANENTLY MOUNTED NEAR THE PUMP PANEL. b21

**Task performed:**

DROP OFF ADAPTER - NO MOUNTING BRACKET AT  
THIS TIME WILL ORDER PART.

Parts

NO PARTS USED

Quantity

**Workorder: V48860**

In Date: 04/24/2012      Meter Reading: 20,270.00  
Close Date: 05/02/2012

**Problem?**

DRIVERS SIDE INSIDE REAR DUAL TIRE IS FLAT. B 21

**Task performed:**

DRIVER'S SIDE INSIDE REAR DUAL TIRE IS FLAT. B  
21.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V48431**

In Date: 04/04/2012      Meter Reading: 20,110.00  
Close Date: 05/07/2012

**Problem?**

MAKE REPAIRS ON ATTACHED LIST

**Task performed:**

1. OIL LEAK FT OF PAN. CHECKED FOR LEAK ONLY CLASS 1 WILL MONITOR OIL LEAK REAR MAIN SEAL CLASS 1 LEAK WILL MONITOR.
2. TIE ROD BENT. REPLACED BENT TIRE ROD AND ADJUSTED TOE.
3. ADJUSTED PUMP PACKING.
4. REPAIRED LIGHT IN L-1 COMPARTMENT.

Parts	Quantity
MMHMT101127TIE ROD	1

**Workorder: V50111**

In Date: 06/13/2012      Meter Reading: 7,713.00  
Close Date: 06/18/2012

**Problem?**

fitting on hose reel broken. water spirting out from top of brush truck. B21

**Task performed:**

REPLACED BROKEN FITTING ON HOSE REEL. INSTALLED NEW VITICLIC SEAL.

Parts	Quantity
7001-15EG150T SEAL	1

**Workorder: V50126**

In Date: 06/14/2012      Meter Reading: 7,713.00  
Close Date: 06/18/2012

**Problem?**

drivers side light on the front grill and the drivers side light in the rear, both are flashing lights

**Task performed:**

R&R STROBE LIGHTS.

Parts	Quantity
NO PARTS USED	

**Workorder: V50601**

In Date: 07/04/2012      Meter Reading: 20,639.00  
Close Date: 07/09/2012

**Problem?**

driver door handle inside cab broken. B21

**Task performed:**

TRAVEL TO 21 REPLACED BROKEN INNER DOOR HANDLE.

Parts	Quantity
6807200575HANDLE DOOR	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V50663**

In Date: 07/07/2012  
Close Date: 07/24/2012

Meter Reading: 20,639.00

**Problem?**

2 rear side above rear wheels and 2 rear on back emergency strobe lights are out. Not sure if its the bulbs or the strobe unit. B 21

**Task performed:**

REPAIRED STROBES ON BODY.

Parts

NO PARTS USED

Quantity

**Workorder: V52095**

In Date: 09/02/2012  
Close Date: 09/12/2012

Meter Reading:

**Problem?**

2 front tires-outside tread wear. need to be replaced soon B 21

**Task performed:**

1. CHK TIRES AND ORDERED REPLACEMENTS.

Parts

NO PARTS USED

Quantity

**Workorder: V52138**

In Date: 09/04/2012  
Close Date: 09/13/2012

Meter Reading: 21,169.00

**Problem?**

REPLACE FRONT TIRES

**Task performed:**

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: GOOD YEAR

**Workorder: V52186**

In Date: 09/06/2012  
Close Date: 09/13/2012

Meter Reading: 21,169.00

**Problem?**

ON CALL PRIMER 10-7 B 21

**Task performed:**

1. TRVL TO ST 21 REPLACED PPRIME PUMP SOLENOID.

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V52306**

In Date: 09/11/2012

Meter Reading:

Close Date: 09/19/2012

**Problem?**

air leaks. low air pressure. B21

**Task performed:**

TRVL TO 21 REPAIRED 2 AIR LEAKS AT AIR TANKS.

Parts

NO PARTS USED

Quantity

**Workorder: V52514**

In Date: 09/19/2012

Meter Reading:

Close Date: 11/09/2012

**Problem?**

fuel starts leaking underneath the truck by transmission area when you first start it cold,then abruptly stops on its own.it does not continue after that while truck keeps running.also pump packing and supply pipe leak.

**Task performed:**

REPLACED GROVE LOCK SEALS AND ADJUSTED PUMP PACKING. NOTE: FUEL PUMP REPAIRED BY CUMMINGS.

Parts

7001-30ESEAL

Quantity

2

**Workorder: V52727**

In Date: 09/30/2012

Meter Reading:

Close Date: 11/09/2012

**Problem?**

Water level gauge on back panel is not reading correctly B 21

**Task performed:**

1. TRAVEL TO 21 REPLACED LEVEL GAUGE AND PROGRAMMED SENSOR BAD NONE ON TRUCK WILL WORK.
2. REPLACED LEVEL SENSOR AND CALIBRATED GAUGES.

Parts

102162TANK LEVEL TRANSDUCER PRES

102245111661 GAUGE TANK LEVEL CLASS 1

Quantity

1

2

**Workorder: V52820**

In Date: 10/03/2012

Meter Reading: 8,537.80

Close Date: 11/20/2012

**Problem?**

repair fuel system b 21

**Task performed:**

REPAIR FUEL SYSTEM B 21.

Parts

NO PARTS USED

Quantity

Vendor?: CUMMINS POWER SOUTH



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V51514

In Date: 08/10/2012

Meter Reading:

Close Date: 11/28/2012

#### Problem?

driver side strobe light is out.. B21

#### Task performed:

REWIRED STROBE LIGHT AND REPLACED BULB.

#### Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

#### Quantity

1

### Workorder: V53321

In Date: 10/26/2012

Meter Reading:

Close Date: 11/28/2012

#### Problem?

multiple things on brush truck need repair. Air leak, both water tank guages not working, pump ignition in cab not working, pump panel lights out, driver's side strobe light out.

#### Task performed:

1. TRAVEL TO 21 REPAIRED AIR LEAKS.
2. REPAIRED PUMP PANEL LIGHT.
3. TRAVEL TO 21 TRACED WIRE FOR FRONT PUMP SWITCH FOUND BROKEN WIRE AT PUMP PANEL REPAIRED WIRE AND STARTED OK.

#### Parts

277147VALVE

#### Quantity

1

### Workorder: V53725

In Date: 11/13/2012

Meter Reading:

Close Date: 11/28/2012

#### Problem?

bad air leak and rear pump is leaking where the packing is... B21

#### Task performed:

1. WENT TO 21 CHK FOR AIR LEAKS- SPRAYED LINES AND FITTING- REPAIRED LEAK AT AIR TANK- FOUND PARK VALVE LEAKING NEED PART.
2. ADJUSTED PUMP PACKING- CHK OK.
3. WENT TO 21-REMOVED DASH PANELS VALVES AND LINES SWAPTED FITTINGS- REPLACE VALVE RAN AND CHK OK FOUND AIR SWITCH LEAKING NEED SW.
4. REMOVED DASH R/R SW- R/R AND CHK O.

#### Parts

800034VALVE PARKING BRK.

FSC17491907NO SWITCH LOW AIR PRESSURE

#### Quantity

1

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V53751**

**In Date:** 11/14/2012

**Meter Reading:** 8,570.00

**Close Date:** 11/28/2012

**Problem?**

on call battery tray came open

**Task performed:**

FOUND LATCH INOP- REPAIRED LATCH AND LUBED

Parts

NO PARTS USED

Quantity





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V55776**

**In Date:** 02/14/2013

**Close Date:** 03/06/2013

**Meter Reading:** 21,612.00

**Problem?**

C inspection

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

1. C-INSPECTION.	05-17223-000CAP RADIATOR 10 LB	1
2. REPLACED BATTERIES.	103081XR7 VALVE	1
3. REPLACED PUMP BATTERIES.	107796DRYER KIT AD9 -NEW	2
4. RRO TIRE FLAT - FILL WITH AIR AND LEAK CHECK - FOUND EXT CAP LEAKING - REPLACED CAP.	107800VALVE CHECK AD9	2
5. DISASSEMBLE AND REMOVE DOG HOUSE. DISPOSE OF METAL HOUSING IN TRASH (METAL) BIN. FABRICATE AIR INTAKE SUPPORT BRACKET FOR PIPING AND AIR FILTER HOUSING - INSTALL AND SECURE.	1094KIT-AIR HORN-GROVER	1
6. PUMP BODY INTAKE AND DISCHARGE VITOLIC COPPLER LEAKING - REMOVE PIPING CLEAN CUPLING SURFACE AND INSTALL NEW VITALIC CUPLER.	1893BULB	1
7. PUMP WATER MANIFOLD RUSTING - CLEAN SURFACE AND APPLY COAT OF RUST INHIBITER PAINT.	194BULB	10
8. ELECTRICAL WIRE BURNT ON PUMP EXHAUST PIPE - SPLICE WIRE AND REROUTE.	24-60BATTERY GROUP 24	2
9. EXHAUST PIPE WRAP - REMOVE DAMAGE EXHAUST WRAP - INSTALL AND SECURE NEW WRAP.	301-502301-104 FUEL GAUGE	1
10. FILL WATER TANK AND OPERATE PUMP PACKING NEED ADJUSTING ADJUST PACKING.	450434450434 PLUG OIL HUB	2
11. PUMP FUEL GAUGE INOP - FOUND FUEL GAUGE BROKEN - REMOVE GAUGE AND INSTALL NEW GAUGE, CLEAN CONTACTS, REWIRE OPERATE. REPLACE PUMP COMP. LIGHT BULB.	7001-30ESEAL	2
12. CHECK PUMP CHARGING SYSTEM - CHARGING VOLTAGE 14.0 V, AMP DRAW 3.4 AMP RUNNING NO LOAD, ALTERNATOR OPERATING WITHIN SPECS STARTER OPERATING NORMAL.	72R31001720 DIFFUSER A/C 3.5 IN	1
13. RIGHT SIDE WHEEL WELL PUSH IN AND LEFT SIDE MUD FLAP TORN - REMOVE MUD FLAP CUT AND INSTALL NEW PIECE - USE PORTO POWER TO PUSH OUT DAMAGE WHEEL WELL AND NUTS AND BOLT TO SECURE WHEEL WELL SHEET METAL.	800405PURGE VALVE KIT	2
14. AIR LEAK MODULATORY VALVE - REMOVE VALVE - INSTALL NEW R-2 MODULATE VALVE AND ROAD TEST. ADJUST BRAKES TO SPECS AND ROAD TEST AGAIN SYSTEM WORKING NORMAL.	92183LENS AMBER	1
15. AIR DRYER SERVICE.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
16. CAB CLEARANCE LIGHT OUT AND ONE LENSE BROKEN - REMOVE BLOWN BULB AND LENSE INSTALL NEW BULB AND REPLACE BROKEN LENSE	CA8193AIR FILTER 46744 WIX	2
17. L-3 COMP DOOR STRUT WEAK AND MOUNTING HOLES STRIP - DRILL AND RETAP TO LARGER SUPPORT HOLES - INSTALL STRUT SUPPORT PLATE AND BALL - INSTALL STRUTS.	CA8737AIR FILTER WIX 46562 L/F LAF4544	1
18. FRONT JUMP LINE SHAFING AT FRONT HANGER AND TRANSMISSION - LOOSEN CLAMPS AND INSTALL 2 RUBBER PROTECTION BOOTH AND SECURE HOSE AT REAR SPRING HANGER SHAFING	EAA-8350-90UGSS6558UK STRUT-LIFT	2
	FP588F33393 FUEL FILTER ISUZU 8-94414796	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	HPH6349AOIL FILTER 51748	1
	LFP5748FILTER OIL 57411	1
	PR338324070 WIX FILTER WATER	1
	R20P33614 FILTER FUEL	1
	R90PFILTER FUEL 33231	1
	S154BLOW GUN USE 150	1
	S777COUPLING NIPPLE	1
	VML-T1264GASKET P/S COVER	1
	VML-T1279WASHER P/S	1
	WAT61401STRAINER 4 IN	1
	9510BELT	1
	K080680BELT SAME AS 3281981 CUMMINS	1
	VML-S1414FILTER P/S	1
	B2420LP-SMUD FLAP 24 X 24	1
	HP-31DBATTERY 950CCA HP-31D	2
	PDB 10395EXH BRAKE PDB20395	1





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

- INSTALL PROTECTIVE BOOTH.
- 19. FRONT HUB SERVICE.
- 20. POWER STEERING FLUID AND FILTER SERVICE.
- 21. BELTS SERVICE A/C AND ENGINE.
- 22. TOOL HOLDER ASSEMBLY STRIP ANCHOR HOLES - REMOVE RETAP ANCHOR HOLES AND INSTALL NEW TOOL HOLDER.
- 23. SECURE LOOSE TURBO INTAKE BOOTH.
- 24. RADIATOR COOLANT VENT HOSE RUBBING ON METAL PIPE - INSTALL PROTECTIVE RUBBER SL???
- 25. AFTER REAR BRAKE ADJUSTMENT AND ROAD TEST FRONT DID NOT PULL OR BRAKE TO RIGHT - CHECK BRAKE ADJUSTMENT AND FRONT SUSPENSION FOR LOOSE NUT AND BOLT ALL ARE SECURE.
- 26. ENGINE TEMP 200 DEGREE F - OPERATE UNIT IN DRIVE BRING ENGINE TEMP UP FAN COMES ON ENGINE TEMP 202 DEGREE F AND TRANSMISSION TEMP 195 DEGREE F UNIT OPERATING WITHIN NORMAL RANGE.
- 27. DIAGNOSING EXHAUST BRAKE MALFUNCTION - TEST AND OPERATE ELECTRIC AIR SELONOID OPERATE GOOD - DISCONNECT AIR CONTROLE VALVE, BENCH TEST UNIT SEAZED UP UNABLE TO DISASSEMBLE TO REBUILD PARTS ON ORDER CLEAN SURFACE INSTALL EXHAUST FLAPER ASSEMBLY CONNECT ELECTRICAL WIRING AND AIR CONTROLE LINE SECURE AND TEST DRIVE.
- 28. R-1 COMP OUTER SURFACE DENT NO REPAIR AS PER S REINES (FM)
- 29. AIR HOR INO - REMOVE AND DISASSEMBLE FOUND WATER AND SPRING CORRODED CLEAN HOUSING - INSTALL NEW WATER AND SPRING REASSEMBLE OPERATE AND ADJUST ONE.
- 30. Q & A.

**Workorder: V48926**

**In Date:** 04/26/2012

**Meter Reading:**

**Close Date:** 04/08/2013

**Problem?**

WE NEED A 4" FEMALE TO 2 1/2 INCH MALE ADAPTOR IN ORDER TO SUPPLY THE PUMP WITH WATER FROM AN OUTSII SOURCE OTHER THAN THE WATER TANK OR A DRAFT.

**Task performed:**

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V57820**

In Date: 05/18/2013

Meter Reading:

Close Date: 05/29/2013

**Problem?**

the right turn signal over the front fender will not blink.the light comes on for the park lights ,but that is all.

**Task performed:**

**Parts**

**Quantity**

CHECK LIGHT R&R BULB AND GROUND.

NO PARTS USED

**Workorder: V58725**

In Date: 06/26/2013

Meter Reading: 9,173.00

Close Date: 06/28/2013

**Problem?**

Weld to fill pipe untill new pipe comes in

**Task performed:**

**Parts**

**Quantity**

WELD UP PIOPE TO SAVE TILL NEW ONE COME IN, TEMPORARY FIX, REPAIRED TO KEEP UNIT INSERVICE TILL NEW COME IN.

NO PARTS USED

**Workorder: V58594**

In Date: 06/21/2013

Meter Reading: 9,173.00

Close Date: 08/02/2013

**Problem?**

CLAMP LEAKING BADLY AT 2 1/2 DIRECT TANK FILL WHERE RUBBER HOSE CONNECTS TO GALVANIZED PIPE.

**Task performed:**

**Parts**

**Quantity**

1. TRAVEL TO MAKO HOSE TO PICKUP FITTINGS FOR GRAVE LEAK CONNECTION. TRAVEL TO 21 INSTALLED FITTING. NEW FITTING TO SHORT TOOK HOSE TO MAKO COULD NOT LENGTHEN? ORDERED NEW FITTING AGAIN.

443411HOSE & FITTING ASSY 1

7001-20ESEAL 1

7001-25ESEAL 7

7001-30ESEAL 1

2. ORDERED SEVERAL PIPES FINALLY GOT RIGHT ONE WHILE INSTALLING INTAKE HOSE CROSSTHREADED PIPE INTO TANK. SENT TO SHOP FOR REPAIR.



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

## Workorder: V59877

In Date: 08/18/2013

Meter Reading: 9,173.00

Close Date: 08/26/2013

### Problem?

float pump throttle linkage broken. E21

### Task performed:

TRAVEL TO 21 REPAIRED BROKEN THROTTLE LEVER  
ON FLOAT PUMP.

Parts

NO PARTS USED

Quantity

## Workorder: V60138

In Date: 08/28/2013

Meter Reading: 9,243.00

Close Date: 08/30/2013

### Problem?

velcro straps that hold hard suction are dry rotten and do not hold. need replaced ASAP. SECTION ALMOST FELL OFF GOING  
DOWN ROAD. HAD TO STOP TRUCK.

### Task performed:

TRAVEL TO 21 REPLACED STRAPS ON HOLD  
SUCTION.

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V59485**

**In Date:** 08/01/2013

**Meter Reading:** 9,173.00

**Close Date:** 09/05/2013

**Problem?**

Tank fill inlet threads damaged

**Task performed:**

TANK FILL INLET PIPE - CHECK OUT PROBLEM WITH PIPE END AND THREADS PULLED FROM TANK - USING A STAINLESS PIPE NIPPLE THREAD CAREFULLY TO CATCH LAST THREE THREAD REMAINING WITHOUT CROSS THREADING AGAIN - FIRST WITH A SMALL CUTTING WHEEL AND PICK STRAIGHTEN ALREADY CROSSED THREADS - AFTER INSTALLING HOSE/PIPE COMBO - INSTALL REMOVED PLUMBING TEMPORARLY TO TAKE MEASUREMENT FOR NEW LENGTH OF A VICTALIC COUPLER PIPE TO THREAD INTO INTAKE VALVE - SEARCHED IN PARTS AND IN OUR PIPE FITTING STASH - NG - HAD NO PIPE FITTING OF THIS SIZE OR LENGTH HAVE PARTS CALL AROUND TO HAVE ONE MADE WILL INSTALL WHEN IT ARRIVES WHILE PLUMBING WAS APART REBUILD RECIRC VALVE INSTALL NEW COUPLER FITTING FINISH ASSEMBLY FILL WATER TANK AND CHECK FOR LEAKS ALL OK NOW. CUT AND MAKE A PROTECTION COVER OVER THE FILL PIPE AND HOSES SO HOSE WILL NOT BE STEPPED ON AND PULL FITTING OUT OF TANK AGAIN CUT PIECE WELD AND INSTALL IN VEHICLE DRILL AND TAP BOLT DOWN HOLES.

**Parts**

**Quantity**

370001ASEAL 35066	2
380003ASEAL	2
91368904 VALVE KIT 1 1/2 IN	1
FREIGHTSHIPPING CHARGES	20
N/I NIPPLESS 2.5 X 5 VIC THD	1

**Workorder: V61474**

**In Date:** 10/23/2013

**Meter Reading:** 22,097.00

**Close Date:** 10/24/2013

**Problem?**

Light out in lightbar

**Task performed:**

TRAVEL TO 21 DRIVER COMPLAINT LIGHT OUT IN LIGHT BAR R&R CORNER STROBE IN LIGHT BOX.

**Parts**

**Quantity**

02036273300 TURBO94 CORNERLINEAR REFLECTOR	1
--	---



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V62355

In Date: 11/30/2013

Meter Reading:

Close Date: 12/31/2013

#### Problem?

Fuel guage in cab not working. B 21

#### Task performed:

DRIVER COMPLAINT FUEL ANGLE INOP CHECKED  
CHANGES ALL WORKING.

Parts

NO PARTS USED

Quantity

### Workorder: V62553

In Date: 12/07/2013

Meter Reading:

Close Date: 12/31/2013

#### Problem?

water gauge are not working in the cab or in the rear,and throttle is very loose in the rear. B 21

#### Task performed:

1. TRAVEL TO 21 DRIVER COMPLAINT WATER  
GAUGES INOP REPAIRED LOOSE CONNECTION AT  
PUMP PANEL.  
2. DRIVER COMPLAINT THROTTLE CABLE LOOSE NO  
PROBLEM FOUND.

Parts

NO PARTS USED

Quantity

### Workorder: V62847

In Date: 12/20/2013

Meter Reading:

Close Date: 12/31/2013

#### Problem?

pump panel throttle is stuck. need to fix asap for dry brush. thanks

#### Task performed:

TRAVEL TO ST-21 CHECK OUT PUMP INOP CHECK  
OUT MOTOR THROTTLE STUCK R&R THROTTLE  
CABLE ON REAR OF BRUSH CONTROL ADJUST TEST  
OK.

Parts

NO PARTS USED

Quantity

### Workorder: V62937

In Date: 12/24/2013

Meter Reading:

Close Date: 12/31/2013

#### Problem?

Left rear facing (driver's side of vehilce) code 3/warning lights do not operate. At first they blink then immediatly stop working. B 2'

#### Task performed:

DRIVER COMPLAINT STROBE LIGHT OUT R/R  
STROBE LIGHT.

Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V63303**

In Date: 01/10/2014

Meter Reading:

Close Date: 01/16/2014

**Problem?**

need front tires replaced worn badly on outside and shakes when driving. also need gear oil replaced and any other maintenance performed for running high water. spent time in high water call in batt 4. B21

**Task performed:**

Parts

Quantity

CHECKED FOR TIRES CALL SHOP FOR REPLACEMENT.

NO PARTS USED

**Workorder: V63336**

In Date: 01/10/2014

Meter Reading: 10,654.00

Close Date: 01/24/2014

**Problem?**

need front tires replaced worn badly on outsides. need alignment checked. shakes when driving/braking. also need gear oil changed. drove in high water in batt 4. also any other service required for running high water.

**Task performed:**

Parts

Quantity

NEED FRONT TIRES REPLACED WORN BADLY ON OUTSIDES. NEED ALIGHMENT CHECKED. SHAKES WHEN DRIVING/BRAKING. ALSO NEED GEAR OIL CHANGED. DROVE IN HIGH WATER IN BATT. 4. ALSO ANY OTHER SERVICE REQUIRED FOR RUNNING HIGH WATER.

NO PARTS USED

**Vendor?:** BOULEVARD TIRE CENTE

**Workorder: V66847**

In Date: 05/29/2014

Meter Reading:

Close Date: 06/11/2014

**Problem?**

Stihl Farm Boss (#41) NEW CHAIN BLADE NEEDED BAR CHAIN OIL NEEDED

**Task performed:**

Parts

Quantity

Travel to 21 Driver complaint chain saw chain worn replaced chain.

NO PARTS USED

**Workorder: V66862**

In Date: 05/30/2014

Meter Reading: 11,590.80

Close Date: 06/17/2014

**Problem?**

B21 check air leak

**Task performed:**

Parts

Quantity

went to scene to lion country safari went into woods found emergency brake line fitting in brake chamber broken off R&R fitting ck, ok.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V67654**

In Date: 07/03/2014  
Close Date: 07/09/2014

Meter Reading: 11,799.00

**Problem?**

Check front end

**Task performed:**

Traveled to station 21. Checked out front end. Tires are wearing bad on outside. Needs alignment on front. No spairs in stock. Will wait till next week to swap out.

Parts

Quantity

NO PARTS USED

**Workorder: V67889**

In Date: 07/14/2014  
Close Date: 07/16/2014

Meter Reading:

**Problem?**

Left turn signal is out. And front emergency light is out. b21

**Task performed:**

Travel to 21 driver complaint left signal light is out and strobe out. Replaced signal and strobe.

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE  
H35SN12BULB

1  
1

**Workorder: V68266**

In Date: 07/29/2014  
Close Date: 08/05/2014

Meter Reading:

**Problem?**

Left turn signal front and back are not working e21

**Task performed:**

Travel to 21. Checked lights on engine, all working fine.

Parts

Quantity

NO PARTS USED

**Workorder: V68356**

In Date: 08/02/2014  
Close Date: 08/06/2014

Meter Reading:

**Problem?**

driver side turn signal/ hazard light not working

**Task performed:**

REPAIRED SIGNAL LIGHTS.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V68626**

In Date: 08/12/2014  
Close Date: 08/13/2014

Meter Reading: 11,813.00

**Problem?**  
replace 2 tires

**Task performed:**

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V69680**

In Date: 09/25/2014  
Close Date: 09/25/2014

Meter Reading: 24,646.00

**Problem?**  
Headlight inop

**Task performed:**

Remove & replace headlight.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

**Workorder: V70456**

In Date: 10/27/2014  
Close Date: 11/03/2014

Meter Reading: 11,890.00

**Problem?**  
Water leak

**Task performed:**

1. Checked out water leak; Found piping for front discharge leaking under truck. (limited visability and acces.) Replaced victalid o-ring but piping still leaked.
2. Removed entire pipe assembly and found pin hole leak near coupler also removed elbow and connector pipe and sent for new parts at Macko
3. Recieved new pipe parts, reassembled all piping and tested. No further leaks found.

Parts	Quantity
485107HOSE AND FITTING	1
7001-15EG150T SEAL	1
7001-20ESEAL	1

**Workorder: V70004**

In Date: 10/08/2014  
Close Date: 11/04/2014

Meter Reading: 11,862.00

**Problem?**  
left turn signal 10/7 reminded of prior work request for front jumpline leak

**Task performed:**

1. Travel to 21-remove and replace rear bulb for signal
2. Rear vehicle fittings are rusted thru will order parts

Parts	Quantity
H35SN12BULB	1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

### Workorder: V70949

In Date: 11/15/2014

Meter Reading:

Close Date: 11/20/2014

#### Problem?

driver side red and back passenger red/yellow emergency lights not working B21

#### Task performed:

#### Parts

#### Quantity

Travel to station 21, check out strobe out-R/R light assy.

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

### Workorder: V71446

In Date: 12/06/2014

Meter Reading:

Close Date: 12/15/2014

#### Problem?

Chainsaw on brush truck is not turning over. This chainsaw was originally on E21 but we swapped them out.

#### Task performed:

#### Parts

#### Quantity

Travel to 21-adjusted carb on saw and ran ok.

NO PARTS USED

### Workorder: V71929

In Date: 12/30/2014

Meter Reading:

11,981.00

Close Date: 01/09/2015

#### Problem?

drivers side pump panel light out in rear of truck under hose bed

#### Task performed:

#### Parts

#### Quantity

Checked all lights no problem found

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

Workorder: V71783

In Date: 12/20/2014

Meter Reading: 12,008.00

Close Date: 02/10/2015

**Problem?**

C inspection B21

**Task performed:**

- 1a. & 1b. C Inspection.
- 2. Batteries. Main battery and pump.
- 3. Air filters.
- 4. Left side strobe out.
- 5. Upper radiator hose on pump engine.
- 6. Service air dryer.
- 7. Repack pump packing and call manufacturer for information.
- 8. Rebuild direct fill valve.
- 9. L1 door loose. Tighten up.
- 10. Front end alignment.
- 11. Assist with alignment.
- 12. Remove exhaust muffler from truck and order parts.
- 13. Install exhaust.
- 14. Finish up exhaust.
- 15. Adjust brake pedal and install new door handles. Rewire compartement light.

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBE	3
020383481RALENS SPLIT RED/AMBER	1
102245111661 GAUGE TANK LEVEL CLASS 1	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1141BULB	3
1893BULB	1
2032-0000-30LENS CLEAR	1
20A-400CLAMP 4" 33969	8
357884 IN CLAMP	2
38171048 PER PACK PACKING-PUMPS DARLEY	1
40022STAINLESS FLEX PIPE 4"	6
5309453094 EXHAUST PIPE	1
6807200575HANDLE DOOR	1
681181583LIS68-1181583-LIS LENS AMBER	1
800405PURGE VALVE KIT	1
91388906 VALVE KIT 2.5 IN AKRON	1
EAA-8350-90UGSS6558UK STRUT-LIFT	6
FP588F33393 FUEL FILTER ISUZU 8-94414796	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LFP5748FILTER OIL 57411	1
R20P33614 FILTER FUEL	1
R90PFILTER FUEL 33231	1
M090594MUFFLER	1
1156BULB	1
99080C ROUND CLEAR LENS	1
24-60BATTERY GROUP 24	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	2
CA8193AIR FILTER 46744 WIX	1
CA8737AIR FILTER WIX 46562 L/F LAF4544	1
FRT 66425FREIGHT CHARGE	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

**Workorder: V73291**

In Date: 02/20/2015  
Close Date: 02/24/2015

Meter Reading: 12,023.00

**Problem?**

water level gauge inop

**Task performed:**

Replaced water level gauge and calibrated.

Parts

Quantity

102245111661 GAUGE TANK LEVEL CLASS 1

1

**Workorder: V73408**

In Date: 02/25/2015  
Close Date: 02/27/2015

Meter Reading:

**Problem?**

LEAK AT COUPLING AT NOZZLE

**Task performed:**

Travel to ST 27. Replaced leaking 90 degree fitting and hose reel.

Parts

Quantity

7001-15EG150T SEAL

1

BD5501516160BD55015-1616-01 SWIVEL

2

**Workorder: V74099**

In Date: 03/23/2015  
Close Date: 03/23/2015

Meter Reading: 12,176.00

**Problem?**

WESTWAY TO TOW FROM ST21 TO SHOP

**Task performed:**

Parts

Quantity

NO PARTS USED

Vendor?: WESTWAY TOWING

**Workorder: V73407**

In Date: 02/25/2015  
Close Date: 04/07/2015

Meter Reading:

**Problem?**

10-7; motor starts, drive shaft won't rotate

**Task performed:**

1. Travel to 21, checked brush truck, drive line ok.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

## Workorder: V73616

In Date: 03/03/2015

Meter Reading:

Close Date: 04/07/2015

### Problem?

wire hanging below motor

### Task performed:

#### Parts

#### Quantity

1. Driver complaint pump will not start in cab. Repaired broken wire to relay.

NO PARTS USED

## Workorder: V74324

In Date: 03/31/2015

Meter Reading: 12,176.00

Close Date: 04/23/2015

### Problem?

A-inspection Back from Cummins

### Task performed:

#### Parts

#### Quantity

- L/F fender maker LT out. Remove lens. Fixture melted. R&R entire L/F turn sig/maker LT and harness assembly
- R&R lens, R&R 2 bulbs L/S mid body marker LT.
- Repair top section of grille- falling off hood.
- Check trans code 6600. Check coolant temp connector. Check coolant levels W. connector. Check TPS connector. R&R R/S of dash. Check both allison trans computer connectors and pins. Erase code, road test veh. No code returned.
- R&R wiper blades.
- Check leaks at fuel INJ lines cyl at and #2. Tighten and road test. Cyl #1 ok, cyl #2 N.G. Loosen and retighten, still N.G. order new #2 cyl ING line.
- R&R cyl #2 INJ line bleed fuel system- Road test, ok no leak. Check eng LT on. Check codes. Erase codes. Road test, no codes returned.
- A- Inspection.
- Diagnose and repair w/washers. Replace tee fitting hose connector.
- Tighten loose bolts on intake manifold.
- Adj A/C fan belt.

1893BULB

2

194BULB

2

3944688FUEL LINE #2 ISC CUMMINS

1

52-24WIPER BLADES ANCO 24

2

6808200020LIGHT ASSY. TURN SIGNAL

1

SPR-W58-1TEE PLASTIC

1

SPR-60191-2600BQWIPER ARM ASSBLY

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136350

\* BRUSH TRUCK

## Workorder: V74034

In Date: 03/20/2015

Meter Reading: 12,176.00

Close Date: 04/27/2015

### Problem?

no start

### Task performed:

check unit for no start

1. Checked truck for codes, found no codes. replaced fuel filters. Checked fuel input and output at fuel pump. Had no output from pump. Truck is going to cummins for fuel pump.

2. Drive to location. Check unit fuel pump, making noise when cranking, possible damage, swap team to SB6.

### Parts

### Quantity

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

1

R90PFILTER FUEL 33231

1

## Workorder: V73273

In Date: 02/19/2015

Meter Reading:

Close Date: 06/30/2015

### Problem?

recalibrate the pump panel water gauge

### Task performed:

### Parts

### Quantity

NO PARTS USED



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10136350) 2001 - FREIGHTLINER FL80BM Brush Truck B21

10136350

**CSHOP-2015-2060**

Comments: **CHAIN SAW WONT START B21**

Date Opened: 8-3-2015      Date Finished      8-4-2015      Meter 1 Reading:      12,230

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE FIGHTING EQUIPMENT

**CSHOP-2015-2301**

Comments: **MIRROR B21**

Date Opened: 8-13-2015      Date Finished      8-18-2015      Meter 1 Reading:      12,230

**TASKS PERFORMED**

**Q      PARTS**

MIRRORS

1      MIRROR; 12173 MIRROR 8 IN

**CSHOP-2015-2642**

Comments: **REAR STROBES AND 2 ABOVE REAR WHEELS NOT WORKING B21**

Date Opened: 9-1-2015      Date Finished      9-8-2015      Meter 1 Reading:      12,230

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS

1      9IP; POWER SUPPLY

**CSHOP-2015-3250**

Comments: **BOOSTER REWIND 10-7 B21**

Date Opened: 10-5-2015      Date Finished      10-8-2015      Meter 1 Reading:      12,775

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
HOSE REEL

1      HOSE; MOTOR HOSE REEL  
1      GEAR; GEAR CHAIN DRIVE HANNA

**Service Requests:**

10/05/2015      BODY / 12: BROKEN / EXCHANGE - NEW  
BOOSTER REEL REWIND BUTTON NOT WORKING ON B21

**CSHOP-2015-3526**

Comments: **B21 STUCK**

Date Opened: 10-20-2015      Date Finished      10-22-2015      Meter 1 Reading:      12,821

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER

**Asset Work Order History 10136350**

**CSHOP-2015-4450**

Comments: **B22 DRIVERS SIDE STEP LOOSE**

Date Opened: 12-14-2015      Date Finished      12-16-2015      Meter 1 Reading:      13,076

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CAB STEP  
HOSES-LINES & FITTINGS

**Service Requests:**

- 
- 12/12/2015      BODY / 12: BROKEN / REPAIRED BROKEN STEP  
DRIVER SIDE STEP IS LOOSE AND NOT REALLY SUPPORTING WEIGHT AS IT SHOULD.IT NEEDS FIXING OR REPLACING IMMEDIATLY.
  - 12/12/2015      HAZARD / 32: POROSITY / REPLACED BOOSTER REEL HOSE  
BOOSTER REEL HOSE IS CRACKING RIGHT BEHIND NOZZEL AND NEEDS REPLACING IMMEDIATLY.
- 

**CSHOP-2015-4612**

Comments: **B21**

Date Opened: 12-23-2015      Date Finished      1-5-2016      Meter 1 Reading:      13,076

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP  
STROBE LIGHTS

- 1      RELAY; RY48 RELAY
- 3      LIGHT; 600 SERIES RED LED W/O FLANGE
- 6      LIGHT; 600 SERIES RED LED W/O FLANGE
- 1      ELECTRICAL; TERMINAL BOX
- 2      9IP; 68-1181363-5S LENS RED 64 SERIES
- 3      LIGHT; 600 LIN SUPER LED FLASH

**Service Requests:**

- 
- 12/23/2015      LIGHTS / 12: BROKEN / REPLACED STROBES WITH LED LIGHTS  
TOP STROBE LIGHT BAR ON PASSENGER SIDE NOT WORKING. REAR STROBE LIGHT, ABOVE TURN SIGNAL, ON DRIVERS SIDE NOT WORKING ORANGE SIDE MARKER LIGHT, IN FRONT OF REAR WHEEL, ON PASSENGER SIDE NOT WORKING WHITE REAR PANEL LIGHT, ABOVE PUMP PANEL, ON PASSENGER SIDE NOT WORKING
  - 12/29/2015      SERVICE REQUEST / 12: BROKEN / SENT TO SHOP FOR REPAIR  
THERE IS A BROKEN THROTTLE CABLE ON THE "FLOAT-A-PUMP" THAT WAS ON BRUSH 21. WE TAGGED IT OUT OF SERVICE AND PLACED IT IN THE CLOSET IN THE BAY AT 21.
- 

**CSHOP-2015-566**

Comments: **FLASHERS ON GRILL AND FENDERS NOT WORKING B21**

Date Opened: 5-11-2015      Date Finished      5-14-2015      Meter 1 Reading:      12,230

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS

- 1      9IP; POWER SUPPLY
-

**Asset Work Order History 10136350**

**CSHOP-2016-1188**

Comments: **B21 AIR BRAKE PROBLEM**

Date Opened: 3-12-2016      Date Finished      3-24-2016      Meter 1 Reading:      13,266

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**Service Requests:**

---

03/12/2016      BRAKES / 18: LEAKING / REPAIR  
CAN NOT DISENGAGE PARKING BRAKE DUE TO VERY LOW AIR PRESSURE. TRUCK REQUIRES TO IDLE IN THE BAY FOR MOMENT(S) TO BUILD UP AIR PRESSURE. MORE NOTABLE DURING MORNING TRUCK CHECK. COULD DELAY RESPONSE TIME(S) AND CAUSES UNNECESSARY PRODUCTION OF DIESEL EXHAUST IN BAYS.

03/12/2016      LIGHTS / 12: BROKEN / REPAIR  
SEVERAL LIGHTS OUT ON VEHICLE. 1. TOP RED STROBE BAR ON PASSENGER SIDE 2. SIDE ORANGE MARKER LIGHT ON PASSENGER SIDE 3. WHITE PUMP PANEL LIGHT, PASSENGER SIDE, DIRECTLY BELOW HOSE BED.

---

**CSHOP-2016-1361**

Comments: **B-21**

Date Opened: 3-22-2016      Date Finished      3-24-2016      Meter 1 Reading:      13,266

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM  
AIR SYSTEM  
STROBE LIGHTS  
SIREN

1      BULB; BULB  
2      9IP; LINEAR REF. ASSY.  
1      REFLECTOR; OBSOLETE 1/2016 TURBO94 CORNERLINEAR REFLECTOR  
1      SIREN; SIREN DRIVER SMALL

**Service Requests:**

---

03/21/2016      BRAKES / 12: BROKEN / EXCHANGE - NEW  
1. AIR TANKS LEAK TO ZERO IN A FEW HOURS. 2. EMERGENCY LIGHTS OUT ON CAB LIGHTBAR 3. SIREN BROKEN 4. RIGHT SIDE PUMP PANEL LIGHT OUT.

---

**CSHOP-2016-2253**

Comments: **B21 STUCK**

Date Opened: 5-10-2016      Date Finished      5-10-2016      Meter 1 Reading:      13,334

**TASKS PERFORMED**

**NO PARTS USED**

FIRE APPARATUS

---



**Asset Work Order History 10136350**

**CSHOP-2016-287**

Comments: **B21 HOSE BED COVER**

Date Opened: 1-21-2016      Date Finished      1-26-2016      Meter 1 Reading:      13,076

**TASKS PERFORMED**

**NO PARTS USED**

HOSE BED BODY

**VENDOR?**      CENTRAL AUTO TRIM CO.

**Service Requests:**

---

01/18/2016      BODY / 41: TORN/PUNCTURED / REPAIR  
WE NEED A HOSEBED COVER FOR B21 MADE BY CENTRAL AUTO TRIM FOR B21. AS SOON AS POSSIBLE. NEED TO PREVENT THE 600' OF SUPPLY HOSE NEWLY PLACED IN THE HOSEBED FROM ACCIDENTALLY FALLING OUT WHEN DRIVING OFF ROAD ON BRUSH FIRES.

---

**CSHOP-2016-3166**

Comments: **B21 LEAKING AIR AND CHECK ENGINE LIGHT ON**

Date Opened: 7-1-2016      Date Finished      7-8-2016      Meter 1 Reading:      13,694

**TASKS PERFORMED**

**Q      PARTS**

FAULT CODE

**1      VALVE; PURGE VALVE KIT**

**Service Requests:**

---

07/01/2016      ENGINE / 18: LEAKING / OVERHAUL  
CHECK ENGINE LIGHT ON, MASSIVE AIR LEAK, AIR LEVEL WAS AT 0 THIS AM, AFTER RUNNING LAST NIGHT AROUND 8 PM

---

**CSHOP-2016-3339**

Date Opened: 7-12-2016      Date Finished      8-9-2016      Meter 1 Reading:      13,718

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**Service Requests:**

---

07/08/2016      BRAKES / 18: LEAKING / REPAIR  
TRUCK TAKES A WHILE TO ENGAGE INTO DRIVE. AIR LEAK.

---

**CSHOP-2016-3667**

Date Opened: 8-1-2016      Date Finished      8-1-2016      Meter 1 Reading:      13,718

**TASKS PERFORMED**

**NO PARTS USED**

REAR TIRES

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**Asset Work Order History 10136350**

**CSHOP-2016-4381**

Comments: **C INSPECTION B21**

Date Opened: 9-7-2016

Date Finished

9-8-2016

Meter 1 Reading:

13,954

**TASKS PERFORMED**

PM SERVICE C

**Q PARTS**

---

1	FILTER; AIR FILTER 46744 WIX
1	FILTER; FILTER FUEL 33231
1	FILTER; 33393 FUEL FILTER ISUZU 8-94414796
1	FILTER; OIL FILTER 51748
1	FILTER; FILTER OIL 57411
1	FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1	9IP; AIR FILTER WIX 46562 L/F LAF4544
38	FLUID; SYN OIL BULK QTS
1	FILTER; 33614 FILTER FUEL

---

**CSHOP-2016-4394**

Comments: **REPAIRS FROM PM**

Date Opened: 9-8-2016

Date Finished

10-3-2016

Meter 1 Reading:

13,954

**TASKS PERFORMED**

GROUND LIGHT BODY  
PRIMING PUMP FIRE PUMP  
GEAR BOX FIRE PUMP  
FIRE PUMP  
HOSE REEL  
EQUIPMENT MOUNTING BRACKETS  
DISCHARGE GAUGE  
WIPER BLADES  
FUEL TANK  
EXHAUST PIPE  
BY-PASS HOSES  
RADIATOR  
COOLING SYSTEM  
ENGINE AND ACCESSORIES  
LIGHTING SYSTEM  
SWITCH-ELECTRICAL  
DIAGNOSE ELECTRICAL  
TRANSFER CASE  
FILTER  
TIRES ALL  
REPAIR FROM PM - BELTS  
SUSPENSION  
STEERING  
AIR DRIER  
AIR SYSTEM  
FAULT CODE  
AIR HORN  
BACK-UP ALARM  
DOOR STRIKER PLATE  
DOOR WEATHER MOLDING  
FENDER  
SEAT BELTS

**Q PARTS**

---

1	ORING; ORING KIT
1	VALVE; 8905 VALVE KIT 2 IN AKRON
1	9IP; STRAINER 4 IN
1	9IP; PACKING PUMPS
1	SWITCH; SWITCH COVER
1	NEWPART; HOSE & FITTING
1	CLASS 1; TRANSDUCER 500 PSI
2	WIPER; WIPER BLADES ANCO 24
8	FLUID; COOLANT ANTIFREEZE GAL
1	FILTER; 24070 WIX FILTER WATER
1	9IP; PLUG RAD. DRAIN
1	LIGHT; 46793 AMBER MARKER LIGHT
1	LIGHT; 4 IN LIGHT
2	SWITCH; 82-2106 TOGGLE GUARD
1	9IP; EL35012 SWITCH ROCKER
1	PLUG; DRAIN PLUG
1	PLUG; FILL PLUG GASKET
10	GEAR; GEAR OIL SYN QT
7	FLUID; ALLISON TRANS FLUID GAL
1	FILTER; 29548988 TRANS FILTER ALLISON
1	BELT; BELT SAME AS 3281981 CUMMINS
1	BELT; BELT
1	FILTER; FILTER P/S
1	9IP; WASHER P/S
1	GASKET; GASKET P/S COVER
1	DRYER; DRYER KIT AD9 -NEW
1	VALVE; 90555409 VALVE CHECK PRESSURE PROTECTED
1	VALVE; VALVE PARKING BRK.
3	DRAIN; DRAIN COCK
1	HORN; KIT-AIR HORN-GROVER
1	HORN; HORN HIGH NEW # 06-52125-039
1	ALARM; BACKUP ALARM ECCO 107 DEC
1	SEAL; SEAL DOOR
1	NEWPART; SPLASH SHIELD

---

**Asset Work Order History 10136350**

**CSHOP-2016-4533**

Date Opened: 9-19-2016      Date Finished      9-19-2016      Meter 1 Reading:      13,954

**TASKS PERFORMED**

**NO PARTS USED**

---

REAR TIRES

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2016-4994**

Date Opened: 10-20-2016      Date Finished      10-21-2016      Meter 1 Reading:      13,954

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
COMPARTMENT LIGHT BODY  
FIRE PUMP

**Service Requests:**

---

10/20/2016      SERVICE REQUEST / 18: LEAKING / REPAIR  
SERVICE REQUEST .....THE 1/4 INCH BRASS BEZEL ON THE HOSE FROM THE PUMP TO THE MAIN DISCHARGE  
PRESSURE GAUGE IS LEAKING

10/20/2016      LIGHTS / 19: LOOSE / REPAIR  
VEHICLE LIGHTS NOT WORKING... PUMP PANEL LIGHT HAS FALLEN OFF AND IS ON THE OFFICERS DESK.

---

**CSHOP-2016-5582**

Date Opened: 11-29-2016      Date Finished      1-13-2017      Meter 1 Reading:      14,164

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP

**Service Requests:**

---

11/24/2016      SERVICE REQUEST / 18: LEAKING / INSPECT  
BRUSH TRUCK HAS A WATER LEAK UNDERNEATH REAR DRIVERS SIDE OF VEHICLE. UPON INVESTIGATION OF  
LEAK, IT SEEMS LIKE IT MAY BE COMING FROM EITHER THE LINE THAT FEEDS THE FRONT HOSE ON THE FRONT  
BUMPER OR THE PASSENGER SIDE HOSE REEL.

---

**CSHOP-2016-5781**

Date Opened: 12-12-2016      Date Finished      1-19-2017      Meter 1 Reading:      14,164

**TASKS PERFORMED**

**NO PARTS USED**

---

INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

---

12/10/2016      SERVICE REQUEST / 12: BROKEN / INSPECT  
WATER GAUGE ON PUMP PANEL NEEDS TO BE RE-CALIBRATED.

---

**Asset Work Order History 10136350**

**CSHOP-2016-6125**

Comments: **B-21 AIR HORN NOT WORKING.**

Date Opened: 12-30-2016      Date Finished      1-10-2017      Meter 1 Reading:      14,164

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR HORN

1      9IP; 9IP

**Service Requests:**

---

12/30/2016      ALARMS / 12: BROKEN / EXCHANGE - NEW  
ALARM SIGNALS AIR HORN IS NOT WORKING AT ALL.

---

**CSHOP-2016-648**

Comments: **B21**

Date Opened: 2-9-2016      Date Finished      3-9-2016      Meter 1 Reading:      13,221

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM

1      9IP; 85 PSI VALVE PR-4

**Service Requests:**

---

02/09/2016      BRAKES / 18: LEAKING / REPLACED LEAKING PRESSURE PROTECTION VALVE  
AIR LEAK,,,,,PROBLEM STILL NOT CORRECTED /REPAIRED

---

**CSHOP-2016-81**

Comments: **B21 AIR LEAK**

Date Opened: 1-7-2016      Date Finished      2-2-2016      Meter 1 Reading:      13,168

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM

**Service Requests:**

---

01/07/2016      BRAKES / 18: LEAKING / REPAIRED LOOSE AIR FITTINGS  
AIRLEAK ,,TRUCK WILL NOT HOLD AIR IN TANKS AND BLEEDS DOWN TO ZERO WITHIN A FEW HOURS,,,THIS CAUSES  
OPERATOR TO "REV" ENGINE FOR SEVERAL MINUTES BEFORE THE BRAKES WILL RELEASE POSSIBLY DELAYING  
RESPONSE

---

**Asset Work Order History 10136350**

**CSHOP-2017-1540**

Date Opened: 3-13-2017      Date Finished      5-16-2017      Meter 1 Reading:      14,934

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM  
INSTRUMENTS-GAUGES-WARNING &

4      5TN; MNT  
2      5TN; LIGHT, MINI BROW 9" LNG  
1      GRO; SWITCH  
1      BK; FUSE HOLDER  
1      NONSTOCK; FREIGHT CHARGE  
1      5SC; HARNESS  
1      5SC; TANK LEVEL DISPLAY 4-LIGHT LARGE  
1      5SC; FOAM/ WATER LEVEL SENSOR  
1      5SC; LABEL, RED FOAM LEVEL

**Service Requests:**

03/11/2017      SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW  
SERVICE REQUEST WATER LEVEL GAUGE ON PUMP PANEL MISSING

**CSHOP-2017-2092**

Date Opened: 4-10-2017      Date Finished      4-13-2017      Meter 1 Reading:      14,735

**TASKS PERFORMED**

**NO PARTS USED**

FIRE PUMP

**Service Requests:**

04/10/2017      SERVICE REQUEST / 18: LEAKING / REPAIR  
SERVICE REQUEST SIGNIFICANT WATER LEAK AT PUMP HOUSING ON BRUSH 21.

**CSHOP-2017-236**

Comments:      **B-21 STROBES NOT WORKING ONLY TOP OF TRUCK.**

Date Opened: 1-11-2017      Date Finished      1-12-2017      Meter 1 Reading:      14,164

**TASKS PERFORMED**

**Q      PARTS**

STROBE LIGHTS

1      9IP; RY-30T RELAY 5 PIN 12V

**Service Requests:**

01/11/2017      LIGHTS / 38: SHORTED / EXCHANGE - NEW  
VEHICLE LIGHTS NOT WORKING. EMERGENCY STROBES ARENT WORKING..ONLY ON THE TOP OF THE CAB

**CSHOP-2017-3157**

Date Opened: 5-30-2017      Date Finished      5-30-2017      Meter 1 Reading:      14,954

**TASKS PERFORMED**

**NO PARTS USED**

SPOT LIGHTS

**Service Requests:**

05/28/2017      LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
OFFICER SIDE REAR FLOODLIGHT OUT.

**Asset Work Order History 10136350**

**CSHOP-2017-4169**

Date Opened: 7-17-2017      Date Finished      8-21-2017      Meter 1 Reading:      15,150

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SIREN

**Service Requests:**

07/16/2017      SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
SERVICE REQUEST. B21 SIRENS COME ON WITHOUT ACTIVATING IT. B21 ALARM DOOR OPEN WHEN DRIVING BUT ALL DOORS ARE CLOSE. CHECK ENGINE LIGHT ON.

**CSHOP-2017-5334**

Date Opened: 9-14-2017      Date Finished      9-15-2017      Meter 1 Reading:      15,349

**TASKS PERFORMED**

**Q      PARTS**

LIGHTING SYSTEM

2      LMP; HALOGEN LAMP

**Service Requests:**

09/12/2017      LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING RIGHT FRONT HEADLIGHT OUT NOT WORKING

**CSHOP-2017-5517**

Date Opened: 9-22-2017      Date Finished      9-25-2017      Meter 1 Reading:      15,349

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP  
BATTERY  
CRANKING SYSTEM

2      1AD; BATTERY

**Service Requests:**

09/22/2017      BODY / 12: BROKEN / REPAIR  
BRUSH 21 LEAKING REALLY BAD THROUGH ALL THE REAR PIPING.

09/25/2017      ENGINE / 12: BROKEN / REPLACE BATTERY``S  
ENGINE - PUMP ENGINE WILL NOT START. BC28 NOTIFIED AND ADVISED TO CALL SHOP, SHOP NOTIFIED.

**CSHOP-2017-5812**

Date Opened: 10-10-2017      Date Finished      12-14-2017      Meter 1 Reading:      28,298

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
PONY PUMP MOTOR  
DIAGNOSE ELECTRICAL  
AIR SYSTEM

**Service Requests:**

10/07/2017      SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST - UNABLE TO TURN PUMP ON USING PUMP IGNITION INSIDE OF CAB - PUMP IGNITION DOES WORK ON BACK OF TRUCK

**Asset Work Order History 10136350**

**CSHOP-2017-582**

Comments: **WATER LEAK AND INSTALL FUEL SYSTEM**

Date Opened: 1-26-2017      Date Finished 4-20-2017      Meter 1 Reading: 14,735

**TASKS PERFORMED**

**NO PARTS USED**

A INSPECTION

---

**CSHOP-2017-7086**

Date Opened: 12-12-2017      Date Finished 12-14-2017      Meter 1 Reading: 28,298

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE C

**Service Requests:**

---

12/12/2017      BRAKES / 12: BROKEN / INSPECT  
BRAKE ISSUES AIR PRESSURE LEAKS COMPLETELY OUT OF BOTH TANKS IN ABOUT 2 HOURS. PLEASE FIX ASAP

---

**CSHOP-2017-932**

Date Opened: 2-14-2017      Date Finished 3-8-2017      Meter 1 Reading: 14,164

**TASKS PERFORMED**

**Q      PARTS**

FIRE PUMP PLUMBING	3	SEAL; SEAL
FIRE PUMP	1	9HY; NIPPLE
STEPS	1	9AP; A1 INDUSTRIAL
BODY EXTERIOR	1	9HY; MAKO PIPE CAPS
	1	9IP; PACKING PUMPS

---

**CSHOP-2018-1199**

Date Opened: 2-27-2018      Date Finished 2-28-2018      Meter 1 Reading: 28,338

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP PLUMBING

---

**Asset Work Order History 10136350**

**CSHOP-2018-2473**

Comments: **PUMP LEAKING CHECK ENGINE LIGHT**

Date Opened: 5-4-2018      Date Finished 5-31-2018      Meter 1 Reading: 16,203

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
REAR HUB

2      TWD; BRAKE DRUM  
12      9AP; BRAKE CLEANER  
2      9IP; SEAL  
2      9IP; GASKET AXLE FL80 R002435  
2      MBI; GRIP/KIT

**Service Requests:**

05/04/2018      SERVICE REQUEST / 18: LEAKING / INSPECT  
OIL POURING DOWN DRIVERS SIDE BACK REAR TIRE FROM AXLE.

05/04/2018      BRAKES / 18: LEAKING / REPAIR  
BRAKE ISSUES SIGNIFICANT OIL LEAK FROM INSIDE THE DRIVER SIDE REAR WHEEL AREA. COLOR BLACK.  
RUNNING DOWN OUTSIDE SIDEWALL BELOW THE WHEEL ASSEMBLY. NEAR WHERE WHEEL MEETS AXLE HOUSING.

**CSHOP-2018-3679**

Date Opened: 6-29-2018      Date Finished 7-2-2018      Meter 1 Reading: 16,203

**TASKS PERFORMED**

**Q      PARTS**

TURN SIGNAL LIGHTS  
AIR CONDITIONING

1      1WL; BULB, 35 WATT 12V SNAP-IN  
1      TEM; SWITCH

**CSHOP-2018-4271**

Date Opened: 7-30-2018      Date Finished 8-1-2018      Meter 1 Reading: 16,203

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP

1      9ME; DARLEY PACKING, PUMP INJECT (8) PELLETS

**Service Requests:**

07/30/2018      SERVICE REQUEST / 18: LEAKING / REPAIR  
TYPE PROBLEM INTO DESCRIPTION BRUSH 21 PUMP IS LEAKING WATER BADLY WHEN RUNNING.

**CSHOP-2018-4472**

Date Opened: 8-10-2018      Date Finished 8-10-2018      Meter 1 Reading: 16,203

**TASKS PERFORMED**

**NO PARTS USED**

TURN SIGNAL LIGHTS

**Service Requests:**

08/10/2018      LIGHTS / 19: LOOSE / REPAIR  
VEHICLE LIGHTS NOT WORKING: LEFT FRONT BLINKER DOES NOT WORK



**Asset Work Order History 10136350**

**CSHOP-2018-6206**

Comments: FOUND ON PM DRIVERS DOOR MOLDING DRIVERS SEAT BELT LR SIDE MARKER OUT REAR MARKER OUT INTERMITTENT PUMP NO START IN CAB COMPARTMENT HOLD OPENS HOSE BED COVER RIGHT SIDE AMBER MARKER OUT RIGHT CORNER STROBE IN LT BAR OUT TO MUCH BRAKE PEDAL FREE PLAY CAB WATER LEVEL

Date Opened: 10-31-2018 Date Finished 3-19-2019 Meter 1 Reading: 16,203

**TASKS PERFORMED**

	<u>Q</u>	<u>PARTS</u>
TRAVEL TO BE CHARGED TO WORK ORDER	2	1AN; WIPER BLADE 24 IN
WIPERS-WASHER	1	FIL; NAPAGOLD AIR FILTER
FAULT CODE	1	FIL; NAPAGOLD AIR FILTER
ENGINE AND ACCESSORIES	2	9IP; BULB
LIGHTING SYSTEM	3	LIT; LED M C LAMP
DIFFERENTIAL	3	LIT; LED FITN FORGET PLG
AIR SYSTEM	32	4PC; GEAR OIL-SYN BULK (DELO)
BODY EXTERIOR	1	2FL; MOLDING LH
CAB-INTERIOR ACCESSORIES	1	9IP; MOLD R/H

**CSHOP-2018-6208**

Date Opened: 10-31-2018 Date Finished 11-21-2018 Meter 1 Reading: 16,450

**TASKS PERFORMED**

	<u>Q</u>	<u>PARTS</u>
PM SERVICE C	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD AIR FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; FUEL WATER SEPARATOR
	1	FIL; NAPAGOLD FUEL FILTER
	-1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; FUEL WATER SEPARATOR
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER

**CSHOP-2018-7296**

Date Opened: 12-26-2018 Date Finished 12-27-2018 Meter 1 Reading: 34,081

**TASKS PERFORMED**

	<u>Q</u>	<u>PARTS</u>
ALTERNATOR-GENERATOR	1	NBH; FHP TRUFLEX V-BELT

**Asset Work Order History 10136350**

**CSHOP-2018-7376**

Date Opened: 12-28-2018      Date Finished      11-4-2019      Meter 1 Reading:      16,203

**TASKS PERFORMED**

**NO PARTS USED**

---

BODY EXTERIOR

**VENDOR?**      CENTRAL AUTO TRIM CO.

**Service Requests:**

---

12/28/2018      SERVICE REQUEST / 18: LEAKING / REPAIR  
TOP EMERGENCY LIGHT BAR - LIGHTS ON ONE SIDE (DRIVERS SIDE) NOT FUNCTIONING

---

**CSHOP-2019-763**

Date Opened: 2-7-2019      Date Finished      2-19-2019      Meter 1 Reading:      16,203

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
EXHAUST SYSTEM

1      BK; CLAMP

---

**RADIO-2018-642**

Date Opened: 6-13-2018      Date Finished      6-12-2018      Meter 1 Reading:      0

**TASKS PERFORMED**

**NO PARTS USED**

---

RADIO

**Service Requests:**

---

06/11/2018      RADIO / /  
RADIO ISSUES

---