



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48286

In Date: 03/29/2012
Close Date: 04/13/2012

Meter Reading: 1,261.00

Problem?

B INSPECTION NEW RESCUE IN SERVICE

Task performed:

1. B INSPECTION.
2. COMPLETE B INSPECTION.
3. R&R AIR HORNS FOR STRIPING.
4. REMOVE MAIN AIR FITTING FROM TOP OF COMPRESSOR, RESEAL AND TIGHTEN.
5. TORQUE FRONT AND REAR U-BOLTS, HAD TO REMOVE BRACKETS FROM REAR U-BOLTS TO TORQUE.
6. REMOVE STAR WASHERS, FROM ALL GROUNDS, CLEAN AND REINSTALL BOLTS.
7. REMOVE STRETCHER MOUNTS, PULL IN R-15 START TV REMOVE STRETCHER MOUNTS, TO SWITCH, TOLD TO STOP.
8. START TO SET TRUCK UP WITH TOOL HOLDERS.
9. MOUNT TOOL HOLDERS IN L-2 COMPARTMENT.
10. MOUNT TOOL HOLDERS IN L-2 COMPARTMENT.
11. FINISH MOUNTING TOOL HOLDERS.
12. INSTALL GUTTER RAILS AND 9-11 STRICKERS.
13. INSTALL AND MAKE PLACARDS AND CAMPAIGN SIGNS.
14. REINSTALL STRETCHER LOCK AND MOUNT, ADJUST TO FIT STRYKER STRETCHER.
15. INSTALL NADER PIN COVERS.
16. INSTALL NEW SCBA BRACKET IN OFFICERS SEAT.

Parts

Quantity

101-124-000CRASH RESTRAINT STRAPS	1
14-7014HGR-1 HELMET HOOK	2
5269LPVM-5 SM MOUNT	3
6092036018J HOOK STRYKER	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
KD-UN-5-SFUSE 6-SF BRACKET	1
L PLACARDLARGE SIDE PLACARD	4
L PLACARD INSERTLARGE PLACARD INSERT CARD	4
LPVM-7LG MOUNT	3
S PLACARDFRONT AND BACK PLACARD	2
S PLACARD INSERTFRONT AND BACK INSERT CARD	2
UMVS162511STRAP	3
FHLP-6TANK CLIP	2

Workorder: V48438

In Date: 04/04/2012
Close Date: 04/18/2012

Meter Reading: 1,261.00

Problem?

drawer slides faulty/inop in pat comp

Task performed:

DRAW SLIDES LOOSE DUE TO SCREWS TOO SHORT, REMOVED ALL DRAW SLIDES AND INSTALLED LONGER SCREWS.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48674

In Date: 04/14/2012
Close Date: 04/25/2012

Meter Reading: 1,369.00

Problem?

The backboard compt. needs a safety strap mounted to protect backboards from falling out. The cab also needs to have some medical glove containers/mounted to the back of the center console.

Task performed:

INSTALLED BACK BOARD SAFETY STRAP IN R4 COMPARTMENT.

Parts

NO PARTS USED

Quantity

Workorder: V49116

In Date: 05/05/2012
Close Date: 05/14/2012

Meter Reading: 2,250.00

Problem?

air brakes are making a high squeeling sound when coming to a stop/start. R 14

Task performed:

1. TRAVEL TO 14 CHECKED BRAKES ON RESCUE - ALL LOOK GOOD. TRUCK MAKING AN ODD NOISE ON LOAD TEST. UNIT GOT CALLED OUT WILL RECHECK.
2. TRAVEL TO 14 ROAD TESTED AGAIN FOUND NOISE COMING FROM DUST BOOT ON LEVELING VALVES - CLEANED OUT VALVE OK.
3. REPROGRAM ECM TO STOP AUTO DOOR LEAKS AND UPDATED SOFTWARE PACKAGE.

Parts

NO PARTS USED

Quantity

Workorder: V49453

In Date: 05/17/2012
Close Date: 05/29/2012

Meter Reading: 2,746.00

Problem?

circuit breaker on R-14's a/c pt. care area keeps tripping. Also we need 4 medical glove box holders mounted in R-14 cab/pt. care area.

Task performed:

INSTALLED GLOVE BOX HOLDERS.

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49510

In Date: 05/21/2012
Close Date: 05/30/2012

Meter Reading: 3,030.00

Problem?

Med radio needs remounting in a forward position. Cab speaker needs remounting to face cab. Lt airpak cradle unsafe, driver airpak cradle not secure.

Task performed:

TRAVEL TO 14 INSTALL GLOVE BOX HOLDERS, SECURED SCBA WITH STRAP ADJUSTED RADIO SPEAKER. SEAT ON ORDER FOR OFFICERS SIDE.

Parts	Quantity
101-124-000CRASH RESTRAINT STRAPS	1

Workorder: V49835

In Date: 06/02/2012
Close Date: 06/21/2012

Meter Reading: 3,569.00

Problem?

Roof AC unit is not coming on when the shore line is plugged in R14

Task performed:

TRAVEL TO 14 CHECKED AMP DRAW ON 110 V A/C UNIT WHILE RUNNING PULLING 14 AMPS WHEN COMPRESSOR FIRST STARTS AMPS JUMP ABOVE TO TRIPS BREAKER NEEDS NEW UNIT.

Parts	Quantity
NO PARTS USED	

Workorder: V49896

In Date: 06/05/2012
Close Date: 06/26/2012

Meter Reading: 3,569.00

Problem?

REPLACE OFFICERS SEAT R14

Task performed:

REMOVED OFFICERS SEAT INSTALL NEW AIR RIDE SEAT RAN AIR LINES TO SEAT MOVED AIR PACK TO L-2 COMPARTMENT REMOUNTED EQUIPMENT.

Parts	Quantity
101-124-000CRASH RESTRAINT STRAPS	1
3711388C1BELT TETHER ASSY.	1
3711391C1BELT	1
FHLP-6TANK CLIP	2
KD-UN-5-SFUSE 6-SF BRACKET	1

Workorder: V50588

In Date: 07/03/2012
Close Date: 07/06/2012

Meter Reading: 5,312.00

Problem?

FEMALE HUB FOR SHORELINE CONNECTOR ON R14 LOOKS TO BE SHORTING OUT AND MAKING MALE CONNECTOR AND TRIPPING THE BREAKER

Task performed:

REPLACED FEMALE PLUG ON CORD FOR SHORE POWER.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50682

In Date: 07/08/2012

Meter Reading: 5,555.00

Close Date: 07/25/2012

Problem?

left rear ground light missing. only wires exposed. E14

Task performed:

TRAVEL TO 14 MOUNT AND REWIRE GROUND LIGHT

Parts

Quantity

607141-05USE 61H01 COPMPARTMENT LIGHT
MFG01876GROUND LT BRACKET

1
1

Workorder: V50990

In Date: 07/19/2012

Meter Reading: 5,822.00

Close Date: 07/25/2012

Problem?

mount axes in driver's side compartment R14

Task performed:

TRAVEL TO STA 19 MOUNTED AXES AND EQUIPMENT
IN L-1 COMPARTMENT.

Parts

Quantity

5269LPVM-5 SM MOUNT
LPVM-7LG MOUNT

4
4

Workorder: V51108

In Date: 07/25/2012

Meter Reading: 6,231.00

Close Date: 07/27/2012

Problem?

air conditioning not working in pt. compartment. tried the fuse/switch. no luck. R14

Task performed:

TRAVEL TO 14 CHECKED SYSTEM FOUND WIRES TO
RELAY UNDER REAR SEAT LOOSE. SECURED
WIRES AND FAN OPERATES OK.

Parts

Quantity

NO PARTS USED

Workorder: V51184

In Date: 07/28/2012

Meter Reading: 6,495.00

Close Date: 08/02/2012

Problem?

exhaust filter light is on, with wrench symbol R 14

Task performed:

1. TRAVEL TO 14 OIL CHANGE LIGHT ON. RESET OIL
CHANGE LIGHT.
2. DOOR HANDLE ON REAR DOOR LOOSE.
SECURED HANDLE WITH NEW SCREWS.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51233

In Date: 07/31/2012

Meter Reading: 6,569.00

Close Date: 08/02/2012

Problem?

110 a/c not working R 14

Task performed:

Parts

Quantity

TRAVEL TO SHOP AND REPLACED ROOF TOP A/C UNIT. UNIT DROWING TO MANY AMPS CAUSING BREAKER TO BLOW.

NO PARTS USED

Workorder: V51366

In Date: 08/04/2012

Meter Reading: 6,976.00

Close Date: 08/07/2012

Problem?

SCBA bracket on drivers compartment door is missing screw and hanging off door. Screw hole seems to be stripped. R14

Task performed:

Parts

Quantity

TRAVEL TO 14 REPLACED SCREWS IN SCBA BRACKET.

NO PARTS USED

Workorder: V51450

In Date: 08/07/2012

Meter Reading: 7,068.00

Close Date: 08/13/2012

Problem?

lights not working in rear cab R 14

Task performed:

Parts

Quantity

TRAVEL TO 14 COULD NOT DUPLICATE LIGHT PROBLEM WILL MONITOR.

NO PARTS USED

Workorder: V51949

In Date: 08/28/2012

Meter Reading:

Close Date: 09/06/2012

Problem?

rear hatch locked, key not working. Stairchair inside hatch r14

Task performed:

Parts

Quantity

1. TRAVEL TO 14 ADJUSTED AND LUBRICATE DOOR LATCH

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51886

In Date: 08/27/2012

Meter Reading:

Close Date: 09/12/2012

Problem?

Electric door locks Inop. R 14

Task performed:

Parts

Quantity

1. CHK ELECTRIC DOOR LOCKS NOT WORKING FOUND NO BLOWN FUSES WILL RECHK.
2. TRAVEL TO 14 REPLACED BLOWN FUSE IN PATENT COMP FOR DOOR LEAKS OK.

NO PARTS USED

Workorder: V51728

In Date: 08/20/2012

Meter Reading:

Close Date: 09/13/2012

Problem?

Left rear outer tire low pressure. Added air previous B shift. Tire is low again. R14

Task performed:

Parts

Quantity

- LFT REAR OUTER TIRE LOW PRESSURE. ADDED AIR PREVIOUSLY B SHIFT. TIRE IS LOW AGAIN.

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V51270

In Date: 08/01/2012

Meter Reading: 6,569.00

Close Date: 09/19/2012

Problem?

Replace roof top a/c R14

Task performed:

Parts

Quantity

- INSTALLED NEW VENT ASSYM W/ SWITCHES.

67305COLEMAN CEILING UNIT

1

Workorder: V52207

In Date: 09/06/2012

Meter Reading: 8,221.00

Close Date: 09/20/2012

Problem?

Honey do list for R14 1.oxygen leaks 2.auto door locks malfunction 3.rear hatch (under rear doors) jammed 4.front end vibration 3 mph 5.Lights in pt area not working 6.a/c breaker constantly tripping

Task performed:

Parts

Quantity

1. ROAD TEST FOR 35MPH VIBRATION COMPLAIN IN FRT END NO PROBLEM DETECTED.
2. AUTO DOOR LOCKS-DESIGN TO UNLOCK NOT LOCK.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52144

In Date: 09/04/2012

Meter Reading: 8,077.00

Close Date: 09/21/2012

Problem?

C INSPECTION AND NEEDED REPAIRS R14

Task performed:

1. C INSPECT
2. C INSPECT
3. L/R HAZARD FLASHER INOP- DIAGNOSE FAULT FOUND- LOOSE CONNECTOR IN BODY- CLEAN AND RESECURE CONNECTOR.
4. TURN SIGNAL L/S INOP-CHK RED ASSEM CHK INPUT AND OUT PUT MODULE GOOD CHK CABLING CONT GOOD CHK RELAYS FOUND ON WEAK RELAY
5. RESET COMP A/C COMPLAIN- CHK VENTS HIGH PRESSURE 160 LOW 30 DISCHARGE AIR TEMP 30 SYST.
6. DIFFERENTIAL SWAY BAR LOOSE- UNCABLE TO FIND TORQUE SPECS- TORQUE LOCK NUT W/ AIR RATCHET.
7. TPOS TIRE SENSOR L/FRT TIRE PRESSURE SET AT 110 PSI SENSOR BLINDING. REMOVE AND INSTALL NEW SENSOR SET TO 110PSI.
8. RESET COMP COT LIGHT INOP-FOUND LOOSE CONNNECTIONS IN SEATING LINEN-CONNECT FAULT.
9. WRENCH LOOSE-SEURE OR WRENCH SND REHUNG TO BULK END.
10. PREVIOUSLY ACTIVE CODES-CLEANED CODES AS PER. ROAD TEST TO SEE IF CODES REAPPEAR. NO CODE RETURNED.
11. INSTALL 2 STALKS BUMP RAILS IN REAR.
12. Q.A

Parts

Quantity

10005596GRABRAIL	2
1884207C92FUEL FILTER MAXFORCE 7	1
1899332C91OIL FILTER MAXFORCE 7	1
3600330C1RELAY	1
RWTG1234LED PRESSURE CAP	1

Workorder: V52318

In Date: 09/11/2012

Meter Reading:

Close Date: 09/24/2012

Problem?

The key for the MDC is stuck in the lock, dispatch sent us a message and we recieved it. But the "dock" light is not lite, and we can't remove the MDC. r 14

Task performed:

GAVE W/O TO RANDY ALI IN RADIO SHOP.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53230

In Date: 10/21/2012

Meter Reading: 9,997.00

Close Date: 10/24/2012

Problem?

Handle in the back of the rescue is broken. R14

Task performed:

Parts

Quantity

TRAVEL TO ST 14 R&R HANDLE ON BACK DOOR
DRILL AND TAP DOOR TO 1/4 BOLTS.

NO PARTS USED

Workorder: V53283

In Date: 10/24/2012

Meter Reading: 10,330.00

Close Date: 10/29/2012

Problem?

AC plug for shore line sparks and smokes when plugging in AC plug. R14

Task performed:

Parts

Quantity

INSTALLED NEW PLUG ON CORD.

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

2

Workorder: V53964

In Date: 11/24/2012

Meter Reading:

Close Date: 11/28/2012

Problem?

Change oil light is on. R14

Task performed:

Parts

Quantity

TRAVEL TO 14 REPROGRAMMED OIL LIFE SENSOR.

NO PARTS USED

Workorder: V54604

In Date: 12/25/2012

Meter Reading: 13,429.00

Close Date: 12/28/2012

Problem?

rear scene on LT side is out R14

Task performed:

Parts

Quantity

REPAIRED SCENE LIGHT.

H35SN12BULB

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55704

In Date: 02/11/2013

Meter Reading: 15,791.00

Close Date: 02/14/2013

Problem?

B inspection

Task performed:

1. B INSP
2. R&R WIPER BLADES.
3. INSTALLED AND SET CALIBRATED ON 4 TIRE PRESSURE MONITOR BUNKERS.
4. ORDER VALVE STEM ADAPTER FOR L/R OUTER TIRE.
5. AXE BRK HDWR LOOSE AND MISSING- REPAIR AIR PARK BRK HDWR LOOSE AND MISSING AND THREADS STRIPPED. R BRKT DRILL AND INSTALL NUTSET REASSEMBLE ALL WITH LOCTITE.
6. REPAIR COMPT HOLD BRKT. R&R LOOSE DOOR PANEL SCREWS AND REINSTALL WITH LOCTITE.
7. TIGHTEN ALL HDWR ON COMPT R-1 HOLD OPEN R&R ALL DOOR PANEL SCREWS AND INSTALL WITH LOCTITE.
8. TIGHTEN ALL HDWR ON COMPT R-2 HOLD OPEN.
9. R&R INTERIOR TRIM PANEL TO ACCESS HOLD OPEN BALL STUD HDWR TO TIGHTEN.
10. REPAIR L-3 HOLD OPEN BRACKET. R&R BRKT REMOUNT CORRECTLY DIAMOND PLATE REDRILL AND TAP BALLSTUD BRCKET. R&R ALL LOOSE PANE SCREWS AND REINSTALL WITH LOCTITE.
11. FABRICATE 2 NEW RUMBLE SIREN BRACKETS. R&R BRACKETS.
12. CHECK REAR A/C OPERATION. CHECK REAR A/C UNIT UNDER JUMPSEAT INSPECT SYSTEM FOR LEAKS. DISCHARGE EVACUATE AND RECHARGE SYSTEM.
13. CHECK REAR AIR SUSPENSION. MEASURE VEH HEIGHT CHECK LEVELING VALVES OPERATION- NO PROBLEM FOUND.
14. Q.C TRUCK.
15. CHECK ALL MOUNTING AND ALEC CONNECTIONS BOTH CITY HORNS TURN HORNS TO FACE CORRECT POSITION.
16. HOOK UP LAPTOP UPDATE DIAMOND LOGIC SOFTWARE. GO TO SERVICE MAX CHECK ENGINE CODES AND RESET OIL LIFE MONITOR.

Parts

Quantity

- 1884207C92FUEL FILTER MAXFORCE 7
- 1899332C91OIL FILTER MAXFORCE 7
- 91-22WIPER BLADE
- RWTG1234LED PRESSURE CAP

- 1
- 1
- 2
- 4



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56397

In Date: 03/14/2013

Meter Reading: 17,357.00

Close Date: 03/15/2013

Problem?

Pat comp heater core leaking

Task performed:

Parts

Quantity

THE RIGHT REAR INSIDE TIRE WAS REPAIRED YESTERDAY 3/13/13 BY A TIRE COMPANY AND IS SHOWING LOW PRESSURE AGAIN THIS MORNING.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V56592

In Date: 03/23/2013

Meter Reading: 17,928.00

Close Date: 03/27/2013

Problem?

Right front siren bracket broken at bumper attachment point. Recently repaired at point where bracket bolts to siren. Thank you

Task performed:

Parts

Quantity

1. SECURED SIREN UNTIL BRACKETS ARRIVE.
2. ADDED AIR TO TIRES.

NO PARTS USED

Workorder: V56483

In Date: 03/18/2013

Meter Reading: 17,625.00

Close Date: 04/12/2013

Problem?

Right front Siren that is mounted to the front bumper upper alliuminum bracket is broken.

Task performed:

Parts

Quantity

1. TRAVEL TO 14 BENT BRACKET TO HOOK BACK UP TO SIREN TO KEEP IT FROM VIBRATING UNTIL NEW BRACKET COMES IN.
2. TRAVEL TO 14 INSTALLED NEW SPEAKER BRACKETS AND RUMBLER.

NO PARTS USED

Workorder: V57853

In Date: 05/20/2013

Meter Reading:

Close Date: 05/29/2013

Problem?

Front cab AC inop. checked fuses/breakers, wiggled relays, recycled electric, re started engine. Not blowing any air. R14

Task performed:

Parts

Quantity

TRAVEL TO ST 14 CHECK OUT A/C SYSTEM BLOWER INOP PULL COVER TO GET TO BLOWER UNIT FOUND BAD CONNECTION CLEAN UP TEST.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58515

In Date: 06/18/2013
Close Date: 06/27/2013

Meter Reading: 21,826.00

Problem?

AC shore line smokeing. Plug prongs came off vehicle and stuck in shore line. Illumination lights in PT compt. work when they wait to. R14

Task performed:

1. TRAVEL TO 14 REPLACED AUTO EJECT AND PLUG ON CORD BOTH BURNT UP.
2. TRAVEL TO 14 REPLACED PWM MODULE FOR REAR LIGHTS TESTED OK.

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1
ON80-2485-00MODULE PWM CONVERTER	1

Workorder: V59341

In Date: 07/25/2013
Close Date: 07/29/2013

Meter Reading: 23,314.00

Problem?

install rumbler brackets

Task performed:

CHECKED BRACKETS OK FOR NOW WILL MONITOR

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59506

In Date: 08/02/2013

Close Date: 08/13/2013

Meter Reading: 23,518.00

Problem?

C inspection R14

Task performed:

Parts

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

1. C-INSPECTION.
2. SERVICE AIR DRYER.
3. COMPARTMENT DOORS - 4 HOLD OPENS ON COMPT DOORS LOOSE - TIGHTEN ALL DOOR HOLD OPENS AND ALL DOOR PANEL SCREWS.
4. 110V WALL RECEIPT- CHECKOUT PROBLEM WITH NO WALL RECEPTICAL POWER - FOUND CIRCUIT BREAKER ON POWER INVEDTER TRIPPED- RESET AND RETEST CIRCUIT - NOW OK.
5. WASHERS - L/SIDE WINDSHIELD WASHER - INOP - CHECK OUT PROBLEM FOUND HOSE KINKED AND SPRAY NOZZLE IS INSTALL IN WRONG PLACE ON WIPER ARM - INSTALL PROPERLY - NOW OK.
6. A/C INTAKE FILTERS - INSTALL NEW A/C INTAKE FILTERS - NOTE: ALL THE SCREWS UNDER THE FILTER CAGES WERE STRIPPED OUT.
7. REPLACE WIPER BLADES.
8. MED. CABINET - LOWER DRAWER SLIDES BROKEN - REMOVE DRAWER AND REPLACE SLIDES - NEWER STYLE SLIDES DON'T MATCH PREDRILLED HOLES FROM OLD SLIDES - MODIFY NEW SLIDES TO MATCH OLD PREDILLED HOLES IN WALL AND SPACER BLOCKS - ALIGN SLIDES FOR DRAWER TO MOVE FREELY.
9. MED LOCKER - UPPER MEDLOCKER DOOR LOOSE IN HINDGES AND LATCH INOP - FIRST SECURE HINGES - NECESSARY TO USE LONGER SCREWS - NEXT ADJUST LATCH PAD SO TO LATCH PROPERLY.
10. LINEN CABINET - ONE SIDE DOOR OF LINEN CABINET AND BROCKEN LEXAN WINDOW - REMOVE AND TAKE TO PARTS DEPT. - PARTS SENT OUT TO HAVE MADE - REINSTALL NEW LEXAN WINDOW.
11. REAR TIRES - SET UP VEHICLE ON STANDS AND REMOVE REAR WHEEL AND TIRE - IN BUILDING 3, FLETCH 4 NEW TIRES FROM HURRICANE SUPPLY - OUTSIDE VENDOR TOMOUNT TIRES ON WHEELS.
12. INFLATION KITS - TIRES - REMOVE OLD STYLE INFLATION KITS THAT DON'T WORK - INSTALL NEW STYLE.
13. FRONT TIRES - SET UP FRONT END ON STANDS AND ROTATE BOTH FRONT TIRES.
14. L/FRONT CAB STEP - BATTERIES CAN'T BE CHECKED WITHOUT SLIDING OUT BATTERY FROM SLIDE TRY FOR ACCESS TO NEG STUDS - NOTE: SLIDE TRAY HITS STEP AND ONLY COMES OUT HALD WAY - REMOVE STEP AND MODIFY SO IT WILL DROP DOWN FAR ENOUGH SO BATTERY TRAY WILL SLIDE ALL THE WAY OUT.

065624AD-IP DRIER	1
1501450007750USE 0775145	1
1884207C92FUEL FILTER MAXFORCE 7	1
1899332C91OIL FILTER MAXFORCE 7	1
2602212C1PRIMARY AIR FILTER 4300M7	1
29539579 57701 TRANS FILTER	1
3839141C1FILTER CAB AIR	1
5632-1212 IN PAIR DRAWER SLIDES	2
602198LATCH TRIGER W/O LOCK	2
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
DOOR-117 3/4 X 24 3/4 2 DR HORTON	1
K022105PURGE VALVE AD-IP-IS	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59698

In Date: 08/09/2013
Close Date: 08/13/2013

Meter Reading: 23,518.00

Problem?

replace 4 rear tires and install balancing beads in front tires

Task performed:

REPLACE 4 REAR TIRES AND INSTALL BALANCING BEADS IN FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V63535

In Date: 01/20/2014
Close Date: 01/22/2014

Meter Reading: 31,733.00

Problem?

Rescue 14 passenger side door we use to access the pt cab, arm up top broke off the door that keeps it from swinging open.

Task performed:

DRIVER COMPLAINT DOOR HOLD OPEN BROKEN. REPLACED DOOR CYLINDER HOLD OPEN.

Parts

10009821DOOR SHOCK

Quantity

1

Workorder: V63838

In Date: 01/30/2014
Close Date: 01/30/2014

Meter Reading: 32,183.00

Problem?

B inspection by OCS on R14

Task performed:

B inspection by OCS oil and filters

Parts

NO PARTS USED

Quantity

Vendor?: OCS

Workorder: V64681

In Date: 03/04/2014
Close Date: 03/10/2014

Meter Reading:

Problem?

rear AC not blowing cold air R14

Task performed:

PATIENT COMPT A/C INOP LINE OFF AT COMP DISCHARGE, SENT TO SHOP.

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64696

In Date: 03/04/2014

Meter Reading: 33,628.00

Close Date: 03/12/2014

Problem?

a/c line came off of pat compressor

Task performed:

1. FOUND DISCHARGE HOSES OFF AT COMPRESSOR FOR PAT A/C- REPLACED O-RING VAC SYSTEM- ADD OIL AND CHANGED SYSTEM COMPRESSOR BAD.
2. RECOVER FREON- REMOVED BELT, OIL FILTER, HOSES AND COMPRESSOR ADJUSTED ON LEVEL IN NEW COMPRESSOR- R&R COMP AND LINE ADAPTERS- BLEWOUT A/C HOSES AND SYSTEM- R&R DRIER.
3. REASSEMBLED ALL PARTS- VAC AND CHARGE SYSTEM- RAN AND CHK OK.
4. CLEAN WORK AREA.

Parts	Quantity
071601A07-0602A DRIER A/C 7118	1
08-0802SINT FLANGE FITTING	1
08-0803SINT FLANGE FITTING	1
1899332C91OIL FILTER MAXFORCE 7	1
3615169C23615169C3 A/C COMPRESSOR 4382 SANDEN	1

Workorder: V65472

In Date: 04/05/2014

Meter Reading:

Close Date: 04/09/2014

Problem?

one of right side flood/scene lights out R14

Task performed:

DRIVER COMPLAINT SCENE LIGHT OUT. REPLACED BULB AND TESTED OK.

Parts	Quantity
H35SN12BULB	1

Workorder: V68240

In Date: 07/26/2014

Meter Reading: 39,836.00

Close Date: 07/29/2014

Problem?

pat a/c no cool

Task performed:

System test out fine. Set to 50 degree. Check A/C. Compressor and pressure , test for operation its nice and cold now.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68165

In Date: 07/24/2014

Meter Reading:

Close Date: 08/06/2014

Problem?

passenger side seat has a long rip in it. When the family of our patients sit in it it dirty's up their clothing.

Task performed:

Parts

Quantity

1-2. Remove right side seat cushion from seat frame and send out to vendor for repair.

NO PARTS USED

Workorder: V68210

In Date: 07/27/2014

Meter Reading: 39,836.00

Close Date: 08/08/2014

Problem?

C inspection R14

Task performed:

Parts

Quantity

- 1-2.C" Inspection
- 3attery slide drawer binding up. Clean debris from slide tracks. Lube and work drawer in and out until free.
- 4. Removed rear torque rod to be sent out to have new bushings pressed in.
- 5.Assist in torsoin bar removal
- 6.Rotated front. Tires right to left and left to right.
- 7.Began replacing fan belts.
- 8.Completed replacing fan belts.
- 9.Replaced wiper blades, clean debris from squirters, adjusted and topped resevoir.
- 10. Replaced left front fender turn/signals bulb.
- 11.Replaced patient compartment. AC fitlers.
- 12. Installed velco to secure O2 wrench.
- 13.Lubed all cab and body door hinges, latches and hold opens. Straightened body , hold open mounts and adjusted door strikers to tighten doors when closed.
- 14.Serviced air brake dryer.
- 15.Installed newly repair torque rod. Adjsuted leveling valves and road tested.
- 16.Checked truck steering for noise turning right. Found groaning noise. Serviced P/S system and noise went away. Road tested extensively.
- 17. Q and A Inspection.
- 18.

065624AD-IP DRIER	1
0775145PANEL FILTER	3
15W40BSYN OIL BULK QTS	23
1847541C2K060764 BELT A/C M7	1
1889037C1FAN BELT V8 INT DUAL AIR COMPRESSOR	1
3157TAIL LIGHT BULBS	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
2602212C1PRIMARY AIR FILTER 4300M7	1
1884207C92FUEL FILTER MAXFORCE 7	1
1899332C91OIL FILTER MAXFORCE 7	1
3839141C1FILTER CAB AIR	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70423

In Date: 10/24/2014

Meter Reading: 43,587.00

Close Date: 11/03/2014

Problem?

inverted triangle light on dash of truck wont go off. we dont know what it is for?

Task performed:

1. Travel to station 14. Check out engine light on. Found transmission code for filter. R & R transmission filter. Reset code.

Parts

Quantity

10008530KNEEL MODULE HORTON

1

29539579 57701 TRANS FILTER

1

2. Go back to station 14. Truck won't dump rear air bags. Check out truck and found inoperable. Check switches, mod power, etc. Air bag module inoperable while order new switch (on dump in cab).

3. Travel to station 14. Install new Neal module and rewire. Test OK.

Workorder: V70686

In Date: 11/03/2014

Meter Reading:

Close Date: 11/21/2014

Problem?

STAIR CHAIR COMPARTMENT, SAGGING BROKEN BRACKET ATTACHED TO THE TRUCK FRAME, UNDERNEATH THE TR R14

Task performed:

1. Checked rear compartment, found bracket broken strapped up temp to get to shop.

Parts

Quantity

NO PARTS USED

2. Remove broken bracket under truck for rear stair chair, removed bracket and make new bracket also under compt. to have weight.

Workorder: V70379

In Date: 10/23/2014

Meter Reading:

Close Date: 01/02/2015

Problem?

STRETCHER HYDRULIC ARM MALFUCTION

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71900

In Date: 12/29/2014
Close Date: 01/05/2015

Meter Reading: 46,919.00

Problem?

passengers side headlight out R14

Task performed:

Travel to station 14-R/R headlight, R/R bulb and holder

Parts

Quantity

2586872C1LOCK RING HEADLITE

1

2587313C1SPRING WASHER HEADLITE

1

9007H9007 BULB ASSY

1

Workorder: V71914

In Date: 12/29/2014
Close Date: 01/07/2015

Meter Reading: 46,919.00

Problem?

air conditioning in cab not working. electric window not working.

Task performed:

1. Repaired loose connection to electric window
2. AC ok

Parts

Quantity

NO PARTS USED

Workorder: V71935

In Date: 12/30/2014
Close Date: 01/07/2015

Meter Reading: 46,919.00

Problem?

CAB A/C FAN IS NOT BLOWING. CAB A/C COMPRESSOR IS OFF FOR 1 MIN AND RUN FOR 5 SEC. no cold air. tension pulle rattles. drivers window does not go down.

Task performed:

1. Travel to 14-replaced blower motor
2. Found no problem with belt tensioner
3. Found no problem with window

Parts

Quantity

2602570C91BLOWER MOTOR 2012 OLD 3839363C91

1

Workorder: V71949

In Date: 12/31/2014
Close Date: 01/07/2015

Meter Reading: 46,919.00

Problem?

DRIVER SIDE WINDOW NO POWER DOOR LOCK NO POWER FRONT AC NOT WORKING R14

Task performed:

1. Repaired loose connection to power door lock
2. AC ok windoe ok

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73251

In Date: 02/04/2015

Meter Reading: 48,830.00

Close Date: 02/18/2015

Problem?

headlight out

Task performed:

1. Went to ST 14. R & R left headlight. Check OK.
Return home.

Parts

NO PARTS USED

Quantity

Workorder: V72888

In Date: 02/04/2015

Meter Reading:

Close Date: 02/23/2015

Problem?

LEFT DRIVER HEADLIGHT OUT

Task performed:

1. Travel to ST 14. Found no problem with headlights.
Left station a spare bulb.
2. Replaced 2 leaking fittings on governor.

Parts

9007H9007 BULB ASSY

Quantity

2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73036

In Date: 02/10/2015

Meter Reading: 48,830.00

Close Date: 03/19/2015

Problem?

B inspection R14

Task performed:

1. "B" Service.
2. PErformed "B" Service.
3. Replaced batteries.
4. Continued/completed "B" Service.
5. Remove all six wheels and tires to be replaced by tire service.
6. Performed rear axle brake job.
7. Replaced marker light on top right rear.
8. Ordered new air brake compressor and began removing old compressor.
9. Continued changing out air brake compressor with reman unit.
10. Began replacing belts. Had to order tensroner and idelers for compressor belt. Will continue belt replace when parts come in.
11. Reinstalled all wheels after tire guy replaced tires.
12. Rebuilt air brake dryer. Had to R&R entire unit to clean out due to compressor failure.
13. Continued/ completed air dryer rebuild and clean out.
14. Replaced rear step/ground light. (smashed) also replaced mounting bracket and gromet. Drilled new mounting hides and rewired.
15. Received tensioner and idler pulleic previously ordered from parts. Installed parts. Attempted to install belt. Found belt was incorrect. Ordered new belt.
16. Continued idlers and tensioner install.
17. Received correct belt from parts and installed. Tested operation.

Parts

Quantity

065624AD-IP DRIER	1
103385NDRAIN COCK	1
1654-8FERRULE .718	1
1677731C1COMPRESSOR MTG GASKET	1
1832712C1PULLEY M7 V8 INT.	2
1847541C2K060764 BELT A/C M7	2
1884207C92FUEL FILTER MAXFORCE 7	1
1889037C1FAN BELT V8 INT DUAL AIR COMPRESSOR	1
1899179C1TENSIONER M7 ENGINE	1
1899332C91OIL FILTER MAXFORCE 7	1
236577GASKET D-2 GOV	1
284358GOVERNOR D-2	1
3757REAR DRUMS 3757X 3647X	2
3945688C1FILTER MINDER V8 INT.	1
601601 MALE HOSE END	1
61H01LED GROUND LITE CLEAR	1
BX802925COMPRESSOR TF550 BX5019445 MAXFORCE 7	1
FRT 66425FREIGHT CHARGE	1
FRT27777FREIGHT	1
K022105PURGE VALVE AD-IP-IS	1
MFG01876GROUND LT BRACKET	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

Workorder: V74617

In Date: 04/13/2015

Meter Reading: 50,505.00

Close Date: 04/22/2015

Problem?

a/c not working

Task performed:

1. Low freon in cab A/C. Filled system and checked for leaks, no leaks found at this time.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74595

In Date: 04/11/2015

Meter Reading:

Close Date: 04/23/2015

Problem?

A/C in cab of truck blows only HOT air. R14

Task performed:

Parts

Quantity

1. Check out A/C. Add freon to check for leaks. Didn't find leak in system. Will need to go to shop.

NO PARTS USED

Workorder: V73956

In Date: 03/17/2015

Meter Reading:

Close Date: 04/24/2015

Problem?

a/c in cab is blowing warm - pt. compt. is fine

Task performed:

Parts

Quantity

1. Charged A/C in cab.

NO PARTS USED

Workorder: V74082

In Date: 03/21/2015

Meter Reading:

Close Date: 04/24/2015

Problem?

A/C in the front cabin only blows HOT AIR! It is cooler to open the window when is 90 degrees outside, at 2:00pm Thanks, Javier R14

Task performed:

Parts

Quantity

1. Charged A/C.

NO PARTS USED

Workorder: V74457

In Date: 04/06/2015

Meter Reading:

Close Date: 05/14/2015

Problem?

roof ac leaking water into pt comp. area

Task performed:

Parts

Quantity

1. Travel to 14 dropped A/C cover and secured all mounting screws.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10187788

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72738

In Date: 01/30/2015

Meter Reading:

Close Date: 06/30/2015

Problem?

air leak near compressor fittings

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74156

In Date: 03/25/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

FRONT AC BLOWING HOT

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74603

In Date: 04/11/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

front AC not blowing cold AIR R14

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10187788) 2012 - INTERNATIONAL HORTON Advanced Life Support Vehicle

10187788

CSHOP-2015-1241

Comments: R14 ACTION AREA SEAT BELT NO EXTENDING FROM HOLDER ROOF A/C LEAKING A LOT OF WATER INTO PAT COMP

Date Opened: 6-18-2015 Date Finished: 6-29-2015 Meter 1 Reading: 51,500

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SEAT BELTS
AIR CONDITIONING

1 SEAT BELT JUMP SEAT HORTON
1 NONSTOCK; FREIGHT CHARGE

CSHOP-2015-1690

Comments: PATIENT AC NOT COOLING R14 / TRAVEL TO STATION 14 CHECK UNIT AC FOUND NEED COMPRESSOR AND DRYER UNIT NEEDS TO COME TO SHOP FOR REPAIR .

Date Opened: 7-10-2015 Date Finished: 7-10-2015 Meter 1 Reading: 51,500

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

1 9IP; 3615169C3 A/C COMPRESSOR 4382 SANDEN
1 DRYER; 07-0602A DRIER A/C 7118
1 A/C; 17-3428 ESTER OIL E7

CSHOP-2015-1832

Comments: A/C NOT WORKING R14

Date Opened: 7-20-2015 Date Finished: 7-20-2015 Meter 1 Reading: 51,500

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2015-1838

Comments: ON-CALL R14 PAT A/C WARM

Date Opened: 7-20-2015 Date Finished: 7-20-2015 Meter 1 Reading: 51,500

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2015-2013

Comments: R14 REAR AC NOT FUNCTIONING

Date Opened: 7-29-2015 Date Finished: 8-4-2015 Meter 1 Reading: 51,507

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Asset Work Order History 10187788

CSHOP-2015-202

Comments: **R-14 CAB AIR CONDITIONING NOT WORKING.**

Date Opened: 4-22-2015 Date Finished 4-22-2015 Meter 1 Reading: 51,114

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2015-2106

Comments: **R14 REAR AC NOT FUNCTIONING**

Date Opened: 8-4-2015 Date Finished 8-4-2015 Meter 1 Reading: 57,507

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
A/C BELT REAR A/C
HOSES-LINES & FITTINGS

CSHOP-2015-2267

Comments: **PATIENT AC INOP R14**

Date Opened: 8-11-2015 Date Finished 8-11-2015 Meter 1 Reading: 57,507

TASKS PERFORMED

NO PARTS USED

A/C LEAK TEST
EVACUATE AND RECHARGE
HOSES-LINES & FITTINGS

CSHOP-2015-2640

Comments: **REAR AC FILTER UNDER SEAT TOP ACTION DRAWER NOT CLOSING ROOF AC LEAKS WATER R14**

Date Opened: 9-1-2015 Date Finished 9-9-2015 Meter 1 Reading: 57,731

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BODY - WORK COMPARTMENT EMER
AIR CONDITIONING

1 SLIDE; 12 IN PAIR DRAWER SLIDES
2 FILTER; PANEL FILTER

CSHOP-2015-3031

Comments: **PT. COMPT. A/C HAS A CONDENSATE LEAK R14**

Date Opened: 9-22-2015 Date Finished 9-30-2015 Meter 1 Reading: 59,324

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2015-314

Comments: **R14 NO CAB A/C**

Date Opened: 4-27-2015 Date Finished 4-29-2015 Meter 1 Reading: 51,456

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

1 BRACKET; KIT AC COMPRESOR BRACKET V8 UPGRADE

Asset Work Order History 10187788

CSHOP-2015-420

Comments: **R14 FRONT AIR CONDITIONING NOT WORKING.**

Date Opened: 5-4-2015 Date Finished 5-5-2015 Meter 1 Reading: 51,456

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2015-4347

Date Opened: 12-7-2015 Date Finished 12-7-2015 Meter 1 Reading: 62,424

TASKS PERFORMED

Q PARTS

AUTO-EJECT

1 9IP; COVER, SQUARE, YELLOW

CSHOP-2015-454

Comments: **R14 FRONT AIR CONDITIONING NOT WORKING.**

Date Opened: 5-13-2015 Date Finished 5-14-2015 Meter 1 Reading: 51,500

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

1 FILTER; FILTER DRYER A/C V8 CAB
1 9IP; AIR COMPRESSOR CAB V8

CSHOP-2015-4646

Comments: **R14 WRENCH LIGHT**

Date Opened: 12-28-2015 Date Finished 12-29-2015 Meter 1 Reading: 63,914

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

Service Requests:

12/27/2015 SERVICE REQUEST / 20: LUBE/OIL SOAKED / RESET OIL CHANGE LIGHT
WRENCH INDICATOR LIGHT ON DASHBOARD IS ON. NO PROBLEMS NOTED WHEN OPERATING VEHICLE.

CSHOP-2016-1591

Comments: **R14**

Date Opened: 4-4-2016 Date Finished 4-5-2016 Meter 1 Reading: 69,317

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HANDLES INSIDE-OUTSIDE

1 HANDLE; TM22676-02 HANDLE DOOR ENTRY

Service Requests:

04/03/2016 DOOR / 12: BROKEN / EXCHANGE - NEW
THE DOOR HANDLE FOR THE SIDE PT COMPARTMENT DOOR HAS BROKEN IN HALF, AND IS NOT OPERATIONAL.

Asset Work Order History 10187788

CSHOP-2016-1794

Comments: **ON-CALL R14 LOW POWER**

Date Opened: 4-15-2016 Date Finished 4-19-2016 Meter 1 Reading: 69,952

TASKS PERFORMED

Q PARTS

FUEL SYSTEM

1 FILTER; FUEL FILTER MAXFORCE 7

Service Requests:

04/14/2016 ENGINE / 12: BROKEN / ADJUST
R14 TRUCK WILL NOT GO ABOVE 69MPH, AT 65 MPH ENGINE WARNING LIGHT COMES ON AND STAYS ON.

CSHOP-2016-1801

Comments: **CHECK ENGINE LIGHT, LOW POWER**

Date Opened: 4-18-2016 Date Finished 4-25-2016 Meter 1 Reading: 69,952

TASKS PERFORMED

Q PARTS

FAULT CODE

1 FILTER; PRIMARY AIR FILTER 4300M7
1 SOLENOID; TUBE ASSY BOOST TO SOLENOID
1 NEWPART; VALVE BOOSTER CONTROL SOLENOID V8
1 SENSOR; SENSOR MAP

Service Requests:

04/15/2016 DECALS / 18: LEAKING / REPAIR
14 PLACARD MISSING OFF LEFT SIDE OF VEHICLE

CSHOP-2016-1979

Comments: **R14 C INSPECTION CK, OVER TRUCK AND FOUND LAST C SERVICE MARK WAS 7/14 LAST MARK OIL FILTER WAS 2/15 JUST TO LET YOU KNOW.**

Date Opened: 4-26-2016 Date Finished 5-2-2016 Meter 1 Reading: 70,015

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; AF27958 FILTER CAB AIR
1 FILTER; OIL FILTER MAXFORCE 7

Asset Work Order History 10187788

CSHOP-2016-2006

Comments: **PM FOLLOW UPS**

Date Opened: 4-27-2016

Date Finished

6-2-2016

Meter 1 Reading:

70,015

TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH	1	OXYGEN; OXM1757-01 OXYGEN WRENCH
WIPER BLADES	2	WIPER; WIPER BLADE
WIPERS-WASHER	-1	FILTER; PRIMARY AIR FILTER 4300M7
AIR FILTER	1	FILTER; PRIMARY AIR FILTER 4300M7
CATALYTIC CONVERTER	1	NONSTOCK; CORE CHARGE
FAN CLUTCH	1	FILTER; FILTER DIESEL PARTICULATE M7
ELECTRIC FAN	2	GASKET; GASKET DPF 2 DOOR
SERPENTINE BELT	1	NEWPART; FAN CLUTCH V8
FRONT SEAL	1	BELT; K060764 BELT A/C M7
OIL PAN-GASKET	1	LIGHT; LIGHT LED RED TIR 6
FAULT CODE	1	9IP; UV LAMP HORTONS
ENGINE AND ACCESSORIES	1	FILTER; 57701 TRANS FILTER
DOMELIGHTS	1	DRYER; AD-IP DRIER
LIGHTING SYSTEM	1	DRYER; AD-IP DRIER
DIAGNOSE ELECTRICAL	2	BRAKE; GY1R11216 AIR BAG INT.
ELECTRICAL	1	VALVE; PURGE VALVE AD-IP-IS
FILTER	1	LIGHT; LOUVER AC HORTON UV LIGHT
AIR DRIER	1	9IP; UV LAMP HORTONS
AIR BAG SYSTEM	2	FILTER; PANEL FILTER
LIGHT BAR	1	BELT; FAN BELT V8 INT DUAL AIR COMPRESSOR
CAB VENT		
CABIN AIR FILTER		
A/C BELT REAR A/C		

CSHOP-2016-262

Comments: **R14**

Date Opened: 1-20-2016

Date Finished

2-2-2016

Meter 1 Reading:

65,782

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	2	BULB; BULB
LIGHTING SYSTEM		

Service Requests:

01/20/2016	LIGHTS / 12: BROKEN / REPLACED SCENE LIGHT BULB REAR RIGHT SIDE FLOOD LIGHT NOT WORKING
------------	--

Asset Work Order History 10187788

CSHOP-2016-3008

Comments: **R14**

Date Opened: 6-22-2016 Date Finished 6-24-2016 Meter 1 Reading: 71,560

COMPARTMENT AC INOP.

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

2 9IP; VALVE CORE A/C 8926
1 VALVE; 1608 2 1/2 TON VALVE EXPANSION
1 BELT; K060764 BELT A/C M7
30 A/C; FREON LB
1 9IP; 3615169C3 A/C COMPRESSOR 4382 SANDEN
1 VALVE; SCHRADER VALVE INT.
1 DRYER; 07-0602A DRIER A/C 7118

Service Requests:

06/21/2016 A/C / 12: BROKEN / REPAIR
REAR A/C NOT WORKING...

CSHOP-2016-3041

Comments: **R14 PAT A/C INOP**

Date Opened: 6-24-2016 Date Finished 6-30-2016 Meter 1 Reading: 71,778

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2016-3388

Comments: **COOLANT LEAK R14**

Date Opened: 7-13-2016 Date Finished 7-20-2016 Meter 1 Reading: 72,804

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
AIR CONDITIONING

1 HOSE; HOSE RADIATOR
6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL
3 A/C; FREON LB

CSHOP-2016-4147

Comments: **R14 TRANS ISSUE**

Date Opened: 8-22-2016 Date Finished 8-22-2016 Meter 1 Reading: 74,113

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

Asset Work Order History 10187788

CSHOP-2016-4212

Date Opened: 8-26-2016 Date Finished 9-27-2016 Meter 1 Reading: 75,861

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TRANSMISSION

Service Requests:

08/26/2016 SERVICE REQUEST / 33: REGISTERS WRONG / REPROGRAMMED ECM FILTER MONITOR
CHECK TRANSMISSION ICON ON DASH ON

CSHOP-2016-4688

Comments: **WILL CALL CALLAGHAN IN THE A.M. 9-28-16 CALLED**

Date Opened: 9-28-2016 Date Finished 10-12-2016 Meter 1 Reading: 76,449

TASKS PERFORMED

NO PARTS USED

REAR DOOR LATCH ASSEMBLY

Service Requests:

09/28/2016 TIRES / 44: WORN / EXCHANGE - NEW
BAD TIRES ON LEFT AND RIGHT REAR

CSHOP-2016-4944

Date Opened: 10-17-2016 Date Finished 10-25-2016 Meter 1 Reading: 77,408

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SPOT LIGHTS
AIR HORN
AIR CONDITIONING

1 HORN; KIT-AIR HORN-GROVER

Service Requests:

10/14/2016 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS: AIR HORN TO RIGHT AND LEFT SIDE NON OPERABLE SOUNDS MUFFLED AND DYING
10/18/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
TWO OF THE HAND HELD LIGHT WILL NOT TURN ON WHEN TAKEN OUT OF CHARGING CRADLE.
10/19/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
ROOF AC LEAKS WATER INTO PT COMPARTMENT

Asset Work Order History 10187788

CSHOP-2016-5196

Date Opened: 11-1-2016 Date Finished 11-7-2016 Meter 1 Reading: 77,743

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR BAG CONTROL MODULE

2 VALVE; VALVE AIR LEVELING 2DOOR M7

Service Requests:

11/01/2016 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE

CSHOP-2016-5516

Date Opened: 11-28-2016 Date Finished 11-29-2016 Meter 1 Reading: 79,257

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HANDLES INSIDE-OUTSIDE

Service Requests:

11/20/2016 DOOR / 19: LOOSE / REPAIR
VEHICLE DOORS, REAR DOOR WILL NOT OPEN FROM THE INSIDE.

CSHOP-2016-589

Comments: **R14**

Date Opened: 2-5-2016 Date Finished 2-16-2016 Meter 1 Reading: 66,457

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM

3 CLAMP; CLAMP EXH SHIELD

Service Requests:

02/05/2016 MUFFLER / 12: BROKEN / REPLACED BROKEN CLAMP ON HEAT SHIELD
THE BOTTOM BRACKET THAT HOLDS THE HEAT SHIELD FOR THE VERTICAL MUFFLER ON THE PASSENGER SIDE IS
BROKEN AND IS ONLY BEING HELD BY THE UPPER BRACKET.

CSHOP-2016-6093

Date Opened: 12-29-2016 Date Finished 12-29-2016 Meter 1 Reading: 80,705

TASKS PERFORMED

NO PARTS USED

SUSPENSION

CSHOP-2016-67

Comments: **COOLANT LEAK R 14**

Date Opened: 1-6-2016 Date Finished 1-6-2016 Meter 1 Reading: 64,432

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Asset Work Order History 10187788

CSHOP-2016-722

Comments: R14

Date Opened: 2-16-2016 Date Finished 2-17-2016 Meter 1 Reading: 66,457

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Service Requests:

02/13/2016 A/C / 15: FOREIGN MATERIAL / CLEANED OUT A/C DRAINS
LEAKING WATER ON FLOOR OR RESCUE.

CSHOP-2016-897

Comments: R14

Date Opened: 2-25-2016 Date Finished 3-8-2016 Meter 1 Reading: 67,512

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB

Service Requests:

02/25/2016 BODY / 18: LEAKING / REPAIRED CAB TO BODY SEAL
RUBBER SEAL BETWEEN CAB AND PT COMP LEAKING WATER WHEN RAINS AND DIESEL EXHAUST WHEN DRIVING

CSHOP-2017-1013

Date Opened: 2-17-2017 Date Finished 3-3-2017 Meter 1 Reading: 83,875

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
FRONT TIRES

2 BK; HEATER VALVE
4 PAF; ANTIFRZ

Service Requests:

02/17/2017 RADIATOR / 18: LEAKING / EXCHANGE - NEW
RADIATOR LEAKING, PUDDLE UNDER TRUCK THIS MORNING. STEADY DRIP POSSIBLY COMING FROM HOSE NEAR
PASSENGERS SIDE WHEEL WELL.

02/19/2017 TIRES / 49: CAN NOT DUPLICATE CONCERN / INSPECT
2 FRONT TIRE WITH SEVER WEAR.

CSHOP-2017-1386

Date Opened: 3-6-2017 Date Finished 3-6-2017 Meter 1 Reading: 84,096

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10187788

CSHOP-2017-1436

Comments: **R14**

Date Opened: 3-8-2017

Date Finished

3-8-2017

Meter 1 Reading:

84,165

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

03/08/2017

ENGINE / 18: LEAKING / INSPECT

SUBSTANTIAL AMOUNT OF OIL SPRAY UNDER COMPRESSOR IN LEFT FRONT WHEEL WELL AREA

CSHOP-2017-1489

Date Opened: 3-10-2017

Date Finished

3-17-2017

Meter 1 Reading:

84,307

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
ENGINE AND ACCESSORIES
AIR SYSTEM

3	MAC; NON-CHLOR BRAKE CLNR
1	MODULE; GENERIC CANBUS VIB
1	9IP; PRIMARY AIR FILTER 4300M7
1	BREATHER; 7085773C92 BREATHER M7
1	2IH; COMPRESSOR

CSHOP-2017-1660

Date Opened: 3-17-2017

Date Finished

4-6-2017

Meter 1 Reading:

85,243

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STEERING

Service Requests:

03/17/2017

STEERING / 22: MISALIGNED / INSPECT

STEERING/ALIGNMENT TRUCK PULLS VERY HARD TO THE RIGHT SPEED SHAKE STARTS AT ABOUT 40 NEW
FIRESTONE TIRES ON REAR, GOODYEAR ON FRONT

CSHOP-2017-1829

Date Opened: 3-27-2017

Date Finished

4-6-2017

Meter 1 Reading:

85,243

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN

Service Requests:

03/25/2017

AIR RIDE / 21: MISADJUSTED / ADJUST

AIR HORN NOT WORKING PROPERLY. AIR HORN MAKES AUDIBLE NOISE BUT IS NOT AS LOUD AS IT SHOULD AND
DIFFERENT TONE.

Asset Work Order History 10187788

CSHOP-2017-2359

Date Opened: 4-21-2017 Date Finished 4-21-2017 Meter 1 Reading: 86,061

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

04/21/2017 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE LIGHTS NOT WORKING FRONT LIGHT BAR NOT WORKING

CSHOP-2017-2600

Date Opened: 5-3-2017 Date Finished 5-8-2017 Meter 1 Reading: 86,826

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS

Service Requests:

05/03/2017 LIGHTS / 19: LOOSE / REPAIR
OFFICER SIDE RIGHT BLINKER DIRECTLY IN FRONT OF OFFICER DOOR NOT WORKING

CSHOP-2017-3191

Date Opened: 5-31-2017 Date Finished 6-9-2017 Meter 1 Reading: 88,555

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

1 9IP; HVAC UNIT ROOF MOUNTED
1 9IP; SEAL KIT DOMETIC A/C UNITS

Service Requests:

05/31/2017 A/C / 18: LEAKING / INSPECT
A/C ISSUE. ROOF AC LEAKING WATER INTO PT COMPARTMENT

CSHOP-2017-3666

Date Opened: 6-21-2017 Date Finished 6-22-2017 Meter 1 Reading: 89,269

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPAGOLD OIL FILTER
21 FLUID; SYN OIL BULK QTS
21 9OC; SYN 15W40
1 2IH; AIR FILTER
1 FIL; NAPA CABIN AIR FILTER
1 FIL; NAPA GOLD FUEL FILTER

Asset Work Order History 10187788

CSHOP-2017-3695

Comments: **REPAIRS FROM PM**

Date Opened: 6-22-2017 Date Finished 6-22-2017 Meter 1 Reading: 89,269

TASKS PERFORMED

Q PARTS

HOLD DOWN CLAMPS	1	2IH; CLAMP EXHUAUST
LIGHTING SYSTEM	1	2IH; LIGHT, DOOR
BATTERY	3	1AD; BATTERY 31 SERIES
REPAIR FROM PM - ENGINE	12	MAC; NON-CHLOR BRAKE CLNR
DOOR PANEL	2	8GR; FILTER
A/C FILTER SCREENS		

CSHOP-2017-4549

Comments: **Q.C. FOR RETURNING TO SERVICE**

Date Opened: 8-7-2017 Date Finished 8-8-2017 Meter 1 Reading: 89,269

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	12	MAC; NON-CHLOR BRAKE CLNR
ENGINE AND ACCESSORIES		

CSHOP-2017-4652

Date Opened: 8-10-2017 Date Finished 8-10-2017 Meter 1 Reading: 89,269

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2017-4776

Comments: **QC BACK FROM RECHTIEN, OIL LEAK REPAIRS 2 MEDS DRAWERS HAVE BROKEN SLIDES CAB, LEFT SIDE, INTELLEPLEX DISPLAY INOP AIR HORNS VERY WEAK**

Date Opened: 8-15-2017 Date Finished 9-25-2017 Meter 1 Reading: 89,399

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	4	SLIDE; 12 IN PAIR DRAWER SLIDES
QUALITY CHECK-REPAIRS	-4	9LO; 12" PAIR DRAWE SLIDES
STORAGE CABINET EMERGENCY VEH	4	9LO; 12" PAIR DRAWE SLIDES
AIR HORN	4	9LO; 12" PAIR DRAWE SLIDES
INSTRUMENTS-GAUGES-WARNING &	1	9HD; KIT
	-1	9HD; KIT
	1	9HD; KIT
	1	9IP; HORN AIR 24"" GROVER P/N-1510
	-1	9IP; HORN AIR 24"" GROVER P/N-1510
	1	9IP; HORN AIR 24"" GROVER P/N-1510
	1	9IP; CIRCUIT BOARD FRONT ASSY

Asset Work Order History 10187788

CSHOP-2017-5318

Date Opened: 9-14-2017 Date Finished 10-30-2017 Meter 1 Reading: 92,602

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM
AIR CONDITIONING

2 2IH; DPF CLAMP
1 2IH; TUBRO KIT MOUNT
2 2IH; DPF GASKET 2 DOOR
1 2IH; DPF 2 DOOR
2 2IH; FILTER, CAB A/C INT BX, BLUE

Service Requests:

09/14/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
ENGINE EXHAUST COMING INTO FRONT CAB AND PT COMPT THRU AC VENTS AFTER VEHICLE SIT IDLE ON A CALL.

CSHOP-2017-5524

Comments: **BEEPING WARNING STAYS ON WONT RE-SET**

Date Opened: 9-22-2017 Date Finished 9-27-2017 Meter 1 Reading: 91,844

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
MODULE

CSHOP-2017-5641

Date Opened: 9-28-2017 Date Finished 9-29-2017 Meter 1 Reading: 92,077

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM

Service Requests:

09/28/2017 ENGINE / 12: BROKEN / REPAIR
ENGINE EXHAUST COMING IN TO CAB AND PT COMPARTMENT AREA.

CSHOP-2017-5741

Date Opened: 10-3-2017 Date Finished 10-30-2017 Meter 1 Reading: 92,602

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
PRE TRIP INSPECTION
EXHAUST SYSTEM
TRANSMISSION

1 2DD; TCM

Service Requests:

10/03/2017 HAZARD / 18: LEAKING / PREFORMED A SHORT TEST DRIVE AND CHECKED WHILE IDLING. INITI.
STRONG EXHAUST ODOR IN THE CAB AS WELL AS THE PATIENT COMPARTMENT. THE SHOP HAS BEEN NOTIFIED AND
A SPARE UNIT HAS ALREADY BEEN BROUGHT TO STATION 14. THE UNIT HAS BEEN SWAPPED OUT AND IS READY TO
BE PICKED UP FOR REPAIR.

Asset Work Order History 10187788

CSHOP-2017-608

Date Opened: 1-27-2017

Date Finished

2-24-2017

Meter 1 Reading:

81,961

TASKS PERFORMED

EXHAUST SYSTEM
PARK BRAKE
REAR BRAKE PADS-SHOES
AIR SYSTEM

Q	PARTS
-1	2IH; DPF FILTER
1	2IH; DPF FILTER
1	2IH; DPF FILTER
-1	2IH; DPF FILTER CORE
1	2IH; DPF FILTER CORE
1	9IP; CLEANED UNIT
-1	2IH; DPF GASKET
1	2IH; DPF GASKET
-1	2IH; DPF GASKET
1	2IH; DPF GASKET
1	2IH; DPF FILTER CORE
1	VALVE; VALVE PARKING BRK.
2	MBI; GRIP/KIT
2	2IH; BRAKE DRUM
1	2TP; AIR DRIER

Service Requests:

01/27/2017 HAZARD / 12: BROKEN / REPAIR
HAZARDOUS ISSUE

01/27/2017 AIR RIDE / 22: MISALIGNED / ADJUST
AIR RIDE ISSUE VERY BOUNCY.

CSHOP-2017-611

Date Opened: 1-27-2017

Date Finished

2-6-2017

Meter 1 Reading:

81,961

TASKS PERFORMED

PM SERVICE B

Q	PARTS
1	2IH; FILTER KIT
1	9IP; FUEL FILTER MAXFORCE 7

CSHOP-2017-6249

Date Opened: 10-30-2017

Date Finished

12-14-2017

Meter 1 Reading:

95,106

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM
DOOR GLASS

Q	PARTS
1	9AP; BRONZE ACRYLIC 7-1/2X24-7/8

Service Requests:

10/28/2017 WINDOW / 12: BROKEN / EXCHANGE - NEW
WINDOW/GLASS, PLASTIC WINDOW LOCATED ON THE LEFT LOWER INTERNAL CABINET DOOR IS CRACKED

Asset Work Order History 10187788

CSHOP-2017-6396

Comments: **CARL PLEASE CHECK THE FRONT TIRES CREW CLAIMS NEW ONES ARE NEEDED BUT TRUCK WAS JUST SERVICED.**

Date Opened: 11-6-2017 Date Finished 11-15-2017 Meter 1 Reading: 93,452

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FRONT TIRES

Service Requests:

11/04/2017 STEERING / 26: OUT OF ROUND / EXCHANGE - NEW
STEERING/ALIGNMENT, FRONT TIRES ARE BOTH BAD

CSHOP-2017-6559

Date Opened: 11-13-2017 Date Finished 11-13-2017 Meter 1 Reading: 93,354

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-746

Comments: **R14**

Date Opened: 2-6-2017 Date Finished 3-3-2017 Meter 1 Reading: 83,875

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

4 1WL; LED FLOOD/SCENE LIGHT

Service Requests:

02/04/2017 LIGHTS / 38: SHORTED / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING ONE OF THE SCENE LIGHTS ON THE RIGHT SIDE IS OUT.

CSHOP-2017-814

Comments: **R14**

Date Opened: 2-8-2017 Date Finished 2-21-2017 Meter 1 Reading: 83,343

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

Service Requests:

02/08/2017 DOOR / 19: LOOSE / REPAIR
VEHICLE DOORS, REAR PT COMPARTMENT DOORS NEED ADJUSTMENT. LEFT SIDE IS DIFFICULT TO OPEN. RIGHT SIDE IS MISSING SCREWS TO SECURE THE INSIDE HANDLE MECHANISM.

Asset Work Order History 10187788

CSHOP-2018-102

Date Opened: 1-5-2018 Date Finished 2-6-2018 Meter 1 Reading: 97,446

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OXYGEN SENSOR
AIR SYSTEM

Service Requests:

01/05/2018 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE LEAK IN REAR AIR BAG

01/05/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST O2 LINE LEAKING

CSHOP-2018-1097

Date Opened: 2-22-2018 Date Finished 2-22-2018 Meter 1 Reading: 97,474

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2018-1284

Date Opened: 3-2-2018 Date Finished 3-20-2018 Meter 1 Reading: 98,241

TASKS PERFORMED

Q PARTS

EMISSIONS SYSTEM

1 MAC; SILICONE SPRAY 10OZ
1 2IH; BREATHER
1 8HD; NOZZLE
1 NCB; BLASTER PENETRANT
2 8GR; FILTER
1 BK; SPRAYER

CSHOP-2018-1457

Date Opened: 3-12-2018 Date Finished 3-12-2018 Meter 1 Reading: 97,873

TASKS PERFORMED

NO PARTS USED

EMISSIONS SYSTEM

CSHOP-2018-1646

Date Opened: 3-22-2018 Date Finished 3-26-2018 Meter 1 Reading: 98,697

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STRETCHER

1 5SP; STRYKER RAIL ASSY

Asset Work Order History 10187788

CSHOP-2018-1754

Date Opened: 3-28-2018 Date Finished 4-2-2018 Meter 1 Reading: 99,092

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

03/28/2018 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE, SIGNIFICANT AIR LEAK

CSHOP-2018-2139

Date Opened: 4-17-2018 Date Finished 4-23-2018 Meter 1 Reading: 100,167

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 2IH; KT SOLND
1 2IH; KT SOLND
1 2IH; ELBOW
1 2IH; ELBOW
1 2IH; BRACKET
1 2IH; BRACKET
2 2IH; KIT
2 2IH; KIT
1 2IH; VALVE CHECK
1 2IH; VALVE CHECK
1 2IH; KIT HORN
1 2IH; KIT HORN

CSHOP-2018-2308

Date Opened: 4-26-2018 Date Finished 5-15-2018 Meter 1 Reading: 100,394

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
EXHAUST SYSTEM
COOLING SYSTEM

1 2IH; THERMOSTAT KIT

Service Requests:

04/26/2018 MUFLER / 18: LEAKING / REPAIR

CSHOP-2018-243

Date Opened: 1-11-2018 Date Finished 2-26-2018 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

STRETCHER

2 5SP; BELT

Service Requests:

01/10/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION THE TRACK ON R14 STAIR CHAIR NEEDS TO BE REPLACED.

Asset Work Order History 10187788

CSHOP-2018-2638

Comments:

Date Opened: 5-14-2018 Date Finished 5-14-2018 Meter 1 Reading: 100,394

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SEAT BELTS

CSHOP-2018-271

Comments: **REPAIRS FROM PM**

Date Opened: 2-27-2018 Date Finished 3-2-2018 Meter 1 Reading: 97,474

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	2	1AN; WIPERS
WIPERS-WASHER	2	NBH; HD HEATER HOSE
FUEL SYSTEM	1	9IP; GROUND LT BRACKET
EXHAUST SYSTEM	1	LIT; GROMMET
COOLING SYSTEM	1	9AP; LIGHT
LIGHTING SYSTEM	1	FIL; POWER STEERING FILTER
STEERING	1	TWD; PURGE VALVE ASSY KIT
AIR SYSTEM	1	TWD; REP/CART
AIR CONDITIONING	2	8GR; FILTER

Service Requests:

01/11/2018 SERVICE REQUEST / 12: BROKEN / INSPECT
ENGINE EXHAUST SMELL IN CAB AND PT COMPARTMENT

CSHOP-2018-2719

Comments: **R-14 A/C INOP.**

Date Opened: 5-16-2018 Date Finished 5-17-2018 Meter 1 Reading: 100,504

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	TWD; CIRCUIT BREAKER
AIR CONDITIONING		

CSHOP-2018-2943

Date Opened: 5-29-2018 Date Finished 5-31-2018 Meter 1 Reading: 101,054

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HANDLES INSIDE-OUTSIDE

Service Requests:

05/26/2018 SERVICE REQUEST / 11: BINDS/STICKS / LUBRICATE
THE REAR PATIENT COMPARTMENT DOOR WILL NOT CLOSE ON ITS OWN. THE LEFT SIDE HANDLE STICKS AND DOES NOT AUTOMATICALLY LATCH.

Asset Work Order History 10187788

CSHOP-2018-3893

Comments: **SMALL PUDDLE OF OIL UNDER TRUCK DURING MORNING CHECK LOOKS LIKE ENGINE IS OVERFULL 2 QTS THIS UNIT IS GOING TO BE DUE FOR PM WITHIN 500 MILES PLEASE CHECK IT OUT WHEN YOU CAN AND WE'LL GET IT IN FOR PM SOON**

Date Opened: 7-10-2018 Date Finished 7-11-2018 Meter 1 Reading: 103,011

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OIL

CSHOP-2018-4150

Date Opened: 7-24-2018 Date Finished 7-24-2018 Meter 1 Reading: 100,342

TASKS PERFORMED

NO PARTS USED

REPAIRS BY RECHTIEN

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2018-5222

Date Opened: 9-13-2018 Date Finished 9-19-2018 Meter 1 Reading: 105,520

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

2	2IH; FILTER, CAB A/C INT BX, BLUE
20	4PC; 15W40 PREMIUM BLUE OIL
2	8GR; FILTER
1	FIL; NAPA CABIN AIR FILTER
-1	1AD; BATTERY 31 SERIES
4	1AD; BATTERY 31 SERIES
1	2IH; AIR FILTER-CAN ORDER-500804
1	FIL; NAPAGOLD OIL FILTER
1	BK; RADIATOR CAP
1	FIL; NAPA GOLD FUEL FILTER

CSHOP-2018-5303

Comments: **PM FUP REPAIRS**

Date Opened: 9-17-2018 Date Finished 9-19-2018 Meter 1 Reading: 105,520

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
ALTERNATOR-GENERATOR
REPAIR FROM PM - ENGINE
DOOR STRIKER PLATE
AIR CONDITIONING

2	1AN; WIPERS
1	1AD; ALTERNATOR, 320A
1	2IH; TUBE ASSM
1	NCB; GUNK ENGINE DEGREASER
12	9AP; BRAKE CLEAN
1	NCB; DEGREASER MULTI PURP
1	NHD; HVAC AIR DOOR ACT

Asset Work Order History 10187788

CSHOP-2018-5398

Date Opened: 9-21-2018 Date Finished 10-5-2018 Meter 1 Reading: 106,353

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - AIR INTAKE SYS

1 9IP; CLAMP

CSHOP-2018-5473

Date Opened: 9-25-2018 Date Finished 9-25-2018 Meter 1 Reading: 105,781

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

1 2IH; BLOWER CAB REAR

CSHOP-2018-580

Date Opened: 1-26-2018 Date Finished 1-31-2018 Meter 1 Reading: 97,446

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
1 CRC; CLEAN-R-CARB 20OZ
22 9OC; SYN 15W40
1 FIL; NAPA GOLD FUEL FILTER

CSHOP-2018-5809

Comments: **INSTALL TIC**

Date Opened: 10-15-2018 Date Finished 11-19-2018 Meter 1 Reading: 107,967

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT
DOOR LOCKS

4 BK; ATC FUSEHOLDER-CARD
2 BK; FUSE HOLDER

Service Requests:

10/14/2018 DOOR / 12: BROKEN / REPAIR
DOOR LOCKS NOT WORKING

CSHOP-2018-6214

Comments: **UNIT BROKE DOWN**

Date Opened: 11-1-2018 Date Finished 11-1-2018 Meter 1 Reading: 108,095

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM

Asset Work Order History 10187788

CSHOP-2018-6390

Date Opened: 11-9-2018 Date Finished 11-16-2018 Meter 1 Reading: 108,815

TASKS PERFORMED

Q PARTS

FIRE EXTINGUISHER

1 9ME; STRAP

Service Requests:

11/09/2018 SERVICE REQUEST / 46: LOST OR MISSING / EXCHANGE - NEW
NEED A BRACKET FOR A 10 POUND FIRE EXTINGUISHER BEHIND THE LIEUTENANT'S SEAT ON R14.

CSHOP-2018-6423

Date Opened: 11-10-2018 Date Finished 11-13-2018 Meter 1 Reading: 108,642

TASKS PERFORMED

Q PARTS

OIL

20 4PC; 15W40 PREMIUM BLUE OIL
2 FIL; NAPAGOLD OIL FILTER

CSHOP-2018-6585

Date Opened: 11-20-2018 Date Finished 11-20-2018 Meter 1 Reading: 109,177

TASKS PERFORMED

NO PARTS USED

REAR TIRES

Service Requests:

11/19/2018 SERVICE REQUEST / 47: HIGH PRESSURE / ADJUST
TYPE PROBLEM INTO DESCRIPTION

CSHOP-2018-6589

Comments: **ENGINE DERATED WHILE DRIVING**

Date Opened: 11-20-2018 Date Finished 11-21-2018 Meter 1 Reading: 108,898

TASKS PERFORMED

NO PARTS USED

EMISSIONS SYSTEM

CSHOP-2018-7293

Date Opened: 12-26-2018 Date Finished 1-8-2019 Meter 1 Reading: 111,888

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPER BLADES

2 1AN; WIPERS

Asset Work Order History 10187788

CSHOP-2018-7294

Date Opened: 12-26-2018 Date Finished 12-28-2018 Meter 1 Reading: 111,082

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
24 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA GOLD FUEL FILTER
2 1AN; 22" WIPER BLADE

CSHOP-2019-126

Date Opened: 1-8-2019 Date Finished 2-22-2019 Meter 1 Reading: 114,651

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SIREN

Service Requests:

01/07/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
LEFT SIREN BRACKET TO BUMPER IS BROKEN ON TOP. SIREN HELD UP BY LOWER BRACKET ONLY.

CSHOP-2019-1324

Date Opened: 3-11-2019 Date Finished 3-14-2019 Meter 1 Reading: 115,636

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM

3 2IH; NUTS

Service Requests:

03/11/2019 ENGINE / 12: BROKEN / REPAIR
BAD EXHAUST LEAK SMELL OF EXHAUST IN THE CAB. POOL OF OIL FROM ENGINE FOUND NEAR THE TURBO.

CSHOP-2019-1843

Date Opened: 4-9-2019 Date Finished 4-15-2019 Meter 1 Reading: 115,716

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPAGOLD OIL FILTER
25 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA GOLD FUEL FILTER

Asset Work Order History 10187788

CSHOP-2019-1861

Comments: **PM REPAIR**

Date Opened: 4-10-2019

Date Finished

4-17-2019

Meter 1 Reading:

115,716

TASKS PERFORMED

Q PARTS

WIPER BLADES
COOLING SYSTEM
REAR HUB SEAL-GASKET
REAR BRAKE PADS-SHOES
FRONT BRAKE PADS-SHOES
AIR DRIER
AIR SYSTEM

2 1AN; 22" WIPER BLADE
2 9IP; GASKET AXEL
2 TWD; CUP CONE SET
2 TWD; CUP CONE SET
30 BK; KNIFE
1 TWD; REP/CART
2 NTL; TEF SEAL
1 BK; PTEX ULTRA BLACK 30Z
12 9AP; BRAKE CLEAN
2 MBI; GRIP/KIT
2 TWD; BRAKE DRUM
2 TWD; BRAKEDRUM15X4
2 TWD; BRAKESHOEKITSNEW
1 TWD; PURGE VALVE ASSY KIT
1 TWD; PURGE VALVE ASSY KIT
2 1AM; LOCKWASHER
2 1NS; AXLGSKT

CSHOP-2019-2000

Date Opened: 4-17-2019

Date Finished

4-22-2019

Meter 1 Reading:

115,716

TASKS PERFORMED

NO PARTS USED

EXHAUST SYSTEM
OIL

CSHOP-2019-2145

Date Opened: 4-23-2019

Date Finished

4-23-2019

Meter 1 Reading:

115,716

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2019-23

Date Opened: 1-2-2019

Date Finished

1-8-2019

Meter 1 Reading:

111,888

TASKS PERFORMED

NO PARTS USED

SHORELINE CHARGER

Service Requests:

01/02/2019 ELECTRICAL / 12: BROKEN / EXCHANGE - USED
SHORELINE COVER IS BROKEN ON R14. (ROUND COVER)

Asset Work Order History 10187788

CSHOP-2019-3364

Date Opened: 6-27-2019 Date Finished 6-27-2019 Meter 1 Reading: 115,770

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-3439

Date Opened: 7-2-2019 Date Finished 7-23-2019 Meter 1 Reading: 115,764

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SIREN

CSHOP-2019-827

Date Opened: 2-11-2019 Date Finished 3-8-2019 Meter 1 Reading: 115,407

TASKS PERFORMED

Q PARTS

GRILLE
1 2IH; GRILL BAR

Service Requests:

02/11/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
PLASTIC RADIATOR GRILL COVER CRACKED
