



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10194779

#### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V63877**

In Date: 01/31/2014  
Close Date: 02/11/2014

Meter Reading: 1,001.00

**Problem?**  
Install Vanner Inverter

**Task performed:**

INSTALL NEW VANNER- INVERTER- ORIGINAL WAS REMOVED TO BE USED TO REPAIR A DRIVE IN AND WAIT SITUATION SET PERIMATORS ON INVERTOR.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V64298**

In Date: 02/18/2014  
Close Date: 02/19/2014

Meter Reading: 1,443.00

**Problem?**  
Stretcher mount needs adjustment Cab a/c inop

**Task performed:**

- A/C INOP FUSE LOOSE AT HOLDER, REPAIRED FUSE HOLDER.
- STRETCHER MOUNT NEEDS ADT ADJUSTED STRETCHER MOUNT.

| Parts           | Quantity |
|-----------------|----------|
| SAHSVS2510STRAP | 2        |
| UMVS056511STRAP | 2        |
| UMVS111611STRAP | 2        |
| UMVS162511STRAP | 2        |

**Workorder: V64319**

In Date: 02/18/2014  
Close Date: 02/19/2014

Meter Reading:

**Problem?**  
NO INTERNET CONNECTION OR WIFI FOR THE TRIPTIX TABLET! R93

**Task performed:**

LET RADIO SHOP REPAIR.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V64318**

In Date: 02/18/2014  
Close Date: 02/25/2014

Meter Reading:

**Problem?**  
CAB DOME LIGHTS DO NOT SHUT OFF. ALL DOORS ARE CLOSED AND SHUT WELL. R93

**Task performed:**

CHECK DOME LTS INOP CHECK OUT SWITCHES TIMMER ECT WORKING OK UNFOUNDED.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V64502**

In Date: 02/24/2014

Meter Reading:

Close Date: 03/11/2014

**Problem?**

OXYGEN SLIDE OUT RELEASE BAR TO PUSH O2 CYLINDER BACK INTO COMPARTMENT IS INOPERABLE. WHEN LATCH DEPRESSED, NOT RELEASING LOCKING MECHANISM. R93

**Task performed:**

TRAVEL TO 93 CHECK O2 SLIDE LUBE UNIT OK.

Parts

Quantity

283255 SLIDE 18IN 500 LBS

1

H50SN12BULB

1

**Workorder: V64631**

In Date: 03/02/2014

Meter Reading:

Close Date: 03/11/2014

**Problem?**

SPEAKER TO RADIO IS NOT WORKING. CAN NOT COMMUNICATE WITH DISPATCH WITH ON BOARD RADIO. HAVE TO U PORTABLE TO CONTACT BOTH DISPATCH AND ALSO ENCODE TO HOSPITAL ABOUT PT. CARE AND ARRIVAL.

**Task performed:**

LET RADIO SHOP KNOW.

Parts

Quantity

NO PARTS USED

**Workorder: V64865**

In Date: 03/11/2014

Meter Reading:

Close Date: 03/13/2014

**Problem?**

Check warning light has been on for 2 shifts. Called today and no mechanic came by the station. R93 RWC #8497

**Task performed:**

TRAVEL TO ST-93 CHECK OUT CHECK ENG LT ON READ CODE SAME ALL, ALL V8'S DPF PRESSURE DIFF OFF NEEDS TO GO TO INTERNATIONAL.

Parts

Quantity

NO PARTS USED

**Workorder: V64941**

In Date: 03/14/2014

Meter Reading:

Close Date: 03/20/2014

**Problem?**

The check engine light came on when driving back from St. Mary's hospital.

**Task performed:**

TRAVEL TO ST-93 CHECK OUT CHECK ENG LT ON HOOK UP READER CODE IS DPF CODE TOLD CREW IT WILL BE REPAIRED ON NEXT PM.

Parts

Quantity

NO PARTS USED



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V64935**

In Date: 03/14/2014

Meter Reading:

Close Date: 03/26/2014

**Problem?**

The automatic door locks do not work. Also R93 description needs to be changed to 4 door

**Task performed:**

Parts

Quantity

REPAIRED ON WO #65149.

NO PARTS USED

**Workorder: V65054**

In Date: 03/20/2014

Meter Reading:

Close Date: 03/26/2014

**Problem?**

Check engine light is on. R93

**Task performed:**

Parts

Quantity

TRAVEL TO ST-93 SAME CODE DPF WILL REPAIR ON NEXT P.M.

NO PARTS USED

**Workorder: V65055**

In Date: 03/20/2014

Meter Reading:

Close Date: 03/26/2014

**Problem?**

Autolocks are not working. Able to manually lock but only the key works to unlock doors. R93

**Task performed:**

Parts

Quantity

REPAIRED ON WO #65149.

NO PARTS USED

**Workorder: V65149**

In Date: 03/24/2014

Meter Reading:

Close Date: 03/26/2014

**Problem?**

R-inside dual tire sensor. door locks, and R-air horn not working r93

**Task performed:**

Parts

Quantity

1. TRAVEL TO ST-93 CHECK NO DOOR LOCKS. CHECK SYSTEM, CHECK MODE IN PT COMPT. FOUND FUSE BLOWN R&R FUSES RETEST OK.
2. CHECK TIRE SENSORS ADJ PRESSURES SAW TEST OK.
3. CHECK AIR HORNS INOP ADJUST R/AIR HORN.

NO PARTS USED



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V65712**

In Date: 04/15/2014  
Close Date: 04/15/2014

Meter Reading: 4,892.00

**Problem?**

No start

**Task performed:**

NO START, DEAD BATT, CHARGED AND TESTED  
MATTERIES OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V64309**

In Date: 02/18/2014  
Close Date: 04/25/2014

Meter Reading:

**Problem?**

CHECK ENGINE LIGHT CAME ON WHILE DRIVING NON EMERGENCY TO ANOTHER STATION FOR MOVE UP

**Task performed:**

CHECK ENGINE LIGHT CAME ON WHILE DRIVING  
NON EMERGENCY TO ANOTHER STATION FOR MOVE  
UP

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V66246**

In Date: 05/05/2014  
Close Date: 05/07/2014

Meter Reading: 5,568.00

**Problem?**

B inspection R93

**Task performed:**

OIL AND FILTER AND Q.A.

**Parts**

15W40BSYN OIL BULK QTS  
1884207C92FUEL FILTER MAXFORCE 7  
1899332C91OIL FILTER MAXFORCE 7  
2602212C1PRIMARY AIR FILTER 4300M7

**Quantity**

26  
1  
1  
1

**Workorder: V65161**

In Date: 03/24/2014  
Close Date: 05/16/2014

Meter Reading:

**Problem?**

Tire presser gauge, int. cab hooks, and glove holder. r93

**Task performed:**

**Parts**

14-7014HGR-1 HELMET HOOK  
516TIRE INFLATOR  
S777COUPLING NIPPLE

**Quantity**

4  
1  
1



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V66594**

In Date: 05/19/2014      Meter Reading:  
Close Date: 05/22/2014

**Problem?**

AIRPACK KEEPS FALLING OUT OF BRACKET AND OUT OF THE TRUCK WHEN DOOR IS OPENED FALLING ONTO THE GROUND. THE BOTTLE KEEPS COMING OUT OF THE VEHICLE HOUSING BRACKET WHEN DOOR IS CLOSED FROM OUTSIDE. NEED QUICK REL STRAP

| Task performed:   | Parts                             | Quantity |
|---|-----------------------------------|----------|
| TRAVEL TO ST-93 INSTALL AIR PACK BRKT. STRAPS ON DOOR COMPT BOTTLE. | 101-124-000CRASH RESTRAINT STRAPS | 1        |

**Workorder: V66948**

In Date: 06/03/2014      Meter Reading:  
Close Date: 06/16/2014

**Problem?**

WRENCH LIGHT INDICATOR IS ILLUMINATED IN THE DASH AND ALSO STATES CHECK ENGINE OIL.

| Task performed:        | Parts         | Quantity |
|------------------------|---------------|----------|
| repaired on other w/o. | NO PARTS USED |          |

**Workorder: V66743**

In Date: 05/25/2014      Meter Reading:  
Close Date: 06/17/2014

**Problem?**

TRUCK WAS SPUTTERING THIS AM WITH TRUCK CHECK OUT AND NOW THIS AFTERNOON THERE IS A CRESENT WRENCH LIGHT ON IN THE DASHBOARD WHEN ENGINE IS RUNNING.

| Task performed:                                    | Parts         | Quantity |
|--|---------------|----------|
| CHECK OUT TRUCK COULD NOT TRUCK TO FAIL UNFOUNDED. | NO PARTS USED |          |

**Workorder: V66821**

In Date: 05/28/2014      Meter Reading:  
Close Date: 06/17/2014

**Problem?**

WRENCH LIGHT HAS BEEN ILLUMINATED FOR 3 DAYS ON RESCUE DASH FOR THE ENTIRE TIME TRUCK IS RUNNING. I SURE WHAT INDICATOR LIGHT IS FOR, BUT ANY LIGHT THAT'S ON PERTAINS TO TRUCK PERFORMANCE NEEDS IMMEDIATE ATTENTION.

| Task performed:  | Parts                       | Quantity |
|--|-----------------------------|----------|
| TRAVEL TO ST-93 CHECK OUT CHECK ENG LIGHT ON DISPLAY SAID OIL CHANGE RESET WARNING LIGHT FOR NOW NO OTHER CODES. | 29539579 57701 TRANS FILTER | 1        |



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67153**

In Date: 06/12/2014  
Close Date: 06/17/2014

Meter Reading: 7,950.00

**Problem?**

o2 leak

**Task performed:**

O2 LEAK SPRAYED SOAP WATER ON CALL O2 FITTINGS AND TIRES- LEAK AT MANIFOLD TIGHTEN MANIFOLD CORRECTLY.

Parts

Quantity

NO PARTS USED

**Workorder: V67434**

In Date: 06/24/2014  
Close Date: 06/30/2014

Meter Reading:

**Problem?**

Shoreline AC does not work when plugged in. E93 RWC #8497

**Task performed:**

travel to sta,93 ck, out 110v a/c system found breaker open reset show driver how to set ck, ok.

Parts

Quantity

NO PARTS USED

**Workorder: V67544**

In Date: 06/29/2014  
Close Date: 07/09/2014

Meter Reading:

**Problem?**

Rubber skir in openingt between cab and box is torn and allows copious amounts of rain to enter box of unit

**Task performed:**

Called forman to see if it is under warranty. They said Horton will repair.

Parts

Quantity

NO PARTS USED

**Workorder: V68169**

In Date: 07/25/2014  
Close Date: 07/28/2014

Meter Reading:

**Problem?**

Right front wheel bearing needs to be replaced on the stair chair. It is in temporary working order, but needs repair.

**Task performed:**

repaired by EMSAR

Parts

Quantity

NO PARTS USED



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V62482**

**In Date:** 12/04/2013

**Meter Reading:** 1,001.00

**Close Date:** 08/08/2014

**Problem?**

**B INSPECTION NEW UNIT IN SERVICE R93**

**Task performed:**

- 1.Remove all rear lights.
- 2.Work installing rear lights back on.
- 3.Work on rear lights and side handle
- 4."B" Inspection
5. Assist Norris with "B" Inspection training.
- 6.Replace bad cab door light swtich on left rear.
- 7.Very rear ground light inop. Check out problem and found harness wiring never connected. Connect wiring and recheck. Now ok.
- 8.Access plates under rear bumper are about to fall off, only one screw holding each one. Find 6 screws and washers and install in plates. Tighten.
- 9.Found 3 under truck ground, light lenses broken and cracked. Replace complete fixtures.
10. Remove steering wheel and retime to straight alignment.
- 11.Install sticker in place , charge batteries for it. Set and adjusted magnet bar and lock handle.
- 12.Install tool brackets and install air tank brackets.

**Parts**

**Quantity**

|                            |   |
|----------------------------|---|
| 14-7014HGR-1 HELMET HOOK   | 6 |
| 3579984C1DOOR SWITCH       | 1 |
| 5269LPVM-5 SM MOUNT        | 2 |
| 61H01LED GROUND LITE CLEAR | 3 |
| FHLP-6TANK CLIP            | 2 |
| LPVM-7LG MOUNT             | 8 |
| UMVS162511STRAP            | 3 |

**Workorder: V68324**

**In Date:** 07/31/2014

**Meter Reading:**

**Close Date:** 08/12/2014

**Problem?**

**Per Road mech. STS that the shore plug on R93 is bad.**

**Task performed:**

travel to sta,93 ck out 110v auto eject found one of the drop bad from biuld call biuld maint, to repair.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V68836**

**In Date:** 08/20/2014

**Meter Reading:** 12,342.00

**Close Date:** 08/25/2014

**Problem?**

**PATIENT COMPARTMENT IS NOT COOLING WITH A/C UNIT RUNNING. VERY HOT WHEN TENDING TO PATIENT CARE**

**Task performed:**

Travel to station 93. Check out rear A/C inop hook up gauges Check fans compartment vent. coling ok.

**Parts**

**Quantity**

NO PARTS USED



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

#### Workorder: V68890

In Date: 08/23/2014

Meter Reading: 12,649.00

Close Date: 08/29/2014

#### Problem?

Regen light was flashing and warning buzzer came on when returning from a call. Did regen and during cycle Severe warning light came on (red stop sign and !). Shop out yesterday for same problem.

#### Task performed:

Perform regen/ replaced DPF filter.

#### Parts

DPFCLEANED UNIT

#### Quantity

1

#### Workorder: V69077

In Date: 08/31/2014

Meter Reading:

Close Date: 09/03/2014

#### Problem?

Yellow wrench light on dash is on, also saying change engine oil. R93

#### Task performed:

TRAVEL TO STA,93 TRY TO CLEAR SREVICE OIL LIGHT COULD NOT GET TO CLEAR.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V70395

In Date: 10/23/2014

Meter Reading: 13,446.00

Close Date: 11/03/2014

#### Problem?

Check eng. light and running rough

#### Task performed:

Repaired on W/O # 70472.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V70472

In Date: 10/27/2014

Meter Reading: 13,684.00

Close Date: 11/03/2014

#### Problem?

Check engine light is on

#### Task performed:

1. Travel to station 93. Check out truck Check Engine light on. Hook up laptop to get codes. Found A/C codes. Clear coder. Retest - OK.

#### Parts

NO PARTS USED

#### Quantity





11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V70513**

In Date: 10/28/2014  
Close Date: 11/03/2014

Meter Reading: 13,684.00

**Problem?**

Front cab A/C not blowing any air at all.

**Task performed:**

1. Check out cab A/C. Found breaker loose in fuse bloc.k Wires bad. Cut out breaker and install auto reset 30 amp breaker and wire up.

Parts

54-53030055-30BX CIRCUIT BREAKER

Quantity

1

**Workorder: V70016**

In Date: 10/09/2014  
Close Date: 11/04/2014

Meter Reading: 13,247.00

**Problem?**

check a/c cab and pat

**Task performed:**

Check both cab A/C systems-check patient A/C system-road tested vehicle. Record temps of all units,clear drain in patient A/C-Remove and replace access in pt a/c to check for hot water HTR core. Check temp drop a cross condensor in and out ok- All systems ok.

Parts

6819634283068-1963428-30 LENS CLR

Quantity

1

**Workorder: V70391**

In Date: 10/23/2014  
Close Date: 11/05/2014

Meter Reading: 13,446.00

**Problem?**

Check a/c compressor mounting bolts

**Task performed:**

Travel from station 37 to station 93  
Inspect and retorque patient A/C compressor bracket.  
Travel back to shop

Parts

NO PARTS USED

Quantity



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69728**

**In Date:** 09/26/2014

**Close Date:** 11/07/2014

**Meter Reading:** 13,247.00

**Problem?**

C inspection R93

**Task performed:**

Parts

Quantity



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

|  |                                  |   |
|--|----------------------------------|---|
| 1. C Inspection. Air tires. Top off fluids.  | 065624AD-IP DRIER                | 1 |
| 2. Remove tire sensors and install gator caps.   | 0775145PANEL FILTER              | 2 |
|  | 091-84-022DIODE 6 AMP            | 4 |
| 3. Driver's squirter aiming wrong way. Found squirter in wrong position. Re-position.  | 1884207C92FUEL FILTER MAXFORCE 7 | 1 |
|  | 1899332C91OIL FILTER MAXFORCE 7  | 1 |
| 4.. Replaced exhaust heat shield brackets. Drill holes larger for correct fit.   | 3579984C1DOOR SWITCH             | 4 |
|  | 3599692C1CLAMP EXH SHIELD        | 2 |
|  | 6101737C1LAMP                    | 1 |
| 5. Right rear courtesy door light missing. R & R door panel to recover light wiring. Install new light, cable and door panel. Test Ok.                               | 91-22WIPER BLADE                 | 2 |
|  | K022105PURGE VALVE AD-IP-IS      | 1 |
|  | SD-210RXSIREN DRIVER SMALL       | 1 |
| 6. Remove rear A/C housing. Remove filter. Clean and replaced filter. Install housing.   |                                  |   |
| 7. Tighten loose side patient door shock bolt.   |                                  |   |
| 8. R-3 door reflectors fell off door. Glue reflectors back on.   |                                  |   |
| 9. L-3 lower and upper door shock blocks loose. Tighten bolts.   |                                  |   |
| 10. Re-build dryer and purge valve.  |                                  |   |
| 11. Replaced rear A/C filters. Repaired filter frames. Drill and install new screws where stripped.  |                                  |   |
| 12. Replaced non-skid strip on side doorstep. Cut to size. Remove glue and clean step.   |                                  |   |
| 13. Torque loose U-bolts.  |                                  |   |
| 14. Torque rear axle strut.  |                                  |   |
| 15. LRI tire pressure low. Air tire and check for nails and leaks. Let vehicle sit for 2 days and recheck OK.  |                                  |   |
| 16. Diagnose and repair siren. Found shorted wire and bad driver. Repair wire and replaced driver.   |                                  |   |
| 17. L-2 door will not open. Found loose latch and striker out of adjustment. Tighten screws and adjust striker.  |                                  |   |
| 18. 110 volt A/C condenser fan noisy. Removed unit. Found mounts for fan motor missing bottom bolts. Install new bolts with lock tight and re-install unit. Test OK. |                                  |   |
| 19. Check rear patient A/C system. Check charge and gauge pressures OK. Let run and check outlet temperature 56 degrees F. OK.                                       |                                  |   |



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

20. Replaced all 4 cab door switches (rubber boot torn).

21. Assist with electrical diagnostic troubleshooting.

22. Diagnose electrical issues with dome and ground lights. Install diodes for dome lights. Switch cab curb and cab street output wires at module 11. Order E-Prom for CPU.

**Workorder: V70001**

In Date: 10/08/2014      Meter Reading: 13,247.00  
Close Date: 11/12/2014

**Problem?**

Replace steer tires

**Task performed:**

WORK REPAIR REQUESTED.

Parts

216568BRIDGESTONE 255/70R22.5

Quantity

2

Vendor?: BLVD TIRE CENTER

**Workorder: V68970**

In Date: 08/26/2014      Meter Reading: 12,697.00  
Close Date: 11/13/2014

**Problem?**

Drivers side flasher light cover, located above wheel well is cracked.

**Task performed:**

1 Check out bad lights. R & R lens on left passenger side.

Parts

6819634283068-1963428-30 LENS CLR

Quantity

1

R/R emer light lens on 4s rear

**Workorder: V70761**

In Date: 11/06/2014      Meter Reading:  
Close Date: 11/18/2014

**Problem?**

There is a roach infestation in the front cab. A few german roaches have been found in the pt compartment.

**Task performed:**

Spray for roaches in truck if gets worse will have to tent truck for bugs

Parts

NO PARTS USED

Quantity



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10194779

#### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V70804**

In Date: 11/09/2014  
Close Date: 11/18/2014

Meter Reading:

**Problem?**

Driver's side rear ground lights not working. All other ground lights are functional R93.

**Task performed:**

Travel to station 93, check out ground light inop found wire pulled out repair connector and wire test ok.

Parts

Quantity

NO PARTS USED

**Workorder: V70834**

In Date: 11/10/2014  
Close Date: 11/18/2014

Meter Reading:

**Problem?**

L. head lt. @ check eng. lt. R93

**Task performed:**

1. R/R headlight out  
2. Check out check engine light on-hook up laptop. Found wheel sensor code, check wiring clear code. Test drive-OK.

Parts

Quantity

9007H9007 BULB ASSY

1

**Workorder: V70838**

In Date: 11/11/2014  
Close Date: 11/18/2014

Meter Reading:

**Problem?**

Drivers side headlight is out

**Task performed:**

Repaired on WO# 70834

Parts

Quantity

NO PARTS USED

**Workorder: V69174**

In Date: 09/04/2014  
Close Date: 12/18/2014

Meter Reading:

**Problem?**

ReGen, the red octagon with exclamation point came on during regen.

**Task performed:**

Corrected during c-inspection-69728

Parts

Quantity

NO PARTS USED



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V71556**

In Date: 12/10/2014      Meter Reading: 16,793.00  
Close Date: 12/18/2014

**Problem?**

door warning lights on doors inop.

**Task performed:**

Travel to station 93-open traffic door lights inop red only.  
R/R body ECM, R/R chip in unit test reinstall ok.

| Parts                    | Quantity |
|--------------------------|----------|
| 10005486EPROM            | 1        |
| FRT V28260FREIGHT CHARGE | 1        |

**Workorder: V71959**

In Date: 12/31/2014      Meter Reading: 18,177.00  
Close Date: 01/07/2015

**Problem?**

1 out of 2 bolts (1/4-20) missing holding the drivers seat in place. r93

**Task performed:**

Travel to station 93-check out seat falling off replace  
belts in seat, test ok.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V71977**

In Date: 01/01/2015      Meter Reading: 18,497.00  
Close Date: 01/07/2015

**Problem?**

noise under body of resuce when battery switch on

**Task performed:**

Checked noise-found suction pump defaults to on when  
battery swiped first turned on. Switched off

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V72308**

In Date: 01/14/2015      Meter Reading:  
Close Date: 01/20/2015

**Problem?**

check engine light/ wrench light on dash. notification of change engine oil. shop was notified.

**Task performed:**

Travel to ST 93. Reset oil change light. Check engine  
light on. Hoop up laptop and check codes. DPF missing  
code. Clear code.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72886**

In Date: 02/04/2015

Meter Reading:

Close Date: 02/11/2015

**Problem?**

A/C IN THE PATIENT COMPARTMENT IS BLOWING WARM

**Task performed:**

Parts

Quantity

Recharged rear a/c pressure were low on the high side, a/c was blowing cold at this time.

NO PARTS USED

**Workorder: V72730**

In Date: 01/29/2015

Meter Reading:

Close Date: 02/19/2015

**Problem?**

Check Engine light turned on. No problems with performance noted

**Task performed:**

Parts

Quantity

Check out check engine light on with laptop. Found DPF pressure code. Will get repaired on next PM. Travel to ST 93.

NO PARTS USED

**Workorder: V73025**

In Date: 02/10/2015

Meter Reading:

Close Date: 02/24/2015

**Problem?**

There is an air leak at a fitting that is connected to a small vertical cylinder at the top of the air compressor under the hood on the drivers side of the vehicle. The cylinder has two lines connected at 45 degrees.

**Task performed:**

Parts

Quantity

Travel to ST 93. Check out air leak lines on governor leaking. R & R lines and fittings. Test ok.

NO PARTS USED

**Workorder: V72769**

In Date: 01/31/2015

Meter Reading:

Close Date: 03/20/2015

**Problem?**

Driver side, outside rear wheel has reached its wear bar and needs to be replaced. R93

**Task performed:**

Parts

Quantity

1. Check a/c. Recover freon and refill system. Found a/c compressor bad. Recover freon. Removed oil filter, belt, trans hose brackets, starter cable harness, lines, fan shroud and compressor. Replaced a/c compressor. Flushed a/c lines and condenser. R & R dryer. Reassembled all parts. Vacuum and charge. Ran and check operation. Check ok.

071601A07-0602A DRIER A/C 7118

1

3615169C23615169C3 A/C COMPRESSOR 4382 SANDEN

1

2. Travel to ST 93. Check tires. Have changed.



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10194779

#### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V74104**

In Date: 03/23/2015  
Close Date: 04/06/2015

Meter Reading: 24,034.00

**Problem?**

Air dump inop

**Task performed:**

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V74696**

In Date: 04/16/2015  
Close Date: 04/16/2015

Meter Reading: 25,677.00

**Problem?**

replace rear tires

**Task performed:**

replace rear tires

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

Vendor?: BOULEVARD

**Workorder: V73678**

In Date: 03/05/2015  
Close Date: 04/22/2015

Meter Reading: 22,549.00

**Problem?**

B inspection R93

**Task performed:**

B-INSP

- CHECK ENGINE LIGHT ON
- L/R & R/R INSIDE TIRES FLAT. AIRED UP BUT MISSING RUBBER STOPS FOR VALVE STEM EXTENSIONS.
- L/WINDSHIELD WASHER NOT WORKING.
- L/FRONT BRAKE MAKING A POPPING NOISE WHEN DEPRESSED

Vendor?: OIL CHANGE SERVICES

| Parts                            | Quantity |
|----------------------------------|----------|
| 1884207C92FUEL FILTER MAXFORCE 7 | 1        |
| 1899332C91OIL FILTER MAXFORCE 7  | 1        |
| 3839141C1FILTER CAB AIR          | 1        |





11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10194779

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V74141**

In Date: 03/24/2015  
Close Date: 05/06/2015

Meter Reading:

**Problem?**

Drivers side grip bar to get into the truck is loose. We tried tightening it but it won't stay sturdy.

**Task performed:**

Parts

Quantity

1. Travel to ST-93, grab bars loose. Tighten all bars on truck.

NO PARTS USED

**Workorder: V73963**

In Date: 03/17/2015  
Close Date: 05/07/2015

Meter Reading: 23,564.00

**Problem?**

CHECK ENGINE LIGHT ON

**Task performed:**

Parts

Quantity

PM FOLLOW UP REPAIRS

- CHECK ENGINE LIGHT ON
- L/R & R/R INSIDE TIRES FLAT. AIRED UP BUT MISSING RUBBER STOPS FOR VALVE STEM EXTENSIONS.
- L/WINDSHIELD WASHER NOT WORKING.
- L/FRONT BRAKE MAKING A POPPING NOISE WHEN DEPRESSED

NO PARTS USED

**Workorder: V73533**

In Date: 03/01/2015  
Close Date: 05/11/2015

Meter Reading:

**Problem?**

The Rescue has damage to the drivers side Rub rail at the bottom. The damage is minor and needs to be buffed out. No scratches or denting was found on the body of the unit.

**Task performed:**

Parts

Quantity

1. Travel to ST-93. Check out damage, straighten mud flap bracket. Rub rail can be repaired at next pm.

NO PARTS USED

**Workorder: V74537**

In Date: 04/09/2015  
Close Date: 05/14/2015

Meter Reading:

**Problem?**

Wrench symbol on dash display. Trans Filter is on other console display.

**Task performed:**

Parts

Quantity

1. Travel to ST-93. Check out truck, DPF missing code, service enging and trans. filter code. R&R filter. Clear codes, test ok.

29539579 57701 TRANS FILTER

1



11/4/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10194779

#### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V70332**

In Date: 10/21/2014  
Close Date: 07/01/2015

Meter Reading: 13,247.00

**Problem?**

replace cab boot

**Task performed:**

| Parts                                       | Quantity |
|---|----------|
| GASK-BEL0110002439 WINDOW BELLOWS 6 IN WIDE | 5        |

**Workorder: V74612**

In Date: 04/13/2015  
Close Date: 07/07/2015

Meter Reading:

**Problem?**

At 3am, the motor was rough, the upside down triangle appeared (along with the wrench and check engine light which has been on a while). It says "check trans filter" and "check trans."

**Task performed:**

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



# Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10194779) 2014 - INTERNATIONAL HORTON Advanced Life Support Vehicle

10194779

## CSHOP-2015-1834

Comments: CHECK ENG. LT ON CHANGE OIL LT ON R93

Date Opened: 7-20-2015 Date Finished 7-20-2015 Meter 1 Reading: 26,800

### TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
ECU-ECM

## CSHOP-2015-1871

Comments: R93 CHECK FRONT TIRE WEAR

Date Opened: 7-21-2015 Date Finished 8-4-2015 Meter 1 Reading: 31,763

### TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH  
CATALYTIC CONVERTER  
BRAKE LIGHTS  
LIGHTING SYSTEM  
CIRCUIT BREAKER  
TIRES & WHEELS  
AIR SYSTEM  
STROBE LIGHTS  
DOOR HINGE-PINS-BUSHINGS  
CABIN AIR FILTER  
BLOWER MOTOR  
HEATING AND VENTILATION  
AIR CONDITIONING

1 SLIDE; 12 IN PAIR DRAWER SLIDES  
1 GASKET; DPF GASKET  
-1 9IP; CLEANED UNIT  
1 9IP; CLEANED UNIT  
1 GASKET; DPF GASKET  
2 FILTER; PANEL FILTER  
1 LOUVER UV  
1 FILTER; CAB FILTER RED DOT

## CSHOP-2015-1884

Comments: R93 C INSPECTION

Date Opened: 7-21-2015 Date Finished 7-29-2015 Meter 1 Reading: 31,761

### TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FILTER CAB AIR  
1 FILTER; FUEL FILTER MAXFORCE 7  
23 FLUID; SYN OIL BULK QTS  
1 FILTER; OIL FILTER MAXFORCE 7

**Asset Work Order History 10194779**

**CSHOP-2015-2026**

Comments: **REPLACE TIRES R 93**

Date Opened: 7-30-2015      Date Finished      7-30-2015      Meter 1 Reading:      31,763

**TASKS PERFORMED**

**NO PARTS USED**

TIRES ALL

**VENDOR?**      ELPEX TIRE    TIRESOLES

---

**CSHOP-2015-2161**

Comments: **REPLACE ALL TIRES**

Date Opened: 8-5-2015      Date Finished      9-17-2015      Meter 1 Reading:      34,070

**TASKS PERFORMED**

**Q      PARTS**

TIRES ALL

**3      FLUID; 50-50 EXTENDED LIFE COOLANT GAL**

**VENDOR?**      ELPEX TIRE    TIRESOLES

---

**CSHOP-2015-2417**

Comments: **R93 AIR HORN DOES NOT WORK DUE TO AIR LEAK**

Date Opened: 8-20-2015      Date Finished      8-24-2015      Meter 1 Reading:      31,863

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR HORN

---

**CSHOP-2015-2638**

Comments: **CHECK ENGINE LIGHT ON R93 CHECK TIRE CONDITION ALSO THANKS**

Date Opened: 9-1-2015      Date Finished      9-1-2015      Meter 1 Reading:      34,070

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FAULT CODE  
TIRES & WHEELS

---

**CSHOP-2015-274**

Comments: **R93 NO START**

Date Opened: 4-24-2015      Date Finished      4-28-2015      Meter 1 Reading:      26,615

**TASKS PERFORMED**

**Q      PARTS**

BATTERY

**3      BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY  
3      BATTERY; BATTERY 950CCA HP-31D**

---

**Asset Work Order History 10194779**

**CSHOP-2015-290**

Comments: **RIGHT HEADLIGHT OUT R93 ENGINE WARNING LIGHT ON**

Date Opened: 4-27-2015      Date Finished 5-6-2015      Meter 1 Reading: 26,715

**TASKS PERFORMED**

**Q      PARTS**

FAULT CODE  
HEADLIGHTS LOW BEAM

1      BULB; H9007 BULB ASSY

---

**CSHOP-2015-3528**

Comments: **R93 BLOWN TURBO - SENT TO RECHTIEN**

Date Opened: 10-21-2015      Date Finished 10-21-2015      Meter 1 Reading: 35,009

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?**      RECHTIEN INTERNATIONAL TRUCKS

---

**CSHOP-2015-3589**

Date Opened: 10-26-2015      Date Finished 10-27-2015      Meter 1 Reading: 35,018

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE B

1      FILTER; FILTER CAB AIR  
1      FILTER; FUEL FILTER MAXFORCE 7  
4      FLUID; SYN OIL BULK QTS  
1      FILTER; OIL FILTER MAXFORCE 7

---

**CSHOP-2015-3617**

Comments: **R93 PM FOLLOW UPS**

Date Opened: 10-27-2015      Date Finished 1-5-2016      Meter 1 Reading: 37,349

**TASKS PERFORMED**

**Q      PARTS**

GROUND LIGHT BODY  
REAR DOOR LATCH ASSEMBLY  
ENGINE AND ACCESSORIES  
BRACKET  
AIR DRIER  
AIR SYSTEM  
STROBE LIGHTS  
DOOR  
STEPS  
RUNNING BOARDS  
DOOR HANDLES INSIDE-OUTSIDE  
CABIN AIR FILTER

1      GROMMET; 91740 GROMMET T/L 4 IN  
1      LIGHT; LED GROUND LITE CLEAR  
1      LIGHT; LIGHT LED RED TIR 6  
1      VALVE; PURGE VALVE AD-IP-IS  
1      DRYER; AD-IP DRIER  
1      FILTER; CAB FILTER RED DOT

---

**Asset Work Order History 10194779**

**CSHOP-2015-4350**

Date Opened: 12-7-2015      Date Finished      12-11-2015      Meter 1 Reading:      35,768

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ENGINE AND ACCESSORIES

**Service Requests:**

---

|            |  |
|------------|--|
| 12/07/2015 | ENGINE / 12: BROKEN / REPAIR<br>THERE IS A SIGNIFICANT AIR LEAK IN THE ENGINE DUE TO A BOLT THAT HAS COME OUT OF ONE OF THE BRACKETS. THE BRACKET STILL HAS ONE BOLT IN IT, BUT IT HAS BEEN RUBBING AGAINST ONE OF THE BELTS. WE WERE ABLE TO TIGHTEN THE BRACKET WITH THE REMAINING BOLT, BUT IT STILL NEEDS THE MISSING BOLT TO BE REPLACED. |
| 12/10/2015 | A/C / 12: BROKEN / REPAIR<br>AC BLOWING HOT AND SMELLS GROSS   |

---

**CSHOP-2015-4663**

Comments: **R93 CAB A/C INOP**  
Date Opened: 12-28-2015      Date Finished      1-20-2016      Meter 1 Reading:      38,408

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM

**Service Requests:**

---

|            |   |
|------------|---|
| 01/15/2016 | RADIATOR / 12: BROKEN / REPAIR<br>THERE IS COOLANT NOTED ON ONE OF THE HOSES CONNECTING TO THE COOLANT RESERVOIR. |
|------------|---|

---

**CSHOP-2016-1048**

Comments: **ON-CALL R93 A/C NOT COLD**  
Date Opened: 3-4-2016      Date Finished      3-10-2016      Meter 1 Reading:      41,972

**TASKS PERFORMED**

**Q      PARTS**

AIR CONDITIONING      1      9IP; 12-2012A EXPANSION VALVE 71R8301

**Service Requests:**

---

|            |   |
|------------|---|
| 03/04/2016 | A/C / 12: BROKEN / EXCHANGE - NEW<br>A/C ONLY HAS ROOM AIR OR HOT AIR WORKING. NO COLD AIR. |
|------------|---|

---

**CSHOP-2016-1239**

Comments: **R93**  
Date Opened: 3-15-2016      Date Finished      3-15-2016      Meter 1 Reading:      42,412

**TASKS PERFORMED**

**Q      PARTS**

AIR CONDITIONING      1      DRYER; 07-0602A DRIER A/C 7118  
1      9IP; 12-2012A EXPANSION VALVE 71R8301

**Service Requests:**

---

|            |  |
|------------|--|
| 03/15/2016 | A/C / 18: LEAKING / REPAIR<br>A/C IN THE FRONT CAB IS NOT COOLING. |
|------------|--|

---

**Asset Work Order History 10194779**

**CSHOP-2016-1401**

Comments: **R93**

Date Opened: 3-23-2016

Date Finished

4-6-2016

Meter 1 Reading:

44,047

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
SEAT BELTS  
AIR CONDITIONING

1 NEWPART; BUCKLE SEAT BELT  
1 9IP; SEAT BELT

**Service Requests:**

03/23/2016 A/C / 12: BROKEN / REPAIR  
R93 IS EXPERIENCING A/C PROBLEMS IN THE CREW CAB, NO COLD AIR.

03/23/2016 SEATS / 12: BROKEN / REPAIR  
PLASTIC SEATBELT COVER BROKEN FOR REAR CREW CAB SEAT, (LT SIDE). COVER- AMSAFE C081112

**CSHOP-2016-1446**

Date Opened: 3-28-2016

Date Finished

4-5-2016

Meter 1 Reading:

43,948

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

2 FILTER; PANEL FILTER  
1 FILTER; PRIMARY AIR FILTER 4300M7  
1 9IP; 5580 CAP-BLACK R134A  
1 9IP; CAP-BLACK 134A 5579 KOOL TEMP  
1 9IP; CAP A/C INTERNATIONAL  
1 NEWPART; LOUVER LARGE  
1 FILTER; CAB FILTER RED DOT

**Service Requests:**

03/25/2016 A/C / 18: LEAKING / REPAIR  
FRONT AC IS NOT BLOWING COLD AIR. BOTH SWITCHES ARE TURNED ON.

03/26/2016 DECALS / 18: LEAKING / REPAIR  
CHECK ENGINE LIGHT CAME ON TODAY 03/26/16

**CSHOP-2016-146**

Comments: **E93 AIR LEAK**

Date Opened: 1-12-2016

Date Finished

1-12-2016

Meter 1 Reading:

37,848

**TASKS PERFORMED**

**Q PARTS**

ELECTRICAL  
AIR SYSTEM

1 PUMP; VPS SHIFT KIT 546-0370-53-0

**Asset Work Order History 10194779**

**CSHOP-2016-2080**

Comments: **R93**

Date Opened: 5-2-2016

Date Finished

5-5-2016

Meter 1 Reading:

45,973

**TASKS PERFORMED**

**Q PARTS**

FAULT CODE  
WHEEL BEARINGS  
AIR DRIER  
AIR CONDITIONING

1 9IP; LOCK PLATE SPINDLE NUT  
1 GASKET; GASKET AXLE FL80 R002435  
1 9IP; 370023A SEAL  
1 VALVE; PURGE VALVE AD-IP-IS  
1 DRYER; AD-IP DRIER  
1 NEWPART; A/C UNIT CAB BACK WALL HORTON  
1 FILTER; CAB FILTER RED DOT

**Service Requests:**

04/29/2016 A/C / 18: LEAKING / REPLACED REAR EVAP  
A/C IN FRONT CAB NOT WORKING.

04/29/2016 ENGINE / 18: LEAKING / EXCHANGE - NEW  
SERVICE ENGINE LIGHT IN ON.

**CSHOP-2016-2134**

Date Opened: 5-3-2016

Date Finished

5-5-2016

Meter 1 Reading:

45,973

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C RESCUE

1 FILTER; AF27958 FILTER CAB AIR  
1 FILTER; FUEL FILTER MAXFORCE 7  
30 FLUID; SYN OIL BULK QTS  
1 FILTER; OIL FILTER MAXFORCE 7



**Asset Work Order History 10194779**

**CSHOP-2016-2671**

Comments: **R93 JUST HAD A PM, MAYBE JUST NEEDS TO BE RE-SET THANKS**

Date Opened: 6-3-2016

Date Finished

9-6-2016

Meter 1 Reading:

54,737

**TASKS PERFORMED**

**Q PARTS**

|                               |   |                                      |
|-------------------------------|---|--------------------------------------|
| DOOR LATCH                    | 1 | FILTER; PRIMARY AIR FILTER 4300M7    |
| WIPERS-WASHER                 | 1 | MOUNT; MOUNT 500 TIR SER CHROME      |
| FUEL SYSTEM                   | 1 | BULB; BULB                           |
| FAULT CODE                    | 1 | 9IP; LENS CLEAR 68-1181349-3         |
| ENGINE AND ACCESSORIES        | 1 | NONSTOCK; DRAG LINK INTERNATIONAL 07 |
| LIGHTING SYSTEM               | 1 | VALVE; PURGE VALVE AD-IP-IS          |
| TORQUE ROD-ARM                | 1 | DRYER; AD-IP DRIER                   |
| SUSPENSION                    | 2 | WIPER; WIPER BLADE                   |
| DRAG LINK                     | 2 | BRAKE; REAR DRUMS 3757X 3647X        |
| AIR DRIER                     | 2 | BRAKE; HD SHOE KIT 3/8 BEAM          |
| REPAIR FROM PM - BRAKES       | 1 | BRAKE; BRK PEDAL PAD                 |
| DOOR WEATHER MOLDING          | 8 | WINDOW; 10002439 WINDOW BELLOWS 6 IN |
| INTERIOR TRIM-MOLDINGS-UPHOLS |   |                                      |
| AIR CONDITIONING              |   |                                      |

**Service Requests:**

06/03/2016 OIL / 47: HIGH PRESSURE / REPAIR  
YELLOW WRENCH ON DASHBOARD WITH CHANGE ENGINE OIL BEING DISPLAYED

06/16/2016 A/C / 12: BROKEN / REPAIR  
THE FRONT CAB AC IS INTERMITTENT THE REAR AC IS WORKING PROPERLY

**CSHOP-2016-3226**

Comments: **R93**

Date Opened: 7-5-2016

Date Finished

9-6-2016

Meter 1 Reading:

54,735

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**Service Requests:**

07/02/2016 ALARMS / 12: BROKEN / REPAIR  
O2 LOW WARNING BUZZER ON REPEATEDLY EVEN WHEN FULL. (EVERY 5-10 SECONDS WHEN USING O2 DURING TRANSPORT YOU NEED TO PRESS WARNING RESET BUTTON)

**Asset Work Order History 10194779**

**CSHOP-2016-3255**

Comments: **R93 CHECK OUT TK NO CODE FOR TRANS**

Date Opened: 7-6-2016

Date Finished

9-6-2016

Meter 1 Reading:

54,735

**TASKS PERFORMED**

**NO PARTS USED**

---

REAR TIRES

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**Service Requests:**

---

07/06/2016

TRANSMISSION / 12: BROKEN / REPAIR

THE TRANSMISSION OIL FILTER WARNING SIGNAL CAME UP ON THE DISPLAY ALONG WITH THE AMBER ENGINE LIGHT AND THE AMBER WRENCH SYMBOL. THE TRUCK SEEMS TO BE RUNNING PROPERLY.

07/13/2016

SERVICE REQUEST / 12: BROKEN / REPAIR

THE LENS FOR THE FORWARD RIGHT SIDE FLOOD LIGHT IS BROKEN.

---

**CSHOP-2016-3543**

Date Opened: 7-25-2016

Date Finished

7-25-2016

Meter 1 Reading:

51,797

**TASKS PERFORMED**

**NO PARTS USED**

---

FRONT TIRES

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**Asset Work Order History 10194779**

**CSHOP-2016-3778**

Comments: **SCENE LIGHT CHECK TRANS LIGHT**

Date Opened: 8-4-2016

Date Finished

9-6-2016

Meter 1 Reading:

54,735

**TASKS PERFORMED**

**Q PARTS**

UL REPAIRS  
EMISSIONS SYSTEM  
LIGHTING SYSTEM  
AUTO-EJECT  
TRANSMISSION  
INTERIOR TRIM-MOLDINGS-UPHOLS  
SEAT FRONT  
AIR CONDITIONING

1 COVER; OVAL AUTO EJECT COVER

**Service Requests:**

- 
- |            |   |
|------------|---|
| 08/03/2016 | LIGHTS / 12: BROKEN / REPAIR<br>SCENE LIGHT DRIVER SIDE OUT   |
| 08/04/2016 | ALARMS / 11: BINDS/STICKS / REPAIR<br>CHECK TRANSMISSION, CHECK TRANS FILTER AND CHECK ENGINE WARNING LIGHTS ON DASH ON. FLUID LEVELS CHECKED AND WITHIN ACCEPTABLE RANGE.    |
| 08/19/2016 | LIGHTS / 12: BROKEN / REPAIR<br>VEHICLE LIGHTS NOT WORKING. FRONT OFFICER SIDE FLOOD SCENE LIGHT IS BROKEN.   |
| 08/22/2016 | BODY / 12: BROKEN / REPAIR<br>SHORE PLUG CAP FOUND BROKEN THIS MORNING.   |
| 08/25/2016 | SERVICE REQUEST / 12: BROKEN / REPAIR<br>SERVICE REQUEST. RUBBER GASKET BETWEEN MAIN CABIN AND PATIENT COMPARTMENT IS TORN WILL NOT PREVENT FROM WATER LEAKING INSIDE RESCUE. |
| 09/03/2016 | ALARMS / 11: BINDS/STICKS / REPAIR<br>ALARM SIGNALS. LOW O2 ALARM SIGNAL MALFUNCTIONING.  |
| 09/03/2016 | SEATS / 12: BROKEN / REPAIR<br>SEAT ISSUE. DRIVER SEAT TORN.  |
| 09/04/2016 | A/C / 12: BROKEN / REPAIR<br>A/C ISSUE- AC FAN/BLOWER WORKING INTERMITTENTLY IN THE FRONT CAB.  |
| 09/06/2016 | ALARMS / 14: CRACKED / INSPECT<br>ALARM SIGNALS. CHECK ENGINE LIGHT IS BACK ON.   |

**CSHOP-2016-3850**

Comments: **E93 CHECK ENGINE LIGHT**

Date Opened: 8-8-2016

Date Finished

8-8-2016

Meter 1 Reading:

52,803

**TASKS PERFORMED**

**NO PARTS USED**

INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

- 
- |            |   |
|------------|---|
| 08/07/2016 | ALARMS / 19: LOOSE / REPAIR<br>***CHECK TRANS' LIGHT STAYS ON WHEN THERE IS PLENTY OF TRANSMISSION FLUID ON BOARD. ***CHANGE ENGINE OIL' LIGHT IS ON. ****TRANS OIL FILTER' LIGHT IS ON. **VARIOUS SYMBOLS ON DASHBOARD PRESENT |
|------------|---|

**Asset Work Order History 10194779**

**CSHOP-2016-4**

Comments: **R93 CAB A/C NOT COLD**

Date Opened: 1-4-2016      Date Finished      1-14-2016      Meter 1 Reading:      37,908

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

01/03/2016      A/C / 12: BROKEN / REPAIR  
A/C IN CAB NOT BLOWING COLD.

**CSHOP-2016-4281**

Date Opened: 8-31-2016      Date Finished      8-31-2016      Meter 1 Reading:      54,500

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE B

1      FILTER; AF27958 FILTER CAB AIR  
1      FILTER; FUEL FILTER MAXFORCE 7  
30      FLUID; SYN OIL BULK QTS  
1      FILTER; OIL FILTER MAXFORCE 7

**CSHOP-2016-4477**

Date Opened: 9-14-2016      Date Finished      9-30-2016      Meter 1 Reading:      56,430

**TASKS PERFORMED**

**Q      PARTS**

EXHAUST SYSTEM  
OIL  
AIR BAG SYSTEM

1      GASKET; DPF GASKET  
1      NEWPART; DPF 5010847R1  
1      GASKET; DPF GASKET  
1      NONSTOCK; CORE CHARGE  
22      FLUID; SYN OIL BULK QTS  
1      FILTER; OIL FILTER MAXFORCE 7  
2      BRAKE; GY1R11216 AIR BAG INT.

**Service Requests:**

09/11/2016      ALARMS / 19: LOOSE / REPAIR  
WE KEEP GETTING A LOW O2 ALARM FOR THE ON-BOARD OXYGEN TANK. THE TANK IS FULL AND FULLY TURNED ON.  
DO NOT KNOW WHY WE KEEP GETTING THE ALARM.

09/11/2016      SERVICE REQUEST / 19: LOOSE / REPAIR  
CHECK ENGINE LIGHT IS ON AGAIN

09/14/2016      SERVICE REQUEST / 19: LOOSE / REPAIR  
SERVICE REQUEST, ENGINE OIL IS EXCESSIVELY HIGH AND IDLE REGEN IS NOT WORKING

**Asset Work Order History 10194779**

**CSHOP-2016-4620**

Comments: **CALLED EMSAR FOR STAIR CHAIR REPAIR ALL REPAIRED ON ANOTHER W/O**  
Date Opened: 9-23-2016      Date Finished      1-6-2017      Meter 1 Reading:      63,128

**TASKS PERFORMED**

**NO PARTS USED**

GUIDE RAILS  
AIR CONDITIONING

**Service Requests:**

- 
- 09/10/2016      SERVICE REQUEST / 12: BROKEN / REPAIR  
FUEL GAUGE IS NOT WORKING ON R93.
  - 09/23/2016      A/C / 12: BROKEN / REPAIR  
FRONT AIR CONDITIONER IN CAB/DASH WORKS INTERMITTENTLY.
  - 09/25/2016      DOOR / 12: BROKEN / REPAIR  
ONE OF THE INTERNAL EQUIPMENT DRAWERS HAS A BROKEN TRACK AND WILL NOT CLOSE
  - 12/02/2016      SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST R93 PELICAN FLASH LIGHT NOT CHARGING OR WORKING. TAGGED.
  - 12/02/2016      SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST R93 STAIR CHAIR WAS A BENT FRONT WHEELS MAKING THE CHAIR DIFFICULT TO STEER AND OPERATE.
- 

**CSHOP-2016-5024**

Date Opened: 10-23-2016      Date Finished      11-8-2016      Meter 1 Reading:      59,265

**TASKS PERFORMED**

**Q      PARTS**

AIR SYSTEM

2      SOLENOID; SOLENOID AIR DUMP INT  
1      VALVE; CHECK VALVE INT

**CSHOP-2016-5106**

Date Opened: 10-26-2016      Date Finished      10-26-2016      Meter 1 Reading:      58,168

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**CSHOP-2016-5292**

Comments: **R93 ISSUE WITH TRANS NOT GOING INTO GEAR**  
Date Opened: 11-10-2016      Date Finished      11-24-2016      Meter 1 Reading:      60,236

**TASKS PERFORMED**

**NO PARTS USED**

TRANSMISSION

**Asset Work Order History 10194779**

**CSHOP-2016-5672**

Date Opened: 12-5-2016

Date Finished

1-6-2017

Meter 1 Reading:

63,128

**TASKS PERFORMED**

|                        | <b>Q</b> | <b>PARTS</b>                            |
|------------------------|----------|---|
| GUIDE RAILS            | 3        | SLIDE; 12 IN PAIR DRAWER SLIDES         |
| FAULT CODE             | 1        | BRAKE; VALVE FOOT VALVE BRAKE           |
| ENGINE AND ACCESSORIES | 1        | NEWPART; BLOWER HARNESS                 |
| COMPUTER CONTROLS      | 1        | MOTOR; BLOWER MOTOR 2012 OLD 3839363C91 |
| TRANSMISSION           |          |   |
| AIR CONDITIONING       |          |   |

**Service Requests:**

- 
- 12/03/2016 A/C / 12: BROKEN / REPAIR  
A/C ISSUE A/C TURNING ON AND OFF INTERMITTENTLY WHEN VEHICLE IS IN DRIVE.
  - 12/03/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST TRANSMISSION NOT SHIFTING INTO GEAR WHEN GEAR IS CHANGED FROM NEUTRAL TO REVERSE OR NEUTRAL TO DRIVE.
  - 12/09/2016 BRAKES / 12: BROKEN / REPAIR  
BRAKE ISSUES WHEN RESCUE DUMPS THE BACK AIR BAGS THE WHOLE TRUCK BEGINS TO ROLL FORWARD. REPEATED 3 TIMES WITH SAME RESULT. CAN HEAR AN AIR LEAK COMING FROM AIR LINE NEXT TO AIR PUMP FOR AIR BRAKE SYSTEM.
  - 12/09/2016 ENGINE / 12: BROKEN / REPAIR  
ENGINE LEAKING OIL, MULTIPLE LARGE SPOTS FOUND ON BAY FLOOR THE MORNING OF 12/09/16
  - 12/09/2016 TRANSMISSION / 12: BROKEN / REPAIR  
TRANSMISSION HAVING A HARD TIME SHIFTING INTO GEAR FROM PARK TO DRIVE AND REVERSE. HAVE TO CYCLE SHIFTER SEVERAL TIMES THROUGH ALL GEARS BEFORE SHIFTING AND VEHICLE BEING ABLE TO MOVE.
  - 12/09/2016 SERVICE REQUEST / 19: LOOSE / REPAIR  
SERVICE REQUEST CHANGE ENGINE OIL, CHECK ENGINE LIGHT ON.
  - 12/09/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST, DRAWER IN PATIENT COMPARTMENT BROKEN OFF TRACK.

**CSHOP-2016-575**

Comments: **R93**

Date Opened: 2-5-2016

Date Finished

4-6-2016

Meter 1 Reading:

44,047

**TASKS PERFORMED**

|                                    | <b>Q</b> | <b>PARTS</b>      |
|------------------------------------|----------|-------------------|
| TRAVEL TO BE CHARGED TO WORK ORDER | 1        | STRAP; STRAP ZICO |
| FAULT CODE                         |          |                   |
| REAR WINDOW                        |          |                   |
| DOOR                               |          |                   |

**Service Requests:**

- 
- 02/04/2016 DOOR / 13: CHIPPED / REPAIR  
PASSENGER SIDE REAR WINDOW WILL NOT GO DOWN WHEN BUTTON IS PRESSED ON DOOR NOR ON DRIVE DOOR.
  - 02/04/2016 DOOR / 12: BROKEN / REPAIR  
REAR DOOR ON PT COMPARTMENT IS BECOMING MORE DIFFICULT TO OPEN FROM OUTSIDE AND INSIDE. IT IS THE DOOR WITH THE LOCKING MECHANISM.
  - 02/26/2016 ENGINE / 12: BROKEN / REPAIR  
CHECK ENGINE / CHANGE OIL LIGHT ON

**Asset Work Order History 10194779**

**CSHOP-2016-6012**

Comments: **R-93 REAR TIRE HAS SCREW IN IT AND LEAKING.**

Date Opened: 12-27-2016      Date Finished      1-3-2017      Meter 1 Reading:      62,800

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

**Service Requests:**

---

12/27/2016      HAZARD / 15: FOREIGN MATERIAL / REPAIR  
HAZARDOUS ISSUE ( PASSENGER SIDE REAR TIRE LEAKING AIR FROM LARGE SCREW )

---

**CSHOP-2016-6117**

Comments: **R-93 SIREN MOUNTING BOLT**

Date Opened: 12-30-2016      Date Finished      1-3-2017      Meter 1 Reading:      62,618

**TASKS PERFORMED**

**NO PARTS USED**

SIREN

**CSHOP-2016-735**

Comments: **R93**

Date Opened: 2-16-2016      Date Finished      2-22-2016      Meter 1 Reading:      40,633

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
SAFTEY-EMERGENCY EQUIPMENT      2      WIPER; WIPER BLADE

**Service Requests:**

---

02/14/2016      W/S WIPER / 19: LOOSE / REPAIR  
WINDSHIELD WIPERS ARE COMING APART AND NEED TO BE REPLACED

---

**CSHOP-2017-106**

Comments: **R-93 SIREN NOT WORKING**

Date Opened: 1-5-2017      Date Finished      1-5-2017      Meter 1 Reading:      63,086

**TASKS PERFORMED**

**NO PARTS USED**

SAFTEY-EMERGENCY EQUIPMENT

**Service Requests:**

---

01/05/2017      ALARMS / 12: BROKEN / REPAIR  
ALARM SIGNALS LEFT SIREN NOT WORKING. NEED WHOLE NEW UNIT.

---

**Asset Work Order History 10194779**

**CSHOP-2017-12**

Comments: **R-93 SIREN HORN HAS PROBLEM**

Date Opened: 1-3-2017

Date Finished

1-6-2017

Meter 1 Reading:

63,086

**TASKS PERFORMED**

**NO PARTS USED**

SIREN

**Service Requests:**

12/31/2016

ALARMS / 12: BROKEN / OVERHAUL

ALARM SIGNALS FRONT SIREN BEHIND FRONT BUMPER ON DRIVERS SIDE HAS A WHOLE IN IT.

**CSHOP-2017-1431**

Comments: **PM FOLLOW UPS**

Date Opened: 3-8-2017

Date Finished

3-13-2017

Meter 1 Reading:

65,714

**TASKS PERFORMED**

**Q PARTS**

WIPERS-WASHER

2 1AN; WIPERS

FUEL SYSTEM

1 2TP; 2TP

TRANSMISSION

1 VALVE; PURGE VALVE AD-IP-IS

AIR SYSTEM

1 TWD; REP/CART

BODY EXTERIOR

2 8GR; FILTER

CAB-INTERIOR ACCESSORIES

1 FILTER; CAB FILTER RED DOT

AIR CONDITIONING

**CSHOP-2017-1847**

Comments: **FINAL QA AND PREP FOR 43**

Date Opened: 3-27-2017

Date Finished

4-7-2017

Meter 1 Reading:

65,788

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION

1 9IP; HANDLE LH HORTON

INTAKE MANIFOLD

1 8HD; WATER NOZZLE

DIAGNOSE ELECTRICAL

3 8HD; HOSE RACK

DOOR HANDLES INSIDE-OUTSIDE

1 8HD; 100FT WATER HOSE

HEATING AND VENTILATION

1 NTH; COUPLER

2 NTH; COUPLER

2 NTH; ADAPTER

2 NTH; ADAPTER

**CSHOP-2017-2449**

Date Opened: 4-26-2017

Date Finished

4-28-2017

Meter 1 Reading:

66,863

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

04/25/2017

SERVICE REQUEST / 18: LEAKING / REPAIR

SERVICE REQUEST. SEVERAL LIGHTS ARE COMING ON THE ODOMETER, "ENGINE" LIGHT " A WRENCH AND THE WORD "ECON" AND IT ALSO STATES AN OIL CHANGE IS NEEDED



**Asset Work Order History 10194779**

**CSHOP-2017-2678**

Date Opened: 5-8-2017      Date Finished      5-13-2017      Meter 1 Reading:      67,762

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

**Service Requests:**

05/08/2017      SERVICE REQUEST / 18: LEAKING / REPAIR  
CHANGE ENGINE OIL LIGHT APPEARS ON DASHBOARD.

**CSHOP-2017-2806**

Comments:      **BLOWING BLACK SMOKE AND WRENCH LIGHT ON**

Date Opened: 5-12-2017      Date Finished      5-12-2017      Meter 1 Reading:      67,713

**TASKS PERFORMED**

**Q      PARTS**

EXHAUST SYSTEM      1      1RA; CLEANED DPF  
FAULT CODE

**CSHOP-2017-3008**

Date Opened: 5-22-2017      Date Finished      5-26-2017      Meter 1 Reading:      68,249

**TASKS PERFORMED**

**Q      PARTS**

BODY EXTERIOR      2      9IP; COVER, SQUARE, YELLOW

**Service Requests:**

05/20/2017      BODY / 18: LEAKING / REPAIR  
BODY ISSUE-RESCUE 43 AC PLUG COVER BROKE OFF PLUG-LEFT SIDE PLUG

**CSHOP-2017-3407**

Comments:      **QC BACK FROM RECHTIEN**

Date Opened: 6-8-2017      Date Finished      6-13-2017      Meter 1 Reading:      68,365

**TASKS PERFORMED**

**Q      PARTS**

QUALITY CHECK-REPAIRS      1      TWD; GOVERNOR  
COMMERCIAL WORK - OUTSIDE AGENCY      1      2IH; AIR FILTER  
AIR FILTER      1      NBH; V-RIBBED BELT  
GOVERNOR      1      2IH; BELT TENSIONER  
SERPENTINE BELT TENSIONER      2      NBH; IDLER PULLEY  
SERPENTINE BELT      1      NBH; PULLEY  
REPAIR FROM PM - AIR INTAKE SYS      -1      NBH; TENSIONER-HEAVY DUTY  
1      NBH; TENSIONER-HEAVY DUTY  
1      NBH; TENSIONER-HEAVY DUTY  
1      NBH; SERPENTINE BELT  
1      NBH; PULLEY

**Asset Work Order History 10194779**

**CSHOP-2017-3524**

Date Opened: 6-14-2017      Date Finished      6-15-2017      Meter 1 Reading:      68,450

**TASKS PERFORMED**

**Q      PARTS**

---

FUEL SYSTEM  
SAFTEY-EMERGENCY EQUIPMENT

1      2AW; VIB, ASSETWORKS  
1      2AW; T RING, ASSETWORKS  
1      9IP; STRIKER BAR

---

**CSHOP-2017-3888**

Comments:      **INTERMITTENT CAB A/C**

Date Opened: 6-30-2017      Date Finished      7-21-2017      Meter 1 Reading:      69,847

**TASKS PERFORMED**

**NO PARTS USED**

---

EXHAUST SYSTEM  
A/C COMPRESSOR

---

**CSHOP-2017-4017**

Comments:      **CK FOR TURBO NOISE**

Date Opened: 7-8-2017      Date Finished      7-10-2017      Meter 1 Reading:      69,847

**TASKS PERFORMED**

**NO PARTS USED**

---

ENGINE AND ACCESSORIES

---

**CSHOP-2017-4262**

Comments:      **FUEL FILTERS ONLY, ENGINE OIL AND FILTER JUST CHANGED**

Date Opened: 7-21-2017      Date Finished      8-21-2017      Meter 1 Reading:      69,964

**TASKS PERFORMED**

**Q      PARTS**

---

PM SERVICE B

1      FIL; NAPAGOLD OIL FILTER

---

**Asset Work Order History 10194779**

**CSHOP-2017-4263**

Comments: **REPAIRS FROM PM, HAVE CARL OR LUIS REPAIR BROKEN HEAT SHIELD MOUNT**

Date Opened: 7-21-2017      Date Finished      8-21-2017      Meter 1 Reading:      69,964

**TASKS PERFORMED**

**Q      PARTS**

|                                 |    |                                |
|---------------------------------|----|--------------------------------|
| WIPERS-WASHER                   | 2  | 1AN; 22" WIPER BLADE           |
| REPAIR FROM PM - POWER STEERING | 1  | FIL; POWER STEERING FILTER     |
| ELECTRICAL                      | 2  | 2IH; POWER STEERING FLUID 32OZ |
| REPAIR FROM PM - WHEEL SEALS    | 1  | 2IH; PROGRAM                   |
| TIRE                            | 3  | 1AD; BATTERY 31 SERIES         |
| WHEEL BEARINGS                  | 1  | 2IH; BODY CONTROL MODULE       |
| AIR DRIER                       | 2  | TWD; TIMKEN                    |
| CABIN AIR FILTER                | 2  | 2TP; BRG SET                   |
|                                 | 1  | 9AP; HAND SOAP PUM (TOTAL TRK) |
|                                 | -7 | 9OC; GEAR OIL BULK             |
|                                 | 7  | 9OC; GEAR OIL BULK             |
|                                 | 2  | 2TP; BRG SET                   |
|                                 | -2 | TWD; TIMKEN BEARINGS           |
|                                 | 2  | TWD; TIMKEN BEARINGS           |
|                                 | 1  | NTH; ADAPTER                   |
|                                 | 7  | GEAR; GEAR OIL SYN QT          |
|                                 | 12 | MAC; NON-CHLOR BRAKE CLNR      |
|                                 | -2 | TWD; TIMKEN                    |
|                                 | 1  | 9IP; 370023A SEAL              |
|                                 | 1  | 9IP; 370023A SEAL              |
|                                 | 1  | TEM; STEEL FILTER DRIER        |
|                                 | 2  | 8GR; FILTER                    |
|                                 | 1  | FIL; NAPA CABIN AIR FILTER     |

**CSHOP-2017-5332**

Date Opened: 9-14-2017      Date Finished      9-17-2017      Meter 1 Reading:      71,670

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM  
BODY EXTERIOR

**Service Requests:**

09/13/2017      DOOR / 18: LEAKING / REPAIR  
DRIVER COMPARTMENT SCBA HOLDER IS FALLING OFF. SCREW HOLE IS STRIPPED. WHEN SCBA IS GRABBED FOR USE THE ENTIRE MOUNT FALLS OFF OF THE DOOR. NEED LONGER SCREWS FOR MOUNT OR NEW HOLES DRILLED

**CSHOP-2017-5533**

Date Opened: 9-24-2017      Date Finished      9-24-2017      Meter 1 Reading:      72,076

**TASKS PERFORMED**

**NO PARTS USED**

INSTRUMENTS-GAUGES-WARNING &

**Asset Work Order History 10194779**

**CSHOP-2017-5852**

Date Opened: 10-11-2017      Date Finished      10-23-2017      Meter 1 Reading:      72,893

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?**      RECHTIEN INTERNATIONAL TRUCKS

**Service Requests:**

- 
- 10/10/2017      OIL / 18: LEAKING / REPAIR  
LEAKING MOTOR OIL
  - 10/12/2017      A/C / 18: LEAKING / REPAIR  
A/C ISSUE A/C IN CAB NOT BLOWING COLD.
  - 10/12/2017      OIL / 18: LEAKING / REPAIR  
LOW ENGINE OIL LARGE AMMOUNT OF OIL LEAKING FROM ENGINE
- 

**CSHOP-2017-6150**

Comments:      **PRE TRIP QC**

Date Opened: 10-25-2017      Date Finished      10-28-2017      Meter 1 Reading:      73,111

**TASKS PERFORMED**

**Q      PARTS**

- 
- |                          |    |                              |
|--------------------------|----|------------------------------|
| QUALITY CHECK-REPAIRS    | 12 | MAC; NON-CHLOR BRAKE CLNR    |
| EXHAUST PIPE             | 2  | 2IH; SPRING AIR              |
| RADIATOR                 | 1  | 2IH; AIR FILTER INDICATOR    |
| ENGINE AND ACCESSORIES   | 1  | 9IP; SWITCH A/C LOW PRESSURE |
| SUSPENSION               | 1  | 2IH; EVAP SENSOR             |
| DOOR PANEL               | 1  | NHD; HVAC AIR DOOR ACT       |
| CAB-INTERIOR ACCESSORIES |    |                              |
| AIR CONDITIONING         |    |                              |
- 

**CSHOP-2017-78**

Comments:      **R-93 LIGHTS AND SIRENS NOT WORKING**

Date Opened: 1-4-2017      Date Finished      1-13-2017      Meter 1 Reading:      63,595

**TASKS PERFORMED**

**Q      PARTS**

- 
- |  |   |          |
|--|---|----------|
| TRAVEL TO BE CHARGED TO WORK ORDER LIGHTING SYSTEM | 1 | 9IP; 9IP |
|--|---|----------|
- 

**Service Requests:**

- 
- 01/04/2017      ALARMS / 12: BROKEN / REPAIR  
WEHLEN SYSTEM STOPPED WORKING ON THE WAY TO A CALL THIS MORNING. WE GOT BACK TO THE STATION, TURNED EVERYTHING OFF AND TRIED IT AGAIN. NEITHER THE AUDIBLE ALARMS OR THE PA SYSTEM ARE PROJECTING OUTSIDE THE IMMEDIATE AREA OF THE RESCUE. ITS ALMOST LIKE SOMEONE TURNED DOWN THE SIRENS VOLUME.
- 

**CSHOP-2017-982**

Date Opened: 2-16-2017      Date Finished      2-17-2017      Meter 1 Reading:      65,714

**TASKS PERFORMED**

**Q      PARTS**

- 
- |                     |   |                            |
|---------------------|---|----------------------------|
| PM SERVICE C RESCUE | 1 | FIL; NAPA GOLD FUEL FILTER |
|                     | 1 | 2IH; FILTER KIT            |
-

**Asset Work Order History 10194779**

**CSHOP-2018-1033**

Date Opened: 2-20-2018

Date Finished

2-26-2018

Meter 1 Reading:

80,411

**TASKS PERFORMED**

**NO PARTS USED**

---

CAB-INTERIOR ACCESSORIES

**Service Requests:**

02/20/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

WARNING LIGHT FOR COMPARTMENT DOOR #7 CONTINUES TO GO OFF, EVEN THOUGHT THE DOOR IS SHUT.

---

**CSHOP-2018-1132**

Date Opened: 2-26-2018

Date Finished

2-26-2018

Meter 1 Reading:

80,411

**TASKS PERFORMED**

**NO PARTS USED**

---

DIAGNOSE ELECTRICAL

**Service Requests:**

02/26/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

ONE OF THE BOX LIGHTS FROM RESCUE 43 DRIVER COMPARTMENT WILL NOT TURN OFF. LIGHT REMAINS ON.

---

**CSHOP-2018-115**

Date Opened: 1-5-2018

Date Finished

1-16-2018

Meter 1 Reading:

77,561

A SERVICE

**TASKS PERFORMED**

PM SERVICE C RESCUE

**Q PARTS**

---

|     |                               |
|-----|-------------------------------|
| 1   | FIL; NAPA GOLD FUEL FILTER    |
| 1   | FLUID; COOLANT ANTIFREEZE GAL |
| 1   | FIL; NAPA TRANS FILTER        |
| 23  | FLUID; SYN OIL BULK QTS       |
| -23 | 9OC; SYN 15W40                |
| 23  | 9OC; SYN 15W40                |
| 1   | FIL; NAPAGOLD OIL FILTER      |
| -1  | 9OC; COOLANT                  |
| 1   | 9OC; COOLANT                  |

---

**Asset Work Order History 10194779**

**CSHOP-2018-116**

Comments: **USE FOR PM FOLLOW UPS**

Date Opened: 1-6-2018      Date Finished      1-9-2018      Meter 1 Reading:      77,342

REPLACE CABIN AIR FILTERS (FRONT AND BACK)

**TASKS PERFORMED**

**Q      PARTS**

---

|                     |   |                                   |
|---------------------|---|-----------------------------------|
| WIPER BLADES        | 2 | 1AN; WIPERS                       |
| POWER STEERING PUMP | 1 | FIL; POWER STEERING FILTER        |
| BRAKES              | 4 | 2IH; POWER STEERING FLUID 32OZ    |
| AIR DRIER           | 2 | MBI; GRIP/KIT                     |
| CABIN AIR FILTER    | 4 | 9AP; BRAKE CLEANER                |
|                     | 2 | TWD; BRAKE SHOE KITS- NEW         |
|                     | 2 | TWD; BRAKE DRUM                   |
|                     | 1 | TWD; BRAKE DRUM                   |
|                     | 1 | TWD; BRAKE DRUM                   |
|                     | 4 | NTH; ADAPTER                      |
|                     | 1 | TWD; REP/CART                     |
|                     | 1 | MBI; PURG/VLV                     |
|                     | 1 | 2IH; FILTER, CAB A/C INT BX, BLUE |
|                     | 1 | FIL; NAPA CABIN AIR FILTER        |

---

**CSHOP-2018-1304**

Comments: **ON-CALL R43 EXHAUST FUMES IN CAB**

Date Opened: 3-5-2018      Date Finished      3-5-2018      Meter 1 Reading:      80,946

ON CALL 3 HR MIN

**TASKS PERFORMED**

**NO PARTS USED**

EXHAUST MANIFOLD

---

**CSHOP-2018-1308**

Date Opened: 3-5-2018      Date Finished      3-5-2018      Meter 1 Reading:      81,089

**TASKS PERFORMED**

**Q      PARTS**

---

|                |   |             |
|----------------|---|-------------|
| EXHAUST SYSTEM | 2 | 2IH; GASKET |
|                | 4 | 2IH; GASKET |
|                | 8 | 2IH; SPACER |
|                | 8 | 2IH; BOLT   |

---

**CSHOP-2018-1334**

Date Opened: 3-6-2018      Date Finished      3-6-2018      Meter 1 Reading:      81,115

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

---

**Service Requests:**

---

03/05/2018      OIL / 18: LEAKING / CRANK CASE BREATHER LEAKING OIL NEED NEW CRANK CASE BREATHER  
LOW ENGINE OIL-MODERATE LEAK, SMOKING ON EXHAUST MANIFOLD.

---

**Asset Work Order History 10194779**

**CSHOP-2018-1538**

Date Opened: 3-15-2018      Date Finished      3-15-2018      Meter 1 Reading:      81,115

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2018-1661**

Comments:      **QUALITY CHECK**  
Date Opened: 3-23-2018      Date Finished      3-23-2018      Meter 1 Reading:      81,174

**TASKS PERFORMED**

**Q      PARTS**

---

QUALITY CHECK-REPAIRS      3      9ME; ZICO RATCHET STRAPS  
OXYGEN SENSOR  
DOOR

---

**CSHOP-2018-1731**

Date Opened: 3-27-2018      Date Finished      3-27-2018      Meter 1 Reading:      81,202

**TASKS PERFORMED**

**NO PARTS USED**

---

ENGINE AND ACCESSORIES

**VENDOR?**      RECHTIEN INTERNATIONAL TRUCKS

---

**CSHOP-2018-1952**

Date Opened: 4-9-2018      Date Finished      4-10-2018      Meter 1 Reading:      82,088

**TASKS PERFORMED**

**Q      PARTS**

---

BODY EXTERIOR      1      6KU; AUTO EJECT YW

**Service Requests:**

---

04/07/2018      BODY / 18: LEAKING / REPAIR  
YELLOW PLASTIC SHORELINE COVER CRACKED OFF

---

**CSHOP-2018-2215**

Date Opened: 4-20-2018      Date Finished      5-30-2018      Meter 1 Reading:      84,415

**TASKS PERFORMED**

**Q      PARTS**

---

ENGINE AND ACCESSORIES      1      2IH; RETAINER NUT, HL BULB  
HEADLIGHTS LOW BEAM  
TIRE

---

**Asset Work Order History 10194779**

**CSHOP-2018-2298**

Date Opened: 4-26-2018

Date Finished

5-30-2018

Meter 1 Reading:

84,415

**TASKS PERFORMED**

**Q PARTS**

STORAGE CABINET EMERGENCY VEH  
CAB  
HEADLIGHTS LOW BEAM  
REPAIR FROM PM - BRAKES  
SIREN  
DOOR HANDLES INSIDE-OUTSIDE  
ALARM-BUZZER-WARNING LIGHT

5 5EF; BELLOWS GASKET FT  
1 MMM; WTHRSTRP ADH-BLK 5OZ  
2 LMP; LAMP

**Service Requests:**

- 
- 04/26/2018 ENGINE / 19: LOOSE / LEAK REPAIR COMPLETED AT DEALER VERIFIED AT SHOP AND B SERVICE  
ENGINE OIL CHANGE LIGHT IS ON
- 04/26/2018 SERVICE REQUEST / 19: LOOSE / ADJUSTED DRAWER SLIDE. ALIGNED DRAWER  
(1) LOCKING LATCH ON MEDBOX FOR R43 BROKEN AND NOT ABLE TO SECURE LID SHUT
- 05/13/2018 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / REPAIR RESET SERVICE INTERVALS AND P  
CHANGE OIL LIGHT ON. ALSO, A LOUD SQUEALING SOUND COMING FROM MOTOR UPON ACCELERATION, AS WELL  
AS A SMELL OF BURNING RUBBER.
- 05/13/2018 ENGINE / 12: BROKEN / REPLACED BULBS ELEMENT IN RIGHT HEADLIGHT BROKEN.  
CHANGE OIL LIGHT IS ON, PASSENGER SIDE HEADLIGHT OUT, ENGINE BELT IS SQUEALING, TRUCK IS EMITTING  
BLACK SMOKE FROM EXHAUST REGULARLY
- 

**CSHOP-2018-2700**

Date Opened: 5-15-2018

Date Finished

5-17-2018

Meter 1 Reading:

84,371

**TASKS PERFORMED**

**NO PARTS USED**

EXHAUST MANIFOLD

---

**CSHOP-2018-2717**

Comments: **SEE FILES FOR RECHTIEN REPAIR OF EXHAUST MANIFOLD UNDER WARRANTY**

Date Opened: 5-16-2018

Date Finished

5-30-2018

Meter 1 Reading:

84,415

**TASKS PERFORMED**

**NO PARTS USED**

EXHAUST MANIFOLD

---

**Service Requests:**

- 
- 05/16/2018 HAZARD / 18: LEAKING / SENT TO DEALER FOR RIGHT HAND EXHAUST MANIFOLD GASKET REPI  
R43 INTERIOR CAB HAS CARBON MONOXIDE ISSUE FROM A LEAK. TRUCK WAS INSPECTED BY ON CALL MECHANIC  
AND EVENTUALLY SWAPPED FOR A SPARE
-



**Asset Work Order History 10194779**

**CSHOP-2018-2937**

Date Opened: 5-29-2018

Date Finished

5-30-2018

Meter 1 Reading:

84,415

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FIL; NAPA GOLD FUEL FILTER  
1 2IH; AIR FILTER-CAN ORDER-500804  
20 4PC; 15W40 PREMIUM BLUE OIL  
2 8GR; FILTER  
1 FIL; NAPAGOLD OIL FILTER  
2 1AN; 22" WIPER BLADE  
1 FIL; NAPA CABIN AIR FILTER

**CSHOP-2018-3133**

Date Opened: 6-5-2018

Date Finished

6-6-2018

Meter 1 Reading:

84,707

**TASKS PERFORMED**

**NO PARTS USED**

TIRES ALL

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2018-3286**

Date Opened: 6-12-2018

Date Finished

6-20-2018

Meter 1 Reading:

85,477

**TASKS PERFORMED**

**Q PARTS**

STRETCHER  
ELECTRICAL

2 5SP; BELT  
1 5SC; AUTOEJECTKITWYELLOWCVR

**Service Requests:**

06/12/2018 SERVICE REQUEST / 18: LEAKING / REPAIR  
SHORELINE NOT AUTO EJECTING

**CSHOP-2018-3826**

Date Opened: 7-6-2018

Date Finished

7-30-2018

Meter 1 Reading:

87,647

**TASKS PERFORMED**

**NO PARTS USED**

SHORELINE CHARGER

**Service Requests:**

07/06/2018 SERVICE REQUEST / 18: LEAKING / REPAIR  
SHORELINE AUTO EJECTOR NOT FUNCTIONING PROPERLY.

**Asset Work Order History 10194779**

**CSHOP-2018-4221**

Date Opened: 7-29-2018

Date Finished

8-2-2018

Meter 1 Reading:

87,780

**TASKS PERFORMED**

**Q PARTS**

ENGINE AND ACCESSORIES  
AIR CONDITIONING

6 4PC; 15W40 PREMIUM BLUE OIL  
1 FIL; NAPAGOLD OIL FILTER  
1 TEM; EXPVALV  
1 TEM; STEEL FILTER DRIER  
1 TEM; NEW COMPRESSOR  
1 9AP; KWIK KLEAN AC FLUSH  
3 9XX; AC FREON 10174676  
1 2TP; NAVISTAR

**CSHOP-2018-4371**

Date Opened: 8-6-2018

Date Finished

8-7-2018

Meter 1 Reading:

87,991

**TASKS PERFORMED**

**NO PARTS USED**

AIR CONDITIONING

**Service Requests:**

08/05/2018 A/C / 18: LEAKING / REPAIR  
REAR CAB COMPARTMENT A/C NON FUNCTIONING

**CSHOP-2018-4674**

Date Opened: 8-20-2018

Date Finished

9-1-2018

Meter 1 Reading:

89,403

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

-1 2IH; BLOWER CAB REAR  
1 2IH; BLOWER CAB REAR  
1 TEM; BLOWER MOTOR

**Service Requests:**

08/20/2018 A/C / 18: LEAKING / REPAIR  
A/C ISSUE

08/20/2018 A/C / 18: LEAKING / REPAIR  
ROOF TOP A/C FOR PATIENT CARE COMPARTMENT LEAKING EXCESSIVELY

08/20/2018 SERVICE REQUEST / 18: LEAKING / REPAIR  
KUSS MAL AUTO EJECTOR NOT FUNCTIONING.

08/23/2018 A/C / 18: LEAKING / REPAIR  
A/C ISSUE- AIR CONDITIONING INSIDE CAB (REAR) DOES NOT WORK. IT DOES NOT TURN ON.

**Asset Work Order History 10194779**

**CSHOP-2018-5647**

Date Opened: 10-4-2018      Date Finished      10-5-2018      Meter 1 Reading:      91,241

**TASKS PERFORMED**

**NO PARTS USED**

---

INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

---

10/03/2018      ALARMS / 18: LEAKING / REPAIR  
ALARM SIGNALS ON R43 - "DPF LOAD" AND "CHANGE ENGINE OIL" LIGHT ARE ON.

---

**CSHOP-2018-5816**

Date Opened: 10-15-2018      Date Finished      10-15-2018      Meter 1 Reading:      91,807

**TASKS PERFORMED**

**NO PARTS USED**

---

SAFTEY-EMERGENCY EQUIPMENT

**Service Requests:**

---

10/15/2018      SERVICE REQUEST / 18: LEAKING / REPAIR  
SHORELINE NOT EJECTING UPON STARTUP.

---

**CSHOP-2018-615**

Comments:      **EXHAUST SMELL IN CAB**

Date Opened: 1-29-2018      Date Finished      1-29-2018      Meter 1 Reading:      78,567

**TASKS PERFORMED**

**NO PARTS USED**

---

EXHAUST SYSTEM

**CSHOP-2018-6167**

Date Opened: 10-29-2018      Date Finished      11-1-2018      Meter 1 Reading:      92,219

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE C RESCUE

---

**Asset Work Order History 10194779**

**CSHOP-2018-6168**

Comments: **PM REPAIR LIST**

Date Opened: 10-29-2018      Date Finished 12-27-2018      Meter 1 Reading: 92,849

**TASKS PERFORMED**

|  | <b>Q</b> | <b>PARTS</b>                     |
|--|----------|----------------------------------|
| REPAIR FROM PM - DRY AIR CLEANER           | 1        | TWD; REP/CART                    |
| REPAIR FROM PM - REAR A/C LIGHTING SYSTEM  | 1        | 9IP; UV LAMP HORTONS             |
| REPAIR FROM PM - POWER STEERING AUTO-EJECT | 1        | 1WL; BULB                        |
| REPAIR FROM PM - REAR SUSPENSION           | 1        | LIT; BULB, WHELEN H27SN12        |
| REPAIR FROM PM - BATTERIES U-BOLTS         | 2        | LMP; BULB                        |
| REPAIR FROM PM - ENGINE                    | 1        | FIL; POWER STEERING FILTER       |
| REPAIR FROM PM - TRANSMISSION              | 3        | 9OC; BULK TRANS SYN              |
| WINDOW REGULATOR                           | 1        | 6KU; AUTO EJECT YW               |
| CAB-INTERIOR ACCESSORIES                   | 2        | 2IH; VALVE, LEVELING             |
|  | 2        | BK; SPRAYER                      |
|  | 3        | 1AD; BATTERY 31 SERIES           |
|  | 1        | NTH; GAUGE                       |
|  | 1        | FIL; NAPA GOLD FUEL FILTER       |
|  | 1        | 2IH; AIR FILTER-CAN ORDER-500804 |
|  | 21       | 4PC; 15W40 PREMIUM BLUE OIL      |
|  | 1        | FIL; NAPAGOLD OIL FILTER         |
|  | 1        | FIL; NAPA TRANS FILTER           |
|  | 1        | 2IH; REGULATOR, DRIVER FRONT     |
|  | -1       | MBI; VALVE KNOB                  |
|  | 1        | MBI; VALVE KNOB                  |

**CSHOP-2018-6438**

Date Opened: 11-13-2018      Date Finished 11-16-2018      Meter 1 Reading: 92,810

**TASKS PERFORMED**

|                        | <b>Q</b> | <b>PARTS</b>   |
|------------------------|----------|----------------|
| ENGINE AND ACCESSORIES | 1        | 2IH; PIPE, AIR |
|                        | 1        | 2IH; CLAMP     |
|                        | 1        | 2IH; CLAMP     |

**Service Requests:**

11/11/2018      ENGINE / 19: LOOSE / INSPECT  
ENGINE EVEN THOUGH ALL THE FLUID LEVELS APPEAR GOOD, TEMPERATURE AND PRESSURE READINGS ON THE GAUGES ALSO APPEAR GOOD, THE ENGINE IS MAKING A LOUD NOISE. MY BEST GUESS IS SOMETHING IS WRONG WITH THE COOLING FAN LIKE BAD BEARINGS OR SOMETHING. OTHER THAN THE EXCESSIVE NOISE, THE VEHICLE IS RUNNING FINE BUT BEFORE SOMETHING DOES GO BAD... THIS IS THE SPARE RESCUE AT 45, R245.

**CSHOP-2018-7363**

Comments: **QUALITY CHECK BACK FROM RECHTIEN**

Date Opened: 12-28-2018      Date Finished 12-28-2018      Meter 1 Reading: 92,854

**TASKS PERFORMED**

|                       | <b>Q</b> | <b>PARTS</b>              |
|-----------------------|----------|---------------------------|
| QUALITY CHECK-REPAIRS | 1        | 9PB; LARGE PLACARD HOLDER |

**Asset Work Order History 10194779**

**CSHOP-2018-759**

Date Opened: 2-5-2018      Date Finished      2-5-2018      Meter 1 Reading:      78,993

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CAB-INTERIOR ACCESSORIES

---

**CSHOP-2019-1037**

Comments:      **SPARE RESCUE AT 32**

Date Opened: 2-25-2019      Date Finished      3-4-2019      Meter 1 Reading:      96,425

DOOR HOLDER GONE

**TASKS PERFORMED**

**Q      PARTS**

REPAIR FROM PM - DECALS/CLEANLINESS  
BODY EXTERIOR

1      DETAIL  
2      5AH; ADJ DOOR GRABBER 4.5"

**Service Requests:**

---

02/25/2019      DOOR / 12: BROKEN / REPAIR  
VEHICLE DOORS. REAR DOOR STOPS ON CAB MISSING.

---

**CSHOP-2019-1224**

Comments:      **AIR LEAK WELLINGTON TRACE AND GREENVIEW SHORES**

Date Opened: 3-6-2019      Date Finished      3-11-2019      Meter 1 Reading:      96,486

**TASKS PERFORMED**

**Q      PARTS**

WAIT TIME TO BE CHARGED TO WORK ORDER  
TRAVEL TO BE CHARGED TO WORK ORDER  
AIR DRIER  
AIR SYSTEM

2      TWD; PURGE VALVE ASSY KIT

**CSHOP-2019-1370**

Date Opened: 3-13-2019      Date Finished      5-8-2019      Meter 1 Reading:      98,411

**TASKS PERFORMED**

**Q      PARTS**

THERMOSTAT  
WATER PUMP  
OIL  
TRANSMISSION

1      2IH; THERMOSTAT KIT  
5      BK; HOSE CLAMP  
1      2IH; WATER PUMP  
1      9AP; HAND SOAP PUM (TOTAL TRK)

---

**Asset Work Order History 10194779**

**CSHOP-2019-1788**

Comments: **SPARE AT 53**

Date Opened: 4-8-2019

Date Finished 4-12-2019

Meter 1 Reading: 98,411

**TASKS PERFORMED**

**Q PARTS**

CAB  
ENGINE AND ACCESSORIES

1 NBH; TENSIONER-HEAVY DUTY

**Service Requests:**

04/06/2019

DOOR / 12: BROKEN / CLEAN

VEHICLE DOORS WEATHER STRIPPING ON THE DRIVERS SIDE HAS PEELED ALL THE WAY OFF

**CSHOP-2019-1833**

Comments: **IS AT ST53 CURRENTLY NEED TO GET IN FOR PM AS SOON AS POSSIBLE 4-9-19**

Date Opened: 4-17-2019

Date Finished 4-18-2019

Meter 1 Reading: 98,411

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FIL; NAPA GOLD FUEL FILTER  
22 4PC; 15W40 PB OIL DRM/QT  
1 FIL; NAPAGOLD OIL FILTER

**CSHOP-2019-1878**

Comments: **SPARE RESCUE AT 53**

Date Opened: 4-11-2019

Date Finished 4-18-2019

Meter 1 Reading: 98,411

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**Service Requests:**

04/11/2019

ENGINE / 12: BROKEN / INSPECT

SPARE R53 IS VERY ROUGH WHEN THE TRANSMISSION IS SHIFTING GEARS AND IT STARTED TO SMOKE HEAVILY FOR A 10 MIN PERIOD LATE LAST NIGHT FROM THE EXHAUST STACK.

**CSHOP-2019-2217**

Date Opened: 4-26-2019

Date Finished 4-26-2019

Meter 1 Reading: 98,411

**TASKS PERFORMED**

**NO PARTS USED**

TIRES ALL

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**Asset Work Order History 10194779**

**CSHOP-2019-2327**

Date Opened: 5-2-2019      Date Finished      5-8-2019      Meter 1 Reading:      98,411

**TASKS PERFORMED**

**NO PARTS USED**

DIAGNOSTIC TEST

**Service Requests:**

05/01/2019      DOOR / 19: LOOSE / INSPECT  
VEHICLE DOORS R43 DRIVER SIDE REAR SCBA TANK COMPARTMENT DOOR WILL NOT LATCH OR CLOSE

**CSHOP-2019-3022**

Date Opened: 6-11-2019      Date Finished      6-12-2019      Meter 1 Reading:      98,411

**TASKS PERFORMED**

**Q      PARTS**

QUALITY CHECK-REPAIRS  
LIGHTING SYSTEM  
AIR HORN

4      2IH; LIGHT, DOOR  
2      9AP; HORN KIT, PAI, 3390-1094

**CSHOP-2019-3173**

Comments:      **SPARE RESCUE AT 34**

Date Opened: 6-19-2019      Date Finished      6-24-2019      Meter 1 Reading:      98,901

**TASKS PERFORMED**

**NO PARTS USED**

INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

06/19/2019      ENGINE / 18: LEAKING / REPAIR  
CHECK ENGINE LIGHT IS ON, WITH THE SERVICE WRENCH LIGHT. AT HIGHWAY SPEEDS IT FEELS LIKE THE TIRES ARE NOT BALANCING OUT.

**CSHOP-2019-325**

Date Opened: 1-18-2019      Date Finished      1-18-2019      Meter 1 Reading:      94,389

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FAULT CODE  
WINDOW ELECTRIC MOTOR

**CSHOP-2019-3267**

Date Opened: 6-24-2019      Date Finished      6-25-2019      Meter 1 Reading:      98,952

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Service Requests:**

06/23/2019      A/C / 18: LEAKING / REPAIR  
A/C ISSUE--- SHORELINE AC FAN BLOWING HARD BUT HARDLY ANY COLD AIR COMING OUT

**Asset Work Order History 10194779**

**CSHOP-2019-3425**

Date Opened: 7-1-2019      Date Finished      7-2-2019      Meter 1 Reading:      99,346

**TASKS PERFORMED**

**NO PARTS USED**

---

INSTRUMENTS-GAUGES-WARNING &

---

**CSHOP-2019-3763**

Date Opened: 7-19-2019      Date Finished      7-23-2019      Meter 1 Reading:      100,312

**TASKS PERFORMED**

**NO PARTS USED**

---

CAB-INTERIOR ACCESSORIES  
INSTRUMENTS-GAUGES-WARNING &

---

**CSHOP-2019-3945**

Date Opened: 7-30-2019      Date Finished      8-21-2019      Meter 1 Reading:      101,758

**TASKS PERFORMED**

**Q      PARTS**

---

COOLING SYSTEM  
ENGINE AND ACCESSORIES

1      2IH; TANK  
1      BK; RADIATOR CAP  
20      4PC; 15W40PREMIUMBLUEOIL

**Service Requests:**

---

07/30/2019      ENGINE / 12: BROKEN / REPAIR  
PARKED REGEN AVAILABLE KEEPS DISPLAYING ON ECM EVEN AFTER MULTIPLE PARKED REGENS PERFORMED FOR R34. 2 PARKED REGENS PERFORMED ON 7/30/19 AND ECM STILL DISPLAYS WITH 1/2 DPF LOAD

---

**CSHOP-2019-4046**

Date Opened: 8-2-2019      Date Finished      8-2-2019      Meter 1 Reading:      100,978

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

---

08/02/2019      SERVICE REQUEST / 12: BROKEN / REPLACED  
UNABLE TO FUEL R34, FUEL RING NOT WORKING AND NO FUEL CARD ON VEHICLE. BC34 FUEL CARD USED

08/02/2019      SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / RESET  
UPSIDE DOWN TRIANGLE / WARNING ENGINE LIGHT TURNS ON AND OFF INTERMITTENTLY WHEN DRIVING ABOVE 65 MPH

---



**Asset Work Order History 10194779**

**CSHOP-2019-4249**

Date Opened: 8-13-2019

Date Finished

9-11-2019

Meter 1 Reading:

101,819

**TASKS PERFORMED**

**Q PARTS**

|                        |    |                                |
|------------------------|----|--------------------------------|
| EMISSIONS SYSTEM       | 1  | 2IH; DPF NEW 4 DOOR            |
| THERMOSTAT             | 1  | SVP; DPF GSKT 2601233C1        |
| WATER PUMP             | 1  | SVP; DPF GSKT 2593986C1        |
| FAN BELT               | 1  | MAC; MAC WITE LITHIUM GRES     |
| HOSE UPPER             | 1  | NBH; PULLEY                    |
| RADIATOR               | 1  | 2IH; HOSE COOLANT M7           |
| FAULT CODE             | 1  | 2IH; HOSE, WATER               |
| ENGINE AND ACCESSORIES | -9 | 9OC; COOLANT                   |
| LIGHTING SYSTEM        | 9  | 9OC; COOLANT                   |
| WIRING                 | 1  | NBH; SERPENTINEBELT            |
| TRANSMISSION           | 1  | 2IH; BELT                      |
| ALIGNMENT              | 1  | 2IH; HOSE RADIATOR             |
| U-BOLTS                | 1  | NBH; TENSIONER-HEAVY DUTY      |
| STEERING               | 1  | 2IH; THERMOSTAT KIT            |
| GRILLE                 | 1  | NBH; PULLEY                    |
| BODY EXTERIOR          | 1  | 2IH; WATER PUMP                |
| DOOR LOCKS             | 9  | FLUID; COOLANT ANTIFREEZE GAL  |
| A/C FILTER SCREENS     | 1  | 2IH; BELTTENSIONERV8           |
| A/C COMPRESSOR         | 1  | 5HO; FANDRIVE                  |
|                        | 2  | NBH; IDLER PULLEY              |
|                        | 1  | 2IH; RADIATOR                  |
|                        | 1  | 2IH; HOUSING                   |
|                        | 2  | TWD; 1000UJOINTASSY            |
|                        | 1  | FIL; POWER STEERING FILTER     |
|                        | 1  | 2IH; GASKET, POWER STEERING    |
|                        | 2  | 2IH; POWER STEERING FLUID 32OZ |
|                        | 1  | 2IH; GRILLBAR                  |
|                        | 1  | 9PB; SMALL PLACARD             |
|                        | 2  | 9PB; LARGE PLACARD             |
|                        | 2  | 9HD; FILTER CABIN 7 75X14 5    |
|                        | 1  | TEM; NEW COMPRESSOR            |

**Service Requests:**

08/11/2019

FUEL / 12: BROKEN / REPAIR & REPROGRAM CK OK

THIS IS THE SPARE RESCUE AT ST 34, RESCUE RECENTLY RECEIVED A NEW FUEL CARD AND NOT YOU HAVE TO MANUALLY ENTER FOR FUEL. CAN A TECH PLEASE COME BY AND FLASH THE RESCUE FUEL READER WITH THE NEW FUEL CARD NUMBER.

**CSHOP-2019-4275**

Date Opened: 8-15-2019

Date Finished

8-15-2019

Meter 1 Reading:

98,494

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?** RECHTIEN INTERNATIONAL TRUCKS

**Asset Work Order History 10194779**

**CSHOP-2019-6115**

Date Opened: 11-21-2019      Date Finished      12-2-2019      Meter 1 Reading:      101,889

**TASKS PERFORMED**

**Q      PARTS**

---

|                             |   |                          |
|-----------------------------|---|--------------------------|
| EQUIPMENT MOUNTING BRACKETS | 2 | 4AH; GAS SPRING 7 5 45LB |
| PRE TRIP INSPECTION         | 1 | 2IH; WASHERPUMP          |
| DOOR PROP CYLINDER          | 1 | 5GI; LED LIGHT           |
| WIPERS-WASHER               | 1 | BK; FUSE HOLDER          |
| LIGHTING SYSTEM             | 2 | LIT; REFLECTOR           |
| SHORELINE CHARGER           |   |                          |
| SAFTEY-EMERGENCY EQUIPMENT  |   |                          |
| CAB-INTERIOR ACCESSORIES    |   |                          |

---

**CSHOP-2019-6186**

Comments: **TRUCK CURRENTLY AT SPECIAL DETAIL**

Date Opened: 11-27-2019      Date Finished      3-16-2020      Meter 1 Reading:      102,081

**TASKS PERFORMED**

**Q      PARTS**

---

|                        |   |                                   |
|------------------------|---|-----------------------------------|
| ENGINE AND ACCESSORIES | 1 | 2IH; REGULATOR                    |
| TRANSMISSION           | 1 | 2IH; REGULATOR DRIVER FRONT       |
| WINDOW REGULATOR       | 1 | 2IH; REGULATOR FRONT RIGHT WINDOW |

---

**Service Requests:**

---

11/26/2019      WINDOW / 18: INSPECT / COMMERCIAL  
WINDOW ON DRIVER SIDE PASSENGER DOOR GOES DOWN BUT WILL NOT GO BACK WITHOUT ASSISTANCE

---

**CSHOP-2019-6215**

Date Opened: 11-29-2019      Date Finished      11-29-2019      Meter 1 Reading:      101,998

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

---

**CSHOP-2019-6220**

Comments: **CHECK ENGINE LIGHT ON**

Date Opened: 12-1-2019      Date Finished      2-12-2020      Meter 1 Reading:      102,081

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

---

**CSHOP-2019-6221**

Comments: **CHECK ENGINE LIGHT ON**

Date Opened: 12-1-2019      Date Finished      2-12-2020      Meter 1 Reading:      102,080

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

---

